

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

1ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.152800
051	15.400000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	.865500
212	.984000
213	1.895000
214	3.490000
221	.098900
224	.070000
231	.695000
241	7.050000
242	5.000000
251	290.000000
252	240.000000
301	4.060000
302	6.700000
360	10.700000
361	27.500000
362	3.500000
363	.580000
364	3.520000
365	22.500000
366	20.630000
367	.118700
368	20.000000
369	12.150000
370	8.000000
371	7.200000
372	1.270000
373	2.040000
374	2.750000
375	1.500000
376	
377	3.190000
378	.540000
379	14.000000
380	.260000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
417	130.670000

420	94.500000
428	425.280000
450	111.820000
451	154.970000
452	94.950000
453	88.120000
454	119.120000
455	420.570000

501	501			
211		50.000000 x	.865500 =	43.275000
214		3.000000 x	3.490000 =	10.470000
401		1.000000 x	260.720000 =	260.720000
118		3.000000 x	10.001019 =	30.003057
114		8.000000 x	23.886192 =	191.089536

				AΘΡΟΙΣΜΑ =
				535.557593

				H.Δ. =
				589.113352
502	502			
211		80.000000 x	.865500 =	69.240000
114		8.000000 x	23.886192 =	191.089536
402		1.000000 x	369.270000 =	369.270000
214		7.000000 x	3.490000 =	24.430000
118		4.000000 x	10.001019 =	40.004076

				AΘΡΟΙΣΜΑ =
				694.033612

				H.Δ. =
				763.436973
503	503			
211		110.000000 x	.865500 =	95.205000
428		1.000000 x	425.280000 =	425.280000
214		10.000000 x	3.490000 =	34.900000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536

				AΘΡΟΙΣΜΑ =
				786.478612

				H.Δ. =
				865.126473
504	504			
211		40.000000 x	.865500 =	34.620000
214		2.000000 x	3.490000 =	6.980000
114		8.000000 x	23.886192 =	191.089536
403		1.000000 x	100.390000 =	100.390000

				AΘΡΟΙΣΜΑ =
				333.079536

				H.Δ. =
				366.387490
505	505			
211		200.000000 x	.865500 =	173.100000
214		10.000000 x	3.490000 =	34.900000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
404		1.000000 x	206.630000 =	206.630000

				AΘΡΟΙΣΜΑ =
				685.727688

				H.Δ. =
				754.300457

506	506				
211		95.000000 x	.865500 =		82.222500
214		6.000000 x	3.490000 =		20.940000
405		1.000000 x	200.790000 =		200.790000
242		2.500000 x	5.000000 =		12.500000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536

		ΑΘΡΟΙΣΜΑ =			587.550188

		H.Δ. =			646.305207
507	507				
211		165.000000 x	.865500 =		142.807500
214		10.000000 x	3.490000 =		34.900000
242		7.000000 x	5.000000 =		35.000000
406		1.000000 x	311.770000 =		311.770000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152

		ΑΘΡΟΙΣΜΑ =			795.575188

		H.Δ. =			875.132707
508	508				
211		40.000000 x	.865500 =		34.620000
407		1.000000 x	53.630000 =		53.630000
115		4.000000 x	21.778427 =		87.113708
116		16.000000 x	20.419486 =		326.711776
408		2.000000 x	4.400000 =		8.800000
214		2.000000 x	3.490000 =		6.980000

		ΑΘΡΟΙΣΜΑ =			517.855484

		H.Δ. =			569.641032
509	509				
211		80.000000 x	.865500 =		69.240000
117		8.000000 x	16.777917 =		134.223336
409		1.000000 x	122.460000 =		122.460000
214		5.000000 x	3.490000 =		17.450000

		ΑΘΡΟΙΣΜΑ =			343.373336

		H.Δ. =			377.710670
510	510				
211		80.000000 x	.865500 =		69.240000
117		8.000000 x	16.777917 =		134.223336
214		5.000000 x	3.490000 =		17.450000
410		1.000000 x	113.190000 =		113.190000

		ΑΘΡΟΙΣΜΑ =			334.103336

		H.Δ. =			367.513670

511	511			
212		17.000000 x	.984000 =	16.728000
411		1.000000 x	26.580000 =	26.580000
214		1.000000 x	3.490000 =	3.490000
115		4.000000 x	21.778427 =	87.113708
112		30.000000 x	17.312112 =	519.363360

				AΘΡΟΙΣΜΑ =
				653.275068

				H.Δ. =
				718.602575
512	512			
211		10.000000 x	.865500 =	8.655000
115		2.000000 x	21.778427 =	43.556854
214		1.000000 x	3.490000 =	3.490000
112		2.000000 x	17.312112 =	34.624224
412		1.000000 x	2.900000 =	2.900000

				AΘΡΟΙΣΜΑ =
				93.226078

				H.Δ. =
				102.548686
518	518			
211		180.000000 x	.865500 =	155.790000
212		5.000000 x	.984000 =	4.920000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
112		8.000000 x	17.312112 =	138.496896
417		1.000000 x	130.670000 =	130.670000
214		12.000000 x	3.490000 =	41.880000

				AΘΡΟΙΣΜΑ =
				742.854584

				H.Δ. =
				817.140042
521	521			
211		40.000000 x	.865500 =	34.620000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536
214		3.000000 x	3.490000 =	10.470000
420		1.000000 x	94.500000 =	94.500000

				AΘΡΟΙΣΜΑ =
				370.683612

				H.Δ. =
				407.751973
550	550			
211		80.000000 x	.865500 =	69.240000
214		5.000000 x	3.490000 =	17.450000
117		8.000000 x	16.777917 =	134.223336
450		1.000000 x	111.820000 =	111.820000

				AΘΡΟΙΣΜΑ =
				332.733336

				H.Δ. =
				366.006670

560	560			
211		80.000000 x	.865500 =	69.240000
117		8.000000 x	16.777917 =	134.223336
455		1.000000 x	420.570000 =	420.570000
214		7.000000 x	3.490000 =	24.430000

			ΑΘΡΟΙΣΜΑ =	648.463336

			H.Δ. =	713.309670
621	621			
213		.100000 x	1.895000 =	.189500
508		.005000 x	569.641032 =	2.848205
116		.200000 x	20.419486 =	4.083897
111		.800000 x	15.741598 =	12.593278

			B.T =	19.714881
623	623			
213		.100000 x	1.895000 =	.189500
508		.005000 x	569.641032 =	2.848205
504		.005000 x	366.387490 =	1.831937
116		.200000 x	20.419486 =	4.083897
112		.100000 x	17.312112 =	1.731211
518		.010000 x	817.140042 =	8.171400
509		.005000 x	377.710670 =	1.888553

			B.T =	20.744705
625	625			
213		.100000 x	1.895000 =	.189500
116		.200000 x	20.419486 =	4.083897
112		.100000 x	17.312112 =	1.731211
504		.005000 x	366.387490 =	1.831937
509		.005000 x	377.710670 =	1.888553
518		.014300 x	817.140042 =	11.685103
508		.005000 x	569.641032 =	2.848205

			B.T =	24.258407
630	630			
512		.020000 x	102.548686 =	2.050974

			B.T =	2.050974
630.1	630.1			
510		.006000 x	367.513670 =	2.205082

			B.T =	2.205082

641	641			
231		.200000 x	.695000 =	.139000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	240.000000 =	.600000

			B.T =	7.385243
651	651			
221		150.000000 x	.098900 =	14.835000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.003600 x	377.710670 =	1.359758
509		.011100 x	377.710670 =	4.192588
511		.050000 x	718.602575 =	35.930129
630		.600000 x	2.050974 =	1.230584
625		1.000000 x	24.258407 =	24.258407
224		120.000000 x	.070000 =	8.400000

			B.T =	122.474920
652	652			
221		650.000000 x	.098900 =	64.285000
509		.011000 x	377.710670 =	4.154817
630		.320000 x	2.050974 =	.656312
625		1.000000 x	24.258407 =	24.258407
511		.050000 x	718.602575 =	35.930129
509		.001920 x	377.710670 =	.725204
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	162.278322
1121	1121			
112		.007000 x	17.312112 =	.121185
501		.000100 x	589.113352 =	.058911
503		.002000 x	865.126473 =	1.730253

			T.E =	1.910349
1122	1122			
112		.007000 x	17.312112 =	.121185
503		.000330 x	865.126473 =	.285492
501		.000080 x	589.113352 =	.047129
505		.000600 x	754.300457 =	.452580
507		.001400 x	875.132707 =	1.225186
509		.004447 x	377.710670 =	1.679679

			T.E =	3.811251

1123A	1123A			
112		.007000 x	17.312112 =	.121185
501		.000100 x	589.113352 =	.058911
503		.002000 x	865.126473 =	1.730253
509		.005312 x	377.710670 =	2.006399
506		.001330 x	646.305207 =	.859586

			T.E =	4.776334
1123B	1123B			
509		.001487 x	377.710670 =	.561656

			T.E =	.561656
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	407.751973 =	.081550
501		.000100 x	589.113352 =	.058911

			T.E =	.313583
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	3.811251 =	.762250
507		.000200 x	875.132707 =	.175027
501		.000100 x	589.113352 =	.058911
502		.000200 x	763.436973 =	.152687

			T.E =	1.935955
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	3.811251 =	3.811251
501		.002000 x	589.113352 =	1.178227

			T.E =	9.317506
1710	1710			
360		1.000000 x	10.700000 =	10.700000
111		.250000 x	15.741598 =	3.935400
501		.000100 x	589.113352 =	.058911

			T.E =	14.694311
2111	2111			
112		.010000 x	17.312112 =	.173121
509		.005202 x	377.710670 =	1.964851
507		.001540 x	875.132707 =	1.347704
502		.002000 x	763.436973 =	1.526874
501		.000830 x	589.113352 =	.488964

			T.E =	5.501514

2112	2112			
213		.400000 x	1.895000 =	.758000
502		.002900 x	763.436973 =	2.213967
112		.250000 x	17.312112 =	4.328028
116		.250000 x	20.419486 =	5.104872
507		.002000 x	875.132707 =	1.750265
509		.004896 x	377.710670 =	1.849271
508		.004000 x	569.641032 =	2.278564

			T.E =	18.282968
2251	2251			
111		.600000 x	15.741598 =	9.444959
621		1.050000 x	19.714881 =	20.700625
112		.600000 x	17.312112 =	10.387267
509		.012432 x	377.710670 =	4.695699

			T.E =	45.228550
2252	2252			
111		1.400000 x	15.741598 =	22.038237
621		1.050000 x	19.714881 =	20.700625
113		1.400000 x	20.419486 =	28.587280
509		.012432 x	377.710670 =	4.695699

			T.E =	76.021842
2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	19.714881 =	20.700625
652		.020000 x	162.278322 =	3.245566
651		.250000 x	122.474920 =	30.618730
509		.012432 x	377.710670 =	4.695699
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

			T.E =	137.384155
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	162.278322 =	16.227832
621		.350000 x	19.714881 =	6.900208
509		.003788 x	377.710670 =	1.430768
113		1.500000 x	20.419486 =	30.629229

			T.E =	67.781316

2522	2522			
221		300.000000 x	.098900 =	29.670000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	20.744705 =	16.595764
630		.250000 x	2.050974 =	.512744
641		3.000000 x	7.385243 =	22.155729
625		.500000 x	24.258407 =	12.129204
511		.040000 x	718.602575 =	28.744103
509		.008880 x	377.710670 =	3.354071
509		.001500 x	377.710670 =	.566566
509		.005550 x	377.710670 =	2.096294
113		1.600000 x	20.419486 =	32.671178

			T.E =	172.732608
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	172.732608 =	.863663
652		.002000 x	162.278322 =	.324557
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.712653
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	162.278322 =	1.947340
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.561887
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	366.006670 =	1.372525

			T.E =	1.844773

5150	5150			
111		.030000 x	15.741598 =	.472248
550		.002500 x	366.006670 =	.915017

			T.E =	1.387265
5160	5160			
213		.400000 x	1.895000 =	.758000
111		.160000 x	15.741598 =	2.518656
508		.001500 x	569.641032 =	.854462

			T.E =	4.131117
5210	5210			
363		.100000 x	.580000 =	.058000
112		.050000 x	17.312112 =	.865606
111		.040000 x	15.741598 =	.629664

			T.E =	1.553270
5220	5220			
363		.100000 x	.580000 =	.058000
112		.030000 x	17.312112 =	.519363
111		.020000 x	15.741598 =	.314832

			T.E =	.892195
5230	5230			
364		1.000000 x	3.520000 =	3.520000
112		.080000 x	17.312112 =	1.384969

			T.E =	4.904969
5240	5240			
112		.080000 x	17.312112 =	1.384969

			T.E =	1.384969
5311	5311			
111		.002000 x	15.741598 =	.031483
630.1		.020000 x	2.205082 =	.044102
510		.000250 x	367.513670 =	.091878
630		.020000 x	2.050974 =	.041019

			T.E =	.208483

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.205082 =	.044102
510		.000163 x	367.513670 =	.059905
630		.020000 x	2.050974 =	.041019

			T.E =	.165490
5321	5321			
111		.004000 x	15.741598 =	.062966

			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947

			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463

			T.E =	.349463
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	15.741598 =	.051947

			T.E =	.109947
5351	5351			
113		.005000 x	20.419486 =	.102097

			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873

			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390

			T.E =	.565806

5354	5354				
111		.035000 x	15.741598 =		.550956
113		.025000 x	20.419486 =		.510487

			T.E =		1.061443
5361A	5361A				
365		.003000 x	22.500000 =		.067500
630		.000300 x	2.050974 =		.000615
510		.000188 x	367.513670 =		.069093
113		.001500 x	20.419486 =		.030629

			T.E =		.167837
5361B	5361B				
366		.003000 x	20.630000 =		.061890
510		.000188 x	367.513670 =		.069093
630		.000300 x	2.050974 =		.000615
113		.001500 x	20.419486 =		.030629

			T.E =		.162227
5362A	5362A				
365		.005000 x	22.500000 =		.112500
630		.000500 x	2.050974 =		.001025
510		.000313 x	367.513670 =		.115032
113		.002500 x	20.419486 =		.051049

			T.E =		.279606
5362B	5362B				
366		.005000 x	20.630000 =		.103150
630		.000500 x	2.050974 =		.001025
510		.000313 x	367.513670 =		.115032
113		.002500 x	20.419486 =		.051049

			T.E =		.270256
5363A	5363A				
365		.003000 x	22.500000 =		.067500
113		.001000 x	20.419486 =		.020419
510		.000125 x	367.513670 =		.045939
630		.000300 x	2.050974 =		.000615

			T.E =		.134474

5363B	5363B			
366		.003000 x	20.630000 =	.061890
113		.001000 x	20.419486 =	.020419
630		.000300 x	2.050974 =	.000615
510		.000125 x	367.513670 =	.045939

			T.E =	.128864
5364A	5364A			
365		.005000 x	22.500000 =	.112500
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.050974 =	.001025
510		.000225 x	367.513670 =	.082691

			T.E =	.232971
5364B	5364B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	2.050974 =	.001025
510		.000225 x	367.513670 =	.082691
113		.001800 x	20.419486 =	.036755

			T.E =	.223621
5371	5371			
111		17.300000 x	15.741598 =	272.329645
111		9.600000 x	15.741598 =	151.119341

			T.E =	423.448986
5372	5372			
379		2.000000 x	14.000000 =	28.000000
510		.100000 x	367.513670 =	36.751367
630		.100000 x	2.050974 =	.205097
113		.800000 x	20.419486 =	16.335589

			T.E =	81.292053
5380	5380			
111		5.000000 x	15.741598 =	78.707990
550		.412500 x	366.006670 =	150.977751

			T.E =	229.685741
5390	5390			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240

5510	5510				
361		15.000000 x	27.500000 =	412.500000	
363		20.000000 x	.580000 =	11.600000	
362		30.000000 x	3.500000 =	105.000000	
550		.375000 x	366.006670 =	137.252501	
113		20.000000 x	20.419486 =	408.389720	
365		2.000000 x	22.500000 =	45.000000	
111		20.000000 x	15.741598 =	314.831960	

				T.E =	1,434.574181
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630.1		10.000000 x	2.205082 =	22.050820	
510		.125000 x	367.513670 =	45.939209	
630		10.000000 x	2.050974 =	20.509740	

				T.E =	104.241367
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

				T.E =	23.612397
5530	5530				
453		.187500 x	88.120000 =	16.522500	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

				T.E =	48.005696
5540	5540				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

				T.E =	20.506199
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

				T.E =	47.224794
5552	5552				
379		1.000000 x	14.000000 =	14.000000	
630		.100000 x	2.050974 =	.205097	
510		.050000 x	367.513670 =	18.375684	
113		.400000 x	20.419486 =	8.167794	

				T.E =	40.748575

5560A	5560A			
365		1.000000 x	22.500000 =	22.500000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.050974 =	.205097
510		.100000 x	367.513670 =	36.751367

			T.E =	75.792053
5560B	5560B			
366		1.000000 x	20.630000 =	20.630000
510		.100000 x	367.513670 =	36.751367
630		.100000 x	2.050974 =	.205097
113		.800000 x	20.419486 =	16.335589

			T.E =	73.922053
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248

			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248

			T.E =	.787080
5610	5610			
363		15.000000 x	.580000 =	8.700000
111		30.000000 x	15.741598 =	472.247940
550		.125000 x	366.006670 =	45.750834
367		20,000.000000 x	.118700 =	2,374.000000

			T.E =	2,900.698774
5621	5621			
111		1.000000 x	15.741598 =	15.741598
630		10.000000 x	2.050974 =	20.509740
630.1		10.000000 x	2.205082 =	22.050820
510		.125000 x	367.513670 =	45.939209

			T.E =	104.241367
5622	5622			
111		1.500000 x	15.741598 =	23.612397

			T.E =	23.612397

5630	5630				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	
5640	5640				
111		10.000000 x	15.741598 =	157.415980	
111		2.000000 x	15.741598 =	31.483196	

			T.E =	188.899176	
5650	5650				
111		.120000 x	15.741598 =	1.888992	
111		.030000 x	15.741598 =	.472248	

			T.E =	2.361240	
5710	5710				
362		40.000000 x	3.500000 =	140.000000	
111		5.000000 x	15.741598 =	78.707990	
112		1.000000 x	17.312112 =	17.312112	
560		.125000 x	713.309670 =	89.163709	
510		.125000 x	367.513670 =	45.939209	
509		.125000 x	377.710670 =	47.213834	
114		1.000000 x	23.886192 =	23.886192	
380		800.000000 x	.260000 =	208.000000	
363		15.000000 x	.580000 =	8.700000	
377		250.000000 x	3.190000 =	797.500000	
378		100.000000 x	.540000 =	54.000000	

			T.E =	1,510.423045	
5720	5720				
111		.500000 x	15.741598 =	7.870799	
510		.062500 x	367.513670 =	22.969604	
630		10.000000 x	2.050974 =	20.509740	
630.1		10.000000 x	2.205082 =	22.050820	

			T.E =	73.400963	
5730	5730				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	