

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

4ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.151500
051	15.400000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.056100
212	1.291000
213	1.949500
214	3.930000
221	.099900
224	.070000
231	.825000
241	7.050000
242	5.000000
251	290.000000
252	290.000000
301	4.060000
302	6.700000
360	11.000000
361	28.200000
362	3.600000
363	.580000
364	3.520000
365	23.000000
366	21.150000
367	.121700
368	20.000000
369	12.150000
370	8.000000
371	7.200000
372	1.270000
373	2.040000
374	2.750000
375	1.500000
376	
377	3.270000
378	.540000
379	14.350000
380	.270000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
417	130.670000

420	94.500000
428	425.280000
450	111.820000
451	154.970000
452	94.950000
453	88.120000
454	119.120000
455	420.570000

501	501				
211		50.000000 x	1.056100 =	52.805000	
214		3.000000 x	3.930000 =	11.790000	
401		1.000000 x	260.720000 =	260.720000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	546.407593

				Η.Δ. =	601.048352
502	502				
211		80.000000 x	1.056100 =	84.488000	
114		8.000000 x	23.886192 =	191.089536	
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.930000 =	27.510000	
118		4.000000 x	10.001019 =	40.004076	

				ΑΘΡΟΙΣΜΑ =	712.361612

				Η.Δ. =	783.597773
503	503				
211		110.000000 x	1.056100 =	116.171000	
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.930000 =	39.300000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	811.844612

				Η.Δ. =	893.029073
504	504				
211		40.000000 x	1.056100 =	42.244000	
214		2.000000 x	3.930000 =	7.860000	
114		8.000000 x	23.886192 =	191.089536	
403		1.000000 x	100.390000 =	100.390000	

				ΑΘΡΟΙΣΜΑ =	341.583536

				Η.Δ. =	375.741890
505	505				
211		200.000000 x	1.056100 =	211.220000	
214		10.000000 x	3.930000 =	39.300000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
404		1.000000 x	206.630000 =	206.630000	

				ΑΘΡΟΙΣΜΑ =	728.247688

				Η.Δ. =	801.072457

506	506				
211		95.000000 x	1.056100 =		100.329500
214		6.000000 x	3.930000 =		23.580000
405		1.000000 x	200.790000 =		200.790000
242		2.500000 x	5.000000 =		12.500000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
				ΑΘΡΟΙΣΜΑ =	608.297188
				Η.Δ. =	669.126907
507	507				
211		165.000000 x	1.056100 =		174.256500
214		10.000000 x	3.930000 =		39.300000
242		7.000000 x	5.000000 =		35.000000
406		1.000000 x	311.770000 =		311.770000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
				ΑΘΡΟΙΣΜΑ =	831.424188
				Η.Δ. =	914.566607
508	508				
211		40.000000 x	1.056100 =		42.244000
407		1.000000 x	53.630000 =		53.630000
115		4.000000 x	21.778427 =		87.113708
116		16.000000 x	20.419486 =		326.711776
408		2.000000 x	4.400000 =		8.800000
214		2.000000 x	3.930000 =		7.860000
				ΑΘΡΟΙΣΜΑ =	526.359484
				Η.Δ. =	578.995432
509	509				
211		80.000000 x	1.056100 =		84.488000
117		8.000000 x	16.777917 =		134.223336
409		1.000000 x	122.460000 =		122.460000
214		5.000000 x	3.930000 =		19.650000
				ΑΘΡΟΙΣΜΑ =	360.821336
				Η.Δ. =	396.903470
510	510				
211		80.000000 x	1.056100 =		84.488000
117		8.000000 x	16.777917 =		134.223336
214		5.000000 x	3.930000 =		19.650000
410		1.000000 x	113.190000 =		113.190000
				ΑΘΡΟΙΣΜΑ =	351.551336
				Η.Δ. =	386.706470

511	511				
212		17.000000 x	1.291000 =	21.947000	
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	3.930000 =	3.930000	
115		4.000000 x	21.778427 =	87.113708	
112		30.000000 x	17.312112 =	519.363360	

				ΑΘΡΟΙΣΜΑ =	658.934068

				Η.Δ. =	724.827475
512	512				
211		10.000000 x	1.056100 =	10.561000	
115		2.000000 x	21.778427 =	43.556854	
214		1.000000 x	3.930000 =	3.930000	
112		2.000000 x	17.312112 =	34.624224	
412		1.000000 x	2.900000 =	2.900000	

				ΑΘΡΟΙΣΜΑ =	95.572078

				Η.Δ. =	105.129286
518	518				
211		180.000000 x	1.056100 =	190.098000	
212		5.000000 x	1.291000 =	6.455000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
417		1.000000 x	130.670000 =	130.670000	
214		12.000000 x	3.930000 =	47.160000	

				ΑΘΡΟΙΣΜΑ =	783.977584

				Η.Δ. =	862.375342
521	521				
211		40.000000 x	1.056100 =	42.244000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.930000 =	11.790000	
420		1.000000 x	94.500000 =	94.500000	

				ΑΘΡΟΙΣΜΑ =	379.627612

				Η.Δ. =	417.590373
550	550				
211		80.000000 x	1.056100 =	84.488000	
214		5.000000 x	3.930000 =	19.650000	
450		1.000000 x	111.820000 =	111.820000	
117		8.000000 x	16.777917 =	134.223336	

				ΑΘΡΟΙΣΜΑ =	350.181336

				Η.Δ. =	385.199470

560	560				
211		80.000000 x	1.056100 =	84.488000	
455		1.000000 x	420.570000 =	420.570000	
117		8.000000 x	16.777917 =	134.223336	
214		7.000000 x	3.930000 =	27.510000	
			ΑΘΡΟΙΣΜΑ =	666.791336	
			Η.Δ. =	733.470470	
621	621				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	578.995432 =	2.894977	
116		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
			B.T =	19.767103	
623	623				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	578.995432 =	2.894977	
504		.005000 x	375.741890 =	1.878709	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
518		.010000 x	862.375342 =	8.623753	
509		.005000 x	396.903470 =	1.984517	
			B.T =	21.392016	
625	625				
213		.100000 x	1.949500 =	.194950	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
504		.005000 x	375.741890 =	1.878709	
509		.005000 x	396.903470 =	1.984517	
518		.014300 x	862.375342 =	12.331967	
508		.005000 x	578.995432 =	2.894977	
			B.T =	25.100230	
630	630				
512		.020000 x	105.129286 =	2.102586	
			B.T =	2.102586	
630.1	630.1				
510		.006000 x	386.706470 =	2.320239	
			B.T =	2.320239	

641	641			
231		.200000 x	.825000 =	.165000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000

			B.T =	7.536243
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.003600 x	396.903470 =	1.428852
509		.011100 x	396.903470 =	4.405629
511		.050000 x	724.827475 =	36.241374
630		.600000 x	2.102586 =	1.261552
625		1.000000 x	25.100230 =	25.100230
224		120.000000 x	.070000 =	8.400000

			B.T =	124.091089
652	652			
221		650.000000 x	.099900 =	64.935000
509		.011000 x	396.903470 =	4.365938
630		.320000 x	2.102586 =	.672828
625		1.000000 x	25.100230 =	25.100230
511		.050000 x	724.827475 =	36.241374
509		.001920 x	396.903470 =	.762055
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	164.345877
1121	1121			
112		.007000 x	17.312112 =	.121185
501		.000100 x	601.048352 =	.060105
503		.002000 x	893.029073 =	1.786058

			T.E =	1.967348
1122	1122			
112		.007000 x	17.312112 =	.121185
503		.000330 x	893.029073 =	.294700
501		.000080 x	601.048352 =	.048084
505		.000600 x	801.072457 =	.480643
507		.001400 x	914.566607 =	1.280393
509		.004447 x	396.903470 =	1.765030

			T.E =	3.990035

1123A	1123A			
112		.007000 x	17.312112 =	.121185
501		.000100 x	601.048352 =	.060105
503		.002000 x	893.029073 =	1.786058
509		.005312 x	396.903470 =	2.108351
506		.001330 x	669.126907 =	.889939

			T.E =	4.965638
1123B	1123B			
509		.001487 x	396.903470 =	.590195

			T.E =	.590195
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	417.590373 =	.083518
501		.000100 x	601.048352 =	.060105

			T.E =	.316744
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	3.990035 =	.798007
507		.000200 x	914.566607 =	.182913
501		.000100 x	601.048352 =	.060105
502		.000200 x	783.597773 =	.156720

			T.E =	1.984825
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	3.990035 =	3.990035
501		.002000 x	601.048352 =	1.202097

			T.E =	9.520160
1710	1710			
360		1.000000 x	11.000000 =	11.000000
111		.250000 x	15.741598 =	3.935400
501		.000100 x	601.048352 =	.060105

			T.E =	14.995504
2111	2111			
112		.010000 x	17.312112 =	.173121
509		.005202 x	396.903470 =	2.064692
507		.001540 x	914.566607 =	1.408433
502		.002000 x	783.597773 =	1.567196
501		.000830 x	601.048352 =	.498870

			T.E =	5.712311

2112	2112			
213		.400000 x	1.949500 =	.779800
502		.002900 x	783.597773 =	2.272434
112		.250000 x	17.312112 =	4.328028
116		.250000 x	20.419486 =	5.104872
507		.002000 x	914.566607 =	1.829133
509		.004896 x	396.903470 =	1.943239
508		.004000 x	578.995432 =	2.315982

			T.E =	18.573487
2251	2251			
111		.600000 x	15.741598 =	9.444959
621		1.050000 x	19.767103 =	20.755458
112		.600000 x	17.312112 =	10.387267
509		.012432 x	396.903470 =	4.934304

			T.E =	45.521988
2252	2252			
111		1.400000 x	15.741598 =	22.038237
621		1.050000 x	19.767103 =	20.755458
113		1.400000 x	20.419486 =	28.587280
509		.012432 x	396.903470 =	4.934304

			T.E =	76.315280
2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	19.767103 =	20.755458
652		.020000 x	164.345877 =	3.286918
651		.250000 x	124.091089 =	31.022772
509		.012432 x	396.903470 =	4.934304
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

			T.E =	138.122986
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	164.345877 =	16.434588
621		.350000 x	19.767103 =	6.918486
509		.003788 x	396.903470 =	1.503470
113		1.500000 x	20.419486 =	30.629229

			T.E =	68.079051

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	21.392016 =	17.113613
630		.250000 x	2.102586 =	.525647
641		3.000000 x	7.536243 =	22.608729
625		.500000 x	25.100230 =	12.550115
511		.040000 x	724.827475 =	28.993099
509		.008880 x	396.903470 =	3.524503
509		.001500 x	396.903470 =	.595355
509		.005550 x	396.903470 =	2.202814
113		1.600000 x	20.419486 =	32.671178

			T.E =	174.992009
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	174.992009 =	.874960
652		.002000 x	164.345877 =	.328692
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.728085
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	164.345877 =	1.972151
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.586698
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	385.199470 =	1.444498

			T.E =	1.916746

5150	5150			
111		.030000 x	15.741598 =	.472248
550		.002500 x	385.199470 =	.962999

			T.E =	1.435247
5160	5160			
213		.400000 x	1.949500 =	.779800
111		.160000 x	15.741598 =	2.518656
508		.001500 x	578.995432 =	.868493

			T.E =	4.166949
5210	5210			
363		.100000 x	.580000 =	.058000
112		.050000 x	17.312112 =	.865606
111		.040000 x	15.741598 =	.629664

			T.E =	1.553270
5220	5220			
363		.100000 x	.580000 =	.058000
112		.030000 x	17.312112 =	.519363
111		.020000 x	15.741598 =	.314832

			T.E =	.892195
5230	5230			
364		1.000000 x	3.520000 =	3.520000
112		.080000 x	17.312112 =	1.384969

			T.E =	4.904969
5240	5240			
112		.080000 x	17.312112 =	1.384969

			T.E =	1.384969
5311	5311			
111		.002000 x	15.741598 =	.031483
630.1		.020000 x	2.320239 =	.046405
510		.000250 x	386.706470 =	.096677
630		.020000 x	2.102586 =	.042052

			T.E =	.216616

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.320239 =	.046405
510		.000163 x	386.706470 =	.063033
630		.020000 x	2.102586 =	.042052

			T.E =	.171954
5321	5321			
111		.004000 x	15.741598 =	.062966

			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947

			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463

			T.E =	.349463
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	15.741598 =	.051947

			T.E =	.109947
5351	5351			
113		.005000 x	20.419486 =	.102097

			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873

			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390

			T.E =	.565806

5354	5354			
111		.035000 x	15.741598 =	.550956
113		.025000 x	20.419486 =	.510487

			T.E =	1.061443
5361A	5361A			
365		.003000 x	23.000000 =	.069000
630		.000300 x	2.102586 =	.000631
510		.000188 x	386.706470 =	.072701
113		.001500 x	20.419486 =	.030629

			T.E =	.172961
5361B	5361B			
366		.003000 x	21.150000 =	.063450
113		.001500 x	20.419486 =	.030629
510		.000188 x	386.706470 =	.072701
630		.000300 x	2.102586 =	.000631

			T.E =	.167411
5362A	5362A			
365		.005000 x	23.000000 =	.115000
113		.002500 x	20.419486 =	.051049
630		.000500 x	2.102586 =	.001051
510		.000313 x	386.706470 =	.121039

			T.E =	.288139
5362B	5362B			
366		.005000 x	21.150000 =	.105750
113		.002500 x	20.419486 =	.051049
630		.000500 x	2.102586 =	.001051
510		.000313 x	386.706470 =	.121039

			T.E =	.278889
5363A	5363A			
365		.003000 x	23.000000 =	.069000
630		.000300 x	2.102586 =	.000631
510		.000125 x	386.706470 =	.048338
113		.001000 x	20.419486 =	.020419

			T.E =	.138389

5363B	5363B			
366		.003000 x	21.150000 =	.063450
113		.001000 x	20.419486 =	.020419
510		.000125 x	386.706470 =	.048338
630		.000300 x	2.102586 =	.000631

			T.E =	.132839
5364A	5364A			
365		.005000 x	23.000000 =	.115000
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.102586 =	.001051
510		.000225 x	386.706470 =	.087009

			T.E =	.239815
5364B	5364B			
366		.005000 x	21.150000 =	.105750
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.102586 =	.001051
510		.000225 x	386.706470 =	.087009

			T.E =	.230565
5371	5371			
111		17.300000 x	15.741598 =	272.329645
111		9.600000 x	15.741598 =	151.119341

			T.E =	423.448986
5372	5372			
379		2.000000 x	14.350000 =	28.700000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.102586 =	.210259
510		.100000 x	386.706470 =	38.670647

			T.E =	83.916494
5380	5380			
111		5.000000 x	15.741598 =	78.707990
550		.412500 x	385.199470 =	158.894781

			T.E =	237.602771
5390	5390			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240

5510	5510				
361		15.000000 x	28.200000 =	423.000000	
362		30.000000 x	3.600000 =	108.000000	
363		20.000000 x	.580000 =	11.600000	
550		.375000 x	385.199470 =	144.449801	
113		20.000000 x	20.419486 =	408.389720	
111		20.000000 x	15.741598 =	314.831960	
365		2.000000 x	23.000000 =	46.000000	

			T.E =	1,456.271481	
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630		10.000000 x	2.102586 =	21.025860	
630.1		10.000000 x	2.320239 =	23.202390	
510		.125000 x	386.706470 =	48.338309	

			T.E =	108.308157	
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

			T.E =	23.612397	
5530	5530				
453		.187500 x	88.120000 =	16.522500	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	48.005696	
5540	5540				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	47.224794	
5552	5552				
379		1.000000 x	14.350000 =	14.350000	
510		.050000 x	386.706470 =	19.335324	
630		.100000 x	2.102586 =	.210259	
113		.400000 x	20.419486 =	8.167794	

			T.E =	42.063377	

5560A	5560A			
365		1.000000 x	23.000000 =	23.000000
630		.100000 x	2.102586 =	.210259
510		.100000 x	386.706470 =	38.670647
113		.800000 x	20.419486 =	16.335589

			T.E =	78.216494
5560B	5560B			
366		1.000000 x	21.150000 =	21.150000
630		.100000 x	2.102586 =	.210259
510		.100000 x	386.706470 =	38.670647
113		.800000 x	20.419486 =	16.335589

			T.E =	76.366494
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248

			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248

			T.E =	.787080
5610	5610			
363		15.000000 x	.580000 =	8.700000
550		.125000 x	385.199470 =	48.149934
111		30.000000 x	15.741598 =	472.247940
367		20,000.000000 x	.121700 =	2,434.000000

			T.E =	2,963.097874
5621	5621			
111		1.000000 x	15.741598 =	15.741598
510		.125000 x	386.706470 =	48.338309
630.1		10.000000 x	2.320239 =	23.202390
630		10.000000 x	2.102586 =	21.025860

			T.E =	108.308157
5622	5622			
111		1.500000 x	15.741598 =	23.612397

			T.E =	23.612397

5630	5630				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	
5640	5640				
111		10.000000 x	15.741598 =	157.415980	
111		2.000000 x	15.741598 =	31.483196	

			T.E =	188.899176	
5650	5650				
111		.120000 x	15.741598 =	1.888992	
111		.030000 x	15.741598 =	.472248	

			T.E =	2.361240	
5710	5710				
362		40.000000 x	3.600000 =	144.000000	
377		250.000000 x	3.270000 =	817.500000	
111		5.000000 x	15.741598 =	78.707990	
380		800.000000 x	.270000 =	216.000000	
114		1.000000 x	23.886192 =	23.886192	
510		.125000 x	386.706470 =	48.338309	
560		.125000 x	733.470470 =	91.683809	
509		.125000 x	396.903470 =	49.612934	
112		1.000000 x	17.312112 =	17.312112	
378		100.000000 x	.540000 =	54.000000	
363		15.000000 x	.580000 =	8.700000	

			T.E =	1,549.741345	
5720	5720				
111		.500000 x	15.741598 =	7.870799	
510		.062500 x	386.706470 =	24.169154	
630		10.000000 x	2.102586 =	21.025860	
630.1		10.000000 x	2.320239 =	23.202390	

			T.E =	76.268203	
5730	5730				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	