

ΑΤΗΕ

Αναλυτικά Τιμολόγια Ηλεκτρομηχανολογικών Έργων

1ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	Κατχ Τιμή X 1.8117/ 6.46	15.951934
002	Κατχ Τιμή X 1.8117/ 6.46	17.729980
003	Κατχ Τιμή X 1.8117/ 6.46	23.479183
026		.097700
036		.128500
273		.936500
297.1		1.500000
510		3.020000
511		.620000
513		1.100000
561		1.650000
565.3		3.060000
566.3		4.090000
567.13		18.120000
571.5.1		1.210000
572.1.7		3.860000
575.3		
581.2		8.750000
582.2		21.370000
588.3		
603.3		4.890000
605.3.5		136.000000
619.2.2		39.000000
620.1		67.800000
621.1		60.000000
630.1.2		280.000000
634.1.1		85.000000
647.2		17.400000
660.1.1		20.340000
667		139.000000
671.3.8		3,820.000000
672.4.6		4,650.000000
673.1.5		4,870.000000
684.6.2		106.000000
686.1		410.000000
687.1.1		2,300.000000
703.2.2		23.660000
714.2.6		5,140.000000
715.2.9		5,098.000000
718.3.3		1,040.000000
719.1.3		1,000.000000
720.11		7.000000
729.1.2		820.000000
730.2.5		1.850000
732.5.30		66.000000
744.9		56,210.000000
755.10		10,660.000000
757.1.4		14,035.000000
760.1.4		3,725.000000
801.3.2		.172000
801.7.1		1.570000
812.1.2		.088400
812.2.3		.951100
813.2.3		1.445300
816.3.2		.510500
820.5.1		.448400
820.5.4		1.513200
825.6.1		.457100
826.2.1		1.580000

835.1.2	66.200000
841.3.5	180.000000
842.3.2	76.000000
848.1.2	32.000000
852.1.6	930.000000
855.1.13	2,633.000000
858.1.2	2.910000
859.1.2	4.480000
865.13.10	16,400.000000
865.13.9	14,200.000000
865.8.3	37.500000
867.1.22	75,800.000000
871.7.4	47.160000
872.23.1	4.070000
880.1.2	.690000
885.1.2	17.500000
890.1.1	105.000000
910.2.5	7,030.000000
911.1.17	3,290.000000
912.1.5	3,059.000000
913.1.9	64.800000
914.1.8	114.000000
915.1.6	300.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	6,880.000000
918.1.1	1,894.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,100.000000
931.1.5	345.000000
931.2.4	895.000000
932.4.2	348.000000
933.1.1	13.610000
934.1.1	313.000000
935.1.1	71.000000
950.1.1	3.560000
951.1.7	600.000000
951.2.2	12,340.000000
952.1.4	335.000000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.097700 =	.107470	
297.1		1.200000 x	1.500000 =	1.800000	
582.2		1.300000 x	21.370000 =	27.781000	
002		1.300000 x	17.729980 =	23.048974	
003		1.300000 x	23.479183 =	30.522938	

			T.E =	83.260382	
10	10				
581.2		1.200000 x	8.750000 =	10.500000	
003		.300000 x	23.479183 =	7.043755	
001		.300000 x	15.951934 =	4.785580	

			T.E =	22.329335	
100	100				
931.1.5		1.000000 x	345.000000 =	345.000000	
003		4.000000 x	23.479183 =	93.916732	
002		6.000000 x	17.729980 =	106.379880	

			T.E =	545.296612	
101	101				
931.2.4		1.000000 x	895.000000 =	895.000000	
002		9.000000 x	17.729980 =	159.569820	
003		6.000000 x	23.479183 =	140.875098	

			T.E =	1,195.444918	
102	102				
820.5.4		1.020000 x	1.513200 =	1.543464	
002		.200000 x	17.729980 =	3.545996	
003		.200000 x	23.479183 =	4.695837	

			T.E =	9.785297	
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	17.729980 =	44.324950	
003		2.500000 x	23.479183 =	58.697958	

			T.E =	451.022908	
104	104				
933.1.1		1.000000 x	13.610000 =	13.610000	
003		1.200000 x	23.479183 =	28.175020	
002		1.200000 x	17.729980 =	21.275976	

			T.E =	63.060996	

105	105				
934.1.1		1.000000 x	313.000000 =	313.000000	
002		2.000000 x	17.729980 =	35.459960	
003		2.000000 x	23.479183 =	46.958366	

			T.E =	395.418326	
106	106				
951.1.7		1.030000 x	600.000000 =	618.000000	
002		4.000000 x	17.729980 =	70.919920	
003		4.000000 x	23.479183 =	93.916732	

			T.E =	782.836652	
107	107				
952.1.4		1.030000 x	335.000000 =	345.050000	
002		1.000000 x	17.729980 =	17.729980	
003		1.000000 x	23.479183 =	23.479183	

			T.E =	386.259163	
108	108				
951.2.2		1.030000 x	12,340.000000 =	12,710.200000	
003		6.000000 x	23.479183 =	140.875098	
002		6.000000 x	17.729980 =	106.379880	

			T.E =	12,957.454978	
109	109				
953.1.3		1.030000 x	26,500.000000 =	27,295.000000	
003		12.000000 x	23.479183 =	281.750196	
002		12.000000 x	17.729980 =	212.759760	

			T.E =	27,789.509956	
11	11				
603.3		1.030000 x	4.890000 =	5.036700	
003		.500000 x	23.479183 =	11.739592	

			T.E =	16.776292	
110	110				
950.1.1		1.050000 x	3.560000 =	3.738000	
002		.200000 x	17.729980 =	3.545996	
003		.200000 x	23.479183 =	4.695837	

			T.E =	11.979833	

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	17.729980 =	10.637988	
003		.600000 x	23.479183 =	14.087510	

			T.E =	167.525498	
13	13				
619.2.2		1.030000 x	39.000000 =	40.170000	
002		.400000 x	17.729980 =	7.091992	
003		.400000 x	23.479183 =	9.391673	

			T.E =	56.653665	
14	14				
026		15.000000 x	.097700 =	1.465500	
620.1		1.000000 x	67.800000 =	67.800000	
003		2.000000 x	23.479183 =	46.958366	
002		2.000000 x	17.729980 =	35.459960	

			T.E =	151.683826	
15	15				
621.1		1.000000 x	60.000000 =	60.000000	
003		2.000000 x	23.479183 =	46.958366	
002		2.000000 x	17.729980 =	35.459960	
621.1		.100000 x	60.000000 =	6.000000	

			T.E =	148.418326	
16	16				
630.1.2		1.000000 x	280.000000 =	280.000000	
003		3.000000 x	23.479183 =	70.437549	
002		3.000000 x	17.729980 =	53.189940	
630.1.2		.050000 x	280.000000 =	14.000000	

			T.E =	417.627489	
17	17				
634.1.1		1.200000 x	85.000000 =	102.000000	
003		2.000000 x	23.479183 =	46.958366	
002		.200000 x	17.729980 =	3.545996	
634.1.1		.050000 x	85.000000 =	4.250000	

			T.E =	156.754362	
18	18				
647.2		1.000000 x	17.400000 =	17.400000	
003		.200000 x	23.479183 =	4.695837	

			T.E =	22.095837	

19	19				
660.1.1		1.030000 x	20.340000 =	20.950200	
003		.200000 x	23.479183 =	4.695837	
002		.200000 x	17.729980 =	3.545996	

			T.E =	29.192033	
2	2				
561		5.320000 x	1.650000 =	8.778000	
003		.600000 x	23.479183 =	14.087510	
002		.600000 x	17.729980 =	10.637988	

			T.E =	33.503498	
20	20				
667		1.000000 x	139.000000 =	139.000000	
667		.020000 x	139.000000 =	2.780000	
003		4.000000 x	23.479183 =	93.916732	
002		4.000000 x	17.729980 =	70.919920	

			T.E =	306.616652	
21	21				
671.3.8		1.000000 x	3,820.000000 =	3,820.000000	
671.3.8		.100000 x	3,820.000000 =	382.000000	
002		20.000000 x	17.729980 =	354.599600	
003		20.000000 x	23.479183 =	469.583660	

			T.E =	5,026.183260	
22	22				
672.4.6		1.000000 x	4,650.000000 =	4,650.000000	
672.4.6		.100000 x	4,650.000000 =	465.000000	
003		20.000000 x	23.479183 =	469.583660	
002		20.000000 x	17.729980 =	354.599600	

			T.E =	5,939.183260	
23	23				
673.1.5		1.000000 x	4,870.000000 =	4,870.000000	
003		25.000000 x	23.479183 =	586.979575	
002		25.000000 x	17.729980 =	443.249500	
687.1.1		1.000000 x	2,300.000000 =	2,300.000000	
687.1.1		.020000 x	2,300.000000 =	46.000000	
673.1.5		.020000 x	4,870.000000 =	97.400000	

			T.E =	8,343.629075	

24	24				
684.6.2		1.000000 x	106.000000 =	106.000000	
003		1.000000 x	23.479183 =	23.479183	
684.6.2		.020000 x	106.000000 =	2.120000	
002		1.000000 x	17.729980 =	17.729980	

			T.E =	149.329163	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	23.479183 =	93.916732	
002		4.000000 x	17.729980 =	70.919920	
686.1		.020000 x	410.000000 =	8.200000	

			T.E =	583.036652	
26	26				
703.2.2		1.020000 x	23.660000 =	24.133200	
003		.250000 x	23.479183 =	5.869796	
002		.250000 x	17.729980 =	4.432495	

			T.E =	34.435491	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	23.479183 =	234.791830	
002		10.000000 x	17.729980 =	177.299800	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.951934 =	79.759670	

			T.E =	5,734.651300	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	23.479183 =	281.750196	
002		12.000000 x	17.729980 =	212.759760	
001		6.000000 x	15.951934 =	95.711604	
715.2.9		.020000 x	5,098.000000 =	101.960000	

			T.E =	5,790.181560	
29	29				
718.3.3		1.000000 x	1,040.000000 =	1,040.000000	
002		8.000000 x	17.729980 =	141.839840	
718.3.3		.050000 x	1,040.000000 =	52.000000	
003		8.000000 x	23.479183 =	187.833464	

			T.E =	1,421.673304	

3	3			
026		1.200000 x	.097700 =	.117240
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976

T.E =

30	30			
719.1.3		1.000000 x	1,000.000000 =	1,000.000000
719.1.3		.100000 x	1,000.000000 =	100.000000
003		16.000000 x	23.479183 =	375.666928
002		16.000000 x	17.729980 =	283.679680
001		8.000000 x	15.951934 =	127.615472

T.E = 1,886.962080

31	31			
720.11		1.020000 x	7.000000 =	7.140000
003		.300000 x	23.479183 =	7.043755

T.E = 14.183755

32	32			
729.1.2		1.000000 x	820.000000 =	820.000000
002		2.000000 x	17.729980 =	35.459960
003		2.000000 x	23.479183 =	46.958366
729.1.2		.030000 x	820.000000 =	24.600000

T.E = 927.018326

33	33			
757.1.4		1.000000 x	14,035.000000 =	14,035.000000
757.1.4		.050000 x	14,035.000000 =	701.750000
002		15.000000 x	17.729980 =	265.949700
003		15.000000 x	23.479183 =	352.187745
001		7.000000 x	15.951934 =	111.663538

T.E = 15,466.550983

34	34			
273		1.000000 x	.936500 =	.936500
003		.300000 x	23.479183 =	7.043755
002		.300000 x	17.729980 =	5.318994
273		.100000 x	.936500 =	.093650

T.E = 13.392899

35	35				
730.2.5		1.050000 x	1.850000 =	1.942500	
003		.120000 x	23.479183 =	2.817502	
002		.120000 x	17.729980 =	2.127598	
730.2.5		.250000 x	1.850000 =	.462500	

			T.E =	7.350100	
36	36				
732.5.30		1.050000 x	66.000000 =	69.300000	
003		.400000 x	23.479183 =	9.391673	
002		.400000 x	17.729980 =	7.091992	

			T.E =	85.783665	
37	37				
744.9		1.000000 x	56,210.000000 =	56,210.000000	
744.9		.020000 x	56,210.000000 =	1,124.200000	
001		10.000000 x	15.951934 =	159.519340	
002		20.000000 x	17.729980 =	354.599600	
003		20.000000 x	23.479183 =	469.583660	

			T.E =	58,317.902600	
38	38				
755.10		1.000000 x	10,660.000000 =	10,660.000000	
755.10		.020000 x	10,660.000000 =	213.200000	
001		10.000000 x	15.951934 =	159.519340	
002		10.000000 x	17.729980 =	177.299800	
003		10.000000 x	23.479183 =	234.791830	

			T.E =	11,444.810970	
39	39				
760.1.4		1.000000 x	3,725.000000 =	3,725.000000	
760.1.4		.050000 x	3,725.000000 =	186.250000	
002		3.500000 x	17.729980 =	62.054930	
003		3.500000 x	23.479183 =	82.177141	

			T.E =	4,055.482071	
4	4				
565.3		1.250000 x	3.060000 =	3.825000	
002		.600000 x	17.729980 =	10.637988	
003		.600000 x	23.479183 =	14.087510	

			T.E =	28.550498	

40	40				
036		3.000000 x	.128500 =		.385500
003		.450000 x	23.479183 =		10.565632
002		.450000 x	17.729980 =		7.978491
510		.350000 x	3.020000 =		1.057000
511		.250000 x	.620000 =		.155000
513		.250000 x	1.100000 =		.275000

			T.E =		20.416623
41	41				
801.3.2		1.050000 x	.172000 =		.180600
003		.100000 x	23.479183 =		2.347918
801.3.2		.105000 x	.172000 =		.018060
002		.100000 x	17.729980 =		1.772998

			T.E =		4.319576
42	42				
801.7.1		1.050000 x	1.570000 =		1.648500
003		.200000 x	23.479183 =		4.695837
002		.200000 x	17.729980 =		3.545996
801.7.1		.210000 x	1.570000 =		.329700

			T.E =		10.220033
43	43				
812.1.2		1.050000 x	.088400 =		.092820
003		.020000 x	23.479183 =		.469584
002		.020000 x	17.729980 =		.354600

			T.E =		.917003
44	44				
812.2.3		1.050000 x	.951100 =		.998655
003		.060000 x	23.479183 =		1.408751
002		.060000 x	17.729980 =		1.063799

			T.E =		3.471205
45	45				
813.2.3		1.050000 x	1.445300 =		1.517565
813.2.3		.105000 x	1.445300 =		.151757
003		.050000 x	23.479183 =		1.173959
002		.050000 x	17.729980 =		.886499

			T.E =		3.729780

46	46				
816.3.2		1.050000 x	.510500 =	.536025	
816.3.2		.157500 x	.510500 =	.080404	
002		.120000 x	17.729980 =	2.127598	
003		.120000 x	23.479183 =	2.817502	

			T.E =	5.561528	
47	47				
820.5.1		1.050000 x	.448400 =	.470820	
820.5.1		.157500 x	.448400 =	.070623	
003		.140000 x	23.479183 =	3.287086	
002		.140000 x	17.729980 =	2.482197	

			T.E =	6.310726	
48	48				
825.6.1		1.050000 x	.457100 =	.479955	
003		.100000 x	23.479183 =	2.347918	
002		.100000 x	17.729980 =	1.772998	
825.6.1		.157500 x	.457100 =	.071993	

			T.E =	4.672865	
49	49				
826.2.1		1.000000 x	1.580000 =	1.580000	
003		.200000 x	23.479183 =	4.695837	

			T.E =	6.275837	
5	5				
566.3		1.250000 x	4.090000 =	5.112500	
002		.600000 x	17.729980 =	10.637988	
003		.600000 x	23.479183 =	14.087510	

			T.E =	29.837998	
50	50				
842.3.2		1.000000 x	76.000000 =	76.000000	
842.3.2		.030000 x	76.000000 =	2.280000	
002		.500000 x	17.729980 =	8.864990	
003		.500000 x	23.479183 =	11.739592	

			T.E =	98.884582	
51	51				
841.3.5		1.000000 x	180.000000 =	180.000000	
841.3.5		.030000 x	180.000000 =	5.400000	
003		1.000000 x	23.479183 =	23.479183	
002		1.000000 x	17.729980 =	17.729980	

			T.E =	226.609163	

52	52				
835.1.2		1.050000 x	66.200000 =	69.510000	
003		3.000000 x	23.479183 =	70.437549	
002		3.000000 x	17.729980 =	53.189940	

			T.E =	193.137489	
53	53				
848.1.2		1.020000 x	32.000000 =	32.640000	
003		.200000 x	23.479183 =	4.695837	

			T.E =	37.335837	
54	54				
858.1.2		1.020000 x	2.910000 =	2.968200	
003		.200000 x	23.479183 =	4.695837	

			T.E =	7.664037	
55	55				
859.1.2		1.020000 x	4.480000 =	4.569600	
003		.200000 x	23.479183 =	4.695837	

			T.E =	9.265437	
56	56				
865.8.3		1.050000 x	37.500000 =	39.375000	
003		2.000000 x	23.479183 =	46.958366	
002		2.000000 x	17.729980 =	35.459960	

			T.E =	121.793326	
57	57				
865.13.9		1.020000 x	14,200.000000 =	14,484.000000	
002		25.000000 x	17.729980 =	443.249500	
003		25.000000 x	23.479183 =	586.979575	
001		10.000000 x	15.951934 =	159.519340	

			T.E =	15,673.748415	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
002		130.000000 x	17.729980 =	2,304.897400	
003		130.000000 x	23.479183 =	3,052.293790	
001		130.000000 x	15.951934 =	2,073.751420	

			T.E =	85,504.942610	

59	59				
871.7.4		1.000000 x	47.160000 =	47.160000	
003		1.200000 x	23.479183 =	28.175020	
002		1.200000 x	17.729980 =	21.275976	
871.7.4		.020000 x	47.160000 =	.943200	

			T.E =	97.554196	
6	6				
567.13		1.300000 x	18.120000 =	23.556000	
003		1.000000 x	23.479183 =	23.479183	
002		1.000000 x	17.729980 =	17.729980	

			T.E =	64.765163	
60	60				
872.23.1		1.020000 x	4.070000 =	4.151400	
003		.600000 x	23.479183 =	14.087510	
002		.600000 x	17.729980 =	10.637988	
880.1.2		1.000000 x	.690000 =	.690000	

			T.E =	29.566898	
61	61				
885.1.2		1.000000 x	17.500000 =	17.500000	
002		.600000 x	17.729980 =	10.637988	
003		.600000 x	23.479183 =	14.087510	

			T.E =	42.225498	
62	62				
890.1.1		1.000000 x	105.000000 =	105.000000	
890.1.1		.050000 x	105.000000 =	5.250000	
002		2.000000 x	17.729980 =	35.459960	
003		2.000000 x	23.479183 =	46.958366	

			T.E =	192.668326	
63	63				
910.2.5		1.000000 x	7,030.000000 =	7,030.000000	
002		50.000000 x	17.729980 =	886.499000	
001		30.000000 x	15.951934 =	478.558020	
003		50.000000 x	23.479183 =	1,173.959150	
910.2.5		.020000 x	7,030.000000 =	140.600000	

			T.E =	9,709.616170	

7	7				
571.5.1		1.400000 x	1.210000 =	1.694000	
003		.300000 x	23.479183 =	7.043755	
002		.300000 x	17.729980 =	5.318994	

			T.E =	14.056749	
8	8				
572.1.7		1.350000 x	3.860000 =	5.211000	
002		.700000 x	17.729980 =	12.410986	
003		.700000 x	23.479183 =	16.435428	

			T.E =	34.057414	
80	80				
911.1.17		1.050000 x	3,290.000000 =	3,454.500000	
002		30.000000 x	17.729980 =	531.899400	
003		30.000000 x	23.479183 =	704.375490	

			T.E =	4,690.774890	
81	81				
912.1.5		1.050000 x	3,059.000000 =	3,211.950000	
002		30.000000 x	17.729980 =	531.899400	
003		30.000000 x	23.479183 =	704.375490	

			T.E =	4,448.224890	
82	82				
913.1.9		1.200000 x	64.800000 =	77.760000	
003		4.000000 x	23.479183 =	93.916732	
002		4.000000 x	17.729980 =	70.919920	

			T.E =	242.596652	
83	83				
914.1.8		1.100000 x	114.000000 =	125.400000	
002		2.000000 x	17.729980 =	35.459960	
003		2.000000 x	23.479183 =	46.958366	

			T.E =	207.818326	
84	84				
915.1.6		1.050000 x	300.000000 =	315.000000	
002		8.000000 x	17.729980 =	141.839840	
003		8.000000 x	23.479183 =	187.833464	

			T.E =	644.673304	

85	85				
915.3.10		1.050000 x	13,101.000000 =	13,756.050000	
002		20.000000 x	17.729980 =	354.599600	
003		20.000000 x	23.479183 =	469.583660	

			T.E =	14,580.233260	
86	86				
865.13.10		1.020000 x	16,400.000000 =	16,728.000000	
003		40.000000 x	23.479183 =	939.167320	
002		40.000000 x	17.729980 =	709.199200	

			T.E =	18,376.366520	
87	87				
916.1.3		1.030000 x	.000000 =	.000000	
916.3.3		1.010000 x	.000000 =	.000000	
916.2.3		1.020000 x	.000000 =	.000000	
003		120.000000 x	23.479183 =	2,817.501960	
002		120.000000 x	17.729980 =	2,127.597600	

			T.E =		
88	88				
917.1		.030000 x	6,880.000000 =	206.400000	
917.1		1.000000 x	6,880.000000 =	6,880.000000	
918.1.1		.030000 x	1,894.000000 =	56.820000	
920.1.1		1.000000 x	7,479.000000 =	7,479.000000	
923.1.1		1.000000 x	61.620000 =	61.620000	
003		40.000000 x	23.479183 =	939.167320	
002		40.000000 x	17.729980 =	709.199200	
923.2.1		1.000000 x	161.400000 =	161.400000	
923.2.1		.030000 x	161.400000 =	4.842000	
923.1.1		.030000 x	61.620000 =	1.848600	
920.1.1		.030000 x	7,479.000000 =	224.370000	
918.1.1		1.000000 x	1,894.000000 =	1,894.000000	

			T.E =	18,618.667120	
89	89				
852.1.6		.020000 x	930.000000 =	18.600000	
855.1.13		1.000000 x	2,633.000000 =	2,633.000000	
855.1.13		.020000 x	2,633.000000 =	52.660000	
925.1.1		1.000000 x	4,100.000000 =	4,100.000000	
003		60.000000 x	23.479183 =	1,408.750980	
002		60.000000 x	17.729980 =	1,063.798800	
925.1.1		.020000 x	4,100.000000 =	82.000000	
852.1.6		1.000000 x	930.000000 =	930.000000	

			T.E =	10,288.809780	

9 9

575.3	1.200000 x	.000000 =	.000000
003	.300000 x	23.479183 =	7.043755
002	.300000 x	17.729980 =	5.318994

 T.E =