

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

1ο Τρίμηνο του 2009

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	Κατχ Τιμή X 1.8117/ 6.46	15.951934
112	Κατχ Τιμή X 1.8117/ 6.46	17.729980
113	Κατχ Τιμή X 1.8117/ 6.46	23.479183
114	Κατχ Τιμή X 1.8117/ 6.46	17.729980
115	Κατχ Τιμή X 1.8117/ 6.46	22.893045
116	Κατχ Τιμή X 1.8117/ 6.67	22.739959
117	Κατχ Τιμή X 1.8117/ 6.67	17.283129
118	Κατχ Τιμή X 1.8117/ 6.67	18.893831
119	Κατχ Τιμή X 1.8117/ 6.67	17.171765
120	Κατχ Τιμή X 1.8117/ 6.67	18.893831
121	Κατχ Τιμή X 1.8117/ 6.67	16.481852
122	Κατχ Τιμή X 1.8117/ 6.67	17.345601
123	Κατχ Τιμή X 1.8117/ 4.00	59.183710
211		.802900
212		.786500
213		3.800000
214		1.875000
221		.097700
222		.070000
231		37.750000
232		39.820000
241		290.000000
242		335.000000
251		.536700
252		1.900000
253		3.500000
254		5.000000
255		.742000
256		3.300000
261		
262		.980000
263		.540000
311		421.470000
312		126.960000
313		199.000000
314		4.280000
315		52.110000
316		4.280000
317		118.980000
318		25.830000
319		20.840000
320		147.920000
321		201.360000
322		279.760000
323		318.580000
324		174.790000
325		299.380000
326		99.490000
327		4.280000
351		426.350000
352		361.980000
353		426.350000
354		559.360000
355		279.760000
356		45.910000
357		219.960000
358		44.290000
359		91.820000
360		96.700000



361	73.960000
362	255.980000
363	96.840000
380	481.920000
381	481.920000
382	481.920000
383	554.260000
384	918.010000
385	166.800000
386	440.110000
387	63.500000
388	63.500000
389	63.500000

401	401				
211		110.000000 x	.802900 =	88.319000	
117		4.000000 x	17.283129 =	69.132516	
116		8.000000 x	22.739959 =	181.919672	
213		10.000000 x	3.800000 =	38.000000	
311		1.000000 x	421.470000 =	421.470000	
			-----		
			ΑΘΡΟΙΣΜΑ =	798.841188	
			-----		
			Η.Δ. =	878.725307	
402	402				
211		180.000000 x	.802900 =	144.522000	
213		12.000000 x	3.800000 =	45.600000	
117		8.000000 x	17.283129 =	138.265032	
116		8.000000 x	22.739959 =	181.919672	
112		8.000000 x	17.729980 =	141.839840	
312		1.000000 x	126.960000 =	126.960000	
212		5.000000 x	.786500 =	3.932500	
			-----		
			ΑΘΡΟΙΣΜΑ =	783.039044	
			-----		
			Η.Δ. =	861.342948	
403	403				
211		80.000000 x	.802900 =	64.232000	
254		2.500000 x	5.000000 =	12.500000	
213		6.000000 x	3.800000 =	22.800000	
116		8.000000 x	22.739959 =	181.919672	
117		8.000000 x	17.283129 =	138.265032	
313		1.000000 x	199.000000 =	199.000000	
			-----		
			ΑΘΡΟΙΣΜΑ =	618.716704	
			-----		
			Η.Δ. =	680.588374	
404	404				
211		80.000000 x	.802900 =	64.232000	
212		2.000000 x	.786500 =	1.573000	
118		8.000000 x	18.893831 =	151.150648	
119		4.000000 x	17.171765 =	68.687060	
314		1.000000 x	4.280000 =	4.280000	
112		4.000000 x	17.729980 =	70.919920	
213		5.000000 x	3.800000 =	19.000000	
			-----		
			ΑΘΡΟΙΣΜΑ =	379.842628	
			-----		
			Η.Δ. =	417.826891	

405	405				
211		40.000000 x	.802900 =		32.116000
213		2.000000 x	3.800000 =		7.600000
118		4.000000 x	18.893831 =		75.575324
115		16.000000 x	22.893045 =		366.288720
316		2.000000 x	4.280000 =		8.560000
315		1.000000 x	52.110000 =		52.110000
				ΑΘΡΟΙΣΜΑ =	542.250044
				Η.Δ. =	596.475048
406	406				
211		80.000000 x	.802900 =		64.232000
213		5.000000 x	3.800000 =		19.000000
317		1.000000 x	118.980000 =		118.980000
120		8.000000 x	18.893831 =		151.150648
				ΑΘΡΟΙΣΜΑ =	353.362648
				Η.Δ. =	388.698913
407	407				
212		17.000000 x	.786500 =		13.370500
112		30.000000 x	17.729980 =		531.899400
118		4.000000 x	18.893831 =		75.575324
213		1.000000 x	3.800000 =		3.800000
318		1.000000 x	25.830000 =		25.830000
				ΑΘΡΟΙΣΜΑ =	650.475224
				Η.Δ. =	715.522746
408	408				
211		30.000000 x	.802900 =		24.087000
320		1.000000 x	147.920000 =		147.920000
117		4.000000 x	17.283129 =		69.132516
116		8.000000 x	22.739959 =		181.919672
112		4.000000 x	17.729980 =		70.919920
213		3.000000 x	3.800000 =		11.400000
				ΑΘΡΟΙΣΜΑ =	505.379108
				Η.Δ. =	555.917019
409	409				
211		50.000000 x	.802900 =		40.145000
213		5.000000 x	3.800000 =		19.000000
117		4.000000 x	17.283129 =		69.132516
116		8.000000 x	22.739959 =		181.919672
112		4.000000 x	17.729980 =		70.919920
324		1.000000 x	174.790000 =		174.790000
				ΑΘΡΟΙΣΜΑ =	555.907108
				Η.Δ. =	611.497819

410	410				
211		100.000000 x	.802900 =	80.290000	
213		10.000000 x	3.800000 =	38.000000	
321		1.000000 x	201.360000 =	201.360000	
116		8.000000 x	22.739959 =	181.919672	
117		4.000000 x	17.283129 =	69.132516	
112		4.000000 x	17.729980 =	70.919920	
				-----	
				ΑΘΡΟΙΣΜΑ =	641.622108
				-----	
				Η.Δ. =	705.784319
411	411				
211		200.000000 x	.802900 =	160.580000	
325		1.000000 x	299.380000 =	299.380000	
117		4.000000 x	17.283129 =	69.132516	
116		8.000000 x	22.739959 =	181.919672	
112		4.000000 x	17.729980 =	70.919920	
213		20.000000 x	3.800000 =	76.000000	
				-----	
				ΑΘΡΟΙΣΜΑ =	857.932108
				-----	
				Η.Δ. =	943.725319
412	412				
211		40.000000 x	.802900 =	32.116000	
116		8.000000 x	22.739959 =	181.919672	
326		1.000000 x	99.490000 =	99.490000	
213		2.000000 x	3.800000 =	7.600000	
				-----	
				ΑΘΡΟΙΣΜΑ =	321.125672
				-----	
				Η.Δ. =	353.238239
413	413				
211		15.000000 x	.802900 =	12.043500	
213		1.500000 x	3.800000 =	5.700000	
118		3.000000 x	18.893831 =	56.681493	
112		3.000000 x	17.729980 =	53.189940	
327		1.000000 x	4.280000 =	4.280000	
				-----	
				ΑΘΡΟΙΣΜΑ =	131.894933
				-----	
				Η.Δ. =	145.084426
501	501				
211		170.000000 x	.802900 =	136.493000	
213		3.000000 x	3.800000 =	11.400000	
351		1.000000 x	426.350000 =	426.350000	
380		1.000000 x	481.920000 =	481.920000	
				-----	
				ΑΘΡΟΙΣΜΑ =	1,056.163000
				-----	
				Η.Δ. =	1,161.779300

502	502				
211		170.000000 x	.802900 =	136.493000	
213		3.000000 x	3.800000 =	11.400000	
381		1.000000 x	481.920000 =	481.920000	
352		1.000000 x	361.980000 =	361.980000	
		-----			
			ΑΘΡΟΙΣΜΑ =	991.793000	
		-----			
			Η.Δ. =	1,090.972300	
503	503				
211		170.000000 x	.802900 =	136.493000	
382		1.000000 x	481.920000 =	481.920000	
353		1.000000 x	426.350000 =	426.350000	
213		3.000000 x	3.800000 =	11.400000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,056.163000	
		-----			
			Η.Δ. =	1,161.779300	
504	504				
211		190.000000 x	.802900 =	152.551000	
213		6.000000 x	3.800000 =	22.800000	
354		1.000000 x	559.360000 =	559.360000	
383		1.000000 x	554.260000 =	554.260000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,288.971000	
		-----			
			Η.Δ. =	1,417.868100	
505	505				
211		1,250.000000 x	.802900 =	1,003.625000	
213		7.500000 x	3.800000 =	28.500000	
384		1.000000 x	918.010000 =	918.010000	
355		1.000000 x	279.760000 =	279.760000	
		-----			
			ΑΘΡΟΙΣΜΑ =	2,229.895000	
		-----			
			Η.Δ. =	2,452.884500	
506	506				
211		200.000000 x	.802900 =	160.580000	
213		2.000000 x	3.800000 =	7.600000	
385		1.000000 x	166.800000 =	166.800000	
356		1.000000 x	45.910000 =	45.910000	
		-----			
			ΑΘΡΟΙΣΜΑ =	380.890000	
		-----			
			Η.Δ. =	418.979000	
507	507				
211		2,100.000000 x	.802900 =	1,686.090000	
386		1.000000 x	440.110000 =	440.110000	
357		1.000000 x	219.960000 =	219.960000	
213		35.000000 x	3.800000 =	133.000000	
		-----			
			ΑΘΡΟΙΣΜΑ =	2,479.160000	
		-----			
			Η.Δ. =	2,677.492800	



508	508				
358		1.000000 x	44.290000 =		44.290000
387		1.000000 x	63.500000 =		63.500000
				ΑΘΡΟΙΣΜΑ =	107.790000
				Η.Δ. =	113.179500
509	509				
359		1.000000 x	91.820000 =		91.820000
388		1.000000 x	63.500000 =		63.500000
				ΑΘΡΟΙΣΜΑ =	155.320000
				Η.Δ. =	163.086000
510	510				
360		1.000000 x	96.700000 =		96.700000
389		1.000000 x	63.500000 =		63.500000
				ΑΘΡΟΙΣΜΑ =	160.200000
				Η.Δ. =	168.210000
511	511				
509		.800000 x	163.086000 =		130.468800
				Η.Δ. =	130.468800
512	512				
501		.600000 x	1,161.779300 =		697.067580
				Η.Δ. =	697.067580
513	513				
363		1.000000 x	96.840000 =		96.840000
123		8.000000 x	59.183710 =		473.469680
122		8.000000 x	17.345601 =		138.764808
121		8.000000 x	16.481852 =		131.854816
				Η.Δ. =	840.929304
1111A	1111A				
214		.200000 x	1.875000 =		.375000
511		.020000 x	130.468800 =		2.609376
405		.020000 x	596.475048 =		11.929501
513		.020000 x	840.929304 =		16.818586
				Β.Τ =	31.732463

1111B	1111B			
501		1.000000 x	1,161.779300 =	1,161.779300
506		1.000000 x	418.979000 =	418.979000
509		2.000000 x	163.086000 =	326.172000
			-----	
			ΑΘΡΟΙΣΜΑ =	1,906.930300
	B.T =	.002500 x	1,906.930300 =	4.767326
			-----	
1112A	1112A			
506		1.000000 x	418.979000 =	418.979000
512		1.000000 x	697.067580 =	697.067580
			-----	
			ΑΘΡΟΙΣΜΑ =	1,116.046580
	B.T =	.025000 x	1,116.046580 =	27.901165
			-----	
1112B	1112B			
1111B		1.000000 x	4.767326 =	4.767326
			-----	
			B.T =	4.767326
1113A	1113A			
214		.200000 x	1.875000 =	.375000
112		.250000 x	17.729980 =	4.432495
511		.035000 x	130.468800 =	4.566408
513		.035000 x	840.929304 =	29.432526
405		.025000 x	596.475048 =	14.911876
			-----	
			B.T =	53.718305
1113B	1113B			
1111B		1.000000 x	4.767326 =	4.767326
			-----	
			B.T =	4.767326
1114A	1114A			
112		.250000 x	17.729980 =	4.432495
506		.033000 x	418.979000 =	13.826307
512		.033000 x	697.067580 =	23.003230
			-----	
			B.T =	41.262032
1114B	1114B			
1111B		1.000000 x	4.767326 =	4.767326
			-----	
			B.T =	4.767326

1121A	1121A			
214		.150000 x	1.875000 =	.281250
115		.500000 x	22.893045 =	11.446523
405		.020000 x	596.475048 =	11.929501
		-----		
			B.T =	23.657273
1121B	1121B			
1111B		1.000000 x	4.767326 =	4.767326
		-----		
			B.T =	4.767326
1122A	1122A			
506		1.000000 x	418.979000 =	418.979000
512		1.000000 x	697.067580 =	697.067580
		-----		
			AΘΡΟΙΣΜΑ =	1,116.046580
	B.T =	.012500 x	1,116.046580 =	13.950582
		-----		
1122B	1122B			
1111B		1.000000 x	4.767326 =	4.767326
		-----		
			B.T =	4.767326
1123A	1123A			
214		.150000 x	1.875000 =	.281250
112		.150000 x	17.729980 =	2.659497
405		.025000 x	596.475048 =	14.911876
115		1.000000 x	22.893045 =	22.893045
		-----		
			B.T =	40.745668
1123B	1123B			
1111B		1.000000 x	4.767326 =	4.767326
		-----		
			B.T =	4.767326
1124A	1124A			
112		.150000 x	17.729980 =	2.659497
506		.020000 x	418.979000 =	8.379580
512		.020000 x	697.067580 =	13.941352
		-----		
			B.T =	24.980429
1124B	1124B			
1111B		1.000000 x	4.767326 =	4.767326
		-----		
			B.T =	4.767326

3110A 1	3110A 1			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.876372 =	.719093
701 2		.800000 x	4.602195 =	3.681756
701 2		.500000 x	4.602195 =	2.301098
630		.250000 x	2.901689 =	.725422
607		.500000 x	9.786409 =	4.893205
606		.800000 x	8.933527 =	7.146822
407		.040000 x	715.522746 =	28.620910
714		1.400000 x	7.709601 =	10.793441
113		1.200000 x	23.479183 =	28.175020
112		1.200000 x	17.729980 =	21.275976
319		.020000 x	20.840000 =	.416800

-----  
B.T = 133.174542

3110A 2	3110A 2			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.876372 =	.719093
701 4		.500000 x	4.314558 =	2.157279
701 2		.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
319		.020000 x	20.840000 =	.416800
112		1.200000 x	17.729980 =	21.275976
407		.040000 x	715.522746 =	28.620910
611		.500000 x	25.548372 =	12.774186
606		.800000 x	8.933527 =	7.146822
714		1.400000 x	7.709601 =	10.793441
113		1.200000 x	23.479183 =	28.175020

-----  
B.T = 140.911705

3110A 3	3110A 3			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.876372 =	.719093
701 4		.800000 x	4.314558 =	3.451646
701 2		.500000 x	4.602195 =	2.301098
630		.250000 x	2.901689 =	.725422
610		.800000 x	21.844597 =	17.475678
607		.500000 x	9.786409 =	4.893205
407		.040000 x	715.522746 =	28.620910
714		1.400000 x	7.709601 =	10.793441
319		.020000 x	20.840000 =	.416800
113		1.200000 x	23.479183 =	28.175020
112		1.200000 x	17.729980 =	21.275976

-----  
B.T = 143.273288

3110A 4	3110A 4			
221		250.000000 x	.097700 =	24.425000
714		1.400000 x	7.709601 =	10.793441
319		.020000 x	20.840000 =	.416800
113		1.200000 x	23.479183 =	28.175020
701 5		.250000 x	2.876372 =	.719093
701 4		.800000 x	4.314558 =	3.451646
701 4		.500000 x	4.314558 =	2.157279
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
610		.800000 x	21.844597 =	17.475678
407		.040000 x	715.522746 =	28.620910
112		1.200000 x	17.729980 =	21.275976
			B.T =	151.010451
3110B	3110B			
713 1		1.000000 x	5.003340 =	5.003340
704		1.000000 x	10.006679 =	10.006679
			B.T =	15.010019
3120A 1	3120A 1			
3110A 1		1.000000 x	133.174542 =	133.174542
			B.T =	133.174542
3120A 2	3120A 2			
3110A 2		1.000000 x	140.911705 =	140.911705
			B.T =	140.911705
3120A 3	3120A 3			
3110A 3		1.000000 x	143.273288 =	143.273288
			B.T =	143.273288
3120A 4	3120A 4			
3110A 4		1.000000 x	151.010451 =	151.010451
			B.T =	151.010451
3120B	3120B			
713 2		1.000000 x	5.475977 =	5.475977
705		1.000000 x	10.951954 =	10.951954
			B.T =	16.427931

3210A 1	3210A 1			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.602195 =	1.472702
601		.320000 x	23.927901 =	7.656928
3110A 1		.800000 x	133.174542 =	106.539634
		-----		
			B.T =	122.050038
3210A 2	3210A 2			
111		.400000 x	15.951934 =	6.380774
3110A 2		.800000 x	140.911705 =	112.729364
701 2		.320000 x	4.602195 =	1.472702
601		.320000 x	23.927901 =	7.656928
		-----		
			B.T =	128.239768
3210A 3	3210A 3			
111		.400000 x	15.951934 =	6.380774
3110A 3		.800000 x	143.273288 =	114.618630
701 2		.320000 x	4.602195 =	1.472702
601		.320000 x	23.927901 =	7.656928
		-----		
			B.T =	130.129035
3210A 4	3210A 4			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.602195 =	1.472702
601		.320000 x	23.927901 =	7.656928
3110A 4		.800000 x	151.010451 =	120.808361
		-----		
			B.T =	136.318765
3210A 5	3210A 5			
111		.400000 x	15.951934 =	6.380774
3110A 1		.800000 x	133.174542 =	106.539634
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
		-----		
			B.T =	120.956320
3210A 6	3210A 6			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
3110A 2		.800000 x	140.911705 =	112.729364
		-----		
			B.T =	127.146050

3210A 7	3210A 7			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
3110A 3		.800000 x	143.273288 =	114.618630
		-----		
			B.T =	129.035316
3210A 8	3210A 8			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
3110A 4		.800000 x	151.010451 =	120.808361
		-----		
			B.T =	135.225047
3210B	3210B			
713 1		1.000000 x	5.003340 =	5.003340
704		1.000000 x	10.006679 =	10.006679
		-----		
			B.T =	15.010019
3220A 1	3220A 1			
3210A 1		1.000000 x	122.050038 =	122.050038
		-----		
			B.T =	122.050038
3220A 2	3220A 2			
3210A 2		1.000000 x	128.239768 =	128.239768
		-----		
			B.T =	128.239768
3220A 3	3220A 3			
3210A 3		1.000000 x	130.129035 =	130.129035
		-----		
			B.T =	130.129035
3220A 4	3220A 4			
3210A 4		1.000000 x	136.318765 =	136.318765
		-----		
			B.T =	136.318765
3220A 5	3220A 5			
3210A 5		1.000000 x	120.956320 =	120.956320
		-----		
			B.T =	120.956320

3220A 6	3220A 6			
3210A 6		1.000000 x	127.146050 =	127.146050
				-----
			B.T =	127.146050
3220A 7	3220A 7			
3210A 7		1.000000 x	129.035316 =	129.035316
				-----
			B.T =	129.035316
3220A 8	3220A 8			
3210A 8		1.000000 x	135.225047 =	135.225047
				-----
			B.T =	135.225047
3220B	3220B			
713 2		1.000000 x	5.475977 =	5.475977
705		1.000000 x	10.951954 =	10.951954
				-----
			B.T =	16.427931
3300A 1	3300A 1			
221		300.000000 x	.097700 =	29.310000
701 5		.250000 x	2.876372 =	.719093
701 2		.500000 x	4.602195 =	2.301098
701 2		.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
607		.500000 x	9.786409 =	4.893205
606		.800000 x	8.933527 =	7.146822
407		.040000 x	715.522746 =	28.620910
714		2.600000 x	7.709601 =	20.044963
113		2.000000 x	23.479183 =	46.958366
111		2.700000 x	15.951934 =	43.070222
319		.040000 x	20.840000 =	.833600
				-----
			B.T =	188.305455
3300A 2	3300A 2			
221		300.000000 x	.097700 =	29.310000
111		2.700000 x	15.951934 =	43.070222
714		2.600000 x	7.709601 =	20.044963
701 5		.250000 x	2.876372 =	.719093
701 4		.500000 x	4.314558 =	2.157279
701 2		.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
606		.800000 x	8.933527 =	7.146822
407		.040000 x	715.522746 =	28.620910
113		2.000000 x	23.479183 =	46.958366
319		.040000 x	20.840000 =	.833600
				-----
			B.T =	196.042618



3300A 3

3300A 3

221		300.000000 x	.097700 =	29.310000
630		.250000 x	2.901689 =	.725422
701	5	.250000 x	2.876372 =	.719093
701	4	.800000 x	4.314558 =	3.451646
701	2	.500000 x	4.602195 =	2.301098
607		.500000 x	9.786409 =	4.893205
610		.800000 x	21.844597 =	17.475678
407		.040000 x	715.522746 =	28.620910
113		2.000000 x	23.479183 =	46.958366
714		2.600000 x	7.709601 =	20.044963
111		2.700000 x	15.951934 =	43.070222
319		.040000 x	20.840000 =	.833600

B.T =

198.404201

3300A 4

3300A 4

221		300.000000 x	.097700 =	29.310000
701	5	.250000 x	2.876372 =	.719093
701	4	.800000 x	4.314558 =	3.451646
701	4	.500000 x	4.314558 =	2.157279
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
610		.800000 x	21.844597 =	17.475678
407		.040000 x	715.522746 =	28.620910
714		2.600000 x	7.709601 =	20.044963
113		2.000000 x	23.479183 =	46.958366
111		2.700000 x	15.951934 =	43.070222
319		.040000 x	20.840000 =	.833600

B.T =

206.141364

3300B 1

3300B 1

713	1	1.000000 x	5.003340 =	5.003340
704		1.000000 x	10.006679 =	10.006679

B.T =

15.010019

3300B 2

3300B 2

713	2	1.000000 x	5.475977 =	5.475977
705		1.000000 x	10.951954 =	10.951954

B.T =

16.427931

3400A 1

3400A 1

221		300.000000 x	.097700 =	29.310000
255		5.000000 x	.742000 =	3.710000
111		2.700000 x	15.951934 =	43.070222
112		1.000000 x	17.729980 =	17.729980
113		2.000000 x	23.479183 =	46.958366
701	5	.250000 x	2.876372 =	.719093
701	2	.800000 x	4.602195 =	3.681756
701	2	.500000 x	4.602195 =	2.301098
630		.250000 x	2.901689 =	.725422
607		.500000 x	9.786409 =	4.893205
606		.800000 x	8.933527 =	7.146822
407		.040000 x	715.522746 =	28.620910
113		.500000 x	23.479183 =	11.739592
319		.030000 x	20.840000 =	.625200

B.T =

201.231664

3400A 2

3400A 2

221		300.000000 x	.097700 =	29.310000
255		5.000000 x	.742000 =	3.710000
611		.500000 x	25.548372 =	12.774186
701	5	.250000 x	2.876372 =	.719093
701	4	.500000 x	4.314558 =	2.157279
701	2	.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
606		.800000 x	8.933527 =	7.146822
407		.040000 x	715.522746 =	28.620910
113		2.000000 x	23.479183 =	46.958366
113		.500000 x	23.479183 =	11.739592
112		1.000000 x	17.729980 =	17.729980
111		2.700000 x	15.951934 =	43.070222
319		.030000 x	20.840000 =	.625200

B.T =

208.968827

3400A 3

3400A 3

221		300.000000 x	.097700 =	29.310000
701	5	.250000 x	2.876372 =	.719093
701	4	.800000 x	4.314558 =	3.451646
701	2	.500000 x	4.602195 =	2.301098
630		.250000 x	2.901689 =	.725422
610		.800000 x	21.844597 =	17.475678
607		.500000 x	9.786409 =	4.893205
407		.040000 x	715.522746 =	28.620910
113		2.000000 x	23.479183 =	46.958366
113		.500000 x	23.479183 =	11.739592
112		1.000000 x	17.729980 =	17.729980
111		2.700000 x	15.951934 =	43.070222
319		.030000 x	20.840000 =	.625200
255		5.000000 x	.742000 =	3.710000

B.T =

211.330410

3400A 4	3400A 4			
221		300.000000 x	.097700 =	29.310000
255		5.000000 x	.742000 =	3.710000
111		2.700000 x	15.951934 =	43.070222
113		2.000000 x	23.479183 =	46.958366
701 5		.250000 x	2.876372 =	.719093
701 4		.800000 x	4.314558 =	3.451646
701 4		.500000 x	4.314558 =	2.157279
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
610		.800000 x	21.844597 =	17.475678
407		.040000 x	715.522746 =	28.620910
113		.500000 x	23.479183 =	11.739592
112		1.000000 x	17.729980 =	17.729980
319		.030000 x	20.840000 =	.625200
			B.T =	219.067573
3400B 1	3400B 1			
704		1.000000 x	10.006679 =	10.006679
			B.T =	10.006679
3400B 2	3400B 2			
705		1.000000 x	10.951954 =	10.951954
			B.T =	10.951954
4110A 1	4110A 1			
221		350.000000 x	.097700 =	34.195000
701 5		.100000 x	2.876372 =	.287637
701 2		.800000 x	4.602195 =	3.681756
701 2		.500000 x	4.602195 =	2.301098
630		.100000 x	2.901689 =	.290169
607		.500000 x	9.786409 =	4.893205
606		.800000 x	8.933527 =	7.146822
407		.070000 x	715.522746 =	50.086592
113		1.500000 x	23.479183 =	35.218775
111		4.000000 x	15.951934 =	63.807736
			B.T =	201.908788

4110A 2	4110A 2			
221		350.000000 x	.097700 =	34.195000
111		4.000000 x	15.951934 =	63.807736
407		.070000 x	715.522746 =	50.086592
611		.500000 x	25.548372 =	12.774186
701 4		.500000 x	4.314558 =	2.157279
701 5		.100000 x	2.876372 =	.287637
701 2		.800000 x	4.602195 =	3.681756
630		.100000 x	2.901689 =	.290169
606		.800000 x	8.933527 =	7.146822
113		1.500000 x	23.479183 =	35.218775

-----  
B.T = 209.645951

4110A 3	4110A 3			
221		350.000000 x	.097700 =	34.195000
701 5		.100000 x	2.876372 =	.287637
701 4		.800000 x	4.314558 =	3.451646
701 2		.500000 x	4.602195 =	2.301098
630		.100000 x	2.901689 =	.290169
610		.800000 x	21.844597 =	17.475678
607		.500000 x	9.786409 =	4.893205
111		4.000000 x	15.951934 =	63.807736
407		.070000 x	715.522746 =	50.086592
113		1.500000 x	23.479183 =	35.218775

-----  
B.T = 212.007535

4110A 4	4110A 4			
221		350.000000 x	.097700 =	34.195000
407		.070000 x	715.522746 =	50.086592
611		.500000 x	25.548372 =	12.774186
701 5		.100000 x	2.876372 =	.287637
701 4		.800000 x	4.314558 =	3.451646
701 4		.500000 x	4.314558 =	2.157279
630		.100000 x	2.901689 =	.290169
610		.800000 x	21.844597 =	17.475678
113		1.500000 x	23.479183 =	35.218775
111		4.000000 x	15.951934 =	63.807736

-----  
B.T = 219.744698

4110B	4110B			
112		8.000000 x	17.729980 =	141.839840
513		1.000000 x	840.929304 =	840.929304
508		1.000000 x	113.179500 =	113.179500
506		1.000000 x	418.979000 =	418.979000

-----  
B.T = 1,514.927644

4120A 1	4120A 1			
221		350.000000 x	.097700 =	34.195000
701 2		1.200000 x	4.602195 =	5.522634
607		1.200000 x	9.786409 =	11.743691
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.729980 =	88.649900

-----  
B.T = 162.791225

4120A 2	4120A 2			
221		350.000000 x	.097700 =	34.195000
701 4		1.200000 x	4.314558 =	5.177470
611		1.200000 x	25.548372 =	30.658046
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.729980 =	88.649900

-----  
B.T = 181.360416

4120B	4120B			
4110B		.040000 x	1,514.927644 =	60.597106

-----  
B.T = 60.597106

4130A 1	4130A 1			
221		350.000000 x	.097700 =	34.195000
263		42.000000 x	.540000 =	22.680000
407		.050000 x	715.522746 =	35.776137
606		.800000 x	8.933527 =	7.146822
607		.500000 x	9.786409 =	4.893205
701 2		.500000 x	4.602195 =	2.301098
701 2		.800000 x	4.602195 =	3.681756
111		2.000000 x	15.951934 =	31.903868

-----  
B.T = 142.577885

4130A 2	4130A 2			
221		350.000000 x	.097700 =	34.195000
407		.050000 x	715.522746 =	35.776137
701 4		.500000 x	4.314558 =	2.157279
701 2		.800000 x	4.602195 =	3.681756
611		.500000 x	25.548372 =	12.774186
606		.800000 x	8.933527 =	7.146822
111		2.000000 x	15.951934 =	31.903868
263		42.000000 x	.540000 =	22.680000

-----  
B.T = 150.315048

4130A 3	4130A 3			
221		350.000000 x	.097700 =	34.195000
701 4		.800000 x	4.314558 =	3.451646
701 2		.500000 x	4.602195 =	2.301098
610		.800000 x	21.844597 =	17.475678
607		.500000 x	9.786409 =	4.893205
407		.050000 x	715.522746 =	35.776137
111		2.000000 x	15.951934 =	31.903868
263		42.000000 x	.540000 =	22.680000
-----				
			B.T =	152.676631
4130A 4	4130A 4			
221		350.000000 x	.097700 =	34.195000
701 4		.500000 x	4.314558 =	2.157279
701 4		.800000 x	4.314558 =	3.451646
611		.500000 x	25.548372 =	12.774186
610		.800000 x	21.844597 =	17.475678
407		.050000 x	715.522746 =	35.776137
111		2.000000 x	15.951934 =	31.903868
263		42.000000 x	.540000 =	22.680000
-----				
			B.T =	160.413794
4130B	4130B			
4120B		1.000000 x	60.597106 =	60.597106
-----				
			B.T =	60.597106
4210A 1	4210A 1			
221		65.000000 x	.097700 =	6.350500
701 5		.150000 x	2.876372 =	.431456
601		1.050000 x	23.927901 =	25.124296
630		.150000 x	2.901689 =	.435253
701 2		1.050000 x	4.602195 =	4.832305
701 2		.300000 x	4.602195 =	1.380659
607		.300000 x	9.786409 =	2.935923
222		10.000000 x	.070000 =	.700000
-----				
			B.T =	42.190391
4210A 2	4210A 2			
221		65.000000 x	.097700 =	6.350500
701 5		.150000 x	2.876372 =	.431456
701 4		.300000 x	4.314558 =	1.294367
701 2		1.050000 x	4.602195 =	4.832305
630		.150000 x	2.901689 =	.435253
611		.300000 x	25.548372 =	7.664512
601		1.050000 x	23.927901 =	25.124296
222		10.000000 x	.070000 =	.700000
-----				
			B.T =	46.832689

4210A 3	4210A 3			
221		65.000000 x	.097700 =	6.350500
222		10.000000 x	.070000 =	.700000
607		.300000 x	9.786409 =	2.935923
630		.150000 x	2.901689 =	.435253
701 5		.150000 x	2.876372 =	.431456
701 2		.300000 x	4.602195 =	1.380659
701 2		1.050000 x	4.602195 =	4.832305
609		1.050000 x	20.510031 =	21.535533

-----  
B.T = 38.601628

4210A 4	4210A 4			
221		65.000000 x	.097700 =	6.350500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.602195 =	4.832305
701 5		.150000 x	2.876372 =	.431456
701 4		.300000 x	4.314558 =	1.294367
609		1.050000 x	20.510031 =	21.535533
630		.150000 x	2.901689 =	.435253
611		.300000 x	25.548372 =	7.664512

-----  
B.T = 43.243925

4210B	4210B			
111		4.000000 x	15.951934 =	63.807736
113		2.500000 x	23.479183 =	58.697958
112		.200000 x	17.729980 =	3.545996
112		1.500000 x	17.729980 =	26.594970

-----  
B.T = 152.646660

4220A 1	4220A 1			
221		200.000000 x	.097700 =	19.540000
111		1.200000 x	15.951934 =	19.142321
113		1.000000 x	23.479183 =	23.479183
407		.040000 x	715.522746 =	28.620910
606		.800000 x	8.933527 =	7.146822
607		.500000 x	9.786409 =	4.893205
630		.250000 x	2.901689 =	.725422
701 5		.250000 x	2.876372 =	.719093
701 2		.800000 x	4.602195 =	3.681756
701 2		.500000 x	4.602195 =	2.301098

-----  
B.T = 110.249808

4220A 2      4220A 2

221		200.000000 x	.097700 =	19.540000
113		1.000000 x	23.479183 =	23.479183
606		.800000 x	8.933527 =	7.146822
701	5	.250000 x	2.876372 =	.719093
701	4	.500000 x	4.314558 =	2.157279
701	2	.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
407		.040000 x	715.522746 =	28.620910
111		1.200000 x	15.951934 =	19.142321

-----  
B.T =      117.986971

4220A 3      4220A 3

221		200.000000 x	.097700 =	19.540000
701	4	.800000 x	4.314558 =	3.451646
701	2	.500000 x	4.602195 =	2.301098
630		.250000 x	2.901689 =	.725422
610		.800000 x	21.844597 =	17.475678
607		.500000 x	9.786409 =	4.893205
407		.040000 x	715.522746 =	28.620910
113		1.000000 x	23.479183 =	23.479183
111		1.200000 x	15.951934 =	19.142321
701	5	.250000 x	2.876372 =	.719093

-----  
B.T =      120.348555

4220A 4      4220A 4

221		200.000000 x	.097700 =	19.540000
111		1.200000 x	15.951934 =	19.142321
407		.040000 x	715.522746 =	28.620910
611		.500000 x	25.548372 =	12.774186
701	5	.250000 x	2.876372 =	.719093
701	4	.500000 x	4.314558 =	2.157279
701	4	.800000 x	4.314558 =	3.451646
630		.250000 x	2.901689 =	.725422
610		.800000 x	21.844597 =	17.475678
113		1.000000 x	23.479183 =	23.479183

-----  
B.T =      128.085718



4300A 1	4300A 1			
221		350.000000 x	.097700 =	34.195000
607		.500000 x	9.786409 =	4.893205
701 2		.500000 x	4.602195 =	2.301098
701 5		.250000 x	2.876372 =	.719093
701 2		.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
606		.800000 x	8.933527 =	7.146822
111		2.000000 x	15.951934 =	31.903868
714		1.150000 x	7.709601 =	8.866041
407		.040000 x	715.522746 =	28.620910
113		1.200000 x	23.479183 =	28.175020

-----  
ΑΘΡΟΙΣΜΑ = 151.228233

B.T = .200000 x 151.228233 = 30.245647  
-----

4300A 2	4300A 2			
221		350.000000 x	.097700 =	34.195000
701 5		.250000 x	2.876372 =	.719093
701 4		.500000 x	4.314558 =	2.157279
701 2		.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
606		.800000 x	8.933527 =	7.146822
407		.040000 x	715.522746 =	28.620910
714		1.150000 x	7.709601 =	8.866041
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868

-----  
ΑΘΡΟΙΣΜΑ = 158.965396

B.T = .200000 x 158.965396 = 31.793079  
-----

4300A 3	4300A 3			
221		350.000000 x	.097700 =	34.195000
607		.500000 x	9.786409 =	4.893205
701 5		.250000 x	2.876372 =	.719093
701 4		.800000 x	4.314558 =	3.451646
701 2		.500000 x	4.602195 =	2.301098
630		.250000 x	2.901689 =	.725422
610		.800000 x	21.844597 =	17.475678
407		.040000 x	715.522746 =	28.620910
714		1.150000 x	7.709601 =	8.866041
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868

-----  
ΑΘΡΟΙΣΜΑ = 161.326980

B.T = .200000 x 161.326980 = 32.265396  
-----

4300A 4	4300A 4			
221		350.000000 x	.097700 =	34.195000
111		2.000000 x	15.951934 =	31.903868
113		1.200000 x	23.479183 =	28.175020
701 5		.250000 x	2.876372 =	.719093
701 4		.800000 x	4.314558 =	3.451646
701 4		.500000 x	4.314558 =	2.157279
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
610		.800000 x	21.844597 =	17.475678
407		.040000 x	715.522746 =	28.620910
714		1.150000 x	7.709601 =	8.866041
			-----	
			ΑΘΡΟΙΣΜΑ =	169.064143
	B.T =	.200000 x	169.064143 =	33.812829
			-----	
4300B	4300B			
221		2.000000 x	.097700 =	.195400
262		4.000000 x	.980000 =	3.920000
112		.400000 x	17.729980 =	7.091992
			-----	
			B.T =	11.207392
601	601			
111		1.500000 x	15.951934 =	23.927901
			-----	
			B.T =	23.927901
602	602			
403		.002500 x	680.588374 =	1.701471
			-----	
			B.T =	1.701471
603	603			
111		.300000 x	15.951934 =	4.785580
401		.001000 x	878.725307 =	.878725
412		.003300 x	353.238239 =	1.165686
			-----	
			B.T =	6.829992
604	604			
111		.200000 x	15.951934 =	3.190387
401		.001100 x	878.725307 =	.966598
412		.004000 x	353.238239 =	1.412953
404		.005000 x	417.826891 =	2.089134
			-----	
			B.T =	7.659072

605	605				
112		.100000 x	17.729980 =		1.772998
402		.006200 x	861.342948 =		5.340326
412		.004000 x	353.238239 =		1.412953
406		.006200 x	388.698913 =		2.409933
401		.001000 x	878.725307 =		.878725
				B.T =	11.814936
606	606				
111		.100000 x	15.951934 =		1.595193
412		.005000 x	353.238239 =		1.766191
406		.006700 x	388.698913 =		2.604283
404		.005000 x	417.826891 =		2.089134
401		.001000 x	878.725307 =		.878725
				B.T =	8.933527
607	607				
111		.100000 x	15.951934 =		1.595193
412		.005000 x	353.238239 =		1.766191
406		.006700 x	388.698913 =		2.604283
404		.006200 x	417.826891 =		2.590527
401		.001400 x	878.725307 =		1.230215
				B.T =	9.786409
608	608				
111		.100000 x	15.951934 =		1.595193
404		.012500 x	417.826891 =		5.222836
401		.002000 x	878.725307 =		1.757451
412		.005000 x	353.238239 =		1.766191
406		.006700 x	388.698913 =		2.604283
				B.T =	12.945954
609	609				
214		.100000 x	1.875000 =		.187500
111		.800000 x	15.951934 =		12.761547
115		.200000 x	22.893045 =		4.578609
405		.005000 x	596.475048 =		2.982375
				B.T =	20.510031

610	610				
214		.100000 x	1.875000 =	.187500	
112		.100000 x	17.729980 =	1.772998	
412		.005000 x	353.238239 =	1.766191	
406		.005000 x	388.698913 =	1.943495	
405		.005000 x	596.475048 =	2.982375	
402		.010000 x	861.342948 =	8.613429	
115		.200000 x	22.893045 =	4.578609	
			B.T =	21.844597	
611	611				
214		.100000 x	1.875000 =	.187500	
112		.100000 x	17.729980 =	1.772998	
115		.200000 x	22.893045 =	4.578609	
406		.005000 x	388.698913 =	1.943495	
412		.005000 x	353.238239 =	1.766191	
405		.005000 x	596.475048 =	2.982375	
402		.014300 x	861.342948 =	12.317204	
			B.T =	25.548372	
612	612				
214		.150000 x	1.875000 =	.281250	
408		.010000 x	555.917019 =	5.559170	
115		.200000 x	22.893045 =	4.578609	
405		.005000 x	596.475048 =	2.982375	
111		.300000 x	15.951934 =	4.785580	
			AΘΡΟΙΣΜΑ =	18.186985	
	B.T =	1.068000 x	18.186985 =	19.423700	
613	613				
214		.150000 x	1.875000 =	.281250	
409		.010000 x	611.497819 =	6.114978	
405		.005000 x	596.475048 =	2.982375	
115		.200000 x	22.893045 =	4.578609	
111		.500000 x	15.951934 =	7.975967	
			AΘΡΟΙΣΜΑ =	21.933179	
	B.T =	1.282000 x	21.933179 =	28.118336	
614	614				
214		.150000 x	1.875000 =	.281250	
111		.500000 x	15.951934 =	7.975967	
115		.200000 x	22.893045 =	4.578609	
410		.010000 x	705.784319 =	7.057843	
405		.005000 x	596.475048 =	2.982375	
			AΘΡΟΙΣΜΑ =	22.876044	
	B.T =	1.602000 x	22.876044 =	36.647423	

615	615				
214		.150000 x	1.875000 =	.281250	
410		.010000 x	705.784319 =	7.057843	
111		.700000 x	15.951934 =	11.166354	
405		.005000 x	596.475048 =	2.982375	
115		.200000 x	22.893045 =	4.578609	
			-----		
			ΑΘΡΟΙΣΜΑ =	26.066431	
	B.T =	1.832000 x	26.066431 =	47.753702	
			-----		
616	616				
214		.150000 x	1.875000 =	.281250	
111		.800000 x	15.951934 =	12.761547	
405		.005000 x	596.475048 =	2.982375	
411		.010000 x	943.725319 =	9.437253	
115		.200000 x	22.893045 =	4.578609	
			-----		
			ΑΘΡΟΙΣΜΑ =	30.041035	
	B.T =	2.137000 x	30.041035 =	64.197691	
			-----		
617	617				
112		4.000000 x	17.729980 =	70.919920	
513		1.000000 x	840.929304 =	840.929304	
506		1.000000 x	418.979000 =	418.979000	
503		1.000000 x	1,161.779300 =	1,161.779300	
			-----		
			ΑΘΡΟΙΣΜΑ =	2,492.607524	
	B.T =	.006250 x	2,492.607524 =	15.578797	
			-----		
618	618				
112		4.000000 x	17.729980 =	70.919920	
513		1.000000 x	840.929304 =	840.929304	
506		1.000000 x	418.979000 =	418.979000	
503		1.000000 x	1,161.779300 =	1,161.779300	
			-----		
			ΑΘΡΟΙΣΜΑ =	2,492.607524	
	B.T =	.007700 x	2,492.607524 =	19.193078	
			-----		
619	619				
112		4.000000 x	17.729980 =	70.919920	
503		1.000000 x	1,161.779300 =	1,161.779300	
506		1.000000 x	418.979000 =	418.979000	
513		1.000000 x	840.929304 =	840.929304	
			-----		
			ΑΘΡΟΙΣΜΑ =	2,492.607524	
	B.T =	.010000 x	2,492.607524 =	24.926075	
			-----		

620	620			
112		4.000000 x	17.729980 =	70.919920
513		1.000000 x	840.929304 =	840.929304
506		1.000000 x	418.979000 =	418.979000
503		1.000000 x	1,161.779300 =	1,161.779300
			-----	
			ΑΘΡΟΙΣΜΑ =	2,492.607524
	B.T =	.012500 x	2,492.607524 =	31.157594
			-----	
621	621			
112		4.000000 x	17.729980 =	70.919920
506		1.000000 x	418.979000 =	418.979000
503		1.000000 x	1,161.779300 =	1,161.779300
513		1.000000 x	840.929304 =	840.929304
			-----	
			ΑΘΡΟΙΣΜΑ =	2,492.607524
	B.T =	.016600 x	2,492.607524 =	41.377285
			-----	
630	630			
413		.020000 x	145.084426 =	2.901689
			-----	
			B.T =	2.901689
701 1	701 1			
406		.012580 x	388.698913 =	4.889832
			-----	
			B.T =	4.889832
701 2	701 2			
406		.011840 x	388.698913 =	4.602195
			-----	
			B.T =	4.602195
701 3	701 3			
406		.011544 x	388.698913 =	4.487140
			-----	
			B.T =	4.487140
701 4	701 4			
406		.011100 x	388.698913 =	4.314558
			-----	
			B.T =	4.314558
701 5	701 5			
406		.007400 x	388.698913 =	2.876372
			-----	
			B.T =	2.876372

702	702			
112		8.000000 x	17.729980 =	141.839840
506		1.000000 x	418.979000 =	418.979000
513		.300000 x	840.929304 =	252.278791
509		2.000000 x	163.086000 =	326.172000
			AΘΡΟΙΣΜΑ =	1,139.269631
	B.T =	.002500 x	1,139.269631 =	2.848174
703	703			
112		4.000000 x	17.729980 =	70.919920
503		1.000000 x	1,161.779300 =	1,161.779300
510		2.000000 x	168.210000 =	336.420000
506		1.000000 x	418.979000 =	418.979000
513		.300000 x	840.929304 =	252.278791
			AΘΡΟΙΣΜΑ =	2,240.377011
	B.T =	.002500 x	2,240.377011 =	5.600943
704	704			
112		4.000000 x	17.729980 =	70.919920
502		1.000000 x	1,090.972300 =	1,090.972300
513		.500000 x	840.929304 =	420.464652
506		1.000000 x	418.979000 =	418.979000
			AΘΡΟΙΣΜΑ =	2,001.335872
	B.T =	.005000 x	2,001.335872 =	10.006679
705	705			
112		4.000000 x	17.729980 =	70.919920
513		.600000 x	840.929304 =	504.557582
506		1.000000 x	418.979000 =	418.979000
504		1.000000 x	1,417.868100 =	1,417.868100
			AΘΡΟΙΣΜΑ =	2,412.324602
	B.T =	.004540 x	2,412.324602 =	10.951954
706	706			
501		1.000000 x	1,161.779300 =	1,161.779300
509		2.000000 x	163.086000 =	326.172000
506		1.000000 x	418.979000 =	418.979000
			AΘΡΟΙΣΜΑ =	1,906.930300
	B.T =	.002500 x	1,906.930300 =	4.767326
707	707			
505		1.000000 x	2,452.884500 =	2,452.884500
510		2.000000 x	168.210000 =	336.420000
506		1.000000 x	418.979000 =	418.979000
			AΘΡΟΙΣΜΑ =	3,208.283500
	B.T =	.001000 x	3,208.283500 =	3.208284

708	708				
708A		1.000000 x	17.263669 =		17.263669
708B		1.000000 x	4.767326 =		4.767326
		-----			
			B.T =		22.030995
708A	708A				
214		.050000 x	1.875000 =		.093750
513		.010000 x	840.929304 =		8.409293
511		.010000 x	130.468800 =		1.304688
405		.012500 x	596.475048 =		7.455938
		-----			
			B.T =		17.263669
708B	708B				
706		1.000000 x	4.767326 =		4.767326
		-----			
			B.T =		4.767326
709	709				
709A		1.000000 x	13.950582 =		13.950582
709B		1.000000 x	4.767326 =		4.767326
		-----			
			B.T =		18.717908
709A	709A				
506		1.000000 x	418.979000 =		418.979000
512		1.000000 x	697.067580 =		697.067580
		-----			
			AΘΡΟΙΣΜΑ =		1,116.046580
	B.T =	.012500 x	1,116.046580 =		13.950582
		-----			
709B	709B				
706		1.000000 x	4.767326 =		4.767326
		-----			
			B.T =		4.767326
710	710				
710A		1.000000 x	49.285810 =		49.285810
710B		1.000000 x	4.767326 =		4.767326
		-----			
			B.T =		54.053136
710A	710A				
214		.200000 x	1.875000 =		.375000
405		.025000 x	596.475048 =		14.911876
513		.035000 x	840.929304 =		29.432526
511		.035000 x	130.468800 =		4.566408
		-----			
			B.T =		49.285810



710B	710B			
706		1.000000 x	4.767326 =	4.767326
		-----		
			B.T =	4.767326
711	711			
711A		1.000000 x	37.164351 =	37.164351
711B		1.000000 x	4.767326 =	4.767326
		-----		
			B.T =	41.931677
711A	711A			
506		1.000000 x	418.979000 =	418.979000
512		1.000000 x	697.067580 =	697.067580
		-----		
			AΘΡΟΙΣΜΑ =	1,116.046580
	B.T =	.033300 x	1,116.046580 =	37.164351
		-----		
711B	711B			
706		1.000000 x	4.767326 =	4.767326
		-----		
			B.T =	4.767326
712	712			
513		1.000000 x	840.929304 =	840.929304
		-----		
			AΘΡΟΙΣΜΑ =	840.929304
	B.T =	.004000 x	840.929304 =	3.363717
		-----		
713 1	713 1			
704		.500000 x	10.006679 =	5.003340
		-----		
			B.T =	5.003340
713 2	713 2			
705		.500000 x	10.951954 =	5.475977
		-----		
			B.T =	5.475977
714	714			
714A		1.000000 x	3.588685 =	3.588685
714B		1.000000 x	4.120916 =	4.120916
		-----		
			B.T =	7.709601

714A	714A			
242		.070000 x	335.000000 =	23.450000
114		2.000000 x	17.729980 =	35.459960
252		1.000000 x	1.900000 =	1.900000
113		2.000000 x	23.479183 =	46.958366
			AΘΡΟΙΣΜΑ =	107.768326
	B.T =	.033300 x	107.768326 =	3.588685
714B	714B			
113		.100000 x	23.479183 =	2.347918
114		.100000 x	17.729980 =	1.772998
			B.T =	4.120916
1111	1111			
1111A		1.000000 x	31.732463 =	31.732463
1111B		1.000000 x	4.767326 =	4.767326
			T.E =	36.499789
1112	1112			
1112A		1.000000 x	27.901165 =	27.901165
1112B		1.000000 x	4.767326 =	4.767326
			T.E =	32.668491
1113	1113			
1113A		1.000000 x	53.718305 =	53.718305
1113B		1.000000 x	4.767326 =	4.767326
			T.E =	58.485631
1114	1114			
1114A		1.000000 x	41.262032 =	41.262032
1114B		1.000000 x	4.767326 =	4.767326
			T.E =	46.029358
1121	1121			
1121A		1.000000 x	23.657273 =	23.657273
1121B		1.000000 x	4.767326 =	4.767326
			T.E =	28.424599
1122	1122			
1122A		1.000000 x	13.950582 =	13.950582
1122B		1.000000 x	4.767326 =	4.767326
			T.E =	18.717908

1123	1123				
1123A		1.000000 x	40.745668 =		40.745668
1123B		1.000000 x	4.767326 =		4.767326
		-----			
			T.E =		45.512994
1124	1124				
1124A		1.000000 x	24.980429 =		24.980429
1124B		1.000000 x	4.767326 =		4.767326
		-----			
			T.E =		29.747755
1210	1210				
707		1.000000 x	3.208284 =		3.208284
		-----			
			T.E =		3.208284
1220	1220				
708		1.000000 x	22.030995 =		22.030995
		-----			
			T.E =		22.030995
1230	1230				
709		1.000000 x	18.717908 =		18.717908
		-----			
			T.E =		18.717908
1311	1311				
712		.250000 x	3.363717 =		.840929
		-----			
			T.E =		.840929
1312	1312				
712		.250000 x	3.363717 =		.840929
701 1		1.000000 x	4.889832 =		4.889832
602		1.000000 x	1.701471 =		1.701471
		-----			
			T.E =		7.432232
1313	1313				
712		.250000 x	3.363717 =		.840929
603		1.000000 x	6.829992 =		6.829992
701 2		1.000000 x	4.602195 =		4.602195
		-----			
			T.E =		12.273116

1314	1314				
232		1.000000 x	39.820000 =	39.820000	
111		.100000 x	15.951934 =	1.595193	
712		.250000 x	3.363717 =	.840929	
		-----			
			T.E =	42.256123	
1321	1321				
112		.200000 x	17.729980 =	3.545996	
701	1	1.000000 x	4.889832 =	4.889832	
602		1.000000 x	1.701471 =	1.701471	
		-----			
			T.E =	10.137299	
1322	1322				
112		.200000 x	17.729980 =	3.545996	
603		1.000000 x	6.829992 =	6.829992	
701	2	1.000000 x	4.602195 =	4.602195	
		-----			
			T.E =	14.978183	
1323	1323				
232		1.000000 x	39.820000 =	39.820000	
111		.100000 x	15.951934 =	1.595193	
112		.100000 x	17.729980 =	1.772998	
		-----			
			T.E =	43.188191	
2110	2110				
712		.500000 x	3.363717 =	1.681859	
702		1.000000 x	2.848174 =	2.848174	
608		1.000000 x	12.945954 =	12.945954	
701	4	1.000000 x	4.314558 =	4.314558	
		-----			
			T.E =	21.790545	
2120	2120				
712		.500000 x	3.363717 =	1.681859	
702		1.000000 x	2.848174 =	2.848174	
701	2	1.000000 x	4.602195 =	4.602195	
603		1.000000 x	6.829992 =	6.829992	
		-----			
			T.E =	15.962220	
2130	2130				
712		.500000 x	3.363717 =	1.681859	
604		1.000000 x	7.659072 =	7.659072	
701	2	1.000000 x	4.602195 =	4.602195	
702		1.000000 x	2.848174 =	2.848174	
		-----			
			T.E =	16.791300	

2140	2140				
712		.500000 x	3.363717 =	1.681859	
605		1.000000 x	11.814936 =	11.814936	
702		1.000000 x	2.848174 =	2.848174	
701	2	1.000000 x	4.602195 =	4.602195	
-----					
			T.E =	20.947164	
2210	2210				
712		.500000 x	3.363717 =	1.681859	
609		1.050000 x	20.510031 =	21.535533	
702		1.000000 x	2.848174 =	2.848174	
701	2	1.000000 x	4.602195 =	4.602195	
-----					
			T.E =	30.667760	
2220	2220				
712		.500000 x	3.363717 =	1.681859	
702		1.000000 x	2.848174 =	2.848174	
701	2	1.000000 x	4.602195 =	4.602195	
609		1.150000 x	20.510031 =	23.586536	
-----					
			T.E =	32.718763	
2230	2230				
111		.200000 x	15.951934 =	3.190387	
609		1.200000 x	20.510031 =	24.612037	
701	2	1.000000 x	4.602195 =	4.602195	
-----					
			T.E =	32.404619	
2240	2240				
111		.300000 x	15.951934 =	4.785580	
609		1.200000 x	20.510031 =	24.612037	
701	2	1.000000 x	4.602195 =	4.602195	
-----					
			T.E =	33.999812	
2310	2310				
612		1.000000 x	19.423700 =	19.423700	
701	3	1.000000 x	4.487140 =	4.487140	
703		1.000000 x	5.600943 =	5.600943	
-----					
			T.E =	29.511783	
2320	2320				
613		1.000000 x	28.118336 =	28.118336	
703		1.000000 x	5.600943 =	5.600943	
701	3	1.000000 x	4.487140 =	4.487140	
-----					
			T.E =	38.206419	

2330	2330				
614		1.000000 x	36.647423 =	36.647423	
703		1.000000 x	5.600943 =	5.600943	
701	3	1.000000 x	4.487140 =	4.487140	
				-----	
				T.E =	46.735506
2340	2340				
615		1.000000 x	47.753702 =	47.753702	
703		1.000000 x	5.600943 =	5.600943	
701	3	1.000000 x	4.487140 =	4.487140	
				-----	
				T.E =	57.841785
2350	2350				
616		1.000000 x	64.197691 =	64.197691	
703		1.000000 x	5.600943 =	5.600943	
701	3	1.000000 x	4.487140 =	4.487140	
				-----	
				T.E =	74.285774
2410	2410				
617		1.000000 x	15.578797 =	15.578797	
703		1.000000 x	5.600943 =	5.600943	
				-----	
				T.E =	21.179740
2420	2420				
618		1.000000 x	19.193078 =	19.193078	
703		1.000000 x	5.600943 =	5.600943	
				-----	
				T.E =	24.794021
2430	2430				
619		1.000000 x	24.926075 =	24.926075	
703		1.000000 x	5.600943 =	5.600943	
				-----	
				T.E =	30.527018
2440	2440				
620		1.000000 x	31.157594 =	31.157594	
703		1.000000 x	5.600943 =	5.600943	
				-----	
				T.E =	36.758537
2450	2450				
621		1.000000 x	41.377285 =	41.377285	
703		1.000000 x	5.600943 =	5.600943	
				-----	
				T.E =	46.978228

3110 1	3110 1				
3110A 1		1.000000 x	133.174542 =		133.174542
3110B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		148.184561
3110 2	3110 2				
3110A 2		1.000000 x	140.911705 =		140.911705
3110B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		155.921724
3110 3	3110 3				
3110A 3		1.000000 x	143.273288 =		143.273288
3110B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		158.283307
3110 4	3110 4				
3110A 4		1.000000 x	151.010451 =		151.010451
3110B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		166.020470
3120 1	3120 1				
3120A 1		1.000000 x	133.174542 =		133.174542
3120B		1.000000 x	16.427931 =		16.427931
		-----			
			T.E =		149.602473
3120 2	3120 2				
3120A 2		1.000000 x	140.911705 =		140.911705
3120B		1.000000 x	16.427931 =		16.427931
		-----			
			T.E =		157.339636
3120 3	3120 3				
3120A 3		1.000000 x	143.273288 =		143.273288
3120B		1.000000 x	16.427931 =		16.427931
		-----			
			T.E =		159.701219
3120 4	3120 4				
3120A 4		1.000000 x	151.010451 =		151.010451
3120B		1.000000 x	16.427931 =		16.427931
		-----			
			T.E =		167.438382

3210 1	3210 1				
3210A 1		1.000000 x	122.050038 =		122.050038
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		137.060057
3210 2	3210 2				
3210A 2		1.000000 x	128.239768 =		128.239768
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		143.249787
3210 3	3210 3				
3210A 3		1.000000 x	130.129035 =		130.129035
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		145.139054
3210 4	3210 4				
3210A 4		1.000000 x	136.318765 =		136.318765
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		151.328784
3210 5	3210 5				
3210A 5		1.000000 x	120.956320 =		120.956320
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		135.966339
3210 6	3210 6				
3210A 6		1.000000 x	127.146050 =		127.146050
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		142.156069
3210 7	3210 7				
3210A 7		1.000000 x	129.035316 =		129.035316
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		144.045335
3210 8	3210 8				
3210A 8		1.000000 x	135.225047 =		135.225047
3210B		1.000000 x	15.010019 =		15.010019
		-----			
			T.E =		150.235066



3220	1	3220	1			
	3220A 1			1.000000 x	122.050038 =	122.050038
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	138.477969
3220	2	3220	2			
	3220A 2			1.000000 x	128.239768 =	128.239768
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	144.667699
3220	3	3220	3			
	3220A 3			1.000000 x	130.129035 =	130.129035
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	146.556966
3220	4	3220	4			
	3220A 4			1.000000 x	136.318765 =	136.318765
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	152.746696
3220	5	3220	5			
	3220A 5			1.000000 x	120.956320 =	120.956320
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	137.384251
3220	6	3220	6			
	3220A 6			1.000000 x	127.146050 =	127.146050
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	143.573981
3220	7	3220	7			
	3220A 7			1.000000 x	129.035316 =	129.035316
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	145.463247
3220	8	3220	8			
	3220A 8			1.000000 x	135.225047 =	135.225047
	3220B			1.000000 x	16.427931 =	16.427931
				-----		
					T.E =	151.652978

3300	1	3300	1			
	3300A	1		1.000000 x	188.305455 =	188.305455
	3300B	1		1.000000 x	15.010019 =	15.010019
-----						
					T.E =	203.315474
3300	2	3300	2			
	3300A	1		1.000000 x	188.305455 =	188.305455
	3300B	2		1.000000 x	16.427931 =	16.427931
-----						
					T.E =	204.733386
3300	3	3300	3			
	3300A	2		1.000000 x	196.042618 =	196.042618
	3300B	1		1.000000 x	15.010019 =	15.010019
-----						
					T.E =	211.052637
3300	4	3300	4			
	3300A	2		1.000000 x	196.042618 =	196.042618
	3300B	2		1.000000 x	16.427931 =	16.427931
-----						
					T.E =	212.470549
3300	5	3300	5			
	3300A	3		1.000000 x	198.404201 =	198.404201
	3300B	1		1.000000 x	15.010019 =	15.010019
-----						
					T.E =	213.414220
3300	6	3300	6			
	3300A	3		1.000000 x	198.404201 =	198.404201
	3300B	2		1.000000 x	16.427931 =	16.427931
-----						
					T.E =	214.832132
3300	7	3300	7			
	3300A	4		1.000000 x	206.141364 =	206.141364
	3300B	1		1.000000 x	15.010019 =	15.010019
-----						
					T.E =	221.151383
3300	8	3300	8			
	3300A	4		1.000000 x	206.141364 =	206.141364
	3300B	2		1.000000 x	16.427931 =	16.427931
-----						
					T.E =	222.569295

3400 1	3400 1				
3400A 1		1.000000 x	201.231664 =	201.231664	
3400B 1		1.000000 x	10.006679 =	10.006679	
				-----	
				T.E =	211.238343
3400 2	3400 2				
3400A 1		1.000000 x	201.231664 =	201.231664	
3400B 2		1.000000 x	10.951954 =	10.951954	
				-----	
				T.E =	212.183618
3400 3	3400 3				
3400A 2		1.000000 x	208.968827 =	208.968827	
3400B 1		1.000000 x	10.006679 =	10.006679	
				-----	
				T.E =	218.975506
3400 4	3400 4				
3400A 2		1.000000 x	208.968827 =	208.968827	
3400B 2		1.000000 x	10.951954 =	10.951954	
				-----	
				T.E =	219.920781
3400 5	3400 5				
3400A 3		1.000000 x	211.330410 =	211.330410	
3400B 1		1.000000 x	10.006679 =	10.006679	
				-----	
				T.E =	221.337089
3400 6	3400 6				
3400A 3		1.000000 x	211.330410 =	211.330410	
3400B 2		1.000000 x	10.951954 =	10.951954	
				-----	
				T.E =	222.282364
3400 7	3400 7				
3400A 4		1.000000 x	219.067573 =	219.067573	
3400B 1		1.000000 x	10.006679 =	10.006679	
				-----	
				T.E =	229.074252
3400 8	3400 8				
3400A 4		1.000000 x	219.067573 =	219.067573	
3400B 2		1.000000 x	10.951954 =	10.951954	
				-----	
				T.E =	230.019527

4110	1	4110	1				
	4110A	1		1.000000 x	201.908788 =		201.908788
	4110B			.025000 x	1,514.927644 =		37.873191
-----							
						T.E =	239.781979
4110	2	4110	2				
	4110A	2		1.000000 x	209.645951 =		209.645951
	4110B			.025000 x	1,514.927644 =		37.873191
-----							
						T.E =	247.519142
4110	3	4110	3				
	4110A	3		1.000000 x	212.007535 =		212.007535
	4110B			.025000 x	1,514.927644 =		37.873191
-----							
						T.E =	249.880726
4110	4	4110	4				
	4110A	4		1.000000 x	219.744698 =		219.744698
	4110B			.025000 x	1,514.927644 =		37.873191
-----							
						T.E =	257.617889
4120	1	4120	1				
	4120A	1		1.000000 x	162.791225 =		162.791225
	4120B			1.000000 x	60.597106 =		60.597106
-----							
						T.E =	223.388331
4120	2	4120	2				
	4120A	2		1.000000 x	181.360416 =		181.360416
	4120B			1.000000 x	60.597106 =		60.597106
-----							
						T.E =	241.957522
4130	1	4130	1				
	4130A	1		1.000000 x	142.577885 =		142.577885
	4130B			1.000000 x	60.597106 =		60.597106
-----							
						T.E =	203.174991
4130	2	4130	2				
	4130A	2		1.000000 x	150.315048 =		150.315048
	4130B			1.000000 x	60.597106 =		60.597106
-----							
						T.E =	210.912154

4130	3	4130	3			
4130A	3			1.000000 x	152.676631 =	152.676631
4130B				1.000000 x	60.597106 =	60.597106
-----						
T.E =						213.273737
4130	4	4130	4			
4130A	4			1.000000 x	160.413794 =	160.413794
4130B				1.000000 x	60.597106 =	60.597106
-----						
T.E =						221.010900
4210	1	4210	1			
4210A	1			1.000000 x	42.190391 =	42.190391
4210B				1.000000 x	152.646660 =	152.646660
-----						
T.E =						194.837051
4210	2	4210	2			
4210A	2			1.000000 x	46.832689 =	46.832689
4210B				1.000000 x	152.646660 =	152.646660
-----						
T.E =						199.479349
4210	3	4210	3			
4210A	3			1.000000 x	38.601628 =	38.601628
4210B				1.000000 x	152.646660 =	152.646660
-----						
T.E =						191.248288
4210	4	4210	4			
4210A	4			1.000000 x	43.243925 =	43.243925
4210B				1.000000 x	152.646660 =	152.646660
-----						
T.E =						195.890585
4220B	1	4220B	1			
319				.020000 x	20.840000 =	.416800
701	2			.320000 x	4.602195 =	1.472702
601				.320000 x	23.927901 =	7.656928
4220A	1			.800000 x	110.249808 =	88.199846
111				.400000 x	15.951934 =	6.380774
714				1.150000 x	7.709601 =	8.866041
-----						
T.E =						112.993092

4220B 2	4220B 2			
319		.020000 x	20.840000 =	.416800
4220A 2		.800000 x	117.986971 =	94.389577
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.602195 =	1.472702
601		.320000 x	23.927901 =	7.656928
714		1.150000 x	7.709601 =	8.866041

T.E = 119.182822

4220B 3	4220B 3			
319		.020000 x	20.840000 =	.416800
701 2		.320000 x	4.602195 =	1.472702
601		.320000 x	23.927901 =	7.656928
4220A 3		.800000 x	120.348555 =	96.278844
714		1.150000 x	7.709601 =	8.866041
111		.400000 x	15.951934 =	6.380774

T.E = 121.072089

4220B 4	4220B 4			
319		.020000 x	20.840000 =	.416800
111		.400000 x	15.951934 =	6.380774
4220A 4		.800000 x	128.085718 =	102.468574
701 2		.320000 x	4.602195 =	1.472702
601		.320000 x	23.927901 =	7.656928
714		1.150000 x	7.709601 =	8.866041

T.E = 127.261820

4220B 5	4220B 5			
319		.020000 x	20.840000 =	.416800
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
4220A 1		.800000 x	110.249808 =	88.199846
111		.400000 x	15.951934 =	6.380774
714		1.150000 x	7.709601 =	8.866041

T.E = 111.899373

4220B 6	4220B 6			
319		.020000 x	20.840000 =	.416800
4220A 2		.800000 x	117.986971 =	94.389577
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
714		1.150000 x	7.709601 =	8.866041

T.E = 118.089104

4220B 7	4220B 7			
319		.020000 x	20.840000 =	.416800
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
4220A 3		.800000 x	120.348555 =	96.278844
714		1.150000 x	7.709601 =	8.866041
111		.400000 x	15.951934 =	6.380774

-----  
T.E = 119.978371

4220B 8	4220B 8			
319		.020000 x	20.840000 =	.416800
111		.400000 x	15.951934 =	6.380774
714		1.150000 x	7.709601 =	8.866041
701 2		.320000 x	4.602195 =	1.472702
609		.320000 x	20.510031 =	6.563210
4220A 4		.800000 x	128.085718 =	102.468574

-----  
T.E = 126.168101

4230 1	4230 1			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.876372 =	.719093
701 2		.500000 x	4.602195 =	2.301098
701 2		.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
319		.020000 x	20.840000 =	.416800
113		1.200000 x	23.479183 =	28.175020
407		.040000 x	715.522746 =	28.620910
607		.500000 x	9.786409 =	4.893205
606		.800000 x	8.933527 =	7.146822
714		1.150000 x	7.709601 =	8.866041
111		2.000000 x	15.951934 =	31.903868

-----  
T.E = 141.875033

4230 2	4230 2			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.876372 =	.719093
701 4		.500000 x	4.314558 =	2.157279
701 2		.800000 x	4.602195 =	3.681756
630		.250000 x	2.901689 =	.725422
611		.500000 x	25.548372 =	12.774186
606		.800000 x	8.933527 =	7.146822
407		.040000 x	715.522746 =	28.620910
714		1.150000 x	7.709601 =	8.866041
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868
319		.020000 x	20.840000 =	.416800

-----  
T.E = 149.612196

4230	3	4230	3			
221				250.000000 x	.097700 =	24.425000
701	5			.250000 x	2.876372 =	.719093
701	4			.800000 x	4.314558 =	3.451646
701	2			.500000 x	4.602195 =	2.301098
630				.250000 x	2.901689 =	.725422
610				.800000 x	21.844597 =	17.475678
319				.020000 x	20.840000 =	.416800
111				2.000000 x	15.951934 =	31.903868
407				.040000 x	715.522746 =	28.620910
607				.500000 x	9.786409 =	4.893205
714				1.150000 x	7.709601 =	8.866041
113				1.200000 x	23.479183 =	28.175020

-----  
T.E = 151.973780

4230	4	4230	4			
221				250.000000 x	.097700 =	24.425000
701	5			.250000 x	2.876372 =	.719093
701	4			.500000 x	4.314558 =	2.157279
701	4			.800000 x	4.314558 =	3.451646
630				.250000 x	2.901689 =	.725422
611				.500000 x	25.548372 =	12.774186
610				.800000 x	21.844597 =	17.475678
407				.040000 x	715.522746 =	28.620910
714				1.150000 x	7.709601 =	8.866041
319				.020000 x	20.840000 =	.416800
113				1.200000 x	23.479183 =	28.175020
111				2.000000 x	15.951934 =	31.903868

-----  
T.E = 159.710943

4240	1	4240	1			
221				300.000000 x	.097700 =	29.310000
701	5			.250000 x	2.876372 =	.719093
701	2			.500000 x	4.602195 =	2.301098
701	2			.800000 x	4.602195 =	3.681756
630				.250000 x	2.901689 =	.725422
607				.500000 x	9.786409 =	4.893205
606				.800000 x	8.933527 =	7.146822
319				.020000 x	20.840000 =	.416800
113				1.200000 x	23.479183 =	28.175020
407				.040000 x	715.522746 =	28.620910
714				1.150000 x	7.709601 =	8.866041
111				2.000000 x	15.951934 =	31.903868

-----  
T.E = 146.760033



4240	2	4240	2		
221				300.000000 x	.097700 = 29.310000
701	5			.250000 x	2.876372 = .719093
701	4			.500000 x	4.314558 = 2.157279
701	2			.800000 x	4.602195 = 3.681756
630				.250000 x	2.901689 = .725422
611				.500000 x	25.548372 = 12.774186
606				.800000 x	8.933527 = 7.146822
407				.040000 x	715.522746 = 28.620910
714				1.150000 x	7.709601 = 8.866041
113				1.200000 x	23.479183 = 28.175020
111				2.000000 x	15.951934 = 31.903868
319				.020000 x	20.840000 = .416800

T.E = 154.497196

4240	3	4240	3		
221				300.000000 x	.097700 = 29.310000
701	5			.250000 x	2.876372 = .719093
701	4			.800000 x	4.314558 = 3.451646
701	2			.500000 x	4.602195 = 2.301098
630				.250000 x	2.901689 = .725422
610				.800000 x	21.844597 = 17.475678
319				.020000 x	20.840000 = .416800
111				2.000000 x	15.951934 = 31.903868
407				.040000 x	715.522746 = 28.620910
607				.500000 x	9.786409 = 4.893205
714				1.150000 x	7.709601 = 8.866041
113				1.200000 x	23.479183 = 28.175020

T.E = 156.858780

4240	4	4240	4		
221				300.000000 x	.097700 = 29.310000
701	5			.250000 x	2.876372 = .719093
701	4			.500000 x	4.314558 = 2.157279
701	4			.800000 x	4.314558 = 3.451646
630				.250000 x	2.901689 = .725422
611				.500000 x	25.548372 = 12.774186
610				.800000 x	21.844597 = 17.475678
407				.040000 x	715.522746 = 28.620910
714				1.150000 x	7.709601 = 8.866041
319				.020000 x	20.840000 = .416800
113				1.200000 x	23.479183 = 28.175020
111				2.000000 x	15.951934 = 31.903868

T.E = 164.595943

4300	1	4300	1		
4300A	1			1.000000 x	30.245647 = 30.245647
4300B				1.000000 x	11.207392 = 11.207392

T.E = 41.453039

4300	2	4300	2			
4300A	2			1.000000 x	31.793079 =	31.793079
4300B				1.000000 x	11.207392 =	11.207392
-----						
T.E =						43.000471
4300	3	4300	3			
4300A	3			1.000000 x	32.265396 =	32.265396
4300B				1.000000 x	11.207392 =	11.207392
-----						
T.E =						43.472788
4300	4	4300	4			
4300A	4			1.000000 x	33.812829 =	33.812829
4300B				1.000000 x	11.207392 =	11.207392
-----						
T.E =						45.020221
4400		4400				
251				1.050000 x	.536700 =	.563535
113				.050000 x	23.479183 =	1.173959
-----						
T.E =						1.737494
4500		4500				
251				1.050000 x	.536700 =	.563535
113				.100000 x	23.479183 =	2.347918
114				.100000 x	17.729980 =	1.772998
-----						
T.E =						4.684451
4600		4600				
256				1.000000 x	3.300000 =	3.300000
113				.100000 x	23.479183 =	2.347918
-----						
T.E =						5.647918
4700		4700				
253				1.000000 x	3.500000 =	3.500000
113				.100000 x	23.479183 =	2.347918
-----						
T.E =						5.847918