

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

3ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	1.047200
212	1.300000
213	3.930000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.583300
252	1.900000
253	4.000000
254	5.000000
255	.901300
256	3.800000
261	
262	.980000
263	.540000
311	425.280000
312	130.670000
313	200.790000
314	4.400000
315	53.630000
316	4.400000
317	122.460000
318	26.580000
319	21.440000
320	152.240000
321	207.240000
322	287.930000
323	327.890000
324	179.890000
325	308.130000
326	100.390000
327	4.400000
351	438.810000
352	372.560000
353	438.810000
354	575.700000
355	287.930000
356	47.250000
357	226.390000
358	45.580000
359	94.500000
360	99.520000

361	76.120000
362	263.460000
363	99.670000
380	552.590000
381	552.590000
382	552.590000
383	635.530000
384	1,052.620000
385	191.250000
386	504.640000
387	72.810000
388	72.810000
389	72.810000

401	401				
211		110.000000 x	1.047200 =	115.192000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
213		10.000000 x	3.930000 =	39.300000	
311		1.000000 x	425.280000 =	425.280000	
			ΑΘΡΟΙΣΜΑ =	810.865612	
			Η.Δ. =	891.952173	
402	402				
211		180.000000 x	1.047200 =	188.496000	
312		1.000000 x	130.670000 =	130.670000	
117		8.000000 x	10.001019 =	80.008152	
116		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
212		5.000000 x	1.300000 =	6.500000	
213		12.000000 x	3.930000 =	47.160000	
			ΑΘΡΟΙΣΜΑ =	782.420584	
			Η.Δ. =	860.662642	
403	403				
211		80.000000 x	1.047200 =	83.776000	
213		6.000000 x	3.930000 =	23.580000	
117		8.000000 x	10.001019 =	80.008152	
116		8.000000 x	23.886192 =	191.089536	
313		1.000000 x	200.790000 =	200.790000	
254		2.500000 x	5.000000 =	12.500000	
			ΑΘΡΟΙΣΜΑ =	591.743688	
			Η.Δ. =	650.918057	
404	404				
211		80.000000 x	1.047200 =	83.776000	
119		4.000000 x	10.001019 =	40.004076	
118		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
213		5.000000 x	3.930000 =	19.650000	
212		2.000000 x	1.300000 =	2.600000	
314		1.000000 x	4.400000 =	4.400000	
			ΑΘΡΟΙΣΜΑ =	393.905940	
			Η.Δ. =	433.296534	

405	405				
211		40.000000 x	1.047200 =	41.888000	
118		4.000000 x	21.778427 =	87.113708	
213		2.000000 x	3.930000 =	7.860000	
315		1.000000 x	53.630000 =	53.630000	
316		2.000000 x	4.400000 =	8.800000	
115		16.000000 x	20.419486 =	326.711776	

			ΑΘΡΟΙΣΜΑ =	526.003484	

			Η.Δ. =	578.603832	
406	406				
211		80.000000 x	1.047200 =	83.776000	
213		5.000000 x	3.930000 =	19.650000	
120		8.000000 x	16.777917 =	134.223336	
317		1.000000 x	122.460000 =	122.460000	

			ΑΘΡΟΙΣΜΑ =	360.109336	

			Η.Δ. =	396.120270	
407	407				
212		17.000000 x	1.300000 =	22.100000	
118		4.000000 x	21.778427 =	87.113708	
112		30.000000 x	17.312112 =	519.363360	
318		1.000000 x	26.580000 =	26.580000	
213		1.000000 x	3.930000 =	3.930000	

			ΑΘΡΟΙΣΜΑ =	659.087068	

			Η.Δ. =	724.995775	
408	408				
211		30.000000 x	1.047200 =	31.416000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
213		3.000000 x	3.930000 =	11.790000	
112		4.000000 x	17.312112 =	69.248448	
320		1.000000 x	152.240000 =	152.240000	

			ΑΘΡΟΙΣΜΑ =	495.788060	

			Η.Δ. =	545.366866	
409	409				
211		50.000000 x	1.047200 =	52.360000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
213		5.000000 x	3.930000 =	19.650000	
324		1.000000 x	179.890000 =	179.890000	

			ΑΘΡΟΙΣΜΑ =	552.242060	

			Η.Δ. =	607.466266	

410	410				
211		100.000000 x	1.047200 =	104.720000	
112		4.000000 x	17.312112 =	69.248448	
321		1.000000 x	207.240000 =	207.240000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
213		10.000000 x	3.930000 =	39.300000	

				ΑΘΡΟΙΣΜΑ =	651.602060

				Η.Δ. =	716.762266
411	411				
211		200.000000 x	1.047200 =	209.440000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
325		1.000000 x	308.130000 =	308.130000	
213		20.000000 x	3.930000 =	78.600000	

				ΑΘΡΟΙΣΜΑ =	896.512060

				Η.Δ. =	986.163266
412	412				
211		40.000000 x	1.047200 =	41.888000	
213		2.000000 x	3.930000 =	7.860000	
326		1.000000 x	100.390000 =	100.390000	
116		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	341.227536

				Η.Δ. =	375.350290
413	413				
211		15.000000 x	1.047200 =	15.708000	
118		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
327		1.000000 x	4.400000 =	4.400000	
213		1.500000 x	3.930000 =	5.895000	

				ΑΘΡΟΙΣΜΑ =	143.274617

				Η.Δ. =	157.602079
501	501				
211		170.000000 x	1.047200 =	178.024000	
380		1.000000 x	552.590000 =	552.590000	
213		3.000000 x	3.930000 =	11.790000	
351		1.000000 x	438.810000 =	438.810000	

				ΑΘΡΟΙΣΜΑ =	1,181.214000

				Η.Δ. =	1,299.335400

502	502				
211		170.000000 x	1.047200 =	178.024000	
352		1.000000 x	372.560000 =	372.560000	
381		1.000000 x	552.590000 =	552.590000	
213		3.000000 x	3.930000 =	11.790000	

			ΑΘΡΟΙΣΜΑ =	1,114.964000	

			Η.Δ. =	1,226.460400	
503	503				
211		170.000000 x	1.047200 =	178.024000	
382		1.000000 x	552.590000 =	552.590000	
353		1.000000 x	438.810000 =	438.810000	
213		3.000000 x	3.930000 =	11.790000	

			ΑΘΡΟΙΣΜΑ =	1,181.214000	

			Η.Δ. =	1,299.335400	
504	504				
211		190.000000 x	1.047200 =	198.968000	
383		1.000000 x	635.530000 =	635.530000	
354		1.000000 x	575.700000 =	575.700000	
213		6.000000 x	3.930000 =	23.580000	

			ΑΘΡΟΙΣΜΑ =	1,433.778000	

			Η.Δ. =	1,577.155800	
505	505				
211		1,250.000000 x	1.047200 =	1,309.000000	
384		1.000000 x	1,052.620000 =	1,052.620000	
213		7.500000 x	3.930000 =	29.475000	
355		1.000000 x	287.930000 =	287.930000	

			ΑΘΡΟΙΣΜΑ =	2,679.025000	

			Η.Δ. =	2,946.927500	
506	506				
211		200.000000 x	1.047200 =	209.440000	
213		2.000000 x	3.930000 =	7.860000	
356		1.000000 x	47.250000 =	47.250000	
385		1.000000 x	191.250000 =	191.250000	

			ΑΘΡΟΙΣΜΑ =	455.800000	

			Η.Δ. =	501.380000	
507	507				
211		2,100.000000 x	1.047200 =	2,199.120000	
213		35.000000 x	3.930000 =	137.550000	
357		1.000000 x	226.390000 =	226.390000	
386		1.000000 x	504.640000 =	504.640000	

			ΑΘΡΟΙΣΜΑ =	3,067.700000	

			Η.Δ. =	3,313.116000	

508	508				
358		1.000000 x	45.580000 =		45.580000
387		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	118.390000
				Η.Δ. =	124.309500
509	509				
359		1.000000 x	94.500000 =		94.500000
388		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	167.310000
				Η.Δ. =	175.675500
510	510				
360		1.000000 x	99.520000 =		99.520000
389		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	172.330000
				Η.Δ. =	180.946500
511	511				
509		.800000 x	175.675500 =		140.540400
				Η.Δ. =	140.540400
512	512				
501		.600000 x	1,299.335400 =		779.601240
				Η.Δ. =	779.601240
513	513				
363		1.000000 x	99.670000 =		99.670000
121		8.000000 x	16.585068 =		132.680544
123		8.000000 x	64.260999 =		514.087992
122		8.000000 x	13.510339 =		108.082712
				Η.Δ. =	854.521248
1111A	1111A				
214		.200000 x	1.949500 =		.389900
511		.020000 x	140.540400 =		2.810808
513		.020000 x	854.521248 =		17.090425
405		.020000 x	578.603832 =		11.572077
				B.T =	31.863210

1111B	1111B				
501		1.000000 x	1,299.335400 =		1,299.335400
506		1.000000 x	501.380000 =		501.380000
509		2.000000 x	175.675500 =		351.351000
			AΘΡΟΙΣΜΑ =		2,152.066400
	B.T =	.002500 x	2,152.066400 =		5.380166
1112A	1112A				
506		1.000000 x	501.380000 =		501.380000
512		1.000000 x	779.601240 =		779.601240
			AΘΡΟΙΣΜΑ =		1,280.981240
	B.T =	.025000 x	1,280.981240 =		32.024531
1112B	1112B				
1111B		1.000000 x	5.380166 =		5.380166
			B.T =		5.380166
1113A	1113A				
214		.200000 x	1.949500 =		.389900
405		.025000 x	578.603832 =		14.465096
112		.250000 x	17.312112 =		4.328028
513		.035000 x	854.521248 =		29.908244
511		.035000 x	140.540400 =		4.918914
			B.T =		54.010181
1113B	1113B				
1111B		1.000000 x	5.380166 =		5.380166
			B.T =		5.380166
1114A	1114A				
112		.250000 x	17.312112 =		4.328028
512		.033000 x	779.601240 =		25.726841
506		.033000 x	501.380000 =		16.545540
			B.T =		46.600409
1114B	1114B				
1111B		1.000000 x	5.380166 =		5.380166
			B.T =		5.380166

1121A	1121A			
214		.150000 x	1.949500 =	.292425
115		.500000 x	20.419486 =	10.209743
405		.020000 x	578.603832 =	11.572077

			B.T =	22.074245
1121B	1121B			
1111B		1.000000 x	5.380166 =	5.380166

			B.T =	5.380166
1122A	1122A			
506		1.000000 x	501.380000 =	501.380000
512		1.000000 x	779.601240 =	779.601240

			AΘΡΟΙΣΜΑ =	1,280.981240
	B.T =	.012500 x	1,280.981240 =	16.012266

1122B	1122B			
1111B		1.000000 x	5.380166 =	5.380166

			B.T =	5.380166
1123A	1123A			
214		.150000 x	1.949500 =	.292425
115		1.000000 x	20.419486 =	20.419486
112		.150000 x	17.312112 =	2.596817
405		.025000 x	578.603832 =	14.465096

			B.T =	37.773824
1123B	1123B			
1111B		1.000000 x	5.380166 =	5.380166

			B.T =	5.380166
1124A	1124A			
112		.150000 x	17.312112 =	2.596817
506		.020000 x	501.380000 =	10.027600
512		.020000 x	779.601240 =	15.592025

			B.T =	28.216442
1124B	1124B			
1111B		1.000000 x	5.380166 =	5.380166

			B.T =	5.380166

3110A 1

3110A 1

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	2.931290 =	.732823
701	2	.800000 x	4.690064 =	3.752051
701	2	.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
607		.500000 x	10.040089 =	5.020045
606		.800000 x	9.163352 =	7.330682
407		.040000 x	724.995775 =	28.999831
714		1.400000 x	7.211824 =	10.096554
113		1.200000 x	20.419486 =	24.503383
319		.020000 x	21.440000 =	.428800
112		1.200000 x	17.312112 =	20.774534

B.T =

129.746745

3110A 2

3110A 2

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	2.931290 =	.732823
701	4	.500000 x	4.396935 =	2.198468
701	2	.800000 x	4.690064 =	3.752051
630		.250000 x	3.152042 =	.788011
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
407		.040000 x	724.995775 =	28.999831
611		.500000 x	25.067906 =	12.533953
606		.800000 x	9.163352 =	7.330682
714		1.400000 x	7.211824 =	10.096554
319		.020000 x	21.440000 =	.428800

B.T =

137.114089

3110A 3

3110A 3

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	2.931290 =	.732823
701	4	.800000 x	4.396935 =	3.517548
701	2	.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
610		.800000 x	21.367057 =	17.093646
607		.500000 x	10.040089 =	5.020045
407		.040000 x	724.995775 =	28.999831
714		1.400000 x	7.211824 =	10.096554
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	21.440000 =	.428800

B.T =

139.275205

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
714		1.400000 x	7.211824 =	10.096554
701 5		.250000 x	2.931290 =	.732823
701 4		.800000 x	4.396935 =	3.517548
701 4		.500000 x	4.396935 =	2.198468
630		.250000 x	3.152042 =	.788011
611		.500000 x	25.067906 =	12.533953
610		.800000 x	21.367057 =	17.093646
407		.040000 x	724.995775 =	28.999831
112		1.200000 x	17.312112 =	20.774534

			B.T =	146.642549
3110B	3110B			
713 1		1.000000 x	5.560874 =	5.560874
704		1.000000 x	11.121747 =	11.121747

			B.T =	16.682621
3120A 1	3120A 1			
3110A 1		1.000000 x	129.746745 =	129.746745

			B.T =	129.746745
3120A 2	3120A 2			
3110A 2		1.000000 x	137.114089 =	137.114089

			B.T =	137.114089
3120A 3	3120A 3			
3110A 3		1.000000 x	139.275205 =	139.275205

			B.T =	139.275205
3120A 4	3120A 4			
3110A 4		1.000000 x	146.642549 =	146.642549

			B.T =	146.642549
3120B	3120B			
713 2		1.000000 x	6.039328 =	6.039328
705		1.000000 x	12.078656 =	12.078656

			B.T =	18.117984

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.690064 =	1.500820
601		.320000 x	23.612397 =	7.555967
3110A 1		.800000 x	129.746745 =	103.797396

			B.T =	119.150823
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	137.114089 =	109.691271
601		.320000 x	23.612397 =	7.555967
701 2		.320000 x	4.690064 =	1.500820

			B.T =	125.044698
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	139.275205 =	111.420164
701 2		.320000 x	4.690064 =	1.500820
601		.320000 x	23.612397 =	7.555967

			B.T =	126.773591
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
3110A 4		.800000 x	146.642549 =	117.314039
701 2		.320000 x	4.690064 =	1.500820
601		.320000 x	23.612397 =	7.555967

			B.T =	132.667466
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.690064 =	1.500820
609		.320000 x	19.765145 =	6.324846
3110A 1		.800000 x	129.746745 =	103.797396

			B.T =	117.919702
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	137.114089 =	109.691271
609		.320000 x	19.765145 =	6.324846
701 2		.320000 x	4.690064 =	1.500820

			B.T =	123.813577

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	139.275205 =	111.420164
701 2		.320000 x	4.690064 =	1.500820
609		.320000 x	19.765145 =	6.324846

			B.T =	125.542470
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
3110A 4		.800000 x	146.642549 =	117.314039
701 2		.320000 x	4.690064 =	1.500820
609		.320000 x	19.765145 =	6.324846

			B.T =	131.436345
3210B	3210B			
713 1		1.000000 x	5.560874 =	5.560874
704		1.000000 x	11.121747 =	11.121747

			B.T =	16.682621
3220A 1	3220A 1			
3210A 1		1.000000 x	119.150823 =	119.150823

			B.T =	119.150823
3220A 2	3220A 2			
3210A 2		1.000000 x	125.044698 =	125.044698

			B.T =	125.044698
3220A 3	3220A 3			
3210A 3		1.000000 x	126.773591 =	126.773591

			B.T =	126.773591
3220A 4	3220A 4			
3210A 4		1.000000 x	132.667466 =	132.667466

			B.T =	132.667466
3220A 5	3220A 5			
3210A 5		1.000000 x	117.919702 =	117.919702

			B.T =	117.919702

3220A 6	3220A 6			
3210A 6		1.000000 x	123.813577 =	123.813577

			B.T =	123.813577
3220A 7	3220A 7			
3210A 7		1.000000 x	125.542470 =	125.542470

			B.T =	125.542470
3220A 8	3220A 8			
3210A 8		1.000000 x	131.436345 =	131.436345

			B.T =	131.436345
3220B	3220B			
713 2		1.000000 x	6.039328 =	6.039328
705		1.000000 x	12.078656 =	12.078656

			B.T =	18.117984
3300A 1	3300A 1			
221		300.000000 x	.099900 =	29.970000
113		2.000000 x	20.419486 =	40.838972
606		.800000 x	9.163352 =	7.330682
630		.250000 x	3.152042 =	.788011
701 2		.500000 x	4.690064 =	2.345032
701 5		.250000 x	2.931290 =	.732823
701 2		.800000 x	4.690064 =	3.752051
607		.500000 x	10.040089 =	5.020045
407		.040000 x	724.995775 =	28.999831
319		.040000 x	21.440000 =	.857600
714		2.600000 x	7.211824 =	18.750742
111		2.700000 x	15.741598 =	42.502315

			B.T =	181.888102
3300A 2	3300A 2			
221		300.000000 x	.099900 =	29.970000
319		.040000 x	21.440000 =	.857600
701 5		.250000 x	2.931290 =	.732823
701 4		.500000 x	4.396935 =	2.198468
701 2		.800000 x	4.690064 =	3.752051
630		.250000 x	3.152042 =	.788011
611		.500000 x	25.067906 =	12.533953
606		.800000 x	9.163352 =	7.330682
407		.040000 x	724.995775 =	28.999831
714		2.600000 x	7.211824 =	18.750742
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315

			B.T =	189.255446

3300A 3	3300A 3			
221		300.000000 x	.099900 =	29.970000
319		.040000 x	21.440000 =	.857600
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
714		2.600000 x	7.211824 =	18.750742
701 5		.250000 x	2.931290 =	.732823
701 4		.800000 x	4.396935 =	3.517548
701 2		.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
610		.800000 x	21.367057 =	17.093646
607		.500000 x	10.040089 =	5.020045
407		.040000 x	724.995775 =	28.999831

			B.T =	191.416563
3300A 4	3300A 4			
221		300.000000 x	.099900 =	29.970000
111		2.700000 x	15.741598 =	42.502315
113		2.000000 x	20.419486 =	40.838972
630		.250000 x	3.152042 =	.788011
701 5		.250000 x	2.931290 =	.732823
701 4		.800000 x	4.396935 =	3.517548
701 4		.500000 x	4.396935 =	2.198468
611		.500000 x	25.067906 =	12.533953
610		.800000 x	21.367057 =	17.093646
407		.040000 x	724.995775 =	28.999831
714		2.600000 x	7.211824 =	18.750742
319		.040000 x	21.440000 =	.857600

			B.T =	198.783907
3300B 1	3300B 1			
713 1		1.000000 x	5.560874 =	5.560874
704		1.000000 x	11.121747 =	11.121747

			B.T =	16.682621
3300B 2	3300B 2			
713 2		1.000000 x	6.039328 =	6.039328
705		1.000000 x	12.078656 =	12.078656

			B.T =	18.117984

3400A 1

3400A 1

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	2.931290 =	.732823
701	2	.800000 x	4.690064 =	3.752051
701	2	.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
607		.500000 x	10.040089 =	5.020045
606		.800000 x	9.163352 =	7.330682
407		.040000 x	724.995775 =	28.999831
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200
255		5.000000 x	.901300 =	4.506500

B.T =

194.951315

3400A 2

3400A 2

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	2.931290 =	.732823
701	4	.500000 x	4.396935 =	2.198468
701	2	.800000 x	4.690064 =	3.752051
630		.250000 x	3.152042 =	.788011
611		.500000 x	25.067906 =	12.533953
606		.800000 x	9.163352 =	7.330682
255		5.000000 x	.901300 =	4.506500
319		.030000 x	21.440000 =	.643200
113		.500000 x	20.419486 =	10.209743
407		.040000 x	724.995775 =	28.999831
113		2.000000 x	20.419486 =	40.838972
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315

B.T =

202.318659

3400A 3

3400A 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	2.931290 =	.732823
701	4	.800000 x	4.396935 =	3.517548
701	2	.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
610		.800000 x	21.367057 =	17.093646
607		.500000 x	10.040089 =	5.020045
407		.040000 x	724.995775 =	28.999831
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
255		5.000000 x	.901300 =	4.506500
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200

B.T =

204.479776

3400A 4

3400A 4

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	2.931290 =	.732823
701	4	.800000 x	4.396935 =	3.517548
701	4	.500000 x	4.396935 =	2.198468
630		.250000 x	3.152042 =	.788011
611		.500000 x	25.067906 =	12.533953
610		.800000 x	21.367057 =	17.093646
255		5.000000 x	.901300 =	4.506500
111		2.700000 x	15.741598 =	42.502315
113		.500000 x	20.419486 =	10.209743
407		.040000 x	724.995775 =	28.999831
113		2.000000 x	20.419486 =	40.838972
112		1.000000 x	17.312112 =	17.312112
319		.030000 x	21.440000 =	.643200

B.T =

211.847120

3400B 1

3400B 1

704		1.000000 x	11.121747 =	11.121747
-----	--	------------	-------------	-----------

B.T =

11.121747

3400B 2

3400B 2

705		1.000000 x	12.078656 =	12.078656
-----	--	------------	-------------	-----------

B.T =

12.078656

4110A 1

4110A 1

221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
701	5	.100000 x	2.931290 =	.293129
701	2	.800000 x	4.690064 =	3.752051
701	2	.500000 x	4.690064 =	2.345032
630		.100000 x	3.152042 =	.315204
607		.500000 x	10.040089 =	5.020045
606		.800000 x	9.163352 =	7.330682
407		.070000 x	724.995775 =	50.749704
113		1.500000 x	20.419486 =	30.629229

B.T =

198.366468

4110A 2	4110A 2			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
407		.070000 x	724.995775 =	50.749704
606		.800000 x	9.163352 =	7.330682
701 5		.100000 x	2.931290 =	.293129
701 4		.500000 x	4.396935 =	2.198468
701 2		.800000 x	4.690064 =	3.752051
630		.100000 x	3.152042 =	.315204
611		.500000 x	25.067906 =	12.533953
113		1.500000 x	20.419486 =	30.629229

B.T = 205.733812

4110A 3	4110A 3			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
701 5		.100000 x	2.931290 =	.293129
701 4		.800000 x	4.396935 =	3.517548
701 2		.500000 x	4.690064 =	2.345032
630		.100000 x	3.152042 =	.315204
610		.800000 x	21.367057 =	17.093646
607		.500000 x	10.040089 =	5.020045
407		.070000 x	724.995775 =	50.749704
113		1.500000 x	20.419486 =	30.629229

B.T = 207.894929

4110A 4	4110A 4			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	2.931290 =	.293129
701 4		.800000 x	4.396935 =	3.517548
701 4		.500000 x	4.396935 =	2.198468
630		.100000 x	3.152042 =	.315204
611		.500000 x	25.067906 =	12.533953
610		.800000 x	21.367057 =	17.093646
407		.070000 x	724.995775 =	50.749704
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

B.T = 215.262273

4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
506		1.000000 x	501.380000 =	501.380000
513		1.000000 x	854.521248 =	854.521248
508		1.000000 x	124.309500 =	124.309500

B.T = 1,618.707644

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.540000 =	22.680000
607		1.200000 x	10.040089 =	12.048107
701 2		1.200000 x	4.690064 =	5.628077
112		5.000000 x	17.312112 =	86.560560

			B.T =	161.881744
4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
112		5.000000 x	17.312112 =	86.560560
611		1.200000 x	25.067906 =	30.081487
701 4		1.200000 x	4.396935 =	5.276322
263		42.000000 x	.540000 =	22.680000

			B.T =	179.563369
4120B	4120B			
4110B		.040000 x	1,618.707644 =	64.748306

			B.T =	64.748306
4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.741598 =	31.483196
407		.050000 x	724.995775 =	36.249789
606		.800000 x	9.163352 =	7.330682
607		.500000 x	10.040089 =	5.020045
701 2		.500000 x	4.690064 =	2.345032
701 2		.800000 x	4.690064 =	3.752051
263		42.000000 x	.540000 =	22.680000

			B.T =	143.825794
4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	724.995775 =	36.249789
701 4		.500000 x	4.396935 =	2.198468
701 2		.800000 x	4.690064 =	3.752051
611		.500000 x	25.067906 =	12.533953
606		.800000 x	9.163352 =	7.330682
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

			B.T =	151.193138

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
701 4		.800000 x	4.396935 =	3.517548
701 2		.500000 x	4.690064 =	2.345032
610		.800000 x	21.367057 =	17.093646
607		.500000 x	10.040089 =	5.020045
407		.050000 x	724.995775 =	36.249789
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

B.T = 153.354255

4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.396935 =	2.198468
701 4		.800000 x	4.396935 =	3.517548
611		.500000 x	25.067906 =	12.533953
610		.800000 x	21.367057 =	17.093646
407		.050000 x	724.995775 =	36.249789
263		42.000000 x	.540000 =	22.680000
111		2.000000 x	15.741598 =	31.483196

B.T = 160.721599

4130B	4130B			
4120B		1.000000 x	64.748306 =	64.748306

B.T = 64.748306

4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
630		.150000 x	3.152042 =	.472806
701 5		.150000 x	2.931290 =	.439694
701 2		.300000 x	4.690064 =	1.407019
701 2		1.050000 x	4.690064 =	4.924567
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.040089 =	3.012027
601		1.050000 x	23.612397 =	24.793017

B.T = 42.242630

4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	2.931290 =	.439694
701 4		.300000 x	4.396935 =	1.319081
630		.150000 x	3.152042 =	.472806
611		.300000 x	25.067906 =	7.520372
701 2		1.050000 x	4.690064 =	4.924567
222		10.000000 x	.070000 =	.700000
601		1.050000 x	23.612397 =	24.793017

B.T = 46.663036

4210A 3

4210A 3

221		65.000000 x	.099900 =	6.493500
701	5	.150000 x	2.931290 =	.439694
701	2	.300000 x	4.690064 =	1.407019
701	2	1.050000 x	4.690064 =	4.924567
630		.150000 x	3.152042 =	.472806
609		1.050000 x	19.765145 =	20.753402
607		.300000 x	10.040089 =	3.012027
222		10.000000 x	.070000 =	.700000

B.T =

38.203015

4210A 4

4210A 4

221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
701	5	.150000 x	2.931290 =	.439694
701	4	.300000 x	4.396935 =	1.319081
701	2	1.050000 x	4.690064 =	4.924567
630		.150000 x	3.152042 =	.472806
611		.300000 x	25.067906 =	7.520372
609		1.050000 x	19.765145 =	20.753402

B.T =

42.623422

4210B

4210B

111		4.000000 x	15.741598 =	62.966392
112		1.500000 x	17.312112 =	25.968168
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

B.T =

143.445697

4220A 1

4220A 1

221		200.000000 x	.099900 =	19.980000
701	2	.800000 x	4.690064 =	3.752051
701	2	.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
607		.500000 x	10.040089 =	5.020045
606		.800000 x	9.163352 =	7.330682
407		.040000 x	724.995775 =	28.999831
113		1.000000 x	20.419486 =	20.419486
111		1.200000 x	15.741598 =	18.889918
701	5	.250000 x	2.931290 =	.732823

B.T =

108.257877

4220A 2

4220A 2

221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
611		.500000 x	25.067906 =	12.533953
701	5	.250000 x	2.931290 =	.732823
701	4	.500000 x	4.396935 =	2.198468
701	2	.800000 x	4.690064 =	3.752051
630		.250000 x	3.152042 =	.788011
606		.800000 x	9.163352 =	7.330682
407		.040000 x	724.995775 =	28.999831

B.T =

115.625221

4220A 3

4220A 3

221		200.000000 x	.099900 =	19.980000
701	4	.800000 x	4.396935 =	3.517548
701	2	.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
610		.800000 x	21.367057 =	17.093646
607		.500000 x	10.040089 =	5.020045
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	724.995775 =	28.999831
113		1.000000 x	20.419486 =	20.419486
701	5	.250000 x	2.931290 =	.732823

B.T =

117.786338

4220A 4

4220A 4

221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	724.995775 =	28.999831
611		.500000 x	25.067906 =	12.533953
701	5	.250000 x	2.931290 =	.732823
701	4	.500000 x	4.396935 =	2.198468
701	4	.800000 x	4.396935 =	3.517548
630		.250000 x	3.152042 =	.788011
610		.800000 x	21.367057 =	17.093646
113		1.000000 x	20.419486 =	20.419486

B.T =

125.153682

4300A 1	4300A 1			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	2.931290 =	.732823
701 2		.800000 x	4.690064 =	3.752051
701 2		.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
607		.500000 x	10.040089 =	5.020045
606		.800000 x	9.163352 =	7.330682
407		.040000 x	724.995775 =	28.999831
111		2.000000 x	15.741598 =	31.483196
714		1.150000 x	7.211824 =	8.293598
113		1.200000 x	20.419486 =	24.503383
			AΘΡΟΙΣΜΑ =	148.213650
	B.T =	.200000 x	148.213650 =	29.642730
4300A 2	4300A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	2.931290 =	.732823
701 4		.500000 x	4.396935 =	2.198468
701 2		.800000 x	4.690064 =	3.752051
111		2.000000 x	15.741598 =	31.483196
714		1.150000 x	7.211824 =	8.293598
606		.800000 x	9.163352 =	7.330682
630		.250000 x	3.152042 =	.788011
611		.500000 x	25.067906 =	12.533953
407		.040000 x	724.995775 =	28.999831
113		1.200000 x	20.419486 =	24.503383
			AΘΡΟΙΣΜΑ =	155.580994
	B.T =	.200000 x	155.580994 =	31.116199
4300A 3	4300A 3			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	2.931290 =	.732823
701 4		.800000 x	4.396935 =	3.517548
701 2		.500000 x	4.690064 =	2.345032
630		.250000 x	3.152042 =	.788011
610		.800000 x	21.367057 =	17.093646
607		.500000 x	10.040089 =	5.020045
407		.040000 x	724.995775 =	28.999831
714		1.150000 x	7.211824 =	8.293598
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
			AΘΡΟΙΣΜΑ =	157.742111
	B.T =	.200000 x	157.742111 =	31.548422

4300A 4	4300A 4			
221		350.000000 x	.099900 =	34.965000
611		.500000 x	25.067906 =	12.533953
701 5		.250000 x	2.931290 =	.732823
701 4		.800000 x	4.396935 =	3.517548
701 4		.500000 x	4.396935 =	2.198468
630		.250000 x	3.152042 =	.788011
610		.800000 x	21.367057 =	17.093646
407		.040000 x	724.995775 =	28.999831
714		1.150000 x	7.211824 =	8.293598
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

			ΑΘΡΟΙΣΜΑ =	165.109455
	B.T =	.200000 x	165.109455 =	33.021891

4300B	4300B			
221		2.000000 x	.099900 =	.199800
262		4.000000 x	.980000 =	3.920000
112		.400000 x	17.312112 =	6.924845

			B.T =	11.044645
601	601			
111		1.500000 x	15.741598 =	23.612397

			B.T =	23.612397
602	602			
403		.002500 x	650.918057 =	1.627295

			B.T =	1.627295
603	603			
111		.300000 x	15.741598 =	4.722479
412		.003300 x	375.350290 =	1.238656
401		.001000 x	891.952173 =	.891952

			B.T =	6.853088
604	604			
111		.200000 x	15.741598 =	3.148320
401		.001100 x	891.952173 =	.981147
404		.005000 x	433.296534 =	2.166483
412		.004000 x	375.350290 =	1.501401

			B.T =	7.797351

605	605				
112		.100000 x	17.312112 =	1.731211	
401		.001000 x	891.952173 =	.891952	
412		.004000 x	375.350290 =	1.501401	
406		.006200 x	396.120270 =	2.455946	
402		.006200 x	860.662642 =	5.336108	
			B.T =	11.916619	
606	606				
111		.100000 x	15.741598 =	1.574160	
412		.005000 x	375.350290 =	1.876751	
406		.006700 x	396.120270 =	2.654006	
404		.005000 x	433.296534 =	2.166483	
401		.001000 x	891.952173 =	.891952	
			B.T =	9.163352	
607	607				
111		.100000 x	15.741598 =	1.574160	
412		.005000 x	375.350290 =	1.876751	
406		.006700 x	396.120270 =	2.654006	
404		.006200 x	433.296534 =	2.686439	
401		.001400 x	891.952173 =	1.248733	
			B.T =	10.040089	
608	608				
111		.100000 x	15.741598 =	1.574160	
412		.005000 x	375.350290 =	1.876751	
406		.006700 x	396.120270 =	2.654006	
404		.012500 x	433.296534 =	5.416207	
401		.002000 x	891.952173 =	1.783904	
			B.T =	13.305028	
609	609				
214		.100000 x	1.949500 =	.194950	
405		.005000 x	578.603832 =	2.893019	
115		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
			B.T =	19.765145	

615	615				
214		.150000 x	1.949500 =	.292425	
111		.700000 x	15.741598 =	11.019119	
405		.005000 x	578.603832 =	2.893019	
410		.010000 x	716.762266 =	7.167623	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	25.456083	
	B.T =	1.832000 x	25.456083 =	46.635543	
616	616				
214		.150000 x	1.949500 =	.292425	
111		.800000 x	15.741598 =	12.593278	
411		.010000 x	986.163266 =	9.861633	
405		.005000 x	578.603832 =	2.893019	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	29.724252	
	B.T =	2.137000 x	29.724252 =	63.520727	
617	617				
112		4.000000 x	17.312112 =	69.248448	
506		1.000000 x	501.380000 =	501.380000	
513		1.000000 x	854.521248 =	854.521248	
503		1.000000 x	1,299.335400 =	1,299.335400	
			AΘΡΟΙΣΜΑ =	2,724.485096	
	B.T =	.006250 x	2,724.485096 =	17.028032	
618	618				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	854.521248 =	854.521248	
506		1.000000 x	501.380000 =	501.380000	
503		1.000000 x	1,299.335400 =	1,299.335400	
			AΘΡΟΙΣΜΑ =	2,724.485096	
	B.T =	.007700 x	2,724.485096 =	20.978535	
619	619				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	854.521248 =	854.521248	
506		1.000000 x	501.380000 =	501.380000	
503		1.000000 x	1,299.335400 =	1,299.335400	
			AΘΡΟΙΣΜΑ =	2,724.485096	
	B.T =	.010000 x	2,724.485096 =	27.244851	

620	620			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,299.335400 =	1,299.335400
506		1.000000 x	501.380000 =	501.380000
513		1.000000 x	854.521248 =	854.521248

			ΑΘΡΟΙΣΜΑ =	2,724.485096
	B.T =	.012500 x	2,724.485096 =	34.056064

621	621			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	501.380000 =	501.380000
503		1.000000 x	1,299.335400 =	1,299.335400
513		1.000000 x	854.521248 =	854.521248

			ΑΘΡΟΙΣΜΑ =	2,724.485096
	B.T =	.016600 x	2,724.485096 =	45.226453

630	630			
413		.020000 x	157.602079 =	3.152042

			B.T =	3.152042
701 1	701 1			
406		.012580 x	396.120270 =	4.983193

			B.T =	4.983193
701 2	701 2			
406		.011840 x	396.120270 =	4.690064

			B.T =	4.690064
701 3	701 3			
406		.011544 x	396.120270 =	4.572812

			B.T =	4.572812
701 4	701 4			
406		.011100 x	396.120270 =	4.396935

			B.T =	4.396935
701 5	701 5			
406		.007400 x	396.120270 =	2.931290

			B.T =	2.931290

702	702			
112		8.000000 x	17.312112 =	138.496896
513		.300000 x	854.521248 =	256.356374
509		2.000000 x	175.675500 =	351.351000
506		1.000000 x	501.380000 =	501.380000

			ΑΘΡΟΙΣΜΑ =	1,247.584270
	B.T =	.002500 x	1,247.584270 =	3.118961

703	703			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,299.335400 =	1,299.335400
506		1.000000 x	501.380000 =	501.380000
513		.300000 x	854.521248 =	256.356374
510		2.000000 x	180.946500 =	361.893000

			ΑΘΡΟΙΣΜΑ =	2,488.213222
	B.T =	.002500 x	2,488.213222 =	6.220533

704	704			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	501.380000 =	501.380000
513		.500000 x	854.521248 =	427.260624
502		1.000000 x	1,226.460400 =	1,226.460400

			ΑΘΡΟΙΣΜΑ =	2,224.349472
	B.T =	.005000 x	2,224.349472 =	11.121747

705	705			
112		4.000000 x	17.312112 =	69.248448
513		.600000 x	854.521248 =	512.712749
504		1.000000 x	1,577.155800 =	1,577.155800
506		1.000000 x	501.380000 =	501.380000

			ΑΘΡΟΙΣΜΑ =	2,660.496997
	B.T =	.004540 x	2,660.496997 =	12.078656

706	706			
501		1.000000 x	1,299.335400 =	1,299.335400
506		1.000000 x	501.380000 =	501.380000
509		2.000000 x	175.675500 =	351.351000

			ΑΘΡΟΙΣΜΑ =	2,152.066400
	B.T =	.002500 x	2,152.066400 =	5.380166

707	707			
505		1.000000 x	2,946.927500 =	2,946.927500
510		2.000000 x	180.946500 =	361.893000
506		1.000000 x	501.380000 =	501.380000

			ΑΘΡΟΙΣΜΑ =	3,810.200500
	B.T =	.001000 x	3,810.200500 =	3.810201

ΑΤΛΕ		3ο Τρίμηνο του 2010		Σελ.	31
				Ημ/νία	16/07/2011
708	708				
708A		1.000000 x	17.280639 =		17.280639
708B		1.000000 x	5.380166 =		5.380166

			B.T =		22.660805
708A	708A				
214		.050000 x	1.949500 =		.097475
513		.010000 x	854.521248 =		8.545212
511		.010000 x	140.540400 =		1.405404
405		.012500 x	578.603832 =		7.232548

			B.T =		17.280639
708B	708B				
706		1.000000 x	5.380166 =		5.380166

			B.T =		5.380166
709	709				
709A		1.000000 x	16.012266 =		16.012266
709B		1.000000 x	5.380166 =		5.380166

			B.T =		21.392432
709A	709A				
506		1.000000 x	501.380000 =		501.380000
512		1.000000 x	779.601240 =		779.601240

			AΘΡΟΙΣΜΑ =		1,280.981240
	B.T =	.012500 x	1,280.981240 =		16.012266

709B	709B				
706		1.000000 x	5.380166 =		5.380166

			B.T =		5.380166
710	710				
710A		1.000000 x	49.682153 =		49.682153
710B		1.000000 x	5.380166 =		5.380166

			B.T =		55.062319
710A	710A				
214		.200000 x	1.949500 =		.389900
405		.025000 x	578.603832 =		14.465096
513		.035000 x	854.521248 =		29.908244
511		.035000 x	140.540400 =		4.918914

			B.T =		49.682153

710B	710B			
706		1.000000 x	5.380166 =	5.380166

			B.T =	5.380166
711	711			
711A		1.000000 x	42.656675 =	42.656675
711B		1.000000 x	5.380166 =	5.380166

			B.T =	48.036841
711A	711A			
506		1.000000 x	501.380000 =	501.380000
512		1.000000 x	779.601240 =	779.601240

			AΘΡΟΙΣΜΑ =	1,280.981240
	B.T =	.033300 x	1,280.981240 =	42.656675

711B	711B			
706		1.000000 x	5.380166 =	5.380166

			B.T =	5.380166
712	712			
513		1.000000 x	854.521248 =	854.521248

			AΘΡΟΙΣΜΑ =	854.521248
	B.T =	.004000 x	854.521248 =	3.418085

713 1	713 1			
704		.500000 x	11.121747 =	5.560874

			B.T =	5.560874
713 2	713 2			
705		.500000 x	12.078656 =	6.039328

			B.T =	6.039328
714	714			
714A		1.000000 x	3.438664 =	3.438664
714B		1.000000 x	3.773160 =	3.773160

			B.T =	7.211824

714A	714A			
242		.070000 x	370.000000 =	25.900000
113		2.000000 x	20.419486 =	40.838972
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	1.900000 =	1.900000
			AΘΡΟΙΣΜΑ =	103.263196
	B.T =	.033300 x	103.263196 =	3.438664
714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211
			B.T =	3.773160
1111	1111			
1111A		1.000000 x	31.863210 =	31.863210
1111B		1.000000 x	5.380166 =	5.380166
			T.E =	37.243376
1112	1112			
1112A		1.000000 x	32.024531 =	32.024531
1112B		1.000000 x	5.380166 =	5.380166
			T.E =	37.404697
1113	1113			
1113A		1.000000 x	54.010181 =	54.010181
1113B		1.000000 x	5.380166 =	5.380166
			T.E =	59.390347
1114	1114			
1114A		1.000000 x	46.600409 =	46.600409
1114B		1.000000 x	5.380166 =	5.380166
			T.E =	51.980575
1121	1121			
1121A		1.000000 x	22.074245 =	22.074245
1121B		1.000000 x	5.380166 =	5.380166
			T.E =	27.454411
1122	1122			
1122A		1.000000 x	16.012266 =	16.012266
1122B		1.000000 x	5.380166 =	5.380166
			T.E =	21.392432

1123	1123				
1123A		1.000000 x	37.773824 =		37.773824
1123B		1.000000 x	5.380166 =		5.380166

			T.E =		43.153990
1124	1124				
1124A		1.000000 x	28.216442 =		28.216442
1124B		1.000000 x	5.380166 =		5.380166

			T.E =		33.596608
1210	1210				
707		1.000000 x	3.810201 =		3.810201

			T.E =		3.810201
1220	1220				
708		1.000000 x	22.660805 =		22.660805

			T.E =		22.660805
1230	1230				
709		1.000000 x	21.392432 =		21.392432

			T.E =		21.392432
1311	1311				
712		.250000 x	3.418085 =		.854521

			T.E =		.854521
1312	1312				
712		.250000 x	3.418085 =		.854521
701 1		1.000000 x	4.983193 =		4.983193
602		1.000000 x	1.627295 =		1.627295

			T.E =		7.465009
1313	1313				
712		.250000 x	3.418085 =		.854521
603		1.000000 x	6.853088 =		6.853088
701 2		1.000000 x	4.690064 =		4.690064

			T.E =		12.397673

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
712		.250000 x	3.418085 =	.854521	

			T.E =	37.428681	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
602		1.000000 x	1.627295 =	1.627295	
701	1	1.000000 x	4.983193 =	4.983193	

			T.E =	10.072910	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
701	2	1.000000 x	4.690064 =	4.690064	
603		1.000000 x	6.853088 =	6.853088	

			T.E =	15.005574	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
112		.100000 x	17.312112 =	1.731211	
111		.100000 x	15.741598 =	1.574160	

			T.E =	38.305371	
2110	2110				
712		.500000 x	3.418085 =	1.709043	
608		1.000000 x	13.305028 =	13.305028	
702		1.000000 x	3.118961 =	3.118961	
701	4	1.000000 x	4.396935 =	4.396935	

			T.E =	22.529967	
2120	2120				
712		.500000 x	3.418085 =	1.709043	
603		1.000000 x	6.853088 =	6.853088	
702		1.000000 x	3.118961 =	3.118961	
701	2	1.000000 x	4.690064 =	4.690064	

			T.E =	16.371156	
2130	2130				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.118961 =	3.118961	
604		1.000000 x	7.797351 =	7.797351	
701	2	1.000000 x	4.690064 =	4.690064	

			T.E =	17.315419	

2140	2140				
712		.500000 x	3.418085 =	1.709043	
701	2	1.000000 x	4.690064 =	4.690064	
702		1.000000 x	3.118961 =	3.118961	
605		1.000000 x	11.916619 =	11.916619	
			T.E =	21.434687	
2210	2210				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.118961 =	3.118961	
701	2	1.000000 x	4.690064 =	4.690064	
609		1.050000 x	19.765145 =	20.753402	
			T.E =	30.271470	
2220	2220				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.118961 =	3.118961	
701	2	1.000000 x	4.690064 =	4.690064	
609		1.150000 x	19.765145 =	22.729917	
			T.E =	32.247984	
2230	2230				
111		.200000 x	15.741598 =	3.148320	
609		1.200000 x	19.765145 =	23.718174	
701	2	1.000000 x	4.690064 =	4.690064	
			T.E =	31.556558	
2240	2240				
111		.300000 x	15.741598 =	4.722479	
609		1.200000 x	19.765145 =	23.718174	
701	2	1.000000 x	4.690064 =	4.690064	
			T.E =	33.130717	
2310	2310				
612		1.000000 x	18.631783 =	18.631783	
701	3	1.000000 x	4.572812 =	4.572812	
703		1.000000 x	6.220533 =	6.220533	
			T.E =	29.425128	
2320	2320				
613		1.000000 x	27.197377 =	27.197377	
703		1.000000 x	6.220533 =	6.220533	
701	3	1.000000 x	4.572812 =	4.572812	
			T.E =	37.990722	

2330	2330				
614		1.000000 x	35.737036 =		35.737036
703		1.000000 x	6.220533 =		6.220533
701	3	1.000000 x	4.572812 =		4.572812

			T.E =		46.530381
2340	2340				
615		1.000000 x	46.635543 =		46.635543
703		1.000000 x	6.220533 =		6.220533
701	3	1.000000 x	4.572812 =		4.572812

			T.E =		57.428888
2350	2350				
616		1.000000 x	63.520727 =		63.520727
703		1.000000 x	6.220533 =		6.220533
701	3	1.000000 x	4.572812 =		4.572812

			T.E =		74.314072
2410	2410				
617		1.000000 x	17.028032 =		17.028032
703		1.000000 x	6.220533 =		6.220533

			T.E =		23.248565
2420	2420				
618		1.000000 x	20.978535 =		20.978535
703		1.000000 x	6.220533 =		6.220533

			T.E =		27.199068
2430	2430				
619		1.000000 x	27.244851 =		27.244851
703		1.000000 x	6.220533 =		6.220533

			T.E =		33.465384
2440	2440				
620		1.000000 x	34.056064 =		34.056064
703		1.000000 x	6.220533 =		6.220533

			T.E =		40.276597
2450	2450				
621		1.000000 x	45.226453 =		45.226453
703		1.000000 x	6.220533 =		6.220533

			T.E =		51.446986

3110 1	3110 1				
3110A 1		1.000000 x	129.746745 =		129.746745
3110B		1.000000 x	16.682621 =		16.682621

			T.E =		146.429366
3110 2	3110 2				
3110A 2		1.000000 x	137.114089 =		137.114089
3110B		1.000000 x	16.682621 =		16.682621

			T.E =		153.796710
3110 3	3110 3				
3110A 3		1.000000 x	139.275205 =		139.275205
3110B		1.000000 x	16.682621 =		16.682621

			T.E =		155.957826
3110 4	3110 4				
3110A 4		1.000000 x	146.642549 =		146.642549
3110B		1.000000 x	16.682621 =		16.682621

			T.E =		163.325170
3120 1	3120 1				
3120A 1		1.000000 x	129.746745 =		129.746745
3120B		1.000000 x	18.117984 =		18.117984

			T.E =		147.864729
3120 2	3120 2				
3120A 2		1.000000 x	137.114089 =		137.114089
3120B		1.000000 x	18.117984 =		18.117984

			T.E =		155.232073
3120 3	3120 3				
3120A 3		1.000000 x	139.275205 =		139.275205
3120B		1.000000 x	18.117984 =		18.117984

			T.E =		157.393189
3120 4	3120 4				
3120A 4		1.000000 x	146.642549 =		146.642549
3120B		1.000000 x	18.117984 =		18.117984

			T.E =		164.760533

3210 1	3210 1				
3210A 1		1.000000 x	119.150823 =		119.150823
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		135.833444
3210 2	3210 2				
3210A 2		1.000000 x	125.044698 =		125.044698
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		141.727319
3210 3	3210 3				
3210A 3		1.000000 x	126.773591 =		126.773591
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		143.456212
3210 4	3210 4				
3210A 4		1.000000 x	132.667466 =		132.667466
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		149.350087
3210 5	3210 5				
3210A 5		1.000000 x	117.919702 =		117.919702
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		134.602323
3210 6	3210 6				
3210A 6		1.000000 x	123.813577 =		123.813577
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		140.496198
3210 7	3210 7				
3210A 7		1.000000 x	125.542470 =		125.542470
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		142.225091
3210 8	3210 8				
3210A 8		1.000000 x	131.436345 =		131.436345
3210B		1.000000 x	16.682621 =		16.682621

			T.E =		148.118966

3220	1	3220	1				
	3220A 1			1.000000 x	119.150823 =		119.150823
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		137.268807
3220	2	3220	2				
	3220A 2			1.000000 x	125.044698 =		125.044698
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		143.162682
3220	3	3220	3				
	3220A 3			1.000000 x	126.773591 =		126.773591
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		144.891575
3220	4	3220	4				
	3220A 4			1.000000 x	132.667466 =		132.667466
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		150.785450
3220	5	3220	5				
	3220A 5			1.000000 x	117.919702 =		117.919702
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		136.037686
3220	6	3220	6				
	3220A 6			1.000000 x	123.813577 =		123.813577
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		141.931561
3220	7	3220	7				
	3220A 7			1.000000 x	125.542470 =		125.542470
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		143.660454
3220	8	3220	8				
	3220A 8			1.000000 x	131.436345 =		131.436345
	3220B			1.000000 x	18.117984 =		18.117984

					T.E =		149.554329

3300 1	3300 1				
3300A 1		1.000000 x	181.888102 =	181.888102	
3300B 1		1.000000 x	16.682621 =	16.682621	

			T.E =	198.570723	
3300 2	3300 2				
3300A 1		1.000000 x	181.888102 =	181.888102	
3300B 2		1.000000 x	18.117984 =	18.117984	

			T.E =	200.006086	
3300 3	3300 3				
3300A 2		1.000000 x	189.255446 =	189.255446	
3300B 1		1.000000 x	16.682621 =	16.682621	

			T.E =	205.938067	
3300 4	3300 4				
3300A 2		1.000000 x	189.255446 =	189.255446	
3300B 2		1.000000 x	18.117984 =	18.117984	

			T.E =	207.373430	
3300 5	3300 5				
3300A 3		1.000000 x	191.416563 =	191.416563	
3300B 1		1.000000 x	16.682621 =	16.682621	

			T.E =	208.099184	
3300 6	3300 6				
3300A 3		1.000000 x	191.416563 =	191.416563	
3300B 2		1.000000 x	18.117984 =	18.117984	

			T.E =	209.534547	
3300 7	3300 7				
3300A 4		1.000000 x	198.783907 =	198.783907	
3300B 1		1.000000 x	16.682621 =	16.682621	

			T.E =	215.466528	
3300 8	3300 8				
3300A 4		1.000000 x	198.783907 =	198.783907	
3300B 2		1.000000 x	18.117984 =	18.117984	

			T.E =	216.901891	

3400	1	3400	1				
	3400A	1		1.000000 x	194.951315 =		194.951315
	3400B	1		1.000000 x	11.121747 =		11.121747

					T.E =		206.073062
3400	2	3400	2				
	3400A	1		1.000000 x	194.951315 =		194.951315
	3400B	2		1.000000 x	12.078656 =		12.078656

					T.E =		207.029971
3400	3	3400	3				
	3400A	2		1.000000 x	202.318659 =		202.318659
	3400B	1		1.000000 x	11.121747 =		11.121747

					T.E =		213.440406
3400	4	3400	4				
	3400A	2		1.000000 x	202.318659 =		202.318659
	3400B	2		1.000000 x	12.078656 =		12.078656

					T.E =		214.397315
3400	5	3400	5				
	3400A	3		1.000000 x	204.479776 =		204.479776
	3400B	1		1.000000 x	11.121747 =		11.121747

					T.E =		215.601523
3400	6	3400	6				
	3400A	3		1.000000 x	204.479776 =		204.479776
	3400B	2		1.000000 x	12.078656 =		12.078656

					T.E =		216.558432
3400	7	3400	7				
	3400A	4		1.000000 x	211.847120 =		211.847120
	3400B	1		1.000000 x	11.121747 =		11.121747

					T.E =		222.968867
3400	8	3400	8				
	3400A	4		1.000000 x	211.847120 =		211.847120
	3400B	2		1.000000 x	12.078656 =		12.078656

					T.E =		223.925776

4110	1	4110	1				
	4110A	1		1.000000 x	198.366468 =		198.366468
	4110B			.025000 x	1,618.707644 =		40.467691

						T.E =	238.834159
4110	2	4110	2				
	4110A	2		1.000000 x	205.733812 =		205.733812
	4110B			.025000 x	1,618.707644 =		40.467691

						T.E =	246.201503
4110	3	4110	3				
	4110A	3		1.000000 x	207.894929 =		207.894929
	4110B			.025000 x	1,618.707644 =		40.467691

						T.E =	248.362620
4110	4	4110	4				
	4110A	4		1.000000 x	215.262273 =		215.262273
	4110B			.025000 x	1,618.707644 =		40.467691

						T.E =	255.729964
4120	1	4120	1				
	4120A	1		1.000000 x	161.881744 =		161.881744
	4120B			1.000000 x	64.748306 =		64.748306

						T.E =	226.630050
4120	2	4120	2				
	4120A	2		1.000000 x	179.563369 =		179.563369
	4120B			1.000000 x	64.748306 =		64.748306

						T.E =	244.311675
4130	1	4130	1				
	4130A	1		1.000000 x	143.825794 =		143.825794
	4130B			1.000000 x	64.748306 =		64.748306

						T.E =	208.574100
4130	2	4130	2				
	4130A	2		1.000000 x	151.193138 =		151.193138
	4130B			1.000000 x	64.748306 =		64.748306

						T.E =	215.941444

4130	3	4130	3			
4130A	3			1.000000 x	153.354255 =	153.354255
4130B				1.000000 x	64.748306 =	64.748306

				T.E =		218.102561
4130	4	4130	4			
4130A	4			1.000000 x	160.721599 =	160.721599
4130B				1.000000 x	64.748306 =	64.748306

				T.E =		225.469905
4210	1	4210	1			
4210A	1			1.000000 x	42.242630 =	42.242630
4210B				1.000000 x	143.445697 =	143.445697

				T.E =		185.688327
4210	2	4210	2			
4210A	2			1.000000 x	46.663036 =	46.663036
4210B				1.000000 x	143.445697 =	143.445697

				T.E =		190.108733
4210	3	4210	3			
4210A	3			1.000000 x	38.203015 =	38.203015
4210B				1.000000 x	143.445697 =	143.445697

				T.E =		181.648712
4210	4	4210	4			
4210A	4			1.000000 x	42.623422 =	42.623422
4210B				1.000000 x	143.445697 =	143.445697

				T.E =		186.069119
4220B	1	4220B	1			
319				.020000 x	21.440000 =	.428800
701	2			.320000 x	4.690064 =	1.500820
601				.320000 x	23.612397 =	7.555967
4220A	1			.800000 x	108.257877 =	86.606302
714				1.150000 x	7.211824 =	8.293598
111				.400000 x	15.741598 =	6.296639

				T.E =		110.682126

4220B 2	4220B 2			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.211824 =	8.293598
701 2		.320000 x	4.690064 =	1.500820
601		.320000 x	23.612397 =	7.555967
4220A 2		.800000 x	115.625221 =	92.500177

T.E = 116.576001

4220B 3	4220B 3			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.690064 =	1.500820
601		.320000 x	23.612397 =	7.555967
111		.400000 x	15.741598 =	6.296639
4220A 3		.800000 x	117.786338 =	94.229070
714		1.150000 x	7.211824 =	8.293598

T.E = 118.304895

4220B 4	4220B 4			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	125.153682 =	100.122946
701 2		.320000 x	4.690064 =	1.500820
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.211824 =	8.293598

T.E = 124.198770

4220B 5	4220B 5			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.690064 =	1.500820
609		.320000 x	19.765145 =	6.324846
4220A 1		.800000 x	108.257877 =	86.606302
714		1.150000 x	7.211824 =	8.293598
111		.400000 x	15.741598 =	6.296639

T.E = 109.451005

4220B 6	4220B 6			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.211824 =	8.293598
701 2		.320000 x	4.690064 =	1.500820
609		.320000 x	19.765145 =	6.324846
4220A 2		.800000 x	115.625221 =	92.500177

T.E = 115.344880

4220B 7	4220B 7			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.690064 =	1.500820
609		.320000 x	19.765145 =	6.324846
111		.400000 x	15.741598 =	6.296639
4220A 3		.800000 x	117.786338 =	94.229070
714		1.150000 x	7.211824 =	8.293598

T.E = 117.073774

4220B 8	4220B 8			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	125.153682 =	100.122946
701 2		.320000 x	4.690064 =	1.500820
609		.320000 x	19.765145 =	6.324846
714		1.150000 x	7.211824 =	8.293598

T.E = 122.967649

4230 1	4230 1			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	2.931290 =	.732823
701 2		.500000 x	4.690064 =	2.345032
701 2		.800000 x	4.690064 =	3.752051
630		.250000 x	3.152042 =	.788011
607		.500000 x	10.040089 =	5.020045
606		.800000 x	9.163352 =	7.330682
407		.040000 x	724.995775 =	28.999831
714		1.150000 x	7.211824 =	8.293598
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

T.E = 138.652450

4230 2	4230 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	2.931290 =	.732823
701 4		.500000 x	4.396935 =	2.198468
701 2		.800000 x	4.690064 =	3.752051
630		.250000 x	3.152042 =	.788011
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
407		.040000 x	724.995775 =	28.999831
611		.500000 x	25.067906 =	12.533953
606		.800000 x	9.163352 =	7.330682
714		1.150000 x	7.211824 =	8.293598
111		2.000000 x	15.741598 =	31.483196

T.E = 146.019794

4230	3	4230	3			
221				250.000000 x	.099900 =	24.975000
701	5			.250000 x	2.931290 =	.732823
701	4			.800000 x	4.396935 =	3.517548
701	2			.500000 x	4.690064 =	2.345032
630				.250000 x	3.152042 =	.788011
610				.800000 x	21.367057 =	17.093646
607				.500000 x	10.040089 =	5.020045
407				.040000 x	724.995775 =	28.999831
714				1.150000 x	7.211824 =	8.293598
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196
319				.020000 x	21.440000 =	.428800

T.E = 148.180911

4230	4	4230	4			
221				250.000000 x	.099900 =	24.975000
701	5			.250000 x	2.931290 =	.732823
701	4			.500000 x	4.396935 =	2.198468
701	4			.800000 x	4.396935 =	3.517548
630				.250000 x	3.152042 =	.788011
319				.020000 x	21.440000 =	.428800
111				2.000000 x	15.741598 =	31.483196
407				.040000 x	724.995775 =	28.999831
611				.500000 x	25.067906 =	12.533953
610				.800000 x	21.367057 =	17.093646
714				1.150000 x	7.211824 =	8.293598
113				1.200000 x	20.419486 =	24.503383

T.E = 155.548255

4240	1	4240	1			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	2.931290 =	.732823
701	2			.500000 x	4.690064 =	2.345032
701	2			.800000 x	4.690064 =	3.752051
630				.250000 x	3.152042 =	.788011
607				.500000 x	10.040089 =	5.020045
606				.800000 x	9.163352 =	7.330682
407				.040000 x	724.995775 =	28.999831
714				1.150000 x	7.211824 =	8.293598
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196

T.E = 143.647450

4240	2	4240	2			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	2.931290 =	.732823
701	4			.500000 x	4.396935 =	2.198468
701	2			.800000 x	4.690064 =	3.752051
630				.250000 x	3.152042 =	.788011
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
407				.040000 x	724.995775 =	28.999831
611				.500000 x	25.067906 =	12.533953
606				.800000 x	9.163352 =	7.330682
714				1.150000 x	7.211824 =	8.293598
111				2.000000 x	15.741598 =	31.483196

T.E = 151.014794

4240	3	4240	3			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	2.931290 =	.732823
701	4			.800000 x	4.396935 =	3.517548
701	2			.500000 x	4.690064 =	2.345032
630				.250000 x	3.152042 =	.788011
610				.800000 x	21.367057 =	17.093646
607				.500000 x	10.040089 =	5.020045
407				.040000 x	724.995775 =	28.999831
714				1.150000 x	7.211824 =	8.293598
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196
319				.020000 x	21.440000 =	.428800

T.E = 153.175911

4240	4	4240	4			
221				300.000000 x	.099900 =	29.970000
319				.020000 x	21.440000 =	.428800
111				2.000000 x	15.741598 =	31.483196
714				1.150000 x	7.211824 =	8.293598
701	5			.250000 x	2.931290 =	.732823
701	4			.500000 x	4.396935 =	2.198468
701	4			.800000 x	4.396935 =	3.517548
630				.250000 x	3.152042 =	.788011
611				.500000 x	25.067906 =	12.533953
610				.800000 x	21.367057 =	17.093646
407				.040000 x	724.995775 =	28.999831
113				1.200000 x	20.419486 =	24.503383

T.E = 160.543255

4300	1	4300	1			
4300A	1			1.000000 x	29.642730 =	29.642730
4300B				1.000000 x	11.044645 =	11.044645

T.E = 40.687375

4300	2	4300	2				
	4300A	2		1.000000 x	31.116199 =	31.116199	
	4300B			1.000000 x	11.044645 =	11.044645	

						T.E =	42.160844
4300	3	4300	3				
	4300A	3		1.000000 x	31.548422 =	31.548422	
	4300B			1.000000 x	11.044645 =	11.044645	

						T.E =	42.593067
4300	4	4300	4				
	4300A	4		1.000000 x	33.021891 =	33.021891	
	4300B			1.000000 x	11.044645 =	11.044645	

						T.E =	44.066536
4400		4400					
	251			1.050000 x	.583300 =	.612465	
	113			.050000 x	20.419486 =	1.020974	

						T.E =	1.633439
4500		4500					
	251			1.050000 x	.583300 =	.612465	
	113			.100000 x	20.419486 =	2.041949	
	114			.100000 x	17.312112 =	1.731211	

						T.E =	4.385625
4600		4600					
	256			1.000000 x	3.800000 =	3.800000	
	113			.100000 x	20.419486 =	2.041949	

						T.E =	5.841949
4700		4700					
	253			1.000000 x	4.000000 =	4.000000	
	113			.100000 x	20.419486 =	2.041949	

						T.E =	6.041949