

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

4ο Τρίμηνο του 2010

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	1.056100
212	1.291000
213	3.930000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.538600
252	2.020000
253	4.000000
254	5.000000
255	.939000
256	3.800000
261	
262	.980000
263	.540000
311	425.280000
312	130.670000
313	200.790000
314	4.400000
315	53.630000
316	4.400000
317	122.460000
318	26.580000
319	21.440000
320	152.240000
321	207.240000
322	287.930000
323	327.890000
324	179.890000
325	308.130000
326	100.390000
327	4.400000
351	438.810000
352	372.560000
353	438.810000
354	575.700000
355	287.930000
356	47.250000
357	226.390000
358	45.580000
359	94.500000
360	99.520000

361	76.120000
362	263.460000
363	99.670000
380	552.590000
381	552.590000
382	552.590000
383	635.530000
384	1,052.620000
385	191.250000
386	504.640000
387	72.810000
388	72.810000
389	72.810000

401	401				
211		110.000000 x	1.056100 =	116.171000	
213		10.000000 x	3.930000 =	39.300000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
311		1.000000 x	425.280000 =	425.280000	
			ΑΘΡΟΙΣΜΑ =	811.844612	
			Η.Δ. =	893.029073	
402	402				
211		180.000000 x	1.056100 =	190.098000	
312		1.000000 x	130.670000 =	130.670000	
112		8.000000 x	17.312112 =	138.496896	
212		5.000000 x	1.291000 =	6.455000	
213		12.000000 x	3.930000 =	47.160000	
116		8.000000 x	23.886192 =	191.089536	
117		8.000000 x	10.001019 =	80.008152	
			ΑΘΡΟΙΣΜΑ =	783.977584	
			Η.Δ. =	862.375342	
403	403				
211		80.000000 x	1.056100 =	84.488000	
254		2.500000 x	5.000000 =	12.500000	
213		6.000000 x	3.930000 =	23.580000	
117		8.000000 x	10.001019 =	80.008152	
116		8.000000 x	23.886192 =	191.089536	
313		1.000000 x	200.790000 =	200.790000	
			ΑΘΡΟΙΣΜΑ =	592.455688	
			Η.Δ. =	651.701257	
404	404				
211		80.000000 x	1.056100 =	84.488000	
213		5.000000 x	3.930000 =	19.650000	
212		2.000000 x	1.291000 =	2.582000	
119		4.000000 x	10.001019 =	40.004076	
118		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
314		1.000000 x	4.400000 =	4.400000	
			ΑΘΡΟΙΣΜΑ =	394.599940	
			Η.Δ. =	434.059934	

405	405				
211		40.000000 x	1.056100 =	42.244000	
213		2.000000 x	3.930000 =	7.860000	
115		16.000000 x	20.419486 =	326.711776	
118		4.000000 x	21.778427 =	87.113708	
316		2.000000 x	4.400000 =	8.800000	
315		1.000000 x	53.630000 =	53.630000	
		-----			
		ΑΘΡΟΙΣΜΑ =		526.359484	
		-----			
		H.Δ. =		578.995432	
406	406				
211		80.000000 x	1.056100 =	84.488000	
213		5.000000 x	3.930000 =	19.650000	
317		1.000000 x	122.460000 =	122.460000	
120		8.000000 x	16.777917 =	134.223336	
		-----			
		ΑΘΡΟΙΣΜΑ =		360.821336	
		-----			
		H.Δ. =		396.903470	
407	407				
212		17.000000 x	1.291000 =	21.947000	
318		1.000000 x	26.580000 =	26.580000	
112		30.000000 x	17.312112 =	519.363360	
213		1.000000 x	3.930000 =	3.930000	
118		4.000000 x	21.778427 =	87.113708	
		-----			
		ΑΘΡΟΙΣΜΑ =		658.934068	
		-----			
		H.Δ. =		724.827475	
408	408				
211		30.000000 x	1.056100 =	31.683000	
112		4.000000 x	17.312112 =	69.248448	
116		8.000000 x	23.886192 =	191.089536	
117		4.000000 x	10.001019 =	40.004076	
320		1.000000 x	152.240000 =	152.240000	
213		3.000000 x	3.930000 =	11.790000	
		-----			
		ΑΘΡΟΙΣΜΑ =		496.055060	
		-----			
		H.Δ. =		545.660566	
409	409				
211		50.000000 x	1.056100 =	52.805000	
112		4.000000 x	17.312112 =	69.248448	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
324		1.000000 x	179.890000 =	179.890000	
213		5.000000 x	3.930000 =	19.650000	
		-----			
		ΑΘΡΟΙΣΜΑ =		552.687060	
		-----			
		H.Δ. =		607.955766	

410	410				
211		100.000000 x	1.056100 =	105.610000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
321		1.000000 x	207.240000 =	207.240000	
213		10.000000 x	3.930000 =	39.300000	
				-----	
				ΑΘΡΟΙΣΜΑ =	652.492060
				-----	
				Η.Δ. =	717.741266
411	411				
211		200.000000 x	1.056100 =	211.220000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
213		20.000000 x	3.930000 =	78.600000	
325		1.000000 x	308.130000 =	308.130000	
				-----	
				ΑΘΡΟΙΣΜΑ =	898.292060
				-----	
				Η.Δ. =	988.121266
412	412				
211		40.000000 x	1.056100 =	42.244000	
116		8.000000 x	23.886192 =	191.089536	
326		1.000000 x	100.390000 =	100.390000	
213		2.000000 x	3.930000 =	7.860000	
				-----	
				ΑΘΡΟΙΣΜΑ =	341.583536
				-----	
				Η.Δ. =	375.741890
413	413				
211		15.000000 x	1.056100 =	15.841500	
213		1.500000 x	3.930000 =	5.895000	
118		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
327		1.000000 x	4.400000 =	4.400000	
				-----	
				ΑΘΡΟΙΣΜΑ =	143.408117
				-----	
				Η.Δ. =	157.748929
501	501				
211		170.000000 x	1.056100 =	179.537000	
351		1.000000 x	438.810000 =	438.810000	
380		1.000000 x	552.590000 =	552.590000	
213		3.000000 x	3.930000 =	11.790000	
				-----	
				ΑΘΡΟΙΣΜΑ =	1,182.727000
				-----	
				Η.Δ. =	1,300.999700

502	502				
211		170.000000 x	1.056100 =	179.537000	
381		1.000000 x	552.590000 =	552.590000	
352		1.000000 x	372.560000 =	372.560000	
213		3.000000 x	3.930000 =	11.790000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,116.477000	
		-----			
			Η.Δ. =	1,228.124700	
503	503				
211		170.000000 x	1.056100 =	179.537000	
213		3.000000 x	3.930000 =	11.790000	
353		1.000000 x	438.810000 =	438.810000	
382		1.000000 x	552.590000 =	552.590000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,182.727000	
		-----			
			Η.Δ. =	1,300.999700	
504	504				
211		190.000000 x	1.056100 =	200.659000	
213		6.000000 x	3.930000 =	23.580000	
383		1.000000 x	635.530000 =	635.530000	
354		1.000000 x	575.700000 =	575.700000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,435.469000	
		-----			
			Η.Δ. =	1,579.015900	
505	505				
211		1,250.000000 x	1.056100 =	1,320.125000	
213		7.500000 x	3.930000 =	29.475000	
384		1.000000 x	1,052.620000 =	1,052.620000	
355		1.000000 x	287.930000 =	287.930000	
		-----			
			ΑΘΡΟΙΣΜΑ =	2,690.150000	
		-----			
			Η.Δ. =	2,959.165000	
506	506				
211		200.000000 x	1.056100 =	211.220000	
385		1.000000 x	191.250000 =	191.250000	
356		1.000000 x	47.250000 =	47.250000	
213		2.000000 x	3.930000 =	7.860000	
		-----			
			ΑΘΡΟΙΣΜΑ =	457.580000	
		-----			
			Η.Δ. =	503.338000	
507	507				
211		2,100.000000 x	1.056100 =	2,217.810000	
213		35.000000 x	3.930000 =	137.550000	
386		1.000000 x	504.640000 =	504.640000	
357		1.000000 x	226.390000 =	226.390000	
		-----			
			ΑΘΡΟΙΣΜΑ =	3,086.390000	
		-----			
			Η.Δ. =	3,333.301200	

508	508				
358		1.000000 x	45.580000 =		45.580000
387		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	118.390000
				Η.Δ. =	124.309500
509	509				
359		1.000000 x	94.500000 =		94.500000
388		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	167.310000
				Η.Δ. =	175.675500
510	510				
360		1.000000 x	99.520000 =		99.520000
389		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	172.330000
				Η.Δ. =	180.946500
511	511				
509		.800000 x	175.675500 =		140.540400
				Η.Δ. =	140.540400
512	512				
501		.600000 x	1,300.999700 =		780.599820
				Η.Δ. =	780.599820
513	513				
363		1.000000 x	99.670000 =		99.670000
121		8.000000 x	16.585068 =		132.680544
122		8.000000 x	13.510339 =		108.082712
123		8.000000 x	64.260999 =		514.087992
				Η.Δ. =	854.521248
1111A	1111A				
214		.200000 x	1.949500 =		.389900
405		.020000 x	578.995432 =		11.579909
511		.020000 x	140.540400 =		2.810808
513		.020000 x	854.521248 =		17.090425
				Β.Τ =	31.871042



1111B	1111B			
501		1.000000 x	1,300.999700 =	1,300.999700
506		1.000000 x	503.338000 =	503.338000
509		2.000000 x	175.675500 =	351.351000
			-----	
			AΘΡΟΙΣΜΑ =	2,155.688700
	B.T =	.002500 x	2,155.688700 =	5.389222
			-----	
1112A	1112A			
506		1.000000 x	503.338000 =	503.338000
512		1.000000 x	780.599820 =	780.599820
			-----	
			AΘΡΟΙΣΜΑ =	1,283.937820
	B.T =	.025000 x	1,283.937820 =	32.098446
			-----	
1112B	1112B			
1111B		1.000000 x	5.389222 =	5.389222
			-----	
			B.T =	5.389222
1113A	1113A			
214		.200000 x	1.949500 =	.389900
112		.250000 x	17.312112 =	4.328028
513		.035000 x	854.521248 =	29.908244
511		.035000 x	140.540400 =	4.918914
405		.025000 x	578.995432 =	14.474886
			-----	
			B.T =	54.019971
1113B	1113B			
1111B		1.000000 x	5.389222 =	5.389222
			-----	
			B.T =	5.389222
1114A	1114A			
112		.250000 x	17.312112 =	4.328028
506		.033000 x	503.338000 =	16.610154
512		.033000 x	780.599820 =	25.759794
			-----	
			B.T =	46.697976
1114B	1114B			
1111B		1.000000 x	5.389222 =	5.389222
			-----	
			B.T =	5.389222

1121A	1121A				
214		.150000 x	1.949500 =		.292425
405		.020000 x	578.995432 =		11.579909
115		.500000 x	20.419486 =		10.209743
		-----			
			B.T =		22.082077
1121B	1121B				
1111B		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		5.389222
1122A	1122A				
506		1.000000 x	503.338000 =		503.338000
512		1.000000 x	780.599820 =		780.599820
		-----			
			AΘΡΟΙΣΜΑ =		1,283.937820
	B.T =	.012500 x	1,283.937820 =		16.049223
		-----			
1122B	1122B				
1111B		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		5.389222
1123A	1123A				
214		.150000 x	1.949500 =		.292425
405		.025000 x	578.995432 =		14.474886
112		.150000 x	17.312112 =		2.596817
115		1.000000 x	20.419486 =		20.419486
		-----			
			B.T =		37.783614
1123B	1123B				
1111B		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		5.389222
1124A	1124A				
112		.150000 x	17.312112 =		2.596817
512		.020000 x	780.599820 =		15.611996
506		.020000 x	503.338000 =		10.066760
		-----			
			B.T =		28.275573
1124B	1124B				
1111B		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		5.389222

3110A 1	3110A 1			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	2.937086 =	.734272
701 2		.800000 x	4.699337 =	3.759470
701 2		.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
607		.500000 x	10.053535 =	5.026768
606		.800000 x	9.175451 =	7.340361
407		.040000 x	724.827475 =	28.993099
714		1.400000 x	7.215820 =	10.102148
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	21.440000 =	.428800

-----  
B.T = 129.776247

3110A 2	3110A 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	2.937086 =	.734272
701 4		.500000 x	4.405629 =	2.202815
701 2		.800000 x	4.699337 =	3.759470
630		.250000 x	3.154979 =	.788745
319		.020000 x	21.440000 =	.428800
112		1.200000 x	17.312112 =	20.774534
407		.040000 x	724.827475 =	28.993099
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
714		1.400000 x	7.215820 =	10.102148
113		1.200000 x	20.419486 =	24.503383

-----  
B.T = 137.152741

3110A 3	3110A 3			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	2.937086 =	.734272
701 4		.800000 x	4.405629 =	3.524503
701 2		.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
610		.800000 x	21.392016 =	17.113613
607		.500000 x	10.053535 =	5.026768
407		.040000 x	724.827475 =	28.993099
714		1.400000 x	7.215820 =	10.102148
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534

-----  
B.T = 139.314533

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
714		1.400000 x	7.215820 =	10.102148
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	2.937086 =	.734272
701 4		.800000 x	4.405629 =	3.524503
701 4		.500000 x	4.405629 =	2.202815
630		.250000 x	3.154979 =	.788745
611		.500000 x	25.100230 =	12.550115
610		.800000 x	21.392016 =	17.113613
407		.040000 x	724.827475 =	28.993099
112		1.200000 x	17.312112 =	20.774534
				-----
			B.T =	146.691026
3110B	3110B			
713 1		1.000000 x	5.569930 =	5.569930
704		1.000000 x	11.139859 =	11.139859
				-----
			B.T =	16.709789
3120A 1	3120A 1			
3110A 1		1.000000 x	129.776247 =	129.776247
				-----
			B.T =	129.776247
3120A 2	3120A 2			
3110A 2		1.000000 x	137.152741 =	137.152741
				-----
			B.T =	137.152741
3120A 3	3120A 3			
3110A 3		1.000000 x	139.314533 =	139.314533
				-----
			B.T =	139.314533
3120A 4	3120A 4			
3110A 4		1.000000 x	146.691026 =	146.691026
				-----
			B.T =	146.691026
3120B	3120B			
713 2		1.000000 x	6.047996 =	6.047996
705		1.000000 x	12.095991 =	12.095991
				-----
			B.T =	18.143987

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.699337 =	1.503788
601		.320000 x	23.612397 =	7.555967
3110A 1		.800000 x	129.776247 =	103.820998
-----				
			B.T =	119.177392
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	137.152741 =	109.722193
701 2		.320000 x	4.699337 =	1.503788
601		.320000 x	23.612397 =	7.555967
-----				
			B.T =	125.078587
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	139.314533 =	111.451626
701 2		.320000 x	4.699337 =	1.503788
601		.320000 x	23.612397 =	7.555967
-----				
			B.T =	126.808020
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.699337 =	1.503788
601		.320000 x	23.612397 =	7.555967
3110A 4		.800000 x	146.691026 =	117.352821
-----				
			B.T =	132.709215
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
3110A 1		.800000 x	129.776247 =	103.820998
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
-----				
			B.T =	117.946898
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
3110A 2		.800000 x	137.152741 =	109.722193
-----				
			B.T =	123.848093

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
3110A 3		.800000 x	139.314533 =	111.451626
		-----		
			B.T =	125.577526
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
3110A 4		.800000 x	146.691026 =	117.352821
		-----		
			B.T =	131.478721
3210B	3210B			
713 1		1.000000 x	5.569930 =	5.569930
704		1.000000 x	11.139859 =	11.139859
		-----		
			B.T =	16.709789
3220A 1	3220A 1			
3210A 1		1.000000 x	119.177392 =	119.177392
		-----		
			B.T =	119.177392
3220A 2	3220A 2			
3210A 2		1.000000 x	125.078587 =	125.078587
		-----		
			B.T =	125.078587
3220A 3	3220A 3			
3210A 3		1.000000 x	126.808020 =	126.808020
		-----		
			B.T =	126.808020
3220A 4	3220A 4			
3210A 4		1.000000 x	132.709215 =	132.709215
		-----		
			B.T =	132.709215
3220A 5	3220A 5			
3210A 5		1.000000 x	117.946898 =	117.946898
		-----		
			B.T =	117.946898

3220A 6	3220A 6			
3210A 6		1.000000 x	123.848093 =	123.848093
		-----		
			B.T =	123.848093
3220A 7	3220A 7			
3210A 7		1.000000 x	125.577526 =	125.577526
		-----		
			B.T =	125.577526
3220A 8	3220A 8			
3210A 8		1.000000 x	131.478721 =	131.478721
		-----		
			B.T =	131.478721
3220B	3220B			
713 2		1.000000 x	6.047996 =	6.047996
705		1.000000 x	12.095991 =	12.095991
		-----		
			B.T =	18.143987
3300A 1	3300A 1			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	2.937086 =	.734272
701 2		.500000 x	4.699337 =	2.349669
701 2		.800000 x	4.699337 =	3.759470
630		.250000 x	3.154979 =	.788745
607		.500000 x	10.053535 =	5.026768
606		.800000 x	9.175451 =	7.340361
407		.040000 x	724.827475 =	28.993099
714		2.600000 x	7.215820 =	18.761132
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	21.440000 =	.857600
		-----		
			B.T =	181.922400
3300A 2	3300A 2			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	2.937086 =	.734272
701 4		.500000 x	4.405629 =	2.202815
701 2		.800000 x	4.699337 =	3.759470
630		.250000 x	3.154979 =	.788745
319		.040000 x	21.440000 =	.857600
113		2.000000 x	20.419486 =	40.838972
407		.040000 x	724.827475 =	28.993099
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
714		2.600000 x	7.215820 =	18.761132
111		2.700000 x	15.741598 =	42.502315
		-----		
			B.T =	189.298894

3300A 3

3300A 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	2.937086 =	.734272
701	4	.800000 x	4.405629 =	3.524503
701	2	.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
610		.800000 x	21.392016 =	17.113613
607		.500000 x	10.053535 =	5.026768
407		.040000 x	724.827475 =	28.993099
714		2.600000 x	7.215820 =	18.761132
319		.040000 x	21.440000 =	.857600
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315

B.T =

191.460686

3300A 4

3300A 4

221		300.000000 x	.099900 =	29.970000
113		2.000000 x	20.419486 =	40.838972
714		2.600000 x	7.215820 =	18.761132
111		2.700000 x	15.741598 =	42.502315
701	5	.250000 x	2.937086 =	.734272
701	4	.800000 x	4.405629 =	3.524503
701	4	.500000 x	4.405629 =	2.202815
630		.250000 x	3.154979 =	.788745
611		.500000 x	25.100230 =	12.550115
610		.800000 x	21.392016 =	17.113613
407		.040000 x	724.827475 =	28.993099
319		.040000 x	21.440000 =	.857600

B.T =

198.837179

3300B 1

3300B 1

713	1	1.000000 x	5.569930 =	5.569930
704		1.000000 x	11.139859 =	11.139859

B.T =

16.709789

3300B 2

3300B 2

713	2	1.000000 x	6.047996 =	6.047996
705		1.000000 x	12.095991 =	12.095991

B.T =

18.143987



3400A 1	3400A 1			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.939000 =	4.695000
701 5		.250000 x	2.937086 =	.734272
701 2		.800000 x	4.699337 =	3.759470
701 2		.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
607		.500000 x	10.053535 =	5.026768
606		.800000 x	9.175451 =	7.340361
407		.040000 x	724.827475 =	28.993099
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200

-----  
B.T = 195.163723

3400A 2	3400A 2			
221		300.000000 x	.099900 =	29.970000
407		.040000 x	724.827475 =	28.993099
701 5		.250000 x	2.937086 =	.734272
701 4		.500000 x	4.405629 =	2.202815
701 2		.800000 x	4.699337 =	3.759470
630		.250000 x	3.154979 =	.788745
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200
255		5.000000 x	.939000 =	4.695000

-----  
B.T = 202.540217

3400A 3	3400A 3			
221		300.000000 x	.099900 =	29.970000
111		2.700000 x	15.741598 =	42.502315
701 5		.250000 x	2.937086 =	.734272
701 4		.800000 x	4.405629 =	3.524503
701 2		.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
610		.800000 x	21.392016 =	17.113613
607		.500000 x	10.053535 =	5.026768
407		.040000 x	724.827475 =	28.993099
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
319		.030000 x	21.440000 =	.643200
255		5.000000 x	.939000 =	4.695000

-----  
B.T = 204.702009

3400A 4	3400A 4			
221		300.000000 x	.099900 =	29.970000
407		.040000 x	724.827475 =	28.993099
701 5		.250000 x	2.937086 =	.734272
701 4		.800000 x	4.405629 =	3.524503
701 4		.500000 x	4.405629 =	2.202815
630		.250000 x	3.154979 =	.788745
611		.500000 x	25.100230 =	12.550115
610		.800000 x	21.392016 =	17.113613
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200
255		5.000000 x	.939000 =	4.695000
-----				
			B.T =	212.078502
3400B 1	3400B 1			
704		1.000000 x	11.139859 =	11.139859
-----				
			B.T =	11.139859
3400B 2	3400B 2			
705		1.000000 x	12.095991 =	12.095991
-----				
			B.T =	12.095991
4110A 1	4110A 1			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
701 5		.100000 x	2.937086 =	.293709
701 2		.800000 x	4.699337 =	3.759470
701 2		.500000 x	4.699337 =	2.349669
630		.100000 x	3.154979 =	.315498
607		.500000 x	10.053535 =	5.026768
606		.800000 x	9.175451 =	7.340361
407		.070000 x	724.827475 =	50.737923
113		1.500000 x	20.419486 =	30.629229
-----				
			B.T =	198.384017

4110A 2	4110A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	2.937086 =	.293709
701 4		.500000 x	4.405629 =	2.202815
701 2		.800000 x	4.699337 =	3.759470
630		.100000 x	3.154979 =	.315498
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
407		.070000 x	724.827475 =	50.737923
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

-----  
B.T = 205.760511

4110A 3	4110A 3			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	724.827475 =	50.737923
701 5		.100000 x	2.937086 =	.293709
701 4		.800000 x	4.405629 =	3.524503
701 2		.500000 x	4.699337 =	2.349669
630		.100000 x	3.154979 =	.315498
610		.800000 x	21.392016 =	17.113613
607		.500000 x	10.053535 =	5.026768
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

-----  
B.T = 207.922303

4110A 4	4110A 4			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	724.827475 =	50.737923
610		.800000 x	21.392016 =	17.113613
701 5		.100000 x	2.937086 =	.293709
701 4		.800000 x	4.405629 =	3.524503
701 4		.500000 x	4.405629 =	2.202815
630		.100000 x	3.154979 =	.315498
611		.500000 x	25.100230 =	12.550115
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

-----  
B.T = 215.298796

4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
508		1.000000 x	124.309500 =	124.309500
513		1.000000 x	854.521248 =	854.521248
506		1.000000 x	503.338000 =	503.338000

-----  
B.T = 1,620.665644

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
701 2		1.200000 x	4.699337 =	5.639204
607		1.200000 x	10.053535 =	12.064242
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.312112 =	86.560560
		-----		
			B.T =	161.909006
4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
701 4		1.200000 x	4.405629 =	5.286755
611		1.200000 x	25.100230 =	30.120276
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.312112 =	86.560560
		-----		
			B.T =	179.612591
4120B	4120B			
4110B		.040000 x	1,620.665644 =	64.826626
		-----		
			B.T =	64.826626
4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.540000 =	22.680000
407		.050000 x	724.827475 =	36.241374
606		.800000 x	9.175451 =	7.340361
607		.500000 x	10.053535 =	5.026768
701 2		.500000 x	4.699337 =	2.349669
701 2		.800000 x	4.699337 =	3.759470
111		2.000000 x	15.741598 =	31.483196
		-----		
			B.T =	143.845836
4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	724.827475 =	36.241374
701 4		.500000 x	4.405629 =	2.202815
701 2		.800000 x	4.699337 =	3.759470
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000
		-----		
			B.T =	151.222330

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
701 4		.800000 x	4.405629 =	3.524503
701 2		.500000 x	4.699337 =	2.349669
610		.800000 x	21.392016 =	17.113613
607		.500000 x	10.053535 =	5.026768
407		.050000 x	724.827475 =	36.241374
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

-----  
B.T = 153.384122

4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.405629 =	2.202815
701 4		.800000 x	4.405629 =	3.524503
611		.500000 x	25.100230 =	12.550115
610		.800000 x	21.392016 =	17.113613
407		.050000 x	724.827475 =	36.241374
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

-----  
B.T = 160.760615

4130B	4130B			
4120B		1.000000 x	64.826626 =	64.826626

-----  
B.T = 64.826626

4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	2.937086 =	.440563
601		1.050000 x	23.612397 =	24.793017
630		.150000 x	3.154979 =	.473247
701 2		1.050000 x	4.699337 =	4.934304
701 2		.300000 x	4.699337 =	1.409801
607		.300000 x	10.053535 =	3.016061
222		10.000000 x	.070000 =	.700000

-----  
B.T = 42.260492

4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	2.937086 =	.440563
701 4		.300000 x	4.405629 =	1.321689
701 2		1.050000 x	4.699337 =	4.934304
630		.150000 x	3.154979 =	.473247
611		.300000 x	25.100230 =	7.530069
601		1.050000 x	23.612397 =	24.793017
222		10.000000 x	.070000 =	.700000

-----  
B.T = 46.686388

4210A 3	4210A 3			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.053535 =	3.016061
630		.150000 x	3.154979 =	.473247
701 5		.150000 x	2.937086 =	.440563
701 2		.300000 x	4.699337 =	1.409801
701 2		1.050000 x	4.699337 =	4.934304
609		1.050000 x	19.767103 =	20.755458

-----  
B.T = 38.222933

4210A 4	4210A 4			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.699337 =	4.934304
701 5		.150000 x	2.937086 =	.440563
701 4		.300000 x	4.405629 =	1.321689
609		1.050000 x	19.767103 =	20.755458
630		.150000 x	3.154979 =	.473247
611		.300000 x	25.100230 =	7.530069

-----  
B.T = 42.648829

4210B	4210B			
111		4.000000 x	15.741598 =	62.966392
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
112		1.500000 x	17.312112 =	25.968168

-----  
B.T = 143.445697

4220A 1	4220A 1			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
407		.040000 x	724.827475 =	28.993099
606		.800000 x	9.175451 =	7.340361
607		.500000 x	10.053535 =	5.026768
630		.250000 x	3.154979 =	.788745
701 5		.250000 x	2.937086 =	.734272
701 2		.800000 x	4.699337 =	3.759470
701 2		.500000 x	4.699337 =	2.349669

-----  
B.T = 108.281785

4220A 2      4220A 2

221	200.000000 x	.099900 =	19.980000
113	1.000000 x	20.419486 =	20.419486
606	.800000 x	9.175451 =	7.340361
701 5	.250000 x	2.937086 =	.734272
701 4	.500000 x	4.405629 =	2.202815
701 2	.800000 x	4.699337 =	3.759470
630	.250000 x	3.154979 =	.788745
611	.500000 x	25.100230 =	12.550115
407	.040000 x	724.827475 =	28.993099
111	1.200000 x	15.741598 =	18.889918

-----  
B.T = 115.658279

4220A 3      4220A 3

221	200.000000 x	.099900 =	19.980000
701 4	.800000 x	4.405629 =	3.524503
701 2	.500000 x	4.699337 =	2.349669
630	.250000 x	3.154979 =	.788745
610	.800000 x	21.392016 =	17.113613
607	.500000 x	10.053535 =	5.026768
407	.040000 x	724.827475 =	28.993099
113	1.000000 x	20.419486 =	20.419486
111	1.200000 x	15.741598 =	18.889918
701 5	.250000 x	2.937086 =	.734272

-----  
B.T = 117.820071

4220A 4      4220A 4

221	200.000000 x	.099900 =	19.980000
111	1.200000 x	15.741598 =	18.889918
407	.040000 x	724.827475 =	28.993099
611	.500000 x	25.100230 =	12.550115
701 5	.250000 x	2.937086 =	.734272
701 4	.500000 x	4.405629 =	2.202815
701 4	.800000 x	4.405629 =	3.524503
630	.250000 x	3.154979 =	.788745
610	.800000 x	21.392016 =	17.113613
113	1.000000 x	20.419486 =	20.419486

-----  
B.T = 125.196564

4300A 1	4300A 1			
221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.741598 =	31.483196
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	2.937086 =	.734272
701 2		.800000 x	4.699337 =	3.759470
701 2		.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
607		.500000 x	10.053535 =	5.026768
606		.800000 x	9.175451 =	7.340361
407		.040000 x	724.827475 =	28.993099
714		1.150000 x	7.215820 =	8.298193
			AΘΡΟΙΣΜΑ =	148.242154
	B.T =	.200000 x	148.242154 =	29.648431
4300A 2	4300A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	2.937086 =	.734272
701 4		.500000 x	4.405629 =	2.202815
701 2		.800000 x	4.699337 =	3.759470
630		.250000 x	3.154979 =	.788745
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
407		.040000 x	724.827475 =	28.993099
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
			AΘΡΟΙΣΜΑ =	155.618647
	B.T =	.200000 x	155.618647 =	31.123729
4300A 3	4300A 3			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	2.937086 =	.734272
701 4		.800000 x	4.405629 =	3.524503
701 2		.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
610		.800000 x	21.392016 =	17.113613
607		.500000 x	10.053535 =	5.026768
407		.040000 x	724.827475 =	28.993099
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
			AΘΡΟΙΣΜΑ =	157.780439
	B.T =	.200000 x	157.780439 =	31.556088



4300A 4	4300A 4			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	2.937086 =	.734272
701 4		.800000 x	4.405629 =	3.524503
701 4		.500000 x	4.405629 =	2.202815
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
610		.800000 x	21.392016 =	17.113613
630		.250000 x	3.154979 =	.788745
611		.500000 x	25.100230 =	12.550115
407		.040000 x	724.827475 =	28.993099
111		2.000000 x	15.741598 =	31.483196
			ΑΘΡΟΙΣΜΑ =	165.156933
	B.T =	.200000 x	165.156933 =	33.031387
4300B	4300B			
221		2.000000 x	.099900 =	.199800
112		.400000 x	17.312112 =	6.924845
262		4.000000 x	.980000 =	3.920000
			B.T =	11.044645
601	601			
111		1.500000 x	15.741598 =	23.612397
			B.T =	23.612397
602	602			
403		.002500 x	651.701257 =	1.629253
			B.T =	1.629253
603	603			
111		.300000 x	15.741598 =	4.722479
412		.003300 x	375.741890 =	1.239948
401		.001000 x	893.029073 =	.893029
			B.T =	6.855457
604	604			
111		.200000 x	15.741598 =	3.148320
404		.005000 x	434.059934 =	2.170300
401		.001100 x	893.029073 =	.982332
412		.004000 x	375.741890 =	1.502968
			B.T =	7.803919

605	605				
112		.100000 x	17.312112 =	1.731211	
401		.001000 x	893.029073 =	.893029	
402		.006200 x	862.375342 =	5.346727	
412		.004000 x	375.741890 =	1.502968	
406		.006200 x	396.903470 =	2.460802	
-----					
			B.T =	11.934736	
606	606				
111		.100000 x	15.741598 =	1.574160	
401		.001000 x	893.029073 =	.893029	
412		.005000 x	375.741890 =	1.878709	
406		.006700 x	396.903470 =	2.659253	
404		.005000 x	434.059934 =	2.170300	
-----					
			B.T =	9.175451	
607	607				
111		.100000 x	15.741598 =	1.574160	
412		.005000 x	375.741890 =	1.878709	
401		.001400 x	893.029073 =	1.250241	
406		.006700 x	396.903470 =	2.659253	
404		.006200 x	434.059934 =	2.691172	
-----					
			B.T =	10.053535	
608	608				
111		.100000 x	15.741598 =	1.574160	
412		.005000 x	375.741890 =	1.878709	
406		.006700 x	396.903470 =	2.659253	
404		.012500 x	434.059934 =	5.425749	
401		.002000 x	893.029073 =	1.786058	
-----					
			B.T =	13.323930	
609	609				
214		.100000 x	1.949500 =	.194950	
405		.005000 x	578.995432 =	2.894977	
115		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
-----					
			B.T =	19.767103	

610	610				
214		.100000 x	1.949500 =	.194950	
412		.005000 x	375.741890 =	1.878709	
406		.005000 x	396.903470 =	1.984517	
405		.005000 x	578.995432 =	2.894977	
402		.010000 x	862.375342 =	8.623753	
112		.100000 x	17.312112 =	1.731211	
115		.200000 x	20.419486 =	4.083897	
			B.T =	21.392016	
611	611				
214		.100000 x	1.949500 =	.194950	
112		.100000 x	17.312112 =	1.731211	
405		.005000 x	578.995432 =	2.894977	
412		.005000 x	375.741890 =	1.878709	
406		.005000 x	396.903470 =	1.984517	
402		.014300 x	862.375342 =	12.331967	
115		.200000 x	20.419486 =	4.083897	
			B.T =	25.100230	
612	612				
214		.150000 x	1.949500 =	.292425	
408		.010000 x	545.660566 =	5.456606	
405		.005000 x	578.995432 =	2.894977	
115		.200000 x	20.419486 =	4.083897	
111		.300000 x	15.741598 =	4.722479	
			AΘΡΟΙΣΜΑ =	17.450384	
	B.T =	1.068000 x	17.450384 =	18.637011	
613	613				
214		.150000 x	1.949500 =	.292425	
409		.010000 x	607.955766 =	6.079558	
405		.005000 x	578.995432 =	2.894977	
115		.200000 x	20.419486 =	4.083897	
111		.500000 x	15.741598 =	7.870799	
			AΘΡΟΙΣΜΑ =	21.221656	
	B.T =	1.282000 x	21.221656 =	27.206163	
614	614				
214		.150000 x	1.949500 =	.292425	
111		.500000 x	15.741598 =	7.870799	
115		.200000 x	20.419486 =	4.083897	
410		.010000 x	717.741266 =	7.177413	
405		.005000 x	578.995432 =	2.894977	
			AΘΡΟΙΣΜΑ =	22.319511	
	B.T =	1.602000 x	22.319511 =	35.755857	

615	615				
214		.150000 x	1.949500 =	.292425	
410		.010000 x	717.741266 =	7.177413	
111		.700000 x	15.741598 =	11.019119	
405		.005000 x	578.995432 =	2.894977	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	25.467831	
	B.T =	1.832000 x	25.467831 =	46.657066	
616	616				
214		.150000 x	1.949500 =	.292425	
111		.800000 x	15.741598 =	12.593278	
405		.005000 x	578.995432 =	2.894977	
411		.010000 x	988.121266 =	9.881213	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	29.745790	
	B.T =	2.137000 x	29.745790 =	63.566754	
617	617				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	854.521248 =	854.521248	
506		1.000000 x	503.338000 =	503.338000	
503		1.000000 x	1,300.999700 =	1,300.999700	
			AΘΡΟΙΣΜΑ =	2,728.107396	
	B.T =	.006250 x	2,728.107396 =	17.050671	
618	618				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	854.521248 =	854.521248	
506		1.000000 x	503.338000 =	503.338000	
503		1.000000 x	1,300.999700 =	1,300.999700	
			AΘΡΟΙΣΜΑ =	2,728.107396	
	B.T =	.007700 x	2,728.107396 =	21.006427	
619	619				
112		4.000000 x	17.312112 =	69.248448	
503		1.000000 x	1,300.999700 =	1,300.999700	
506		1.000000 x	503.338000 =	503.338000	
513		1.000000 x	854.521248 =	854.521248	
			AΘΡΟΙΣΜΑ =	2,728.107396	
	B.T =	.010000 x	2,728.107396 =	27.281074	

620	620			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	854.521248 =	854.521248
506		1.000000 x	503.338000 =	503.338000
503		1.000000 x	1,300.999700 =	1,300.999700
			-----	
			ΑΘΡΟΙΣΜΑ =	2,728.107396
	B.T =	.012500 x	2,728.107396 =	34.101342
			-----	
621	621			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	503.338000 =	503.338000
503		1.000000 x	1,300.999700 =	1,300.999700
513		1.000000 x	854.521248 =	854.521248
			-----	
			ΑΘΡΟΙΣΜΑ =	2,728.107396
	B.T =	.016600 x	2,728.107396 =	45.286583
			-----	
630	630			
413		.020000 x	157.748929 =	3.154979
			-----	
			B.T =	3.154979
701 1	701 1			
406		.012580 x	396.903470 =	4.993046
			-----	
			B.T =	4.993046
701 2	701 2			
406		.011840 x	396.903470 =	4.699337
			-----	
			B.T =	4.699337
701 3	701 3			
406		.011544 x	396.903470 =	4.581854
			-----	
			B.T =	4.581854
701 4	701 4			
406		.011100 x	396.903470 =	4.405629
			-----	
			B.T =	4.405629
701 5	701 5			
406		.007400 x	396.903470 =	2.937086
			-----	
			B.T =	2.937086

702	702			
112		8.000000 x	17.312112 =	138.496896
506		1.000000 x	503.338000 =	503.338000
513		.300000 x	854.521248 =	256.356374
509		2.000000 x	175.675500 =	351.351000
			-----	
			ΑΘΡΟΙΣΜΑ =	1,249.542270
	B.T =	.002500 x	1,249.542270 =	3.123856
			-----	
703	703			
112		4.000000 x	17.312112 =	69.248448
513		.300000 x	854.521248 =	256.356374
503		1.000000 x	1,300.999700 =	1,300.999700
510		2.000000 x	180.946500 =	361.893000
506		1.000000 x	503.338000 =	503.338000
			-----	
			ΑΘΡΟΙΣΜΑ =	2,491.835522
	B.T =	.002500 x	2,491.835522 =	6.229589
			-----	
704	704			
112		4.000000 x	17.312112 =	69.248448
513		.500000 x	854.521248 =	427.260624
506		1.000000 x	503.338000 =	503.338000
502		1.000000 x	1,228.124700 =	1,228.124700
			-----	
			ΑΘΡΟΙΣΜΑ =	2,227.971772
	B.T =	.005000 x	2,227.971772 =	11.139859
			-----	
705	705			
112		4.000000 x	17.312112 =	69.248448
513		.600000 x	854.521248 =	512.712749
506		1.000000 x	503.338000 =	503.338000
504		1.000000 x	1,579.015900 =	1,579.015900
			-----	
			ΑΘΡΟΙΣΜΑ =	2,664.315097
	B.T =	.004540 x	2,664.315097 =	12.095991
			-----	
706	706			
501		1.000000 x	1,300.999700 =	1,300.999700
509		2.000000 x	175.675500 =	351.351000
506		1.000000 x	503.338000 =	503.338000
			-----	
			ΑΘΡΟΙΣΜΑ =	2,155.688700
	B.T =	.002500 x	2,155.688700 =	5.389222
			-----	
707	707			
505		1.000000 x	2,959.165000 =	2,959.165000
510		2.000000 x	180.946500 =	361.893000
506		1.000000 x	503.338000 =	503.338000
			-----	
			ΑΘΡΟΙΣΜΑ =	3,824.396000
	B.T =	.001000 x	3,824.396000 =	3.824396
			-----	

708	708				
708A		1.000000 x	17.285534 =		17.285534
708B		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		22.674756
708A	708A				
214		.050000 x	1.949500 =		.097475
513		.010000 x	854.521248 =		8.545212
511		.010000 x	140.540400 =		1.405404
405		.012500 x	578.995432 =		7.237443
		-----			
			B.T =		17.285534
708B	708B				
706		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		5.389222
709	709				
709A		1.000000 x	16.049223 =		16.049223
709B		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		21.438445
709A	709A				
506		1.000000 x	503.338000 =		503.338000
512		1.000000 x	780.599820 =		780.599820
		-----			
			AΘΡΟΙΣΜΑ =		1,283.937820
	B.T =	.012500 x	1,283.937820 =		16.049223
		-----			
709B	709B				
706		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		5.389222
710	710				
710A		1.000000 x	49.691943 =		49.691943
710B		1.000000 x	5.389222 =		5.389222
		-----			
			B.T =		55.081165
710A	710A				
214		.200000 x	1.949500 =		.389900
405		.025000 x	578.995432 =		14.474886
513		.035000 x	854.521248 =		29.908244
511		.035000 x	140.540400 =		4.918914
		-----			
			B.T =		49.691943

710B	710B			
706		1.000000 x	5.389222 =	5.389222
		-----		
			B.T =	5.389222
711	711			
711A		1.000000 x	42.755129 =	42.755129
711B		1.000000 x	5.389222 =	5.389222
		-----		
			B.T =	48.144351
711A	711A			
506		1.000000 x	503.338000 =	503.338000
512		1.000000 x	780.599820 =	780.599820
		-----		
			AΘΡΟΙΣΜΑ =	1,283.937820
	B.T =	.033300 x	1,283.937820 =	42.755129
		-----		
711B	711B			
706		1.000000 x	5.389222 =	5.389222
		-----		
			B.T =	5.389222
712	712			
513		1.000000 x	854.521248 =	854.521248
		-----		
			AΘΡΟΙΣΜΑ =	854.521248
	B.T =	.004000 x	854.521248 =	3.418085
		-----		
713 1	713 1			
704		.500000 x	11.139859 =	5.569930
		-----		
			B.T =	5.569930
713 2	713 2			
705		.500000 x	12.095991 =	6.047996
		-----		
			B.T =	6.047996
714	714			
714A		1.000000 x	3.442660 =	3.442660
714B		1.000000 x	3.773160 =	3.773160
		-----		
			B.T =	7.215820



714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	2.020000 =	2.020000
113		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	103.383196
	B.T =	.033300 x	103.383196 =	3.442660
714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211
			B.T =	3.773160
1111	1111			
1111A		1.000000 x	31.871042 =	31.871042
1111B		1.000000 x	5.389222 =	5.389222
			T.E =	37.260264
1112	1112			
1112A		1.000000 x	32.098446 =	32.098446
1112B		1.000000 x	5.389222 =	5.389222
			T.E =	37.487668
1113	1113			
1113A		1.000000 x	54.019971 =	54.019971
1113B		1.000000 x	5.389222 =	5.389222
			T.E =	59.409193
1114	1114			
1114A		1.000000 x	46.697976 =	46.697976
1114B		1.000000 x	5.389222 =	5.389222
			T.E =	52.087198
1121	1121			
1121A		1.000000 x	22.082077 =	22.082077
1121B		1.000000 x	5.389222 =	5.389222
			T.E =	27.471299
1122	1122			
1122A		1.000000 x	16.049223 =	16.049223
1122B		1.000000 x	5.389222 =	5.389222
			T.E =	21.438445

1123	1123				
1123A		1.000000 x	37.783614 =		37.783614
1123B		1.000000 x	5.389222 =		5.389222
		-----			
			T.E =		43.172836
1124	1124				
1124A		1.000000 x	28.275573 =		28.275573
1124B		1.000000 x	5.389222 =		5.389222
		-----			
			T.E =		33.664795
1210	1210				
707		1.000000 x	3.824396 =		3.824396
		-----			
			T.E =		3.824396
1220	1220				
708		1.000000 x	22.674756 =		22.674756
		-----			
			T.E =		22.674756
1230	1230				
709		1.000000 x	21.438445 =		21.438445
		-----			
			T.E =		21.438445
1311	1311				
712		.250000 x	3.418085 =		.854521
		-----			
			T.E =		.854521
1312	1312				
712		.250000 x	3.418085 =		.854521
602		1.000000 x	1.629253 =		1.629253
701 1		1.000000 x	4.993046 =		4.993046
		-----			
			T.E =		7.476820
1313	1313				
712		.250000 x	3.418085 =		.854521
701 2		1.000000 x	4.699337 =		4.699337
603		1.000000 x	6.855457 =		6.855457
		-----			
			T.E =		12.409315

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
712		.250000 x	3.418085 =	.854521	
111		.100000 x	15.741598 =	1.574160	
		-----			
			T.E =	37.428681	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
602		1.000000 x	1.629253 =	1.629253	
701	1	1.000000 x	4.993046 =	4.993046	
		-----			
			T.E =	10.084721	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
603		1.000000 x	6.855457 =	6.855457	
701	2	1.000000 x	4.699337 =	4.699337	
		-----			
			T.E =	15.017216	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
112		.100000 x	17.312112 =	1.731211	
111		.100000 x	15.741598 =	1.574160	
		-----			
			T.E =	38.305371	
2110	2110				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.123856 =	3.123856	
701	4	1.000000 x	4.405629 =	4.405629	
608		1.000000 x	13.323930 =	13.323930	
		-----			
			T.E =	22.562458	
2120	2120				
712		.500000 x	3.418085 =	1.709043	
701	2	1.000000 x	4.699337 =	4.699337	
702		1.000000 x	3.123856 =	3.123856	
603		1.000000 x	6.855457 =	6.855457	
		-----			
			T.E =	16.387693	
2130	2130				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.123856 =	3.123856	
701	2	1.000000 x	4.699337 =	4.699337	
604		1.000000 x	7.803919 =	7.803919	
		-----			
			T.E =	17.336155	

2140	2140				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.123856 =	3.123856	
701	2	1.000000 x	4.699337 =	4.699337	
605		1.000000 x	11.934736 =	11.934736	
				-----	
				T.E =	21.466972
2210	2210				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.123856 =	3.123856	
701	2	1.000000 x	4.699337 =	4.699337	
609		1.050000 x	19.767103 =	20.755458	
				-----	
				T.E =	30.287694
2220	2220				
712		.500000 x	3.418085 =	1.709043	
609		1.150000 x	19.767103 =	22.732168	
701	2	1.000000 x	4.699337 =	4.699337	
702		1.000000 x	3.123856 =	3.123856	
				-----	
				T.E =	32.264404
2230	2230				
111		.200000 x	15.741598 =	3.148320	
609		1.200000 x	19.767103 =	23.720524	
701	2	1.000000 x	4.699337 =	4.699337	
				-----	
				T.E =	31.568180
2240	2240				
111		.300000 x	15.741598 =	4.722479	
609		1.200000 x	19.767103 =	23.720524	
701	2	1.000000 x	4.699337 =	4.699337	
				-----	
				T.E =	33.142340
2310	2310				
612		1.000000 x	18.637011 =	18.637011	
703		1.000000 x	6.229589 =	6.229589	
701	3	1.000000 x	4.581854 =	4.581854	
				-----	
				T.E =	29.448454
2320	2320				
613		1.000000 x	27.206163 =	27.206163	
701	3	1.000000 x	4.581854 =	4.581854	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	38.017606

2330	2330				
614		1.000000 x	35.755857 =	35.755857	
701	3	1.000000 x	4.581854 =	4.581854	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	46.567300
2340	2340				
615		1.000000 x	46.657066 =	46.657066	
701	3	1.000000 x	4.581854 =	4.581854	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	57.468509
2350	2350				
616		1.000000 x	63.566754 =	63.566754	
703		1.000000 x	6.229589 =	6.229589	
701	3	1.000000 x	4.581854 =	4.581854	
				-----	
				T.E =	74.378197
2410	2410				
617		1.000000 x	17.050671 =	17.050671	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	23.280260
2420	2420				
618		1.000000 x	21.006427 =	21.006427	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	27.236016
2430	2430				
619		1.000000 x	27.281074 =	27.281074	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	33.510663
2440	2440				
620		1.000000 x	34.101342 =	34.101342	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	40.330931
2450	2450				
621		1.000000 x	45.286583 =	45.286583	
703		1.000000 x	6.229589 =	6.229589	
				-----	
				T.E =	51.516172

3110	1	3110	1			
	3110A 1			1.000000 x	129.776247 =	129.776247
	3110B			1.000000 x	16.709789 =	16.709789
				-----		
				T.E =		146.486036
3110	2	3110	2			
	3110A 2			1.000000 x	137.152741 =	137.152741
	3110B			1.000000 x	16.709789 =	16.709789
				-----		
				T.E =		153.862530
3110	3	3110	3			
	3110A 3			1.000000 x	139.314533 =	139.314533
	3110B			1.000000 x	16.709789 =	16.709789
				-----		
				T.E =		156.024322
3110	4	3110	4			
	3110A 4			1.000000 x	146.691026 =	146.691026
	3110B			1.000000 x	16.709789 =	16.709789
				-----		
				T.E =		163.400815
3120	1	3120	1			
	3120A 1			1.000000 x	129.776247 =	129.776247
	3120B			1.000000 x	18.143987 =	18.143987
				-----		
				T.E =		147.920234
3120	2	3120	2			
	3120A 2			1.000000 x	137.152741 =	137.152741
	3120B			1.000000 x	18.143987 =	18.143987
				-----		
				T.E =		155.296728
3120	3	3120	3			
	3120A 3			1.000000 x	139.314533 =	139.314533
	3120B			1.000000 x	18.143987 =	18.143987
				-----		
				T.E =		157.458520
3120	4	3120	4			
	3120A 4			1.000000 x	146.691026 =	146.691026
	3120B			1.000000 x	18.143987 =	18.143987
				-----		
				T.E =		164.835013

3210 1	3210 1				
3210A 1		1.000000 x	119.177392 =		119.177392
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		135.887181
3210 2	3210 2				
3210A 2		1.000000 x	125.078587 =		125.078587
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		141.788376
3210 3	3210 3				
3210A 3		1.000000 x	126.808020 =		126.808020
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		143.517809
3210 4	3210 4				
3210A 4		1.000000 x	132.709215 =		132.709215
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		149.419004
3210 5	3210 5				
3210A 5		1.000000 x	117.946898 =		117.946898
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		134.656687
3210 6	3210 6				
3210A 6		1.000000 x	123.848093 =		123.848093
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		140.557882
3210 7	3210 7				
3210A 7		1.000000 x	125.577526 =		125.577526
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		142.287315
3210 8	3210 8				
3210A 8		1.000000 x	131.478721 =		131.478721
3210B		1.000000 x	16.709789 =		16.709789
		-----			
			T.E =		148.188510

3220	1	3220	1			
	3220A	1		1.000000 x	119.177392 =	119.177392
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						137.321379
3220	2	3220	2			
	3220A	2		1.000000 x	125.078587 =	125.078587
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						143.222574
3220	3	3220	3			
	3220A	3		1.000000 x	126.808020 =	126.808020
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						144.952007
3220	4	3220	4			
	3220A	4		1.000000 x	132.709215 =	132.709215
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						150.853202
3220	5	3220	5			
	3220A	5		1.000000 x	117.946898 =	117.946898
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						136.090885
3220	6	3220	6			
	3220A	6		1.000000 x	123.848093 =	123.848093
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						141.992080
3220	7	3220	7			
	3220A	7		1.000000 x	125.577526 =	125.577526
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						143.721513
3220	8	3220	8			
	3220A	8		1.000000 x	131.478721 =	131.478721
	3220B			1.000000 x	18.143987 =	18.143987
-----						
						T.E =
						149.622708



3300 1	3300 1				
3300A 1		1.000000 x	181.922400 =	181.922400	
3300B 1		1.000000 x	16.709789 =	16.709789	
			T.E =	198.632189	
3300 2	3300 2				
3300A 1		1.000000 x	181.922400 =	181.922400	
3300B 2		1.000000 x	18.143987 =	18.143987	
			T.E =	200.066387	
3300 3	3300 3				
3300A 2		1.000000 x	189.298894 =	189.298894	
3300B 1		1.000000 x	16.709789 =	16.709789	
			T.E =	206.008683	
3300 4	3300 4				
3300A 2		1.000000 x	189.298894 =	189.298894	
3300B 2		1.000000 x	18.143987 =	18.143987	
			T.E =	207.442881	
3300 5	3300 5				
3300A 3		1.000000 x	191.460686 =	191.460686	
3300B 1		1.000000 x	16.709789 =	16.709789	
			T.E =	208.170475	
3300 6	3300 6				
3300A 3		1.000000 x	191.460686 =	191.460686	
3300B 2		1.000000 x	18.143987 =	18.143987	
			T.E =	209.604673	
3300 7	3300 7				
3300A 4		1.000000 x	198.837179 =	198.837179	
3300B 1		1.000000 x	16.709789 =	16.709789	
			T.E =	215.546968	
3300 8	3300 8				
3300A 4		1.000000 x	198.837179 =	198.837179	
3300B 2		1.000000 x	18.143987 =	18.143987	
			T.E =	216.981166	

3400	1	3400	1				
	3400A	1		1.000000 x	195.163723 =	195.163723	
	3400B	1		1.000000 x	11.139859 =	11.139859	
-----							
						T.E =	206.303582
3400	2	3400	2				
	3400A	1		1.000000 x	195.163723 =	195.163723	
	3400B	2		1.000000 x	12.095991 =	12.095991	
-----							
						T.E =	207.259714
3400	3	3400	3				
	3400A	2		1.000000 x	202.540217 =	202.540217	
	3400B	1		1.000000 x	11.139859 =	11.139859	
-----							
						T.E =	213.680076
3400	4	3400	4				
	3400A	2		1.000000 x	202.540217 =	202.540217	
	3400B	2		1.000000 x	12.095991 =	12.095991	
-----							
						T.E =	214.636208
3400	5	3400	5				
	3400A	3		1.000000 x	204.702009 =	204.702009	
	3400B	1		1.000000 x	11.139859 =	11.139859	
-----							
						T.E =	215.841868
3400	6	3400	6				
	3400A	3		1.000000 x	204.702009 =	204.702009	
	3400B	2		1.000000 x	12.095991 =	12.095991	
-----							
						T.E =	216.798000
3400	7	3400	7				
	3400A	4		1.000000 x	212.078502 =	212.078502	
	3400B	1		1.000000 x	11.139859 =	11.139859	
-----							
						T.E =	223.218361
3400	8	3400	8				
	3400A	4		1.000000 x	212.078502 =	212.078502	
	3400B	2		1.000000 x	12.095991 =	12.095991	
-----							
						T.E =	224.174493

4110	1	4110	1				
	4110A	1		1.000000 x	198.384017 =		198.384017
	4110B			.025000 x	1,620.665644 =		40.516641
-----							
						T.E =	238.900658
4110	2	4110	2				
	4110A	2		1.000000 x	205.760511 =		205.760511
	4110B			.025000 x	1,620.665644 =		40.516641
-----							
						T.E =	246.277152
4110	3	4110	3				
	4110A	3		1.000000 x	207.922303 =		207.922303
	4110B			.025000 x	1,620.665644 =		40.516641
-----							
						T.E =	248.438944
4110	4	4110	4				
	4110A	4		1.000000 x	215.298796 =		215.298796
	4110B			.025000 x	1,620.665644 =		40.516641
-----							
						T.E =	255.815437
4120	1	4120	1				
	4120A	1		1.000000 x	161.909006 =		161.909006
	4120B			1.000000 x	64.826626 =		64.826626
-----							
						T.E =	226.735632
4120	2	4120	2				
	4120A	2		1.000000 x	179.612591 =		179.612591
	4120B			1.000000 x	64.826626 =		64.826626
-----							
						T.E =	244.439217
4130	1	4130	1				
	4130A	1		1.000000 x	143.845836 =		143.845836
	4130B			1.000000 x	64.826626 =		64.826626
-----							
						T.E =	208.672462
4130	2	4130	2				
	4130A	2		1.000000 x	151.222330 =		151.222330
	4130B			1.000000 x	64.826626 =		64.826626
-----							
						T.E =	216.048956

4130	3	4130	3			
4130A	3			1.000000 x	153.384122 =	153.384122
4130B				1.000000 x	64.826626 =	64.826626
-----						
T.E =						218.210748
4130	4	4130	4			
4130A	4			1.000000 x	160.760615 =	160.760615
4130B				1.000000 x	64.826626 =	64.826626
-----						
T.E =						225.587241
4210	1	4210	1			
4210A	1			1.000000 x	42.260492 =	42.260492
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						185.706189
4210	2	4210	2			
4210A	2			1.000000 x	46.686388 =	46.686388
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						190.132085
4210	3	4210	3			
4210A	3			1.000000 x	38.222933 =	38.222933
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						181.668630
4210	4	4210	4			
4210A	4			1.000000 x	42.648829 =	42.648829
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						186.094526
4220B	1	4220B	1			
319				.020000 x	21.440000 =	.428800
701	2			.320000 x	4.699337 =	1.503788
601				.320000 x	23.612397 =	7.555967
4220A	1			.800000 x	108.281785 =	86.625428
111				.400000 x	15.741598 =	6.296639
714				1.150000 x	7.215820 =	8.298193
-----						
T.E =						110.708815

4220B 2	4220B 2			
319		.020000 x	21.440000 =	.428800
4220A 2		.800000 x	115.658279 =	92.526623
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.699337 =	1.503788
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.215820 =	8.298193

T.E = 116.610010

4220B 3	4220B 3			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.699337 =	1.503788
601		.320000 x	23.612397 =	7.555967
4220A 3		.800000 x	117.820071 =	94.256057
714		1.150000 x	7.215820 =	8.298193
111		.400000 x	15.741598 =	6.296639

T.E = 118.339444

4220B 4	4220B 4			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	125.196564 =	100.157251
701 2		.320000 x	4.699337 =	1.503788
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.215820 =	8.298193

T.E = 124.240638

4220B 5	4220B 5			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
4220A 1		.800000 x	108.281785 =	86.625428
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.215820 =	8.298193

T.E = 109.478321

4220B 6	4220B 6			
319		.020000 x	21.440000 =	.428800
4220A 2		.800000 x	115.658279 =	92.526623
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
714		1.150000 x	7.215820 =	8.298193

T.E = 115.379516

4220B 7	4220B 7			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
4220A 3		.800000 x	117.820071 =	94.256057
714		1.150000 x	7.215820 =	8.298193
111		.400000 x	15.741598 =	6.296639
-----				
			T.E =	117.108950
4220B 8	4220B 8			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.699337 =	1.503788
609		.320000 x	19.767103 =	6.325473
4220A 4		.800000 x	125.196564 =	100.157251
714		1.150000 x	7.215820 =	8.298193
111		.400000 x	15.741598 =	6.296639
-----				
			T.E =	123.010144
4230 1	4230 1			
221		250.000000 x	.099900 =	24.975000
111		2.000000 x	15.741598 =	31.483196
714		1.150000 x	7.215820 =	8.298193
701 5		.250000 x	2.937086 =	.734272
701 2		.500000 x	4.699337 =	2.349669
701 2		.800000 x	4.699337 =	3.759470
630		.250000 x	3.154979 =	.788745
607		.500000 x	10.053535 =	5.026768
606		.800000 x	9.175451 =	7.340361
407		.040000 x	724.827475 =	28.993099
113		1.200000 x	20.419486 =	24.503383
319		.020000 x	21.440000 =	.428800
-----				
			T.E =	138.680954
4230 2	4230 2			
221		250.000000 x	.099900 =	24.975000
630		.250000 x	3.154979 =	.788745
701 5		.250000 x	2.937086 =	.734272
701 4		.500000 x	4.405629 =	2.202815
701 2		.800000 x	4.699337 =	3.759470
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
407		.040000 x	724.827475 =	28.993099
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	21.440000 =	.428800
-----				
			T.E =	146.057447

4230	3	4230	3		
221				250.000000 x	.099900 = 24.975000
701	5			.250000 x	2.937086 = .734272
701	4			.800000 x	4.405629 = 3.524503
701	2			.500000 x	4.699337 = 2.349669
630				.250000 x	3.154979 = .788745
610				.800000 x	21.392016 = 17.113613
607				.500000 x	10.053535 = 5.026768
407				.040000 x	724.827475 = 28.993099
714				1.150000 x	7.215820 = 8.298193
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196
319				.020000 x	21.440000 = .428800

T.E = 148.219239

4230	4	4230	4		
221				250.000000 x	.099900 = 24.975000
701	5			.250000 x	2.937086 = .734272
701	4			.500000 x	4.405629 = 2.202815
701	4			.800000 x	4.405629 = 3.524503
630				.250000 x	3.154979 = .788745
319				.020000 x	21.440000 = .428800
111				2.000000 x	15.741598 = 31.483196
407				.040000 x	724.827475 = 28.993099
611				.500000 x	25.100230 = 12.550115
610				.800000 x	21.392016 = 17.113613
714				1.150000 x	7.215820 = 8.298193
113				1.200000 x	20.419486 = 24.503383

T.E = 155.595733

4240	1	4240	1		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	2.937086 = .734272
701	2			.500000 x	4.699337 = 2.349669
701	2			.800000 x	4.699337 = 3.759470
630				.250000 x	3.154979 = .788745
607				.500000 x	10.053535 = 5.026768
606				.800000 x	9.175451 = 7.340361
407				.040000 x	724.827475 = 28.993099
714				1.150000 x	7.215820 = 8.298193
319				.020000 x	21.440000 = .428800
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196

T.E = 143.675954

4240 2      4240 2

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	2.937086 =	.734272
701	4	.500000 x	4.405629 =	2.202815
701	2	.800000 x	4.699337 =	3.759470
630		.250000 x	3.154979 =	.788745
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
407		.040000 x	724.827475 =	28.993099
611		.500000 x	25.100230 =	12.550115
606		.800000 x	9.175451 =	7.340361
714		1.150000 x	7.215820 =	8.298193
111		2.000000 x	15.741598 =	31.483196

-----  
T.E = 151.052447

4240 3      4240 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	2.937086 =	.734272
701	4	.800000 x	4.405629 =	3.524503
701	2	.500000 x	4.699337 =	2.349669
630		.250000 x	3.154979 =	.788745
610		.800000 x	21.392016 =	17.113613
607		.500000 x	10.053535 =	5.026768
407		.040000 x	724.827475 =	28.993099
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	21.440000 =	.428800

-----  
T.E = 153.214239

4240 4      4240 4

221		300.000000 x	.099900 =	29.970000
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
701	5	.250000 x	2.937086 =	.734272
701	4	.500000 x	4.405629 =	2.202815
701	4	.800000 x	4.405629 =	3.524503
630		.250000 x	3.154979 =	.788745
611		.500000 x	25.100230 =	12.550115
610		.800000 x	21.392016 =	17.113613
407		.040000 x	724.827475 =	28.993099
319		.020000 x	21.440000 =	.428800

-----  
T.E = 160.590733

4300 1      4300 1

4300A	1	1.000000 x	29.648431 =	29.648431
4300B		1.000000 x	11.044645 =	11.044645

-----  
T.E = 40.693076



4300	2	4300	2			
	4300A	2		1.000000 x	31.123729 =	31.123729
	4300B			1.000000 x	11.044645 =	11.044645
-----						
					T.E =	42.168374
4300	3	4300	3			
	4300A	3		1.000000 x	31.556088 =	31.556088
	4300B			1.000000 x	11.044645 =	11.044645
-----						
					T.E =	42.600733
4300	4	4300	4			
	4300A	4		1.000000 x	33.031387 =	33.031387
	4300B			1.000000 x	11.044645 =	11.044645
-----						
					T.E =	44.076032
4400		4400				
	251			1.050000 x	.538600 =	.565530
	113			.050000 x	20.419486 =	1.020974
-----						
					T.E =	1.586504
4500		4500				
	251			1.050000 x	.538600 =	.565530
	114			.100000 x	17.312112 =	1.731211
	113			.100000 x	20.419486 =	2.041949
-----						
					T.E =	4.338690
4600		4600				
	256			1.000000 x	3.800000 =	3.800000
	113			.100000 x	20.419486 =	2.041949
-----						
					T.E =	5.841949
4700		4700				
	253			1.000000 x	4.000000 =	4.000000
	113			.100000 x	20.419486 =	2.041949
-----						
					T.E =	6.041949