

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

3ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	1.175600
212	1.433300
213	4.160000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.545500
252	2.100000
253	4.500000
254	5.000000
255	1.006500
256	4.300000
261	
262	.980000
263	.640000
311	437.840000
312	134.530000
313	206.720000
314	4.530000
315	55.210000
316	4.530000
317	126.080000
318	27.370000
319	22.070000
320	156.740000
321	213.360000
322	296.440000
323	337.580000
324	185.200000
325	317.230000
326	103.360000
327	4.530000
351	451.770000
352	383.570000
353	451.770000
354	592.710000
355	296.440000
356	48.650000
357	233.080000
358	46.930000
359	97.290000
360	102.460000

361	78.370000
362	271.240000
363	102.610000
380	568.910000
381	568.910000
382	568.910000
383	654.300000
384	1,083.720000
385	196.900000
386	519.550000
387	74.960000
388	74.960000
389	74.960000

401	401				
211		110.000000 x	1.175600 =	129.316000	
213		10.000000 x	4.160000 =	41.600000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
311		1.000000 x	437.840000 =	437.840000	
			ΑΘΡΟΙΣΜΑ =	839.849612	
			Η.Δ. =	923.834573	
402	402				
211		180.000000 x	1.175600 =	211.608000	
312		1.000000 x	134.530000 =	134.530000	
112		8.000000 x	17.312112 =	138.496896	
212		5.000000 x	1.433300 =	7.166500	
213		12.000000 x	4.160000 =	49.920000	
116		8.000000 x	23.886192 =	191.089536	
117		8.000000 x	10.001019 =	80.008152	
			ΑΘΡΟΙΣΜΑ =	812.819084	
			Η.Δ. =	894.100992	
403	403				
211		80.000000 x	1.175600 =	94.048000	
254		2.500000 x	5.000000 =	12.500000	
213		6.000000 x	4.160000 =	24.960000	
117		8.000000 x	10.001019 =	80.008152	
116		8.000000 x	23.886192 =	191.089536	
313		1.000000 x	206.720000 =	206.720000	
			ΑΘΡΟΙΣΜΑ =	609.325688	
			Η.Δ. =	670.258257	
404	404				
211		80.000000 x	1.175600 =	94.048000	
213		5.000000 x	4.160000 =	20.800000	
212		2.000000 x	1.433300 =	2.866600	
119		4.000000 x	10.001019 =	40.004076	
118		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
314		1.000000 x	4.530000 =	4.530000	
			ΑΘΡΟΙΣΜΑ =	405.724540	
			Η.Δ. =	446.296994	

405	405				
211		40.000000 x	1.175600 =	47.024000	
213		2.000000 x	4.160000 =	8.320000	
115		16.000000 x	20.419486 =	326.711776	
118		4.000000 x	21.778427 =	87.113708	
316		2.000000 x	4.530000 =	9.060000	
315		1.000000 x	55.210000 =	55.210000	

			ΑΘΡΟΙΣΜΑ =	533.439484	

			Η.Δ. =	586.783432	
406	406				
211		80.000000 x	1.175600 =	94.048000	
213		5.000000 x	4.160000 =	20.800000	
317		1.000000 x	126.080000 =	126.080000	
120		8.000000 x	16.777917 =	134.223336	

			ΑΘΡΟΙΣΜΑ =	375.151336	

			Η.Δ. =	412.666470	
407	407				
212		17.000000 x	1.433300 =	24.366100	
318		1.000000 x	27.370000 =	27.370000	
112		30.000000 x	17.312112 =	519.363360	
213		1.000000 x	4.160000 =	4.160000	
118		4.000000 x	21.778427 =	87.113708	

			ΑΘΡΟΙΣΜΑ =	662.373168	

			Η.Δ. =	728.610485	
408	408				
211		30.000000 x	1.175600 =	35.268000	
112		4.000000 x	17.312112 =	69.248448	
116		8.000000 x	23.886192 =	191.089536	
117		4.000000 x	10.001019 =	40.004076	
320		1.000000 x	156.740000 =	156.740000	
213		3.000000 x	4.160000 =	12.480000	

			ΑΘΡΟΙΣΜΑ =	504.830060	

			Η.Δ. =	555.313066	
409	409				
211		50.000000 x	1.175600 =	58.780000	
112		4.000000 x	17.312112 =	69.248448	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
324		1.000000 x	185.200000 =	185.200000	
213		5.000000 x	4.160000 =	20.800000	

			ΑΘΡΟΙΣΜΑ =	565.122060	

			Η.Δ. =	621.634266	

410	410				
211		100.000000 x	1.175600 =	117.560000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
321		1.000000 x	213.360000 =	213.360000	
213		10.000000 x	4.160000 =	41.600000	

				ΑΘΡΟΙΣΜΑ =	672.862060

				Η.Δ. =	740.148266
411	411				
211		200.000000 x	1.175600 =	235.120000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
213		20.000000 x	4.160000 =	83.200000	
325		1.000000 x	317.230000 =	317.230000	

				ΑΘΡΟΙΣΜΑ =	935.892060

				Η.Δ. =	1,029.481266
412	412				
211		40.000000 x	1.175600 =	47.024000	
116		8.000000 x	23.886192 =	191.089536	
326		1.000000 x	103.360000 =	103.360000	
213		2.000000 x	4.160000 =	8.320000	

				ΑΘΡΟΙΣΜΑ =	349.793536

				Η.Δ. =	384.772890
413	413				
211		15.000000 x	1.175600 =	17.634000	
213		1.500000 x	4.160000 =	6.240000	
118		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
327		1.000000 x	4.530000 =	4.530000	

				ΑΘΡΟΙΣΜΑ =	145.675617

				Η.Δ. =	160.243179
501	501				
211		170.000000 x	1.175600 =	199.852000	
351		1.000000 x	451.770000 =	451.770000	
380		1.000000 x	568.910000 =	568.910000	
213		3.000000 x	4.160000 =	12.480000	

				ΑΘΡΟΙΣΜΑ =	1,233.012000

				Η.Δ. =	1,356.313200

502	502				
211		170.000000 x	1.175600 =	199.852000	
381		1.000000 x	568.910000 =	568.910000	
352		1.000000 x	383.570000 =	383.570000	
213		3.000000 x	4.160000 =	12.480000	
			AΘΡΟΙΣΜΑ =	1,164.812000	
			H.Δ. =	1,281.293200	
503	503				
211		170.000000 x	1.175600 =	199.852000	
213		3.000000 x	4.160000 =	12.480000	
353		1.000000 x	451.770000 =	451.770000	
382		1.000000 x	568.910000 =	568.910000	
			AΘΡΟΙΣΜΑ =	1,233.012000	
			H.Δ. =	1,356.313200	
504	504				
211		190.000000 x	1.175600 =	223.364000	
213		6.000000 x	4.160000 =	24.960000	
383		1.000000 x	654.300000 =	654.300000	
354		1.000000 x	592.710000 =	592.710000	
			AΘΡΟΙΣΜΑ =	1,495.334000	
			H.Δ. =	1,644.867400	
505	505				
211		1,250.000000 x	1.175600 =	1,469.500000	
213		7.500000 x	4.160000 =	31.200000	
384		1.000000 x	1,083.720000 =	1,083.720000	
355		1.000000 x	296.440000 =	296.440000	
			AΘΡΟΙΣΜΑ =	2,880.860000	
			H.Δ. =	3,168.946000	
506	506				
211		200.000000 x	1.175600 =	235.120000	
385		1.000000 x	196.900000 =	196.900000	
356		1.000000 x	48.650000 =	48.650000	
213		2.000000 x	4.160000 =	8.320000	
			AΘΡΟΙΣΜΑ =	488.990000	
			H.Δ. =	537.889000	
507	507				
211		2,100.000000 x	1.175600 =	2,468.760000	
213		35.000000 x	4.160000 =	145.600000	
386		1.000000 x	519.550000 =	519.550000	
357		1.000000 x	233.080000 =	233.080000	
			AΘΡΟΙΣΜΑ =	3,366.990000	
			H.Δ. =	3,636.349200	

508	508				
358		1.000000 x	46.930000 =		46.930000
387		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	121.890000
				Η.Δ. =	127.984500
509	509				
359		1.000000 x	97.290000 =		97.290000
388		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	172.250000
				Η.Δ. =	180.862500
510	510				
360		1.000000 x	102.460000 =		102.460000
389		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	177.420000
				Η.Δ. =	186.291000
511	511				
509		.800000 x	180.862500 =		144.690000
				Η.Δ. =	144.690000
512	512				
501		.600000 x	1,356.313200 =		813.787920
				Η.Δ. =	813.787920
513	513				
363		1.000000 x	102.610000 =		102.610000
121		8.000000 x	16.585068 =		132.680544
122		8.000000 x	13.510339 =		108.082712
123		8.000000 x	64.260999 =		514.087992
				Η.Δ. =	857.461248
1111A	1111A				
214		.200000 x	1.949500 =		.389900
511		.020000 x	144.690000 =		2.893800
405		.020000 x	586.783432 =		11.735669
513		.020000 x	857.461248 =		17.149225
				Β.Τ =	32.168594

1111B	1111B			
501		1.000000 x	1,356.313200 =	1,356.313200
506		1.000000 x	537.889000 =	537.889000
509		2.000000 x	180.862500 =	361.725000

			AΘΡΟΙΣΜΑ =	2,255.927200
	B.T =	.002500 x	2,255.927200 =	5.639818

1112A	1112A			
506		1.000000 x	537.889000 =	537.889000
512		1.000000 x	813.787920 =	813.787920

			AΘΡΟΙΣΜΑ =	1,351.676920
	B.T =	.025000 x	1,351.676920 =	33.791923

1112B	1112B			
1111B		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818
1113A	1113A			
214		.200000 x	1.949500 =	.389900
112		.250000 x	17.312112 =	4.328028
511		.035000 x	144.690000 =	5.064150
513		.035000 x	857.461248 =	30.011144
405		.025000 x	586.783432 =	14.669586

			B.T =	54.462807
1113B	1113B			
1111B		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818
1114A	1114A			
112		.250000 x	17.312112 =	4.328028
506		.033000 x	537.889000 =	17.750337
512		.033000 x	813.787920 =	26.855001

			B.T =	48.933366
1114B	1114B			
1111B		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818

1121A	1121A			
214		.150000 x	1.949500 =	.292425
115		.500000 x	20.419486 =	10.209743
405		.020000 x	586.783432 =	11.735669

			B.T =	22.237837
1121B	1121B			
1111B		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818
1122A	1122A			
506		1.000000 x	537.889000 =	537.889000
512		1.000000 x	813.787920 =	813.787920

			AΘΡΟΙΣΜΑ =	1,351.676920
	B.T =	.012500 x	1,351.676920 =	16.895962

1122B	1122B			
1111B		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818
1123A	1123A			
214		.150000 x	1.949500 =	.292425
112		.150000 x	17.312112 =	2.596817
405		.025000 x	586.783432 =	14.669586
115		1.000000 x	20.419486 =	20.419486

			B.T =	37.978314
1123B	1123B			
1111B		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818
1124A	1124A			
112		.150000 x	17.312112 =	2.596817
506		.020000 x	537.889000 =	10.757780
512		.020000 x	813.787920 =	16.275758

			B.T =	29.630355
1124B	1124B			
1111B		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818

3110A 1	3110A 1			
221		250.000000 x	.099900 =	24.975000
607		.500000 x	10.323299 =	5.161650
701 2		.500000 x	4.885971 =	2.442986
701 5		.250000 x	3.053732 =	.763433
701 2		.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
606		.800000 x	9.418209 =	7.534567
113		1.200000 x	20.419486 =	24.503383
714		1.400000 x	7.218484 =	10.105878
407		.040000 x	728.610485 =	29.144419
319		.020000 x	22.070000 =	.441400
112		1.200000 x	17.312112 =	20.774534

B.T = 130.557243

3110A 2	3110A 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.053732 =	.763433
701 4		.500000 x	4.580598 =	2.290299
701 2		.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
611		.500000 x	25.716817 =	12.858409
606		.800000 x	9.418209 =	7.534567
407		.040000 x	728.610485 =	29.144419
714		1.400000 x	7.218484 =	10.105878
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	22.070000 =	.441400

B.T = 138.101315

3110A 3	3110A 3			
221		250.000000 x	.099900 =	24.975000
112		1.200000 x	17.312112 =	20.774534
113		1.200000 x	20.419486 =	24.503383
714		1.400000 x	7.218484 =	10.105878
701 5		.250000 x	3.053732 =	.763433
701 4		.800000 x	4.580598 =	3.664478
701 2		.500000 x	4.885971 =	2.442986
630		.250000 x	3.204864 =	.801216
610		.800000 x	21.872182 =	17.497746
607		.500000 x	10.323299 =	5.161650
407		.040000 x	728.610485 =	29.144419
319		.020000 x	22.070000 =	.441400

B.T = 140.276123

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
113		1.200000 x	20.419486 =	24.503383
630		.250000 x	3.204864 =	.801216
701 5		.250000 x	3.053732 =	.763433
701 4		.800000 x	4.580598 =	3.664478
701 4		.500000 x	4.580598 =	2.290299
611		.500000 x	25.716817 =	12.858409
610		.800000 x	21.872182 =	17.497746
407		.040000 x	728.610485 =	29.144419
112		1.200000 x	17.312112 =	20.774534
714		1.400000 x	7.218484 =	10.105878
319		.020000 x	22.070000 =	.441400
			B.T =	147.820195
3110B	3110B			
713 1		1.000000 x	5.792903 =	5.792903
704		1.000000 x	11.585806 =	11.585806
			B.T =	17.378709
3120A 1	3120A 1			
3110A 1		1.000000 x	130.557243 =	130.557243
			B.T =	130.557243
3120A 2	3120A 2			
3110A 2		1.000000 x	138.101315 =	138.101315
			B.T =	138.101315
3120A 3	3120A 3			
3110A 3		1.000000 x	140.276123 =	140.276123
			B.T =	140.276123
3120A 4	3120A 4			
3110A 4		1.000000 x	147.820195 =	147.820195
			B.T =	147.820195
3120B	3120B			
713 2		1.000000 x	6.279913 =	6.279913
705		1.000000 x	12.559826 =	12.559826
			B.T =	18.839739

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.885971 =	1.563511
601		.320000 x	23.612397 =	7.555967
3110A 1		.800000 x	130.557243 =	104.445794

			B.T =	119.861911
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	138.101315 =	110.481052
701 2		.320000 x	4.885971 =	1.563511
601		.320000 x	23.612397 =	7.555967

			B.T =	125.897169
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	140.276123 =	112.220898
701 2		.320000 x	4.885971 =	1.563511
601		.320000 x	23.612397 =	7.555967

			B.T =	127.637015
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.885971 =	1.563511
601		.320000 x	23.612397 =	7.555967
3110A 4		.800000 x	147.820195 =	118.256156

			B.T =	133.672273
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
3110A 1		.800000 x	130.557243 =	104.445794
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934

			B.T =	118.643878
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934
3110A 2		.800000 x	138.101315 =	110.481052

			B.T =	124.679136

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934
3110A 3		.800000 x	140.276123 =	112.220898

			B.T =	126.418982
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934
3110A 4		.800000 x	147.820195 =	118.256156

			B.T =	132.454240
3210B	3210B			
713 1		1.000000 x	5.792903 =	5.792903
704		1.000000 x	11.585806 =	11.585806

			B.T =	17.378709
3220A 1	3220A 1			
3210A 1		1.000000 x	119.861911 =	119.861911

			B.T =	119.861911
3220A 2	3220A 2			
3210A 2		1.000000 x	125.897169 =	125.897169

			B.T =	125.897169
3220A 3	3220A 3			
3210A 3		1.000000 x	127.637015 =	127.637015

			B.T =	127.637015
3220A 4	3220A 4			
3210A 4		1.000000 x	133.672273 =	133.672273

			B.T =	133.672273
3220A 5	3220A 5			
3210A 5		1.000000 x	118.643878 =	118.643878

			B.T =	118.643878

3220A 6	3220A 6			
3210A 6		1.000000 x	124.679136 =	124.679136

			B.T =	124.679136
3220A 7	3220A 7			
3210A 7		1.000000 x	126.418982 =	126.418982

			B.T =	126.418982
3220A 8	3220A 8			
3210A 8		1.000000 x	132.454240 =	132.454240

			B.T =	132.454240
3220B	3220B			
713 2		1.000000 x	6.279913 =	6.279913
705		1.000000 x	12.559826 =	12.559826

			B.T =	18.839739
3300A 1	3300A 1			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.053732 =	.763433
701 2		.500000 x	4.885971 =	2.442986
701 2		.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
607		.500000 x	10.323299 =	5.161650
606		.800000 x	9.418209 =	7.534567
407		.040000 x	728.610485 =	29.144419
714		2.600000 x	7.218484 =	18.768058
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800

			B.T =	182.719192
3300A 2	3300A 2			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.053732 =	.763433
701 4		.500000 x	4.580598 =	2.290299
701 2		.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
319		.040000 x	22.070000 =	.882800
113		2.000000 x	20.419486 =	40.838972
407		.040000 x	728.610485 =	29.144419
611		.500000 x	25.716817 =	12.858409
606		.800000 x	9.418209 =	7.534567
714		2.600000 x	7.218484 =	18.768058
111		2.700000 x	15.741598 =	42.502315

			B.T =	190.263265

3300A 3

3300A 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.053732 =	.763433
701	4	.800000 x	4.580598 =	3.664478
701	2	.500000 x	4.885971 =	2.442986
630		.250000 x	3.204864 =	.801216
610		.800000 x	21.872182 =	17.497746
607		.500000 x	10.323299 =	5.161650
407		.040000 x	728.610485 =	29.144419
714		2.600000 x	7.218484 =	18.768058
319		.040000 x	22.070000 =	.882800
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315

B.T =

192.438072

3300A 4

3300A 4

221		300.000000 x	.099900 =	29.970000
113		2.000000 x	20.419486 =	40.838972
714		2.600000 x	7.218484 =	18.768058
111		2.700000 x	15.741598 =	42.502315
701	5	.250000 x	3.053732 =	.763433
701	4	.800000 x	4.580598 =	3.664478
701	4	.500000 x	4.580598 =	2.290299
630		.250000 x	3.204864 =	.801216
611		.500000 x	25.716817 =	12.858409
610		.800000 x	21.872182 =	17.497746
407		.040000 x	728.610485 =	29.144419
319		.040000 x	22.070000 =	.882800

B.T =

199.982145

3300B 1

3300B 1

713	1	1.000000 x	5.792903 =	5.792903
704		1.000000 x	11.585806 =	11.585806

B.T =

17.378709

3300B 2

3300B 2

713	2	1.000000 x	6.279913 =	6.279913
705		1.000000 x	12.559826 =	12.559826

B.T =

18.839739

3400A 1

3400A 1

221		300.000000 x	.099900 =	29.970000
255		5.000000 x	1.006500 =	5.032500
701	5	.250000 x	3.053732 =	.763433
701	2	.800000 x	4.885971 =	3.908777
701	2	.500000 x	4.885971 =	2.442986
630		.250000 x	3.204864 =	.801216
607		.500000 x	10.323299 =	5.161650
606		.800000 x	9.418209 =	7.534567
407		.040000 x	728.610485 =	29.144419
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100

B.T =

196.284789

3400A 2

3400A 2

221		300.000000 x	.099900 =	29.970000
407		.040000 x	728.610485 =	29.144419
701	5	.250000 x	3.053732 =	.763433
701	4	.500000 x	4.580598 =	2.290299
701	2	.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
611		.500000 x	25.716817 =	12.858409
606		.800000 x	9.418209 =	7.534567
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
255		5.000000 x	1.006500 =	5.032500

B.T =

203.828862

3400A 3

3400A 3

221		300.000000 x	.099900 =	29.970000
111		2.700000 x	15.741598 =	42.502315
701	5	.250000 x	3.053732 =	.763433
701	4	.800000 x	4.580598 =	3.664478
701	2	.500000 x	4.885971 =	2.442986
630		.250000 x	3.204864 =	.801216
610		.800000 x	21.872182 =	17.497746
607		.500000 x	10.323299 =	5.161650
407		.040000 x	728.610485 =	29.144419
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
319		.030000 x	22.070000 =	.662100
255		5.000000 x	1.006500 =	5.032500

B.T =

206.003669

3400A 4	3400A 4			
221		300.000000 x	.099900 =	29.970000
407		.040000 x	728.610485 =	29.144419
701 5		.250000 x	3.053732 =	.763433
701 4		.800000 x	4.580598 =	3.664478
701 4		.500000 x	4.580598 =	2.290299
630		.250000 x	3.204864 =	.801216
611		.500000 x	25.716817 =	12.858409
610		.800000 x	21.872182 =	17.497746
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
255		5.000000 x	1.006500 =	5.032500

			B.T =	213.547742
3400B 1	3400B 1			
704		1.000000 x	11.585806 =	11.585806

			B.T =	11.585806
3400B 2	3400B 2			
705		1.000000 x	12.559826 =	12.559826

			B.T =	12.559826
4110A 1	4110A 1			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
701 5		.100000 x	3.053732 =	.305373
701 2		.800000 x	4.885971 =	3.908777
701 2		.500000 x	4.885971 =	2.442986
630		.100000 x	3.204864 =	.320486
607		.500000 x	10.323299 =	5.161650
606		.800000 x	9.418209 =	7.534567
407		.070000 x	728.610485 =	51.002734
113		1.500000 x	20.419486 =	30.629229

			B.T =	199.237194

4110A 2	4110A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.053732 =	.305373
701 4		.500000 x	4.580598 =	2.290299
701 2		.800000 x	4.885971 =	3.908777
630		.100000 x	3.204864 =	.320486
611		.500000 x	25.716817 =	12.858409
606		.800000 x	9.418209 =	7.534567
407		.070000 x	728.610485 =	51.002734
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

B.T = 206.781266

4110A 3	4110A 3			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	728.610485 =	51.002734
701 5		.100000 x	3.053732 =	.305373
701 4		.800000 x	4.580598 =	3.664478
701 2		.500000 x	4.885971 =	2.442986
630		.100000 x	3.204864 =	.320486
610		.800000 x	21.872182 =	17.497746
607		.500000 x	10.323299 =	5.161650
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

B.T = 208.956074

4110A 4	4110A 4			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	728.610485 =	51.002734
610		.800000 x	21.872182 =	17.497746
701 5		.100000 x	3.053732 =	.305373
701 4		.800000 x	4.580598 =	3.664478
701 4		.500000 x	4.580598 =	2.290299
630		.100000 x	3.204864 =	.320486
611		.500000 x	25.716817 =	12.858409
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

B.T = 216.500146

4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
508		1.000000 x	127.984500 =	127.984500
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	537.889000 =	537.889000

B.T = 1,661.831644

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
701 2		1.200000 x	4.885971 =	5.863165
607		1.200000 x	10.323299 =	12.387959
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	17.312112 =	86.560560

			B.T =	166.656684
4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
701 4		1.200000 x	4.580598 =	5.496718
611		1.200000 x	25.716817 =	30.860180
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	17.312112 =	86.560560

			B.T =	184.762458
4120B	4120B			
4110B		.040000 x	1,661.831644 =	66.473266

			B.T =	66.473266
4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.640000 =	26.880000
407		.050000 x	728.610485 =	36.430524
606		.800000 x	9.418209 =	7.534567
607		.500000 x	10.323299 =	5.161650
701 2		.500000 x	4.885971 =	2.442986
701 2		.800000 x	4.885971 =	3.908777
111		2.000000 x	15.741598 =	31.483196

			B.T =	148.806699
4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	728.610485 =	36.430524
701 4		.500000 x	4.580598 =	2.290299
701 2		.800000 x	4.885971 =	3.908777
611		.500000 x	25.716817 =	12.858409
606		.800000 x	9.418209 =	7.534567
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000

			B.T =	156.350772

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
701 4		.800000 x	4.580598 =	3.664478
701 2		.500000 x	4.885971 =	2.442986
610		.800000 x	21.872182 =	17.497746
607		.500000 x	10.323299 =	5.161650
407		.050000 x	728.610485 =	36.430524
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000

B.T = 158.525579

4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.580598 =	2.290299
701 4		.800000 x	4.580598 =	3.664478
611		.500000 x	25.716817 =	12.858409
610		.800000 x	21.872182 =	17.497746
407		.050000 x	728.610485 =	36.430524
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000

B.T = 166.069652

4130B	4130B			
4120B		1.000000 x	66.473266 =	66.473266

B.T = 66.473266

4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.053732 =	.458060
601		1.050000 x	23.612397 =	24.793017
630		.150000 x	3.204864 =	.480730
701 2		1.050000 x	4.885971 =	5.130270
701 2		.300000 x	4.885971 =	1.465791
607		.300000 x	10.323299 =	3.096990
222		10.000000 x	.070000 =	.700000

B.T = 42.618357

4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.053732 =	.458060
701 4		.300000 x	4.580598 =	1.374179
701 2		1.050000 x	4.885971 =	5.130270
630		.150000 x	3.204864 =	.480730
611		.300000 x	25.716817 =	7.715045
601		1.050000 x	23.612397 =	24.793017
222		10.000000 x	.070000 =	.700000

B.T = 47.144800

4210A 3	4210A 3			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.323299 =	3.096990
630		.150000 x	3.204864 =	.480730
701 5		.150000 x	3.053732 =	.458060
701 2		.300000 x	4.885971 =	1.465791
701 2		1.050000 x	4.885971 =	5.130270
609		1.050000 x	19.806043 =	20.796345

B.T = 38.621685

4210A 4	4210A 4			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.885971 =	5.130270
701 5		.150000 x	3.053732 =	.458060
701 4		.300000 x	4.580598 =	1.374179
609		1.050000 x	19.806043 =	20.796345
630		.150000 x	3.204864 =	.480730
611		.300000 x	25.716817 =	7.715045

B.T = 43.148129

4210B	4210B			
111		4.000000 x	15.741598 =	62.966392
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
112		1.500000 x	17.312112 =	25.968168

B.T = 143.445697

4220A 1	4220A 1			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
407		.040000 x	728.610485 =	29.144419
606		.800000 x	9.418209 =	7.534567
607		.500000 x	10.323299 =	5.161650
630		.250000 x	3.204864 =	.801216
701 5		.250000 x	3.053732 =	.763433
701 2		.800000 x	4.885971 =	3.908777
701 2		.500000 x	4.885971 =	2.442986

B.T = 109.046451

4220A 2	4220A 2			
221		200.000000 x	.099900 =	19.980000
113		1.000000 x	20.419486 =	20.419486
606		.800000 x	9.418209 =	7.534567
701 5		.250000 x	3.053732 =	.763433
701 4		.500000 x	4.580598 =	2.290299
701 2		.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
611		.500000 x	25.716817 =	12.858409
407		.040000 x	728.610485 =	29.144419
111		1.200000 x	15.741598 =	18.889918

B.T = 116.590524

4220A 3	4220A 3			
221		200.000000 x	.099900 =	19.980000
701 4		.800000 x	4.580598 =	3.664478
701 2		.500000 x	4.885971 =	2.442986
630		.250000 x	3.204864 =	.801216
610		.800000 x	21.872182 =	17.497746
607		.500000 x	10.323299 =	5.161650
407		.040000 x	728.610485 =	29.144419
113		1.000000 x	20.419486 =	20.419486
111		1.200000 x	15.741598 =	18.889918
701 5		.250000 x	3.053732 =	.763433

B.T = 118.765331

4220A 4	4220A 4			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	728.610485 =	29.144419
611		.500000 x	25.716817 =	12.858409
701 5		.250000 x	3.053732 =	.763433
701 4		.500000 x	4.580598 =	2.290299
701 4		.800000 x	4.580598 =	3.664478
630		.250000 x	3.204864 =	.801216
610		.800000 x	21.872182 =	17.497746
113		1.000000 x	20.419486 =	20.419486

B.T = 126.309404

4300A 1	4300A 1			
221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.741598 =	31.483196
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	3.053732 =	.763433
701 2		.800000 x	4.885971 =	3.908777
701 2		.500000 x	4.885971 =	2.442986
630		.250000 x	3.204864 =	.801216
607		.500000 x	10.323299 =	5.161650
606		.800000 x	9.418209 =	7.534567
407		.040000 x	728.610485 =	29.144419
714		1.150000 x	7.218484 =	8.301257
			AΘΡΟΙΣΜΑ =	149.009883
	B.T =	.200000 x	149.009883 =	29.801977
4300A 2	4300A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.053732 =	.763433
701 4		.500000 x	4.580598 =	2.290299
701 2		.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
611		.500000 x	25.716817 =	12.858409
606		.800000 x	9.418209 =	7.534567
407		.040000 x	728.610485 =	29.144419
714		1.150000 x	7.218484 =	8.301257
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
			AΘΡΟΙΣΜΑ =	156.553956
	B.T =	.200000 x	156.553956 =	31.310791
4300A 3	4300A 3			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.053732 =	.763433
701 4		.800000 x	4.580598 =	3.664478
701 2		.500000 x	4.885971 =	2.442986
630		.250000 x	3.204864 =	.801216
610		.800000 x	21.872182 =	17.497746
607		.500000 x	10.323299 =	5.161650
407		.040000 x	728.610485 =	29.144419
714		1.150000 x	7.218484 =	8.301257
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
			AΘΡΟΙΣΜΑ =	158.728763
	B.T =	.200000 x	158.728763 =	31.745753

4300A 4	4300A 4			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.053732 =	.763433
701 4		.800000 x	4.580598 =	3.664478
701 4		.500000 x	4.580598 =	2.290299
714		1.150000 x	7.218484 =	8.301257
113		1.200000 x	20.419486 =	24.503383
610		.800000 x	21.872182 =	17.497746
630		.250000 x	3.204864 =	.801216
611		.500000 x	25.716817 =	12.858409
407		.040000 x	728.610485 =	29.144419
111		2.000000 x	15.741598 =	31.483196

			ΑΘΡΟΙΣΜΑ =	166.272836
	B.T =	.200000 x	166.272836 =	33.254567

4300B	4300B			
221		2.000000 x	.099900 =	.199800
112		.400000 x	17.312112 =	6.924845
262		4.000000 x	.980000 =	3.920000

			B.T =	11.044645
601	601			
111		1.500000 x	15.741598 =	23.612397

			B.T =	23.612397
602	602			
403		.002500 x	670.258257 =	1.675646

			B.T =	1.675646
603	603			
111		.300000 x	15.741598 =	4.722479
412		.003300 x	384.772890 =	1.269751
401		.001000 x	923.834573 =	.923835

			B.T =	6.916065
604	604			
111		.200000 x	15.741598 =	3.148320
404		.005000 x	446.296994 =	2.231485
401		.001100 x	923.834573 =	1.016218
412		.004000 x	384.772890 =	1.539092

			B.T =	7.935114

605	605				
112		.100000 x	17.312112 =		1.731211
401		.001000 x	923.834573 =		.923835
402		.006200 x	894.100992 =		5.543426
412		.004000 x	384.772890 =		1.539092
406		.006200 x	412.666470 =		2.558532

			B.T =		12.296096
606	606				
111		.100000 x	15.741598 =		1.574160
401		.001000 x	923.834573 =		.923835
412		.005000 x	384.772890 =		1.923864
406		.006700 x	412.666470 =		2.764865
404		.005000 x	446.296994 =		2.231485

			B.T =		9.418209
607	607				
111		.100000 x	15.741598 =		1.574160
412		.005000 x	384.772890 =		1.923864
401		.001400 x	923.834573 =		1.293368
406		.006700 x	412.666470 =		2.764865
404		.006200 x	446.296994 =		2.767041

			B.T =		10.323299
608	608				
111		.100000 x	15.741598 =		1.574160
412		.005000 x	384.772890 =		1.923864
406		.006700 x	412.666470 =		2.764865
404		.012500 x	446.296994 =		5.578712
401		.002000 x	923.834573 =		1.847669

			B.T =		13.689271
609	609				
214		.100000 x	1.949500 =		.194950
405		.005000 x	586.783432 =		2.933917
115		.200000 x	20.419486 =		4.083897
111		.800000 x	15.741598 =		12.593278

			B.T =		19.806043

610	610				
214		.100000 x	1.949500 =	.194950	
412		.005000 x	384.772890 =	1.923864	
406		.005000 x	412.666470 =	2.063332	
405		.005000 x	586.783432 =	2.933917	
402		.010000 x	894.100992 =	8.941010	
112		.100000 x	17.312112 =	1.731211	
115		.200000 x	20.419486 =	4.083897	
			B.T =	21.872182	
611	611				
214		.100000 x	1.949500 =	.194950	
112		.100000 x	17.312112 =	1.731211	
405		.005000 x	586.783432 =	2.933917	
412		.005000 x	384.772890 =	1.923864	
406		.005000 x	412.666470 =	2.063332	
402		.014300 x	894.100992 =	12.785644	
115		.200000 x	20.419486 =	4.083897	
			B.T =	25.716817	
612	612				
214		.150000 x	1.949500 =	.292425	
408		.010000 x	555.313066 =	5.553131	
405		.005000 x	586.783432 =	2.933917	
115		.200000 x	20.419486 =	4.083897	
111		.300000 x	15.741598 =	4.722479	
			AΘΡΟΙΣΜΑ =	17.585849	
	B.T =	1.068000 x	17.585849 =	18.781687	
613	613				
214		.150000 x	1.949500 =	.292425	
409		.010000 x	621.634266 =	6.216343	
405		.005000 x	586.783432 =	2.933917	
115		.200000 x	20.419486 =	4.083897	
111		.500000 x	15.741598 =	7.870799	
			AΘΡΟΙΣΜΑ =	21.397381	
	B.T =	1.282000 x	21.397381 =	27.431442	
614	614				
214		.150000 x	1.949500 =	.292425	
111		.500000 x	15.741598 =	7.870799	
115		.200000 x	20.419486 =	4.083897	
410		.010000 x	740.148266 =	7.401483	
405		.005000 x	586.783432 =	2.933917	
			AΘΡΟΙΣΜΑ =	22.582521	
	B.T =	1.602000 x	22.582521 =	36.177199	

615	615				
214		.150000 x	1.949500 =	.292425	
410		.010000 x	740.148266 =	7.401483	
111		.700000 x	15.741598 =	11.019119	
405		.005000 x	586.783432 =	2.933917	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	25.730841	
	B.T =	1.832000 x	25.730841 =	47.138900	
616	616				
214		.150000 x	1.949500 =	.292425	
111		.800000 x	15.741598 =	12.593278	
405		.005000 x	586.783432 =	2.933917	
411		.010000 x	1,029.481266 =	10.294813	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	30.198330	
	B.T =	2.137000 x	30.198330 =	64.533832	
617	617				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	857.461248 =	857.461248	
506		1.000000 x	537.889000 =	537.889000	
503		1.000000 x	1,356.313200 =	1,356.313200	
			AΘΡΟΙΣΜΑ =	2,820.911896	
	B.T =	.006250 x	2,820.911896 =	17.630699	
618	618				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	857.461248 =	857.461248	
506		1.000000 x	537.889000 =	537.889000	
503		1.000000 x	1,356.313200 =	1,356.313200	
			AΘΡΟΙΣΜΑ =	2,820.911896	
	B.T =	.007700 x	2,820.911896 =	21.721022	
619	619				
112		4.000000 x	17.312112 =	69.248448	
503		1.000000 x	1,356.313200 =	1,356.313200	
506		1.000000 x	537.889000 =	537.889000	
513		1.000000 x	857.461248 =	857.461248	
			AΘΡΟΙΣΜΑ =	2,820.911896	
	B.T =	.010000 x	2,820.911896 =	28.209119	

620	620			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	537.889000 =	537.889000
503		1.000000 x	1,356.313200 =	1,356.313200

			ΑΘΡΟΙΣΜΑ =	2,820.911896
	B.T =	.012500 x	2,820.911896 =	35.261399

621	621			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	537.889000 =	537.889000
503		1.000000 x	1,356.313200 =	1,356.313200
513		1.000000 x	857.461248 =	857.461248

			ΑΘΡΟΙΣΜΑ =	2,820.911896
	B.T =	.016600 x	2,820.911896 =	46.827137

630	630			
413		.020000 x	160.243179 =	3.204864

			B.T =	3.204864
701 1	701 1			
406		.012580 x	412.666470 =	5.191344

			B.T =	5.191344
701 2	701 2			
406		.011840 x	412.666470 =	4.885971

			B.T =	4.885971
701 3	701 3			
406		.011544 x	412.666470 =	4.763822

			B.T =	4.763822
701 4	701 4			
406		.011100 x	412.666470 =	4.580598

			B.T =	4.580598
701 5	701 5			
406		.007400 x	412.666470 =	3.053732

			B.T =	3.053732

702	702			
112		8.000000 x	17.312112 =	138.496896
506		1.000000 x	537.889000 =	537.889000
513		.300000 x	857.461248 =	257.238374
509		2.000000 x	180.862500 =	361.725000

			ΑΘΡΟΙΣΜΑ =	1,295.349270
	B.T =	.002500 x	1,295.349270 =	3.238373

703	703			
112		4.000000 x	17.312112 =	69.248448
513		.300000 x	857.461248 =	257.238374
503		1.000000 x	1,356.313200 =	1,356.313200
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	537.889000 =	537.889000

			ΑΘΡΟΙΣΜΑ =	2,593.271022
	B.T =	.002500 x	2,593.271022 =	6.483178

704	704			
112		4.000000 x	17.312112 =	69.248448
513		.500000 x	857.461248 =	428.730624
506		1.000000 x	537.889000 =	537.889000
502		1.000000 x	1,281.293200 =	1,281.293200

			ΑΘΡΟΙΣΜΑ =	2,317.161272
	B.T =	.005000 x	2,317.161272 =	11.585806

705	705			
112		4.000000 x	17.312112 =	69.248448
513		.600000 x	857.461248 =	514.476749
506		1.000000 x	537.889000 =	537.889000
504		1.000000 x	1,644.867400 =	1,644.867400

			ΑΘΡΟΙΣΜΑ =	2,766.481597
	B.T =	.004540 x	2,766.481597 =	12.559826

706	706			
501		1.000000 x	1,356.313200 =	1,356.313200
509		2.000000 x	180.862500 =	361.725000
506		1.000000 x	537.889000 =	537.889000

			ΑΘΡΟΙΣΜΑ =	2,255.927200
	B.T =	.002500 x	2,255.927200 =	5.639818

707	707			
505		1.000000 x	3,168.946000 =	3,168.946000
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	537.889000 =	537.889000

			ΑΘΡΟΙΣΜΑ =	4,079.417000
	B.T =	.001000 x	4,079.417000 =	4.079417

ΑΤΛΕ		3ο Τρίμηνο του 2011		Σελ.	31
				Ημ/νία	22/12/2011
708	708				
708A		1.000000 x	17.453780 =		17.453780
708B		1.000000 x	5.639818 =		5.639818

			B.T =		23.093598
708A	708A				
214		.050000 x	1.949500 =		.097475
513		.010000 x	857.461248 =		8.574612
511		.010000 x	144.690000 =		1.446900
405		.012500 x	586.783432 =		7.334793

			B.T =		17.453780
708B	708B				
706		1.000000 x	5.639818 =		5.639818

			B.T =		5.639818
709	709				
709A		1.000000 x	16.895962 =		16.895962
709B		1.000000 x	5.639818 =		5.639818

			B.T =		22.535780
709A	709A				
506		1.000000 x	537.889000 =		537.889000
512		1.000000 x	813.787920 =		813.787920

			AΘΡΟΙΣΜΑ =		1,351.676920
	B.T =	.012500 x	1,351.676920 =		16.895962

709B	709B				
706		1.000000 x	5.639818 =		5.639818

			B.T =		5.639818
710	710				
710A		1.000000 x	50.134779 =		50.134779
710B		1.000000 x	5.639818 =		5.639818

			B.T =		55.774597
710A	710A				
214		.200000 x	1.949500 =		.389900
405		.025000 x	586.783432 =		14.669586
513		.035000 x	857.461248 =		30.011144
511		.035000 x	144.690000 =		5.064150

			B.T =		50.134779

710B	710B			
706		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818
711	711			
711A		1.000000 x	45.010841 =	45.010841
711B		1.000000 x	5.639818 =	5.639818

			B.T =	50.650659
711A	711A			
506		1.000000 x	537.889000 =	537.889000
512		1.000000 x	813.787920 =	813.787920

			AΘΡΟΙΣΜΑ =	1,351.676920
	B.T =	.033300 x	1,351.676920 =	45.010841

711B	711B			
706		1.000000 x	5.639818 =	5.639818

			B.T =	5.639818
712	712			
513		1.000000 x	857.461248 =	857.461248

			AΘΡΟΙΣΜΑ =	857.461248
	B.T =	.004000 x	857.461248 =	3.429845

713 1	713 1			
704		.500000 x	11.585806 =	5.792903

			B.T =	5.792903
713 2	713 2			
705		.500000 x	12.559826 =	6.279913

			B.T =	6.279913
714	714			
714A		1.000000 x	3.445324 =	3.445324
714B		1.000000 x	3.773160 =	3.773160

			B.T =	7.218484

714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	2.100000 =	2.100000
113		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	103.463196
	B.T =	.033300 x	103.463196 =	3.445324
714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211
			B.T =	3.773160
1111	1111			
1111A		1.000000 x	32.168594 =	32.168594
1111B		1.000000 x	5.639818 =	5.639818
			T.E =	37.808412
1112	1112			
1112A		1.000000 x	33.791923 =	33.791923
1112B		1.000000 x	5.639818 =	5.639818
			T.E =	39.431741
1113	1113			
1113A		1.000000 x	54.462807 =	54.462807
1113B		1.000000 x	5.639818 =	5.639818
			T.E =	60.102625
1114	1114			
1114A		1.000000 x	48.933366 =	48.933366
1114B		1.000000 x	5.639818 =	5.639818
			T.E =	54.573184
1121	1121			
1121A		1.000000 x	22.237837 =	22.237837
1121B		1.000000 x	5.639818 =	5.639818
			T.E =	27.877655
1122	1122			
1122A		1.000000 x	16.895962 =	16.895962
1122B		1.000000 x	5.639818 =	5.639818
			T.E =	22.535780

1123	1123				
1123A		1.000000 x	37.978314 =		37.978314
1123B		1.000000 x	5.639818 =		5.639818

			T.E =		43.618132
1124	1124				
1124A		1.000000 x	29.630355 =		29.630355
1124B		1.000000 x	5.639818 =		5.639818

			T.E =		35.270173
1210	1210				
707		1.000000 x	4.079417 =		4.079417

			T.E =		4.079417
1220	1220				
708		1.000000 x	23.093598 =		23.093598

			T.E =		23.093598
1230	1230				
709		1.000000 x	22.535780 =		22.535780

			T.E =		22.535780
1311	1311				
712		.250000 x	3.429845 =		.857461

			T.E =		.857461
1312	1312				
712		.250000 x	3.429845 =		.857461
701 1		1.000000 x	5.191344 =		5.191344
602		1.000000 x	1.675646 =		1.675646

			T.E =		7.724451
1313	1313				
712		.250000 x	3.429845 =		.857461
603		1.000000 x	6.916065 =		6.916065
701 2		1.000000 x	4.885971 =		4.885971

			T.E =		12.659497

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
712		.250000 x	3.429845 =	.857461	

			T.E =	37.431621	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
701	1	1.000000 x	5.191344 =	5.191344	
602		1.000000 x	1.675646 =	1.675646	

			T.E =	10.329412	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
603		1.000000 x	6.916065 =	6.916065	
701	2	1.000000 x	4.885971 =	4.885971	

			T.E =	15.264458	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
112		.100000 x	17.312112 =	1.731211	

			T.E =	38.305371	
2110	2110				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.238373 =	3.238373	
608		1.000000 x	13.689271 =	13.689271	
701	4	1.000000 x	4.580598 =	4.580598	

			T.E =	23.223165	
2120	2120				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.238373 =	3.238373	
701	2	1.000000 x	4.885971 =	4.885971	
603		1.000000 x	6.916065 =	6.916065	

			T.E =	16.755332	
2130	2130				
712		.500000 x	3.429845 =	1.714923	
604		1.000000 x	7.935114 =	7.935114	
701	2	1.000000 x	4.885971 =	4.885971	
702		1.000000 x	3.238373 =	3.238373	

			T.E =	17.774381	

2140	2140				
712		.500000 x	3.429845 =	1.714923	
605		1.000000 x	12.296096 =	12.296096	
702		1.000000 x	3.238373 =	3.238373	
701	2	1.000000 x	4.885971 =	4.885971	

			T.E =	22.135363	
2210	2210				
712		.500000 x	3.429845 =	1.714923	
609		1.050000 x	19.806043 =	20.796345	
702		1.000000 x	3.238373 =	3.238373	
701	2	1.000000 x	4.885971 =	4.885971	

			T.E =	30.635612	
2220	2220				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.238373 =	3.238373	
701	2	1.000000 x	4.885971 =	4.885971	
609		1.150000 x	19.806043 =	22.776949	

			T.E =	32.616216	
2230	2230				
111		.200000 x	15.741598 =	3.148320	
609		1.200000 x	19.806043 =	23.767252	
701	2	1.000000 x	4.885971 =	4.885971	

			T.E =	31.801542	
2240	2240				
111		.300000 x	15.741598 =	4.722479	
609		1.200000 x	19.806043 =	23.767252	
701	2	1.000000 x	4.885971 =	4.885971	

			T.E =	33.375702	
2310	2310				
612		1.000000 x	18.781687 =	18.781687	
701	3	1.000000 x	4.763822 =	4.763822	
703		1.000000 x	6.483178 =	6.483178	

			T.E =	30.028687	
2320	2320				
613		1.000000 x	27.431442 =	27.431442	
703		1.000000 x	6.483178 =	6.483178	
701	3	1.000000 x	4.763822 =	4.763822	

			T.E =	38.678442	

2330	2330				
614		1.000000 x	36.177199 =		36.177199
703		1.000000 x	6.483178 =		6.483178
701	3	1.000000 x	4.763822 =		4.763822
				T.E =	47.424199
2340	2340				
615		1.000000 x	47.138900 =		47.138900
703		1.000000 x	6.483178 =		6.483178
701	3	1.000000 x	4.763822 =		4.763822
				T.E =	58.385900
2350	2350				
616		1.000000 x	64.533832 =		64.533832
701	3	1.000000 x	4.763822 =		4.763822
703		1.000000 x	6.483178 =		6.483178
				T.E =	75.780832
2410	2410				
617		1.000000 x	17.630699 =		17.630699
703		1.000000 x	6.483178 =		6.483178
				T.E =	24.113877
2420	2420				
618		1.000000 x	21.721022 =		21.721022
703		1.000000 x	6.483178 =		6.483178
				T.E =	28.204200
2430	2430				
619		1.000000 x	28.209119 =		28.209119
703		1.000000 x	6.483178 =		6.483178
				T.E =	34.692297
2440	2440				
620		1.000000 x	35.261399 =		35.261399
703		1.000000 x	6.483178 =		6.483178
				T.E =	41.744577
2450	2450				
621		1.000000 x	46.827137 =		46.827137
703		1.000000 x	6.483178 =		6.483178
				T.E =	53.310315

3110	1	3110	1			
	3110A 1			1.000000 x	130.557243 =	130.557243
	3110B			1.000000 x	17.378709 =	17.378709

					T.E =	147.935952
3110	2	3110	2			
	3110A 2			1.000000 x	138.101315 =	138.101315
	3110B			1.000000 x	17.378709 =	17.378709

					T.E =	155.480024
3110	3	3110	3			
	3110A 3			1.000000 x	140.276123 =	140.276123
	3110B			1.000000 x	17.378709 =	17.378709

					T.E =	157.654832
3110	4	3110	4			
	3110A 4			1.000000 x	147.820195 =	147.820195
	3110B			1.000000 x	17.378709 =	17.378709

					T.E =	165.198904
3120	1	3120	1			
	3120A 1			1.000000 x	130.557243 =	130.557243
	3120B			1.000000 x	18.839739 =	18.839739

					T.E =	149.396982
3120	2	3120	2			
	3120A 2			1.000000 x	138.101315 =	138.101315
	3120B			1.000000 x	18.839739 =	18.839739

					T.E =	156.941054
3120	3	3120	3			
	3120A 3			1.000000 x	140.276123 =	140.276123
	3120B			1.000000 x	18.839739 =	18.839739

					T.E =	159.115862
3120	4	3120	4			
	3120A 4			1.000000 x	147.820195 =	147.820195
	3120B			1.000000 x	18.839739 =	18.839739

					T.E =	166.659934

3210 1	3210 1				
3210A 1		1.000000 x	119.861911 =	119.861911	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	137.240620	
3210 2	3210 2				
3210A 2		1.000000 x	125.897169 =	125.897169	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	143.275878	
3210 3	3210 3				
3210A 3		1.000000 x	127.637015 =	127.637015	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	145.015724	
3210 4	3210 4				
3210A 4		1.000000 x	133.672273 =	133.672273	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	151.050982	
3210 5	3210 5				
3210A 5		1.000000 x	118.643878 =	118.643878	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	136.022587	
3210 6	3210 6				
3210A 6		1.000000 x	124.679136 =	124.679136	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	142.057845	
3210 7	3210 7				
3210A 7		1.000000 x	126.418982 =	126.418982	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	143.797691	
3210 8	3210 8				
3210A 8		1.000000 x	132.454240 =	132.454240	
3210B		1.000000 x	17.378709 =	17.378709	

			T.E =	149.832949	

3220	1	3220	1				
	3220A	1		1.000000 x	119.861911 =	119.861911	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	138.701650
3220	2	3220	2				
	3220A	2		1.000000 x	125.897169 =	125.897169	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	144.736908
3220	3	3220	3				
	3220A	3		1.000000 x	127.637015 =	127.637015	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	146.476754
3220	4	3220	4				
	3220A	4		1.000000 x	133.672273 =	133.672273	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	152.512012
3220	5	3220	5				
	3220A	5		1.000000 x	118.643878 =	118.643878	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	137.483617
3220	6	3220	6				
	3220A	6		1.000000 x	124.679136 =	124.679136	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	143.518875
3220	7	3220	7				
	3220A	7		1.000000 x	126.418982 =	126.418982	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	145.258721
3220	8	3220	8				
	3220A	8		1.000000 x	132.454240 =	132.454240	
	3220B			1.000000 x	18.839739 =	18.839739	

						T.E =	151.293979

3300 1	3300 1				
3300A 1		1.000000 x	182.719192 =		182.719192
3300B 1		1.000000 x	17.378709 =		17.378709
			T.E =		200.097901
3300 2	3300 2				
3300A 1		1.000000 x	182.719192 =		182.719192
3300B 2		1.000000 x	18.839739 =		18.839739
			T.E =		201.558931
3300 3	3300 3				
3300A 2		1.000000 x	190.263265 =		190.263265
3300B 1		1.000000 x	17.378709 =		17.378709
			T.E =		207.641974
3300 4	3300 4				
3300A 2		1.000000 x	190.263265 =		190.263265
3300B 2		1.000000 x	18.839739 =		18.839739
			T.E =		209.103004
3300 5	3300 5				
3300A 3		1.000000 x	192.438072 =		192.438072
3300B 1		1.000000 x	17.378709 =		17.378709
			T.E =		209.816781
3300 6	3300 6				
3300A 3		1.000000 x	192.438072 =		192.438072
3300B 2		1.000000 x	18.839739 =		18.839739
			T.E =		211.277811
3300 7	3300 7				
3300A 4		1.000000 x	199.982145 =		199.982145
3300B 1		1.000000 x	17.378709 =		17.378709
			T.E =		217.360854
3300 8	3300 8				
3300A 4		1.000000 x	199.982145 =		199.982145
3300B 2		1.000000 x	18.839739 =		18.839739
			T.E =		218.821884

3400	1	3400	1			
	3400A	1		1.000000 x	196.284789 =	196.284789
	3400B	1		1.000000 x	11.585806 =	11.585806

				T.E =		207.870595
3400	2	3400	2			
	3400A	1		1.000000 x	196.284789 =	196.284789
	3400B	2		1.000000 x	12.559826 =	12.559826

				T.E =		208.844615
3400	3	3400	3			
	3400A	2		1.000000 x	203.828862 =	203.828862
	3400B	1		1.000000 x	11.585806 =	11.585806

				T.E =		215.414668
3400	4	3400	4			
	3400A	2		1.000000 x	203.828862 =	203.828862
	3400B	2		1.000000 x	12.559826 =	12.559826

				T.E =		216.388688
3400	5	3400	5			
	3400A	3		1.000000 x	206.003669 =	206.003669
	3400B	1		1.000000 x	11.585806 =	11.585806

				T.E =		217.589475
3400	6	3400	6			
	3400A	3		1.000000 x	206.003669 =	206.003669
	3400B	2		1.000000 x	12.559826 =	12.559826

				T.E =		218.563495
3400	7	3400	7			
	3400A	4		1.000000 x	213.547742 =	213.547742
	3400B	1		1.000000 x	11.585806 =	11.585806

				T.E =		225.133548
3400	8	3400	8			
	3400A	4		1.000000 x	213.547742 =	213.547742
	3400B	2		1.000000 x	12.559826 =	12.559826

				T.E =		226.107568

4110	1	4110	1			
4110A	1			1.000000 x	199.237194 =	199.237194
4110B				.025000 x	1,661.831644 =	41.545791

						T.E =
						240.782985
4110	2	4110	2			
4110A	2			1.000000 x	206.781266 =	206.781266
4110B				.025000 x	1,661.831644 =	41.545791

						T.E =
						248.327057
4110	3	4110	3			
4110A	3			1.000000 x	208.956074 =	208.956074
4110B				.025000 x	1,661.831644 =	41.545791

						T.E =
						250.501865
4110	4	4110	4			
4110A	4			1.000000 x	216.500146 =	216.500146
4110B				.025000 x	1,661.831644 =	41.545791

						T.E =
						258.045937
4120	1	4120	1			
4120A	1			1.000000 x	166.656684 =	166.656684
4120B				1.000000 x	66.473266 =	66.473266

						T.E =
						233.129950
4120	2	4120	2			
4120A	2			1.000000 x	184.762458 =	184.762458
4120B				1.000000 x	66.473266 =	66.473266

						T.E =
						251.235724
4130	1	4130	1			
4130A	1			1.000000 x	148.806699 =	148.806699
4130B				1.000000 x	66.473266 =	66.473266

						T.E =
						215.279965
4130	2	4130	2			
4130A	2			1.000000 x	156.350772 =	156.350772
4130B				1.000000 x	66.473266 =	66.473266

						T.E =
						222.824038

4130	3	4130	3			
4130A	3			1.000000 x	158.525579 =	158.525579
4130B				1.000000 x	66.473266 =	66.473266

T.E =						224.998845
4130	4	4130	4			
4130A	4			1.000000 x	166.069652 =	166.069652
4130B				1.000000 x	66.473266 =	66.473266

T.E =						232.542918
4210	1	4210	1			
4210A	1			1.000000 x	42.618357 =	42.618357
4210B				1.000000 x	143.445697 =	143.445697

T.E =						186.064054
4210	2	4210	2			
4210A	2			1.000000 x	47.144800 =	47.144800
4210B				1.000000 x	143.445697 =	143.445697

T.E =						190.590497
4210	3	4210	3			
4210A	3			1.000000 x	38.621685 =	38.621685
4210B				1.000000 x	143.445697 =	143.445697

T.E =						182.067382
4210	4	4210	4			
4210A	4			1.000000 x	43.148129 =	43.148129
4210B				1.000000 x	143.445697 =	143.445697

T.E =						186.593826
4220B	1	4220B	1			
319				.020000 x	22.070000 =	.441400
701	2			.320000 x	4.885971 =	1.563511
601				.320000 x	23.612397 =	7.555967
4220A	1			.800000 x	109.046451 =	87.237161
111				.400000 x	15.741598 =	6.296639
714				1.150000 x	7.218484 =	8.301257

T.E =						111.395934

4220B 2	4220B 2			
319		.020000 x	22.070000 =	.441400
4220A 2		.800000 x	116.590524 =	93.272419
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.885971 =	1.563511
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.218484 =	8.301257

T.E = 117.431193

4220B 3	4220B 3			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.885971 =	1.563511
601		.320000 x	23.612397 =	7.555967
4220A 3		.800000 x	118.765331 =	95.012265
714		1.150000 x	7.218484 =	8.301257
111		.400000 x	15.741598 =	6.296639

T.E = 119.171038

4220B 4	4220B 4			
319		.020000 x	22.070000 =	.441400
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	126.309404 =	101.047523
701 2		.320000 x	4.885971 =	1.563511
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.218484 =	8.301257

T.E = 125.206297

4220B 5	4220B 5			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934
4220A 1		.800000 x	109.046451 =	87.237161
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.218484 =	8.301257

T.E = 110.177901

4220B 6	4220B 6			
319		.020000 x	22.070000 =	.441400
4220A 2		.800000 x	116.590524 =	93.272419
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934
714		1.150000 x	7.218484 =	8.301257

T.E = 116.213159

4220B 7	4220B 7			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934
4220A 3		.800000 x	118.765331 =	95.012265
714		1.150000 x	7.218484 =	8.301257
111		.400000 x	15.741598 =	6.296639

T.E = 117.953005

4220B 8	4220B 8			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.885971 =	1.563511
609		.320000 x	19.806043 =	6.337934
4220A 4		.800000 x	126.309404 =	101.047523
714		1.150000 x	7.218484 =	8.301257
111		.400000 x	15.741598 =	6.296639

T.E = 123.988263

4230 1	4230 1			
221		250.000000 x	.099900 =	24.975000
111		2.000000 x	15.741598 =	31.483196
714		1.150000 x	7.218484 =	8.301257
701 5		.250000 x	3.053732 =	.763433
701 2		.500000 x	4.885971 =	2.442986
701 2		.800000 x	4.885971 =	3.908777
630		.250000 x	3.204864 =	.801216
607		.500000 x	10.323299 =	5.161650
606		.800000 x	9.418209 =	7.534567
407		.040000 x	728.610485 =	29.144419
113		1.200000 x	20.419486 =	24.503383
319		.020000 x	22.070000 =	.441400

T.E = 139.461283

4230 2	4230 2			
221		250.000000 x	.099900 =	24.975000
630		.250000 x	3.204864 =	.801216
701 5		.250000 x	3.053732 =	.763433
701 4		.500000 x	4.580598 =	2.290299
701 2		.800000 x	4.885971 =	3.908777
611		.500000 x	25.716817 =	12.858409
606		.800000 x	9.418209 =	7.534567
407		.040000 x	728.610485 =	29.144419
714		1.150000 x	7.218484 =	8.301257
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	22.070000 =	.441400

T.E = 147.005356

4230	3	4230	3		
221				250.000000 x	.099900 = 24.975000
701	5			.250000 x	3.053732 = .763433
701	4			.800000 x	4.580598 = 3.664478
701	2			.500000 x	4.885971 = 2.442986
630				.250000 x	3.204864 = .801216
610				.800000 x	21.872182 = 17.497746
607				.500000 x	10.323299 = 5.161650
407				.040000 x	728.610485 = 29.144419
714				1.150000 x	7.218484 = 8.301257
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196
319				.020000 x	22.070000 = .441400

T.E = 149.180163

4230	4	4230	4		
221				250.000000 x	.099900 = 24.975000
701	5			.250000 x	3.053732 = .763433
701	4			.500000 x	4.580598 = 2.290299
701	4			.800000 x	4.580598 = 3.664478
630				.250000 x	3.204864 = .801216
319				.020000 x	22.070000 = .441400
111				2.000000 x	15.741598 = 31.483196
407				.040000 x	728.610485 = 29.144419
611				.500000 x	25.716817 = 12.858409
610				.800000 x	21.872182 = 17.497746
714				1.150000 x	7.218484 = 8.301257
113				1.200000 x	20.419486 = 24.503383

T.E = 156.724236

4240	1	4240	1		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	3.053732 = .763433
701	2			.500000 x	4.885971 = 2.442986
701	2			.800000 x	4.885971 = 3.908777
630				.250000 x	3.204864 = .801216
607				.500000 x	10.323299 = 5.161650
606				.800000 x	9.418209 = 7.534567
407				.040000 x	728.610485 = 29.144419
714				1.150000 x	7.218484 = 8.301257
319				.020000 x	22.070000 = .441400
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196

T.E = 144.456283

4240	2	4240	2		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	3.053732 = .763433
701	4			.500000 x	4.580598 = 2.290299
701	2			.800000 x	4.885971 = 3.908777
630				.250000 x	3.204864 = .801216
319				.020000 x	22.070000 = .441400
113				1.200000 x	20.419486 = 24.503383
407				.040000 x	728.610485 = 29.144419
611				.500000 x	25.716817 = 12.858409
606				.800000 x	9.418209 = 7.534567
714				1.150000 x	7.218484 = 8.301257
111				2.000000 x	15.741598 = 31.483196

T.E = 152.000356

4240	3	4240	3		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	3.053732 = .763433
701	4			.800000 x	4.580598 = 3.664478
701	2			.500000 x	4.885971 = 2.442986
630				.250000 x	3.204864 = .801216
610				.800000 x	21.872182 = 17.497746
607				.500000 x	10.323299 = 5.161650
407				.040000 x	728.610485 = 29.144419
714				1.150000 x	7.218484 = 8.301257
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196
319				.020000 x	22.070000 = .441400

T.E = 154.175163

4240	4	4240	4		
221				300.000000 x	.099900 = 29.970000
714				1.150000 x	7.218484 = 8.301257
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196
701	5			.250000 x	3.053732 = .763433
701	4			.500000 x	4.580598 = 2.290299
701	4			.800000 x	4.580598 = 3.664478
630				.250000 x	3.204864 = .801216
611				.500000 x	25.716817 = 12.858409
610				.800000 x	21.872182 = 17.497746
407				.040000 x	728.610485 = 29.144419
319				.020000 x	22.070000 = .441400

T.E = 161.719236

4300	1	4300	1		
4300A	1			1.000000 x	29.801977 = 29.801977
4300B				1.000000 x	11.044645 = 11.044645

T.E = 40.846622

4300	2	4300	2			
	4300A	2		1.000000 x	31.310791 =	31.310791
	4300B			1.000000 x	11.044645 =	11.044645

				T.E =		42.355436
4300	3	4300	3			
	4300A	3		1.000000 x	31.745753 =	31.745753
	4300B			1.000000 x	11.044645 =	11.044645

				T.E =		42.790398
4300	4	4300	4			
	4300A	4		1.000000 x	33.254567 =	33.254567
	4300B			1.000000 x	11.044645 =	11.044645

				T.E =		44.299212
4400		4400				
	251			1.050000 x	.545500 =	.572775
	113			.050000 x	20.419486 =	1.020974

				T.E =		1.593749
4500		4500				
	251			1.050000 x	.545500 =	.572775
	114			.100000 x	17.312112 =	1.731211
	113			.100000 x	20.419486 =	2.041949

				T.E =		4.345935
4600		4600				
	256			1.000000 x	4.300000 =	4.300000
	113			.100000 x	20.419486 =	2.041949

				T.E =		6.341949
4700		4700				
	253			1.000000 x	4.500000 =	4.500000
	113			.100000 x	20.419486 =	2.041949

				T.E =		6.541949