

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών

4ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	1.186900
212	1.419500
213	4.160000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.545500
252	2.184000
253	4.500000
254	4.500000
255	1.006500
256	4.300000
261	
262	.980000
263	.640000
311	437.840000
312	134.530000
313	206.720000
314	4.530000
315	55.210000
316	4.530000
317	126.080000
318	27.370000
319	22.070000
320	156.740000
321	213.360000
322	296.440000
323	337.580000
324	185.200000
325	317.230000
326	103.360000
327	4.530000
351	451.770000
352	383.570000
353	451.770000
354	592.710000
355	296.440000
356	48.650000
357	233.080000
358	46.930000
359	97.290000
360	102.460000

361	78.370000
362	271.240000
363	102.610000
380	568.910000
381	568.910000
382	568.910000
383	654.300000
384	1,083.720000
385	196.900000
386	519.550000
387	74.960000
388	74.960000
389	74.960000

401	401			
211		110.000000 x	1.186900 =	130.559000
213		10.000000 x	4.160000 =	41.600000
311		1.000000 x	437.840000 =	437.840000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	841.092612

			Η.Δ. =	925.201873
402	402			
211		180.000000 x	1.186900 =	213.642000
213		12.000000 x	4.160000 =	49.920000
117		8.000000 x	10.001019 =	80.008152
116		8.000000 x	23.886192 =	191.089536
112		8.000000 x	17.312112 =	138.496896
312		1.000000 x	134.530000 =	134.530000
212		5.000000 x	1.419500 =	7.097500

			ΑΘΡΟΙΣΜΑ =	814.784084

			Η.Δ. =	896.262492
403	403			
211		80.000000 x	1.186900 =	94.952000
254		2.500000 x	4.500000 =	11.250000
213		6.000000 x	4.160000 =	24.960000
313		1.000000 x	206.720000 =	206.720000
117		8.000000 x	10.001019 =	80.008152
116		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	608.979688

			Η.Δ. =	669.877657
404	404			
211		80.000000 x	1.186900 =	94.952000
212		2.000000 x	1.419500 =	2.839000
118		8.000000 x	21.778427 =	174.227416
119		4.000000 x	10.001019 =	40.004076
314		1.000000 x	4.530000 =	4.530000
112		4.000000 x	17.312112 =	69.248448
213		5.000000 x	4.160000 =	20.800000

			ΑΘΡΟΙΣΜΑ =	406.600940

			Η.Δ. =	447.261034

405	405			
211		40.000000 x	1.186900 =	47.476000
213		2.000000 x	4.160000 =	8.320000
118		4.000000 x	21.778427 =	87.113708
115		16.000000 x	20.419486 =	326.711776
316		2.000000 x	4.530000 =	9.060000
315		1.000000 x	55.210000 =	55.210000

			ΑΘΡΟΙΣΜΑ =	533.891484

			Η.Δ. =	587.280632
406	406			
211		80.000000 x	1.186900 =	94.952000
120		8.000000 x	16.777917 =	134.223336
213		5.000000 x	4.160000 =	20.800000
317		1.000000 x	126.080000 =	126.080000

			ΑΘΡΟΙΣΜΑ =	376.055336

			Η.Δ. =	413.660870
407	407			
212		17.000000 x	1.419500 =	24.131500
318		1.000000 x	27.370000 =	27.370000
213		1.000000 x	4.160000 =	4.160000
118		4.000000 x	21.778427 =	87.113708
112		30.000000 x	17.312112 =	519.363360

			ΑΘΡΟΙΣΜΑ =	662.138568

			Η.Δ. =	728.352425
408	408			
211		30.000000 x	1.186900 =	35.607000
213		3.000000 x	4.160000 =	12.480000
320		1.000000 x	156.740000 =	156.740000
112		4.000000 x	17.312112 =	69.248448
116		8.000000 x	23.886192 =	191.089536
117		4.000000 x	10.001019 =	40.004076

			ΑΘΡΟΙΣΜΑ =	505.169060

			Η.Δ. =	555.685966
409	409			
211		50.000000 x	1.186900 =	59.345000
213		5.000000 x	4.160000 =	20.800000
116		8.000000 x	23.886192 =	191.089536
117		4.000000 x	10.001019 =	40.004076
112		4.000000 x	17.312112 =	69.248448
324		1.000000 x	185.200000 =	185.200000

			ΑΘΡΟΙΣΜΑ =	565.687060

			Η.Δ. =	622.255766

410	410			
211		100.000000 x	1.186900 =	118.690000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.886192 =	191.089536
112		4.000000 x	17.312112 =	69.248448
321		1.000000 x	213.360000 =	213.360000
213		10.000000 x	4.160000 =	41.600000

			ΑΘΡΟΙΣΜΑ =	673.992060

			Η.Δ. =	741.391266
411	411			
211		200.000000 x	1.186900 =	237.380000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.886192 =	191.089536
112		4.000000 x	17.312112 =	69.248448
213		20.000000 x	4.160000 =	83.200000
325		1.000000 x	317.230000 =	317.230000

			ΑΘΡΟΙΣΜΑ =	938.152060

			Η.Δ. =	1,031.967266
412	412			
211		40.000000 x	1.186900 =	47.476000
116		8.000000 x	23.886192 =	191.089536
326		1.000000 x	103.360000 =	103.360000
213		2.000000 x	4.160000 =	8.320000

			ΑΘΡΟΙΣΜΑ =	350.245536

			Η.Δ. =	385.270090
413	413			
211		15.000000 x	1.186900 =	17.803500
213		1.500000 x	4.160000 =	6.240000
118		3.000000 x	21.778427 =	65.335281
112		3.000000 x	17.312112 =	51.936336
327		1.000000 x	4.530000 =	4.530000

			ΑΘΡΟΙΣΜΑ =	145.845117

			Η.Δ. =	160.429629
501	501			
211		170.000000 x	1.186900 =	201.773000
351		1.000000 x	451.770000 =	451.770000
380		1.000000 x	568.910000 =	568.910000
213		3.000000 x	4.160000 =	12.480000

			ΑΘΡΟΙΣΜΑ =	1,234.933000

			Η.Δ. =	1,358.426300

502	502			
211		170.000000 x	1.186900 =	201.773000
213		3.000000 x	4.160000 =	12.480000
381		1.000000 x	568.910000 =	568.910000
352		1.000000 x	383.570000 =	383.570000

			ΑΘΡΟΙΣΜΑ =	1,166.733000

			Η.Δ. =	1,283.406300
503	503			
211		170.000000 x	1.186900 =	201.773000
382		1.000000 x	568.910000 =	568.910000
353		1.000000 x	451.770000 =	451.770000
213		3.000000 x	4.160000 =	12.480000

			ΑΘΡΟΙΣΜΑ =	1,234.933000

			Η.Δ. =	1,358.426300
504	504			
211		190.000000 x	1.186900 =	225.511000
383		1.000000 x	654.300000 =	654.300000
354		1.000000 x	592.710000 =	592.710000
213		6.000000 x	4.160000 =	24.960000

			ΑΘΡΟΙΣΜΑ =	1,497.481000

			Η.Δ. =	1,647.229100
505	505			
211		1,250.000000 x	1.186900 =	1,483.625000
384		1.000000 x	1,083.720000 =	1,083.720000
355		1.000000 x	296.440000 =	296.440000
213		7.500000 x	4.160000 =	31.200000

			ΑΘΡΟΙΣΜΑ =	2,894.985000

			Η.Δ. =	3,184.483500
506	506			
211		200.000000 x	1.186900 =	237.380000
213		2.000000 x	4.160000 =	8.320000
385		1.000000 x	196.900000 =	196.900000
356		1.000000 x	48.650000 =	48.650000

			ΑΘΡΟΙΣΜΑ =	491.250000

			Η.Δ. =	540.375000
507	507			
211		2,100.000000 x	1.186900 =	2,492.490000
386		1.000000 x	519.550000 =	519.550000
357		1.000000 x	233.080000 =	233.080000
213		35.000000 x	4.160000 =	145.600000

			ΑΘΡΟΙΣΜΑ =	3,390.720000

			Η.Δ. =	3,661.977600

508	508				
358		1.000000 x	46.930000 =		46.930000
387		1.000000 x	74.960000 =		74.960000

			ΑΘΡΟΙΣΜΑ =		121.890000

			Η.Δ. =		127.984500
509	509				
359		1.000000 x	97.290000 =		97.290000
388		1.000000 x	74.960000 =		74.960000

			ΑΘΡΟΙΣΜΑ =		172.250000

			Η.Δ. =		180.862500
510	510				
360		1.000000 x	102.460000 =		102.460000
389		1.000000 x	74.960000 =		74.960000

			ΑΘΡΟΙΣΜΑ =		177.420000

			Η.Δ. =		186.291000
511	511				
509		.800000 x	180.862500 =		144.690000

			Η.Δ. =		144.690000
512	512				
501		.600000 x	1,358.426300 =		815.055780

			Η.Δ. =		815.055780
513	513				
363		1.000000 x	102.610000 =		102.610000
123		8.000000 x	64.260999 =		514.087992
121		8.000000 x	16.585068 =		132.680544
122		8.000000 x	13.510339 =		108.082712

			Η.Δ. =		857.461248
1111A	1111A				
214		.200000 x	1.949500 =		.389900
511		.020000 x	144.690000 =		2.893800
405		.020000 x	587.280632 =		11.745613
513		.020000 x	857.461248 =		17.149225

			Β.Τ =		32.178538

1111B	1111B			
501		1.000000 x	1,358.426300 =	1,358.426300
506		1.000000 x	540.375000 =	540.375000
509		2.000000 x	180.862500 =	361.725000

			AΘΡΟΙΣΜΑ =	2,260.526300
	B.T =	.002500 x	2,260.526300 =	5.651316

1112A	1112A			
506		1.000000 x	540.375000 =	540.375000
512		1.000000 x	815.055780 =	815.055780

			AΘΡΟΙΣΜΑ =	1,355.430780
	B.T =	.025000 x	1,355.430780 =	33.885770

1112B	1112B			
1111B		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
1113A	1113A			
214		.200000 x	1.949500 =	.389900
112		.250000 x	17.312112 =	4.328028
511		.035000 x	144.690000 =	5.064150
513		.035000 x	857.461248 =	30.011144
405		.025000 x	587.280632 =	14.682016

			B.T =	54.475237
1113B	1113B			
1111B		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
1114A	1114A			
112		.250000 x	17.312112 =	4.328028
506		.033000 x	540.375000 =	17.832375
512		.033000 x	815.055780 =	26.896841

			B.T =	49.057244
1114B	1114B			
1111B		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316

1121A	1121A			
214		.150000 x	1.949500 =	.292425
115		.500000 x	20.419486 =	10.209743
405		.020000 x	587.280632 =	11.745613

			B.T =	22.247781
1121B	1121B			
1111B		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
1122A	1122A			
506		1.000000 x	540.375000 =	540.375000
512		1.000000 x	815.055780 =	815.055780

			AΘΡΟΙΣΜΑ =	1,355.430780
	B.T =	.012500 x	1,355.430780 =	16.942885

1122B	1122B			
1111B		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
1123A	1123A			
214		.150000 x	1.949500 =	.292425
112		.150000 x	17.312112 =	2.596817
405		.025000 x	587.280632 =	14.682016
115		1.000000 x	20.419486 =	20.419486

			B.T =	37.990744
1123B	1123B			
1111B		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
1124A	1124A			
112		.150000 x	17.312112 =	2.596817
506		.020000 x	540.375000 =	10.807500
512		.020000 x	815.055780 =	16.301116

			B.T =	29.705432
1124B	1124B			
1111B		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316

3110A 1	3110A 1			
221		250.000000 x	.099900 =	24.975000
607		.500000 x	10.340339 =	5.170170
701 2		.500000 x	4.897745 =	2.448873
701 5		.250000 x	3.061090 =	.765273
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
606		.800000 x	9.433545 =	7.546836
113		1.200000 x	20.419486 =	24.503383
714		1.400000 x	7.221282 =	10.109795
407		.040000 x	728.352425 =	29.134097
319		.020000 x	22.070000 =	.441400
112		1.200000 x	17.312112 =	20.774534
			B.T =	130.589704
3110A 2	3110A 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.061090 =	.765273
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
611		.500000 x	25.757670 =	12.878835
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
714		1.400000 x	7.221282 =	10.109795
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	22.070000 =	.441400
			B.T =	138.145315
3110A 3	3110A 3			
221		250.000000 x	.099900 =	24.975000
112		1.200000 x	17.312112 =	20.774534
113		1.200000 x	20.419486 =	24.503383
714		1.400000 x	7.221282 =	10.109795
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 2		.500000 x	4.897745 =	2.448873
630		.250000 x	3.208593 =	.802148
610		.800000 x	21.903741 =	17.522993
607		.500000 x	10.340339 =	5.170170
407		.040000 x	728.352425 =	29.134097
319		.020000 x	22.070000 =	.441400
			B.T =	140.320974

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
113		1.200000 x	20.419486 =	24.503383
630		.250000 x	3.208593 =	.802148
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 4		.500000 x	4.591636 =	2.295818
611		.500000 x	25.757670 =	12.878835
610		.800000 x	21.903741 =	17.522993
407		.040000 x	728.352425 =	29.134097
112		1.200000 x	17.312112 =	20.774534
714		1.400000 x	7.221282 =	10.109795
319		.020000 x	22.070000 =	.441400

			B.T =	147.876585
3110B	3110B			
713 1		1.000000 x	5.804401 =	5.804401
704		1.000000 x	11.608802 =	11.608802

			B.T =	17.413203
3120A 1	3120A 1			
3110A 1		1.000000 x	130.589704 =	130.589704

			B.T =	130.589704
3120A 2	3120A 2			
3110A 2		1.000000 x	138.145315 =	138.145315

			B.T =	138.145315
3120A 3	3120A 3			
3110A 3		1.000000 x	140.320974 =	140.320974

			B.T =	140.320974
3120A 4	3120A 4			
3110A 4		1.000000 x	147.876585 =	147.876585

			B.T =	147.876585
3120B	3120B			
713 2		1.000000 x	6.290918 =	6.290918
705		1.000000 x	12.581835 =	12.581835

			B.T =	18.872753

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967
3110A 1		.800000 x	130.589704 =	104.471763

			B.T =	119.891648
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	138.145315 =	110.516252
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967

			B.T =	125.936137
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	140.320974 =	112.256779
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967

			B.T =	127.676664
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967
3110A 4		.800000 x	147.876585 =	118.301268

			B.T =	133.721153
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
3110A 1		.800000 x	130.589704 =	104.471763
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729

			B.T =	118.674410
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729
3110A 2		.800000 x	138.145315 =	110.516252

			B.T =	124.718899

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729
3110A 3		.800000 x	140.320974 =	112.256779
			B.T =	126.459426
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729
3110A 4		.800000 x	147.876585 =	118.301268
			B.T =	132.503915
3210B	3210B			
713 1		1.000000 x	5.804401 =	5.804401
704		1.000000 x	11.608802 =	11.608802
			B.T =	17.413203
3220A 1	3220A 1			
3210A 1		1.000000 x	119.891648 =	119.891648
			B.T =	119.891648
3220A 2	3220A 2			
3210A 2		1.000000 x	125.936137 =	125.936137
			B.T =	125.936137
3220A 3	3220A 3			
3210A 3		1.000000 x	127.676664 =	127.676664
			B.T =	127.676664
3220A 4	3220A 4			
3210A 4		1.000000 x	133.721153 =	133.721153
			B.T =	133.721153
3220A 5	3220A 5			
3210A 5		1.000000 x	118.674410 =	118.674410
			B.T =	118.674410

3220A 6	3220A 6			
3210A 6		1.000000 x	124.718899 =	124.718899
			B.T =	124.718899
3220A 7	3220A 7			
3210A 7		1.000000 x	126.459426 =	126.459426
			B.T =	126.459426
3220A 8	3220A 8			
3210A 8		1.000000 x	132.503915 =	132.503915
			B.T =	132.503915
3220B	3220B			
713 2		1.000000 x	6.290918 =	6.290918
705		1.000000 x	12.581835 =	12.581835
			B.T =	18.872753
3300A 1	3300A 1			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.061090 =	.765273
701 2		.500000 x	4.897745 =	2.448873
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
607		.500000 x	10.340339 =	5.170170
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
714		2.600000 x	7.221282 =	18.775333
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800
			B.T =	182.755012
3300A 2	3300A 2			
221		300.000000 x	.099900 =	29.970000
111		2.700000 x	15.741598 =	42.502315
714		2.600000 x	7.221282 =	18.775333
701 5		.250000 x	3.061090 =	.765273
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
611		.500000 x	25.757670 =	12.878835
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
113		2.000000 x	20.419486 =	40.838972
319		.040000 x	22.070000 =	.882800
			B.T =	190.310623

3300A 3	3300A 3			
221		300.000000 x	.099900 =	29.970000
630		.250000 x	3.208593 =	.802148
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 2		.500000 x	4.897745 =	2.448873
607		.500000 x	10.340339 =	5.170170
610		.800000 x	21.903741 =	17.522993
407		.040000 x	728.352425 =	29.134097
113		2.000000 x	20.419486 =	40.838972
714		2.600000 x	7.221282 =	18.775333
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800

			B.T =	192.486281
3300A 4	3300A 4			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 4		.500000 x	4.591636 =	2.295818
630		.250000 x	3.208593 =	.802148
611		.500000 x	25.757670 =	12.878835
610		.800000 x	21.903741 =	17.522993
407		.040000 x	728.352425 =	29.134097
714		2.600000 x	7.221282 =	18.775333
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800

			B.T =	200.041892
3300B 1	3300B 1			
713 1		1.000000 x	5.804401 =	5.804401
704		1.000000 x	11.608802 =	11.608802

			B.T =	17.413203
3300B 2	3300B 2			
713 2		1.000000 x	6.290918 =	6.290918
705		1.000000 x	12.581835 =	12.581835

			B.T =	18.872753

3400A 1	3400A 1			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	1.006500 =	5.032500
111		2.700000 x	15.741598 =	42.502315
112		1.000000 x	17.312112 =	17.312112
113		2.000000 x	20.419486 =	40.838972
701 5		.250000 x	3.061090 =	.765273
701 2		.800000 x	4.897745 =	3.918196
701 2		.500000 x	4.897745 =	2.448873
630		.250000 x	3.208593 =	.802148
607		.500000 x	10.340339 =	5.170170
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
113		.500000 x	20.419486 =	10.209743
319		.030000 x	22.070000 =	.662100

B.T = 196.313333

3400A 2	3400A 2			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	1.006500 =	5.032500
611		.500000 x	25.757670 =	12.878835
701 5		.250000 x	3.061090 =	.765273
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100

B.T = 203.868944

3400A 3	3400A 3			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 2		.500000 x	4.897745 =	2.448873
630		.250000 x	3.208593 =	.802148
610		.800000 x	21.903741 =	17.522993
607		.500000 x	10.340339 =	5.170170
407		.040000 x	728.352425 =	29.134097
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
255		5.000000 x	1.006500 =	5.032500

B.T = 206.044603

3400A 4	3400A 4			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	1.006500 =	5.032500
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 4		.500000 x	4.591636 =	2.295818
630		.250000 x	3.208593 =	.802148
611		.500000 x	25.757670 =	12.878835
610		.800000 x	21.903741 =	17.522993
407		.040000 x	728.352425 =	29.134097
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
			B.T =	213.600214
3400B 1	3400B 1			
704		1.000000 x	11.608802 =	11.608802
			B.T =	11.608802
3400B 2	3400B 2			
705		1.000000 x	12.581835 =	12.581835
			B.T =	12.581835
4110A 1	4110A 1			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
701 5		.100000 x	3.061090 =	.306109
701 2		.800000 x	4.897745 =	3.918196
701 2		.500000 x	4.897745 =	2.448873
630		.100000 x	3.208593 =	.320859
607		.500000 x	10.340339 =	5.170170
606		.800000 x	9.433545 =	7.546836
407		.070000 x	728.352425 =	50.984670
113		1.500000 x	20.419486 =	30.629229
			B.T =	199.256333

4110A 2	4110A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.061090 =	.306109
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
630		.100000 x	3.208593 =	.320859
611		.500000 x	25.757670 =	12.878835
606		.800000 x	9.433545 =	7.546836
407		.070000 x	728.352425 =	50.984670
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

			B.T =	206.811944
4110A 3	4110A 3			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	728.352425 =	50.984670
701 5		.100000 x	3.061090 =	.306109
701 4		.800000 x	4.591636 =	3.673309
701 2		.500000 x	4.897745 =	2.448873
630		.100000 x	3.208593 =	.320859
610		.800000 x	21.903741 =	17.522993
607		.500000 x	10.340339 =	5.170170
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

			B.T =	208.987603
4110A 4	4110A 4			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	728.352425 =	50.984670
610		.800000 x	21.903741 =	17.522993
701 5		.100000 x	3.061090 =	.306109
701 4		.800000 x	4.591636 =	3.673309
701 4		.500000 x	4.591636 =	2.295818
630		.100000 x	3.208593 =	.320859
611		.500000 x	25.757670 =	12.878835
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

			B.T =	216.543214
4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
508		1.000000 x	127.984500 =	127.984500
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	540.375000 =	540.375000

			B.T =	1,664.317644

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
701 2		1.200000 x	4.897745 =	5.877294
607		1.200000 x	10.340339 =	12.408407
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	17.312112 =	86.560560

			B.T =	166.691261
4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
701 4		1.200000 x	4.591636 =	5.509963
611		1.200000 x	25.757670 =	30.909204
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	17.312112 =	86.560560

			B.T =	184.824727
4120B	4120B			
4110B		.040000 x	1,664.317644 =	66.572706

			B.T =	66.572706
4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.640000 =	26.880000
407		.050000 x	728.352425 =	36.417621
606		.800000 x	9.433545 =	7.546836
607		.500000 x	10.340339 =	5.170170
701 2		.500000 x	4.897745 =	2.448873
701 2		.800000 x	4.897745 =	3.918196
111		2.000000 x	15.741598 =	31.483196

			B.T =	148.829891
4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	728.352425 =	36.417621
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
611		.500000 x	25.757670 =	12.878835
606		.800000 x	9.433545 =	7.546836
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000

			B.T =	156.385502

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
701 4		.800000 x	4.591636 =	3.673309
701 2		.500000 x	4.897745 =	2.448873
610		.800000 x	21.903741 =	17.522993
607		.500000 x	10.340339 =	5.170170
407		.050000 x	728.352425 =	36.417621
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000
			B.T =	158.561161
4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.591636 =	2.295818
701 4		.800000 x	4.591636 =	3.673309
611		.500000 x	25.757670 =	12.878835
610		.800000 x	21.903741 =	17.522993
407		.050000 x	728.352425 =	36.417621
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000
			B.T =	166.116772
4130B	4130B			
4120B		1.000000 x	66.572706 =	66.572706
			B.T =	66.572706
4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.061090 =	.459164
601		1.050000 x	23.612397 =	24.793017
630		.150000 x	3.208593 =	.481289
701 2		1.050000 x	4.897745 =	5.142632
701 2		.300000 x	4.897745 =	1.469324
607		.300000 x	10.340339 =	3.102102
222		10.000000 x	.070000 =	.700000
			B.T =	42.641027
4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.061090 =	.459164
701 4		.300000 x	4.591636 =	1.377491
701 2		1.050000 x	4.897745 =	5.142632
630		.150000 x	3.208593 =	.481289
611		.300000 x	25.757670 =	7.727301
601		1.050000 x	23.612397 =	24.793017
222		10.000000 x	.070000 =	.700000
			B.T =	47.174393

4210A 3	4210A 3			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.340339 =	3.102102
630		.150000 x	3.208593 =	.481289
701 5		.150000 x	3.061090 =	.459164
701 2		.300000 x	4.897745 =	1.469324
701 2		1.050000 x	4.897745 =	5.142632
609		1.050000 x	19.808529 =	20.798955
			B.T =	38.646965
4210A 4	4210A 4			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.897745 =	5.142632
701 5		.150000 x	3.061090 =	.459164
701 4		.300000 x	4.591636 =	1.377491
609		1.050000 x	19.808529 =	20.798955
630		.150000 x	3.208593 =	.481289
611		.300000 x	25.757670 =	7.727301
			B.T =	43.180332
4210B	4210B			
111		4.000000 x	15.741598 =	62.966392
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
112		1.500000 x	17.312112 =	25.968168
			B.T =	143.445697
4220A 1	4220A 1			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
407		.040000 x	728.352425 =	29.134097
606		.800000 x	9.433545 =	7.546836
607		.500000 x	10.340339 =	5.170170
630		.250000 x	3.208593 =	.802148
701 5		.250000 x	3.061090 =	.765273
701 2		.800000 x	4.897745 =	3.918196
701 2		.500000 x	4.897745 =	2.448873
			B.T =	109.074995

4220A 2	4220A 2			
221		200.000000 x	.099900 =	19.980000
113		1.000000 x	20.419486 =	20.419486
606		.800000 x	9.433545 =	7.546836
701 5		.250000 x	3.061090 =	.765273
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
611		.500000 x	25.757670 =	12.878835
407		.040000 x	728.352425 =	29.134097
111		1.200000 x	15.741598 =	18.889918

B.T = 116.630606

4220A 3	4220A 3			
221		200.000000 x	.099900 =	19.980000
701 4		.800000 x	4.591636 =	3.673309
701 2		.500000 x	4.897745 =	2.448873
630		.250000 x	3.208593 =	.802148
610		.800000 x	21.903741 =	17.522993
607		.500000 x	10.340339 =	5.170170
407		.040000 x	728.352425 =	29.134097
113		1.000000 x	20.419486 =	20.419486
111		1.200000 x	15.741598 =	18.889918
701 5		.250000 x	3.061090 =	.765273

B.T = 118.806265

4220A 4	4220A 4			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	728.352425 =	29.134097
611		.500000 x	25.757670 =	12.878835
701 5		.250000 x	3.061090 =	.765273
701 4		.500000 x	4.591636 =	2.295818
701 4		.800000 x	4.591636 =	3.673309
630		.250000 x	3.208593 =	.802148
610		.800000 x	21.903741 =	17.522993
113		1.000000 x	20.419486 =	20.419486

B.T = 126.361876

4300A 1	4300A 1			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.061090 =	.765273
701 2		.800000 x	4.897745 =	3.918196
701 2		.500000 x	4.897745 =	2.448873
630		.250000 x	3.208593 =	.802148
607		.500000 x	10.340339 =	5.170170
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

			ΑΘΡΟΙΣΜΑ =	149.041645
	B.T =	.200000 x	149.041645 =	29.808329

4300A 2	4300A 2			
221		350.000000 x	.099900 =	34.965000
611		.500000 x	25.757670 =	12.878835
701 5		.250000 x	3.061090 =	.765273
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

			ΑΘΡΟΙΣΜΑ =	156.597256
	B.T =	.200000 x	156.597256 =	31.319451

4300A 3	4300A 3			
221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.741598 =	31.483196
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 2		.500000 x	4.897745 =	2.448873
630		.250000 x	3.208593 =	.802148
610		.800000 x	21.903741 =	17.522993
607		.500000 x	10.340339 =	5.170170
407		.040000 x	728.352425 =	29.134097
714		1.150000 x	7.221282 =	8.304474

			ΑΘΡΟΙΣΜΑ =	158.772915
	B.T =	.200000 x	158.772915 =	31.754583

4300A 4	4300A 4			
221		350.000000 x	.099900 =	34.965000
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383
610		.800000 x	21.903741 =	17.522993
701 5		.250000 x	3.061090 =	.765273
701 4		.800000 x	4.591636 =	3.673309
701 4		.500000 x	4.591636 =	2.295818
630		.250000 x	3.208593 =	.802148
611		.500000 x	25.757670 =	12.878835
111		2.000000 x	15.741598 =	31.483196
407		.040000 x	728.352425 =	29.134097

			AΘΡΟΙΣΜΑ =	166.328526
	B.T =	.200000 x	166.328526 =	33.265705

4300B	4300B			
221		2.000000 x	.099900 =	.199800
112		.400000 x	17.312112 =	6.924845
262		4.000000 x	.980000 =	3.920000

			B.T =	11.044645
601	601			
111		1.500000 x	15.741598 =	23.612397

			B.T =	23.612397
602	602			
403		.002500 x	669.877657 =	1.674694

			B.T =	1.674694
603	603			
111		.300000 x	15.741598 =	4.722479
401		.001000 x	925.201873 =	.925202
412		.003300 x	385.270090 =	1.271391

			B.T =	6.919073
604	604			
111		.200000 x	15.741598 =	3.148320
412		.004000 x	385.270090 =	1.541080
404		.005000 x	447.261034 =	2.236305
401		.001100 x	925.201873 =	1.017722

			B.T =	7.943427

605	605			
112		.100000 x	17.312112 =	1.731211
401		.001000 x	925.201873 =	.925202
406		.006200 x	413.660870 =	2.564697
412		.004000 x	385.270090 =	1.541080
402		.006200 x	896.262492 =	5.556827

			B.T =	12.319018
606	606			
111		.100000 x	15.741598 =	1.574160
404		.005000 x	447.261034 =	2.236305
412		.005000 x	385.270090 =	1.926350
406		.006700 x	413.660870 =	2.771528
401		.001000 x	925.201873 =	.925202

			B.T =	9.433545
607	607			
111		.100000 x	15.741598 =	1.574160
412		.005000 x	385.270090 =	1.926350
406		.006700 x	413.660870 =	2.771528
404		.006200 x	447.261034 =	2.773018
401		.001400 x	925.201873 =	1.295283

			B.T =	10.340339
608	608			
111		.100000 x	15.741598 =	1.574160
401		.002000 x	925.201873 =	1.850404
404		.012500 x	447.261034 =	5.590763
412		.005000 x	385.270090 =	1.926350
406		.006700 x	413.660870 =	2.771528

			B.T =	13.713205
609	609			
214		.100000 x	1.949500 =	.194950
111		.800000 x	15.741598 =	12.593278
405		.005000 x	587.280632 =	2.936403
115		.200000 x	20.419486 =	4.083897

			B.T =	19.808529

610	610			
214		.100000 x	1.949500 =	.194950
412		.005000 x	385.270090 =	1.926350
406		.005000 x	413.660870 =	2.068304
405		.005000 x	587.280632 =	2.936403
402		.010000 x	896.262492 =	8.962625
115		.200000 x	20.419486 =	4.083897
112		.100000 x	17.312112 =	1.731211
			B.T =	21.903741
611	611			
214		.100000 x	1.949500 =	.194950
112		.100000 x	17.312112 =	1.731211
402		.014300 x	896.262492 =	12.816554
412		.005000 x	385.270090 =	1.926350
406		.005000 x	413.660870 =	2.068304
405		.005000 x	587.280632 =	2.936403
115		.200000 x	20.419486 =	4.083897
			B.T =	25.757670
612	612			
214		.150000 x	1.949500 =	.292425
408		.010000 x	555.685966 =	5.556860
405		.005000 x	587.280632 =	2.936403
111		.300000 x	15.741598 =	4.722479
115		.200000 x	20.419486 =	4.083897
			AΘΡΟΙΣΜΑ =	17.592064
	B.T =	1.068000 x	17.592064 =	18.788325
613	613			
214		.150000 x	1.949500 =	.292425
409		.010000 x	622.255766 =	6.222558
405		.005000 x	587.280632 =	2.936403
115		.200000 x	20.419486 =	4.083897
111		.500000 x	15.741598 =	7.870799
			AΘΡΟΙΣΜΑ =	21.406082
	B.T =	1.282000 x	21.406082 =	27.442597
614	614			
214		.150000 x	1.949500 =	.292425
111		.500000 x	15.741598 =	7.870799
115		.200000 x	20.419486 =	4.083897
410		.010000 x	741.391266 =	7.413913
405		.005000 x	587.280632 =	2.936403
			AΘΡΟΙΣΜΑ =	22.597437
	B.T =	1.602000 x	22.597437 =	36.201094

615	615			
214		.150000 x	1.949500 =	.292425
410		.010000 x	741.391266 =	7.413913
111		.700000 x	15.741598 =	11.019119
405		.005000 x	587.280632 =	2.936403
115		.200000 x	20.419486 =	4.083897

			ΑΘΡΟΙΣΜΑ =	25.745757
	B.T =	1.832000 x	25.745757 =	47.166226

616	616			
214		.150000 x	1.949500 =	.292425
111		.800000 x	15.741598 =	12.593278
405		.005000 x	587.280632 =	2.936403
411		.010000 x	1,031.967266 =	10.319673
115		.200000 x	20.419486 =	4.083897

			ΑΘΡΟΙΣΜΑ =	30.225676
	B.T =	2.137000 x	30.225676 =	64.592271

617	617			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	540.375000 =	540.375000
503		1.000000 x	1,358.426300 =	1,358.426300

			ΑΘΡΟΙΣΜΑ =	2,825.510996
	B.T =	.006250 x	2,825.510996 =	17.659444

618	618			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	540.375000 =	540.375000
503		1.000000 x	1,358.426300 =	1,358.426300

			ΑΘΡΟΙΣΜΑ =	2,825.510996
	B.T =	.007700 x	2,825.510996 =	21.756435

619	619			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,358.426300 =	1,358.426300
506		1.000000 x	540.375000 =	540.375000
513		1.000000 x	857.461248 =	857.461248

			ΑΘΡΟΙΣΜΑ =	2,825.510996
	B.T =	.010000 x	2,825.510996 =	28.255110

620	620			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	540.375000 =	540.375000
503		1.000000 x	1,358.426300 =	1,358.426300

			ΑΘΡΟΙΣΜΑ =	2,825.510996
	B.T =	.012500 x	2,825.510996 =	35.318887

621	621			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	540.375000 =	540.375000
503		1.000000 x	1,358.426300 =	1,358.426300
513		1.000000 x	857.461248 =	857.461248

			ΑΘΡΟΙΣΜΑ =	2,825.510996
	B.T =	.016600 x	2,825.510996 =	46.903483

630	630			
413		.020000 x	160.429629 =	3.208593

			B.T =	3.208593
701 1	701 1			
406		.012580 x	413.660870 =	5.203854

			B.T =	5.203854
701 2	701 2			
406		.011840 x	413.660870 =	4.897745

			B.T =	4.897745
701 3	701 3			
406		.011544 x	413.660870 =	4.775301

			B.T =	4.775301
701 4	701 4			
406		.011100 x	413.660870 =	4.591636

			B.T =	4.591636
701 5	701 5			
406		.007400 x	413.660870 =	3.061090

			B.T =	3.061090

702	702			
112		8.000000 x	17.312112 =	138.496896
506		1.000000 x	540.375000 =	540.375000
513		.300000 x	857.461248 =	257.238374
509		2.000000 x	180.862500 =	361.725000

			ΑΘΡΟΙΣΜΑ =	1,297.835270
	B.T =	.002500 x	1,297.835270 =	3.244588

703	703			
112		4.000000 x	17.312112 =	69.248448
513		.300000 x	857.461248 =	257.238374
503		1.000000 x	1,358.426300 =	1,358.426300
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	540.375000 =	540.375000

			ΑΘΡΟΙΣΜΑ =	2,597.870122
	B.T =	.002500 x	2,597.870122 =	6.494675

704	704			
112		4.000000 x	17.312112 =	69.248448
513		.500000 x	857.461248 =	428.730624
506		1.000000 x	540.375000 =	540.375000
502		1.000000 x	1,283.406300 =	1,283.406300

			ΑΘΡΟΙΣΜΑ =	2,321.760372
	B.T =	.005000 x	2,321.760372 =	11.608802

705	705			
112		4.000000 x	17.312112 =	69.248448
513		.600000 x	857.461248 =	514.476749
506		1.000000 x	540.375000 =	540.375000
504		1.000000 x	1,647.229100 =	1,647.229100

			ΑΘΡΟΙΣΜΑ =	2,771.329297
	B.T =	.004540 x	2,771.329297 =	12.581835

706	706			
501		1.000000 x	1,358.426300 =	1,358.426300
509		2.000000 x	180.862500 =	361.725000
506		1.000000 x	540.375000 =	540.375000

			ΑΘΡΟΙΣΜΑ =	2,260.526300
	B.T =	.002500 x	2,260.526300 =	5.651316

707	707			
505		1.000000 x	3,184.483500 =	3,184.483500
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	540.375000 =	540.375000

			ΑΘΡΟΙΣΜΑ =	4,097.440500
	B.T =	.001000 x	4,097.440500 =	4.097441

708	708			
708A		1.000000 x	17.459995 =	17.459995
708B		1.000000 x	5.651316 =	5.651316

			B.T =	23.111311
708A	708A			
214		.050000 x	1.949500 =	.097475
513		.010000 x	857.461248 =	8.574612
511		.010000 x	144.690000 =	1.446900
405		.012500 x	587.280632 =	7.341008

			B.T =	17.459995
708B	708B			
706		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
709	709			
709A		1.000000 x	16.942885 =	16.942885
709B		1.000000 x	5.651316 =	5.651316

			B.T =	22.594201
709A	709A			
506		1.000000 x	540.375000 =	540.375000
512		1.000000 x	815.055780 =	815.055780

			AΘΡΟΙΣΜΑ =	1,355.430780
	B.T =	.012500 x	1,355.430780 =	16.942885

709B	709B			
706		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
710	710			
710A		1.000000 x	50.147209 =	50.147209
710B		1.000000 x	5.651316 =	5.651316

			B.T =	55.798525
710A	710A			
214		.200000 x	1.949500 =	.389900
405		.025000 x	587.280632 =	14.682016
513		.035000 x	857.461248 =	30.011144
511		.035000 x	144.690000 =	5.064150

			B.T =	50.147209

710B	710B			
706		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
711	711			
711A		1.000000 x	45.135845 =	45.135845
711B		1.000000 x	5.651316 =	5.651316

			B.T =	50.787161
711A	711A			
506		1.000000 x	540.375000 =	540.375000
512		1.000000 x	815.055780 =	815.055780

			AΘΡΟΙΣΜΑ =	1,355.430780
	B.T =	.033300 x	1,355.430780 =	45.135845

711B	711B			
706		1.000000 x	5.651316 =	5.651316

			B.T =	5.651316
712	712			
513		1.000000 x	857.461248 =	857.461248

			AΘΡΟΙΣΜΑ =	857.461248
	B.T =	.004000 x	857.461248 =	3.429845

713 1	713 1			
704		.500000 x	11.608802 =	5.804401

			B.T =	5.804401
713 2	713 2			
705		.500000 x	12.581835 =	6.290918

			B.T =	6.290918
714	714			
714A		1.000000 x	3.448122 =	3.448122
714B		1.000000 x	3.773160 =	3.773160

			B.T =	7.221282

714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	2.184000 =	2.184000
113		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	103.547196
	B.T =	.033300 x	103.547196 =	3.448122
714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211
			B.T =	3.773160
1111	1111			
1111A		1.000000 x	32.178538 =	32.178538
1111B		1.000000 x	5.651316 =	5.651316
			T.E =	37.829854
1112	1112			
1112A		1.000000 x	33.885770 =	33.885770
1112B		1.000000 x	5.651316 =	5.651316
			T.E =	39.537086
1113	1113			
1113A		1.000000 x	54.475237 =	54.475237
1113B		1.000000 x	5.651316 =	5.651316
			T.E =	60.126553
1114	1114			
1114A		1.000000 x	49.057244 =	49.057244
1114B		1.000000 x	5.651316 =	5.651316
			T.E =	54.708560
1121	1121			
1121A		1.000000 x	22.247781 =	22.247781
1121B		1.000000 x	5.651316 =	5.651316
			T.E =	27.899097
1122	1122			
1122A		1.000000 x	16.942885 =	16.942885
1122B		1.000000 x	5.651316 =	5.651316
			T.E =	22.594201

1123	1123				
1123A		1.000000 x	37.990744 =		37.990744
1123B		1.000000 x	5.651316 =		5.651316
			T.E =		43.642060
1124	1124				
1124A		1.000000 x	29.705432 =		29.705432
1124B		1.000000 x	5.651316 =		5.651316
			T.E =		35.356748
1210	1210				
707		1.000000 x	4.097441 =		4.097441
			T.E =		4.097441
1220	1220				
708		1.000000 x	23.111311 =		23.111311
			T.E =		23.111311
1230	1230				
709		1.000000 x	22.594201 =		22.594201
			T.E =		22.594201
1311	1311				
712		.250000 x	3.429845 =		.857461
			T.E =		.857461
1312	1312				
712		.250000 x	3.429845 =		.857461
701 1		1.000000 x	5.203854 =		5.203854
602		1.000000 x	1.674694 =		1.674694
			T.E =		7.736009
1313	1313				
712		.250000 x	3.429845 =		.857461
603		1.000000 x	6.919073 =		6.919073
701 2		1.000000 x	4.897745 =		4.897745
			T.E =		12.674279

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
712		.250000 x	3.429845 =	.857461	

			T.E =	37.431621	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
701	1	1.000000 x	5.203854 =	5.203854	
602		1.000000 x	1.674694 =	1.674694	

			T.E =	10.340970	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
603		1.000000 x	6.919073 =	6.919073	
701	2	1.000000 x	4.897745 =	4.897745	

			T.E =	15.279240	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
112		.100000 x	17.312112 =	1.731211	

			T.E =	38.305371	
2110	2110				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.244588 =	3.244588	
608		1.000000 x	13.713205 =	13.713205	
701	4	1.000000 x	4.591636 =	4.591636	

			T.E =	23.264352	
2120	2120				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.244588 =	3.244588	
701	2	1.000000 x	4.897745 =	4.897745	
603		1.000000 x	6.919073 =	6.919073	

			T.E =	16.776329	
2130	2130				
712		.500000 x	3.429845 =	1.714923	
604		1.000000 x	7.943427 =	7.943427	
701	2	1.000000 x	4.897745 =	4.897745	
702		1.000000 x	3.244588 =	3.244588	

			T.E =	17.800683	

2140	2140			
712		.500000 x	3.429845 =	1.714923
605		1.000000 x	12.319018 =	12.319018
702		1.000000 x	3.244588 =	3.244588
701 2		1.000000 x	4.897745 =	4.897745

			T.E =	22.176274
2210	2210			
712		.500000 x	3.429845 =	1.714923
609		1.050000 x	19.808529 =	20.798955
702		1.000000 x	3.244588 =	3.244588
701 2		1.000000 x	4.897745 =	4.897745

			T.E =	30.656211
2220	2220			
712		.500000 x	3.429845 =	1.714923
702		1.000000 x	3.244588 =	3.244588
701 2		1.000000 x	4.897745 =	4.897745
609		1.150000 x	19.808529 =	22.779808

			T.E =	32.637064
2230	2230			
111		.200000 x	15.741598 =	3.148320
609		1.200000 x	19.808529 =	23.770235
701 2		1.000000 x	4.897745 =	4.897745

			T.E =	31.816299
2240	2240			
111		.300000 x	15.741598 =	4.722479
609		1.200000 x	19.808529 =	23.770235
701 2		1.000000 x	4.897745 =	4.897745

			T.E =	33.390459
2310	2310			
612		1.000000 x	18.788325 =	18.788325
701 3		1.000000 x	4.775301 =	4.775301
703		1.000000 x	6.494675 =	6.494675

			T.E =	30.058301
2320	2320			
613		1.000000 x	27.442597 =	27.442597
703		1.000000 x	6.494675 =	6.494675
701 3		1.000000 x	4.775301 =	4.775301

			T.E =	38.712573

2330	2330				
614		1.000000 x	36.201094 =		36.201094
703		1.000000 x	6.494675 =		6.494675
701 3		1.000000 x	4.775301 =		4.775301
				T.E =	47.471070
2340	2340				
615		1.000000 x	47.166226 =		47.166226
703		1.000000 x	6.494675 =		6.494675
701 3		1.000000 x	4.775301 =		4.775301
				T.E =	58.436202
2350	2350				
616		1.000000 x	64.592271 =		64.592271
701 3		1.000000 x	4.775301 =		4.775301
703		1.000000 x	6.494675 =		6.494675
				T.E =	75.862247
2410	2410				
617		1.000000 x	17.659444 =		17.659444
703		1.000000 x	6.494675 =		6.494675
				T.E =	24.154119
2420	2420				
618		1.000000 x	21.756435 =		21.756435
703		1.000000 x	6.494675 =		6.494675
				T.E =	28.251110
2430	2430				
619		1.000000 x	28.255110 =		28.255110
703		1.000000 x	6.494675 =		6.494675
				T.E =	34.749785
2440	2440				
620		1.000000 x	35.318887 =		35.318887
703		1.000000 x	6.494675 =		6.494675
				T.E =	41.813562
2450	2450				
621		1.000000 x	46.903483 =		46.903483
703		1.000000 x	6.494675 =		6.494675
				T.E =	53.398158

3110 1	3110 1				
3110A 1		1.000000 x	130.589704 =		130.589704
3110B		1.000000 x	17.413203 =		17.413203

			T.E =		148.002907
3110 2	3110 2				
3110A 2		1.000000 x	138.145315 =		138.145315
3110B		1.000000 x	17.413203 =		17.413203

			T.E =		155.558518
3110 3	3110 3				
3110A 3		1.000000 x	140.320974 =		140.320974
3110B		1.000000 x	17.413203 =		17.413203

			T.E =		157.734177
3110 4	3110 4				
3110A 4		1.000000 x	147.876585 =		147.876585
3110B		1.000000 x	17.413203 =		17.413203

			T.E =		165.289788
3120 1	3120 1				
3120A 1		1.000000 x	130.589704 =		130.589704
3120B		1.000000 x	18.872753 =		18.872753

			T.E =		149.462457
3120 2	3120 2				
3120A 2		1.000000 x	138.145315 =		138.145315
3120B		1.000000 x	18.872753 =		18.872753

			T.E =		157.018068
3120 3	3120 3				
3120A 3		1.000000 x	140.320974 =		140.320974
3120B		1.000000 x	18.872753 =		18.872753

			T.E =		159.193727
3120 4	3120 4				
3120A 4		1.000000 x	147.876585 =		147.876585
3120B		1.000000 x	18.872753 =		18.872753

			T.E =		166.749338

3210 1	3210 1				
3210A 1		1.000000 x	119.891648 =		119.891648
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		137.304851
3210 2	3210 2				
3210A 2		1.000000 x	125.936137 =		125.936137
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		143.349340
3210 3	3210 3				
3210A 3		1.000000 x	127.676664 =		127.676664
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		145.089867
3210 4	3210 4				
3210A 4		1.000000 x	133.721153 =		133.721153
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		151.134356
3210 5	3210 5				
3210A 5		1.000000 x	118.674410 =		118.674410
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		136.087613
3210 6	3210 6				
3210A 6		1.000000 x	124.718899 =		124.718899
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		142.132102
3210 7	3210 7				
3210A 7		1.000000 x	126.459426 =		126.459426
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		143.872629
3210 8	3210 8				
3210A 8		1.000000 x	132.503915 =		132.503915
3210B		1.000000 x	17.413203 =		17.413203

			T.E =		149.917118

3220 1	3220 1				
3220A 1		1.000000 x	119.891648 =		119.891648
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		138.764401
3220 2	3220 2				
3220A 2		1.000000 x	125.936137 =		125.936137
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		144.808890
3220 3	3220 3				
3220A 3		1.000000 x	127.676664 =		127.676664
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		146.549417
3220 4	3220 4				
3220A 4		1.000000 x	133.721153 =		133.721153
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		152.593906
3220 5	3220 5				
3220A 5		1.000000 x	118.674410 =		118.674410
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		137.547163
3220 6	3220 6				
3220A 6		1.000000 x	124.718899 =		124.718899
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		143.591652
3220 7	3220 7				
3220A 7		1.000000 x	126.459426 =		126.459426
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		145.332179
3220 8	3220 8				
3220A 8		1.000000 x	132.503915 =		132.503915
3220B		1.000000 x	18.872753 =		18.872753

			T.E =		151.376668

ΑΤΛΕ		4ο Τρίμηνο του 2011		Σελ.	41
				Ημ/νία	20/07/2012
3300	1	3300	1		
	3300A 1		1.000000 x	182.755012 =	182.755012
	3300B 1		1.000000 x	17.413203 =	17.413203

				T.E =	200.168215
3300	2	3300	2		
	3300A 1		1.000000 x	182.755012 =	182.755012
	3300B 2		1.000000 x	18.872753 =	18.872753

				T.E =	201.627765
3300	3	3300	3		
	3300A 2		1.000000 x	190.310623 =	190.310623
	3300B 1		1.000000 x	17.413203 =	17.413203

				T.E =	207.723826
3300	4	3300	4		
	3300A 2		1.000000 x	190.310623 =	190.310623
	3300B 2		1.000000 x	18.872753 =	18.872753

				T.E =	209.183376
3300	5	3300	5		
	3300A 3		1.000000 x	192.486281 =	192.486281
	3300B 1		1.000000 x	17.413203 =	17.413203

				T.E =	209.899484
3300	6	3300	6		
	3300A 3		1.000000 x	192.486281 =	192.486281
	3300B 2		1.000000 x	18.872753 =	18.872753

				T.E =	211.359034
3300	7	3300	7		
	3300A 4		1.000000 x	200.041892 =	200.041892
	3300B 1		1.000000 x	17.413203 =	17.413203

				T.E =	217.455095
3300	8	3300	8		
	3300A 4		1.000000 x	200.041892 =	200.041892
	3300B 2		1.000000 x	18.872753 =	18.872753

				T.E =	218.914645

3400 1	3400 1				
3400A 1		1.000000 x	196.313333 =	196.313333	
3400B 1		1.000000 x	11.608802 =	11.608802	

			T.E =	207.922135	
3400 2	3400 2				
3400A 1		1.000000 x	196.313333 =	196.313333	
3400B 2		1.000000 x	12.581835 =	12.581835	

			T.E =	208.895168	
3400 3	3400 3				
3400A 2		1.000000 x	203.868944 =	203.868944	
3400B 1		1.000000 x	11.608802 =	11.608802	

			T.E =	215.477746	
3400 4	3400 4				
3400A 2		1.000000 x	203.868944 =	203.868944	
3400B 2		1.000000 x	12.581835 =	12.581835	

			T.E =	216.450779	
3400 5	3400 5				
3400A 3		1.000000 x	206.044603 =	206.044603	
3400B 1		1.000000 x	11.608802 =	11.608802	

			T.E =	217.653405	
3400 6	3400 6				
3400A 3		1.000000 x	206.044603 =	206.044603	
3400B 2		1.000000 x	12.581835 =	12.581835	

			T.E =	218.626438	
3400 7	3400 7				
3400A 4		1.000000 x	213.600214 =	213.600214	
3400B 1		1.000000 x	11.608802 =	11.608802	

			T.E =	225.209016	
3400 8	3400 8				
3400A 4		1.000000 x	213.600214 =	213.600214	
3400B 2		1.000000 x	12.581835 =	12.581835	

			T.E =	226.182049	

4110 1	4110 1				
4110A 1		1.000000 x	199.256333 =	199.256333	
4110B		.025000 x	1,664.317644 =	41.607941	

				T.E =	240.864274
4110 2	4110 2				
4110A 2		1.000000 x	206.811944 =	206.811944	
4110B		.025000 x	1,664.317644 =	41.607941	

				T.E =	248.419885
4110 3	4110 3				
4110A 3		1.000000 x	208.987603 =	208.987603	
4110B		.025000 x	1,664.317644 =	41.607941	

				T.E =	250.595544
4110 4	4110 4				
4110A 4		1.000000 x	216.543214 =	216.543214	
4110B		.025000 x	1,664.317644 =	41.607941	

				T.E =	258.151155
4120 1	4120 1				
4120A 1		1.000000 x	166.691261 =	166.691261	
4120B		1.000000 x	66.572706 =	66.572706	

				T.E =	233.263967
4120 2	4120 2				
4120A 2		1.000000 x	184.824727 =	184.824727	
4120B		1.000000 x	66.572706 =	66.572706	

				T.E =	251.397433
4130 1	4130 1				
4130A 1		1.000000 x	148.829891 =	148.829891	
4130B		1.000000 x	66.572706 =	66.572706	

				T.E =	215.402597
4130 2	4130 2				
4130A 2		1.000000 x	156.385502 =	156.385502	
4130B		1.000000 x	66.572706 =	66.572706	

				T.E =	222.958208

4130 3	4130 3			
4130A 3		1.000000 x	158.561161 =	158.561161
4130B		1.000000 x	66.572706 =	66.572706

			T.E =	225.133867
4130 4	4130 4			
4130A 4		1.000000 x	166.116772 =	166.116772
4130B		1.000000 x	66.572706 =	66.572706

			T.E =	232.689478
4210 1	4210 1			
4210A 1		1.000000 x	42.641027 =	42.641027
4210B		1.000000 x	143.445697 =	143.445697

			T.E =	186.086724
4210 2	4210 2			
4210A 2		1.000000 x	47.174393 =	47.174393
4210B		1.000000 x	143.445697 =	143.445697

			T.E =	190.620090
4210 3	4210 3			
4210A 3		1.000000 x	38.646965 =	38.646965
4210B		1.000000 x	143.445697 =	143.445697

			T.E =	182.092662
4210 4	4210 4			
4210A 4		1.000000 x	43.180332 =	43.180332
4210B		1.000000 x	143.445697 =	143.445697

			T.E =	186.626029
4220B 1	4220B 1			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967
4220A 1		.800000 x	109.074995 =	87.259996
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.221282 =	8.304474

			T.E =	111.425755

4220B 2	4220B 2			
319		.020000 x	22.070000 =	.441400
4220A 2		.800000 x	116.630606 =	93.304485
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.221282 =	8.304474

			T.E =	117.470244
4220B 3	4220B 3			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967
4220A 3		.800000 x	118.806265 =	95.045012
714		1.150000 x	7.221282 =	8.304474
111		.400000 x	15.741598 =	6.296639

			T.E =	119.210771
4220B 4	4220B 4			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.897745 =	1.567278
601		.320000 x	23.612397 =	7.555967
4220A 4		.800000 x	126.361876 =	101.089501
714		1.150000 x	7.221282 =	8.304474
111		.400000 x	15.741598 =	6.296639

			T.E =	125.255260
4220B 5	4220B 5			
319		.020000 x	22.070000 =	.441400
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.221282 =	8.304474
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729
4220A 1		.800000 x	109.074995 =	87.259996

			T.E =	110.208517
4220B 6	4220B 6			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729
4220A 2		.800000 x	116.630606 =	93.304485
714		1.150000 x	7.221282 =	8.304474
111		.400000 x	15.741598 =	6.296639

			T.E =	116.253006

4220B 7	4220B 7			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729
4220A 3		.800000 x	118.806265 =	95.045012
714		1.150000 x	7.221282 =	8.304474
111		.400000 x	15.741598 =	6.296639

T.E = 117.993533

4220B 8	4220B 8			
319		.020000 x	22.070000 =	.441400
4220A 4		.800000 x	126.361876 =	101.089501
714		1.150000 x	7.221282 =	8.304474
701 2		.320000 x	4.897745 =	1.567278
609		.320000 x	19.808529 =	6.338729
111		.400000 x	15.741598 =	6.296639

T.E = 124.038022

4230 1	4230 1			
221		250.000000 x	.0999900 =	24.975000
701 5		.250000 x	3.061090 =	.765273
701 2		.500000 x	4.897745 =	2.448873
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
607		.500000 x	10.340339 =	5.170170
606		.800000 x	9.433545 =	7.546836
407		.040000 x	728.352425 =	29.134097
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	22.070000 =	.441400

T.E = 139.493045

4230 2	4230 2			
221		250.000000 x	.0999900 =	24.975000
701 5		.250000 x	3.061090 =	.765273
701 4		.500000 x	4.591636 =	2.295818
701 2		.800000 x	4.897745 =	3.918196
630		.250000 x	3.208593 =	.802148
319		.020000 x	22.070000 =	.441400
111		2.000000 x	15.741598 =	31.483196
407		.040000 x	728.352425 =	29.134097
611		.500000 x	25.757670 =	12.878835
606		.800000 x	9.433545 =	7.546836
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383

T.E = 147.048656

4230	3	4230	3			
221				250.000000 x	.099900 =	24.975000
701	5			.250000 x	3.061090 =	.765273
701	4			.800000 x	4.591636 =	3.673309
701	2			.500000 x	4.897745 =	2.448873
630				.250000 x	3.208593 =	.802148
610				.800000 x	21.903741 =	17.522993
607				.500000 x	10.340339 =	5.170170
407				.040000 x	728.352425 =	29.134097
714				1.150000 x	7.221282 =	8.304474
319				.020000 x	22.070000 =	.441400
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196

					T.E =	149.224315
4230	4	4230	4			
221				250.000000 x	.099900 =	24.975000
701	5			.250000 x	3.061090 =	.765273
701	4			.500000 x	4.591636 =	2.295818
701	4			.800000 x	4.591636 =	3.673309
630				.250000 x	3.208593 =	.802148
319				.020000 x	22.070000 =	.441400
113				1.200000 x	20.419486 =	24.503383
407				.040000 x	728.352425 =	29.134097
611				.500000 x	25.757670 =	12.878835
610				.800000 x	21.903741 =	17.522993
714				1.150000 x	7.221282 =	8.304474
111				2.000000 x	15.741598 =	31.483196

					T.E =	156.779926
4240	1	4240	1			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	3.061090 =	.765273
701	2			.500000 x	4.897745 =	2.448873
701	2			.800000 x	4.897745 =	3.918196
630				.250000 x	3.208593 =	.802148
607				.500000 x	10.340339 =	5.170170
606				.800000 x	9.433545 =	7.546836
407				.040000 x	728.352425 =	29.134097
714				1.150000 x	7.221282 =	8.304474
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196
319				.020000 x	22.070000 =	.441400

					T.E =	144.488045

4240	2	4240	2			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	3.061090 =	.765273
701	4			.500000 x	4.591636 =	2.295818
701	2			.800000 x	4.897745 =	3.918196
630				.250000 x	3.208593 =	.802148
319				.020000 x	22.070000 =	.441400
111				2.000000 x	15.741598 =	31.483196
407				.040000 x	728.352425 =	29.134097
611				.500000 x	25.757670 =	12.878835
606				.800000 x	9.433545 =	7.546836
714				1.150000 x	7.221282 =	8.304474
113				1.200000 x	20.419486 =	24.503383

T.E = 152.043656

4240	3	4240	3			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	3.061090 =	.765273
701	4			.800000 x	4.591636 =	3.673309
701	2			.500000 x	4.897745 =	2.448873
630				.250000 x	3.208593 =	.802148
610				.800000 x	21.903741 =	17.522993
607				.500000 x	10.340339 =	5.170170
407				.040000 x	728.352425 =	29.134097
714				1.150000 x	7.221282 =	8.304474
319				.020000 x	22.070000 =	.441400
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196

T.E = 154.219315

4240	4	4240	4			
221				300.000000 x	.099900 =	29.970000
319				.020000 x	22.070000 =	.441400
113				1.200000 x	20.419486 =	24.503383
714				1.150000 x	7.221282 =	8.304474
701	5			.250000 x	3.061090 =	.765273
701	4			.500000 x	4.591636 =	2.295818
701	4			.800000 x	4.591636 =	3.673309
630				.250000 x	3.208593 =	.802148
611				.500000 x	25.757670 =	12.878835
610				.800000 x	21.903741 =	17.522993
407				.040000 x	728.352425 =	29.134097
111				2.000000 x	15.741598 =	31.483196

T.E = 161.774926

4300	1	4300	1			
4300A	1			1.000000 x	29.808329 =	29.808329
4300B				1.000000 x	11.044645 =	11.044645

T.E = 40.852974

4300	2	4300	2			
	4300A			1.000000 x	31.319451 =	31.319451
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	42.364096
4300	3	4300	3			
	4300A			1.000000 x	31.754583 =	31.754583
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	42.799228
4300	4	4300	4			
	4300A			1.000000 x	33.265705 =	33.265705
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	44.310350
4400		4400				
	251			1.050000 x	.545500 =	.572775
	113			.050000 x	20.419486 =	1.020974

					T.E =	1.593749
4500		4500				
	251			1.050000 x	.545500 =	.572775
	114			.100000 x	17.312112 =	1.731211
	113			.100000 x	20.419486 =	2.041949

					T.E =	4.345935
4600		4600				
	256			1.000000 x	4.300000 =	4.300000
	113			.100000 x	20.419486 =	2.041949

					T.E =	6.341949
4700		4700				
	253			1.000000 x	4.500000 =	4.500000
	113			.100000 x	20.419486 =	2.041949

					T.E =	6.541949