

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

3ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	Κατχ Τιμή X 1.8117/ 6.46	16.829739
002	Κατχ Τιμή X 1.8117/ 6.46	18.705943
003	Κατχ Τιμή X 1.8117/ 6.46	24.769248
004	Κατχ Τιμή X 1.8117/ 6.67	23.989407
005	Κατχ Τιμή X 1.8117/ 6.67	19.931416
006	(Κατχ Τιμή + Εξαρτ.Τιμή X .8117)	166.700117
007	(Κατχ Τιμή + Εξαρτ.Τιμή X .8117)	166.700117
008	Κατχ Τιμή X 1.8117/ 6.67	19.931416
009		.074800
011		52.420000
012		4.300000
013		25.980000
014		254.850000
015		200.190000
016		30.920000
017		368.170000
018.1		2.830000
018.2		4.300000
019.1		2.830000
019.2		4.300000
021		2.670000
022		.070000
024		50.000000
026		.097700
027		.117200
029		.149900
032		35.000000
035		.125600
036		.128500
040		.203400
051		15.400000
052		15.400000
053		.070000
054		.080000
055		.090000
056		10.580000
057		10.580000
058		9.090000
061		13.560000
062		13.560000
065		13.610000
066		35.000000
067		45.000000
081		11.010000
101		
102		
111		.078400
112		.087900
113		.570000
114		
116		.090300
117		
118		
124		5.900000
127		83.240000
128		90.430000
131		.650000
132		.930000
142		.325000

146	.340000
155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.281700
181	
201	290.000000
203.2	335.000000
203.4	210.000000
205	420.000000
208	1,239.000000
210	
211	
212	1,400.000000
214	
219	3.500000
223.1	1,700.000000
223.2	1,450.000000
223.3	1,135.000000
223.4	1,440.000000
225	4.000000
226	11.500000
227	11.500000
228	35.000000
229	
230	
231	20.000000
232	45.000000
233	21.300000
234	2.700000
236	2.600000
237	1.100000
238	2.600000
240	1.600000
241	
242	1.300000
243.1	2.660000
243.2	3.650000
243.3	4.450000
243.5	6.250000
244	
245	18.600000
246	9.000000
249	19.000000
251	.680000
252	1.750000
253	2.200000
254	2.780000
258	7.390500
259	24.205000
260	.511400
261	.549400
262	.511400
264	1.026200
265	.676500
266	.563000

267	.726500
268	.836500
271	.766500
272	.696500
273	.861500
274	1.062700
276	.602400
277	.781500
278	3.600000
279	3.720000
280	1.000000
281	5.780000
282	.766500
283	1.000100
284	
285	.057500
286	1.562300
288	1.695700
289	.707000
290	3.300000
291	5.000000
293	
294	3.149800
295	5.649200
296	11.781900
297.2	
298.1	4.330000
298.2	3.800000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.668400
352	1.030000
354	.895800
356	.601500
357	1.310300
358	3.035000
360	13.580000
361	1.136300
362	1.270000
363	1.617600
364	1.030000
366	4.545900
370	.267400
371	1.617600

372	2.246200
373	2.486800
375	3.155400
376	.200400
377	.842200
378	13.590000
379	26.780000
380	16.150000
381	67.970000
386	28.630000
388	48.870000
390	1.500000
392	24.930000
401	13.560000
403	15.880000
406	19.630000
409	23.370000
410	31.790000
411	29.680000
412	32.030000
414	23.370000
415	23.370000
418	32.720000
419	32.720000
421	108.710000
422	149.410000
428	4.390000
429	5.390000
430	7.480000
441	.075500
442	.118300
443	1.930000
444	2.143200
445	1.553500
446	2.540000
447	4.393700
450	2.760000
451	1.178800
453	.093000
455	3.000000
456	1.610000
457	.803800
458	5.030000
459	5.030000
460	4.250000
462	
463	3.970000
464	3.720000
465	5.870000
467	3.380000
471	4.100000
473	2.750000
474	3.770000
475	6.230000
476	2.366400
477	
478	2.937600
479	1.815600
480	3.366000

481	5.535000
482	.937000
483	.165000
484	3.800000
485	.820200
487	13.480000
488	5.000000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	1.006100
498	1.124000
499	1.540900
500	2.266200
501	3.070000
502	4.230000
503	1.006100
504	1.332400
505	19.170000
506	1.149500
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.375000
514	41.560000
515	41.230000
519	47.670000
520	40.000000
521	2.390000
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.000000
536	2.500000
537	1.700000
565.3	3.100000
565.5	4.630000
565.6	6.390000
566.3	4.140000
566.5	6.340000
566.6	8.460000

1101	1101				
001		.500000 x	16.829739 =		8.414870

			B.T =		8.414870
1102	1102				
001		1.000000 x	16.829739 =		16.829739

			B.T =		16.829739
1103	1103				
001		.300000 x	16.829739 =		5.048922

			B.T =		5.048922
1104	1104				
015		1.000000 x	200.190000 =		200.190000
291		2.200000 x	5.000000 =		11.000000
004		7.000000 x	23.989407 =		167.925849
002		7.000000 x	18.705943 =		130.941601
484		5.250000 x	3.800000 =		19.950000
485		83.000000 x	.820200 =		68.076600

			AΘΡΟΙΣΜΑ =		598.084050
	B.T =	.004000 x	598.084050 =		2.392336

1111	1111				
006		.060000 x	166.700117 =		10.002007

			B.T =		10.002007
1112	1112				
006		.090000 x	166.700117 =		15.003011

			B.T =		15.003011
1116	1116				
007		.025000 x	166.700117 =		4.167503

			B.T =		4.167503
1117	1117				
007		.110000 x	166.700117 =		18.337013

			B.T =		18.337013
1121	1121				
009		4.000000 x	.074800 =		.299200

			B.T =		.299200

1122	1122			
009		5.000000 x	.074800 =	.374000

			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600

			B.T =	.149600
1126	1126			
001		.400000 x	16.829739 =	6.731896

			B.T =	6.731896
1127	1127			
001		.130000 x	16.829739 =	2.187866

			B.T =	2.187866
1128	1128			
006		.024000 x	166.700117 =	4.000803

			B.T =	4.000803
1131	1131			
007		.090000 x	166.700117 =	15.003011

			B.T =	15.003011
1136	1136			
009		1.000000 x	.074800 =	.074800

			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200

			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000

			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000
			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000
			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
1407		.320000 x	37.605000 =	12.033600
			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.360000 x	37.605000 =	13.537800
			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100
			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.097700 =	14.655000
			B.T =	39.374250
1417	1417			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.097700 =	14.655000
1407		.290000 x	37.605000 =	10.905450
051		.900000 x	15.400000 =	13.860000
			B.T =	39.954450

1418	1418			
021		.200000 x	2.670000 =	.534000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000
026		150.000000 x	.097700 =	14.655000

B.T = 41.286750

1421	1421			
021		.200000 x	2.670000 =	.534000
051		.540000 x	15.400000 =	8.316000
1407		.540000 x	37.605000 =	20.306700
039		4.000000 x	.000000 =	.000000

B.T =

1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.125600 =	9.420000
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	15.400000 =	5.082000
039		5.000000 x	.000000 =	.000000

B.T =

1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000

B.T = 152.456250

1427	1427			
021		.200000 x	2.670000 =	.534000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000
026		150.000000 x	.097700 =	14.655000

B.T = 162.974700

1428	1428			
021		.200000 x	2.670000 =	.534000
051		.200000 x	15.400000 =	3.080000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000

B.T = 126.656000

1429	1429			
021		.200000 x	2.670000 =	.534000
035		200.000000 x	.125600 =	25.120000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000

			B.T =	148.696000
1431	1431			
021		.300000 x	2.670000 =	.801000
032		.960000 x	35.000000 =	33.600000
1407		.320000 x	37.605000 =	12.033600

			B.T =	46.434600
1432	1432			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
051		.640000 x	15.400000 =	9.856000
032		.320000 x	35.000000 =	11.200000

			B.T =	33.890600
1436	1436			
021		.350000 x	2.670000 =	.934500
035		1,100.000000 x	.125600 =	138.160000

			B.T =	139.094500
1437	1437			
021		.200000 x	2.670000 =	.534000
035		75.000000 x	.125600 =	9.420000
051		.380000 x	15.400000 =	5.852000
1407		.620000 x	37.605000 =	23.315100

			B.T =	39.121100
1441	1441			
021		.800000 x	2.670000 =	2.136000
026		250.000000 x	.097700 =	24.425000

			B.T =	26.561000
1442	1442			
021		.250000 x	2.670000 =	.667500
051		.740000 x	15.400000 =	11.396000
026		900.000000 x	.097700 =	87.930000

			B.T =	99.993500

1443	1443			
021		.250000 x	2.670000 =	.667500
051		.860000 x	15.400000 =	13.244000
026		700.000000 x	.097700 =	68.390000

			B.T =	82.301500
1444	1444			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.097700 =	58.620000
051		1.000000 x	15.400000 =	15.400000

			B.T =	74.687500
1445	1445			
021		.250000 x	2.670000 =	.667500
026		450.000000 x	.097700 =	43.965000
051		1.060000 x	15.400000 =	16.324000

			B.T =	60.956500
1446	1446			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.097700 =	34.195000
051		1.120000 x	15.400000 =	17.248000

			B.T =	52.110500
1447	1447			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
051		1.000000 x	15.400000 =	15.400000
026		400.000000 x	.097700 =	39.080000

			B.T =	58.155900
1448	1448			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
051		1.000000 x	15.400000 =	15.400000
039		5.000000 x	.000000 =	.000000
026		400.000000 x	.097700 =	39.080000

			B.T =	
1449	1449			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.097700 =	34.195000
1407		.040000 x	37.605000 =	1.504200
051		1.060000 x	15.400000 =	16.324000

			B.T =	52.690700

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.097700 =	58.620000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.070000 =	105.000000

			B.T =	166.167750
1452	1452			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.070000 =	105.000000
1407		.050000 x	37.605000 =	1.880250
029		600.000000 x	.149900 =	89.940000

			B.T =	197.487750
1453	1453			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.070000 =	115.500000
026		450.000000 x	.097700 =	43.965000

			B.T =	162.012750
1454	1454			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.149900 =	67.455000
053		1,650.000000 x	.070000 =	115.500000
1407		.050000 x	37.605000 =	1.880250

			B.T =	185.502750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.070000 =	115.500000

			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.097700 =	58.620000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.080000 =	120.000000

			B.T =	181.167750

1457	1457			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.080000 =	120.000000
029		600.000000 x	.149900 =	89.940000

			B.T =	212.487750
1458	1458			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.080000 =	132.000000
028		450.000000 x	.000000 =	.000000

			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
054		1,650.000000 x	.080000 =	132.000000
1407		.050000 x	37.605000 =	1.880250
029		450.000000 x	.149900 =	67.455000

			B.T =	202.002750
1461	1461			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.070000 =	105.000000
1407		.080000 x	37.605000 =	3.008400
026		500.000000 x	.097700 =	48.850000

			B.T =	157.525900
1462	1462			
021		.300000 x	2.670000 =	.801000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	41.230000 =	41.230000
051		.100000 x	15.400000 =	1.540000
026		400.000000 x	.097700 =	39.080000

			B.T =	84.531250
1463	1463			
021		.300000 x	2.670000 =	.801000
051		.100000 x	15.400000 =	1.540000
1407		.050000 x	37.605000 =	1.880250
515		1.050000 x	41.230000 =	43.291500
026		250.000000 x	.097700 =	24.425000

			B.T =	71.937750

1464	1464				
021		.200000 x	2.670000 =	.534000	
519		.600000 x	47.670000 =	28.602000	
1407		.120000 x	37.605000 =	4.512600	
051		.420000 x	15.400000 =	6.468000	
026		150.000000 x	.097700 =	14.655000	
			B.T =	54.771600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.900000 x	47.670000 =	42.903000	
051		.150000 x	15.400000 =	2.310000	
026		450.000000 x	.097700 =	43.965000	
			B.T =	90.840150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	47.670000 =	40.042800	
026		450.000000 x	.097700 =	43.965000	
051		.210000 x	15.400000 =	3.234000	
			B.T =	88.903950	
1467	1467				
021		.200000 x	2.670000 =	.534000	
026		450.000000 x	.097700 =	43.965000	
051		.350000 x	15.400000 =	5.390000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	47.670000 =	33.369000	
			B.T =	84.386150	
1471	1471				
251		1.000000 x	.680000 =	.680000	
351		4.000000 x	.668400 =	2.673600	
358		1.000000 x	3.035000 =	3.035000	
364		2.000000 x	1.030000 =	2.060000	
372		.400000 x	2.246200 =	.898480	
370		6.000000 x	.267400 =	1.604400	
			AΘΡΟΙΣΜΑ =	10.951480	
	B.T =	.476190 x	10.951480 =	5.214985	

1472	1472			
251		.600000 x	.680000 =	.408000
351		2.000000 x	.668400 =	1.336800
361		1.000000 x	1.136300 =	1.136300
363		2.000000 x	1.617600 =	3.235200
372		.300000 x	2.246200 =	.673860
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	9.463760
	B.T =	.666667 x	9.463760 =	6.309176
1473	1473			
251		.500000 x	.680000 =	.340000
354		4.000000 x	.895800 =	3.583200
364		2.000000 x	1.030000 =	2.060000
372		.700000 x	2.246200 =	1.572340
370		4.000000 x	.267400 =	1.069600
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	26.015040
	B.T =	.416667 x	26.015040 =	10.839609
1474	1474			
251		.500000 x	.680000 =	.340000
372		.500000 x	2.246200 =	1.123100
370		4.000000 x	.267400 =	1.069600
366		2.000000 x	4.545900 =	9.091800
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
357		4.000000 x	1.310300 =	5.241200
			AΘΡΟΙΣΜΑ =	31.582000
	B.T =	.416667 x	31.582000 =	13.159177
1475	1475			
251		.300000 x	.680000 =	.204000
379		1.000000 x	26.780000 =	26.780000
371		2.000000 x	1.617600 =	3.235200
376		160.000000 x	.200400 =	32.064000
377		6.000000 x	.842200 =	5.053200
378		1.000000 x	13.590000 =	13.590000
375		2.000000 x	3.155400 =	6.310800
354		3.000000 x	.895800 =	2.687400
			AΘΡΟΙΣΜΑ =	89.924600
	B.T =	.416667 x	89.924600 =	37.468613

1476	1476			
251		.500000 x	.680000 =	.340000
373		.200000 x	2.486800 =	.497360
370		6.000000 x	.267400 =	1.604400
352		3.000000 x	1.030000 =	3.090000
			AΘΡΟΙΣΜΑ =	5.531760
	B.T =	.500000 x	5.531760 =	2.765880
1478	1478			
251		3.000000 x	.680000 =	2.040000
372		.500000 x	2.246200 =	1.123100
356		2.000000 x	.601500 =	1.203000
370		6.000000 x	.267400 =	1.604400
			AΘΡΟΙΣΜΑ =	5.970500
	B.T =	.500000 x	5.970500 =	2.985250
1479	1479			
251		6.000000 x	.680000 =	4.080000
370		12.000000 x	.267400 =	3.208800
381		1.000000 x	67.970000 =	67.970000
			AΘΡΟΙΣΜΑ =	75.258800
	B.T =	.454545 x	75.258800 =	34.208511
1480	1480			
251		8.000000 x	.680000 =	5.440000
381		2.000000 x	67.970000 =	135.940000
370		16.000000 x	.267400 =	4.278400
			AΘΡΟΙΣΜΑ =	145.658400
	B.T =	.227273 x	145.658400 =	33.104222
1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.093000 =	.021390
487		.040000 x	13.480000 =	.539200
451		.230000 x	1.178800 =	.271124
			B.T =	.833049
1487	1487			
443		.120000 x	1.930000 =	.231600
451		.170000 x	1.178800 =	.200396
453		.640000 x	.093000 =	.059520
446		.010000 x	2.540000 =	.025400
445		.060000 x	1.553500 =	.093210
			B.T =	.610126

1488	1488			
444		.170000 x	2.143200 =	.364344
453		.500000 x	.093000 =	.046500
451		.170000 x	1.178800 =	.200396
446		.030000 x	2.540000 =	.076200
445		.050000 x	1.553500 =	.077675

			B.T =	.765115
1489	1489			
444		.100000 x	2.143200 =	.214320
453		.430000 x	.093000 =	.039990
451		.350000 x	1.178800 =	.412580
446		.020000 x	2.540000 =	.050800
445		.100000 x	1.553500 =	.155350

			B.T =	.873040
1490	1490			
444		.300000 x	2.143200 =	.642960
445		.100000 x	1.553500 =	.155350
446		.030000 x	2.540000 =	.076200
451		.570000 x	1.178800 =	.671916

			B.T =	1.546426
1491	1491			
444		.270000 x	2.143200 =	.578664
445		.060000 x	1.553500 =	.093210
451		.650000 x	1.178800 =	.766220
446		.020000 x	2.540000 =	.050800

			B.T =	1.488894
1492	1492			
444		.200000 x	2.143200 =	.428640
446		.030000 x	2.540000 =	.076200
445		.040000 x	1.553500 =	.062140
455		.730000 x	3.000000 =	2.190000

			B.T =	2.756980
1501	1501			
011		1.000000 x	52.420000 =	52.420000
012		2.000000 x	4.300000 =	8.600000
005		3.500000 x	19.931416 =	69.759956
005		14.000000 x	19.931416 =	279.039824
485		15.000000 x	.820200 =	12.303000
484		1.750000 x	3.800000 =	6.650000

			B.T =	428.772780

1502	1502				
013		1.000000 x	25.980000 =	25.980000	
005		3.500000 x	19.931416 =	69.759956	
001		26.000000 x	16.829739 =	437.573214	
482		15.000000 x	.937000 =	14.055000	
484		.900000 x	3.800000 =	3.420000	

			B.T =	550.788170	
1503	1503				
014		1.000000 x	254.850000 =	254.850000	
002		2.600000 x	18.705943 =	48.635452	
004		7.000000 x	23.989407 =	167.925849	
484		2.600000 x	3.800000 =	9.880000	
485		44.000000 x	.820200 =	36.088800	

			B.T =	517.380101	
1504	1504				
015		1.000000 x	200.190000 =	200.190000	
004		7.000000 x	23.989407 =	167.925849	
002		7.000000 x	18.705943 =	130.941601	
485		83.000000 x	.820200 =	68.076600	
484		5.250000 x	3.800000 =	19.950000	
291		2.200000 x	5.000000 =	11.000000	

			B.T =	598.084050	
1505	1505				
016		1.000000 x	30.920000 =	30.920000	
004		7.000000 x	23.989407 =	167.925849	
002		1.750000 x	18.705943 =	32.735400	
485		17.500000 x	.820200 =	14.353500	
484		1.750000 x	3.800000 =	6.650000	

			B.T =	252.584749	
1506	1506				
017		1.000000 x	368.170000 =	368.170000	
004		7.000000 x	23.989407 =	167.925849	
002		3.500000 x	18.705943 =	65.470801	
484		6.000000 x	3.800000 =	22.800000	
485		70.000000 x	.820200 =	57.414000	

			B.T =	681.780650	
2101	2101				
002		.300000 x	18.705943 =	5.611783	

			T.E =	5.611783	

2102	2102			
002		.400000 x	18.705943 =	7.482377

			T.E =	7.482377
2103	2103			
002		.400000 x	18.705943 =	7.482377

			T.E =	7.482377
2104A	2104A			
002		.900000 x	18.705943 =	16.835349

			T.E =	16.835349
2104B	2104B			
002		1.400000 x	18.705943 =	26.188320

			T.E =	26.188320
2104E	2104E			
002		2.900000 x	18.705943 =	54.247235

			T.E =	54.247235
2104H	2104H			
002		4.400000 x	18.705943 =	82.306149

			T.E =	82.306149
2104Z	2104Z			
002		3.900000 x	18.705943 =	72.953178

			T.E =	72.953178
2104Γ	2104Γ			
002		1.900000 x	18.705943 =	35.541292

			T.E =	35.541292
2104Δ	2104Δ			
002		2.400000 x	18.705943 =	44.894263

			T.E =	44.894263
2104ΣΤ	2104ΣΤ			
002		3.400000 x	18.705943 =	63.600206

			T.E =	63.600206

2105A	2105A			
002		.900000 x	18.705943 =	16.835349

			T.E =	16.835349
2105B	2105B			
002		1.400000 x	18.705943 =	26.188320

			T.E =	26.188320
2105E	2105E			
002		2.900000 x	18.705943 =	54.247235

			T.E =	54.247235
2105H	2105H			
002		4.400000 x	18.705943 =	82.306149

			T.E =	82.306149
2105Z	2105Z			
002		3.900000 x	18.705943 =	72.953178

			T.E =	72.953178
2105Γ	2105Γ			
002		1.900000 x	18.705943 =	35.541292

			T.E =	35.541292
2105Δ	2105Δ			
002		2.400000 x	18.705943 =	44.894263

			T.E =	44.894263
2105ΣΤ	2105ΣΤ			
002		3.400000 x	18.705943 =	63.600206

			T.E =	63.600206
2106A	2106A			
002		5.900000 x	18.705943 =	110.365064

			T.E =	110.365064
2106B	2106B			
002		7.400000 x	18.705943 =	138.423978

			T.E =	138.423978

2106E	2106E			
002		11.900000 x	18.705943 =	222.600722

			T.E =	222.600722
2106H	2106H			
002		16.400000 x	18.705943 =	306.777465

			T.E =	306.777465
2106I	2106I			
002		19.400000 x	18.705943 =	362.895294

			T.E =	362.895294
2106Z	2106Z			
002		14.900000 x	18.705943 =	278.718551

			T.E =	278.718551
2106Γ	2106Γ			
002		8.900000 x	18.705943 =	166.482893

			T.E =	166.482893
2106Δ	2106Δ			
002		10.400000 x	18.705943 =	194.541807

			T.E =	194.541807
2106Θ	2106Θ			
002		17.900000 x	18.705943 =	334.836380

			T.E =	334.836380
2106ΣΤ	2106ΣΤ			
002		13.400000 x	18.705943 =	250.659636

			T.E =	250.659636
2107A	2107A			
002		5.900000 x	18.705943 =	110.365064

			T.E =	110.365064
2107B	2107B			
002		7.400000 x	18.705943 =	138.423978

			T.E =	138.423978

2107E	2107E			
002		11.900000 x	18.705943 =	222.600722

			T.E =	222.600722
2107H	2107H			
002		16.400000 x	18.705943 =	306.777465

			T.E =	306.777465
2107I	2107I			
002		19.400000 x	18.705943 =	362.895294

			T.E =	362.895294
2107Z	2107Z			
002		14.900000 x	18.705943 =	278.718551

			T.E =	278.718551
2107Γ	2107Γ			
002		8.900000 x	18.705943 =	166.482893

			T.E =	166.482893
2107Δ	2107Δ			
002		10.400000 x	18.705943 =	194.541807

			T.E =	194.541807
2107Θ	2107Θ			
002		17.900000 x	18.705943 =	334.836380

			T.E =	334.836380
2107ΣΤ	2107ΣΤ			
002		13.400000 x	18.705943 =	250.659636

			T.E =	250.659636
2108A	2108A			
002		.700000 x	18.705943 =	13.094160

			T.E =	13.094160
2108B	2108B			
002		1.600000 x	18.705943 =	29.929509

			T.E =	29.929509

2108E	2108E			
002		4.600000 x	18.705943 =	86.047338

			T.E =	86.047338
2108H	2108H			
002		7.600000 x	18.705943 =	142.165167

			T.E =	142.165167
2108Z	2108Z			
002		6.600000 x	18.705943 =	123.459224

			T.E =	123.459224
2108Γ	2108Γ			
002		2.600000 x	18.705943 =	48.635452

			T.E =	48.635452
2108Δ	2108Δ			
002		3.600000 x	18.705943 =	67.341395

			T.E =	67.341395
2108Θ	2108Θ			
002		8.600000 x	18.705943 =	160.871110

			T.E =	160.871110
2108ΣΤ	2108ΣΤ			
002		5.600000 x	18.705943 =	104.753281

			T.E =	104.753281
2109	2109			
002		.030000 x	18.705943 =	.561178
1503		.001000 x	517.380101 =	.517380
1506		.004000 x	681.780650 =	2.727123

			T.E =	3.805681
2110	2110			
002		.040000 x	18.705943 =	.748238
1506		.004000 x	681.780650 =	2.727123
1503		.001000 x	517.380101 =	.517380
1501		.005000 x	428.772780 =	2.143864

			T.E =	6.136604

2111	2111				
002		.100000 x	18.705943 =		1.870594
1504		.005000 x	598.084050 =		2.990420

			T.E =		4.861015
2112	2112				
002		.120000 x	18.705943 =		2.244713
1501		.004000 x	428.772780 =		1.715091
1504		.005500 x	598.084050 =		3.289462

			T.E =		7.249267
2113	2113				
002		1.400000 x	18.705943 =		26.188320
002		.300000 x	18.705943 =		5.611783

			T.E =		31.800103
2114	2114				
002		1.500000 x	18.705943 =		28.058915
1501		.005000 x	428.772780 =		2.143864
002		.400000 x	18.705943 =		7.482377

			T.E =		37.685156
2115	2115				
481		.300000 x	5.535000 =		1.660500
1501		.011000 x	428.772780 =		4.716501
003		1.200000 x	24.769248 =		29.723098
002		.600000 x	18.705943 =		11.223566

			T.E =		47.323664
2116	2116				
2115		1.300000 x	47.323664 =		61.520763

			T.E =		61.520763
2117	2117				
002		.600000 x	18.705943 =		11.223566
1501		.125000 x	428.772780 =		53.596598

			T.E =		64.820163
2118	2118				
2117		1.300000 x	64.820163 =		84.266212

			T.E =		84.266212

2121	2121				
001		.400000 x	16.829739 =	6.731896	
002		1.800000 x	18.705943 =	33.670697	

				T.E =	40.402593
2122	2122				
001		.500000 x	16.829739 =	8.414870	
002		2.000000 x	18.705943 =	37.411886	
1501		.005000 x	428.772780 =	2.143864	

				T.E =	47.970619
2123	2123				
002		.200000 x	18.705943 =	3.741189	
1504		.008300 x	598.084050 =	4.964098	

				T.E =	8.705286
2124	2124				
002		.200000 x	18.705943 =	3.741189	
1504		.010000 x	598.084050 =	5.980841	
1501		.005000 x	428.772780 =	2.143864	

				T.E =	11.865893
2125	2125				
481		.400000 x	5.535000 =	2.214000	
002		1.000000 x	18.705943 =	18.705943	
1501		.020000 x	428.772780 =	8.575456	
003		1.500000 x	24.769248 =	37.153872	

				T.E =	66.649271
2126	2126				
2125		1.300000 x	66.649271 =	86.644052	

				T.E =	86.644052
2127	2127				
002		1.000000 x	18.705943 =	18.705943	
1501		.166600 x	428.772780 =	71.433545	

				T.E =	90.139488
2128	2128				
2127		1.300000 x	90.139488 =	117.181334	

				T.E =	117.181334

2131	2131			
001		.300000 x	16.829739 =	5.048922

			T.E =	5.048922
2132	2132			
1504		.001600 x	598.084050 =	.956934

			T.E =	.956934
2133	2133			
002		.100000 x	18.705943 =	1.870594
002		.600000 x	18.705943 =	11.223566

			T.E =	13.094160
2134	2134			
1504		.002500 x	598.084050 =	1.495210

			T.E =	1.495210
2135.1	2135.1			
2121		1.300000 x	40.402593 =	52.523371

			T.E =	52.523371
2135.2	2135.2			
2122		1.300000 x	47.970619 =	62.361805

			T.E =	62.361805
2135.3	2135.3			
2127		1.300000 x	90.139488 =	117.181334

			T.E =	117.181334
2135.4	2135.4			
2128		1.300000 x	117.181334 =	152.335734

			T.E =	152.335734
2141	2141			
001		2.000000 x	16.829739 =	33.659478
003		2.500000 x	24.769248 =	61.923120

			T.E =	95.582598

2142	2142				
001		2.000000 x	16.829739 =	33.659478	
1501		.005000 x	428.772780 =	2.143864	
003		3.000000 x	24.769248 =	74.307744	

			T.E =	110.111086	
2143	2143				
481		.500000 x	5.535000 =	2.767500	
001		2.000000 x	16.829739 =	33.659478	
1501		.025000 x	428.772780 =	10.719320	
003		3.000000 x	24.769248 =	74.307744	

			T.E =	121.454042	
2144	2144				
2143		1.300000 x	121.454042 =	157.890255	

			T.E =	157.890255	
2145	2145				
001		2.000000 x	16.829739 =	33.659478	
1501		.200000 x	428.772780 =	85.754556	
003		1.000000 x	24.769248 =	24.769248	

			T.E =	144.183282	
2146	2146				
2145		1.300000 x	144.183282 =	187.438267	

			T.E =	187.438267	
2151	2151				
001		1.200000 x	16.829739 =	20.195687	
003		.800000 x	24.769248 =	19.815398	

			T.E =	40.011085	
2152	2152				
001		1.500000 x	16.829739 =	25.244609	
003		1.000000 x	24.769248 =	24.769248	

			T.E =	50.013857	
2161	2161				
1505		.003300 x	252.584749 =	.833530	

			T.E =	.833530	

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	16.829739 =	13.463791

			T.E =	13.730791
2163	2163			
001		.300000 x	16.829739 =	5.048922

			T.E =	5.048922
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	598.084050 =	2.392336

			T.E =	2.541936
2172	2172			
001		.800000 x	16.829739 =	13.463791

			T.E =	13.463791
2173	2173			
001		.600000 x	16.829739 =	10.097843

			T.E =	10.097843
2174	2174			
007		.050000 x	166.700117 =	8.335006

			T.E =	8.335006
2175	2175			
009		5.500000 x	.074800 =	.411400

			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2177	2177			
001		.800000 x	16.829739 =	13.463791

			T.E =	13.463791

2178	2178			
001		.200000 x	16.829739 =	3.365948

			T.E =	3.365948
2179	2179			
007		.018000 x	166.700117 =	3.000602

			T.E =	3.000602
2180	2180			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2185	2185			
018.1		.142800 x	2.830000 =	.404124
005		.400000 x	19.931416 =	7.972566
484		.100000 x	3.800000 =	.380000
482		.700000 x	.937000 =	.655900
018.1		.042800 x	2.830000 =	.121124

			T.E =	9.533714
2186	2186			
018.2		.142800 x	4.300000 =	.614040
005		.400000 x	19.931416 =	7.972566
018.2		.042800 x	4.300000 =	.184040
482		1.400000 x	.937000 =	1.311800
484		.200000 x	3.800000 =	.760000

			T.E =	10.842446
2187	2187			
019.1		.142800 x	2.830000 =	.404124
485		1.100000 x	.820200 =	.902220
019.1		.428000 x	2.830000 =	1.211240
005		.400000 x	19.931416 =	7.972566
484		.100000 x	3.800000 =	.380000

			T.E =	10.870150
2188	2188			
019.2		.142800 x	4.300000 =	.614040
005		.400000 x	19.931416 =	7.972566
485		1.800000 x	.820200 =	1.476360
484		.200000 x	3.800000 =	.760000
019.2		.042800 x	4.300000 =	.184040

			T.E =	11.007006

2201	2201				
001		1.000000 x	16.829739 =	16.829739	
002		2.000000 x	18.705943 =	37.411886	

			T.E =	54.241625	
2202	2202				
001		1.000000 x	16.829739 =	16.829739	
002		5.000000 x	18.705943 =	93.529715	

			T.E =	110.359454	
2203	2203				
001		1.000000 x	16.829739 =	16.829739	
002		2.500000 x	18.705943 =	46.764858	

			T.E =	63.594597	
2204	2204				
001		1.000000 x	16.829739 =	16.829739	
002		5.000000 x	18.705943 =	93.529715	

			T.E =	110.359454	
2206	2206				
001		1.000000 x	16.829739 =	16.829739	
003		3.000000 x	24.769248 =	74.307744	

			T.E =	91.137483	
2207	2207				
001		1.000000 x	16.829739 =	16.829739	
003		6.000000 x	24.769248 =	148.615488	

			T.E =	165.445227	
2211	2211				
001		2.000000 x	16.829739 =	33.659478	

			T.E =	33.659478	
2212	2212				
001		1.000000 x	16.829739 =	16.829739	

			T.E =	16.829739	
2213	2213				
001		2.000000 x	16.829739 =	33.659478	

			T.E =	33.659478	

2214	2214			
001		.600000 x	16.829739 =	10.097843

			T.E =	10.097843
2221	2221			
001		1.200000 x	16.829739 =	20.195687
002		1.600000 x	18.705943 =	29.929509

			T.E =	50.125196
2222	2222			
001		1.200000 x	16.829739 =	20.195687
002		2.500000 x	18.705943 =	46.764858

			T.E =	66.960544
2223	2223			
001		3.000000 x	16.829739 =	50.489217

			T.E =	50.489217
2224	2224			
001		5.000000 x	16.829739 =	84.148695

			T.E =	84.148695
2226	2226			
001		1.500000 x	16.829739 =	25.244609
002		5.000000 x	18.705943 =	93.529715

			T.E =	118.774324
2227	2227			
001		1.500000 x	16.829739 =	25.244609
002		12.000000 x	18.705943 =	224.471316

			T.E =	249.715925
2231	2231			
001		.600000 x	16.829739 =	10.097843

			T.E =	10.097843
2232	2232			
003		.020000 x	24.769248 =	.495385

			T.E =	.495385

2236	2236				
001		.100000 x	16.829739 =	1.682974	
002		.300000 x	18.705943 =	5.611783	

				T.E =	7.294757
2237	2237				
001		.200000 x	16.829739 =	3.365948	
003		.700000 x	24.769248 =	17.338474	

				T.E =	20.704421
2238	2238				
001		.100000 x	16.829739 =	1.682974	
002		.400000 x	18.705943 =	7.482377	

				T.E =	9.165351
2239	2239				
001		.200000 x	16.829739 =	3.365948	
003		.800000 x	24.769248 =	19.815398	

				T.E =	23.181346
2241	2241				
001		.300000 x	16.829739 =	5.048922	
003		.100000 x	24.769248 =	2.476925	

				T.E =	7.525847
2242	2242				
001		.400000 x	16.829739 =	6.731896	
003		.150000 x	24.769248 =	3.715387	

				T.E =	10.447283
2243	2243				
001		.500000 x	16.829739 =	8.414870	
003		.250000 x	24.769248 =	6.192312	

				T.E =	14.607182
2246	2246				
001		.250000 x	16.829739 =	4.207435	
003		.050000 x	24.769248 =	1.238462	

				T.E =	5.445897

2247	2247				
001		.350000 x	16.829739 =	5.890409	
003		.100000 x	24.769248 =	2.476925	

			T.E =	8.367333	
2248	2248				
001		.450000 x	16.829739 =	7.573383	
003		.200000 x	24.769248 =	4.953850	

			T.E =	12.527232	
2251	2251				
001		.100000 x	16.829739 =	1.682974	
002		.300000 x	18.705943 =	5.611783	

			T.E =	7.294757	
2252	2252				
001		.100000 x	16.829739 =	1.682974	
002		.600000 x	18.705943 =	11.223566	

			T.E =	12.906540	
2261A	2261A				
003		.400000 x	24.769248 =	9.907699	

			T.E =	9.907699	
2261B	2261B				
003		.700000 x	24.769248 =	17.338474	

			T.E =	17.338474	
2261Γ	2261Γ				
003		.900000 x	24.769248 =	22.292323	

			T.E =	22.292323	
2261Δ	2261Δ				
003		1.200000 x	24.769248 =	29.723098	

			T.E =	29.723098	
2262A	2262A				
003		.550000 x	24.769248 =	13.623086	

			T.E =	13.623086	

2262B	2262B			
003		.900000 x	24.769248 =	22.292323

			T.E =	22.292323
2262Γ	2262Γ			
003		1.200000 x	24.769248 =	29.723098

			T.E =	29.723098
2262Δ	2262Δ			
003		1.600000 x	24.769248 =	39.630797

			T.E =	39.630797
2263A	2263A			
003		.700000 x	24.769248 =	17.338474

			T.E =	17.338474
2263B	2263B			
003		1.200000 x	24.769248 =	29.723098

			T.E =	29.723098
2263Γ	2263Γ			
003		1.600000 x	24.769248 =	39.630797

			T.E =	39.630797
2263Δ	2263Δ			
003		2.100000 x	24.769248 =	52.015421

			T.E =	52.015421
2264.1A	2264.1A			
003		1.600000 x	24.769248 =	39.630797

			T.E =	39.630797
2264.1B	2264.1B			
003		1.850000 x	24.769248 =	45.823109

			T.E =	45.823109
2264.1Γ	2264.1Γ			
003		2.100000 x	24.769248 =	52.015421

			T.E =	52.015421

2264.1Δ	2264.1Δ			
003		2.300000 x	24.769248 =	56.969270

			T.E =	56.969270
2264.2Α	2264.2Α			
003		2.000000 x	24.769248 =	49.538496

			T.E =	49.538496
2264.2Β	2264.2Β			
003		2.400000 x	24.769248 =	59.446195

			T.E =	59.446195
2264.2Γ	2264.2Γ			
003		2.800000 x	24.769248 =	69.353894

			T.E =	69.353894
2264.2Δ	2264.2Δ			
003		3.200000 x	24.769248 =	79.261594

			T.E =	79.261594
2264.3Α	2264.3Α			
003		2.400000 x	24.769248 =	59.446195

			T.E =	59.446195
2264.3Β	2264.3Β			
003		2.850000 x	24.769248 =	70.592357

			T.E =	70.592357
2264.3Γ	2264.3Γ			
003		3.300000 x	24.769248 =	81.738518

			T.E =	81.738518
2264.3Δ	2264.3Δ			
003		3.750000 x	24.769248 =	92.884680

			T.E =	92.884680
2265Α	2265Α			
003		.500000 x	24.769248 =	12.384624

			T.E =	12.384624

2265B	2265B			
003		.800000 x	24.769248 =	19.815398

			T.E =	19.815398
2266.1	2266.1			
2261A		1.000000 x	9.907699 =	9.907699
2261A		.350000 x	9.907699 =	3.467695

			T.E =	13.375394
2266.10	2266.10			
2263B		1.000000 x	29.723098 =	29.723098
2263B		.350000 x	29.723098 =	10.403084

			T.E =	40.126182
2266.11	2266.11			
2263Γ		1.000000 x	39.630797 =	39.630797
2263Γ		.350000 x	39.630797 =	13.870779

			T.E =	53.501576
2266.12	2266.12			
2263Δ		1.000000 x	52.015421 =	52.015421
2263Δ		.350000 x	52.015421 =	18.205397

			T.E =	70.220818
2266.13	2266.13			
2264.1A		1.000000 x	39.630797 =	39.630797
2264.1A		.350000 x	39.630797 =	13.870779

			T.E =	53.501576
2266.14	2266.14			
2264.1B		1.000000 x	45.823109 =	45.823109
2264.1B		.350000 x	45.823109 =	16.038088

			T.E =	61.861197
2266.15	2266.15			
2264.1Γ		1.000000 x	52.015421 =	52.015421
2264.1Γ		.350000 x	52.015421 =	18.205397

			T.E =	70.220818

2266.16	2266.16			
2264.1Δ		1.000000 x	56.969270 =	56.969270
2264.1Δ		.350000 x	56.969270 =	19.939245

			T.E =	76.908515
2266.17	2266.17			
2264.2A		1.000000 x	49.538496 =	49.538496
2264.2A		.350000 x	49.538496 =	17.338474

			T.E =	66.876970
2266.18	2266.18			
2264.2B		1.000000 x	59.446195 =	59.446195
2264.2B		.350000 x	59.446195 =	20.806168

			T.E =	80.252363
2266.19	2266.19			
2264.2Γ		1.000000 x	69.353894 =	69.353894
2264.2Γ		.350000 x	69.353894 =	24.273863

			T.E =	93.627757
2266.2	2266.2			
2261B		1.000000 x	17.338474 =	17.338474
2261B		.350000 x	17.338474 =	6.068466

			T.E =	23.406940
2266.20	2266.20			
2264.2Δ		1.000000 x	79.261594 =	79.261594
2264.2Δ		.350000 x	79.261594 =	27.741558

			T.E =	107.003152
2266.21	2266.21			
2264.3A		1.000000 x	59.446195 =	59.446195
2264.3A		.350000 x	59.446195 =	20.806168

			T.E =	80.252363
2266.22	2266.22			
2264.3B		1.000000 x	70.592357 =	70.592357
2264.3B		.350000 x	70.592357 =	24.707325

			T.E =	95.299682

2266.23	2266.23				
2264.3Γ		1.000000 x	81.738518 =		81.738518
2264.3Γ		.350000 x	81.738518 =		28.608481
				T.E =	110.346999
2266.24	2266.24				
2264.3Δ		1.000000 x	92.884680 =		92.884680
2264.3Δ		.350000 x	92.884680 =		32.509638
				T.E =	125.394318
2266.25	2266.25				
2265A		1.000000 x	12.384624 =		12.384624
2265A		.350000 x	12.384624 =		4.334618
				T.E =	16.719242
2266.26	2266.26				
2265B		1.000000 x	19.815398 =		19.815398
2265B		.350000 x	19.815398 =		6.935389
				T.E =	26.750787
2266.3	2266.3				
2261Γ		1.000000 x	22.292323 =		22.292323
2261Γ		.350000 x	22.292323 =		7.802313
				T.E =	30.094636
2266.4	2266.4				
2261Δ		1.000000 x	29.723098 =		29.723098
2261Δ		.350000 x	29.723098 =		10.403084
				T.E =	40.126182
2266.5	2266.5				
2262A		1.000000 x	13.623086 =		13.623086
2262A		.350000 x	13.623086 =		4.768080
				T.E =	18.391166
2266.6	2266.6				
2262B		1.000000 x	22.292323 =		22.292323
2262B		.350000 x	22.292323 =		7.802313
				T.E =	30.094636

2266.7	2266.7			
2262Γ		1.000000 x	29.723098 =	29.723098
2262Γ		.350000 x	29.723098 =	10.403084

			T.E =	40.126182
2266.8	2266.8			
2262Δ		1.000000 x	39.630797 =	39.630797
2262Δ		.350000 x	39.630797 =	13.870779

			T.E =	53.501576
2266.9	2266.9			
2263A		1.000000 x	17.338474 =	17.338474
2263A		.350000 x	17.338474 =	6.068466

			T.E =	23.406940
2267	2267			
003		3.500000 x	24.769248 =	86.692368

			T.E =	86.692368
2268A	2268A			
003		5.000000 x	24.769248 =	123.846240

			T.E =	123.846240
2268B	2268B			
003		5.900000 x	24.769248 =	146.138563

			T.E =	146.138563
2268Γ	2268Γ			
003		6.400000 x	24.769248 =	158.523187

			T.E =	158.523187
2268Δ	2268Δ			
003		6.900000 x	24.769248 =	170.907811

			T.E =	170.907811
2269A	2269A			
003		2.000000 x	24.769248 =	49.538496

			T.E =	49.538496

2269B	2269B				
003		3.000000 x	24.769248 =	74.307744	

			T.E =	74.307744	
2269Γ	2269Γ				
003		4.000000 x	24.769248 =	99.076992	

			T.E =	99.076992	
2270.1	2270.1				
2267		1.000000 x	86.692368 =	86.692368	
2267		.600000 x	86.692368 =	52.015421	

			T.E =	138.707789	
2270.2	2270.2				
2268A		1.000000 x	123.846240 =	123.846240	
2268A		.600000 x	123.846240 =	74.307744	

			T.E =	198.153984	
2270.3	2270.3				
2268B		1.000000 x	146.138563 =	146.138563	
2268B		.600000 x	146.138563 =	87.683138	

			T.E =	233.821701	
2270.4	2270.4				
2268Γ		1.000000 x	158.523187 =	158.523187	
2268Γ		.600000 x	158.523187 =	95.113912	

			T.E =	253.637099	
2270.5	2270.5				
2268Δ		1.000000 x	170.907811 =	170.907811	
2268Δ		.600000 x	170.907811 =	102.544687	

			T.E =	273.452498	
2271A	2271A				
003		2.500000 x	24.769248 =	61.923120	

			T.E =	61.923120	
2271B	2271B				
003		3.000000 x	24.769248 =	74.307744	

			T.E =	74.307744	

2271E	2271E			
003		4.500000 x	24.769248 =	111.461616

			T.E =	111.461616
2271H	2271H			
003		6.000000 x	24.769248 =	148.615488

			T.E =	148.615488
2271I	2271I			
003		7.000000 x	24.769248 =	173.384736

			T.E =	173.384736
2271Z	2271Z			
003		5.500000 x	24.769248 =	136.230864

			T.E =	136.230864
2271Γ	2271Γ			
003		3.500000 x	24.769248 =	86.692368

			T.E =	86.692368
2271Δ	2271Δ			
003		4.000000 x	24.769248 =	99.076992

			T.E =	99.076992
2271Θ	2271Θ			
003		6.500000 x	24.769248 =	161.000112

			T.E =	161.000112
2271ΣΤ	2271ΣΤ			
003		5.000000 x	24.769248 =	123.846240

			T.E =	123.846240
2272A	2272A			
003		3.000000 x	24.769248 =	74.307744

			T.E =	74.307744
2272B	2272B			
003		3.700000 x	24.769248 =	91.646218

			T.E =	91.646218

2272E	2272E			
003		5.800000 x	24.769248 =	143.661638

			T.E =	143.661638
2272H	2272H			
003		7.900000 x	24.769248 =	195.677059

			T.E =	195.677059
2272I	2272I			
003		9.300000 x	24.769248 =	230.354006

			T.E =	230.354006
2272Z	2272Z			
003		7.200000 x	24.769248 =	178.338586

			T.E =	178.338586
2272Γ	2272Γ			
003		4.400000 x	24.769248 =	108.984691

			T.E =	108.984691
2272Δ	2272Δ			
003		5.100000 x	24.769248 =	126.323165

			T.E =	126.323165
2272Θ	2272Θ			
003		8.600000 x	24.769248 =	213.015533

			T.E =	213.015533
2272ΣΤ	2272ΣΤ			
003		6.500000 x	24.769248 =	161.000112

			T.E =	161.000112
2273A	2273A			
003		8.500000 x	24.769248 =	210.538608

			T.E =	210.538608
2273B	2273B			
003		10.000000 x	24.769248 =	247.692480

			T.E =	247.692480

2273Γ	2273Γ			
003		11.500000 x	24.769248 =	284.846352

			T.E =	284.846352
2273Δ	2273Δ			
003		13.000000 x	24.769248 =	322.000224

			T.E =	322.000224
2274.1	2274.1			
2271A		1.300000 x	61.923120 =	80.500056

			T.E =	80.500056
2274.10	2274.10			
2271I		1.300000 x	173.384736 =	225.400157

			T.E =	225.400157
2274.11	2274.11			
2272A		1.300000 x	74.307744 =	96.600067

			T.E =	96.600067
2274.12	2274.12			
2272B		1.300000 x	91.646218 =	119.140083

			T.E =	119.140083
2274.13	2274.13			
2272Γ		1.300000 x	108.984691 =	141.680098

			T.E =	141.680098
2274.14	2274.14			
2272Δ		1.300000 x	126.323165 =	164.220115

			T.E =	164.220115
2274.15	2274.15			
2272E		1.300000 x	143.661638 =	186.760129

			T.E =	186.760129
2274.16	2274.16			
2272ΣΤ		1.300000 x	161.000112 =	209.300146

			T.E =	209.300146

2274.17	2274.17			
2272Z		1.300000 x	178.338586 =	231.840162

			T.E =	231.840162
2274.18	2274.18			
2272H		1.300000 x	195.677059 =	254.380177

			T.E =	254.380177
2274.19	2274.19			
2272Θ		1.300000 x	213.015533 =	276.920193

			T.E =	276.920193
2274.2	2274.2			
2271B		1.300000 x	74.307744 =	96.600067

			T.E =	96.600067
2274.20	2274.20			
2272I		1.300000 x	230.354006 =	299.460208

			T.E =	299.460208
2274.21	2274.21			
2273A		1.300000 x	210.538608 =	273.700190

			T.E =	273.700190
2274.22	2274.22			
2273B		1.300000 x	247.692480 =	322.000224

			T.E =	322.000224
2274.23	2274.23			
2273Γ		1.300000 x	284.846352 =	370.300258

			T.E =	370.300258
2274.24	2274.24			
2273Δ		1.300000 x	322.000224 =	418.600291

			T.E =	418.600291
2274.3	2274.3			
2271Γ		1.300000 x	86.692368 =	112.700078

			T.E =	112.700078

2274.4	2274.4			
2271Δ		1.300000 x	99.076992 =	128.800090

			T.E =	128.800090
2274.5	2274.5			
2271Ε		1.300000 x	111.461616 =	144.900101

			T.E =	144.900101
2274.6	2274.6			
2271ΣΤ		1.300000 x	123.846240 =	161.000112

			T.E =	161.000112
2274.7	2274.7			
2271Ζ		1.300000 x	136.230864 =	177.100123

			T.E =	177.100123
2274.8	2274.8			
2271Η		1.300000 x	148.615488 =	193.200134

			T.E =	193.200134
2274.9	2274.9			
2271Θ		1.300000 x	161.000112 =	209.300146

			T.E =	209.300146
2275	2275			
003		1.000000 x	24.769248 =	24.769248

			T.E =	24.769248
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	210.000000 =	6.930000
251		6.000000 x	.680000 =	4.080000
003		5.000000 x	24.769248 =	123.846240
001		9.000000 x	16.829739 =	151.467651

			T.E =	295.023891
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	18.705943 =	5.611783

			T.E =	5.901783

2303	2303				
001		.250000 x	16.829739 =	4.207435	
003		.250000 x	24.769248 =	6.192312	

				T.E =	10.399747
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	18.705943 =	1.870594	

				T.E =	1.986594
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	210.000000 =	8.400000	
003		7.000000 x	24.769248 =	173.384736	
001		9.000000 x	16.829739 =	151.467651	
251		6.000000 x	.680000 =	4.080000	

				T.E =	348.932387
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	210.000000 =	.420000	
251		.250000 x	.680000 =	.170000	
001		.250000 x	16.829739 =	4.207435	
003		.150000 x	24.769248 =	3.715387	

				T.E =	9.092822
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.680000 =	.136000	
203.4		.001000 x	210.000000 =	.210000	
003		.100000 x	24.769248 =	2.476925	
001		.200000 x	16.829739 =	3.365948	

				T.E =	6.768873
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	24.769248 =	.743077	

				T.E =	1.232577
2314.2	2314.2				
512		1.000000 x	.375000 =	.375000	
003		.030000 x	24.769248 =	.743077	

				T.E =	1.118077

3101	3101				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
026		175.000000 x	.097700 =	17.097500	
052		.430000 x	15.400000 =	6.622000	
056		.860000 x	10.580000 =	9.098800	

			T.E =	109.728360	
3102	3102				
021		.250000 x	2.670000 =	.667500	
052		.420000 x	15.400000 =	6.468000	
056		.840000 x	10.580000 =	8.887200	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
026		200.000000 x	.097700 =	19.540000	

			T.E =	111.805260	
3103	3103				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
056		.820000 x	10.580000 =	8.675600	
052		.410000 x	15.400000 =	6.314000	
026		250.000000 x	.097700 =	24.425000	

			T.E =	116.324660	
3104	3104				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.097700 =	29.310000	
052		.400000 x	15.400000 =	6.160000	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
056		.800000 x	10.580000 =	8.464000	

			T.E =	120.844060	
3111	3111				
021		.250000 x	2.670000 =	.667500	
003		1.500000 x	24.769248 =	37.153872	
001		4.000000 x	16.829739 =	67.318956	
026		200.000000 x	.097700 =	19.540000	
057		.840000 x	10.580000 =	8.887200	
052		.420000 x	15.400000 =	6.468000	

			T.E =	140.035528	

3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.788170 =	27.539409
026		250.000000 x	.097700 =	24.425000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	24.769248 =	37.153872
001		2.000000 x	16.829739 =	33.659478
052		.410000 x	15.400000 =	6.314000

			T.E =	138.434859
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496
001		3.000000 x	16.829739 =	50.489217
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.097700 =	29.310000

			T.E =	172.168622
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.097700 =	14.655000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	16.829739 =	84.148695
052		.420000 x	15.400000 =	6.468000

			T.E =	122.480895
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	24.769248 =	17.338474
001		3.500000 x	16.829739 =	58.904087
026		175.000000 x	.097700 =	17.097500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000

			T.E =	114.311560
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.097700 =	19.540000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	24.769248 =	17.338474
001		3.500000 x	16.829739 =	58.904087
052		.560000 x	15.400000 =	8.624000

			T.E =	116.464460

3203	3203				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
061		.820000 x	13.560000 =	11.119200	
052		.540000 x	15.400000 =	8.316000	
026		250.000000 x	.097700 =	24.425000	
			T.E =	120.770260	
3204	3204				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.097700 =	29.310000	
052		.530000 x	15.400000 =	8.162000	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
061		.800000 x	13.560000 =	10.848000	
			T.E =	125.230060	
3205	3205				
021		.250000 x	2.670000 =	.667500	
003		5.500000 x	24.769248 =	136.230864	
001		7.000000 x	16.829739 =	117.808173	
026		200.000000 x	.097700 =	19.540000	
065		.750000 x	13.610000 =	10.207500	
052		.430000 x	15.400000 =	6.622000	
			T.E =	291.076037	
3206	3206				
021		.250000 x	2.670000 =	.667500	
026		250.000000 x	.097700 =	24.425000	
065		.730000 x	13.610000 =	9.935300	
003		5.500000 x	24.769248 =	136.230864	
001		7.000000 x	16.829739 =	117.808173	
052		.410000 x	15.400000 =	6.314000	
			T.E =	295.380837	
3207	3207				
021		.250000 x	2.670000 =	.667500	
003		3.000000 x	24.769248 =	74.307744	
001		6.000000 x	16.829739 =	100.978434	
065		.750000 x	13.610000 =	10.207500	
052		.430000 x	15.400000 =	6.622000	
026		200.000000 x	.097700 =	19.540000	
			T.E =	212.323178	

3208	3208			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	24.769248 =	74.307744
001		6.000000 x	16.829739 =	100.978434
065		.730000 x	13.610000 =	9.935300
052		.430000 x	15.400000 =	6.622000
026		250.000000 x	.097700 =	24.425000

			T.E =	216.935978
3211	3211			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.097700 =	19.540000
062		.840000 x	13.560000 =	11.390400
003		1.500000 x	24.769248 =	37.153872
001		4.000000 x	16.829739 =	67.318956
052		.560000 x	15.400000 =	8.624000

			T.E =	144.694728
3212	3212			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.097700 =	24.425000
052		.540000 x	15.400000 =	8.316000
001		2.000000 x	16.829739 =	33.659478
003		1.500000 x	24.769248 =	37.153872
1502		.050000 x	550.788170 =	27.539409
062		.820000 x	13.560000 =	11.119200

			T.E =	142.880459
3213	3213			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.097700 =	29.310000
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496
001		3.000000 x	16.829739 =	50.489217
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000

			T.E =	176.554622
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496
001		3.500000 x	16.829739 =	58.904087
065		.270000 x	13.610000 =	3.674700
062		.600000 x	13.560000 =	8.136000
052		.400000 x	15.400000 =	6.160000
026		350.000000 x	.097700 =	34.195000

			T.E =	188.815191

3215	3215			
021		.250000 x	2.670000 =	.667500
027		350.000000 x	.117200 =	41.020000
062		.560000 x	13.560000 =	7.593600
001		3.500000 x	16.829739 =	58.904087
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496
065		.250000 x	13.610000 =	3.402500
052		.420000 x	15.400000 =	6.468000

			T.E =	195.133591
3216	3216			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496
001		4.000000 x	16.829739 =	67.318956
065		.270000 x	13.610000 =	3.674700
027		425.000000 x	.117200 =	49.810000
062		.550000 x	13.560000 =	7.458000
052		.350000 x	15.400000 =	5.390000

			T.E =	211.397061
3217	3217			
001		2.500000 x	16.829739 =	42.074348

			T.E =	42.074348
3218	3218			
001		5.000000 x	16.829739 =	84.148695

			T.E =	84.148695
3219	3219			
001		3.000000 x	16.829739 =	50.489217
003		4.000000 x	24.769248 =	99.076992

			T.E =	149.566209
3220	3220			
001		5.000000 x	16.829739 =	84.148695
003		4.000000 x	24.769248 =	99.076992

			T.E =	183.225687
3221	3221			
001		3.000000 x	16.829739 =	50.489217
003		6.000000 x	24.769248 =	148.615488

			T.E =	199.104705

3222	3222				
001		5.000000 x	16.829739 =		84.148695
003		6.000000 x	24.769248 =		148.615488

			T.E =		232.764183
3223A.1	3223A.1				
001		2.000000 x	16.829739 =		33.659478
1502		.050000 x	550.788170 =		27.539409
003		1.500000 x	24.769248 =		37.153872

			AΘΡΟΙΣΜΑ =		98.352759
	T.E =	.500000 x	98.352759 =		49.176379

3223A.2	3223A.2				
001		3.000000 x	16.829739 =		50.489217
1502		.050000 x	550.788170 =		27.539409
003		2.000000 x	24.769248 =		49.538496

			AΘΡΟΙΣΜΑ =		127.567122
	T.E =	.500000 x	127.567122 =		63.783561

3223A.3	3223A.3				
001		2.000000 x	16.829739 =		33.659478
1502		.050000 x	550.788170 =		27.539409
003		1.500000 x	24.769248 =		37.153872

			AΘΡΟΙΣΜΑ =		98.352759
	T.E =	.500000 x	98.352759 =		49.176379

3223A.4	3223A.4				
001		3.000000 x	16.829739 =		50.489217
1502		.050000 x	550.788170 =		27.539409
003		2.000000 x	24.769248 =		49.538496

			AΘΡΟΙΣΜΑ =		127.567122
	T.E =	.500000 x	127.567122 =		63.783561

3223A.5	3223A.5				
001		3.500000 x	16.829739 =		58.904087
003		2.000000 x	24.769248 =		49.538496
1502		.050000 x	550.788170 =		27.539409

			AΘΡΟΙΣΜΑ =		135.981991
	T.E =	.500000 x	135.981991 =		67.990996

3223A.6	3223A.6			
001		3.500000 x	16.829739 =	58.904087
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.788170 =	27.539409

			ΑΘΡΟΙΣΜΑ =	135.981991
	T.E =	.500000 x	135.981991 =	67.990996

3223A.7	3223A.7			
001		4.000000 x	16.829739 =	67.318956
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496

			ΑΘΡΟΙΣΜΑ =	144.396861
	T.E =	.500000 x	144.396861 =	72.198430

3223B.1	3223B.1			
001		2.000000 x	16.829739 =	33.659478
003		1.500000 x	24.769248 =	37.153872
1502		.050000 x	550.788170 =	27.539409

			ΑΘΡΟΙΣΜΑ =	98.352759
	T.E =	.250000 x	98.352759 =	24.588190

3223B.2	3223B.2			
001		3.000000 x	16.829739 =	50.489217
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496

			ΑΘΡΟΙΣΜΑ =	127.567122
	T.E =	.250000 x	127.567122 =	31.891780

3223B.3	3223B.3			
001		2.000000 x	16.829739 =	33.659478
003		1.500000 x	24.769248 =	37.153872
1502		.050000 x	550.788170 =	27.539409

			ΑΘΡΟΙΣΜΑ =	98.352759
	T.E =	.250000 x	98.352759 =	24.588190

3223B.4	3223B.4			
001		3.000000 x	16.829739 =	50.489217
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.788170 =	27.539409

			ΑΘΡΟΙΣΜΑ =	127.567122
	T.E =	.250000 x	127.567122 =	31.891780

3223B.5	3223B.5			
001		3.500000 x	16.829739 =	58.904087
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496

			ΑΘΡΟΙΣΜΑ =	135.981991
	T.E =	.250000 x	135.981991 =	33.995498

3223B.6	3223B.6			
001		3.500000 x	16.829739 =	58.904087
1502		.050000 x	550.788170 =	27.539409
003		2.000000 x	24.769248 =	49.538496

			ΑΘΡΟΙΣΜΑ =	135.981991
	T.E =	.250000 x	135.981991 =	33.995498

3223B.7	3223B.7			
001		4.000000 x	16.829739 =	67.318956
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.788170 =	27.539409

			ΑΘΡΟΙΣΜΑ =	144.396861
	T.E =	.250000 x	144.396861 =	36.099215

3231	3231			
021		.300000 x	2.670000 =	.801000
061		.840000 x	13.560000 =	11.390400
001		5.000000 x	16.829739 =	84.148695
1407		.200000 x	37.605000 =	7.521000
052		.560000 x	15.400000 =	8.624000
026		150.000000 x	.097700 =	14.655000

			T.E =	127.140095
3301	3301			
021		.200000 x	2.670000 =	.534000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	24.769248 =	19.815398
001		3.500000 x	16.829739 =	58.904087
056		.800000 x	10.580000 =	8.464000
032		.150000 x	35.000000 =	5.250000
051		.300000 x	15.400000 =	4.620000

			T.E =	103.228235

3302	3302			
021		.200000 x	2.670000 =	.534000
056		.800000 x	10.580000 =	8.464000
003		.800000 x	24.769248 =	19.815398
1407		.200000 x	37.605000 =	7.521000
001		3.500000 x	16.829739 =	58.904087
051		.200000 x	15.400000 =	3.080000
032		.200000 x	35.000000 =	7.000000

			T.E =	105.318485
3303	3303			
021		.200000 x	2.670000 =	.534000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	24.769248 =	19.815398
001		3.500000 x	16.829739 =	58.904087
056		.800000 x	10.580000 =	8.464000
032		.400000 x	35.000000 =	14.000000

			T.E =	109.238485
3304	3304			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	24.769248 =	29.723098
001		3.500000 x	16.829739 =	58.904087
056		.800000 x	10.580000 =	8.464000
032		.400000 x	35.000000 =	14.000000
026		100.000000 x	.097700 =	9.770000

			T.E =	125.907784
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	35.000000 =	5.600000
051		.320000 x	15.400000 =	4.928000
061		.840000 x	13.560000 =	11.390400
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	24.769248 =	19.815398
001		3.500000 x	16.829739 =	58.904087

			T.E =	107.188685
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	35.000000 =	7.350000
051		.210000 x	15.400000 =	3.234000
001		3.500000 x	16.829739 =	58.904087
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	24.769248 =	29.723098
061		.840000 x	13.560000 =	11.390400

			T.E =	119.032634

3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	35.000000 =	14.700000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	24.769248 =	29.723098
001		3.500000 x	16.829739 =	58.904087
061		.840000 x	13.560000 =	11.390400

			T.E =	123.148634
3314	3314			
021		.200000 x	2.670000 =	.534000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	24.769248 =	29.723098
001		3.500000 x	16.829739 =	58.904087
061		.840000 x	13.560000 =	11.390400
032		.420000 x	35.000000 =	14.700000
026		100.000000 x	.097700 =	9.770000

			T.E =	129.910234
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
058		.500000 x	9.090000 =	4.545000
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.097700 =	13.678000
052		.294000 x	15.400000 =	4.527600

			T.E =	98.759410
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
061		.588000 x	13.560000 =	7.973280
026		140.000000 x	.097700 =	13.678000
058		.500000 x	9.090000 =	4.545000
052		.392000 x	15.400000 =	6.036800

			T.E =	102.020850
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
058		.500000 x	9.090000 =	4.545000
056		.574000 x	10.580000 =	6.072920
001		2.500000 x	16.829739 =	42.074348
003		1.100000 x	24.769248 =	27.246173
026		175.000000 x	.097700 =	17.097500
052		.287000 x	15.400000 =	4.419800

			T.E =	101.922990

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
061		.574000 x	13.560000 =	7.783440
058		.500000 x	9.090000 =	4.545000
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.097700 =	17.097500

			T.E =	105.034910
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.097700 =	13.678000
052		.294000 x	15.400000 =	4.527600
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
081		.500000 x	11.010000 =	5.505000

			T.E =	99.719410
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.097700 =	13.678000
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800
001		2.500000 x	16.829739 =	42.074348
003		1.100000 x	24.769248 =	27.246173
081		.500000 x	11.010000 =	5.505000

			T.E =	102.980850
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
056		.574000 x	10.580000 =	6.072920
003		1.100000 x	24.769248 =	27.246173
081		.500000 x	11.010000 =	5.505000
001		2.500000 x	16.829739 =	42.074348
026		175.000000 x	.097700 =	17.097500
052		.287000 x	15.400000 =	4.419800

			T.E =	102.882990

3407.2	3407.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
081		.500000 x	11.010000 =	5.505000
061		.574000 x	13.560000 =	7.783440
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.097700 =	17.097500

			T.E =	105.994910
3501	3501			
021		.200000 x	2.670000 =	.534000
032		.200000 x	35.000000 =	7.000000
003		2.000000 x	24.769248 =	49.538496
1407		.180000 x	37.605000 =	6.768900
001		5.000000 x	16.829739 =	84.148695
067		1.050000 x	45.000000 =	47.250000

			T.E =	195.240091
3502	3502			
021		.200000 x	2.670000 =	.534000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	24.769248 =	49.538496
001		5.000000 x	16.829739 =	84.148695
032		.200000 x	35.000000 =	7.000000
067		1.050000 x	45.000000 =	47.250000
026		100.000000 x	.097700 =	9.770000

			T.E =	202.001691
3503	3503			
021		.200000 x	2.670000 =	.534000
067		1.000000 x	45.000000 =	45.000000
032		.200000 x	35.000000 =	7.000000
003		2.000000 x	24.769248 =	49.538496
1407		.080000 x	37.605000 =	3.008400
001		5.000000 x	16.829739 =	84.148695
026		150.000000 x	.097700 =	14.655000

			T.E =	203.884591
3504	3504			
021		.200000 x	2.670000 =	.534000
003		3.200000 x	24.769248 =	79.261594
001		5.000000 x	16.829739 =	84.148695
517		4.000000 x	.000000 =	.000000
055		180.000000 x	.090000 =	16.200000
026		250.000000 x	.097700 =	24.425000

			T.E =	

3505	3505			
021		.200000 x	2.670000 =	.534000
026		250.000000 x	.097700 =	24.425000
517		4.000000 x	.000000 =	.000000
055		420.000000 x	.090000 =	37.800000
003		5.000000 x	24.769248 =	123.846240
001		5.500000 x	16.829739 =	92.563565

T.E =

3506	3506			
021		.300000 x	2.670000 =	.801000
515		1.150000 x	41.230000 =	47.414500
026		200.000000 x	.097700 =	19.540000
001		5.000000 x	16.829739 =	84.148695
003		2.500000 x	24.769248 =	61.923120

T.E =

213.827315

3511	3511			
021		.200000 x	2.670000 =	.534000
069		1.050000 x	.000000 =	.000000
032		.200000 x	35.000000 =	7.000000
003		2.000000 x	24.769248 =	49.538496
1407		.180000 x	37.605000 =	6.768900
001		5.000000 x	16.829739 =	84.148695

T.E =

3512	3512			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.097700 =	9.770000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	24.769248 =	49.538496
001		5.000000 x	16.829739 =	84.148695
069		1.050000 x	.000000 =	.000000
032		.200000 x	35.000000 =	7.000000

T.E =

3513	3513			
001		2.500000 x	16.829739 =	42.074348

T.E =

42.074348

3514	3514			
001		5.000000 x	16.829739 =	84.148695

T.E =

84.148695

3801	3801				
201		.001500 x	290.000000 =		.435000
203.4		.002500 x	210.000000 =		.525000
251		.300000 x	.680000 =		.204000
003		.500000 x	24.769248 =		12.384624
001		.400000 x	16.829739 =		6.731896
				T.E =	20.280520
3802	3802				
3801		.050000 x	20.280520 =		1.014026
				T.E =	1.014026
3811	3811				
203.4		.004000 x	210.000000 =		.840000
001		.200000 x	16.829739 =		3.365948
251		.100000 x	.680000 =		.068000
003		.800000 x	24.769248 =		19.815398
				T.E =	24.089346
3816	3816				
201		.002500 x	290.000000 =		.725000
001		.400000 x	16.829739 =		6.731896
251		.200000 x	.680000 =		.136000
003		.600000 x	24.769248 =		14.861549
203.4		.003000 x	210.000000 =		.630000
				T.E =	23.084444
3817	3817				
3816		.150000 x	23.084444 =		3.462667
				T.E =	3.462667
3821	3821				
201		.014000 x	290.000000 =		4.060000
003		2.400000 x	24.769248 =		59.446195
001		.600000 x	16.829739 =		10.097843
251		.600000 x	.680000 =		.408000
203.4		.018000 x	210.000000 =		3.780000
				T.E =	77.792039
3822	3822				
3821		.150000 x	77.792039 =		11.668806
				T.E =	11.668806

3823	3823				
201		.020000 x	290.000000 =	5.800000	
003		3.000000 x	24.769248 =	74.307744	
001		.600000 x	16.829739 =	10.097843	
203.4		.025000 x	210.000000 =	5.250000	
251		.180000 x	.680000 =	.122400	

			T.E =	95.577987	
3824	3824				
3823		.200000 x	95.577987 =	19.115597	

			T.E =	19.115597	
3831	3831				
201		.020000 x	290.000000 =	5.800000	
251		.800000 x	.680000 =	.544000	
203.4		.024000 x	210.000000 =	5.040000	
003		4.500000 x	24.769248 =	111.461616	
001		1.100000 x	16.829739 =	18.512713	

			T.E =	141.358329	
3832	3832				
3831		.150000 x	141.358329 =	21.203749	

			T.E =	21.203749	
3833	3833				
201		.022000 x	290.000000 =	6.380000	
203.4		.025000 x	210.000000 =	5.250000	
003		6.000000 x	24.769248 =	148.615488	
001		1.100000 x	16.829739 =	18.512713	
251		1.000000 x	.680000 =	.680000	

			T.E =	179.438201	
3834	3834				
3833		.200000 x	179.438201 =	35.887640	

			T.E =	35.887640	
3841	3841				
203.4		.001500 x	210.000000 =	.315000	
003		.500000 x	24.769248 =	12.384624	

			T.E =	12.699624	

3851	3851			
203.4		.052000 x	210.000000 =	10.920000
003		1.300000 x	24.769248 =	32.200022
251		1.100000 x	.680000 =	.748000

			T.E =	43.868022
3852	3852			
001		.300000 x	16.829739 =	5.048922
003		.100000 x	24.769248 =	2.476925

			T.E =	7.525847
3871	3871			
260		1.030000 x	.511400 =	.526742
003		.050000 x	24.769248 =	1.238462

			T.E =	1.765204
3872	3872			
261		1.030000 x	.549400 =	.565882
003		.040000 x	24.769248 =	.990770

			T.E =	1.556652
3873	3873			
262		1.030000 x	.511400 =	.526742
003		.050000 x	24.769248 =	1.238462

			T.E =	1.765204
3874	3874			
258		1.450000 x	7.390500 =	10.716225
003		.150000 x	24.769248 =	3.715387

			T.E =	14.431612
3875	3875			
259		1.000000 x	24.205000 =	24.205000
003		.300000 x	24.769248 =	7.430774

			T.E =	31.635774
3876	3876			
003		.060000 x	24.769248 =	1.486155

			T.E =	1.486155

3881.1	3881.1			
111		1,023.391800 x	.078400 =	80.233917
001		5.000000 x	16.829739 =	84.148695

			T.E =	164.382612
3881.2	3881.2			
112		627.989998 x	.087900 =	55.200321
001		5.000000 x	16.829739 =	84.148695

			T.E =	139.349016
3882	3882			
127		1.050000 x	83.240000 =	87.402000
001		4.000000 x	16.829739 =	67.318956

			T.E =	154.720956
4101	4101			
081		1.150000 x	11.010000 =	12.661500
003		2.000000 x	24.769248 =	49.538496
001		1.300000 x	16.829739 =	21.878661

			T.E =	84.078657
4102	4102			
081		1.200000 x	11.010000 =	13.212000
003		3.500000 x	24.769248 =	86.692368
001		1.700000 x	16.829739 =	28.610556

			T.E =	128.514924
4103	4103			
081		1.150000 x	11.010000 =	12.661500
001		3.000000 x	16.829739 =	50.489217
003		4.000000 x	24.769248 =	99.076992

			T.E =	162.227709
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	16.829739 =	50.489217

			T.E =	62.049717
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	24.769248 =	22.292323
001		1.000000 x	16.829739 =	16.829739

			T.E =	42.975562

4106	4106			
081		.320000 x	11.010000 =	3.523200
003		.900000 x	24.769248 =	22.292323
001		.700000 x	16.829739 =	11.780817

			T.E =	37.596341
4107	4107			
081		1.200000 x	11.010000 =	13.212000
001		2.000000 x	16.829739 =	33.659478
003		3.000000 x	24.769248 =	74.307744

			T.E =	121.179222
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	16.829739 =	48.806243
003		4.000000 x	24.769248 =	99.076992

			T.E =	170.320865
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	39.954450 =	13.984058
001		2.900000 x	16.829739 =	48.806243
003		2.500000 x	24.769248 =	61.923120

			T.E =	137.374921
4206	4206			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	39.954450 =	13.984058
003		3.100000 x	24.769248 =	76.784669
001		2.900000 x	16.829739 =	48.806243

			T.E =	152.236469
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	16.829739 =	48.806243
003		4.000000 x	24.769248 =	99.076992
1417		.350000 x	39.954450 =	13.984058

			T.E =	174.528793

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	16.829739 =	48.806243	
1447		.350000 x	58.155900 =	20.354565	
003		2.500000 x	24.769248 =	61.923120	

			T.E =	143.745428	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	16.829739 =	48.806243	
1447		.350000 x	58.155900 =	20.354565	
003		3.100000 x	24.769248 =	76.784669	

			T.E =	158.606977	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	58.155900 =	20.354565	
003		4.000000 x	24.769248 =	99.076992	
001		2.900000 x	16.829739 =	48.806243	

			T.E =	180.899300	
4221	4221				
001		.800000 x	16.829739 =	13.463791	
003		1.000000 x	24.769248 =	24.769248	

			T.E =	38.233039	
4222	4222				
001		.400000 x	16.829739 =	6.731896	
003		.400000 x	24.769248 =	9.907699	

			T.E =	16.639595	
4226	4226				
003		1.300000 x	24.769248 =	32.200022	

			T.E =	32.200022	
4251	4251				
083		32.000000 x	.000000 =	.000000	
001		2.900000 x	16.829739 =	48.806243	
1412		.200000 x	27.931800 =	5.586360	
003		4.000000 x	24.769248 =	99.076992	

			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	16.829739 =	48.806243
1417		.200000 x	39.954450 =	7.990890
003		4.000000 x	24.769248 =	99.076992

T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	60.956500 =	12.191300
003		4.000000 x	24.769248 =	99.076992
001		2.900000 x	16.829739 =	48.806243

T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	16.829739 =	48.806243
1447		.200000 x	58.155900 =	11.631180
003		4.000000 x	24.769248 =	99.076992

T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	16.829739 =	16.829739

T.E =

4301	4301			17.264739
081		1.020000 x	11.010000 =	11.230200
083		5.000000 x	.000000 =	.000000
003		4.200000 x	24.769248 =	104.030842
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	16.829739 =	48.806243

T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
1417		.350000 x	39.954450 =	13.984058
003		2.700000 x	24.769248 =	66.876970
001		2.900000 x	16.829739 =	48.806243

T.E =

4306	4306			
081		1.050000 x	11.010000 =	11.560500
1417		.350000 x	39.954450 =	13.984058
003		3.300000 x	24.769248 =	81.738518
001		2.900000 x	16.829739 =	48.806243
083		3.000000 x	.000000 =	.000000

			T.E =	
4307	4307			
081		1.020000 x	11.010000 =	11.230200
003		4.200000 x	24.769248 =	104.030842
1417		.350000 x	39.954450 =	13.984058
001		2.900000 x	16.829739 =	48.806243
083		5.000000 x	.000000 =	.000000

			T.E =	
4311	4311			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	58.155900 =	20.354565
003		2.700000 x	24.769248 =	66.876970
001		2.900000 x	16.829739 =	48.806243
083		2.000000 x	.000000 =	.000000

			T.E =	
4312	4312			
081		1.050000 x	11.010000 =	11.560500
083		3.000000 x	.000000 =	.000000
1447		.350000 x	58.155900 =	20.354565
003		3.300000 x	24.769248 =	81.738518
001		2.900000 x	16.829739 =	48.806243

			T.E =	
4313	4313			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	58.155900 =	20.354565
003		2.700000 x	24.769248 =	66.876970
001		2.900000 x	16.829739 =	48.806243
083		2.000000 x	.000000 =	.000000

			T.E =	
4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	16.829739 =	16.829739

			T.E =	17.264739

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
251		4.000000 x	.680000 =	2.720000
001		10.000000 x	16.829739 =	168.297390
003		25.000000 x	24.769248 =	619.231200
1446		.100000 x	52.110500 =	5.211050

T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
251		4.000000 x	.680000 =	2.720000
003		25.000000 x	24.769248 =	619.231200
1446		.100000 x	52.110500 =	5.211050
001		10.000000 x	16.829739 =	168.297390

T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
1446		.100000 x	52.110500 =	5.211050
003		25.000000 x	24.769248 =	619.231200
001		10.000000 x	16.829739 =	168.297390
251		4.000000 x	.680000 =	2.720000

T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
251		8.000000 x	.680000 =	5.440000
003		32.000000 x	24.769248 =	792.615936
1446		.200000 x	52.110500 =	10.422100
001		11.000000 x	16.829739 =	185.127129

T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
1446		.200000 x	52.110500 =	10.422100
003		32.000000 x	24.769248 =	792.615936
251		8.000000 x	.680000 =	5.440000
001		11.000000 x	16.829739 =	185.127129

T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.110500 =	10.422100
003		32.000000 x	24.769248 =	792.615936
251		8.000000 x	.680000 =	5.440000
001		11.000000 x	16.829739 =	185.127129
			T.E =	
4401	4401			
001		1.200000 x	16.829739 =	20.195687
			T.E =	20.195687
4402	4402			
001		3.000000 x	16.829739 =	50.489217
			T.E =	50.489217
4501	4501			
081		.050000 x	11.010000 =	.550500
003		1.000000 x	24.769248 =	24.769248
002		.500000 x	18.705943 =	9.352972
			T.E =	34.672720
4502	4502			
081		.050000 x	11.010000 =	.550500
002		.500000 x	18.705943 =	9.352972
003		1.300000 x	24.769248 =	32.200022
			T.E =	42.103494
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	18.705943 =	9.352972
003		1.400000 x	24.769248 =	34.676947
			T.E =	44.580419
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		2.300000 x	24.769248 =	56.969270
			T.E =	63.131553

4505	4505				
081		.050000 x	11.010000 =	.550500	
003		2.700000 x	24.769248 =	66.876970	
002		.300000 x	18.705943 =	5.611783	

			T.E =	73.039253	
4506	4506				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		3.600000 x	24.769248 =	89.169293	

			T.E =	95.331576	
4507	4507				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		3.200000 x	24.769248 =	79.261594	

			T.E =	85.423877	
4508	4508				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		3.000000 x	24.769248 =	74.307744	

			T.E =	80.470027	
4511	4511				
081		.050000 x	11.010000 =	.550500	
003		3.800000 x	24.769248 =	94.123142	
002		.300000 x	18.705943 =	5.611783	

			T.E =	100.285425	
4512	4512				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		4.000000 x	24.769248 =	99.076992	

			T.E =	105.239275	
4515	4515				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		5.000000 x	24.769248 =	123.846240	

			T.E =	130.008523	

4516	4516			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		4.500000 x	24.769248 =	111.461616

			T.E =	117.623899
4517	4517			
081		.050000 x	11.010000 =	.550500
003		6.500000 x	24.769248 =	161.000112
002		.300000 x	18.705943 =	5.611783

			T.E =	167.162395
4518	4518			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		5.700000 x	24.769248 =	141.184714

			T.E =	147.346997
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		5.200000 x	24.769248 =	128.800090

			T.E =	134.962373
4521	4521			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		3.500000 x	24.769248 =	86.692368

			T.E =	92.854651
4522	4522			
081		.050000 x	11.010000 =	.550500
003		2.700000 x	24.769248 =	66.876970
002		.300000 x	18.705943 =	5.611783

			T.E =	73.039253
4525	4525			
081		.050000 x	11.010000 =	.550500
003		4.500000 x	24.769248 =	111.461616
002		.300000 x	18.705943 =	5.611783

			T.E =	117.623899

4526	4526			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	24.769248 =	99.076992
002		.300000 x	18.705943 =	5.611783

			T.E =	105.239275
4527	4527			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	24.769248 =	148.615488
002		.300000 x	18.705943 =	5.611783

			T.E =	154.777771
4528	4528			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		5.200000 x	24.769248 =	128.800090

			T.E =	134.962373
4529	4529			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		4.700000 x	24.769248 =	116.415466

			T.E =	122.577749
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	24.769248 =	61.923120

			T.E =	62.473620
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	24.769248 =	49.538496

			T.E =	50.088996
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	24.769248 =	94.123142

			T.E =	94.673642
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	24.769248 =	76.784669

			T.E =	77.335169

4537	4537				
081		.050000 x	11.010000 =	.550500	
003		5.500000 x	24.769248 =	136.230864	

				T.E =	136.781364
4538	4538				
081		.050000 x	11.010000 =	.550500	
003		4.600000 x	24.769248 =	113.938541	

				T.E =	114.489041
4539	4539				
081		.050000 x	11.010000 =	.550500	
003		4.200000 x	24.769248 =	104.030842	

				T.E =	104.581342
4541	4541				
081		.050000 x	11.010000 =	.550500	
003		2.500000 x	24.769248 =	61.923120	

				T.E =	62.473620
4542	4542				
081		.050000 x	11.010000 =	.550500	
003		2.000000 x	24.769248 =	49.538496	

				T.E =	50.088996
4543	4543				
081		.050000 x	11.010000 =	.550500	
003		4.000000 x	24.769248 =	99.076992	

				T.E =	99.627492
4544	4544				
081		.050000 x	11.010000 =	.550500	
003		6.000000 x	24.769248 =	148.615488	

				T.E =	149.165988
4601.1	4601.1				
101		105.000000 x	.000000 =	.000000	
1417		.023000 x	39.954450 =	.918952	
003		.700000 x	24.769248 =	17.338474	
001		.600000 x	16.829739 =	10.097843	

				T.E =	

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
1447		.023000 x	58.155900 =	1.337586
003		.700000 x	24.769248 =	17.338474
001		.600000 x	16.829739 =	10.097843

T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
1417		.056000 x	39.954450 =	2.237449
003		1.300000 x	24.769248 =	32.200022
001		1.300000 x	16.829739 =	21.878661

T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
1447		.056000 x	58.155900 =	3.256730
003		1.300000 x	24.769248 =	32.200022
001		1.300000 x	16.829739 =	21.878661

T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
1417		.089000 x	39.954450 =	3.555946
001		1.900000 x	16.829739 =	31.976504
003		1.800000 x	24.769248 =	44.584646

T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	16.829739 =	31.976504
1447		.089000 x	58.155900 =	5.175875
003		1.800000 x	24.769248 =	44.584646

T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
1417		.332000 x	39.954450 =	13.264877
001		6.300000 x	16.829739 =	106.027356
003		5.500000 x	24.769248 =	136.230864

T.E =

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
1447		.332000 x	58.155900 =	19.307759
003		5.500000 x	24.769248 =	136.230864
001		6.300000 x	16.829739 =	106.027356

T.E =

4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	39.954450 =	1.198634
003		.700000 x	24.769248 =	17.338474
001		.700000 x	16.829739 =	11.780817

T.E =

4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
1447		.030000 x	58.155900 =	1.744677
001		.700000 x	16.829739 =	11.780817
003		.700000 x	24.769248 =	17.338474

T.E =

4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
1417		.070000 x	39.954450 =	2.796812
003		1.300000 x	24.769248 =	32.200022
001		1.400000 x	16.829739 =	23.561635

T.E =

4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
1447		.070000 x	58.155900 =	4.070913
003		1.300000 x	24.769248 =	32.200022
001		1.400000 x	16.829739 =	23.561635

T.E =

4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
1417		.110000 x	39.954450 =	4.394990
001		2.100000 x	16.829739 =	35.342452
003		1.800000 x	24.769248 =	44.584646

T.E =

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	16.829739 =	35.342452
1447		.110000 x	58.155900 =	6.397149
003		1.800000 x	24.769248 =	44.584646

T.E =

4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
1417		.404000 x	39.954450 =	16.141598
001		6.500000 x	16.829739 =	109.393304
003		5.500000 x	24.769248 =	136.230864

T.E =

4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
1447		.404000 x	58.155900 =	23.494984
003		5.500000 x	24.769248 =	136.230864
001		6.500000 x	16.829739 =	109.393304

T.E =

4621.1	4621.1			
111		53.000000 x	.078400 =	4.155200
1417		.010000 x	39.954450 =	.399545
001		.400000 x	16.829739 =	6.731896
003		.500000 x	24.769248 =	12.384624

T.E = 23.671264

4621.2	4621.2			
111		53.000000 x	.078400 =	4.155200
001		.400000 x	16.829739 =	6.731896
1447		.010000 x	58.155900 =	.581559
003		.500000 x	24.769248 =	12.384624

T.E = 23.853279

4622.1	4622.1			
111		75.000000 x	.078400 =	5.880000
1417		.020000 x	39.954450 =	.799089
003		.500000 x	24.769248 =	12.384624
001		.450000 x	16.829739 =	7.573383

T.E = 26.637096

4622.2	4622.2			
111		75.000000 x	.078400 =	5.880000
1447		.020000 x	58.155900 =	1.163118
003		.500000 x	24.769248 =	12.384624
001		.450000 x	16.829739 =	7.573383

			T.E =	27.001125
4623.1	4623.1			
111		150.000000 x	.078400 =	11.760000
1417		.050000 x	39.954450 =	1.997723
001		.950000 x	16.829739 =	15.988252
003		.950000 x	24.769248 =	23.530786

			T.E =	53.276760
4623.2	4623.2			
111		150.000000 x	.078400 =	11.760000
001		.950000 x	16.829739 =	15.988252
1447		.050000 x	58.155900 =	2.907795
003		.950000 x	24.769248 =	23.530786

			T.E =	54.186833
4624.1	4624.1			
111		225.000000 x	.078400 =	17.640000
1417		.085000 x	39.954450 =	3.396128
001		1.500000 x	16.829739 =	25.244609
003		1.300000 x	24.769248 =	32.200022

			T.E =	78.480759
4624.2	4624.2			
111		225.000000 x	.078400 =	17.640000
1447		.085000 x	58.155900 =	4.943252
003		1.300000 x	24.769248 =	32.200022
001		1.500000 x	16.829739 =	25.244609

			T.E =	80.027882
4625.1	4625.1			
111		750.000000 x	.078400 =	58.800000
003		4.300000 x	24.769248 =	106.507766
1417		.320000 x	39.954450 =	12.785424
001		5.200000 x	16.829739 =	87.514643

			T.E =	265.607833

4625.2	4625.2			
111		750.000000 x	.078400 =	58.800000
001		5.200000 x	16.829739 =	87.514643
003		4.300000 x	24.769248 =	106.507766
1447		.320000 x	58.155900 =	18.609888

			T.E =	271.432297
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000

			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000

			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000

			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000

			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000

			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000

			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	26.637096 =	58.601611

			T.E =	58.601611
4633.2	4633.2			
4622.2		2.200000 x	27.001125 =	59.402475

			T.E =	59.402475
4634.1	4634.1			
4622.1		1.200000 x	26.637096 =	31.964515
4623.1		1.000000 x	53.276760 =	53.276760

			T.E =	85.241275
4634.2	4634.2			
4622.2		1.200000 x	27.001125 =	32.401350
4623.2		1.000000 x	54.186833 =	54.186833

			T.E =	86.588183
4661.1	4661.1			
112		43.750000 x	.087900 =	3.845625
001		.400000 x	16.829739 =	6.731896
003		.500000 x	24.769248 =	12.384624
1417		.014507 x	39.954450 =	.579619

			T.E =	23.541764
4661.2	4661.2			
112		43.750000 x	.087900 =	3.845625
001		.400000 x	16.829739 =	6.731896
1447		.014507 x	58.155900 =	.843668
003		.500000 x	24.769248 =	12.384624

			T.E =	23.805812
4662.1	4662.1			
112		58.333300 x	.087900 =	5.127497
1417		.022840 x	39.954450 =	.912560
003		.500000 x	24.769248 =	12.384624
001		.450000 x	16.829739 =	7.573383

			T.E =	25.998063

4662.2	4662.2			
112		58.333300 x	.087900 =	5.127497
1447		.022840 x	58.155900 =	1.328281
001		.450000 x	16.829739 =	7.573383
003		.500000 x	24.769248 =	12.384624

			T.E =	26.413784
4663.1	4663.1			
112		105.000000 x	.087900 =	9.229500
003		.900000 x	24.769248 =	22.292323
1417		.043218 x	39.954450 =	1.726751
001		.900000 x	16.829739 =	15.146765

			T.E =	48.395340
4663.2	4663.2			
112		105.000000 x	.087900 =	9.229500
003		.900000 x	24.769248 =	22.292323
001		.900000 x	16.829739 =	15.146765
1447		.043218 x	58.155900 =	2.513382

			T.E =	49.181970
4664.1	4664.1			
112		97.222221 x	.087900 =	8.545833
001		.950000 x	16.829739 =	15.988252
1417		.045077 x	39.954450 =	1.801027
003		.950000 x	24.769248 =	23.530786

			T.E =	49.865898
4664.2	4664.2			
112		97.222221 x	.087900 =	8.545833
1447		.045077 x	58.155900 =	2.621494
003		.950000 x	24.769248 =	23.530786
001		.950000 x	16.829739 =	15.988252

			T.E =	50.686364
4665.1	4665.1			
112		174.999001 x	.087900 =	15.382412
1417		.047530 x	39.954450 =	1.899035
001		1.500000 x	16.829739 =	25.244609
003		1.300000 x	24.769248 =	32.200022

			T.E =	74.726078

4665.2	4665.2			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	16.829739 =	25.244609
1447		.047530 x	58.155900 =	2.764150
003		1.300000 x	24.769248 =	32.200022

			T.E =	75.591193
4666.1	4666.1			
112		486.111099 x	.087900 =	42.729166
1417		.277862 x	39.954450 =	11.101823
001		5.200000 x	16.829739 =	87.514643
003		4.300000 x	24.769248 =	106.507766

			T.E =	247.853398
4666.2	4666.2			
112		486.111000 x	.087900 =	42.729157
1447		.277862 x	58.155900 =	16.159315
003		4.300000 x	24.769248 =	106.507766
001		5.200000 x	16.829739 =	87.514643

			T.E =	252.910881
4701	4701			
113		13.000000 x	.570000 =	7.410000
1417		.020000 x	39.954450 =	.799089
001		.500000 x	16.829739 =	8.414870
003		.400000 x	24.769248 =	9.907699

			T.E =	26.531658
4702	4702			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	16.829739 =	8.414870
1447		.020000 x	58.155900 =	1.163118
003		.400000 x	24.769248 =	9.907699

			T.E =	26.895687
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	39.954450 =	.599317
001		.400000 x	16.829739 =	6.731896
003		.350000 x	24.769248 =	8.669237

			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
1447		.015000 x	58.155900 =	.872339
003		.350000 x	24.769248 =	8.669237
001		.400000 x	16.829739 =	6.731896

T.E =

4711	4711			
117		13.000000 x	.000000 =	.000000
1417		.020000 x	39.954450 =	.799089
001		.500000 x	16.829739 =	8.414870
003		.400000 x	24.769248 =	9.907699

T.E =

4712	4712			
117		13.000000 x	.000000 =	.000000
001		.500000 x	16.829739 =	8.414870
1447		.020000 x	58.155900 =	1.163118
003		.400000 x	24.769248 =	9.907699

T.E =

4713	4713			
118		13.000000 x	.000000 =	.000000
1417		.015000 x	39.954450 =	.599317
001		.400000 x	16.829739 =	6.731896
003		.350000 x	24.769248 =	8.669237

T.E =

4714	4714			
118		13.000000 x	.000000 =	.000000
1447		.015000 x	58.155900 =	.872339
003		.350000 x	24.769248 =	8.669237
001		.400000 x	16.829739 =	6.731896

T.E =

4721.1	4721.1			
128		.080000 x	90.430000 =	7.234400
1417		.004000 x	39.954450 =	.159818
001		.300000 x	16.829739 =	5.048922
003		.350000 x	24.769248 =	8.669237

T.E =

21.112376

4721.2	4721.2			
128		.080000 x	90.430000 =	7.234400
001		.300000 x	16.829739 =	5.048922
1447		.004000 x	58.155900 =	.232624
003		.350000 x	24.769248 =	8.669237

			T.E =	21.185182
4722.1	4722.1			
128		.100000 x	90.430000 =	9.043000
1417		.005000 x	39.954450 =	.199772
001		.350000 x	16.829739 =	5.890409
003		.350000 x	24.769248 =	8.669237

			T.E =	23.802418
4722.2	4722.2			
128		.100000 x	90.430000 =	9.043000
1447		.005000 x	58.155900 =	.290780
003		.350000 x	24.769248 =	8.669237
001		.350000 x	16.829739 =	5.890409

			T.E =	23.893425
4723	4723			
128		.120000 x	90.430000 =	10.851600
1417		.006000 x	39.954450 =	.239727
001		.400000 x	16.829739 =	6.731896
003		.350000 x	24.769248 =	8.669237

			T.E =	26.492459
4724.1	4724.1			
128		.150000 x	90.430000 =	13.564500
001		.400000 x	16.829739 =	6.731896
1417		.008000 x	39.954450 =	.319636
003		.400000 x	24.769248 =	9.907699

			T.E =	30.523730
4724.2	4724.2			
128		.150000 x	90.430000 =	13.564500
001		.400000 x	16.829739 =	6.731896
1447		.008000 x	58.155900 =	.465247
003		.400000 x	24.769248 =	9.907699

			T.E =	30.669342

4725.1	4725.1			
128		.180000 x	90.430000 =	16.277400
1417		.009000 x	39.954450 =	.359590
003		.400000 x	24.769248 =	9.907699
001		.450000 x	16.829739 =	7.573383

			T.E =	34.118072
4725.2	4725.2			
128		.180000 x	90.430000 =	16.277400
001		.450000 x	16.829739 =	7.573383
003		.400000 x	24.769248 =	9.907699
1447		.009000 x	58.155900 =	.523403

			T.E =	34.281885
4801.1	4801.1			
4662.1		1.000000 x	25.998063 =	25.998063
4662.1		.100000 x	25.998063 =	2.599806

			T.E =	28.597869
4801.2	4801.2			
4662.2		1.000000 x	26.413784 =	26.413784
4662.2		.100000 x	26.413784 =	2.641378

			T.E =	29.055162
4802.1	4802.1			
4664.1		1.000000 x	49.865898 =	49.865898
4664.1		.050000 x	49.865898 =	2.493295

			T.E =	52.359193
4802.2	4802.2			
4664.2		1.000000 x	50.686364 =	50.686364
4664.2		.050000 x	50.686364 =	2.534318

			T.E =	53.220682
4803.1	4803.1			
4665.1		1.000000 x	74.726078 =	74.726078
4665.1		.030000 x	74.726078 =	2.241782

			T.E =	76.967860
4803.2	4803.2			
4665.2		1.000000 x	75.591193 =	75.591193
4665.2		.030000 x	75.591193 =	2.267736

			T.E =	77.858929

4811.1	4811.1				
001		.225000 x	16.829739 =	3.786691	
4662.1		1.000000 x	25.998063 =	25.998063	
003		.250000 x	24.769248 =	6.192312	

			T.E =	35.977066	
4811.2	4811.2				
001		.225000 x	16.829739 =	3.786691	
003		.250000 x	24.769248 =	6.192312	
4662.2		1.000000 x	26.413784 =	26.413784	

			T.E =	36.392787	
4812.1	4812.1				
001		.475000 x	16.829739 =	7.994126	
003		.475000 x	24.769248 =	11.765393	
4664.1		1.000000 x	49.865898 =	49.865898	

			T.E =	69.625417	
4812.2	4812.2				
001		.475000 x	16.829739 =	7.994126	
4664.2		1.000000 x	50.686364 =	50.686364	
003		.475000 x	24.769248 =	11.765393	

			T.E =	70.445883	
4813.1	4813.1				
001		.750000 x	16.829739 =	12.622304	
003		.650000 x	24.769248 =	16.100011	
4665.1		1.000000 x	74.726078 =	74.726078	

			T.E =	103.448393	
4813.2	4813.2				
001		.750000 x	16.829739 =	12.622304	
003		.650000 x	24.769248 =	16.100011	
4665.2		1.000000 x	75.591193 =	75.591193	

			T.E =	104.313508	
4814.1	4814.1				
001		2.600000 x	16.829739 =	43.757321	
003		2.150000 x	24.769248 =	53.253883	
4666.1		1.000000 x	247.853398 =	247.853398	

			T.E =	344.864603	

4814.2	4814.2			
001		2.600000 x	16.829739 =	43.757321
4666.2		1.000000 x	252.910881 =	252.910881
003		2.150000 x	24.769248 =	53.253883

			T.E =	349.922086
4821.1	4821.1			
003		.450000 x	24.769248 =	11.146162
4662.1		1.000000 x	25.998063 =	25.998063

			T.E =	37.144225
4821.2	4821.2			
003		.450000 x	24.769248 =	11.146162
4662.2		1.000000 x	26.413784 =	26.413784

			T.E =	37.559946
4822.1	4822.1			
003		.807500 x	24.769248 =	20.001168
4664.1		1.000000 x	49.865898 =	49.865898

			T.E =	69.867066
4822.2	4822.2			
003		.807500 x	24.769248 =	20.001168
4664.2		1.000000 x	50.686364 =	50.686364

			T.E =	70.687532
4823.1	4823.1			
003		1.040000 x	24.769248 =	25.760018
4665.1		1.000000 x	74.726078 =	74.726078

			T.E =	100.486096
4823.2	4823.2			
003		1.040000 x	24.769248 =	25.760018
4665.2		1.000000 x	75.591193 =	75.591193

			T.E =	101.351211
4824.1	4824.1			
003		3.010000 x	24.769248 =	74.555436
4666.1		1.000000 x	247.853398 =	247.853398

			T.E =	322.408834

4824.2	4824.2			
003		3.010000 x	24.769248 =	74.555436
4666.2		1.000000 x	252.910881 =	252.910881

			T.E =	327.466317
4831.1	4831.1			
003		1.200000 x	24.769248 =	29.723098
4661.1		1.000000 x	23.541764 =	23.541764

			T.E =	53.264862
4831.2	4831.2			
003		1.200000 x	24.769248 =	29.723098
4661.2		1.000000 x	23.805812 =	23.805812

			T.E =	53.528910
4832.1	4832.1			
003		1.600000 x	24.769248 =	39.630797
4662.1		1.000000 x	25.998063 =	25.998063

			T.E =	65.628860
4832.2	4832.2			
003		1.600000 x	24.769248 =	39.630797
4662.2		1.000000 x	26.413784 =	26.413784

			T.E =	66.044581
4833.1	4833.1			
002		2.000000 x	18.705943 =	37.411886
4664.1		1.000000 x	49.865898 =	49.865898

			T.E =	87.277784
4833.2	4833.2			
002		2.000000 x	18.705943 =	37.411886
4664.2		1.000000 x	50.686364 =	50.686364

			T.E =	88.098250
4834.1	4834.1			
003		2.300000 x	24.769248 =	56.969270
4665.1		1.000000 x	74.726078 =	74.726078

			T.E =	131.695348

4834.2	4834.2			
003		2.300000 x	24.769248 =	56.969270
4665.2		1.000000 x	75.591193 =	75.591193

T.E = 132.560463

4835	4835			
122		1.050000 x	.000000 =	.000000
265		2.000000 x	.676500 =	1.353000
1417		.005000 x	39.954450 =	.199772
003		1.000000 x	24.769248 =	24.769248
001		1.000000 x	16.829739 =	16.829739
201		.010000 x	290.000000 =	2.900000

T.E =

4835.2	4835.2			
122		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	16.829739 =	16.829739
003		1.000000 x	24.769248 =	24.769248
1447		.005000 x	58.155900 =	.290780
265		2.000000 x	.676500 =	1.353000

T.E =

4836.1	4836.1			
123		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
1417		.005000 x	39.954450 =	.199772
003		1.000000 x	24.769248 =	24.769248
001		1.000000 x	16.829739 =	16.829739
265		2.000000 x	.676500 =	1.353000

T.E =

4836.2	4836.2			
123		1.050000 x	.000000 =	.000000
1447		.005000 x	58.155900 =	.290780
003		1.000000 x	24.769248 =	24.769248
001		1.000000 x	16.829739 =	16.829739
265		2.000000 x	.676500 =	1.353000
201		.010000 x	290.000000 =	2.900000

T.E =

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
003		1.000000 x	24.769248 =	24.769248
1417		.010000 x	39.954450 =	.399545
001		1.000000 x	16.829739 =	16.829739
265		2.000000 x	.676500 =	1.353000
201		.010000 x	290.000000 =	2.900000

			T.E =	52.446532
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
265		2.000000 x	.676500 =	1.353000
201		.010000 x	290.000000 =	2.900000
1447		.010000 x	58.155900 =	.581559
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943

			T.E =	54.504750
4841	4841			
003		.700000 x	24.769248 =	17.338474

			T.E =	17.338474
4842	4842			
003		1.000000 x	24.769248 =	24.769248

			T.E =	24.769248
4843	4843			
003		.250000 x	24.769248 =	6.192312

			T.E =	6.192312
4844	4844			
131		1,200.000000 x	.650000 =	780.000000
003		25.000000 x	24.769248 =	619.231200
1401		.250000 x	234.711000 =	58.677750
001		10.000000 x	16.829739 =	168.297390

			T.E =	1,626.206340
4845	4845			
132		620.000000 x	.930000 =	576.600000
003		15.000000 x	24.769248 =	371.538720
001		6.000000 x	16.829739 =	100.978434
1401		.180000 x	234.711000 =	42.247980

			T.E =	1,091.365134

4851	4851			
001		.100000 x	16.829739 =	1.682974

			T.E =	1.682974
4852	4852			
001		.150000 x	16.829739 =	2.524461

			T.E =	2.524461
4853	4853			
001		.200000 x	16.829739 =	3.365948

			T.E =	3.365948
4854	4854			
001		.250000 x	16.829739 =	4.207435

			T.E =	4.207435
4855	4855			
001		.300000 x	16.829739 =	5.048922

			T.E =	5.048922
4856	4856			
001		.800000 x	16.829739 =	13.463791

			T.E =	13.463791
4857	4857			
001		.200000 x	16.829739 =	3.365948

			T.E =	3.365948
4858	4858			
001		.300000 x	16.829739 =	5.048922

			T.E =	5.048922
4859	4859			
001		.400000 x	16.829739 =	6.731896

			T.E =	6.731896
4860	4860			
001		.500000 x	16.829739 =	8.414870

			T.E =	8.414870

4861	4861			
001		.600000 x	16.829739 =	10.097843

			T.E =	10.097843
4862	4862			
001		1.700000 x	16.829739 =	28.610556

			T.E =	28.610556
5101	5101			
214		1.100000 x	.000000 =	.000000
001		1.000000 x	16.829739 =	16.829739
003		4.000000 x	24.769248 =	99.076992

			T.E =	
5102	5102			
483		1.800000 x	.165000 =	.297000
001		1.000000 x	16.829739 =	16.829739
489		.360000 x	.000000 =	.000000
492		1.440000 x	.540000 =	.777600
491		1.260000 x	.540000 =	.680400
488		.540000 x	5.000000 =	2.700000

			T.E =	
5103	5103			
265		1.050000 x	.676500 =	.710325
003		.200000 x	24.769248 =	4.953850
002		.050000 x	18.705943 =	.935297

			T.E =	6.599472
5104	5104			
001		2.000000 x	16.829739 =	33.659478
003		.150000 x	24.769248 =	3.715387

			T.E =	37.374865
5105	5105			
214		.010000 x	.000000 =	.000000
003		.500000 x	24.769248 =	12.384624
001		2.000000 x	16.829739 =	33.659478

			T.E =	

5106	5106			
214		.050000 x	.000000 =	.000000
003		2.500000 x	24.769248 =	61.923120
001		2.000000 x	16.829739 =	33.659478

			T.E =	
5201	5201			
201		1.100000 x	290.000000 =	319.000000
003		10.000000 x	24.769248 =	247.692480
002		5.000000 x	18.705943 =	93.529715
251		6.000000 x	.680000 =	4.080000

			T.E =	664.302195
5202	5202			
203.2		1.080000 x	335.000000 =	361.800000
002		4.500000 x	18.705943 =	84.176744
003		9.000000 x	24.769248 =	222.923232
251		6.000000 x	.680000 =	4.080000

			T.E =	672.979976
5203	5203			
201		1.120000 x	290.000000 =	324.800000
003		16.000000 x	24.769248 =	396.307968
002		8.000000 x	18.705943 =	149.647544
251		12.000000 x	.680000 =	8.160000

			T.E =	878.915512
5204	5204			
203.2		1.100000 x	335.000000 =	368.500000
003		14.000000 x	24.769248 =	346.769472
002		7.000000 x	18.705943 =	130.941601
251		12.000000 x	.680000 =	8.160000

			T.E =	854.371073
5211	5211			
201		1.100000 x	290.000000 =	319.000000
251		14.000000 x	.680000 =	9.520000
002		6.000000 x	18.705943 =	112.235658
003		12.000000 x	24.769248 =	297.230976

			T.E =	737.986634

5212	5212				
203.2		1.080000 x	335.000000 =	361.800000	
002		5.000000 x	18.705943 =	93.529715	
251		14.000000 x	.680000 =	9.520000	
003		10.000000 x	24.769248 =	247.692480	

			T.E =	712.542195	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
251		8.000000 x	.680000 =	5.440000	
003		9.000000 x	24.769248 =	222.923232	
002		4.500000 x	18.705943 =	84.176744	

			T.E =	631.539976	
5221	5221				
203.2		.014000 x	335.000000 =	4.690000	
003		.200000 x	24.769248 =	4.953850	
002		.050000 x	18.705943 =	.935297	
251		.100000 x	.680000 =	.068000	

			T.E =	10.647147	
5222	5222				
203.2		.018000 x	335.000000 =	6.030000	
002		.070000 x	18.705943 =	1.309416	
003		.200000 x	24.769248 =	4.953850	
251		.100000 x	.680000 =	.068000	

			T.E =	12.361266	
5223	5223				
203.2		.026000 x	335.000000 =	8.710000	
251		.100000 x	.680000 =	.068000	
003		.200000 x	24.769248 =	4.953850	
002		.100000 x	18.705943 =	1.870594	

			T.E =	15.602444	
5226	5226				
203.2		.016000 x	335.000000 =	5.360000	
251		.100000 x	.680000 =	.068000	
003		.200000 x	24.769248 =	4.953850	
002		.050000 x	18.705943 =	.935297	

			T.E =	11.317147	

5227	5227				
203.2		.022000 x	335.000000 =	7.370000	
003		.200000 x	24.769248 =	4.953850	
002		.100000 x	18.705943 =	1.870594	
251		.100000 x	.680000 =	.068000	

			T.E =	14.262444	
5228	5228				
203.2		.030000 x	335.000000 =	10.050000	
251		.150000 x	.680000 =	.102000	
002		.150000 x	18.705943 =	2.805891	
003		.200000 x	24.769248 =	4.953850	

			T.E =	17.911741	
5231	5231				
203.2		.018000 x	335.000000 =	6.030000	
251		.150000 x	.680000 =	.102000	
003		.250000 x	24.769248 =	6.192312	
002		.100000 x	18.705943 =	1.870594	

			T.E =	14.194906	
5232	5232				
203.2		.025000 x	335.000000 =	8.375000	
251		.150000 x	.680000 =	.102000	
003		.250000 x	24.769248 =	6.192312	
002		.120000 x	18.705943 =	2.244713	

			T.E =	16.914025	
5233	5233				
203.2		.034000 x	335.000000 =	11.390000	
003		.250000 x	24.769248 =	6.192312	
002		.150000 x	18.705943 =	2.805891	
251		.200000 x	.680000 =	.136000	

			T.E =	20.524203	
5236	5236				
203.2		.016000 x	335.000000 =	5.360000	
251		.080000 x	.680000 =	.054400	
002		.250000 x	18.705943 =	4.676486	
003		.350000 x	24.769248 =	8.669237	

			T.E =	18.760123	

5237	5237				
203.2		.022000 x	335.000000 =		7.370000
251		.080000 x	.680000 =		.054400
003		.350000 x	24.769248 =		8.669237
002		.300000 x	18.705943 =		5.611783

			T.E =		21.705420
5238	5238				
203.2		.030000 x	335.000000 =		10.050000
251		.100000 x	.680000 =		.068000
003		.350000 x	24.769248 =		8.669237
002		.350000 x	18.705943 =		6.547080

			T.E =		25.334317
5241	5241				
203.2		.030000 x	335.000000 =		10.050000
003		.500000 x	24.769248 =		12.384624
002		.500000 x	18.705943 =		9.352972
251		.100000 x	.680000 =		.068000

			T.E =		31.855596
5243	5243				
003		.150000 x	24.769248 =		3.715387

			T.E =		3.715387
5244	5244				
003		.350000 x	24.769248 =		8.669237

			T.E =		8.669237
5246	5246				
220		26.000000 x	.000000 =		.000000
002		.500000 x	18.705943 =		9.352972
251		.200000 x	.680000 =		.136000

			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
251		.100000 x	.680000 =		.068000
002		.600000 x	18.705943 =		11.223566
283		.100000 x	1.000100 =		.100010

			T.E =		

5251	5251				
243.3		1.050000 x	4.450000 =	4.672500	
003		.300000 x	24.769248 =	7.430774	
002		.300000 x	18.705943 =	5.611783	
251		.100000 x	.680000 =	.068000	

			T.E =	17.783057	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
003		2.500000 x	24.769248 =	61.923120	
245		.110000 x	18.600000 =	2.046000	
002		2.500000 x	18.705943 =	46.764858	

			T.E =	131.193978	
5252.2	5252.2				
246		1.100000 x	9.000000 =	9.900000	
003		2.500000 x	24.769248 =	61.923120	
002		2.500000 x	18.705943 =	46.764858	
246		.110000 x	9.000000 =	.990000	

			T.E =	119.577978	
5252.3	5252.3				
249		1.100000 x	19.000000 =	20.900000	
003		2.500000 x	24.769248 =	61.923120	
002		2.500000 x	18.705943 =	46.764858	
249		.110000 x	19.000000 =	2.090000	

			T.E =	131.677978	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
003		1.500000 x	24.769248 =	37.153872	
002		1.500000 x	18.705943 =	28.058915	
219		.060000 x	3.500000 =	.210000	

			T.E =	69.622787	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
251		.600000 x	.680000 =	.408000	
002		.800000 x	18.705943 =	14.964754	
003		.800000 x	24.769248 =	19.815398	
203.2		.025000 x	335.000000 =	8.375000	

			T.E =	49.363153	

5262	5262			
201		.030000 x	290.000000 =	8.700000
251		.300000 x	.680000 =	.204000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
265		.300000 x	.676500 =	.202950
252		.200000 x	1.750000 =	.350000
203.2		.025000 x	335.000000 =	8.375000

			T.E =	61.307141
5266	5266			
201		.020000 x	290.000000 =	5.800000
003		.600000 x	24.769248 =	14.861549
002		.600000 x	18.705943 =	11.223566
251		.600000 x	.680000 =	.408000
203.2		.015000 x	335.000000 =	5.025000

			T.E =	37.318115
5267	5267			
201		.030000 x	290.000000 =	8.700000
251		.300000 x	.680000 =	.204000
003		.800000 x	24.769248 =	19.815398
002		.800000 x	18.705943 =	14.964754
265		.300000 x	.676500 =	.202950
252		.300000 x	1.750000 =	.525000
203.2		.015000 x	335.000000 =	5.025000

			T.E =	49.437103
5271	5271			
201		.016000 x	290.000000 =	4.640000
203.2		.025000 x	335.000000 =	8.375000
251		.600000 x	.680000 =	.408000
003		.500000 x	24.769248 =	12.384624
002		.500000 x	18.705943 =	9.352972

			T.E =	35.160596
5272	5272			
201		.024000 x	290.000000 =	6.960000
251		.300000 x	.680000 =	.204000
003		.700000 x	24.769248 =	17.338474
002		.700000 x	18.705943 =	13.094160
252		.100000 x	1.750000 =	.175000
265		.200000 x	.676500 =	.135300
203.2		.025000 x	335.000000 =	8.375000

			T.E =	46.281934

5273	5273				
201		.016000 x	290.000000 =	4.640000	
003		.500000 x	24.769248 =	12.384624	
002		.500000 x	18.705943 =	9.352972	
251		.600000 x	.680000 =	.408000	
203.2		.015000 x	335.000000 =	5.025000	

			T.E =	31.810596	
5274	5274				
201		.024000 x	290.000000 =	6.960000	
003		.700000 x	24.769248 =	17.338474	
002		.700000 x	18.705943 =	13.094160	
252		.100000 x	1.750000 =	.175000	
265		.200000 x	.676500 =	.135300	
251		.300000 x	.680000 =	.204000	
203.2		.015000 x	335.000000 =	5.025000	

			T.E =	42.931934	
5276	5276				
201		1.080000 x	290.000000 =	313.200000	
003		19.000000 x	24.769248 =	470.615712	
002		19.000000 x	18.705943 =	355.412917	
252		18.000000 x	1.750000 =	31.500000	
251		6.000000 x	.680000 =	4.080000	

			T.E =	1,174.808629	
5277	5277				
203.2		1.080000 x	335.000000 =	361.800000	
251		6.000000 x	.680000 =	4.080000	
002		18.000000 x	18.705943 =	336.706974	
003		18.000000 x	24.769248 =	445.846464	
252		18.000000 x	1.750000 =	31.500000	

			T.E =	1,179.933438	
5279	5279				
201		1.080000 x	290.000000 =	313.200000	
251		12.000000 x	.680000 =	8.160000	
002		5.000000 x	18.705943 =	93.529715	
003		10.000000 x	24.769248 =	247.692480	

			T.E =	662.582195	

5280	5280				
203.2		1.080000 x	335.000000 =	361.800000	
251		12.000000 x	.680000 =	8.160000	
003		10.000000 x	24.769248 =	247.692480	
002		5.000000 x	18.705943 =	93.529715	

			T.E =	711.182195	
5281	5281				
203.2		.014000 x	335.000000 =	4.690000	
002		.250000 x	18.705943 =	4.676486	
251		.040000 x	.680000 =	.027200	

			T.E =	9.393686	
5282	5282				
203.2		.020000 x	335.000000 =	6.700000	
251		.060000 x	.680000 =	.040800	
002		.350000 x	18.705943 =	6.547080	

			T.E =	13.287880	
5283	5283				
203.2		.026000 x	335.000000 =	8.710000	
251		.080000 x	.680000 =	.054400	
002		.400000 x	18.705943 =	7.482377	

			T.E =	16.246777	
5286	5286				
203.2		.008000 x	335.000000 =	2.680000	
003		.120000 x	24.769248 =	2.972310	
251		.030000 x	.680000 =	.020400	
002		.120000 x	18.705943 =	2.244713	

			T.E =	7.917423	
5288	5288				
003		.300000 x	24.769248 =	7.430774	

			T.E =	7.430774	
5289	5289				
003		1.000000 x	24.769248 =	24.769248	

			T.E =	24.769248	

5291	5291			
203.2		.020000 x	335.000000 =	6.700000
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377
251		.200000 x	.680000 =	.136000
220		26.000000 x	.000000 =	.000000

			T.E =	
5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	24.769248 =	14.861549
002		.600000 x	18.705943 =	11.223566
251		.200000 x	.680000 =	.136000
220		26.000000 x	.000000 =	.000000
203.2		.010000 x	335.000000 =	3.350000

			T.E =	
5293	5293			
203.2		.020000 x	335.000000 =	6.700000
251		.150000 x	.680000 =	.102000
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377
203.2		.016000 x	335.000000 =	5.360000

			T.E =	29.552076
5294	5294			
203.2		.020000 x	335.000000 =	6.700000
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377
203.2		.022000 x	335.000000 =	7.370000
251		.100000 x	.680000 =	.068000

			T.E =	31.528076
5295	5295			
203.2		.020000 x	335.000000 =	6.700000
251		.050000 x	.680000 =	.034000
003		.250000 x	24.769248 =	6.192312
002		.250000 x	18.705943 =	4.676486

			T.E =	17.602798
5301	5301			
226		1.050000 x	11.500000 =	12.075000
251		.250000 x	.680000 =	.170000
003		.600000 x	24.769248 =	14.861549
002		.600000 x	18.705943 =	11.223566

			T.E =	38.330115

5302	5302				
227		1.050000 x	11.500000 =	12.075000	
002		.500000 x	18.705943 =	9.352972	
003		.500000 x	24.769248 =	12.384624	
251		.200000 x	.680000 =	.136000	

			T.E =	33.948596	
5321	5321				
203.2		.012000 x	335.000000 =	4.020000	
003		.900000 x	24.769248 =	22.292323	
002		.900000 x	18.705943 =	16.835349	
251		.500000 x	.680000 =	.340000	
226		1.050000 x	11.500000 =	12.075000	

			T.E =	55.562672	
5322	5322				
203.2		.012000 x	335.000000 =	4.020000	
003		.800000 x	24.769248 =	19.815398	
002		.800000 x	18.705943 =	14.964754	
227		1.050000 x	11.500000 =	12.075000	
251		.450000 x	.680000 =	.306000	

			T.E =	51.181153	
5323	5323				
203.2		.012000 x	335.000000 =	4.020000	
251		.500000 x	.680000 =	.340000	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
228		1.050000 x	35.000000 =	36.750000	

			T.E =	84.585191	
5324	5324				
203.2		.012000 x	335.000000 =	4.020000	
229		1.050000 x	.000000 =	.000000	
002		1.000000 x	18.705943 =	18.705943	
003		1.000000 x	24.769248 =	24.769248	
251		.500000 x	.680000 =	.340000	

			T.E =		
5325	5325				
203.2		.012000 x	335.000000 =	4.020000	
230		1.050000 x	.000000 =	.000000	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
251		.500000 x	.680000 =	.340000	

			T.E =		

5326	5326				
203.2		.012000 x	335.000000 =	4.020000	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
251		.500000 x	.680000 =	.340000	
231		1.050000 x	20.000000 =	21.000000	
			T.E =	68.835191	
5341	5341				
203.2		.037000 x	335.000000 =	12.395000	
232		1.050000 x	45.000000 =	47.250000	
251		.600000 x	.680000 =	.408000	
002		1.100000 x	18.705943 =	20.576537	
003		1.100000 x	24.769248 =	27.246173	
			T.E =	107.875710	
5342	5342				
203.2		.037000 x	335.000000 =	12.395000	
232		1.100000 x	45.000000 =	49.500000	
251		.600000 x	.680000 =	.408000	
003		1.700000 x	24.769248 =	42.107722	
002		1.700000 x	18.705943 =	31.800103	
			T.E =	136.210825	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
233		.084000 x	21.300000 =	1.789200	
003		.800000 x	24.769248 =	19.815398	
002		.800000 x	18.705943 =	14.964754	
			T.E =	58.934353	
5351	5351				
035		.200000 x	.125600 =	.025120	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
251		.100000 x	.680000 =	.068000	
236		1.060000 x	2.600000 =	2.756000	
			T.E =	11.544158	
5352	5352				
035		.200000 x	.125600 =	.025120	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
237		1.060000 x	1.100000 =	1.166000	
251		.100000 x	.680000 =	.068000	
			T.E =	9.954158	

5353	5353			
035		.200000 x	.125600 =	.025120
251		.100000 x	.680000 =	.068000
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
238		1.060000 x	2.600000 =	2.756000

			T.E =	11.544158
5354	5354			
035		.200000 x	.125600 =	.025120
239		1.060000 x	.000000 =	.000000
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850
251		.100000 x	.680000 =	.068000

			T.E =	
5355	5355			
035		.200000 x	.125600 =	.025120
240		1.060000 x	1.600000 =	1.696000
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
251		.100000 x	.680000 =	.068000

			T.E =	10.484158
5356	5356			
035		.200000 x	.125600 =	.025120
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
251		.100000 x	.680000 =	.068000
241		1.060000 x	.000000 =	.000000

			T.E =	
5421	5421			
205		.055000 x	420.000000 =	23.100000
1471		1.000000 x	5.214985 =	5.214985
002		3.500000 x	18.705943 =	65.470801
003		3.500000 x	24.769248 =	86.692368

			T.E =	180.478154
5422	5422			
205		.035000 x	420.000000 =	14.700000
1472		1.000000 x	6.309176 =	6.309176
003		3.000000 x	24.769248 =	74.307744
002		3.000000 x	18.705943 =	56.117829

			T.E =	151.434749

5426	5426			
205		.095000 x	420.000000 =	39.900000
1473		1.000000 x	10.839609 =	10.839609
1471		1.000000 x	5.214985 =	5.214985
003		6.000000 x	24.769248 =	148.615488
002		6.000000 x	18.705943 =	112.235658

T.E = 316.805740

5427	5427			
205		.105000 x	420.000000 =	44.100000
1474		1.000000 x	13.159177 =	13.159177
1471		1.000000 x	5.214985 =	5.214985
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601

T.E = 366.800499

5428	5428			
205		.075000 x	420.000000 =	31.500000
002		5.500000 x	18.705943 =	102.882687
003		5.500000 x	24.769248 =	136.230864
1474		1.000000 x	13.159177 =	13.159177
1472		1.000000 x	6.309176 =	6.309176

T.E = 290.081904

5431	5431			
205		.070000 x	420.000000 =	29.400000
208		.030000 x	1,239.000000 =	37.170000
002		7.000000 x	18.705943 =	130.941601
003		7.000000 x	24.769248 =	173.384736
1475		1.000000 x	37.468613 =	37.468613
1471		1.000000 x	5.214985 =	5.214985

T.E = 413.579935

5432	5432			
205		.070000 x	420.000000 =	29.400000
380		1.000000 x	16.150000 =	16.150000
003		5.000000 x	24.769248 =	123.846240
1475		.800000 x	37.468613 =	29.974890
1471		1.000000 x	5.214985 =	5.214985
002		5.000000 x	18.705943 =	93.529715

T.E = 298.115830

5436	5436				
205		.050000 x	420.000000 =	21.000000	
1476		1.000000 x	2.765880 =	2.765880	
003		4.500000 x	24.769248 =	111.461616	
002		4.500000 x	18.705943 =	84.176744	

			T.E =	219.404240	
5437	5437				
205		.065000 x	420.000000 =	27.300000	
002		5.000000 x	18.705943 =	93.529715	
1476		1.000000 x	2.765880 =	2.765880	
003		5.000000 x	24.769248 =	123.846240	

			T.E =	247.441835	
5438	5438				
205		.050000 x	420.000000 =	21.000000	
002		4.000000 x	18.705943 =	74.823772	
1476		1.000000 x	2.765880 =	2.765880	
003		4.000000 x	24.769248 =	99.076992	

			T.E =	197.666644	
5441.1	5441.1				
205		.065000 x	420.000000 =	27.300000	
1476		1.000000 x	2.765880 =	2.765880	
003		4.500000 x	24.769248 =	111.461616	
002		4.500000 x	18.705943 =	84.176744	
223.3		.004000 x	.000000 =	.000000	

			T.E =	230.244240	
5441.2	5441.2				
205		.065000 x	420.000000 =	27.300000	
1476		1.000000 x	2.765880 =	2.765880	
003		4.500000 x	24.769248 =	111.461616	
002		4.500000 x	18.705943 =	84.176744	
223.3		.004000 x	1,135.000000 =	4.540000	

			T.E =	230.244240	
5441.3	5441.3				
205		.065000 x	420.000000 =	27.300000	
243.1		.550000 x	2.660000 =	1.463000	
002		4.500000 x	18.705943 =	84.176744	
1476		1.000000 x	2.765880 =	2.765880	
003		4.500000 x	24.769248 =	111.461616	

			T.E =	227.167240	

5442.1	5442.1			
205		.080000 x	420.000000 =	33.600000
1476		1.000000 x	2.765880 =	2.765880
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715

T.E =

5442.2	5442.2			
205		.080000 x	420.000000 =	33.600000
223.3		.004000 x	1,135.000000 =	4.540000
003		5.000000 x	24.769248 =	123.846240
1476		1.000000 x	2.765880 =	2.765880
002		5.000000 x	18.705943 =	93.529715

T.E =

5442.3	5442.3			258.281835
205		.080000 x	420.000000 =	33.600000
1476		1.000000 x	2.765880 =	2.765880
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715
243.1		.055000 x	2.660000 =	.146300

T.E =

5443.1	5443.1			253.888135
205		.065000 x	420.000000 =	27.300000
002		4.000000 x	18.705943 =	74.823772
1476		1.000000 x	2.765880 =	2.765880
003		4.000000 x	24.769248 =	99.076992
222.3		.004000 x	.000000 =	.000000

T.E =

5443.2	5443.2			
205		.065000 x	420.000000 =	27.300000
003		4.000000 x	24.769248 =	99.076992
1476		1.000000 x	2.765880 =	2.765880
002		4.000000 x	18.705943 =	74.823772
223.3		.004000 x	1,135.000000 =	4.540000

T.E =

208.506644

5443.3	5443.3			
205		.065000 x	420.000000 =	27.300000
1476		1.000000 x	2.765880 =	2.765880
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
243.1		.550000 x	2.660000 =	1.463000

T.E = 205.429644

5446.1	5446.1			
203.2		.025000 x	335.000000 =	8.375000
222.2		.010000 x	.000000 =	.000000
002		4.000000 x	18.705943 =	74.823772
1476		1.000000 x	2.765880 =	2.765880
003		4.000000 x	24.769248 =	99.076992
205		.025000 x	420.000000 =	10.500000

T.E =

5446.2	5446.2			
203.2		.025000 x	335.000000 =	8.375000
223.2		.010000 x	1,450.000000 =	14.500000
1476		1.000000 x	2.765880 =	2.765880
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
205		.025000 x	420.000000 =	10.500000

T.E = 210.041644

5447.1	5447.1			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.765880 =	2.765880
003		4.500000 x	24.769248 =	111.461616
002		4.500000 x	18.705943 =	84.176744
222.2		.010000 x	.000000 =	.000000
205		.040000 x	420.000000 =	16.800000

T.E =

5447.2	5447.2			
203.2		.025000 x	335.000000 =	8.375000
205		.040000 x	420.000000 =	16.800000
223.2		.010000 x	1,450.000000 =	14.500000
1476		1.000000 x	2.765880 =	2.765880
003		4.500000 x	24.769248 =	111.461616
002		4.500000 x	18.705943 =	84.176744

T.E = 238.079240

5448.1	5448.1			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.765880 =	2.765880
003		3.500000 x	24.769248 =	86.692368
205		.025000 x	420.000000 =	10.500000
002		3.500000 x	18.705943 =	65.470801
222.2		.010000 x	.000000 =	.000000

T.E =

5448.2	5448.2			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
002		3.500000 x	18.705943 =	65.470801
1476		1.000000 x	2.765880 =	2.765880
003		3.500000 x	24.769248 =	86.692368
223.2		.010000 x	1,450.000000 =	14.500000

T.E =

188.304049

5449	5449			
205		.045000 x	420.000000 =	18.900000
1476		1.000000 x	2.765880 =	2.765880
003		3.000000 x	24.769248 =	74.307744
002		3.000000 x	18.705943 =	56.117829
243.5		.850000 x	6.250000 =	5.312500

T.E =

157.403953

5451.1	5451.1			
205		.090000 x	420.000000 =	37.800000
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	24.769248 =	123.846240
1476		1.000000 x	2.765880 =	2.765880
002		5.000000 x	18.705943 =	93.529715

T.E =

5451.2	5451.2			
205		.090000 x	420.000000 =	37.800000
223.3		.004000 x	1,135.000000 =	4.540000
1476		1.000000 x	2.765880 =	2.765880
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715

T.E =

262.481835

5451.3	5451.3			
205		.090000 x	420.000000 =	37.800000
243.1		.550000 x	2.660000 =	1.463000
1476		1.000000 x	2.765880 =	2.765880
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715

			T.E =	259.404835
5456	5456			
205		.055000 x	420.000000 =	23.100000
1478		1.000000 x	2.985250 =	2.985250
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772

			T.E =	199.986014
5457	5457			
205		.085000 x	420.000000 =	35.700000
261		2.200000 x	.549400 =	1.208680
003		7.000000 x	24.769248 =	173.384736
1476		1.500000 x	2.765880 =	4.148820
002		7.000000 x	18.705943 =	130.941601

			T.E =	345.383837
5461.1	5461.1			
205		.065000 x	420.000000 =	27.300000
222.2		.010000 x	.000000 =	.000000
002		5.500000 x	18.705943 =	102.882687
1479		1.000000 x	34.208511 =	34.208511
003		5.500000 x	24.769248 =	136.230864

			T.E =	
5461.2	5461.2			
205		.065000 x	420.000000 =	27.300000
223.2		.010000 x	1,450.000000 =	14.500000
1479		1.000000 x	34.208511 =	34.208511
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687

			T.E =	315.122062
5462.1	5462.1			
205		.065000 x	420.000000 =	27.300000
1480		1.000000 x	33.104222 =	33.104222
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687
222.2		.010000 x	.000000 =	.000000

			T.E =	

5462.2	5462.2			
205		.065000 x	420.000000 =	27.300000
223.2		.010000 x	1,450.000000 =	14.500000
003		5.500000 x	24.769248 =	136.230864
1480		1.000000 x	33.104222 =	33.104222
002		5.500000 x	18.705943 =	102.882687

T.E = 314.017773

5463.1	5463.1			
205		.055000 x	420.000000 =	23.100000
222.2		.010000 x	.000000 =	.000000
003		6.000000 x	24.769248 =	148.615488
1479		.500000 x	34.208511 =	17.104256
002		6.000000 x	18.705943 =	112.235658

T.E =

5463.2	5463.2			
205		.055000 x	420.000000 =	23.100000
223.2		.010000 x	1,450.000000 =	14.500000
1479		.500000 x	34.208511 =	17.104256
003		6.000000 x	24.769248 =	148.615488
002		6.000000 x	18.705943 =	112.235658

T.E = 315.555402

5464.1	5464.1			
205		.070000 x	420.000000 =	29.400000
1479		.500000 x	34.208511 =	17.104256
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601
222.2		.010000 x	.000000 =	.000000

T.E =

5464.2	5464.2			
205		.070000 x	420.000000 =	29.400000
003		7.000000 x	24.769248 =	173.384736
1479		.500000 x	34.208511 =	17.104256
002		7.000000 x	18.705943 =	130.941601
223.2		.010000 x	1,450.000000 =	14.500000

T.E = 365.330593

5465.1	5465.1			
203.2		.045000 x	335.000000 =	15.075000
003		5.500000 x	24.769248 =	136.230864
1476		1.000000 x	2.765880 =	2.765880
002		5.500000 x	18.705943 =	102.882687
208		.030000 x	1,239.000000 =	37.170000
222.2		.005000 x	.000000 =	.000000

T.E =

5465.2	5465.2			
203.2		.045000 x	335.000000 =	15.075000
1476		1.000000 x	2.765880 =	2.765880
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687
223.2		.005000 x	1,450.000000 =	7.250000
208		.030000 x	1,239.000000 =	37.170000

T.E =

301.374431

5466.1	5466.1			
203.2		.025000 x	335.000000 =	8.375000
002		5.000000 x	18.705943 =	93.529715
1479		.900000 x	34.208511 =	30.787660
003		5.000000 x	24.769248 =	123.846240
222.2		.010000 x	.000000 =	.000000

T.E =

5466.2	5466.2			
203.2		.025000 x	335.000000 =	8.375000
223.2		.010000 x	1,450.000000 =	14.500000
1479		.900000 x	34.208511 =	30.787660
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715

T.E =

271.038615

5467.1	5467.1			
203.2		.013000 x	335.000000 =	4.355000
222.2		.000960 x	.000000 =	.000000
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
222.2		.012000 x	.000000 =	.000000
203.2		.001040 x	335.000000 =	.348400

T.E =

5467.2	5467.2			
203.2		.013000 x	335.000000 =	4.355000
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
223.2		.012000 x	1,450.000000 =	17.400000
223.2		.000960 x	1,450.000000 =	1.392000
203.2		.001040 x	335.000000 =	.348400

T.E = 175.658569

5468.1	5468.1			
203.2		.025000 x	335.000000 =	8.375000
203.2		.002000 x	335.000000 =	.670000
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
222.2		.000800 x	.000000 =	.000000
222.2		.010000 x	.000000 =	.000000

T.E =

5468.2	5468.2			
203.2		.025000 x	335.000000 =	8.375000
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
223.2		.000800 x	1,450.000000 =	1.160000
223.2		.010000 x	1,450.000000 =	14.500000
203.2		.002000 x	335.000000 =	.670000

T.E = 198.605764

5469.1	5469.1			
203.2		.025000 x	335.000000 =	8.375000
222.2		.010000 x	.000000 =	.000000
1479		.500000 x	34.208511 =	17.104256
003		4.500000 x	24.769248 =	111.461616
002		4.500000 x	18.705943 =	84.176744

T.E =

5469.2	5469.2			
203.2		.025000 x	335.000000 =	8.375000
223.2		.010000 x	1,450.000000 =	14.500000
003		4.500000 x	24.769248 =	111.461616
1479		.500000 x	34.208511 =	17.104256
002		4.500000 x	18.705943 =	84.176744

T.E = 235.617615

5471	5471				
203.2		.035000 x	335.000000 =	11.725000	
251		3.000000 x	.680000 =	2.040000	
003		3.500000 x	24.769248 =	86.692368	
002		3.500000 x	18.705943 =	65.470801	

			T.E =	165.928169	
5472.1	5472.1				
203.2		.026000 x	335.000000 =	8.710000	
003		3.500000 x	24.769248 =	86.692368	
222.4		.010000 x	.000000 =	.000000	
002		3.500000 x	18.705943 =	65.470801	
251		3.000000 x	.680000 =	2.040000	

			T.E =		
5472.2	5472.2				
203.2		.026000 x	335.000000 =	8.710000	
251		3.000000 x	.680000 =	2.040000	
002		3.500000 x	18.705943 =	65.470801	
003		3.500000 x	24.769248 =	86.692368	
223.4		.010000 x	1,440.000000 =	14.400000	

			T.E =	177.313169	
5501.1	5501.1				
211		.040000 x	.000000 =	.000000	
003		5.000000 x	24.769248 =	123.846240	
002		2.500000 x	18.705943 =	46.764858	
252		.100000 x	1.750000 =	.175000	
251		.050000 x	.680000 =	.034000	

			T.E =		
5501.2	5501.2				
212		.040000 x	1,400.000000 =	56.000000	
003		5.000000 x	24.769248 =	123.846240	
002		2.500000 x	18.705943 =	46.764858	
252		.100000 x	1.750000 =	.175000	
251		.050000 x	.680000 =	.034000	

			T.E =	226.820098	
5502	5502				
210		.040000 x	.000000 =	.000000	
252		.100000 x	1.750000 =	.175000	
251		.050000 x	.680000 =	.034000	
003		4.000000 x	24.769248 =	99.076992	
002		2.000000 x	18.705943 =	37.411886	

			T.E =		

5511.1	5511.1			
211		.020000 x	.000000 =	.000000
252		.100000 x	1.750000 =	.175000
003		3.200000 x	24.769248 =	79.261594
002		1.600000 x	18.705943 =	29.929509

T.E =

5511.2	5511.2			
212		.020000 x	1,400.000000 =	28.000000
252		.100000 x	1.750000 =	.175000
003		3.200000 x	24.769248 =	79.261594
002		1.600000 x	18.705943 =	29.929509

T.E =

137.366102

5512	5512			
205		.020000 x	420.000000 =	8.400000
003		3.000000 x	24.769248 =	74.307744
252		.100000 x	1.750000 =	.175000
002		1.500000 x	18.705943 =	28.058915

T.E =

110.941659

5513.1	5513.1			
211		.020000 x	.000000 =	.000000
002		2.000000 x	18.705943 =	37.411886
003		4.000000 x	24.769248 =	99.076992
252		.100000 x	1.750000 =	.175000

T.E =

5513.2	5513.2			
212		.020000 x	1,400.000000 =	28.000000
003		4.000000 x	24.769248 =	99.076992
002		2.000000 x	18.705943 =	37.411886
252		.100000 x	1.750000 =	.175000

T.E =

164.663878

5514	5514			
205		.020000 x	420.000000 =	8.400000
003		3.800000 x	24.769248 =	94.123142
002		1.800000 x	18.705943 =	33.670697
252		.100000 x	1.750000 =	.175000

T.E =

136.368840

5521	5521				
205		.030000 x	420.000000 =		12.600000
252		.150000 x	1.750000 =		.262500
002		.800000 x	18.705943 =		14.964754
003		2.000000 x	24.769248 =		49.538496
				T.E =	77.365750
5531.1	5531.1				
211		.010000 x	.000000 =		.000000
252		.020000 x	1.750000 =		.035000
003		2.200000 x	24.769248 =		54.492346
002		.700000 x	18.705943 =		13.094160
				T.E =	
5531.2	5531.2				
212		.010000 x	1,400.000000 =		14.000000
252		.020000 x	1.750000 =		.035000
003		2.200000 x	24.769248 =		54.492346
002		.700000 x	18.705943 =		13.094160
				T.E =	81.621506
5531.3	5531.3				
205		.010000 x	420.000000 =		4.200000
003		2.200000 x	24.769248 =		54.492346
002		.700000 x	18.705943 =		13.094160
252		.020000 x	1.750000 =		.035000
				T.E =	71.821506
5532.1	5532.1				
211		.010000 x	.000000 =		.000000
252		.020000 x	1.750000 =		.035000
003		3.000000 x	24.769248 =		74.307744
002		1.000000 x	18.705943 =		18.705943
				T.E =	
5532.2	5532.2				
212		.010000 x	1,400.000000 =		14.000000
252		.020000 x	1.750000 =		.035000
003		3.000000 x	24.769248 =		74.307744
002		1.000000 x	18.705943 =		18.705943
				T.E =	107.048687

5532.3	5532.3			
205		.010000 x	420.000000 =	4.200000
003		3.000000 x	24.769248 =	74.307744
002		1.000000 x	18.705943 =	18.705943
252		.020000 x	1.750000 =	.035000
			T.E =	97.248687
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	24.769248 =	8.669237
			T.E =	10.454237
5601	5601			
203.2		.028000 x	335.000000 =	9.380000
003		2.500000 x	24.769248 =	61.923120
002		2.500000 x	18.705943 =	46.764858
251		4.000000 x	.680000 =	2.720000
			T.E =	120.787978
5602	5602			
203.2		.018000 x	335.000000 =	6.030000
003		2.300000 x	24.769248 =	56.969270
002		2.300000 x	18.705943 =	43.023669
251		3.000000 x	.680000 =	2.040000
			T.E =	108.062939
5603	5603			
203.2		.013000 x	335.000000 =	4.355000
251		2.500000 x	.680000 =	1.700000
002		2.000000 x	18.705943 =	37.411886
003		2.000000 x	24.769248 =	49.538496
			T.E =	93.005382
5604	5604			
243.5		1.100000 x	6.250000 =	6.875000
243.5		.165000 x	6.250000 =	1.031250
003		2.200000 x	24.769248 =	54.492346
002		2.200000 x	18.705943 =	41.153075
			T.E =	103.551670

5605	5605				
243.3		1.100000 x	4.450000 =	4.895000	
003		2.000000 x	24.769248 =	49.538496	
002		2.000000 x	18.705943 =	37.411886	
243.3		.187000 x	4.450000 =	.832150	

			T.E =	92.677532	
5606	5606				
243.2		1.100000 x	3.650000 =	4.015000	
243.2		.220000 x	3.650000 =	.803000	
003		1.800000 x	24.769248 =	44.584646	
002		1.800000 x	18.705943 =	33.670697	

			T.E =	83.073344	
5607	5607				
205		.012000 x	420.000000 =	5.040000	
205		.002400 x	420.000000 =	1.008000	
003		2.500000 x	24.769248 =	61.923120	
002		2.500000 x	18.705943 =	46.764858	
242		.440000 x	1.300000 =	.572000	
242		2.200000 x	1.300000 =	2.860000	

			T.E =	118.167978	
5608.1	5608.1				
205		.012000 x	420.000000 =	5.040000	
003		3.500000 x	24.769248 =	86.692368	
002		3.500000 x	18.705943 =	65.470801	
205		.002400 x	420.000000 =	1.008000	
222.1		.006000 x	.000000 =	.000000	
222.1		.001200 x	.000000 =	.000000	

			T.E =		
5608.2	5608.2				
205		.012000 x	420.000000 =	5.040000	
205		.002400 x	420.000000 =	1.008000	
003		3.500000 x	24.769248 =	86.692368	
002		3.500000 x	18.705943 =	65.470801	
223.1		.006000 x	1,700.000000 =	10.200000	
223.1		.001200 x	1,700.000000 =	2.040000	

			T.E =	170.451169	

5611	5611			
205		.060000 x	420.000000 =	25.200000
002		7.000000 x	18.705943 =	130.941601
003		7.000000 x	24.769248 =	173.384736
251		5.000000 x	.680000 =	3.400000

			T.E =	332.926337
5612.1	5612.1			
205		.060000 x	420.000000 =	25.200000
251		5.000000 x	.680000 =	3.400000
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601
222.1		.006000 x	.000000 =	.000000

			T.E =	
5612.2	5612.2			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601
251		5.000000 x	.680000 =	3.400000
223.1		.006000 x	1,700.000000 =	10.200000

			T.E =	343.126337
5613.1	5613.1			
205		.015000 x	420.000000 =	6.300000
205		.001500 x	420.000000 =	.630000
003		1.500000 x	24.769248 =	37.153872
002		1.500000 x	18.705943 =	28.058915
222.2		.003000 x	.000000 =	.000000

			T.E =	
5613.2	5613.2			
205		.015000 x	420.000000 =	6.300000
002		1.500000 x	18.705943 =	28.058915
003		1.500000 x	24.769248 =	37.153872
205		.001500 x	420.000000 =	.630000
223.2		.003000 x	1,450.000000 =	4.350000

			T.E =	76.492787
5614.1	5614.1			
205		.010000 x	420.000000 =	4.200000
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132
222.2		.002000 x	.000000 =	.000000
205		.001500 x	420.000000 =	.630000

			T.E =	

5614.2	5614.2			
205		.010000 x	420.000000 =	4.200000
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132
223.2		.002000 x	1,450.000000 =	2.900000
205		.001500 x	420.000000 =	.630000

			T.E =	59.900229
5615.1	5615.1			
205		.008000 x	420.000000 =	3.360000
205		.001440 x	420.000000 =	.604800
222.2		.000900 x	.000000 =	.000000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943

			T.E =	
5615.2	5615.2			
205		.008000 x	420.000000 =	3.360000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
223.2		.000900 x	1,450.000000 =	1.305000
205		.001440 x	420.000000 =	.604800

			T.E =	48.744991
5616	5616			
205		.003000 x	420.000000 =	1.260000
205		.007500 x	420.000000 =	3.150000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943

			T.E =	47.885191
5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
521		.250000 x	2.390000 =	.597500

			T.E =	48.472691
5619	5619			
205		.001400 x	420.000000 =	.588000
003		.200000 x	24.769248 =	4.953850

			T.E =	5.541850

5620	5620			
203.2		.012000 x	335.000000 =	4.020000
003		.300000 x	24.769248 =	7.430774
002		.300000 x	18.705943 =	5.611783
251		.020000 x	.680000 =	.013600
220		4.200000 x	.000000 =	.000000

			T.E =	
5621	5621			
210		1.100000 x	.000000 =	.000000
002		30.000000 x	18.705943 =	561.178290
003		30.000000 x	24.769248 =	743.077440
251		16.000000 x	.680000 =	10.880000

			T.E =	
5622	5622			
211		1.100000 x	.000000 =	.000000
251		16.000000 x	.680000 =	10.880000
003		30.000000 x	24.769248 =	743.077440
002		30.000000 x	18.705943 =	561.178290

			T.E =	
5626	5626			
205		.030000 x	420.000000 =	12.600000
251		1.000000 x	.680000 =	.680000
003		1.500000 x	24.769248 =	37.153872
002		1.500000 x	18.705943 =	28.058915

			T.E =	78.492787
6101	6101			
267		1.050000 x	.726500 =	.762825
003		.050000 x	24.769248 =	1.238462

			T.E =	2.001287
6102	6102			
252		.050000 x	1.750000 =	.087500
267		1.030000 x	.726500 =	.748295
003		.060000 x	24.769248 =	1.486155

			T.E =	2.321950
6103	6103			
268		1.050000 x	.836500 =	.878325
003		.050000 x	24.769248 =	1.238462

			T.E =	2.116787

6104	6104				
252		.050000 x	1.750000 =	.087500	
268		1.030000 x	.836500 =	.861595	
003		.060000 x	24.769248 =	1.486155	

				T.E =	2.435250
6111	6111				
266		1.100000 x	.563000 =	.619300	
003		.150000 x	24.769248 =	3.715387	

				T.E =	4.334687
6116	6116				
280		1.050000 x	1.000000 =	1.050000	
003		.100000 x	24.769248 =	2.476925	

				T.E =	3.526925
6117	6117				
281		1.050000 x	5.780000 =	6.069000	
003		.150000 x	24.769248 =	3.715387	

				T.E =	9.784387
6118	6118				
266		1.150000 x	.563000 =	.647450	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	

				T.E =	9.342488
6119	6119				
293		1.100000 x	.000000 =	.000000	
003		.150000 x	24.769248 =	3.715387	

				T.E =	
6120	6120				
289		1.050000 x	.707000 =	.742350	
003		.100000 x	24.769248 =	2.476925	

				T.E =	3.219275
6121	6121				
266		1.100000 x	.563000 =	.619300	
002		.200000 x	18.705943 =	3.741189	
003		.200000 x	24.769248 =	4.953850	

				T.E =	9.314338

6122	6122			
265		1.050000 x	.676500 =	.710325
003		.200000 x	24.769248 =	4.953850

			T.E =	5.664175
6123	6123			
265		.900000 x	.676500 =	.608850
002		.150000 x	18.705943 =	2.805891
003		.150000 x	24.769248 =	3.715387
265		.090000 x	.676500 =	.060885
266		.010000 x	.563000 =	.005630
266		.100000 x	.563000 =	.056300

			T.E =	7.252944
6126	6126			
265		1.250000 x	.676500 =	.845625
003		.200000 x	24.769248 =	4.953850
003		.200000 x	24.769248 =	4.953850

			T.E =	10.753324
6127	6127			
290		4.800000 x	3.300000 =	15.840000
002		.800000 x	18.705943 =	14.964754
003		.800000 x	24.769248 =	19.815398

			T.E =	50.620153
6128	6128			
290		1.200000 x	3.300000 =	3.960000
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850

			T.E =	12.655038
6201	6201			
264		1.400000 x	1.026200 =	1.436680
003		.250000 x	24.769248 =	6.192312
002		.250000 x	18.705943 =	4.676486

			T.E =	12.305478
6202	6202			
264		1.300000 x	1.026200 =	1.334060
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850

			T.E =	10.029098

6203	6203			
282		1.200000 x	.766500 =	.919800
002		.350000 x	18.705943 =	6.547080
003		.350000 x	24.769248 =	8.669237

			T.E =	16.136117
6204	6204			
282		1.300000 x	.766500 =	.996450
002		.400000 x	18.705943 =	7.482377
003		.400000 x	24.769248 =	9.907699

			T.E =	18.386526
6205	6205			
277		1.250000 x	.781500 =	.976875
003		.500000 x	24.769248 =	12.384624
002		.500000 x	18.705943 =	9.352972

			T.E =	22.714471
6221	6221			
265		1.150000 x	.676500 =	.777975
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189

			T.E =	9.473013
6222	6222			
265		1.200000 x	.676500 =	.811800
003		.350000 x	24.769248 =	8.669237
002		.350000 x	18.705943 =	6.547080

			T.E =	16.028117
6223	6223			
265		1.250000 x	.676500 =	.845625
003		.500000 x	24.769248 =	12.384624
002		.500000 x	18.705943 =	9.352972

			T.E =	22.583221
6224	6224			
271		.720000 x	.766500 =	.551880
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850
282		.480000 x	.766500 =	.367920

			T.E =	9.614838

6225	6225			
271		.720000 x	.766500 =	.551880
003		.250000 x	24.769248 =	6.192312
002		.250000 x	18.705943 =	4.676486
282		.480000 x	.766500 =	.367920

			T.E =	11.788598
6226	6226			
265		1.200000 x	.676500 =	.811800
003		.700000 x	24.769248 =	17.338474
002		.700000 x	18.705943 =	13.094160

			T.E =	31.244434
6227	6227			
265		1.250000 x	.676500 =	.845625
003		.850000 x	24.769248 =	21.053861
002		.850000 x	18.705943 =	15.900052

			T.E =	37.799537
6228	6228			
282		1.250000 x	.766500 =	.958125
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377

			T.E =	18.348201
6229	6229			
282		1.250000 x	.766500 =	.958125
002		.450000 x	18.705943 =	8.417674
003		.450000 x	24.769248 =	11.146162

			T.E =	20.521961
6230	6230			
277		1.100000 x	.781500 =	.859650
002		.500000 x	18.705943 =	9.352972
003		.500000 x	24.769248 =	12.384624

			T.E =	22.597246
6231	6231			
265		1.150000 x	.676500 =	.777975
002		.250000 x	18.705943 =	4.676486
003		.250000 x	24.769248 =	6.192312

			T.E =	11.646773

6232	6232			
265		1.150000 x	.676500 =	.777975
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377

			T.E =	18.168051
6236	6236			
253		.500000 x	2.200000 =	1.100000
266		2.000000 x	.563000 =	1.126000
386		.350000 x	28.630000 =	10.020500
390		2.100000 x	1.500000 =	3.150000
003		1.800000 x	24.769248 =	44.584646
002		1.800000 x	18.705943 =	33.670697
565.3		.350000 x	3.100000 =	1.085000
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
276		5.850000 x	.602400 =	3.524040
272		1.500000 x	.696500 =	1.044750

			T.E =	125.135634
6237	6237			
253		.850000 x	2.200000 =	1.870000
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
565.5		.350000 x	4.630000 =	1.620500
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	.696500 =	3.482500
266		2.100000 x	.563000 =	1.182300
260		9.500000 x	.511400 =	4.858300

			T.E =	222.764864
6238	6238			
253		.400000 x	2.200000 =	.880000
265		6.000000 x	.676500 =	4.059000
266		13.000000 x	.563000 =	7.319000
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715

			T.E =	229.633955
6239	6239			
277		1.100000 x	.781500 =	.859650
002		.300000 x	18.705943 =	5.611783
003		.300000 x	24.769248 =	7.430774

			T.E =	13.902207

6301	6301			
266		1.250000 x	.563000 =	.703750
002		.400000 x	18.705943 =	7.482377
003		.400000 x	24.769248 =	9.907699

			T.E =	18.093826
6302	6302			
266		9.000000 x	.563000 =	5.067000
002		3.500000 x	18.705943 =	65.470801
003		3.500000 x	24.769248 =	86.692368

			T.E =	157.230169
6401	6401			
265		1.150000 x	.676500 =	.777975
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189

			T.E =	9.473013
6402	6402			
265		1.200000 x	.676500 =	.811800
002		.300000 x	18.705943 =	5.611783
003		.300000 x	24.769248 =	7.430774

			T.E =	13.854357
6403	6403			
265		1.250000 x	.676500 =	.845625
002		.350000 x	18.705943 =	6.547080
003		.350000 x	24.769248 =	8.669237

			T.E =	16.061942
6406	6406			
265		1.200000 x	.676500 =	.811800
002		.600000 x	18.705943 =	11.223566
003		.600000 x	24.769248 =	14.861549

			T.E =	26.896915
6407	6407			
265		1.250000 x	.676500 =	.845625
003		.700000 x	24.769248 =	17.338474
002		.700000 x	18.705943 =	13.094160

			T.E =	31.278259

6411	6411				
565.3		1.650000 x	3.100000 =	5.115000	
002		.350000 x	18.705943 =	6.547080	
003		.350000 x	24.769248 =	8.669237	

			T.E =	20.331317	
6412	6412				
565.5		1.550000 x	4.630000 =	7.176500	
003		.450000 x	24.769248 =	11.146162	
002		.450000 x	18.705943 =	8.417674	

			T.E =	26.740336	
6413	6413				
565.6		1.450000 x	6.390000 =	9.265500	
002		.550000 x	18.705943 =	10.288269	
003		.550000 x	24.769248 =	13.623086	

			T.E =	33.176855	
6416	6416				
566.3		1.600000 x	4.140000 =	6.624000	
002		.350000 x	18.705943 =	6.547080	
003		.350000 x	24.769248 =	8.669237	

			T.E =	21.840317	
6417	6417				
566.5		1.500000 x	6.340000 =	9.510000	
003		.450000 x	24.769248 =	11.146162	
002		.450000 x	18.705943 =	8.417674	

			T.E =	29.073836	
6418	6418				
566.6		1.400000 x	8.460000 =	11.844000	
002		.550000 x	18.705943 =	10.288269	
003		.550000 x	24.769248 =	13.623086	

			T.E =	35.755355	
6421	6421				
565.3		1.050000 x	3.100000 =	3.255000	
003		.400000 x	24.769248 =	9.907699	

			T.E =	13.162699	

6422	6422				
565.5		1.050000 x	4.630000 =	4.861500	
003		.500000 x	24.769248 =	12.384624	

				T.E =	17.246124
6423	6423				
565.6		1.050000 x	6.390000 =	6.709500	
003		.600000 x	24.769248 =	14.861549	

				T.E =	21.571049
6426	6426				
566.3		1.050000 x	4.140000 =	4.347000	
003		.400000 x	24.769248 =	9.907699	

				T.E =	14.254699
6427	6427				
566.5		1.050000 x	6.340000 =	6.657000	
003		.500000 x	24.769248 =	12.384624	

				T.E =	19.041624
6428	6428				
566.6		1.050000 x	8.460000 =	8.883000	
003		.600000 x	24.769248 =	14.861549	

				T.E =	23.744549
6431	6431				
278		1.100000 x	3.600000 =	3.960000	
003		.150000 x	24.769248 =	3.715387	

				T.E =	7.675387
6432	6432				
251		.100000 x	.680000 =	.068000	
279		1.080000 x	3.720000 =	4.017600	
003		.250000 x	24.769248 =	6.192312	
002		.250000 x	18.705943 =	4.676486	

				T.E =	14.954398
6441	6441				
266		1.100000 x	.563000 =	.619300	
003		.100000 x	24.769248 =	2.476925	
002		.100000 x	18.705943 =	1.870594	

				T.E =	4.966819

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	24.769248 =	.990770

			T.E =	
6446.2	6446.2			
285		1.100000 x	.057500 =	.063250
003		.040000 x	24.769248 =	.990770

			T.E =	1.054020
6447	6447			
251		.050000 x	.680000 =	.034000
002		.100000 x	18.705943 =	1.870594
003		.100000 x	24.769248 =	2.476925
286		1.050000 x	1.562300 =	1.640415

			T.E =	6.021934
6448	6448			
251		.050000 x	.680000 =	.034000
003		.100000 x	24.769248 =	2.476925
002		.100000 x	18.705943 =	1.870594
288		1.050000 x	1.695700 =	1.780485

			T.E =	6.162004
6501	6501			
282		3.000000 x	.766500 =	2.299500
002		4.000000 x	18.705943 =	74.823772
003		4.000000 x	24.769248 =	99.076992
296		1.000000 x	11.781900 =	11.781900
295		11.000000 x	5.649200 =	62.141200

			T.E =	250.123364
6502	6502			
002		1.500000 x	18.705943 =	28.058915
003		1.500000 x	24.769248 =	37.153872
6501		1.000000 x	250.123364 =	250.123364

			T.E =	315.336151
6503	6503			
002		1.300000 x	18.705943 =	24.317726
6501		.950000 x	250.123364 =	237.617196
003		1.300000 x	24.769248 =	32.200022

			T.E =	294.134944

6504	6504			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		.910000 x	250.123364 =	227.612261

			T.E =	279.782490
6505	6505			
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
6501		.870000 x	250.123364 =	217.607327

			T.E =	261.082518
6506	6506			
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
6501		.810000 x	250.123364 =	202.599925

			T.E =	246.075116
6507	6507			
002		.900000 x	18.705943 =	16.835349
6501		.920000 x	250.123364 =	230.113495
003		.900000 x	24.769248 =	22.292323

			T.E =	269.241167
6508	6508			
002		1.300000 x	18.705943 =	24.317726
6501		1.030000 x	250.123364 =	257.627065
003		1.300000 x	24.769248 =	32.200022

			T.E =	314.144813
6509	6509			
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
6501		1.010000 x	250.123364 =	252.624598

			T.E =	296.099789
6510	6510			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.080000 x	250.123364 =	270.133233

			T.E =	322.303462

6511	6511			
002		1.500000 x	18.705943 =	28.058915
003		1.500000 x	24.769248 =	37.153872
6501		.920000 x	250.123364 =	230.113495

			T.E =	295.326281
6512	6512			
002		1.400000 x	18.705943 =	26.188320
6501		.820000 x	250.123364 =	205.101158
003		1.400000 x	24.769248 =	34.676947

			T.E =	265.966426
6513	6513			
002		1.300000 x	18.705943 =	24.317726
003		1.300000 x	24.769248 =	32.200022
6501		.780000 x	250.123364 =	195.096224

			T.E =	251.613972
6514	6514			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		.760000 x	250.123364 =	190.093757

			T.E =	242.263986
6515	6515			
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
6501		.800000 x	250.123364 =	200.098691

			T.E =	243.573882
6516	6516			
002		1.300000 x	18.705943 =	24.317726
6501		1.220000 x	250.123364 =	305.150504
003		1.300000 x	24.769248 =	32.200022

			T.E =	361.668252
6517	6517			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.120000 x	250.123364 =	280.138168

			T.E =	332.308397

6518	6518			
002		1.100000 x	18.705943 =	20.576537
003		1.100000 x	24.769248 =	27.246173
6501		.670000 x	250.123364 =	167.582654

			T.E =	215.405364
6519	6519			
002		1.300000 x	18.705943 =	24.317726
003		1.300000 x	24.769248 =	32.200022
6501		1.280000 x	250.123364 =	320.157906

			T.E =	376.675654
6520	6520			
002		1.200000 x	18.705943 =	22.447132
6501		1.120000 x	250.123364 =	280.138168
003		1.200000 x	24.769248 =	29.723098

			T.E =	332.308397
6521	6521			
002		1.300000 x	18.705943 =	24.317726
003		1.300000 x	24.769248 =	32.200022
6501		1.210000 x	250.123364 =	302.649270

			T.E =	359.167019
6522	6522			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.190000 x	250.123364 =	297.646803

			T.E =	349.817032
6523	6523			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.280000 x	250.123364 =	320.157906

			T.E =	372.328135
6524	6524			
002		1.200000 x	18.705943 =	22.447132
6501		.800000 x	250.123364 =	200.098691
003		1.200000 x	24.769248 =	29.723098

			T.E =	252.268920

6525	6525				
002		1.200000 x	18.705943 =	22.447132	
003		1.200000 x	24.769248 =	29.723098	
6501		1.040000 x	250.123364 =	260.128299	

			T.E =	312.298528	
6526	6526				
002		1.300000 x	18.705943 =	24.317726	
003		1.300000 x	24.769248 =	32.200022	
6501		.900000 x	250.123364 =	225.111028	

			T.E =	281.628776	
6527	6527				
002		1.300000 x	18.705943 =	24.317726	
003		1.300000 x	24.769248 =	32.200022	
6501		1.120000 x	250.123364 =	280.138168	

			T.E =	336.655916	
6528	6528				
002		1.200000 x	18.705943 =	22.447132	
6501		.840000 x	250.123364 =	210.103626	
003		1.200000 x	24.769248 =	29.723098	

			T.E =	262.273855	
6529	6529				
002		1.200000 x	18.705943 =	22.447132	
003		1.200000 x	24.769248 =	29.723098	
6501		1.080000 x	250.123364 =	270.133233	

			T.E =	322.303462	
6530	6530				
002		1.000000 x	18.705943 =	18.705943	
003		1.000000 x	24.769248 =	24.769248	
6501		.710000 x	250.123364 =	177.587588	

			T.E =	221.062779	
6531	6531				
002		.600000 x	18.705943 =	11.223566	
003		.600000 x	24.769248 =	14.861549	
6501		.480000 x	250.123364 =	120.059215	

			T.E =	146.144329	

6532	6532				
294		6.000000 x	3.149800 =	18.898800	
003		2.500000 x	24.769248 =	61.923120	
294		.300000 x	3.149800 =	.944940	
002		2.500000 x	18.705943 =	46.764858	
296		1.000000 x	11.781900 =	11.781900	

			T.E =	140.313618	
6541	6541				
282		.350000 x	.766500 =	.268275	
002		.500000 x	18.705943 =	9.352972	
296		.120000 x	11.781900 =	1.413828	
003		.500000 x	24.769248 =	12.384624	
295		1.050000 x	5.649200 =	5.931660	

			T.E =	29.351359	
6542	6542				
295		1.050000 x	5.649200 =	5.931660	
003		.800000 x	24.769248 =	19.815398	
002		.800000 x	18.705943 =	14.964754	
296		.100000 x	11.781900 =	1.178190	

			T.E =	41.890003	
6543	6543				
295		.400000 x	5.649200 =	2.259680	
296		.130000 x	11.781900 =	1.531647	
003		.200000 x	24.769248 =	4.953850	

			T.E =	8.745177	
7101	7101				
201		.000500 x	290.000000 =	.145000	
002		.500000 x	18.705943 =	9.352972	
1445		.010000 x	60.956500 =	.609565	
003		.850000 x	24.769248 =	21.053861	

			T.E =	31.161397	
7102	7102				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	60.956500 =	.609565	
002		.400000 x	18.705943 =	7.482377	
003		.700000 x	24.769248 =	17.338474	

			T.E =	25.575416	

7103	7103				
201		.000500 x	290.000000 =	.145000	
1445		.004000 x	60.956500 =	.243826	
003		.600000 x	24.769248 =	14.861549	
002		.300000 x	18.705943 =	5.611783	

			T.E =	20.862158	
7104	7104				
201		.000500 x	290.000000 =	.145000	
1445		.008000 x	60.956500 =	.487652	
002		.600000 x	18.705943 =	11.223566	
003		1.000000 x	24.769248 =	24.769248	

			T.E =	36.625466	
7111	7111				
201		.000500 x	290.000000 =	.145000	
003		.600000 x	24.769248 =	14.861549	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	16.829739 =	5.048922	

			T.E =	20.845601	
7116	7116				
201		.000500 x	290.000000 =	.145000	
001		.350000 x	16.829739 =	5.890409	
003		.650000 x	24.769248 =	16.100011	
1418		.027000 x	41.286750 =	1.114742	

			T.E =	23.250162	
7121	7121				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	16.829739 =	5.048922	
1445		.027000 x	60.956500 =	1.645826	
003		.800000 x	24.769248 =	19.815398	

			T.E =	26.655146	
7122	7122				
201		.000500 x	290.000000 =	.145000	
1444		.027000 x	74.687500 =	2.016563	
003		.800000 x	24.769248 =	19.815398	
001		.300000 x	16.829739 =	5.048922	

			T.E =	27.025883	

7123	7123				
201		.000500 x	290.000000 =		.145000
1462		.015000 x	84.531250 =		1.267969
1446		.006000 x	52.110500 =		.312663
001		.300000 x	16.829739 =		5.048922
003		.900000 x	24.769248 =		22.292323
1445		.006000 x	60.956500 =		.365739
				T.E =	29.432616
7124.1	7124.1				
201		.000500 x	290.000000 =		.145000
1465		.015000 x	90.840150 =		1.362602
001		.300000 x	16.829739 =		5.048922
1445		.012000 x	60.956500 =		.731478
003		.900000 x	24.769248 =		22.292323
				T.E =	29.580325
7124.2	7124.2				
201		.000500 x	290.000000 =		.145000
001		.300000 x	16.829739 =		5.048922
1445		.012000 x	60.956500 =		.731478
1466		.015000 x	88.903950 =		1.333559
003		.900000 x	24.769248 =		22.292323
				T.E =	29.551282
7124.3	7124.3				
201		.000500 x	290.000000 =		.145000
1467		.015000 x	84.386150 =		1.265792
1445		.012000 x	60.956500 =		.731478
003		.900000 x	24.769248 =		22.292323
001		.300000 x	16.829739 =		5.048922
				T.E =	29.483515
7131	7131				
201		.000500 x	290.000000 =		.145000
1426		.006000 x	152.456250 =		.914738
1413		.021000 x	29.264100 =		.614546
001		.300000 x	16.829739 =		5.048922
003		.600000 x	24.769248 =		14.861549
				T.E =	21.584754

7132	7132				
201		.000500 x	290.000000 =		.145000
1427		.006000 x	162.974700 =		.977848
001		.350000 x	16.829739 =		5.890409
1418		.021000 x	41.286750 =		.867022
003		.650000 x	24.769248 =		16.100011

			T.E =		23.980290
7133	7133				
201		.000500 x	290.000000 =		.145000
1463		.015000 x	71.937750 =		1.079066
1418		.006000 x	41.286750 =		.247721
001		.350000 x	16.829739 =		5.890409
1427		.006000 x	162.974700 =		.977848
003		.600000 x	24.769248 =		14.861549

			T.E =		23.201592
7134	7134				
201		.000500 x	290.000000 =		.145000
1464		.015000 x	54.771600 =		.821574
1427		.006000 x	162.974700 =		.977848
1418		.006000 x	41.286750 =		.247721
003		.600000 x	24.769248 =		14.861549
001		.350000 x	16.829739 =		5.890409

			T.E =		22.944100
7136	7136				
201		.000500 x	290.000000 =		.145000
001		.250000 x	16.829739 =		4.207435
003		.400000 x	24.769248 =		9.907699
1418		.017000 x	41.286750 =		.701875

			T.E =		14.962009
7138	7138				
201		.000500 x	290.000000 =		.145000
001		.300000 x	16.829739 =		5.048922
1418		.027000 x	41.286750 =		1.114742
003		.800000 x	24.769248 =		19.815398

			T.E =		26.124062
7141	7141				
201		.000500 x	290.000000 =		.145000
001		.400000 x	16.829739 =		6.731896
1445		.027000 x	60.956500 =		1.645826
003		1.000000 x	24.769248 =		24.769248

			T.E =		33.291969

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
003		.650000 x	24.769248 =	16.100011
001		.350000 x	16.829739 =	5.890409

T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
001		.350000 x	16.829739 =	5.890409
003		.650000 x	24.769248 =	16.100011
1421		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849

T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
001		.450000 x	16.829739 =	7.573383
1413		.014000 x	29.264100 =	.409697
003		.600000 x	24.769248 =	14.861549

T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
001		.450000 x	16.829739 =	7.573383
1413		.007000 x	29.264100 =	.204849
1422		.016000 x	.000000 =	.000000
003		.600000 x	24.769248 =	14.861549

T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
1418		.014000 x	41.286750 =	.578015
003		.650000 x	24.769248 =	16.100011
001		.350000 x	16.829739 =	5.890409

T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
001		.350000 x	16.829739 =	5.890409
003		.650000 x	24.769248 =	16.100011
1422		.016000 x	.000000 =	.000000
1427		.007000 x	162.974700 =	1.140823
1418		.007000 x	41.286750 =	.289007

T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
001		.450000 x	16.829739 =	7.573383
003		.700000 x	24.769248 =	17.338474
1447		.014000 x	58.155900 =	.814183
1448		.016000 x	.000000 =	.000000

T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
001		.450000 x	16.829739 =	7.573383
1447		.007000 x	58.155900 =	.407091
1448		.016000 x	.000000 =	.000000
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	24.769248 =	17.338474

T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1453		.020000 x	162.012750 =	3.240255
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	24.769248 =	39.630797
002		1.600000 x	18.705943 =	29.929509
001		.600000 x	16.829739 =	10.097843

T.E =

84.471447

7162	7162			
201		.000800 x	290.000000 =	.232000
001		.600000 x	16.829739 =	10.097843
002		1.600000 x	18.705943 =	29.929509
1458		.020000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	24.769248 =	39.630797

T.E =

7163	7163			
201		.000800 x	290.000000 =	.232000
1454		.020000 x	185.502750 =	3.710055
1445		.022000 x	60.956500 =	1.341043
001		.600000 x	16.829739 =	10.097843
003		1.600000 x	24.769248 =	39.630797
002		1.600000 x	18.705943 =	29.929509

T.E = 84.941247

7164	7164			
201		.000800 x	290.000000 =	.232000
001		.600000 x	16.829739 =	10.097843
003		1.600000 x	24.769248 =	39.630797
1455		.020000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
002		1.600000 x	18.705943 =	29.929509

T.E =

7165	7165			
201		.000800 x	290.000000 =	.232000
1459		.020000 x	202.002750 =	4.040055
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	24.769248 =	39.630797
002		1.600000 x	18.705943 =	29.929509
001		.600000 x	16.829739 =	10.097843

T.E = 85.271247

7166	7166			
201		.000800 x	290.000000 =	.232000
001		.500000 x	16.829739 =	8.414870
003		1.200000 x	24.769248 =	29.723098
1445		.022000 x	60.956500 =	1.341043
1453		.017000 x	162.012750 =	2.754217
002		1.200000 x	18.705943 =	22.447132

T.E = 64.912358

7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	16.829739 =	8.414870
1458		.017000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132

T.E =

7168	7168			
201		.000800 x	290.000000 =	.232000
001		.500000 x	16.829739 =	8.414870
1454		.017000 x	185.502750 =	3.153547
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132

			T.E =	65.311688
7169	7169			
201		.000800 x	290.000000 =	.232000
1455		.017000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132
001		.500000 x	16.829739 =	8.414870

			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
003		1.200000 x	24.769248 =	29.723098
1459		.017000 x	202.002750 =	3.434047
1445		.022000 x	60.956500 =	1.341043
002		1.200000 x	18.705943 =	22.447132
001		.500000 x	16.829739 =	8.414870

			T.E =	65.592188
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	16.829739 =	1.682974

			T.E =	1.885974
7176	7176			
003		1.500000 x	24.769248 =	37.153872

			T.E =	37.153872
7177	7177			
003		1.100000 x	24.769248 =	27.246173

			T.E =	27.246173
7178	7178			
003		.900000 x	24.769248 =	22.292323

			T.E =	22.292323

7179	7179			
003		.500000 x	24.769248 =	12.384624

			T.E =	12.384624
7181	7181			
003		.700000 x	24.769248 =	17.338474

			T.E =	17.338474
7206	7206			
142		26.000000 x	.325000 =	8.450000
1412		.040000 x	27.931800 =	1.117272
002		.300000 x	18.705943 =	5.611783
003		.600000 x	24.769248 =	14.861549

			T.E =	30.040604
7207	7207			
142		26.000000 x	.325000 =	8.450000
1412		.020000 x	27.931800 =	.558636
003		.500000 x	24.769248 =	12.384624
002		.250000 x	18.705943 =	4.676486

			T.E =	26.069746
7208	7208			
142		26.000000 x	.325000 =	8.450000
003		.400000 x	24.769248 =	9.907699
1412		.025000 x	27.931800 =	.698295
002		.200000 x	18.705943 =	3.741189

			T.E =	22.797183
7209	7209			
142		26.000000 x	.325000 =	8.450000
1412		.005000 x	27.931800 =	.139659
003		.300000 x	24.769248 =	7.430774
002		.150000 x	18.705943 =	2.805891

			T.E =	18.826325
7211	7211			
146		15.000000 x	.340000 =	5.100000
1445		.001000 x	60.956500 =	.060957
003		.400000 x	24.769248 =	9.907699
002		.200000 x	18.705943 =	3.741189
283		.075000 x	1.000100 =	.075008

			T.E =	18.884852

7221	7221				
203.2		.001500 x	335.000000 =	.502500	
003		.200000 x	24.769248 =	4.953850	
492		.200000 x	.540000 =	.108000	
002		.150000 x	18.705943 =	2.805891	
506		1.150000 x	1.149500 =	1.321925	
254		.020000 x	2.780000 =	.055600	
			T.E =	9.747766	
7222	7222				
254		.050000 x	2.780000 =	.139000	
003		.250000 x	24.769248 =	6.192312	
002		.150000 x	18.705943 =	2.805891	
506		1.200000 x	1.149500 =	1.379400	
492		.200000 x	.540000 =	.108000	
			T.E =	10.624603	
7223	7223				
254		.050000 x	2.780000 =	.139000	
002		.200000 x	18.705943 =	3.741189	
003		.200000 x	24.769248 =	4.953850	
508		1.200000 x	.860000 =	1.032000	
493		.200000 x	.730000 =	.146000	
			T.E =	10.012038	
7231	7231				
274		1.200000 x	1.062700 =	1.275240	
003		.250000 x	24.769248 =	6.192312	
002		.250000 x	18.705943 =	4.676486	
274		.200000 x	1.062700 =	.212540	
			T.E =	12.356578	
7241	7241				
297.2		.051072 x	.000000 =	.000000	
003		1.400000 x	24.769248 =	34.676947	
002		1.400000 x	18.705943 =	26.188320	
495		.500000 x	.000000 =	.000000	
001		.200000 x	16.829739 =	3.365948	
			T.E =		

7242	7242			
297.2		.057000 x	.000000 =	.000000
002		2.800000 x	18.705943 =	52.376640
003		2.800000 x	24.769248 =	69.353894
001		.200000 x	16.829739 =	3.365948
495		1.000000 x	.000000 =	.000000

			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
251		1.300000 x	.680000 =	.884000

			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
251		1.300000 x	.680000 =	.884000

			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
251		1.300000 x	.680000 =	.884000
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850

			T.E =	
7244	7244			
251		1.200000 x	.680000 =	.816000
273		1.200000 x	.861500 =	1.033800
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943

			T.E =	45.324991
7245	7245			
251		.500000 x	.680000 =	.340000
273		1.200000 x	.861500 =	1.033800
003		.700000 x	24.769248 =	17.338474
002		.700000 x	18.705943 =	13.094160

			T.E =	31.806434

7246	7246			
265		.500000 x	.676500 =	.338250
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
298.1		6.700000 x	4.330000 =	29.011000
			T.E =	72.824441
7301	7301			
096		1.050000 x	.000000 =	.000000
003		.900000 x	24.769248 =	22.292323
1444		.001500 x	74.687500 =	.112031
1445		.025000 x	60.956500 =	1.523913
001		.400000 x	16.829739 =	6.731896
			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
1444		.002000 x	74.687500 =	.149375
1445		.025000 x	60.956500 =	1.523913
003		1.000000 x	24.769248 =	24.769248
001		.500000 x	16.829739 =	8.414870
			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	60.956500 =	1.523913
1444		.001000 x	74.687500 =	.074688
003		2.000000 x	24.769248 =	49.538496
001		1.000000 x	16.829739 =	16.829739
			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
001		.800000 x	16.829739 =	13.463791
1444		.001500 x	74.687500 =	.112031
1445		.025000 x	60.956500 =	1.523913
003		1.600000 x	24.769248 =	39.630797
			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
1445		.004000 x	60.956500 =	.243826
001		.150000 x	16.829739 =	2.524461
1444		.000200 x	74.687500 =	.014938
003		.300000 x	24.769248 =	7.430774
			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1417		.033000 x	39.954450 =	1.318497
001		.600000 x	16.829739 =	10.097843
1445		.005000 x	60.956500 =	.304783
003		2.200000 x	24.769248 =	54.492346

T.E =

7312	7312			
099		1.050000 x	.000000 =	.000000
1445		.005000 x	60.956500 =	.304783
1417		.033000 x	39.954450 =	1.318497
003		1.100000 x	24.769248 =	27.246173
001		.500000 x	16.829739 =	8.414870

T.E =

7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	16.829739 =	6.731896
003		.900000 x	24.769248 =	22.292323
1445		.004000 x	60.956500 =	.243826
1417		.022000 x	39.954450 =	.878998

T.E =

7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	16.829739 =	8.414870
003		2.500000 x	24.769248 =	61.923120
1449		.030000 x	52.690700 =	1.580721

T.E =

7315	7315			
155		1.050000 x	2.481600 =	2.605680
001		.100000 x	16.829739 =	1.682974
1449		.004000 x	52.690700 =	.210763
003		.300000 x	24.769248 =	7.430774

T.E =

7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	52.690700 =	1.317268
1444		.002000 x	74.687500 =	.149375
003		.600000 x	24.769248 =	14.861549
001		.300000 x	16.829739 =	5.048922

T.E =11.930191
28.412113

7317	7317			
163		1.050000 x	6.900000 =	7.245000
001		.300000 x	16.829739 =	5.048922
003		.800000 x	24.769248 =	19.815398
1449		.025000 x	52.690700 =	1.317268
1444		.001500 x	74.687500 =	.112031

			T.E =	33.538619
7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1449		.025000 x	52.690700 =	1.317268
001		.100000 x	16.829739 =	1.682974
1444		.001000 x	74.687500 =	.074688
003		1.300000 x	24.769248 =	32.200022

			T.E =	
7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
001		.100000 x	16.829739 =	1.682974
1444		.001000 x	74.687500 =	.074688
1449		.025000 x	52.690700 =	1.317268
003		1.300000 x	24.769248 =	32.200022

			T.E =	
7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
1449		.025000 x	52.690700 =	1.317268
1444		.001000 x	74.687500 =	.074688
003		1.500000 x	24.769248 =	37.153872
001		.400000 x	16.829739 =	6.731896

			T.E =	
7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
001		.400000 x	16.829739 =	6.731896
1444		.001000 x	74.687500 =	.074688
1449		.025000 x	52.690700 =	1.317268
003		1.500000 x	24.769248 =	37.153872

			T.E =	

7324	7324			
166		1.050000 x	.000000 =	.000000
001		.040000 x	16.829739 =	.673190
1449		.002000 x	52.690700 =	1.05381
1444		.000100 x	74.687500 =	.007469
003		.200000 x	24.769248 =	4.953850

T.E =

7326.1	7326.1			
029		.200000 x	.149900 =	.029980
001		.500000 x	16.829739 =	8.414870
1449		.020000 x	52.690700 =	1.053814
1444		.005000 x	74.687500 =	.373438
003		3.000000 x	24.769248 =	74.307744
173		48.000000 x	.281700 =	13.521600

T.E =

97.701445

7326.2	7326.2			
029		.200000 x	.149900 =	.029980
174		48.000000 x	.000000 =	.000000
003		3.000000 x	24.769248 =	74.307744
1449		.020000 x	52.690700 =	1.053814
1444		.005000 x	74.687500 =	.373438
001		.500000 x	16.829739 =	8.414870

T.E =

7327	7327			
029		.200000 x	.149900 =	.029980
175		95.000000 x	.000000 =	.000000
1449		.020000 x	52.690700 =	1.053814
1444		.007000 x	74.687500 =	.522813
003		4.000000 x	24.769248 =	99.076992
001		.600000 x	16.829739 =	10.097843

T.E =

7328.1	7328.1			
029		.300000 x	.149900 =	.044970
1449		.020000 x	52.690700 =	1.053814
1444		.007000 x	74.687500 =	.522813
003		4.000000 x	24.769248 =	99.076992
001		.700000 x	16.829739 =	11.780817
171		108.000000 x	.000000 =	.000000

T.E =

7328.2 7328.2

029	.300000 x	.149900 =	.044970
172	108.000000 x	.000000 =	.000000
001	.700000 x	16.829739 =	11.780817
1449	.020000 x	52.690700 =	1.053814
1444	.007000 x	74.687500 =	.522813
003	4.000000 x	24.769248 =	99.076992

T.E =

7331 7331

029	1.500000 x	.149900 =	.224850
1449	.020000 x	52.690700 =	1.053814
1444	.005000 x	74.687500 =	.373438
169	54.000000 x	.000000 =	.000000
003	3.500000 x	24.769248 =	86.692368
001	.500000 x	16.829739 =	8.414870

T.E =

7332 7332

029	2.000000 x	.149900 =	.299800
170	108.000000 x	.000000 =	.000000
003	4.500000 x	24.769248 =	111.461616
1449	.020000 x	52.690700 =	1.053814
1444	.005000 x	74.687500 =	.373438
001	.800000 x	16.829739 =	13.463791

T.E =

7333 7333

029	.300000 x	.149900 =	.044970
1449	.020000 x	52.690700 =	1.053814
003	2.500000 x	24.769248 =	61.923120
002	.500000 x	18.705943 =	9.352972
167	1.050000 x	.000000 =	.000000

T.E =

7334 7334

029	.300000 x	.149900 =	.044970
168	1.050000 x	.000000 =	.000000
003	3.000000 x	24.769248 =	74.307744
1449	.020000 x	52.690700 =	1.053814
002	.600000 x	18.705943 =	11.223566

T.E =

7335	7335				
001		.450000 x	16.829739 =	7.573383	
1445		.026000 x	60.956500 =	1.584869	
003		1.000000 x	24.769248 =	24.769248	
1444		.007000 x	74.687500 =	.522813	
			T.E =	34.450312	
7336	7336				
001		.400000 x	16.829739 =	6.731896	
003		.900000 x	24.769248 =	22.292323	
1445		.022000 x	60.956500 =	1.341043	
1444		.006000 x	74.687500 =	.448125	
			T.E =	30.813387	
7337	7337				
001		.350000 x	16.829739 =	5.890409	
003		.800000 x	24.769248 =	19.815398	
1445		.017000 x	60.956500 =	1.036261	
1444		.005000 x	74.687500 =	.373438	
			T.E =	27.115505	
7338	7338				
026		.500000 x	.097700 =	.048850	
001		.300000 x	16.829739 =	5.048922	
1445		.017000 x	60.956500 =	1.036261	
003		.700000 x	24.769248 =	17.338474	
			T.E =	23.472506	
7340	7340				
289		1.100000 x	.707000 =	.777700	
001		.400000 x	16.829739 =	6.731896	
003		1.100000 x	24.769248 =	27.246173	
1445		.026000 x	60.956500 =	1.584869	
1444		.007000 x	74.687500 =	.522813	
			T.E =	36.863450	
7341	7341				
003		.200000 x	24.769248 =	4.953850	
1441		.003000 x	26.561000 =	.079683	
			T.E =	5.033533	
7346	7346				
003		.200000 x	24.769248 =	4.953850	
			T.E =	4.953850	

7347	7347				
001		.200000 x	16.829739 =	3.365948	
003		.500000 x	24.769248 =	12.384624	
1445		.009000 x	60.956500 =	.548609	
1444		.002000 x	74.687500 =	.149375	

			T.E =	16.448555	
7351	7351				
001		.200000 x	16.829739 =	3.365948	
003		.600000 x	24.769248 =	14.861549	
1444		.009000 x	74.687500 =	.672188	

			T.E =	18.899684	
7352	7352				
001		.200000 x	16.829739 =	3.365948	
1444		.012000 x	74.687500 =	.896250	
003		.700000 x	24.769248 =	17.338474	

			T.E =	21.600671	
7355	7355				
001		.150000 x	16.829739 =	2.524461	
1444		.008000 x	74.687500 =	.597500	
003		.600000 x	24.769248 =	14.861549	

			T.E =	17.983510	
7356	7356				
001		.100000 x	16.829739 =	1.682974	
003		.550000 x	24.769248 =	13.623086	
1444		.007000 x	74.687500 =	.522813	

			T.E =	15.828873	
7357	7357				
001		.050000 x	16.829739 =	.841487	
003		.500000 x	24.769248 =	12.384624	
1444		.006000 x	74.687500 =	.448125	

			T.E =	13.674236	
7359	7359				
021		.100000 x	2.670000 =	.267000	
026		20.000000 x	.097700 =	1.954000	
065		.040000 x	13.610000 =	.544400	
003		.900000 x	24.769248 =	22.292323	
002		.900000 x	18.705943 =	16.835349	

			T.E =	41.893072	

7360	7360			
021		.050000 x	2.670000 =	.133500
026		13.000000 x	.097700 =	1.270100
065		.027000 x	13.610000 =	.367470
002		.700000 x	18.705943 =	13.094160
003		.700000 x	24.769248 =	17.338474

			T.E =	32.203704
7361	7361			
021		.050000 x	2.670000 =	.133500
026		14.000000 x	.097700 =	1.367800
346.1		30.000000 x	.057200 =	1.716000
003		1.400000 x	24.769248 =	34.676947
002		1.000000 x	18.705943 =	18.705943
065		.015000 x	13.610000 =	.204150

			T.E =	56.804340
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	24.769248 =	34.676947
002		1.000000 x	18.705943 =	18.705943
348		8.000000 x	.103600 =	.828800
346.1		22.000000 x	.057200 =	1.258400
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.097700 =	1.367800

			T.E =	57.175540
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	24.769248 =	34.676947
002		1.000000 x	18.705943 =	18.705943
348		8.000000 x	.103600 =	.828800
346.2		22.000000 x	.103600 =	2.279200
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.097700 =	1.367800

			T.E =	58.196340
7363	7363			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.097700 =	1.660900
065		.020000 x	13.610000 =	.272200
003		1.600000 x	24.769248 =	39.630797
002		1.200000 x	18.705943 =	22.447132
346.1		35.000000 x	.057200 =	2.002000

			T.E =	66.146528

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.097700 =	1.660900
003		1.600000 x	24.769248 =	39.630797
002		1.200000 x	18.705943 =	22.447132
348		11.000000 x	.103600 =	1.139600
346.1		24.000000 x	.057200 =	1.372800
065		.020000 x	13.610000 =	.272200

			T.E =	66.656928
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
348		11.000000 x	.103600 =	1.139600
003		1.600000 x	24.769248 =	39.630797
002		1.200000 x	18.705943 =	22.447132
346.2		24.000000 x	.103600 =	2.486400
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.097700 =	1.660900

			T.E =	67.770528
7366	7366			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.110500 =	.521105
003		3.000000 x	24.769248 =	74.307744
002		2.000000 x	18.705943 =	37.411886
026		10.000000 x	.097700 =	.977000
346.1		45.000000 x	.057200 =	2.574000

			T.E =	115.925235
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.097700 =	.977000
1446		.010000 x	52.110500 =	.521105
003		3.000000 x	24.769248 =	74.307744
002		2.000000 x	18.705943 =	37.411886
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000

			T.E =	116.621235
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.097700 =	.977000
1446		.010000 x	52.110500 =	.521105
003		3.000000 x	24.769248 =	74.307744
002		2.000000 x	18.705943 =	37.411886
348		15.000000 x	.103600 =	1.554000
346.2		30.000000 x	.103600 =	3.108000

			T.E =	118.013235

7371.1	7371.1					
026	-	14.000000 x	.097700 =	-	1.367800	
7361		1.000000 x	56.804340 =		56.804340	
029		14.000000 x	.149900 =		2.098600	

					T.E =	57.535140
7371.2	7371.2					
026	-	14.000000 x	.097700 =	-	1.367800	
7361		1.000000 x	56.804340 =		56.804340	
028		14.000000 x	.000000 =		.000000	

					T.E =	
7372.1	7372.1					
026	-	14.000000 x	.097700 =	-	1.367800	
029		14.000000 x	.149900 =		2.098600	
7362.1		1.000000 x	57.175540 =		57.175540	

					T.E =	57.906340
7372.2	7372.2					
026	-	14.000000 x	.097700 =	-	1.367800	
028		14.000000 x	.000000 =		.000000	
7362.1		1.000000 x	57.175540 =		57.175540	

					T.E =	
7372.3	7372.3					
026	-	14.000000 x	.097700 =	-	1.367800	
029		14.000000 x	.149900 =		2.098600	
7362.2		1.000000 x	58.196340 =		58.196340	

					T.E =	58.927140
7372.4	7372.4					
026	-	14.000000 x	.097700 =	-	1.367800	
7362.2		1.000000 x	58.196340 =		58.196340	
028		14.000000 x	.000000 =		.000000	

					T.E =	
7373.1	7373.1					
026	-	17.000000 x	.097700 =	-	1.660900	
029		17.000000 x	.149900 =		2.548300	
7363		1.000000 x	66.146528 =		66.146528	

					T.E =	67.033928

7373.2	7373.2					
026	-	17.000000 x	.097700 =	-	1.660900	
7363		1.000000 x	66.146528 =		66.146528	
028		17.000000 x	.000000 =		.000000	

			T.E =			
7374.1	7374.1					
026	-	17.000000 x	.097700 =	-	1.660900	
029		17.000000 x	.149900 =		2.548300	
7364.1		1.000000 x	66.656928 =		66.656928	

			T.E =		67.544328	
7374.2	7374.2					
026	-	17.000000 x	.097700 =	-	1.660900	
028		17.000000 x	.000000 =		.000000	
7364.1		1.000000 x	66.656928 =		66.656928	

			T.E =			
7374.3	7374.3					
026	-	17.000000 x	.097700 =	-	1.660900	
7364.2		1.000000 x	67.770528 =		67.770528	
029		17.000000 x	.149900 =		2.548300	

			T.E =		68.657928	
7374.4	7374.4					
026	-	17.000000 x	.097700 =	-	1.660900	
028		17.000000 x	.000000 =		.000000	
7364.2		1.000000 x	67.770528 =		67.770528	

			T.E =			
7376.1	7376.1					
026	-	10.000000 x	.097700 =	-	.977000	
029		10.000000 x	.149900 =		1.499000	
7366		1.000000 x	115.925235 =		115.925235	

			T.E =		116.447235	
7376.2	7376.2					
026	-	10.000000 x	.097700 =	-	.977000	
028		10.000000 x	.000000 =		.000000	
7366		1.000000 x	115.925235 =		115.925235	

			T.E =			

7377.1	7377.1					
026	-	10.000000 x	.097700 =	-	.977000	
7367.1		1.000000 x	116.621235 =		116.621235	
029		10.000000 x	.149900 =		1.499000	

						T.E = 117.143235
7377.2	7377.2					
026	-	10.000000 x	.097700 =	-	.977000	
028		10.000000 x	.000000 =		.000000	
7367.1		1.000000 x	116.621235 =		116.621235	

						T.E =
7377.3	7377.3					
026	-	10.000000 x	.097700 =	-	.977000	
029		10.000000 x	.149900 =		1.499000	
7367.2		1.000000 x	118.013235 =		118.013235	

						T.E = 118.535235
7377.4	7377.4					
026	-	10.000000 x	.097700 =	-	.977000	
028		10.000000 x	.000000 =		.000000	
7367.2		1.000000 x	118.013235 =		118.013235	

						T.E =
7381	7381					
456		.100000 x	1.610000 =		.161000	

						T.E = .161000
7382	7382					
443		.150000 x	1.930000 =		.289500	
003		.300000 x	24.769248 =		7.430774	
447		.050000 x	4.393700 =		.219685	

						T.E = 7.939959
7383	7383					
002		.250000 x	18.705943 =		4.676486	
003		.150000 x	24.769248 =		3.715387	

						T.E = 8.391873
7384	7384					
003		.500000 x	24.769248 =		12.384624	

						T.E = 12.384624

7385	7385			
003		.500000 x	24.769248 =	12.384624

			T.E =	12.384624
7386	7386			
003		.600000 x	24.769248 =	14.861549

			T.E =	14.861549
7387	7387			
261		1.500000 x	.549400 =	.824100
7361		1.100000 x	56.804340 =	62.484774
003		1.000000 x	24.769248 =	24.769248

			T.E =	88.078122
7388	7388			
003		2.500000 x	24.769248 =	61.923120
7361		.600000 x	56.804340 =	34.082604

			T.E =	96.005724
7389.1.1	7389.1.1			
7371.1		.300000 x	57.535140 =	17.260542

			T.E =	17.260542
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	68.657928 =	20.597378

			T.E =	20.597378
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000

			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	57.906340 =	17.371902

			T.E =	17.371902
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	58.927140 =	17.678142

			T.E =	17.678142
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	67.033928 =	20.110178

			T.E =	20.110178
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	67.544328 =	20.263298

			T.E =	20.263298
7389.2.1	7389.2.1			
7371.1		.500000 x	57.535140 =	28.767570

			T.E =	28.767570
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	68.657928 =	34.328964

			T.E =	34.328964

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	57.906340 =	28.953170

			T.E =	28.953170
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	58.927140 =	29.463570

			T.E =	29.463570
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	67.033928 =	33.516964

			T.E =	33.516964
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	67.544328 =	33.772164

			T.E =	33.772164
7391	7391			
003		.250000 x	24.769248 =	6.192312

			T.E =	6.192312

7392	7392				
298.1		1.081080 x	4.330000 =	4.681076	
003		.400000 x	24.769248 =	9.907699	

			T.E =	14.588776	
7393	7393				
294		.347760 x	3.149800 =	1.095374	
003		.300000 x	24.769248 =	7.430774	

			T.E =	8.526149	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	24.769248 =	9.907699	

			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	24.769248 =	7.430774	

			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	18.705943 =	6.547080	
003		.350000 x	24.769248 =	8.669237	

			T.E =	24.216317	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	24.769248 =	17.338474	

			T.E =	25.963474	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
003		.400000 x	24.769248 =	9.907699	
002		.400000 x	18.705943 =	7.482377	

			T.E =	25.778876	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	24.769248 =	6.192312	

			T.E =	7.732312	

7416	7416			
003		.800000 x	24.769248 =	19.815398

			T.E =	19.815398
7417	7417			
003		1.800000 x	24.769248 =	44.584646

			T.E =	44.584646
7418	7418			
003		2.600000 x	24.769248 =	64.400045

			T.E =	64.400045
7419	7419			
003		.800000 x	24.769248 =	19.815398

			T.E =	19.815398
7420	7420			
003		1.200000 x	24.769248 =	29.723098

			T.E =	29.723098
7421	7421			
003		.800000 x	24.769248 =	19.815398

			T.E =	19.815398
7422	7422			
003		.350000 x	24.769248 =	8.669237

			T.E =	8.669237
7431	7431			
332		1.150000 x	88.540000 =	101.821000
1445		.020000 x	60.956500 =	1.219130
003		4.000000 x	24.769248 =	99.076992
1444		.001000 x	74.687500 =	.074688

			T.E =	202.191810
7432	7432			
331		1.150000 x	85.390000 =	98.198500
003		4.400000 x	24.769248 =	108.984691
1445		.020000 x	60.956500 =	1.219130
1444		.001000 x	74.687500 =	.074688

			T.E =	208.477009

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	60.956500 =	1.219130	
003		5.100000 x	24.769248 =	126.323165	
1444		.001000 x	74.687500 =	.074688	

			T.E =	225.815482	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
003		6.100000 x	24.769248 =	151.092413	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	250.584730	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		4.200000 x	24.769248 =	104.030842	

			T.E =	212.062159	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		4.600000 x	24.769248 =	113.938541	

			T.E =	221.969858	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		5.300000 x	24.769248 =	131.277014	

			T.E =	239.308332	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
003		6.300000 x	24.769248 =	156.046262	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	264.077580	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
003		4.500000 x	24.769248 =	111.461616	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	255.320934	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		4.900000 x	24.769248 =	121.369315	

			T.E =	265.228633	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		5.600000 x	24.769248 =	138.707789	

			T.E =	282.567106	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
003		6.600000 x	24.769248 =	163.477037	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	307.336354	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
003		4.900000 x	24.769248 =	121.369315	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	277.625633	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		5.300000 x	24.769248 =	131.277014	

			T.E =	287.533332	

7463	7463				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.000000 x	24.769248 =	148.615488	

			T.E =	304.871806	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
003		7.000000 x	24.769248 =	173.384736	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	329.641054	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
003		.915000 x	24.769248 =	22.663862	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	

			T.E =	32.613094	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	
003		.945000 x	24.769248 =	23.406939	

			T.E =	34.210071	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
003		.990000 x	24.769248 =	24.521556	
1444		.000100 x	74.687500 =	.007469	
1445		.002000 x	60.956500 =	.121913	

			T.E =	38.907487	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
003		1.050000 x	24.769248 =	26.007710	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	

			T.E =	41.633342	

7496	7496			
331		.057500 x	85.390000 =	4.909925
003		.488000 x	24.769248 =	12.087393
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734

			T.E =	17.062009
7497	7497			
331		.062500 x	85.390000 =	5.336875
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734
003		.504000 x	24.769248 =	12.483701

			T.E =	17.885267
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	24.769248 =	13.078163
1444		.000050 x	74.687500 =	.003734
1445		.001000 x	60.956500 =	.060957

			T.E =	20.271129
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	24.769248 =	13.870779
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734

			T.E =	21.683595
7501	7501			
7433		1.000000 x	225.815482 =	225.815482

			T.E =	225.815482
7503	7503			
7443		1.000000 x	239.308332 =	239.308332

			T.E =	239.308332
7506	7506			
7453		1.000000 x	282.567106 =	282.567106

			T.E =	282.567106
7508	7508			
7463		1.000000 x	304.871806 =	304.871806

			T.E =	304.871806

7511	7511				
331		.115000 x	85.390000 =	9.819850	
003		.915000 x	24.769248 =	22.663862	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	

			T.E =	32.613094	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	
003		.945000 x	24.769248 =	23.406939	

			T.E =	34.210071	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	24.769248 =	141.184714	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	240.602344	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
003		4.800000 x	24.769248 =	118.892390	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	218.310020	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
003		6.100000 x	24.769248 =	151.092413	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	259.049043	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
003		5.000000 x	24.769248 =	123.846240	

			T.E =	231.802870	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	24.769248 =	128.800090	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	231.840220	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
003		5.400000 x	24.769248 =	133.753939	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	245.648069	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	24.769248 =	141.184714	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	295.158344	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	60.956500 =	1.219130	
003		6.100000 x	24.769248 =	151.092413	

			T.E =	318.349043	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
003		3.000000 x	24.769248 =	74.307744	
1445		.010000 x	60.956500 =	.609565	

			T.E =	114.766309	
7537	7537				
336		.300000 x	.000000 =	.000000	
003		4.000000 x	24.769248 =	99.076992	
1445		.010000 x	60.956500 =	.609565	

			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
1445		.010000 x	60.956500 =	.609565	
003		3.700000 x	24.769248 =	91.646218	
334		.350000 x	132.830000 =	46.490500	

			T.E =	153.798083	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
1445		.010000 x	60.956500 =	.609565	
003		4.200000 x	24.769248 =	104.030842	
336		.350000 x	.000000 =	.000000	

			T.E =		

7543	7543			
332		.170000 x	88.540000 =	15.051800
338		.350000 x	.000000 =	.000000
1445		.010000 x	60.956500 =	.609565
003		4.800000 x	24.769248 =	118.892390

			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	60.956500 =	1.219130
003		7.000000 x	24.769248 =	173.384736

			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
003		7.000000 x	24.769248 =	173.384736
1445		.020000 x	60.956500 =	1.219130

			T.E =	301.897366
7553	7553			
323		1.150000 x	126.500000 =	145.475000
003		7.000000 x	24.769248 =	173.384736
1445		.020000 x	60.956500 =	1.219130

			T.E =	320.078866
7554	7554			
321		1.150000 x	.000000 =	.000000
003		9.000000 x	24.769248 =	222.923232
1445		.020000 x	60.956500 =	1.219130

			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	24.769248 =	222.923232

			T.E =	351.435862
7556	7556			
323		1.150000 x	126.500000 =	145.475000
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	24.769248 =	222.923232

			T.E =	369.617362

7558	7558				
331		.080000 x	85.390000 =	6.831200	
1445		.003000 x	60.956500 =	.182870	
003		1.500000 x	24.769248 =	37.153872	

			T.E =	44.167942	
7559	7559				
331		.080000 x	85.390000 =	6.831200	
1445		.003000 x	60.956500 =	.182870	
003		1.500000 x	24.769248 =	37.153872	

			T.E =	44.167942	
7561	7561				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	24.769248 =	128.800090	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	231.840220	
7562	7562				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	24.769248 =	141.184714	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	295.158344	
7563	7563				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	60.956500 =	1.219130	
003		5.400000 x	24.769248 =	133.753939	

			T.E =	245.648069	
7564	7564				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	60.956500 =	1.219130	
003		6.100000 x	24.769248 =	151.092413	

			T.E =	318.349043	
7565	7565				
003		1.500000 x	24.769248 =	37.153872	

			T.E =	37.153872	
7566	7566				
7561		1.500000 x	231.840220 =	347.760330	

			T.E =	347.760330	

7567	7567			
7562		1.500000 x	295.158344 =	442.737516

			T.E =	442.737516
7568	7568			
7563		1.500000 x	245.648069 =	368.472104

			T.E =	368.472104
7569	7569			
7564		1.500000 x	318.349043 =	477.523565

			T.E =	477.523565
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
003		3.000000 x	24.769248 =	74.307744
327.1		.030000 x	.000000 =	.000000

			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	24.769248 =	74.307744
327.2		.030000 x	.000000 =	.000000

			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
327.3		.030000 x	196.650000 =	5.899500
003		3.000000 x	24.769248 =	74.307744

			T.E =	276.857244
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	24.769248 =	99.076992
328		.030000 x	.000000 =	.000000

			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	24.769248 =	94.123142

			T.E =	192.321642

7577	7577				
334		1.150000 x	132.830000 =	152.754500	
003		4.200000 x	24.769248 =	104.030842	

			T.E =	256.785342	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	24.769248 =	116.415466	

			T.E =		
7581	7581				
326		1.050000 x	63.530000 =	66.706500	
003		2.300000 x	24.769248 =	56.969270	
3211		.020000 x	144.694728 =	2.893895	
1445		.005000 x	60.956500 =	.304783	

			T.E =	126.874447	
7601	7601				
401		1.100000 x	13.560000 =	14.916000	
003		.500000 x	24.769248 =	12.384624	
457		.500000 x	.803800 =	.401900	

			T.E =	27.702524	
7602	7602				
403		1.100000 x	15.880000 =	17.468000	
003		.550000 x	24.769248 =	13.623086	
457		.500000 x	.803800 =	.401900	

			T.E =	31.492986	
7603	7603				
406		1.100000 x	19.630000 =	21.593000	
003		.650000 x	24.769248 =	16.100011	
457		.500000 x	.803800 =	.401900	

			T.E =	38.094911	
7604.1	7604.1				
409		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.750000 x	24.769248 =	18.576936	

			T.E =	44.685836	

7604.2	7604.2			
410		1.100000 x	31.790000 =	34.969000
003		.750000 x	24.769248 =	18.576936
457		.500000 x	.803800 =	.401900

			T.E =	53.947836
7606	7606			
401		1.100000 x	13.560000 =	14.916000
003		.600000 x	24.769248 =	14.861549

			T.E =	29.777549
7607	7607			
403		1.100000 x	15.880000 =	17.468000
003		.650000 x	24.769248 =	16.100011

			T.E =	33.568011
7608	7608			
406		1.100000 x	19.630000 =	21.593000
003		.750000 x	24.769248 =	18.576936

			T.E =	40.169936
7609.1	7609.1			
409		1.100000 x	23.370000 =	25.707000
003		.850000 x	24.769248 =	21.053861

			T.E =	46.760861
7609.2	7609.2			
410		1.100000 x	31.790000 =	34.969000
003		.850000 x	24.769248 =	21.053861

			T.E =	56.022861
7611	7611			
411		1.100000 x	29.680000 =	32.648000
457		.500000 x	.803800 =	.401900
003		.500000 x	24.769248 =	12.384624

			T.E =	45.434524
7612	7612			
412		1.100000 x	32.030000 =	35.233000
003		.550000 x	24.769248 =	13.623086
457		.500000 x	.803800 =	.401900

			T.E =	49.257986

7613	7613				
411		1.100000 x	29.680000 =	32.648000	
003		.600000 x	24.769248 =	14.861549	
			T.E =	47.509549	
7614	7614				
412		1.100000 x	32.030000 =	35.233000	
003		.650000 x	24.769248 =	16.100011	
			T.E =	51.333011	
7616	7616				
414		1.100000 x	23.370000 =	25.707000	
003		.600000 x	24.769248 =	14.861549	
457		.500000 x	.803800 =	.401900	
			T.E =	40.970449	
7617	7617				
415		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	24.769248 =	16.100011	
			T.E =	42.208911	
7618	7618				
414		1.100000 x	23.370000 =	25.707000	
003		.700000 x	24.769248 =	17.338474	
			T.E =	43.045474	
7619	7619				
415		1.100000 x	23.370000 =	25.707000	
003		.750000 x	24.769248 =	18.576936	
			T.E =	44.283936	
7621	7621				
418		1.100000 x	32.720000 =	35.992000	
457		.800000 x	.803800 =	.643040	
003		1.200000 x	24.769248 =	29.723098	
			T.E =	66.358138	
7622	7622				
419		1.100000 x	32.720000 =	35.992000	
003		1.400000 x	24.769248 =	34.676947	
457		.800000 x	.803800 =	.643040	
			T.E =	71.311987	

7626.1	7626.1			
298.2		18.000000 x	3.800000 =	68.400000
002		7.000000 x	18.705943 =	130.941601
003		7.000000 x	24.769248 =	173.384736
421		1.000000 x	108.710000 =	108.710000

			T.E =	481.436337
7626.2	7626.2			
298.2		18.000000 x	3.800000 =	68.400000
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601
422		1.000000 x	149.410000 =	149.410000

			T.E =	522.136337
7627.1	7627.1			
298.2		16.000000 x	3.800000 =	60.800000
421		1.000000 x	108.710000 =	108.710000
003		6.000000 x	24.769248 =	148.615488
002		6.000000 x	18.705943 =	112.235658

			T.E =	430.361146
7627.2	7627.2			
298.2		16.000000 x	3.800000 =	60.800000
003		6.000000 x	24.769248 =	148.615488
002		6.000000 x	18.705943 =	112.235658
422		1.000000 x	149.410000 =	149.410000

			T.E =	471.061146
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	24.769248 =	1.238462

			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	24.769248 =	1.486155

			T.E =	6.315155
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	24.769248 =	1.981540

			T.E =	7.910540

7638	7638			
430		1.100000 x	7.480000 =	8.228000
003		.100000 x	24.769248 =	2.476925

			T.E =	10.704925
7641	7641			
431		1.000000 x	.000000 =	.000000
003		.060000 x	24.769248 =	1.486155

			T.E =	
7642	7642			
432		1.000000 x	.000000 =	.000000
003		.060000 x	24.769248 =	1.486155

			T.E =	
7701	7701			
024		.001500 x	50.000000 =	.075000
003		.120000 x	24.769248 =	2.972310
002		.050000 x	18.705943 =	.935297

			T.E =	3.982607
7702	7702			
024		.001800 x	50.000000 =	.090000
002		.050000 x	18.705943 =	.935297
003		.080000 x	24.769248 =	1.981540

			T.E =	3.006837
7706	7706			
024		.002000 x	50.000000 =	.100000
002		.080000 x	18.705943 =	1.496475
003		.150000 x	24.769248 =	3.715387

			T.E =	5.311863
7707	7707			
024		.002300 x	50.000000 =	.115000
002		.100000 x	18.705943 =	1.870594
003		.090000 x	24.769248 =	2.229232

			T.E =	4.214827

7708	7708			
024		.002500 x	50.000000 =	.125000
003		.180000 x	24.769248 =	4.458465
002		.120000 x	18.705943 =	2.244713

			T.E =	6.828178
7709	7709			
024		.002800 x	50.000000 =	.140000
002		.150000 x	18.705943 =	2.805891
003		.120000 x	24.769248 =	2.972310

			T.E =	5.918201
7711	7711			
002		.050000 x	18.705943 =	.935297
1485		.200000 x	.833049 =	.166610
003		.200000 x	24.769248 =	4.953850

			T.E =	6.055757
7712	7712			
002		.080000 x	18.705943 =	1.496475
1485		.250000 x	.833049 =	.208262
003		.250000 x	24.769248 =	6.192312

			T.E =	7.897050
7713	7713			
002		.160000 x	18.705943 =	2.992951
003		.300000 x	24.769248 =	7.430774
1485		.280000 x	.833049 =	.233254

			T.E =	10.656979
7720	7720			
443		.080000 x	1.930000 =	.154400
003		.300000 x	24.769248 =	7.430774
1485		.200000 x	.833049 =	.166610
002		.100000 x	18.705943 =	1.870594

			T.E =	9.622379
7721	7721			
002		.070000 x	18.705943 =	1.309416
1485		.200000 x	.833049 =	.166610
003		.200000 x	24.769248 =	4.953850

			T.E =	6.429875

7722.1.1	7722.1.1			
7720		.300000 x	9.622379 =	2.886714

			T.E =	2.886714
7722.1.2	7722.1.2			
7721		.300000 x	6.429875 =	1.928963

			T.E =	1.928963
7722.2.1	7722.2.1			
7720		.400000 x	9.622379 =	3.848952

			T.E =	3.848952
7722.2.2	7722.2.2			
7721		.400000 x	6.429875 =	2.571950

			T.E =	2.571950
7725	7725			
471		.300000 x	4.100000 =	1.230000
003		.250000 x	24.769248 =	6.192312
002		.150000 x	18.705943 =	2.805891

			T.E =	10.228203
7735	7735			
441		.350000 x	.075500 =	.026425
003		.150000 x	24.769248 =	3.715387
444		.150000 x	2.143200 =	.321480

			T.E =	4.063292
7736	7736			
441		.500000 x	.075500 =	.037750
446		.005000 x	2.540000 =	.012700
003		.250000 x	24.769248 =	6.192312
444		.085000 x	2.143200 =	.182172
445		.010000 x	1.553500 =	.015535

			T.E =	6.440469
7737	7737			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.873040 =	.174608
1488		.600000 x	.765115 =	.459069
003		.300000 x	24.769248 =	7.430774

			T.E =	8.079551

7738	7738			
441		.200000 x	.075500 =	.015100
003		.300000 x	24.769248 =	7.430774
1488		.300000 x	.765115 =	.229535
1489		.200000 x	.873040 =	.174608

			T.E =	7.850017
7739	7739			
441		.100000 x	.075500 =	.007550
467		.100000 x	3.380000 =	.338000
003		.150000 x	24.769248 =	3.715387

			T.E =	4.060937
7740	7740			
442		.250000 x	.118300 =	.029575
003		.250000 x	24.769248 =	6.192312
1492		.250000 x	2.756980 =	.689245

			T.E =	6.911132
7741	7741			
442		.250000 x	.118300 =	.029575
003		.250000 x	24.769248 =	6.192312
462		.250000 x	.000000 =	.000000

			T.E =	
7742	7742			
442		.250000 x	.118300 =	.029575
463		.125000 x	3.970000 =	.496250
003		.200000 x	24.769248 =	4.953850

			T.E =	5.479675
7743	7743			
442		.250000 x	.118300 =	.029575
464		.125000 x	3.720000 =	.465000
003		.150000 x	24.769248 =	3.715387

			T.E =	4.209962
7744	7744			
442		.250000 x	.118300 =	.029575
465		.125000 x	5.870000 =	.733750
003		.150000 x	24.769248 =	3.715387

			T.E =	4.478712

7745	7745			
442		.250000 x	.118300 =	.029575
1492		.250000 x	2.756980 =	.689245
1489		.200000 x	.873040 =	.174608
003		.800000 x	24.769248 =	19.815398

			T.E =	20.708826
7746	7746			
441		.350000 x	.075500 =	.026425
003		.150000 x	24.769248 =	3.715387
443		.090000 x	1.930000 =	.173700

			T.E =	3.915512
7747	7747			
441		.350000 x	.075500 =	.026425
003		.250000 x	24.769248 =	6.192312
443		.170000 x	1.930000 =	.328100

			T.E =	6.546837
7748	7748			
443		.090000 x	1.930000 =	.173700
445		.030000 x	1.553500 =	.046605
450		.060000 x	2.760000 =	.165600
002		.100000 x	18.705943 =	1.870594
003		.200000 x	24.769248 =	4.953850

			T.E =	7.210349
7749	7749			
443		.160000 x	1.930000 =	.308800
450		.100000 x	2.760000 =	.276000
445		.050000 x	1.553500 =	.077675
003		.250000 x	24.769248 =	6.192312
002		.150000 x	18.705943 =	2.805891

			T.E =	9.660678
7751	7751			
003		.150000 x	24.769248 =	3.715387
1491		.125000 x	1.488894 =	.186112

			T.E =	3.901499
7752	7752			
003		.250000 x	24.769248 =	6.192312
1491		.250000 x	1.488894 =	.372224

			T.E =	6.564536

7753	7753			
441		1.000000 x	.075500 =	.075500
003		.650000 x	24.769248 =	16.100011
443		.080000 x	1.930000 =	.154400
1490		.090000 x	1.546426 =	.139178
1491		.200000 x	1.488894 =	.297779

			T.E =	16.766868
7754	7754			
441		.800000 x	.075500 =	.060400
003		.800000 x	24.769248 =	19.815398
1491		.200000 x	1.488894 =	.297779
1490		.090000 x	1.546426 =	.139178
1487		.090000 x	.610126 =	.054911

			T.E =	20.367667
7755	7755			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
1491		.200000 x	1.488894 =	.297779
003		1.000000 x	24.769248 =	24.769248

			T.E =	25.537719
7756	7756			
442		.300000 x	.118300 =	.035490
003		.350000 x	24.769248 =	8.669237
1492		.300000 x	2.756980 =	.827094

			T.E =	9.531821
7761	7761			
441		.650000 x	.075500 =	.049075
003		.800000 x	24.769248 =	19.815398
1489		.200000 x	.873040 =	.174608
1488		.600000 x	.765115 =	.459069
467		.100000 x	3.380000 =	.338000
473		.100000 x	2.750000 =	.275000

			T.E =	21.111150
7762	7762			
473		.100000 x	2.750000 =	.275000
003		.200000 x	24.769248 =	4.953850

			T.E =	5.228850

7764	7764			
474		.125000 x	3.770000 =	.471250
003		.100000 x	24.769248 =	2.476925

			T.E =	2.948175
7765	7765			
475		.125000 x	6.230000 =	.778750
003		.200000 x	24.769248 =	4.953850

			T.E =	5.732600
7766	7766			
442		.275000 x	.118300 =	.032533
473		.110000 x	2.750000 =	.302500
003		.880000 x	24.769248 =	21.796938
1492		.275000 x	2.756980 =	.758170

			T.E =	22.890140
7767.1	7767.1			
7755		.150000 x	25.537719 =	3.830658

			T.E =	3.830658
7767.2	7767.2			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	24.769248 =	24.769248

			AΘΡΟΙΣΜΑ =	25.789940
	T.E =	.150000 x	25.789940 =	3.868491

7767.3	7767.3			
7755		.250000 x	25.537719 =	6.384430

			T.E =	6.384430
7767.4	7767.4			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	24.769248 =	24.769248

			AΘΡΟΙΣΜΑ =	25.789940
	T.E =	.250000 x	25.789940 =	6.447485

7767.5	7767.5			
7755		.350000 x	25.537719 =	8.938202

			T.E =	8.938202
7767.6	7767.6			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	24.769248 =	24.769248
473		.200000 x	2.750000 =	.550000

			ΑΘΡΟΙΣΜΑ =	25.789940
	T.E =	.350000 x	25.789940 =	9.026479

7767.7	7767.7			
7755		.450000 x	25.537719 =	11.491974

			T.E =	11.491974
7767.8	7767.8			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	24.769248 =	24.769248
473		.200000 x	2.750000 =	.550000

			ΑΘΡΟΙΣΜΑ =	25.789940
	T.E =	.450000 x	25.789940 =	11.605473

7768	7768			
460		.200000 x	4.250000 =	.850000
460		.030000 x	4.250000 =	.127500
003		.450000 x	24.769248 =	11.146162
002		.450000 x	18.705943 =	8.417674

			T.E =	20.541336
7769	7769			
460		.200000 x	4.250000 =	.850000
460		.030000 x	4.250000 =	.127500
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850

			T.E =	9.672538
7770	7770			
460		.090000 x	4.250000 =	.382500
460		.020000 x	4.250000 =	.085000
003		.150000 x	24.769248 =	3.715387
002		.150000 x	18.705943 =	2.805891

			T.E =	6.988779

7771	7771				
441		1.000000 x	.075500 =	.075500	
1488		.160000 x	.765115 =	.122418	
1487		.080000 x	.610126 =	.048810	
003		1.300000 x	24.769248 =	32.200022	
473		.100000 x	2.750000 =	.275000	
467		.110000 x	3.380000 =	.371800	

			T.E =	33.093551	
7772	7772				
441		1.000000 x	.075500 =	.075500	
003		.500000 x	24.769248 =	12.384624	
443		.100000 x	1.930000 =	.193000	
458		.100000 x	5.030000 =	.503000	

			T.E =	13.156124	
7773	7773				
441		1.000000 x	.075500 =	.075500	
443		.100000 x	1.930000 =	.193000	
459		.100000 x	5.030000 =	.503000	
003		.600000 x	24.769248 =	14.861549	

			T.E =	15.633049	
7774	7774				
442		.250000 x	.118300 =	.029575	
473		.200000 x	2.750000 =	.550000	
003		1.000000 x	24.769248 =	24.769248	
1492		.160000 x	2.756980 =	.441117	

			T.E =	25.789940	
7785.1	7785.1				
441		.350000 x	.075500 =	.026425	
476		.120000 x	2.366400 =	.283968	
477		.160000 x	.000000 =	.000000	
003		.700000 x	24.769248 =	17.338474	

			T.E =		
7785.2	7785.2				
441		.350000 x	.075500 =	.026425	
476		.120000 x	2.366400 =	.283968	
003		.700000 x	24.769248 =	17.338474	
478		.160000 x	2.937600 =	.470016	

			T.E =	18.118883	

7786.1	7786.1			
441		.350000 x	.075500 =	.026425
1488		.600000 x	.765115 =	.459069
1489		.200000 x	.873040 =	.174608
477		.110000 x	.000000 =	.000000
003		1.000000 x	24.769248 =	24.769248

			T.E =	
7786.2	7786.2			
441		.350000 x	.075500 =	.026425
1488		.600000 x	.765115 =	.459069
1489		.200000 x	.873040 =	.174608
003		1.000000 x	24.769248 =	24.769248
478		.110000 x	2.937600 =	.323136

			T.E =	25.752486
7787	7787			
441		1.000000 x	.075500 =	.075500
1488		.160000 x	.765115 =	.122418
1487		.080000 x	.610126 =	.048810
003		1.000000 x	24.769248 =	24.769248
477		.160000 x	.000000 =	.000000
476		.090000 x	2.366400 =	.212976

			T.E =	
7788	7788			
441		.250000 x	.075500 =	.018875
003		.700000 x	24.769248 =	17.338474
479		1.000000 x	1.815600 =	1.815600

			T.E =	19.172949
7791	7791			
441		1.000000 x	.075500 =	.075500
003		.500000 x	24.769248 =	12.384624
1491		.200000 x	1.488894 =	.297779
1487		.050000 x	.610126 =	.030506

			T.E =	12.788409
7792	7792			
482		.150000 x	.937000 =	.140550
003		.500000 x	24.769248 =	12.384624

			T.E =	12.525174

7793	7793				
480		.500000 x	3.366000 =	1.683000	
003		.200000 x	24.769248 =	4.953850	

				T.E =	6.636850
7794	7794				
482		.150000 x	.937000 =	.140550	
003		.500000 x	24.769248 =	12.384624	

				T.E =	12.525174
7797	7797				
201		.000500 x	290.000000 =	.145000	
002		.060000 x	18.705943 =	1.122357	

				T.E =	1.267357
7798	7798				
201		.000600 x	290.000000 =	.174000	
002		.070000 x	18.705943 =	1.309416	

				T.E =	1.483416
7801	7801				
496		1.200000 x	1.006100 =	1.207320	
003		.150000 x	24.769248 =	3.715387	

				T.E =	4.922707
7806	7806				
498		1.150000 x	1.124000 =	1.292600	
003		.300000 x	24.769248 =	7.430774	

				T.E =	8.723374
7807	7807				
499		1.150000 x	1.540900 =	1.772035	
003		.400000 x	24.769248 =	9.907699	

				T.E =	11.679734
7808	7808				
500		1.150000 x	2.266200 =	2.606130	
003		.600000 x	24.769248 =	14.861549	

				T.E =	17.467679

7809	7809				
501		1.200000 x	3.070000 =		3.684000
003		.800000 x	24.769248 =		19.815398
				T.E =	23.499398
7810	7810				
502		1.200000 x	4.230000 =		5.076000
003		.900000 x	24.769248 =		22.292323
				T.E =	27.368323
7811	7811				
503		1.200000 x	1.006100 =		1.207320
003		.800000 x	24.769248 =		19.815398
				T.E =	21.022718
7812	7812				
504		1.300000 x	1.332400 =		1.732120
003		.900000 x	24.769248 =		22.292323
				T.E =	24.024443
7813	7813				
505		1.000000 x	19.170000 =		19.170000
003		.600000 x	24.769248 =		14.861549
				T.E =	34.031549
7901	7901				
490		1.080000 x	.730000 =		.788400
003		.200000 x	24.769248 =		4.953850
				T.E =	5.742250
7902	7902				
527		1.050000 x	5.120000 =		5.376000
003		1.000000 x	24.769248 =		24.769248
				T.E =	30.145248
7903	7903				
528		1.050000 x	6.910000 =		7.255500
003		.600000 x	24.769248 =		14.861549
				T.E =	22.117049

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	24.769248 =	12.384624

			T.E =	18.138624
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.149500 =	1.264450
002		.300000 x	18.705943 =	5.611783
003		.150000 x	24.769248 =	3.715387

			T.E =	11.467620
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	24.769248 =	3.715387
002		.350000 x	18.705943 =	6.547080

			T.E =	13.206467
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	24.769248 =	3.715387
002		.400000 x	18.705943 =	7.482377

			T.E =	13.019764
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	24.769248 =	1.981540

			T.E =	2.432540
7915.1	7915.1			
7911		.850000 x	11.467620 =	9.747477

			T.E =	9.747477
7915.2	7915.2			
7912		.850000 x	13.206467 =	11.225497

			T.E =	11.225497
7915.3	7915.3			
7913		.850000 x	13.019764 =	11.066799

			T.E =	11.066799

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	18.705943 =	.748238

			T.E =	2.190238
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	18.705943 =	.935297

			T.E =	3.190997
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	18.705943 =	.935297

			T.E =	2.150697
7931	7931			
519		1.050000 x	47.670000 =	50.053500
003		1.500000 x	24.769248 =	37.153872

			T.E =	87.207372
7932.1	7932.1			
514		.000000 x	41.560000 =	.000000
003		.000000 x	24.769248 =	.000000

			T.E =	.000000
7932.2	7932.2			
520		.000000 x	40.000000 =	.000000
003		.000000 x	24.769248 =	.000000

			T.E =	.000000
7933.1	7933.1			
514		.000000 x	41.560000 =	.000000
003		.000000 x	24.769248 =	.000000

			T.E =	.000000
7933.2	7933.2			
520		.000000 x	40.000000 =	.000000
003		.000000 x	24.769248 =	.000000

			T.E =	.000000

7934	7934			
535		1.150000 x	6.000000 =	6.900000
002		.500000 x	18.705943 =	9.352972
003		.500000 x	24.769248 =	12.384624

			T.E =	28.637596
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	24.769248 =	6.192312

			T.E =	6.567312
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	24.769248 =	2.476925

			T.E =	3.226925
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	18.705943 =	5.611783
003		.300000 x	24.769248 =	7.430774
251		.100000 x	.680000 =	.068000

			T.E =	
7941	7941			
067		.040000 x	45.000000 =	1.800000
001		.100000 x	16.829739 =	1.682974

			T.E =	3.482974
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	16.829739 =	1.682974

			T.E =	9.232974