

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

4ο Τρίμηνο του 2009

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

001	Κατχ Τιμή X 1.8117/ 6.46	16.829739
002	Κατχ Τιμή X 1.8117/ 6.46	18.705943
003	Κατχ Τιμή X 1.8117/ 6.46	24.769248
004	Κατχ Τιμή X 1.8117/ 6.67	23.989407
005	Κατχ Τιμή X 1.8117/ 6.67	19.931416
006	(Κατχ Τιμή + Εξαρτ.Τιμή X .8117)	166.700117
007	(Κατχ Τιμή + Εξαρτ.Τιμή X .8117)	166.700117
008	Κατχ Τιμή X 1.8117/ 6.67	19.931416
009		.074800
011		52.580000
012		4.310000
013		26.060000
014		255.610000
015		200.790000
016		31.010000
017		369.270000
018.1		2.840000
018.2		4.310000
019.1		2.840000
019.2		4.310000
021		2.670000
022		.070000
024		50.000000
026		.098900
027		.119300
029		.152800
032		35.000000
035		.116800
036		.119500
040		.203400
051		15.400000
052		15.400000
053		.070000
054		.080000
055		.090000
056		10.580000
057		10.580000
058		9.090000
061		13.560000
062		13.560000
065		13.610000
066		35.000000
067		45.000000
081		11.010000
101		
102		
111		.078400
112		.087900
113		.570000
114		
116		.090300
117		
118		
124		5.900000
127		83.240000
128		90.430000
131		.650000
132		.930000
142		.325000



146	.340000
155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.281700
181	
201	290.000000
203.2	335.000000
203.4	210.000000
205	420.000000
208	1,239.000000
210	
211	
212	1,400.000000
214	
219	3.500000
223.1	1,700.000000
223.2	1,450.000000
223.3	1,135.000000
223.4	1,440.000000
225	4.000000
226	11.500000
227	11.500000
228	35.000000
229	
230	
231	20.000000
232	45.000000
233	21.300000
234	2.700000
236	2.600000
237	1.100000
238	2.600000
240	1.600000
241	
242	1.300000
243.1	2.660000
243.2	3.650000
243.3	4.450000
243.5	6.250000
244	
245	18.600000
246	9.000000
249	19.000000
251	.695000
252	1.785000
253	2.244000
254	2.780000
258	7.515000
259	24.475000
260	.528700
261	.560100
262	.528700
264	1.007900
265	.691500
266	.553000



267	.744000
268	.859000
271	.792500
272	.719000
273	.884000
274	1.090400
276	.618100
277	.806500
278	3.600000
279	3.720000
280	1.000000
281	5.780000
282	.786500
283	1.036900
284	
285	.057500
286	1.626900
288	1.765800
289	.659100
290	3.300000
291	5.000000
293	
294	3.149800
295	5.649200
296	11.781900
297.2	
298.1	4.750000
298.2	4.110000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.668400
352	1.030000
354	.895800
356	.601500
357	1.310300
358	3.035000
360	13.580000
361	1.136300
362	1.270000
363	1.617600
364	1.030000
366	4.545900
370	.267400
371	1.617600



372	2.246200
373	2.486800
375	3.155400
376	.200400
377	.842200
378	13.590000
379	26.780000
380	16.150000
381	67.970000
386	28.630000
388	48.870000
390	1.500000
392	24.930000
401	13.560000
403	15.880000
406	19.630000
409	23.370000
410	31.790000
411	29.680000
412	32.030000
414	23.370000
415	23.370000
418	32.720000
419	32.720000
421	108.710000
422	149.410000
428	4.390000
429	5.390000
430	7.480000
441	.075500
442	.118300
443	1.930000
444	2.143200
445	1.553500
446	2.540000
447	4.393700
450	2.760000
451	1.178800
453	.100000
455	3.000000
456	1.610000
457	.803800
458	5.030000
459	5.030000
460	4.250000
462	
463	3.970000
464	3.720000
465	5.870000
467	3.380000
471	4.100000
473	2.750000
474	3.770000
475	6.230000
476	2.366400
477	
478	2.937600
479	1.815600
480	3.366000





481	5.535000
482	.961300
483	.165000
484	3.490000
485	.826000
487	13.480000
488	5.000000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	1.006100
498	1.124000
499	1.540900
500	2.266200
501	3.070000
502	4.230000
503	1.006100
504	1.332400
505	19.170000
506	1.149500
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.375000
514	41.560000
515	41.230000
519	47.670000
520	40.000000
521	2.390000
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.000000
536	2.500000
537	1.700000
565.3	3.450000
565.5	5.150000
565.6	7.100000
566.3	4.600000
566.5	7.050000
566.6	9.400000

1101	1101				
001		.500000 x	16.829739 =		8.414870
		-----			
			B.T =		8.414870
1102	1102				
001		1.000000 x	16.829739 =		16.829739
		-----			
			B.T =		16.829739
1103	1103				
001		.300000 x	16.829739 =		5.048922
		-----			
			B.T =		5.048922
1104	1104				
015		1.000000 x	200.790000 =		200.790000
291		2.200000 x	5.000000 =		11.000000
004		7.000000 x	23.989407 =		167.925849
002		7.000000 x	18.705943 =		130.941601
484		5.250000 x	3.490000 =		18.322500
485		83.000000 x	.826000 =		68.558000
		-----			
			AΘΡΟΙΣΜΑ =		597.537950
	B.T =	.004000 x	597.537950 =		2.390152
		-----			
1111	1111				
006		.060000 x	166.700117 =		10.002007
		-----			
			B.T =		10.002007
1112	1112				
006		.090000 x	166.700117 =		15.003011
		-----			
			B.T =		15.003011
1116	1116				
007		.025000 x	166.700117 =		4.167503
		-----			
			B.T =		4.167503
1117	1117				
007		.110000 x	166.700117 =		18.337013
		-----			
			B.T =		18.337013
1121	1121				
009		4.000000 x	.074800 =		.299200
		-----			
			B.T =		.299200

1122	1122			
009		5.000000 x	.074800 =	.374000
		-----		
			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600
		-----		
			B.T =	.149600
1126	1126			
001		.400000 x	16.829739 =	6.731896
		-----		
			B.T =	6.731896
1127	1127			
001		.130000 x	16.829739 =	2.187866
		-----		
			B.T =	2.187866
1128	1128			
006		.024000 x	166.700117 =	4.000803
		-----		
			B.T =	4.000803
1131	1131			
007		.090000 x	166.700117 =	15.003011
		-----		
			B.T =	15.003011
1136	1136			
009		1.000000 x	.074800 =	.074800
		-----		
			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200
		-----		
			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000
		-----		
			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000
				-----
			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000
				-----
			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
1407		.320000 x	37.605000 =	12.033600
				-----
			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.360000 x	37.605000 =	13.537800
				-----
			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100
				-----
			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.098900 =	14.835000
				-----
			B.T =	39.554250
1417	1417			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.098900 =	14.835000
1407		.290000 x	37.605000 =	10.905450
051		.900000 x	15.400000 =	13.860000
				-----
			B.T =	40.134450

1418	1418			
021		.200000 x	2.670000 =	.534000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000
026		150.000000 x	.098900 =	14.835000
		-----		
			B.T =	41.466750
1421	1421			
021		.200000 x	2.670000 =	.534000
051		.540000 x	15.400000 =	8.316000
1407		.540000 x	37.605000 =	20.306700
039		4.000000 x	.000000 =	.000000
		-----		
			B.T =	
1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.116800 =	8.760000
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	15.400000 =	5.082000
039		5.000000 x	.000000 =	.000000
		-----		
			B.T =	
1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000
		-----		
			B.T =	152.456250
1427	1427			
021		.200000 x	2.670000 =	.534000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000
026		150.000000 x	.098900 =	14.835000
		-----		
			B.T =	163.154700
1428	1428			
021		.200000 x	2.670000 =	.534000
051		.200000 x	15.400000 =	3.080000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000
		-----		
			B.T =	126.656000

1429	1429				
021		.200000 x	2.670000 =	.534000	
035		200.000000 x	.116800 =	23.360000	
055		1,200.000000 x	.090000 =	108.000000	
1407		.400000 x	37.605000 =	15.042000	
		-----			
			B.T =	146.936000	
1431	1431				
021		.300000 x	2.670000 =	.801000	
032		.960000 x	35.000000 =	33.600000	
1407		.320000 x	37.605000 =	12.033600	
		-----			
			B.T =	46.434600	
1432	1432				
021		.300000 x	2.670000 =	.801000	
1407		.320000 x	37.605000 =	12.033600	
051		.640000 x	15.400000 =	9.856000	
032		.320000 x	35.000000 =	11.200000	
		-----			
			B.T =	33.890600	
1436	1436				
021		.350000 x	2.670000 =	.934500	
035		1,100.000000 x	.116800 =	128.480000	
		-----			
			B.T =	129.414500	
1437	1437				
021		.200000 x	2.670000 =	.534000	
035		75.000000 x	.116800 =	8.760000	
051		.380000 x	15.400000 =	5.852000	
1407		.620000 x	37.605000 =	23.315100	
		-----			
			B.T =	38.461100	
1441	1441				
021		.800000 x	2.670000 =	2.136000	
026		250.000000 x	.098900 =	24.725000	
		-----			
			B.T =	26.861000	
1442	1442				
021		.250000 x	2.670000 =	.667500	
051		.740000 x	15.400000 =	11.396000	
026		900.000000 x	.098900 =	89.010000	
		-----			
			B.T =	101.073500	

1443	1443				
021		.250000 x	2.670000 =	.667500	
051		.860000 x	15.400000 =	13.244000	
026		700.000000 x	.098900 =	69.230000	
-----					
			B.T =	83.141500	
1444	1444				
021		.250000 x	2.670000 =	.667500	
026		600.000000 x	.098900 =	59.340000	
051		1.000000 x	15.400000 =	15.400000	
-----					
			B.T =	75.407500	
1445	1445				
021		.250000 x	2.670000 =	.667500	
026		450.000000 x	.098900 =	44.505000	
051		1.060000 x	15.400000 =	16.324000	
-----					
			B.T =	61.496500	
1446	1446				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.098900 =	34.615000	
051		1.120000 x	15.400000 =	17.248000	
-----					
			B.T =	52.530500	
1447	1447				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	15.400000 =	15.400000	
026		400.000000 x	.098900 =	39.560000	
-----					
			B.T =	58.635900	
1448	1448				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	15.400000 =	15.400000	
039		5.000000 x	.000000 =	.000000	
026		400.000000 x	.098900 =	39.560000	
-----					
			B.T =	53.110700	
1449	1449				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.098900 =	34.615000	
1407		.040000 x	37.605000 =	1.504200	
051		1.060000 x	15.400000 =	16.324000	
-----					
			B.T =	53.110700	



1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.098900 =	59.340000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.070000 =	105.000000
		-----		
			B.T =	166.887750
1452	1452			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.070000 =	105.000000
1407		.050000 x	37.605000 =	1.880250
029		600.000000 x	.152800 =	91.680000
		-----		
			B.T =	199.227750
1453	1453			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.070000 =	115.500000
026		450.000000 x	.098900 =	44.505000
		-----		
			B.T =	162.552750
1454	1454			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.152800 =	68.760000
053		1,650.000000 x	.070000 =	115.500000
1407		.050000 x	37.605000 =	1.880250
		-----		
			B.T =	186.807750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.070000 =	115.500000
		-----		
			B.T =	186.807750
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.098900 =	59.340000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.080000 =	120.000000
		-----		
			B.T =	181.887750

1457	1457			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.080000 =	120.000000
029		600.000000 x	.152800 =	91.680000
		-----		
			B.T =	214.227750
1458	1458			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.080000 =	132.000000
028		450.000000 x	.000000 =	.000000
		-----		
			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
054		1,650.000000 x	.080000 =	132.000000
1407		.050000 x	37.605000 =	1.880250
029		450.000000 x	.152800 =	68.760000
		-----		
			B.T =	203.307750
1461	1461			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.070000 =	105.000000
1407		.080000 x	37.605000 =	3.008400
026		500.000000 x	.098900 =	49.450000
		-----		
			B.T =	158.125900
1462	1462			
021		.300000 x	2.670000 =	.801000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	41.230000 =	41.230000
051		.100000 x	15.400000 =	1.540000
026		400.000000 x	.098900 =	39.560000
		-----		
			B.T =	85.011250
1463	1463			
021		.300000 x	2.670000 =	.801000
051		.100000 x	15.400000 =	1.540000
1407		.050000 x	37.605000 =	1.880250
515		1.050000 x	41.230000 =	43.291500
026		250.000000 x	.098900 =	24.725000
		-----		
			B.T =	72.237750

1464	1464				
021		.200000 x	2.670000 =	.534000	
519		.600000 x	47.670000 =	28.602000	
1407		.120000 x	37.605000 =	4.512600	
051		.420000 x	15.400000 =	6.468000	
026		150.000000 x	.098900 =	14.835000	
			B.T =	54.951600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.900000 x	47.670000 =	42.903000	
051		.150000 x	15.400000 =	2.310000	
026		450.000000 x	.098900 =	44.505000	
			B.T =	91.380150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	47.670000 =	40.042800	
026		450.000000 x	.098900 =	44.505000	
051		.210000 x	15.400000 =	3.234000	
			B.T =	89.443950	
1467	1467				
021		.200000 x	2.670000 =	.534000	
026		450.000000 x	.098900 =	44.505000	
051		.350000 x	15.400000 =	5.390000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	47.670000 =	33.369000	
			B.T =	84.926150	
1471	1471				
251		1.000000 x	.695000 =	.695000	
351		4.000000 x	.668400 =	2.673600	
358		1.000000 x	3.035000 =	3.035000	
364		2.000000 x	1.030000 =	2.060000	
372		.400000 x	2.246200 =	.898480	
370		6.000000 x	.267400 =	1.604400	
			AΘΡΟΙΣΜΑ =	10.966480	
	B.T =	.476190 x	10.966480 =	5.222128	

1472	1472			
251		.600000 x	.695000 =	.417000
351		2.000000 x	.668400 =	1.336800
361		1.000000 x	1.136300 =	1.136300
363		2.000000 x	1.617600 =	3.235200
372		.300000 x	2.246200 =	.673860
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	9.472760
	B.T =	.666667 x	9.472760 =	6.315176
1473	1473			
251		.500000 x	.695000 =	.347500
354		4.000000 x	.895800 =	3.583200
364		2.000000 x	1.030000 =	2.060000
372		.700000 x	2.246200 =	1.572340
370		4.000000 x	.267400 =	1.069600
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	26.022540
	B.T =	.416667 x	26.022540 =	10.842734
1474	1474			
251		.500000 x	.695000 =	.347500
372		.500000 x	2.246200 =	1.123100
370		4.000000 x	.267400 =	1.069600
366		2.000000 x	4.545900 =	9.091800
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
357		4.000000 x	1.310300 =	5.241200
			AΘΡΟΙΣΜΑ =	31.589500
	B.T =	.416667 x	31.589500 =	13.162302
1475	1475			
251		.300000 x	.695000 =	.208500
379		1.000000 x	26.780000 =	26.780000
371		2.000000 x	1.617600 =	3.235200
376		160.000000 x	.200400 =	32.064000
377		6.000000 x	.842200 =	5.053200
378		1.000000 x	13.590000 =	13.590000
375		2.000000 x	3.155400 =	6.310800
354		3.000000 x	.895800 =	2.687400
			AΘΡΟΙΣΜΑ =	89.929100
	B.T =	.416667 x	89.929100 =	37.470488

1476	1476			
251		.500000 x	.695000 =	.347500
373		.200000 x	2.486800 =	.497360
370		6.000000 x	.267400 =	1.604400
352		3.000000 x	1.030000 =	3.090000
			AΘΡΟΙΣΜΑ =	5.539260
	B.T =	.500000 x	5.539260 =	2.769630
1478	1478			
251		3.000000 x	.695000 =	2.085000
372		.500000 x	2.246200 =	1.123100
356		2.000000 x	.601500 =	1.203000
370		6.000000 x	.267400 =	1.604400
			AΘΡΟΙΣΜΑ =	6.015500
	B.T =	.500000 x	6.015500 =	3.007750
1479	1479			
251		6.000000 x	.695000 =	4.170000
370		12.000000 x	.267400 =	3.208800
381		1.000000 x	67.970000 =	67.970000
			AΘΡΟΙΣΜΑ =	75.348800
	B.T =	.454545 x	75.348800 =	34.249420
1480	1480			
251		8.000000 x	.695000 =	5.560000
381		2.000000 x	67.970000 =	135.940000
370		16.000000 x	.267400 =	4.278400
			AΘΡΟΙΣΜΑ =	145.778400
	B.T =	.227273 x	145.778400 =	33.131494
1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.100000 =	.023000
487		.040000 x	13.480000 =	.539200
451		.230000 x	1.178800 =	.271124
			B.T =	.834659
1487	1487			
443		.120000 x	1.930000 =	.231600
451		.170000 x	1.178800 =	.200396
453		.640000 x	.100000 =	.064000
446		.010000 x	2.540000 =	.025400
445		.060000 x	1.553500 =	.093210
			B.T =	.614606

1488	1488			
444		.170000 x	2.143200 =	.364344
453		.500000 x	.100000 =	.050000
451		.170000 x	1.178800 =	.200396
446		.030000 x	2.540000 =	.076200
445		.050000 x	1.553500 =	.077675
-----				
			B.T =	.768615
1489	1489			
444		.100000 x	2.143200 =	.214320
453		.430000 x	.100000 =	.043000
451		.350000 x	1.178800 =	.412580
446		.020000 x	2.540000 =	.050800
445		.100000 x	1.553500 =	.155350
-----				
			B.T =	.876050
1490	1490			
444		.300000 x	2.143200 =	.642960
445		.100000 x	1.553500 =	.155350
446		.030000 x	2.540000 =	.076200
451		.570000 x	1.178800 =	.671916
-----				
			B.T =	1.546426
1491	1491			
444		.270000 x	2.143200 =	.578664
445		.060000 x	1.553500 =	.093210
451		.650000 x	1.178800 =	.766220
446		.020000 x	2.540000 =	.050800
-----				
			B.T =	1.488894
1492	1492			
444		.200000 x	2.143200 =	.428640
446		.030000 x	2.540000 =	.076200
445		.040000 x	1.553500 =	.062140
455		.730000 x	3.000000 =	2.190000
-----				
			B.T =	2.756980
1501	1501			
011		1.000000 x	52.580000 =	52.580000
012		2.000000 x	4.310000 =	8.620000
005		3.500000 x	19.931416 =	69.759956
005		14.000000 x	19.931416 =	279.039824
485		15.000000 x	.826000 =	12.390000
484		1.750000 x	3.490000 =	6.107500
-----				
			B.T =	428.497280

1502	1502				
013		1.000000 x	26.060000 =	26.060000	
005		3.500000 x	19.931416 =	69.759956	
001		26.000000 x	16.829739 =	437.573214	
482		15.000000 x	.961300 =	14.419500	
484		.900000 x	3.490000 =	3.141000	
		-----			
			B.T =	550.953670	
1503	1503				
014		1.000000 x	255.610000 =	255.610000	
002		2.600000 x	18.705943 =	48.635452	
004		7.000000 x	23.989407 =	167.925849	
484		2.600000 x	3.490000 =	9.074000	
485		44.000000 x	.826000 =	36.344000	
		-----			
			B.T =	517.589301	
1504	1504				
015		1.000000 x	200.790000 =	200.790000	
004		7.000000 x	23.989407 =	167.925849	
002		7.000000 x	18.705943 =	130.941601	
485		83.000000 x	.826000 =	68.558000	
484		5.250000 x	3.490000 =	18.322500	
291		2.200000 x	5.000000 =	11.000000	
		-----			
			B.T =	597.537950	
1505	1505				
016		1.000000 x	31.010000 =	31.010000	
004		7.000000 x	23.989407 =	167.925849	
002		1.750000 x	18.705943 =	32.735400	
485		17.500000 x	.826000 =	14.455000	
484		1.750000 x	3.490000 =	6.107500	
		-----			
			B.T =	252.233749	
1506	1506				
017		1.000000 x	369.270000 =	369.270000	
002		3.500000 x	18.705943 =	65.470801	
484		6.000000 x	3.490000 =	20.940000	
004		7.000000 x	23.989407 =	167.925849	
485		70.000000 x	.826000 =	57.820000	
		-----			
			B.T =	681.426650	
2101	2101				
002		.300000 x	18.705943 =	5.611783	
		-----			
			T.E =	5.611783	

2102	2102			
002		.400000 x	18.705943 =	7.482377
		-----		
			T.E =	7.482377
2103	2103			
002		.400000 x	18.705943 =	7.482377
		-----		
			T.E =	7.482377
2104A	2104A			
002		.900000 x	18.705943 =	16.835349
		-----		
			T.E =	16.835349
2104B	2104B			
002		1.400000 x	18.705943 =	26.188320
		-----		
			T.E =	26.188320
2104E	2104E			
002		2.900000 x	18.705943 =	54.247235
		-----		
			T.E =	54.247235
2104H	2104H			
002		4.400000 x	18.705943 =	82.306149
		-----		
			T.E =	82.306149
2104Z	2104Z			
002		3.900000 x	18.705943 =	72.953178
		-----		
			T.E =	72.953178
2104Γ	2104Γ			
002		1.900000 x	18.705943 =	35.541292
		-----		
			T.E =	35.541292
2104Δ	2104Δ			
002		2.400000 x	18.705943 =	44.894263
		-----		
			T.E =	44.894263
2104ΣΤ	2104ΣΤ			
002		3.400000 x	18.705943 =	63.600206
		-----		
			T.E =	63.600206



2105A	2105A			
002		.900000 x	18.705943 =	16.835349
		-----		
			T.E =	16.835349
2105B	2105B			
002		1.400000 x	18.705943 =	26.188320
		-----		
			T.E =	26.188320
2105E	2105E			
002		2.900000 x	18.705943 =	54.247235
		-----		
			T.E =	54.247235
2105H	2105H			
002		4.400000 x	18.705943 =	82.306149
		-----		
			T.E =	82.306149
2105Z	2105Z			
002		3.900000 x	18.705943 =	72.953178
		-----		
			T.E =	72.953178
2105Γ	2105Γ			
002		1.900000 x	18.705943 =	35.541292
		-----		
			T.E =	35.541292
2105Δ	2105Δ			
002		2.400000 x	18.705943 =	44.894263
		-----		
			T.E =	44.894263
2105ΣΤ	2105ΣΤ			
002		3.400000 x	18.705943 =	63.600206
		-----		
			T.E =	63.600206
2106A	2106A			
002		5.900000 x	18.705943 =	110.365064
		-----		
			T.E =	110.365064
2106B	2106B			
002		7.400000 x	18.705943 =	138.423978
		-----		
			T.E =	138.423978

2106E	2106E			
002		11.900000 x	18.705943 =	222.600722
		-----		
			T.E =	222.600722
2106H	2106H			
002		16.400000 x	18.705943 =	306.777465
		-----		
			T.E =	306.777465
2106I	2106I			
002		19.400000 x	18.705943 =	362.895294
		-----		
			T.E =	362.895294
2106Z	2106Z			
002		14.900000 x	18.705943 =	278.718551
		-----		
			T.E =	278.718551
2106Γ	2106Γ			
002		8.900000 x	18.705943 =	166.482893
		-----		
			T.E =	166.482893
2106Δ	2106Δ			
002		10.400000 x	18.705943 =	194.541807
		-----		
			T.E =	194.541807
2106Θ	2106Θ			
002		17.900000 x	18.705943 =	334.836380
		-----		
			T.E =	334.836380
2106ΣΤ	2106ΣΤ			
002		13.400000 x	18.705943 =	250.659636
		-----		
			T.E =	250.659636
2107A	2107A			
002		5.900000 x	18.705943 =	110.365064
		-----		
			T.E =	110.365064
2107B	2107B			
002		7.400000 x	18.705943 =	138.423978
		-----		
			T.E =	138.423978

2107E	2107E			
002		11.900000 x	18.705943 =	222.600722
		-----		
			T.E =	222.600722
2107H	2107H			
002		16.400000 x	18.705943 =	306.777465
		-----		
			T.E =	306.777465
2107I	2107I			
002		19.400000 x	18.705943 =	362.895294
		-----		
			T.E =	362.895294
2107Z	2107Z			
002		14.900000 x	18.705943 =	278.718551
		-----		
			T.E =	278.718551
2107Γ	2107Γ			
002		8.900000 x	18.705943 =	166.482893
		-----		
			T.E =	166.482893
2107Δ	2107Δ			
002		10.400000 x	18.705943 =	194.541807
		-----		
			T.E =	194.541807
2107Θ	2107Θ			
002		17.900000 x	18.705943 =	334.836380
		-----		
			T.E =	334.836380
2107ΣΤ	2107ΣΤ			
002		13.400000 x	18.705943 =	250.659636
		-----		
			T.E =	250.659636
2108A	2108A			
002		.700000 x	18.705943 =	13.094160
		-----		
			T.E =	13.094160
2108B	2108B			
002		1.600000 x	18.705943 =	29.929509
		-----		
			T.E =	29.929509

2108E	2108E			
002		4.600000 x	18.705943 =	86.047338
		-----		
			T.E =	86.047338
2108H	2108H			
002		7.600000 x	18.705943 =	142.165167
		-----		
			T.E =	142.165167
2108Z	2108Z			
002		6.600000 x	18.705943 =	123.459224
		-----		
			T.E =	123.459224
2108Γ	2108Γ			
002		2.600000 x	18.705943 =	48.635452
		-----		
			T.E =	48.635452
2108Δ	2108Δ			
002		3.600000 x	18.705943 =	67.341395
		-----		
			T.E =	67.341395
2108Θ	2108Θ			
002		8.600000 x	18.705943 =	160.871110
		-----		
			T.E =	160.871110
2108ΣΤ	2108ΣΤ			
002		5.600000 x	18.705943 =	104.753281
		-----		
			T.E =	104.753281
2109	2109			
002		.030000 x	18.705943 =	.561178
1506		.004000 x	681.426650 =	2.725707
1503		.001000 x	517.589301 =	.517589
		-----		
			T.E =	3.804474
2110	2110			
002		.040000 x	18.705943 =	.748238
1501		.005000 x	428.497280 =	2.142486
1506		.004000 x	681.426650 =	2.725707
1503		.001000 x	517.589301 =	.517589
		-----		
			T.E =	6.134020

2111	2111				
002		.100000 x	18.705943 =		1.870594
1504		.005000 x	597.537950 =		2.987690
		-----			
			T.E =		4.858284
2112	2112				
002		.120000 x	18.705943 =		2.244713
1504		.005500 x	597.537950 =		3.286459
1501		.004000 x	428.497280 =		1.713989
		-----			
			T.E =		7.245161
2113	2113				
002		1.400000 x	18.705943 =		26.188320
002		.300000 x	18.705943 =		5.611783
		-----			
			T.E =		31.800103
2114	2114				
002		1.500000 x	18.705943 =		28.058915
1501		.005000 x	428.497280 =		2.142486
002		.400000 x	18.705943 =		7.482377
		-----			
			T.E =		37.683778
2115	2115				
481		.300000 x	5.535000 =		1.660500
003		1.200000 x	24.769248 =		29.723098
1501		.011000 x	428.497280 =		4.713470
002		.600000 x	18.705943 =		11.223566
		-----			
			T.E =		47.320633
2116	2116				
2115		1.300000 x	47.320633 =		61.516823
		-----			
			T.E =		61.516823
2117	2117				
002		.600000 x	18.705943 =		11.223566
1501		.125000 x	428.497280 =		53.562160
		-----			
			T.E =		64.785726
2118	2118				
2117		1.300000 x	64.785726 =		84.221444
		-----			
			T.E =		84.221444

2121	2121				
001		.400000 x	16.829739 =		6.731896
002		1.800000 x	18.705943 =		33.670697
-----					
			T.E =		40.402593
2122	2122				
001		.500000 x	16.829739 =		8.414870
1501		.005000 x	428.497280 =		2.142486
002		2.000000 x	18.705943 =		37.411886
-----					
			T.E =		47.969242
2123	2123				
002		.200000 x	18.705943 =		3.741189
1504		.008300 x	597.537950 =		4.959565
-----					
			T.E =		8.700754
2124	2124				
002		.200000 x	18.705943 =		3.741189
1501		.005000 x	428.497280 =		2.142486
1504		.010000 x	597.537950 =		5.975380
-----					
			T.E =		11.859055
2125	2125				
481		.400000 x	5.535000 =		2.214000
1501		.020000 x	428.497280 =		8.569946
002		1.000000 x	18.705943 =		18.705943
003		1.500000 x	24.769248 =		37.153872
-----					
			T.E =		66.643761
2126	2126				
2125		1.300000 x	66.643761 =		86.636889
-----					
			T.E =		86.636889
2127	2127				
002		1.000000 x	18.705943 =		18.705943
1501		.166600 x	428.497280 =		71.387647
-----					
			T.E =		90.093590
2128	2128				
2127		1.300000 x	90.093590 =		117.121667
-----					
			T.E =		117.121667

2131	2131			
001		.300000 x	16.829739 =	5.048922
		-----		
			T.E =	5.048922
2132	2132			
1504		.001600 x	597.537950 =	.956061
		-----		
			T.E =	.956061
2133	2133			
002		.100000 x	18.705943 =	1.870594
002		.600000 x	18.705943 =	11.223566
		-----		
			T.E =	13.094160
2134	2134			
1504		.002500 x	597.537950 =	1.493845
		-----		
			T.E =	1.493845
2135.1	2135.1			
2121		1.300000 x	40.402593 =	52.523371
		-----		
			T.E =	52.523371
2135.2	2135.2			
2122		1.300000 x	47.969242 =	62.360015
		-----		
			T.E =	62.360015
2135.3	2135.3			
2127		1.300000 x	90.093590 =	117.121667
		-----		
			T.E =	117.121667
2135.4	2135.4			
2128		1.300000 x	117.121667 =	152.258167
		-----		
			T.E =	152.258167
2141	2141			
001		2.000000 x	16.829739 =	33.659478
003		2.500000 x	24.769248 =	61.923120
		-----		
			T.E =	95.582598

2142	2142				
001		2.000000 x	16.829739 =	33.659478	
1501		.005000 x	428.497280 =	2.142486	
003		3.000000 x	24.769248 =	74.307744	
		-----			
			T.E =	110.109708	
2143	2143				
481		.500000 x	5.535000 =	2.767500	
001		2.000000 x	16.829739 =	33.659478	
003		3.000000 x	24.769248 =	74.307744	
1501		.025000 x	428.497280 =	10.712432	
		-----			
			T.E =	121.447154	
2144	2144				
2143		1.300000 x	121.447154 =	157.881300	
		-----			
			T.E =	157.881300	
2145	2145				
001		2.000000 x	16.829739 =	33.659478	
003		1.000000 x	24.769248 =	24.769248	
1501		.200000 x	428.497280 =	85.699456	
		-----			
			T.E =	144.128182	
2146	2146				
2145		1.300000 x	144.128182 =	187.366637	
		-----			
			T.E =	187.366637	
2151	2151				
001		1.200000 x	16.829739 =	20.195687	
003		.800000 x	24.769248 =	19.815398	
		-----			
			T.E =	40.011085	
2152	2152				
001		1.500000 x	16.829739 =	25.244609	
003		1.000000 x	24.769248 =	24.769248	
		-----			
			T.E =	50.013857	
2161	2161				
1505		.003300 x	252.233749 =	.832371	
		-----			
			T.E =	.832371	



2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	16.829739 =	13.463791
		-----		
			T.E =	13.730791
2163	2163			
001		.300000 x	16.829739 =	5.048922
		-----		
			T.E =	5.048922
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	597.537950 =	2.390152
		-----		
			T.E =	2.539752
2172	2172			
001		.800000 x	16.829739 =	13.463791
		-----		
			T.E =	13.463791
2173	2173			
001		.600000 x	16.829739 =	10.097843
		-----		
			T.E =	10.097843
2174	2174			
007		.050000 x	166.700117 =	8.335006
		-----		
			T.E =	8.335006
2175	2175			
009		5.500000 x	.074800 =	.411400
		-----		
			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2177	2177			
001		.800000 x	16.829739 =	13.463791
		-----		
			T.E =	13.463791

2178	2178			
001		.200000 x	16.829739 =	3.365948
		-----		
			T.E =	3.365948
2179	2179			
007		.018000 x	166.700117 =	3.000602
		-----		
			T.E =	3.000602
2180	2180			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2185	2185			
018.1		.142800 x	2.840000 =	.405552
005		.400000 x	19.931416 =	7.972566
484		.100000 x	3.490000 =	.349000
482		.700000 x	.961300 =	.672910
018.1		.042800 x	2.840000 =	.121552
		-----		
			T.E =	9.521580
2186	2186			
018.2		.142800 x	4.310000 =	.615468
005		.400000 x	19.931416 =	7.972566
018.2		.042800 x	4.310000 =	.184468
482		1.400000 x	.961300 =	1.345820
484		.200000 x	3.490000 =	.698000
		-----		
			T.E =	10.816322
2187	2187			
019.1		.142800 x	2.840000 =	.405552
485		1.100000 x	.826000 =	.908600
019.1		.428000 x	2.840000 =	1.215520
005		.400000 x	19.931416 =	7.972566
484		.100000 x	3.490000 =	.349000
		-----		
			T.E =	10.851238
2188	2188			
019.2		.142800 x	4.310000 =	.615468
005		.400000 x	19.931416 =	7.972566
485		1.800000 x	.826000 =	1.486800
484		.200000 x	3.490000 =	.698000
019.2		.042800 x	4.310000 =	.184468
		-----		
			T.E =	10.957302

2201	2201				
001		1.000000 x	16.829739 =	16.829739	
002		2.000000 x	18.705943 =	37.411886	
		-----			
			T.E =	54.241625	
2202	2202				
001		1.000000 x	16.829739 =	16.829739	
002		5.000000 x	18.705943 =	93.529715	
		-----			
			T.E =	110.359454	
2203	2203				
001		1.000000 x	16.829739 =	16.829739	
002		2.500000 x	18.705943 =	46.764858	
		-----			
			T.E =	63.594597	
2204	2204				
001		1.000000 x	16.829739 =	16.829739	
002		5.000000 x	18.705943 =	93.529715	
		-----			
			T.E =	110.359454	
2206	2206				
001		1.000000 x	16.829739 =	16.829739	
003		3.000000 x	24.769248 =	74.307744	
		-----			
			T.E =	91.137483	
2207	2207				
001		1.000000 x	16.829739 =	16.829739	
003		6.000000 x	24.769248 =	148.615488	
		-----			
			T.E =	165.445227	
2211	2211				
001		2.000000 x	16.829739 =	33.659478	
		-----			
			T.E =	33.659478	
2212	2212				
001		1.000000 x	16.829739 =	16.829739	
		-----			
			T.E =	16.829739	
2213	2213				
001		2.000000 x	16.829739 =	33.659478	
		-----			
			T.E =	33.659478	

2214	2214				
001		.600000 x	16.829739 =	10.097843	
		-----			
			T.E =	10.097843	
2221	2221				
001		1.200000 x	16.829739 =	20.195687	
002		1.600000 x	18.705943 =	29.929509	
		-----			
			T.E =	50.125196	
2222	2222				
001		1.200000 x	16.829739 =	20.195687	
002		2.500000 x	18.705943 =	46.764858	
		-----			
			T.E =	66.960544	
2223	2223				
001		3.000000 x	16.829739 =	50.489217	
		-----			
			T.E =	50.489217	
2224	2224				
001		5.000000 x	16.829739 =	84.148695	
		-----			
			T.E =	84.148695	
2226	2226				
001		1.500000 x	16.829739 =	25.244609	
002		5.000000 x	18.705943 =	93.529715	
		-----			
			T.E =	118.774324	
2227	2227				
001		1.500000 x	16.829739 =	25.244609	
002		12.000000 x	18.705943 =	224.471316	
		-----			
			T.E =	249.715925	
2231	2231				
001		.600000 x	16.829739 =	10.097843	
		-----			
			T.E =	10.097843	
2232	2232				
003		.020000 x	24.769248 =	.495385	
		-----			
			T.E =	.495385	

2236	2236				
001		.100000 x	16.829739 =	1.682974	
002		.300000 x	18.705943 =	5.611783	
				-----	
				T.E =	7.294757
2237	2237				
001		.200000 x	16.829739 =	3.365948	
003		.700000 x	24.769248 =	17.338474	
				-----	
				T.E =	20.704421
2238	2238				
001		.100000 x	16.829739 =	1.682974	
002		.400000 x	18.705943 =	7.482377	
				-----	
				T.E =	9.165351
2239	2239				
001		.200000 x	16.829739 =	3.365948	
003		.800000 x	24.769248 =	19.815398	
				-----	
				T.E =	23.181346
2241	2241				
001		.300000 x	16.829739 =	5.048922	
003		.100000 x	24.769248 =	2.476925	
				-----	
				T.E =	7.525847
2242	2242				
001		.400000 x	16.829739 =	6.731896	
003		.150000 x	24.769248 =	3.715387	
				-----	
				T.E =	10.447283
2243	2243				
001		.500000 x	16.829739 =	8.414870	
003		.250000 x	24.769248 =	6.192312	
				-----	
				T.E =	14.607182
2246	2246				
001		.250000 x	16.829739 =	4.207435	
003		.050000 x	24.769248 =	1.238462	
				-----	
				T.E =	5.445897

2247	2247				
001		.350000 x	16.829739 =	5.890409	
003		.100000 x	24.769248 =	2.476925	
				-----	
				T.E =	8.367333
2248	2248				
001		.450000 x	16.829739 =	7.573383	
003		.200000 x	24.769248 =	4.953850	
				-----	
				T.E =	12.527232
2251	2251				
001		.100000 x	16.829739 =	1.682974	
002		.300000 x	18.705943 =	5.611783	
				-----	
				T.E =	7.294757
2252	2252				
001		.100000 x	16.829739 =	1.682974	
002		.600000 x	18.705943 =	11.223566	
				-----	
				T.E =	12.906540
2261A	2261A				
003		.400000 x	24.769248 =	9.907699	
				-----	
				T.E =	9.907699
2261B	2261B				
003		.700000 x	24.769248 =	17.338474	
				-----	
				T.E =	17.338474
2261Γ	2261Γ				
003		.900000 x	24.769248 =	22.292323	
				-----	
				T.E =	22.292323
2261Δ	2261Δ				
003		1.200000 x	24.769248 =	29.723098	
				-----	
				T.E =	29.723098
2262A	2262A				
003		.550000 x	24.769248 =	13.623086	
				-----	
				T.E =	13.623086

2262B	2262B			
003		.900000 x	24.769248 =	22.292323
		-----		
			T.E =	22.292323
2262Γ	2262Γ			
003		1.200000 x	24.769248 =	29.723098
		-----		
			T.E =	29.723098
2262Δ	2262Δ			
003		1.600000 x	24.769248 =	39.630797
		-----		
			T.E =	39.630797
2263A	2263A			
003		.700000 x	24.769248 =	17.338474
		-----		
			T.E =	17.338474
2263B	2263B			
003		1.200000 x	24.769248 =	29.723098
		-----		
			T.E =	29.723098
2263Γ	2263Γ			
003		1.600000 x	24.769248 =	39.630797
		-----		
			T.E =	39.630797
2263Δ	2263Δ			
003		2.100000 x	24.769248 =	52.015421
		-----		
			T.E =	52.015421
2264.1A	2264.1A			
003		1.600000 x	24.769248 =	39.630797
		-----		
			T.E =	39.630797
2264.1B	2264.1B			
003		1.850000 x	24.769248 =	45.823109
		-----		
			T.E =	45.823109
2264.1Γ	2264.1Γ			
003		2.100000 x	24.769248 =	52.015421
		-----		
			T.E =	52.015421

2264.1Δ	2264.1Δ			
003		2.300000 x	24.769248 =	56.969270
		-----		
			T.E =	56.969270
2264.2Α	2264.2Α			
003		2.000000 x	24.769248 =	49.538496
		-----		
			T.E =	49.538496
2264.2Β	2264.2Β			
003		2.400000 x	24.769248 =	59.446195
		-----		
			T.E =	59.446195
2264.2Γ	2264.2Γ			
003		2.800000 x	24.769248 =	69.353894
		-----		
			T.E =	69.353894
2264.2Δ	2264.2Δ			
003		3.200000 x	24.769248 =	79.261594
		-----		
			T.E =	79.261594
2264.3Α	2264.3Α			
003		2.400000 x	24.769248 =	59.446195
		-----		
			T.E =	59.446195
2264.3Β	2264.3Β			
003		2.850000 x	24.769248 =	70.592357
		-----		
			T.E =	70.592357
2264.3Γ	2264.3Γ			
003		3.300000 x	24.769248 =	81.738518
		-----		
			T.E =	81.738518
2264.3Δ	2264.3Δ			
003		3.750000 x	24.769248 =	92.884680
		-----		
			T.E =	92.884680
2265Α	2265Α			
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	12.384624



2265B	2265B			
003		.800000 x	24.769248 =	19.815398
		-----		
			T.E =	19.815398
2266.1	2266.1			
2261A		1.000000 x	9.907699 =	9.907699
2261A		.350000 x	9.907699 =	3.467695
		-----		
			T.E =	13.375394
2266.10	2266.10			
2263B		1.000000 x	29.723098 =	29.723098
2263B		.350000 x	29.723098 =	10.403084
		-----		
			T.E =	40.126182
2266.11	2266.11			
2263Γ		1.000000 x	39.630797 =	39.630797
2263Γ		.350000 x	39.630797 =	13.870779
		-----		
			T.E =	53.501576
2266.12	2266.12			
2263Δ		1.000000 x	52.015421 =	52.015421
2263Δ		.350000 x	52.015421 =	18.205397
		-----		
			T.E =	70.220818
2266.13	2266.13			
2264.1A		1.000000 x	39.630797 =	39.630797
2264.1A		.350000 x	39.630797 =	13.870779
		-----		
			T.E =	53.501576
2266.14	2266.14			
2264.1B		1.000000 x	45.823109 =	45.823109
2264.1B		.350000 x	45.823109 =	16.038088
		-----		
			T.E =	61.861197
2266.15	2266.15			
2264.1Γ		1.000000 x	52.015421 =	52.015421
2264.1Γ		.350000 x	52.015421 =	18.205397
		-----		
			T.E =	70.220818

2266.16	2266.16			
2264.1Δ		1.000000 x	56.969270 =	56.969270
2264.1Δ		.350000 x	56.969270 =	19.939245
			-----	
			T.E =	76.908515
2266.17	2266.17			
2264.2A		1.000000 x	49.538496 =	49.538496
2264.2A		.350000 x	49.538496 =	17.338474
			-----	
			T.E =	66.876970
2266.18	2266.18			
2264.2B		1.000000 x	59.446195 =	59.446195
2264.2B		.350000 x	59.446195 =	20.806168
			-----	
			T.E =	80.252363
2266.19	2266.19			
2264.2Γ		1.000000 x	69.353894 =	69.353894
2264.2Γ		.350000 x	69.353894 =	24.273863
			-----	
			T.E =	93.627757
2266.2	2266.2			
2261B		1.000000 x	17.338474 =	17.338474
2261B		.350000 x	17.338474 =	6.068466
			-----	
			T.E =	23.406940
2266.20	2266.20			
2264.2Δ		1.000000 x	79.261594 =	79.261594
2264.2Δ		.350000 x	79.261594 =	27.741558
			-----	
			T.E =	107.003152
2266.21	2266.21			
2264.3A		1.000000 x	59.446195 =	59.446195
2264.3A		.350000 x	59.446195 =	20.806168
			-----	
			T.E =	80.252363
2266.22	2266.22			
2264.3B		1.000000 x	70.592357 =	70.592357
2264.3B		.350000 x	70.592357 =	24.707325
			-----	
			T.E =	95.299682

2266.23	2266.23				
2264.3Γ		1.000000 x	81.738518 =		81.738518
2264.3Γ		.350000 x	81.738518 =		28.608481
			T.E =		110.346999
2266.24	2266.24				
2264.3Δ		1.000000 x	92.884680 =		92.884680
2264.3Δ		.350000 x	92.884680 =		32.509638
			T.E =		125.394318
2266.25	2266.25				
2265A		1.000000 x	12.384624 =		12.384624
2265A		.350000 x	12.384624 =		4.334618
			T.E =		16.719242
2266.26	2266.26				
2265B		1.000000 x	19.815398 =		19.815398
2265B		.350000 x	19.815398 =		6.935389
			T.E =		26.750787
2266.3	2266.3				
2261Γ		1.000000 x	22.292323 =		22.292323
2261Γ		.350000 x	22.292323 =		7.802313
			T.E =		30.094636
2266.4	2266.4				
2261Δ		1.000000 x	29.723098 =		29.723098
2261Δ		.350000 x	29.723098 =		10.403084
			T.E =		40.126182
2266.5	2266.5				
2262A		1.000000 x	13.623086 =		13.623086
2262A		.350000 x	13.623086 =		4.768080
			T.E =		18.391166
2266.6	2266.6				
2262B		1.000000 x	22.292323 =		22.292323
2262B		.350000 x	22.292323 =		7.802313
			T.E =		30.094636

2266.7	2266.7			
2262Γ		1.000000 x	29.723098 =	29.723098
2262Γ		.350000 x	29.723098 =	10.403084
				-----
			T.E =	40.126182
2266.8	2266.8			
2262Δ		1.000000 x	39.630797 =	39.630797
2262Δ		.350000 x	39.630797 =	13.870779
				-----
			T.E =	53.501576
2266.9	2266.9			
2263A		1.000000 x	17.338474 =	17.338474
2263A		.350000 x	17.338474 =	6.068466
				-----
			T.E =	23.406940
2267	2267			
003		3.500000 x	24.769248 =	86.692368
				-----
			T.E =	86.692368
2268A	2268A			
003		5.000000 x	24.769248 =	123.846240
				-----
			T.E =	123.846240
2268B	2268B			
003		5.900000 x	24.769248 =	146.138563
				-----
			T.E =	146.138563
2268Γ	2268Γ			
003		6.400000 x	24.769248 =	158.523187
				-----
			T.E =	158.523187
2268Δ	2268Δ			
003		6.900000 x	24.769248 =	170.907811
				-----
			T.E =	170.907811
2269A	2269A			
003		2.000000 x	24.769248 =	49.538496
				-----
			T.E =	49.538496

2269B	2269B			
003		3.000000 x	24.769248 =	74.307744
		-----		
			T.E =	74.307744
2269Γ	2269Γ			
003		4.000000 x	24.769248 =	99.076992
		-----		
			T.E =	99.076992
2270.1	2270.1			
2267		1.000000 x	86.692368 =	86.692368
2267		.600000 x	86.692368 =	52.015421
		-----		
			T.E =	138.707789
2270.2	2270.2			
2268A		1.000000 x	123.846240 =	123.846240
2268A		.600000 x	123.846240 =	74.307744
		-----		
			T.E =	198.153984
2270.3	2270.3			
2268B		1.000000 x	146.138563 =	146.138563
2268B		.600000 x	146.138563 =	87.683138
		-----		
			T.E =	233.821701
2270.4	2270.4			
2268Γ		1.000000 x	158.523187 =	158.523187
2268Γ		.600000 x	158.523187 =	95.113912
		-----		
			T.E =	253.637099
2270.5	2270.5			
2268Δ		1.000000 x	170.907811 =	170.907811
2268Δ		.600000 x	170.907811 =	102.544687
		-----		
			T.E =	273.452498
2271A	2271A			
003		2.500000 x	24.769248 =	61.923120
		-----		
			T.E =	61.923120
2271B	2271B			
003		3.000000 x	24.769248 =	74.307744
		-----		
			T.E =	74.307744

2271E	2271E			
003		4.500000 x	24.769248 =	111.461616
		-----		
			T.E =	111.461616
2271H	2271H			
003		6.000000 x	24.769248 =	148.615488
		-----		
			T.E =	148.615488
2271I	2271I			
003		7.000000 x	24.769248 =	173.384736
		-----		
			T.E =	173.384736
2271Z	2271Z			
003		5.500000 x	24.769248 =	136.230864
		-----		
			T.E =	136.230864
2271Γ	2271Γ			
003		3.500000 x	24.769248 =	86.692368
		-----		
			T.E =	86.692368
2271Δ	2271Δ			
003		4.000000 x	24.769248 =	99.076992
		-----		
			T.E =	99.076992
2271Θ	2271Θ			
003		6.500000 x	24.769248 =	161.000112
		-----		
			T.E =	161.000112
2271ΣΤ	2271ΣΤ			
003		5.000000 x	24.769248 =	123.846240
		-----		
			T.E =	123.846240
2272A	2272A			
003		3.000000 x	24.769248 =	74.307744
		-----		
			T.E =	74.307744
2272B	2272B			
003		3.700000 x	24.769248 =	91.646218
		-----		
			T.E =	91.646218

2272E	2272E			
003		5.800000 x	24.769248 =	143.661638
		-----		
			T.E =	143.661638
2272H	2272H			
003		7.900000 x	24.769248 =	195.677059
		-----		
			T.E =	195.677059
2272I	2272I			
003		9.300000 x	24.769248 =	230.354006
		-----		
			T.E =	230.354006
2272Z	2272Z			
003		7.200000 x	24.769248 =	178.338586
		-----		
			T.E =	178.338586
2272Γ	2272Γ			
003		4.400000 x	24.769248 =	108.984691
		-----		
			T.E =	108.984691
2272Δ	2272Δ			
003		5.100000 x	24.769248 =	126.323165
		-----		
			T.E =	126.323165
2272Θ	2272Θ			
003		8.600000 x	24.769248 =	213.015533
		-----		
			T.E =	213.015533
2272ΣΤ	2272ΣΤ			
003		6.500000 x	24.769248 =	161.000112
		-----		
			T.E =	161.000112
2273A	2273A			
003		8.500000 x	24.769248 =	210.538608
		-----		
			T.E =	210.538608
2273B	2273B			
003		10.000000 x	24.769248 =	247.692480
		-----		
			T.E =	247.692480

2273Γ	2273Γ			
003		11.500000 x	24.769248 =	284.846352
		-----		
			T.E =	284.846352
2273Δ	2273Δ			
003		13.000000 x	24.769248 =	322.000224
		-----		
			T.E =	322.000224
2274.1	2274.1			
2271A		1.300000 x	61.923120 =	80.500056
		-----		
			T.E =	80.500056
2274.10	2274.10			
2271I		1.300000 x	173.384736 =	225.400157
		-----		
			T.E =	225.400157
2274.11	2274.11			
2272A		1.300000 x	74.307744 =	96.600067
		-----		
			T.E =	96.600067
2274.12	2274.12			
2272B		1.300000 x	91.646218 =	119.140083
		-----		
			T.E =	119.140083
2274.13	2274.13			
2272Γ		1.300000 x	108.984691 =	141.680098
		-----		
			T.E =	141.680098
2274.14	2274.14			
2272Δ		1.300000 x	126.323165 =	164.220115
		-----		
			T.E =	164.220115
2274.15	2274.15			
2272E		1.300000 x	143.661638 =	186.760129
		-----		
			T.E =	186.760129
2274.16	2274.16			
2272ΣΤ		1.300000 x	161.000112 =	209.300146
		-----		
			T.E =	209.300146



2274.17	2274.17			
2272Z		1.300000 x	178.338586 =	231.840162
			T.E =	231.840162
2274.18	2274.18			
2272H		1.300000 x	195.677059 =	254.380177
			T.E =	254.380177
2274.19	2274.19			
2272Θ		1.300000 x	213.015533 =	276.920193
			T.E =	276.920193
2274.2	2274.2			
2271B		1.300000 x	74.307744 =	96.600067
			T.E =	96.600067
2274.20	2274.20			
2272I		1.300000 x	230.354006 =	299.460208
			T.E =	299.460208
2274.21	2274.21			
2273A		1.300000 x	210.538608 =	273.700190
			T.E =	273.700190
2274.22	2274.22			
2273B		1.300000 x	247.692480 =	322.000224
			T.E =	322.000224
2274.23	2274.23			
2273Γ		1.300000 x	284.846352 =	370.300258
			T.E =	370.300258
2274.24	2274.24			
2273Δ		1.300000 x	322.000224 =	418.600291
			T.E =	418.600291
2274.3	2274.3			
2271Γ		1.300000 x	86.692368 =	112.700078
			T.E =	112.700078

2274.4	2274.4			
2271Δ		1.300000 x	99.076992 =	128.800090
		-----		
			T.E =	128.800090
2274.5	2274.5			
2271E		1.300000 x	111.461616 =	144.900101
		-----		
			T.E =	144.900101
2274.6	2274.6			
2271ΣΤ		1.300000 x	123.846240 =	161.000112
		-----		
			T.E =	161.000112
2274.7	2274.7			
2271Ζ		1.300000 x	136.230864 =	177.100123
		-----		
			T.E =	177.100123
2274.8	2274.8			
2271Η		1.300000 x	148.615488 =	193.200134
		-----		
			T.E =	193.200134
2274.9	2274.9			
2271Θ		1.300000 x	161.000112 =	209.300146
		-----		
			T.E =	209.300146
2275	2275			
003		1.000000 x	24.769248 =	24.769248
		-----		
			T.E =	24.769248
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	210.000000 =	6.930000
251		6.000000 x	.695000 =	4.170000
003		5.000000 x	24.769248 =	123.846240
001		9.000000 x	16.829739 =	151.467651
		-----		
			T.E =	295.113891
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	18.705943 =	5.611783
		-----		
			T.E =	5.901783

2303	2303				
001		.250000 x	16.829739 =	4.207435	
003		.250000 x	24.769248 =	6.192312	
		-----			
			T.E =	10.399747	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	18.705943 =	1.870594	
		-----			
			T.E =	1.986594	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	210.000000 =	8.400000	
003		7.000000 x	24.769248 =	173.384736	
001		9.000000 x	16.829739 =	151.467651	
251		6.000000 x	.695000 =	4.170000	
		-----			
			T.E =	349.022387	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	210.000000 =	.420000	
251		.250000 x	.695000 =	.173750	
001		.250000 x	16.829739 =	4.207435	
003		.150000 x	24.769248 =	3.715387	
		-----			
			T.E =	9.096572	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.695000 =	.139000	
203.4		.001000 x	210.000000 =	.210000	
003		.100000 x	24.769248 =	2.476925	
001		.200000 x	16.829739 =	3.365948	
		-----			
			T.E =	6.771873	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	24.769248 =	.743077	
		-----			
			T.E =	1.232577	
2314.2	2314.2				
512		1.000000 x	.375000 =	.375000	
003		.030000 x	24.769248 =	.743077	
		-----			
			T.E =	1.118077	

3101	3101				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
026		175.000000 x	.098900 =	17.307500	
052		.430000 x	15.400000 =	6.622000	
056		.860000 x	10.580000 =	9.098800	
-----					
			T.E =	109.938360	
3102	3102				
021		.250000 x	2.670000 =	.667500	
052		.420000 x	15.400000 =	6.468000	
056		.840000 x	10.580000 =	8.887200	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
026		200.000000 x	.098900 =	19.780000	
-----					
			T.E =	112.045260	
3103	3103				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
056		.820000 x	10.580000 =	8.675600	
052		.410000 x	15.400000 =	6.314000	
026		250.000000 x	.098900 =	24.725000	
-----					
			T.E =	116.624660	
3104	3104				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.098900 =	29.670000	
052		.400000 x	15.400000 =	6.160000	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
056		.800000 x	10.580000 =	8.464000	
-----					
			T.E =	121.204060	
3111	3111				
021		.250000 x	2.670000 =	.667500	
003		1.500000 x	24.769248 =	37.153872	
001		4.000000 x	16.829739 =	67.318956	
026		200.000000 x	.098900 =	19.780000	
057		.840000 x	10.580000 =	8.887200	
052		.420000 x	15.400000 =	6.468000	
-----					
			T.E =	140.275528	

3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.953670 =	27.547684
026		250.000000 x	.098900 =	24.725000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	24.769248 =	37.153872
001		2.000000 x	16.829739 =	33.659478
052		.410000 x	15.400000 =	6.314000
		-----		
			T.E =	138.743134
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.953670 =	27.547684
003		2.000000 x	24.769248 =	49.538496
001		3.000000 x	16.829739 =	50.489217
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.098900 =	29.670000
		-----		
			T.E =	172.536897
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.098900 =	14.835000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	16.829739 =	84.148695
052		.420000 x	15.400000 =	6.468000
		-----		
			T.E =	122.660895
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	24.769248 =	17.338474
001		3.500000 x	16.829739 =	58.904087
026		175.000000 x	.098900 =	17.307500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000
		-----		
			T.E =	114.521560
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.098900 =	19.780000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	24.769248 =	17.338474
001		3.500000 x	16.829739 =	58.904087
052		.560000 x	15.400000 =	8.624000
		-----		
			T.E =	116.704460

3203	3203				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
061		.820000 x	13.560000 =	11.119200	
052		.540000 x	15.400000 =	8.316000	
026		250.000000 x	.098900 =	24.725000	
			T.E =	121.070260	
3204	3204				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.098900 =	29.670000	
052		.530000 x	15.400000 =	8.162000	
003		.700000 x	24.769248 =	17.338474	
001		3.500000 x	16.829739 =	58.904087	
061		.800000 x	13.560000 =	10.848000	
			T.E =	125.590060	
3205	3205				
021		.250000 x	2.670000 =	.667500	
003		5.500000 x	24.769248 =	136.230864	
001		7.000000 x	16.829739 =	117.808173	
026		200.000000 x	.098900 =	19.780000	
065		.750000 x	13.610000 =	10.207500	
052		.430000 x	15.400000 =	6.622000	
			T.E =	291.316037	
3206	3206				
021		.250000 x	2.670000 =	.667500	
026		250.000000 x	.098900 =	24.725000	
065		.730000 x	13.610000 =	9.935300	
003		5.500000 x	24.769248 =	136.230864	
001		7.000000 x	16.829739 =	117.808173	
052		.410000 x	15.400000 =	6.314000	
			T.E =	295.680837	
3207	3207				
021		.250000 x	2.670000 =	.667500	
003		3.000000 x	24.769248 =	74.307744	
001		6.000000 x	16.829739 =	100.978434	
065		.750000 x	13.610000 =	10.207500	
052		.430000 x	15.400000 =	6.622000	
026		200.000000 x	.098900 =	19.780000	
			T.E =	212.563178	

3208	3208			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.098900 =	24.725000
065		.730000 x	13.610000 =	9.935300
003		3.000000 x	24.769248 =	74.307744
001		6.000000 x	16.829739 =	100.978434
052		.430000 x	15.400000 =	6.622000
-----				
			T.E =	217.235978
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	24.769248 =	37.153872
001		4.000000 x	16.829739 =	67.318956
062		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		200.000000 x	.098900 =	19.780000
-----				
			T.E =	144.934728
3212	3212			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.953670 =	27.547684
062		.820000 x	13.560000 =	11.119200
026		250.000000 x	.098900 =	24.725000
003		1.500000 x	24.769248 =	37.153872
001		2.000000 x	16.829739 =	33.659478
052		.540000 x	15.400000 =	8.316000
-----				
			T.E =	143.188734
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.953670 =	27.547684
003		2.000000 x	24.769248 =	49.538496
001		3.000000 x	16.829739 =	50.489217
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.098900 =	29.670000
-----				
			T.E =	176.922897
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.953670 =	27.547684
003		2.000000 x	24.769248 =	49.538496
001		3.500000 x	16.829739 =	58.904087
065		.270000 x	13.610000 =	3.674700
026		350.000000 x	.098900 =	34.615000
052		.400000 x	15.400000 =	6.160000
062		.600000 x	13.560000 =	8.136000
-----				
			T.E =	189.243466

3215	3215			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	550.953670 =	27.547684
003		2.000000 x	24.769248 =	49.538496
001		3.500000 x	16.829739 =	58.904087
065		.250000 x	13.610000 =	3.402500
027		350.000000 x	.119300 =	41.755000
062		.560000 x	13.560000 =	7.593600
052		.420000 x	15.400000 =	6.468000
-----				
			T.E =	195.876866
3216	3216			
021		.250000 x	2.670000 =	.667500
027		425.000000 x	.119300 =	50.702500
062		.550000 x	13.560000 =	7.458000
1502		.050000 x	550.953670 =	27.547684
003		2.000000 x	24.769248 =	49.538496
001		4.000000 x	16.829739 =	67.318956
065		.270000 x	13.610000 =	3.674700
052		.350000 x	15.400000 =	5.390000
-----				
			T.E =	212.297836
3217	3217			
001		2.500000 x	16.829739 =	42.074348
-----				
			T.E =	42.074348
3218	3218			
001		5.000000 x	16.829739 =	84.148695
-----				
			T.E =	84.148695
3219	3219			
001		3.000000 x	16.829739 =	50.489217
003		4.000000 x	24.769248 =	99.076992
-----				
			T.E =	149.566209
3220	3220			
001		5.000000 x	16.829739 =	84.148695
003		4.000000 x	24.769248 =	99.076992
-----				
			T.E =	183.225687
3221	3221			
001		3.000000 x	16.829739 =	50.489217
003		6.000000 x	24.769248 =	148.615488
-----				
			T.E =	199.104705



3222	3222				
001		5.000000 x	16.829739 =		84.148695
003		6.000000 x	24.769248 =		148.615488
		-----			
			T.E =		232.764183
3223A.1	3223A.1				
001		2.000000 x	16.829739 =		33.659478
1502		.050000 x	550.953670 =		27.547684
003		1.500000 x	24.769248 =		37.153872
		-----			
			AΘΡΟΙΣΜΑ =		98.361034
	T.E =	.500000 x	98.361034 =		49.180517
		-----			
3223A.2	3223A.2				
001		3.000000 x	16.829739 =		50.489217
1502		.050000 x	550.953670 =		27.547684
003		2.000000 x	24.769248 =		49.538496
		-----			
			AΘΡΟΙΣΜΑ =		127.575397
	T.E =	.500000 x	127.575397 =		63.787698
		-----			
3223A.3	3223A.3				
001		2.000000 x	16.829739 =		33.659478
1502		.050000 x	550.953670 =		27.547684
003		1.500000 x	24.769248 =		37.153872
		-----			
			AΘΡΟΙΣΜΑ =		98.361034
	T.E =	.500000 x	98.361034 =		49.180517
		-----			
3223A.4	3223A.4				
001		3.000000 x	16.829739 =		50.489217
003		2.000000 x	24.769248 =		49.538496
1502		.050000 x	550.953670 =		27.547684
		-----			
			AΘΡΟΙΣΜΑ =		127.575397
	T.E =	.500000 x	127.575397 =		63.787698
		-----			
3223A.5	3223A.5				
001		3.500000 x	16.829739 =		58.904087
003		2.000000 x	24.769248 =		49.538496
1502		.050000 x	550.953670 =		27.547684
		-----			
			AΘΡΟΙΣΜΑ =		135.990266
	T.E =	.500000 x	135.990266 =		67.995133
		-----			

3223A.6	3223A.6			
001		3.500000 x	16.829739 =	58.904087
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.953670 =	27.547684
			-----	
			ΑΘΡΟΙΣΜΑ =	135.990266
	T.E =	.500000 x	135.990266 =	67.995133
			-----	
3223A.7	3223A.7			
001		4.000000 x	16.829739 =	67.318956
1502		.050000 x	550.953670 =	27.547684
003		2.000000 x	24.769248 =	49.538496
			-----	
			ΑΘΡΟΙΣΜΑ =	144.405136
	T.E =	.500000 x	144.405136 =	72.202568
			-----	
3223B.1	3223B.1			
001		2.000000 x	16.829739 =	33.659478
003		1.500000 x	24.769248 =	37.153872
1502		.050000 x	550.953670 =	27.547684
			-----	
			ΑΘΡΟΙΣΜΑ =	98.361034
	T.E =	.250000 x	98.361034 =	24.590258
			-----	
3223B.2	3223B.2			
001		3.000000 x	16.829739 =	50.489217
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.953670 =	27.547684
			-----	
			ΑΘΡΟΙΣΜΑ =	127.575397
	T.E =	.250000 x	127.575397 =	31.893849
			-----	
3223B.3	3223B.3			
001		2.000000 x	16.829739 =	33.659478
003		1.500000 x	24.769248 =	37.153872
1502		.050000 x	550.953670 =	27.547684
			-----	
			ΑΘΡΟΙΣΜΑ =	98.361034
	T.E =	.250000 x	98.361034 =	24.590258
			-----	
3223B.4	3223B.4			
001		3.000000 x	16.829739 =	50.489217
1502		.050000 x	550.953670 =	27.547684
003		2.000000 x	24.769248 =	49.538496
			-----	
			ΑΘΡΟΙΣΜΑ =	127.575397
	T.E =	.250000 x	127.575397 =	31.893849
			-----	

3223B.5	3223B.5			
001		3.500000 x	16.829739 =	58.904087
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.953670 =	27.547684
			-----	
			ΑΘΡΟΙΣΜΑ =	135.990266
	T.E =	.250000 x	135.990266 =	33.997567
			-----	
3223B.6	3223B.6			
001		3.500000 x	16.829739 =	58.904087
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.953670 =	27.547684
			-----	
			ΑΘΡΟΙΣΜΑ =	135.990266
	T.E =	.250000 x	135.990266 =	33.997567
			-----	
3223B.7	3223B.7			
001		4.000000 x	16.829739 =	67.318956
003		2.000000 x	24.769248 =	49.538496
1502		.050000 x	550.953670 =	27.547684
			-----	
			ΑΘΡΟΙΣΜΑ =	144.405136
	T.E =	.250000 x	144.405136 =	36.101284
			-----	
3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	16.829739 =	84.148695
061		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		150.000000 x	.098900 =	14.835000
			-----	
			T.E =	127.320095
3301	3301			
021		.200000 x	2.670000 =	.534000
051		.300000 x	15.400000 =	4.620000
032		.150000 x	35.000000 =	5.250000
056		.800000 x	10.580000 =	8.464000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	24.769248 =	19.815398
001		3.500000 x	16.829739 =	58.904087
			-----	
			T.E =	103.228235

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	35.000000 =	7.000000
051		.200000 x	15.400000 =	3.080000
001		3.500000 x	16.829739 =	58.904087
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	24.769248 =	19.815398
056		.800000 x	10.580000 =	8.464000
-----				
			T.E =	105.318485
3303	3303			
021		.200000 x	2.670000 =	.534000
032		.400000 x	35.000000 =	14.000000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	24.769248 =	19.815398
001		3.500000 x	16.829739 =	58.904087
056		.800000 x	10.580000 =	8.464000
-----				
			T.E =	109.238485
3304	3304			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	24.769248 =	29.723098
001		3.500000 x	16.829739 =	58.904087
056		.800000 x	10.580000 =	8.464000
032		.400000 x	35.000000 =	14.000000
026		100.000000 x	.098900 =	9.890000
-----				
			T.E =	126.027784
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	35.000000 =	5.600000
051		.320000 x	15.400000 =	4.928000
061		.840000 x	13.560000 =	11.390400
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	24.769248 =	19.815398
001		3.500000 x	16.829739 =	58.904087
-----				
			T.E =	107.188685
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	35.000000 =	7.350000
051		.210000 x	15.400000 =	3.234000
001		3.500000 x	16.829739 =	58.904087
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	24.769248 =	29.723098
061		.840000 x	13.560000 =	11.390400
-----				
			T.E =	119.032634

3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	35.000000 =	14.700000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	24.769248 =	29.723098
001		3.500000 x	16.829739 =	58.904087
061		.840000 x	13.560000 =	11.390400
-----				
			T.E =	123.148634
3314	3314			
021		.200000 x	2.670000 =	.534000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	24.769248 =	29.723098
001		3.500000 x	16.829739 =	58.904087
061		.840000 x	13.560000 =	11.390400
032		.420000 x	35.000000 =	14.700000
026		100.000000 x	.098900 =	9.890000
-----				
			T.E =	130.030234
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
058		.500000 x	9.090000 =	4.545000
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.098900 =	13.846000
052		.294000 x	15.400000 =	4.527600
-----				
			T.E =	98.927410
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
061		.588000 x	13.560000 =	7.973280
026		140.000000 x	.098900 =	13.846000
058		.500000 x	9.090000 =	4.545000
052		.392000 x	15.400000 =	6.036800
-----				
			T.E =	102.188850
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
058		.500000 x	9.090000 =	4.545000
056		.574000 x	10.580000 =	6.072920
001		2.500000 x	16.829739 =	42.074348
003		1.100000 x	24.769248 =	27.246173
026		175.000000 x	.098900 =	17.307500
052		.287000 x	15.400000 =	4.419800
-----				
			T.E =	102.132990

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
061		.574000 x	13.560000 =	7.783440
058		.500000 x	9.090000 =	4.545000
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.098900 =	17.307500
-----				
			T.E =	105.244910
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.098900 =	13.846000
052		.294000 x	15.400000 =	4.527600
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
081		.500000 x	11.010000 =	5.505000
-----				
			T.E =	99.887410
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.098900 =	13.846000
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800
001		2.500000 x	16.829739 =	42.074348
003		1.100000 x	24.769248 =	27.246173
081		.500000 x	11.010000 =	5.505000
-----				
			T.E =	103.148850
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
056		.574000 x	10.580000 =	6.072920
003		1.100000 x	24.769248 =	27.246173
081		.500000 x	11.010000 =	5.505000
001		2.500000 x	16.829739 =	42.074348
026		175.000000 x	.098900 =	17.307500
052		.287000 x	15.400000 =	4.419800
-----				
			T.E =	103.092990

3407.2	3407.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	24.769248 =	27.246173
001		2.500000 x	16.829739 =	42.074348
081		.500000 x	11.010000 =	5.505000
061		.574000 x	13.560000 =	7.783440
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.098900 =	17.307500
-----				
			T.E =	106.204910
3501	3501			
021		.200000 x	2.670000 =	.534000
032		.200000 x	35.000000 =	7.000000
001		5.000000 x	16.829739 =	84.148695
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	24.769248 =	49.538496
067		1.050000 x	45.000000 =	47.250000
-----				
			T.E =	195.240091
3502	3502			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.098900 =	9.890000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	24.769248 =	49.538496
001		5.000000 x	16.829739 =	84.148695
067		1.050000 x	45.000000 =	47.250000
032		.200000 x	35.000000 =	7.000000
-----				
			T.E =	202.121691
3503	3503			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.098900 =	14.835000
1407		.080000 x	37.605000 =	3.008400
003		2.000000 x	24.769248 =	49.538496
001		5.000000 x	16.829739 =	84.148695
067		1.000000 x	45.000000 =	45.000000
032		.200000 x	35.000000 =	7.000000
-----				
			T.E =	204.064591
3504	3504			
021		.200000 x	2.670000 =	.534000
003		3.200000 x	24.769248 =	79.261594
001		5.000000 x	16.829739 =	84.148695
517		4.000000 x	.000000 =	.000000
055		180.000000 x	.090000 =	16.200000
026		250.000000 x	.098900 =	24.725000
-----				
			T.E =	

3505	3505			
021		.200000 x	2.670000 =	.534000
055		420.000000 x	.090000 =	37.800000
003		5.000000 x	24.769248 =	123.846240
001		5.500000 x	16.829739 =	92.563565
517		4.000000 x	.000000 =	.000000
026		250.000000 x	.098900 =	24.725000

-----  
T.E =

3506	3506			
021		.300000 x	2.670000 =	.801000
515		1.150000 x	41.230000 =	47.414500
003		2.500000 x	24.769248 =	61.923120
001		5.000000 x	16.829739 =	84.148695
026		200.000000 x	.098900 =	19.780000

-----  
T.E =

214.067315

3511	3511			
021		.200000 x	2.670000 =	.534000
001		5.000000 x	16.829739 =	84.148695
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	24.769248 =	49.538496
032		.200000 x	35.000000 =	7.000000
069		1.050000 x	.000000 =	.000000

-----  
T.E =

3512	3512			
021		.200000 x	2.670000 =	.534000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	24.769248 =	49.538496
001		5.000000 x	16.829739 =	84.148695
069		1.050000 x	.000000 =	.000000
032		.200000 x	35.000000 =	7.000000
026		100.000000 x	.098900 =	9.890000

-----  
T.E =

3513	3513			
001		2.500000 x	16.829739 =	42.074348

-----  
T.E =

42.074348

3514	3514			
001		5.000000 x	16.829739 =	84.148695

-----  
T.E =

84.148695



3801	3801				
201		.001500 x	290.000000 =		.435000
003		.500000 x	24.769248 =		12.384624
001		.400000 x	16.829739 =		6.731896
203.4		.002500 x	210.000000 =		.525000
251		.300000 x	.695000 =		.208500
					-----
			T.E =		20.285020
3802	3802				
3801		.050000 x	20.285020 =		1.014251
					-----
			T.E =		1.014251
3811	3811				
203.4		.004000 x	210.000000 =		.840000
251		.100000 x	.695000 =		.069500
003		.800000 x	24.769248 =		19.815398
001		.200000 x	16.829739 =		3.365948
					-----
			T.E =		24.090846
3816	3816				
201		.002500 x	290.000000 =		.725000
003		.600000 x	24.769248 =		14.861549
001		.400000 x	16.829739 =		6.731896
203.4		.003000 x	210.000000 =		.630000
251		.200000 x	.695000 =		.139000
					-----
			T.E =		23.087444
3817	3817				
3816		.150000 x	23.087444 =		3.463117
					-----
			T.E =		3.463117
3821	3821				
201		.014000 x	290.000000 =		4.060000
251		.600000 x	.695000 =		.417000
003		2.400000 x	24.769248 =		59.446195
001		.600000 x	16.829739 =		10.097843
203.4		.018000 x	210.000000 =		3.780000
					-----
			T.E =		77.801039
3822	3822				
3821		.150000 x	77.801039 =		11.670156
					-----
			T.E =		11.670156

3823	3823			
201		.020000 x	290.000000 =	5.800000
001		.600000 x	16.829739 =	10.097843
003		3.000000 x	24.769248 =	74.307744
251		.180000 x	.695000 =	.125100
203.4		.025000 x	210.000000 =	5.250000
		-----		
			T.E =	95.580687
3824	3824			
3823		.200000 x	95.580687 =	19.116137
		-----		
			T.E =	19.116137
3831	3831			
201		.020000 x	290.000000 =	5.800000
003		4.500000 x	24.769248 =	111.461616
001		1.100000 x	16.829739 =	18.512713
251		.800000 x	.695000 =	.556000
203.4		.024000 x	210.000000 =	5.040000
		-----		
			T.E =	141.370329
3832	3832			
3831		.150000 x	141.370329 =	21.205549
		-----		
			T.E =	21.205549
3833	3833			
201		.022000 x	290.000000 =	6.380000
003		6.000000 x	24.769248 =	148.615488
001		1.100000 x	16.829739 =	18.512713
251		1.000000 x	.695000 =	.695000
203.4		.025000 x	210.000000 =	5.250000
		-----		
			T.E =	179.453201
3834	3834			
3833		.200000 x	179.453201 =	35.890640
		-----		
			T.E =	35.890640
3841	3841			
203.4		.001500 x	210.000000 =	.315000
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	12.699624

3851	3851				
203.4		.052000 x	210.000000 =	10.920000	
251		1.100000 x	.695000 =	.764500	
003		1.300000 x	24.769248 =	32.200022	
		-----			
			T.E =	43.884522	
3852	3852				
001		.300000 x	16.829739 =	5.048922	
003		.100000 x	24.769248 =	2.476925	
		-----			
			T.E =	7.525847	
3871	3871				
260		1.030000 x	.528700 =	.544561	
003		.050000 x	24.769248 =	1.238462	
		-----			
			T.E =	1.783023	
3872	3872				
261		1.030000 x	.560100 =	.576903	
003		.040000 x	24.769248 =	.990770	
		-----			
			T.E =	1.567673	
3873	3873				
262		1.030000 x	.528700 =	.544561	
003		.050000 x	24.769248 =	1.238462	
		-----			
			T.E =	1.783023	
3874	3874				
258		1.450000 x	7.515000 =	10.896750	
003		.150000 x	24.769248 =	3.715387	
		-----			
			T.E =	14.612137	
3875	3875				
259		1.000000 x	24.475000 =	24.475000	
003		.300000 x	24.769248 =	7.430774	
		-----			
			T.E =	31.905774	
3876	3876				
003		.060000 x	24.769248 =	1.486155	
		-----			
			T.E =	1.486155	

3881.1	3881.1			
111		1,023.391800 x	.078400 =	80.233917
001		5.000000 x	16.829739 =	84.148695
		-----		
			T.E =	164.382612
3881.2	3881.2			
112		627.989998 x	.087900 =	55.200321
001		5.000000 x	16.829739 =	84.148695
		-----		
			T.E =	139.349016
3882	3882			
127		1.050000 x	83.240000 =	87.402000
001		4.000000 x	16.829739 =	67.318956
		-----		
			T.E =	154.720956
4101	4101			
081		1.150000 x	11.010000 =	12.661500
001		1.300000 x	16.829739 =	21.878661
003		2.000000 x	24.769248 =	49.538496
		-----		
			T.E =	84.078657
4102	4102			
081		1.200000 x	11.010000 =	13.212000
001		1.700000 x	16.829739 =	28.610556
003		3.500000 x	24.769248 =	86.692368
		-----		
			T.E =	128.514924
4103	4103			
081		1.150000 x	11.010000 =	12.661500
003		4.000000 x	24.769248 =	99.076992
001		3.000000 x	16.829739 =	50.489217
		-----		
			T.E =	162.227709
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	16.829739 =	50.489217
		-----		
			T.E =	62.049717
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	24.769248 =	22.292323
001		1.000000 x	16.829739 =	16.829739
		-----		
			T.E =	42.975562

4106	4106			
081		.320000 x	11.010000 =	3.523200
001		.700000 x	16.829739 =	11.780817
003		.900000 x	24.769248 =	22.292323
-----				
			T.E =	37.596341
4107	4107			
081		1.200000 x	11.010000 =	13.212000
001		2.000000 x	16.829739 =	33.659478
003		3.000000 x	24.769248 =	74.307744
-----				
			T.E =	121.179222
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	16.829739 =	48.806243
003		4.000000 x	24.769248 =	99.076992
-----				
			T.E =	170.320865
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.134450 =	14.047058
003		2.500000 x	24.769248 =	61.923120
001		2.900000 x	16.829739 =	48.806243
-----				
			T.E =	137.437921
4206	4206			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	16.829739 =	48.806243
003		3.100000 x	24.769248 =	76.784669
1417		.350000 x	40.134450 =	14.047058
-----				
			T.E =	152.299469
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	16.829739 =	48.806243
1417		.350000 x	40.134450 =	14.047058
003		4.000000 x	24.769248 =	99.076992
-----				
			T.E =	174.591793

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	16.829739 =	48.806243	
1447		.350000 x	58.635900 =	20.522565	
003		2.500000 x	24.769248 =	61.923120	
		-----			
			T.E =	143.913428	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	58.635900 =	20.522565	
003		3.100000 x	24.769248 =	76.784669	
001		2.900000 x	16.829739 =	48.806243	
		-----			
			T.E =	158.774977	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	58.635900 =	20.522565	
001		2.900000 x	16.829739 =	48.806243	
003		4.000000 x	24.769248 =	99.076992	
		-----			
			T.E =	181.067300	
4221	4221				
001		.800000 x	16.829739 =	13.463791	
003		1.000000 x	24.769248 =	24.769248	
		-----			
			T.E =	38.233039	
4222	4222				
001		.400000 x	16.829739 =	6.731896	
003		.400000 x	24.769248 =	9.907699	
		-----			
			T.E =	16.639595	
4226	4226				
003		1.300000 x	24.769248 =	32.200022	
		-----			
			T.E =	32.200022	
4251	4251				
083		32.000000 x	.000000 =	.000000	
1412		.200000 x	27.931800 =	5.586360	
001		2.900000 x	16.829739 =	48.806243	
003		4.000000 x	24.769248 =	99.076992	
		-----			
			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
1417		.200000 x	40.134450 =	8.026890
003		4.000000 x	24.769248 =	99.076992
001		2.900000 x	16.829739 =	48.806243

-----  
T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	61.496500 =	12.299300
003		4.000000 x	24.769248 =	99.076992
001		2.900000 x	16.829739 =	48.806243

-----  
T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
003		4.000000 x	24.769248 =	99.076992
001		2.900000 x	16.829739 =	48.806243
1447		.200000 x	58.635900 =	11.727180

-----  
T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	16.829739 =	16.829739

-----  
T.E =

4301	4301			17.264739
081		1.020000 x	11.010000 =	11.230200
1412		.350000 x	27.931800 =	9.776130
003		4.200000 x	24.769248 =	104.030842
001		2.900000 x	16.829739 =	48.806243
083		5.000000 x	.000000 =	.000000

-----  
T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
1417		.350000 x	40.134450 =	14.047058
003		2.700000 x	24.769248 =	66.876970
001		2.900000 x	16.829739 =	48.806243
083		2.000000 x	.000000 =	.000000

-----  
T.E =

4306	4306			
081		1.050000 x	11.010000 =	11.560500
1417		.350000 x	40.134450 =	14.047058
003		3.300000 x	24.769248 =	81.738518
083		3.000000 x	.000000 =	.000000
001		2.900000 x	16.829739 =	48.806243

-----  
T.E =

4307	4307			
081		1.020000 x	11.010000 =	11.230200
001		2.900000 x	16.829739 =	48.806243
1417		.350000 x	40.134450 =	14.047058
003		4.200000 x	24.769248 =	104.030842
083		5.000000 x	.000000 =	.000000

-----  
T.E =

4311	4311			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
003		2.700000 x	24.769248 =	66.876970
1447		.350000 x	58.635900 =	20.522565
001		2.900000 x	16.829739 =	48.806243

-----  
T.E =

4312	4312			
081		1.050000 x	11.010000 =	11.560500
083		3.000000 x	.000000 =	.000000
1447		.350000 x	58.635900 =	20.522565
003		3.300000 x	24.769248 =	81.738518
001		2.900000 x	16.829739 =	48.806243

-----  
T.E =

4313	4313			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	58.635900 =	20.522565
003		2.700000 x	24.769248 =	66.876970
001		2.900000 x	16.829739 =	48.806243
083		2.000000 x	.000000 =	.000000

-----  
T.E =

4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	16.829739 =	16.829739

-----  
T.E = 17.264739



4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
001		10.000000 x	16.829739 =	168.297390
003		25.000000 x	24.769248 =	619.231200
1446		.100000 x	52.530500 =	5.253050
251		4.000000 x	.695000 =	2.780000

-----  
T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
1446		.100000 x	52.530500 =	5.253050
003		25.000000 x	24.769248 =	619.231200
001		10.000000 x	16.829739 =	168.297390
251		4.000000 x	.695000 =	2.780000

-----  
T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
251		4.000000 x	.695000 =	2.780000
001		10.000000 x	16.829739 =	168.297390
1446		.100000 x	52.530500 =	5.253050
003		25.000000 x	24.769248 =	619.231200

-----  
T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
1446		.200000 x	52.530500 =	10.506100
251		8.000000 x	.695000 =	5.560000
003		32.000000 x	24.769248 =	792.615936
001		11.000000 x	16.829739 =	185.127129

-----  
T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
251		8.000000 x	.695000 =	5.560000
003		32.000000 x	24.769248 =	792.615936
1446		.200000 x	52.530500 =	10.506100
001		11.000000 x	16.829739 =	185.127129

-----  
T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.530500 =	10.506100
003		32.000000 x	24.769248 =	792.615936
001		11.000000 x	16.829739 =	185.127129
251		8.000000 x	.695000 =	5.560000
		-----		
			T.E =	
4401	4401			
001		1.200000 x	16.829739 =	20.195687
		-----		
			T.E =	20.195687
4402	4402			
001		3.000000 x	16.829739 =	50.489217
		-----		
			T.E =	50.489217
4501	4501			
081		.050000 x	11.010000 =	.550500
002		.500000 x	18.705943 =	9.352972
003		1.000000 x	24.769248 =	24.769248
		-----		
			T.E =	34.672720
4502	4502			
081		.050000 x	11.010000 =	.550500
002		.500000 x	18.705943 =	9.352972
003		1.300000 x	24.769248 =	32.200022
		-----		
			T.E =	42.103494
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	18.705943 =	9.352972
003		1.400000 x	24.769248 =	34.676947
		-----		
			T.E =	44.580419
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		2.300000 x	24.769248 =	56.969270
		-----		
			T.E =	63.131553

4505	4505				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		2.700000 x	24.769248 =	66.876970	
-----					
			T.E =	73.039253	
4506	4506				
081		.050000 x	11.010000 =	.550500	
003		3.600000 x	24.769248 =	89.169293	
002		.300000 x	18.705943 =	5.611783	
-----					
			T.E =	95.331576	
4507	4507				
081		.050000 x	11.010000 =	.550500	
003		3.200000 x	24.769248 =	79.261594	
002		.300000 x	18.705943 =	5.611783	
-----					
			T.E =	85.423877	
4508	4508				
081		.050000 x	11.010000 =	.550500	
003		3.000000 x	24.769248 =	74.307744	
002		.300000 x	18.705943 =	5.611783	
-----					
			T.E =	80.470027	
4511	4511				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		3.800000 x	24.769248 =	94.123142	
-----					
			T.E =	100.285425	
4512	4512				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		4.000000 x	24.769248 =	99.076992	
-----					
			T.E =	105.239275	
4515	4515				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	18.705943 =	5.611783	
003		5.000000 x	24.769248 =	123.846240	
-----					
			T.E =	130.008523	

4516	4516			
081		.050000 x	11.010000 =	.550500
003		4.500000 x	24.769248 =	111.461616
002		.300000 x	18.705943 =	5.611783
-----				
			T.E =	117.623899
4517	4517			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		6.500000 x	24.769248 =	161.000112
-----				
			T.E =	167.162395
4518	4518			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		5.700000 x	24.769248 =	141.184714
-----				
			T.E =	147.346997
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		5.200000 x	24.769248 =	128.800090
-----				
			T.E =	134.962373
4521	4521			
081		.050000 x	11.010000 =	.550500
003		3.500000 x	24.769248 =	86.692368
002		.300000 x	18.705943 =	5.611783
-----				
			T.E =	92.854651
4522	4522			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		2.700000 x	24.769248 =	66.876970
-----				
			T.E =	73.039253
4525	4525			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		4.500000 x	24.769248 =	111.461616
-----				
			T.E =	117.623899

4526	4526			
081		.050000 x	11.010000 =	.550500
002		.300000 x	18.705943 =	5.611783
003		4.000000 x	24.769248 =	99.076992
-----				
			T.E =	105.239275
4527	4527			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	24.769248 =	148.615488
002		.300000 x	18.705943 =	5.611783
-----				
			T.E =	154.777771
4528	4528			
081		.050000 x	11.010000 =	.550500
003		5.200000 x	24.769248 =	128.800090
002		.300000 x	18.705943 =	5.611783
-----				
			T.E =	134.962373
4529	4529			
081		.050000 x	11.010000 =	.550500
003		4.700000 x	24.769248 =	116.415466
002		.300000 x	18.705943 =	5.611783
-----				
			T.E =	122.577749
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	24.769248 =	61.923120
-----				
			T.E =	62.473620
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	24.769248 =	49.538496
-----				
			T.E =	50.088996
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	24.769248 =	94.123142
-----				
			T.E =	94.673642
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	24.769248 =	76.784669
-----				
			T.E =	77.335169

4537	4537			
081		.050000 x	11.010000 =	.550500
003		5.500000 x	24.769248 =	136.230864
-----				
			T.E =	136.781364
4538	4538			
081		.050000 x	11.010000 =	.550500
003		4.600000 x	24.769248 =	113.938541
-----				
			T.E =	114.489041
4539	4539			
081		.050000 x	11.010000 =	.550500
003		4.200000 x	24.769248 =	104.030842
-----				
			T.E =	104.581342
4541	4541			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	24.769248 =	61.923120
-----				
			T.E =	62.473620
4542	4542			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	24.769248 =	49.538496
-----				
			T.E =	50.088996
4543	4543			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	24.769248 =	99.076992
-----				
			T.E =	99.627492
4544	4544			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	24.769248 =	148.615488
-----				
			T.E =	149.165988
4601.1	4601.1			
101		105.000000 x	.000000 =	.000000
001		.600000 x	16.829739 =	10.097843
1417		.023000 x	40.134450 =	.923092
003		.700000 x	24.769248 =	17.338474
-----				
			T.E =	

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
1447		.023000 x	58.635900 =	1.348626
003		.700000 x	24.769248 =	17.338474
001		.600000 x	16.829739 =	10.097843

-----  
T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
1417		.056000 x	40.134450 =	2.247529
003		1.300000 x	24.769248 =	32.200022
001		1.300000 x	16.829739 =	21.878661

-----  
T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	16.829739 =	21.878661
1447		.056000 x	58.635900 =	3.283610
003		1.300000 x	24.769248 =	32.200022

-----  
T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	16.829739 =	31.976504
1417		.089000 x	40.134450 =	3.571966
003		1.800000 x	24.769248 =	44.584646

-----  
T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	16.829739 =	31.976504
1447		.089000 x	58.635900 =	5.218595
003		1.800000 x	24.769248 =	44.584646

-----  
T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
1417		.332000 x	40.134450 =	13.324637
003		5.500000 x	24.769248 =	136.230864
001		6.300000 x	16.829739 =	106.027356

-----  
T.E =

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	16.829739 =	106.027356
1447		.332000 x	58.635900 =	19.467119
003		5.500000 x	24.769248 =	136.230864

-----  
T.E =

4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	40.134450 =	1.204034
003		.700000 x	24.769248 =	17.338474
001		.700000 x	16.829739 =	11.780817

-----  
T.E =

4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
1447		.030000 x	58.635900 =	1.759077
003		.700000 x	24.769248 =	17.338474
001		.700000 x	16.829739 =	11.780817

-----  
T.E =

4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
1417		.070000 x	40.134450 =	2.809412
003		1.300000 x	24.769248 =	32.200022
001		1.400000 x	16.829739 =	23.561635

-----  
T.E =

4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	16.829739 =	23.561635
1447		.070000 x	58.635900 =	4.104513
003		1.300000 x	24.769248 =	32.200022

-----  
T.E =

4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	16.829739 =	35.342452
1417		.110000 x	40.134450 =	4.414790
003		1.800000 x	24.769248 =	44.584646

-----  
T.E =



4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	16.829739 =	35.342452
1447		.110000 x	58.635900 =	6.449949
003		1.800000 x	24.769248 =	44.584646

-----  
T.E =

4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
1417		.404000 x	40.134450 =	16.214318
003		5.500000 x	24.769248 =	136.230864
001		6.500000 x	16.829739 =	109.393304

-----  
T.E =

4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	16.829739 =	109.393304
1447		.404000 x	58.635900 =	23.688904
003		5.500000 x	24.769248 =	136.230864

-----  
T.E =

4621.1	4621.1			
111		53.000000 x	.078400 =	4.155200
001		.400000 x	16.829739 =	6.731896
1417		.010000 x	40.134450 =	.401345
003		.500000 x	24.769248 =	12.384624

-----  
T.E = 23.673064

4621.2	4621.2			
111		53.000000 x	.078400 =	4.155200
001		.400000 x	16.829739 =	6.731896
1447		.010000 x	58.635900 =	.586359
003		.500000 x	24.769248 =	12.384624

-----  
T.E = 23.858079

4622.1	4622.1			
111		75.000000 x	.078400 =	5.880000
1417		.020000 x	40.134450 =	.802689
003		.500000 x	24.769248 =	12.384624
001		.450000 x	16.829739 =	7.573383

-----  
T.E = 26.640696

4622.2	4622.2			
111		75.000000 x	.078400 =	5.880000
001		.450000 x	16.829739 =	7.573383
1447		.020000 x	58.635900 =	1.172718
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	27.010725
4623.1	4623.1			
111		150.000000 x	.078400 =	11.760000
001		.950000 x	16.829739 =	15.988252
1417		.050000 x	40.134450 =	2.006723
003		.950000 x	24.769248 =	23.530786
		-----		
			T.E =	53.285760
4623.2	4623.2			
111		150.000000 x	.078400 =	11.760000
001		.950000 x	16.829739 =	15.988252
1447		.050000 x	58.635900 =	2.931795
003		.950000 x	24.769248 =	23.530786
		-----		
			T.E =	54.210833
4624.1	4624.1			
111		225.000000 x	.078400 =	17.640000
1417		.085000 x	40.134450 =	3.411428
003		1.300000 x	24.769248 =	32.200022
001		1.500000 x	16.829739 =	25.244609
		-----		
			T.E =	78.496059
4624.2	4624.2			
111		225.000000 x	.078400 =	17.640000
1447		.085000 x	58.635900 =	4.984052
003		1.300000 x	24.769248 =	32.200022
001		1.500000 x	16.829739 =	25.244609
		-----		
			T.E =	80.068682
4625.1	4625.1			
111		750.000000 x	.078400 =	58.800000
003		4.300000 x	24.769248 =	106.507766
001		5.200000 x	16.829739 =	87.514643
1417		.320000 x	40.134450 =	12.843024
		-----		
			T.E =	265.665433

4625.2	4625.2			
111		750.000000 x	.078400 =	58.800000
003		4.300000 x	24.769248 =	106.507766
001		5.200000 x	16.829739 =	87.514643
1447		.320000 x	58.635900 =	18.763488
		-----		
			T.E =	271.585897
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000
		-----		
			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000
-----				
			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	26.640696 =	58.609531
-----				
			T.E =	58.609531
4633.2	4633.2			
4622.2		2.200000 x	27.010725 =	59.423595
-----				
			T.E =	59.423595
4634.1	4634.1			
4622.1		1.200000 x	26.640696 =	31.968835
4623.1		1.000000 x	53.285760 =	53.285760
-----				
			T.E =	85.254595
4634.2	4634.2			
4622.2		1.200000 x	27.010725 =	32.412870
4623.2		1.000000 x	54.210833 =	54.210833
-----				
			T.E =	86.623703
4661.1	4661.1			
112		43.750000 x	.087900 =	3.845625
003		.500000 x	24.769248 =	12.384624
1417		.014507 x	40.134450 =	.582230
001		.400000 x	16.829739 =	6.731896
-----				
			T.E =	23.544375
4661.2	4661.2			
112		43.750000 x	.087900 =	3.845625
1447		.014507 x	58.635900 =	.850631
003		.500000 x	24.769248 =	12.384624
001		.400000 x	16.829739 =	6.731896
-----				
			T.E =	23.812776
4662.1	4662.1			
112		58.333300 x	.087900 =	5.127497
1417		.022840 x	40.134450 =	.916671
001		.450000 x	16.829739 =	7.573383
003		.500000 x	24.769248 =	12.384624
-----				
			T.E =	26.002174

4662.2	4662.2			
112		58.333300 x	.087900 =	5.127497
003		.500000 x	24.769248 =	12.384624
1447		.022840 x	58.635900 =	1.339244
001		.450000 x	16.829739 =	7.573383
		-----		
			T.E =	26.424748
4663.1	4663.1			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	16.829739 =	15.146765
003		.900000 x	24.769248 =	22.292323
1417		.043218 x	40.134450 =	1.734531
		-----		
			T.E =	48.403119
4663.2	4663.2			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	16.829739 =	15.146765
1447		.043218 x	58.635900 =	2.534126
003		.900000 x	24.769248 =	22.292323
		-----		
			T.E =	49.202715
4664.1	4664.1			
112		97.222221 x	.087900 =	8.545833
1417		.045077 x	40.134450 =	1.809141
003		.950000 x	24.769248 =	23.530786
001		.950000 x	16.829739 =	15.988252
		-----		
			T.E =	49.874011
4664.2	4664.2			
112		97.222221 x	.087900 =	8.545833
001		.950000 x	16.829739 =	15.988252
1447		.045077 x	58.635900 =	2.643130
003		.950000 x	24.769248 =	23.530786
		-----		
			T.E =	50.708001
4665.1	4665.1			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	16.829739 =	25.244609
1417		.047530 x	40.134450 =	1.907590
003		1.300000 x	24.769248 =	32.200022
		-----		
			T.E =	74.734633

4665.2	4665.2			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	16.829739 =	25.244609
1447		.047530 x	58.635900 =	2.786964
003		1.300000 x	24.769248 =	32.200022
		-----		
			T.E =	75.614007
4666.1	4666.1			
112		486.111099 x	.087900 =	42.729166
1417		.277862 x	40.134450 =	11.151839
003		4.300000 x	24.769248 =	106.507766
001		5.200000 x	16.829739 =	87.514643
		-----		
			T.E =	247.903413
4666.2	4666.2			
112		486.111000 x	.087900 =	42.729157
001		5.200000 x	16.829739 =	87.514643
1447		.277862 x	58.635900 =	16.292688
003		4.300000 x	24.769248 =	106.507766
		-----		
			T.E =	253.044255
4701	4701			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	16.829739 =	8.414870
1417		.020000 x	40.134450 =	.802689
003		.400000 x	24.769248 =	9.907699
		-----		
			T.E =	26.535258
4702	4702			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	16.829739 =	8.414870
1447		.020000 x	58.635900 =	1.172718
003		.400000 x	24.769248 =	9.907699
		-----		
			T.E =	26.905287
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	40.134450 =	.602017
003		.350000 x	24.769248 =	8.669237
001		.400000 x	16.829739 =	6.731896
		-----		
			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
001		.400000 x	16.829739 =	6.731896
1447		.015000 x	58.635900 =	.879539
003		.350000 x	24.769248 =	8.669237

-----  
T.E =

4711	4711			
117		13.000000 x	.000000 =	.000000
001		.500000 x	16.829739 =	8.414870
1417		.020000 x	40.134450 =	.802689
003		.400000 x	24.769248 =	9.907699

-----  
T.E =

4712	4712			
117		13.000000 x	.000000 =	.000000
001		.500000 x	16.829739 =	8.414870
1447		.020000 x	58.635900 =	1.172718
003		.400000 x	24.769248 =	9.907699

-----  
T.E =

4713	4713			
118		13.000000 x	.000000 =	.000000
1417		.015000 x	40.134450 =	.602017
003		.350000 x	24.769248 =	8.669237
001		.400000 x	16.829739 =	6.731896

-----  
T.E =

4714	4714			
118		13.000000 x	.000000 =	.000000
001		.400000 x	16.829739 =	6.731896
1447		.015000 x	58.635900 =	.879539
003		.350000 x	24.769248 =	8.669237

-----  
T.E =

4721.1	4721.1			
128		.080000 x	90.430000 =	7.234400
001		.300000 x	16.829739 =	5.048922
1417		.004000 x	40.134450 =	.160538
003		.350000 x	24.769248 =	8.669237

-----  
T.E = 21.113096

4721.2	4721.2				
128		.080000 x	90.430000 =	7.234400	
001		.300000 x	16.829739 =	5.048922	
1447		.004000 x	58.635900 =	.234544	
003		.350000 x	24.769248 =	8.669237	
			T.E =	21.187102	
4722.1	4722.1				
128		.100000 x	90.430000 =	9.043000	
1417		.005000 x	40.134450 =	.200672	
003		.350000 x	24.769248 =	8.669237	
001		.350000 x	16.829739 =	5.890409	
			T.E =	23.803318	
4722.2	4722.2				
128		.100000 x	90.430000 =	9.043000	
1447		.005000 x	58.635900 =	.293180	
001		.350000 x	16.829739 =	5.890409	
003		.350000 x	24.769248 =	8.669237	
			T.E =	23.895825	
4723	4723				
128		.120000 x	90.430000 =	10.851600	
003		.350000 x	24.769248 =	8.669237	
1417		.006000 x	40.134450 =	.240807	
001		.400000 x	16.829739 =	6.731896	
			T.E =	26.493539	
4724.1	4724.1				
128		.150000 x	90.430000 =	13.564500	
001		.400000 x	16.829739 =	6.731896	
1417		.008000 x	40.134450 =	.321076	
003		.400000 x	24.769248 =	9.907699	
			T.E =	30.525170	
4724.2	4724.2				
128		.150000 x	90.430000 =	13.564500	
001		.400000 x	16.829739 =	6.731896	
1447		.008000 x	58.635900 =	.469087	
003		.400000 x	24.769248 =	9.907699	
			T.E =	30.673182	



4725.1	4725.1			
128		.180000 x	90.430000 =	16.277400
1417		.009000 x	40.134450 =	.361210
003		.400000 x	24.769248 =	9.907699
001		.450000 x	16.829739 =	7.573383
		-----		
			T.E =	34.119692
4725.2	4725.2			
128		.180000 x	90.430000 =	16.277400
001		.450000 x	16.829739 =	7.573383
1447		.009000 x	58.635900 =	.527723
003		.400000 x	24.769248 =	9.907699
		-----		
			T.E =	34.286205
4801.1	4801.1			
4662.1		1.000000 x	26.002174 =	26.002174
4662.1		.100000 x	26.002174 =	2.600217
		-----		
			T.E =	28.602391
4801.2	4801.2			
4662.2		1.000000 x	26.424748 =	26.424748
4662.2		.100000 x	26.424748 =	2.642475
		-----		
			T.E =	29.067223
4802.1	4802.1			
4664.1		1.000000 x	49.874011 =	49.874011
4664.1		.050000 x	49.874011 =	2.493701
		-----		
			T.E =	52.367712
4802.2	4802.2			
4664.2		1.000000 x	50.708001 =	50.708001
4664.2		.050000 x	50.708001 =	2.535400
		-----		
			T.E =	53.243401
4803.1	4803.1			
4665.1		1.000000 x	74.734633 =	74.734633
4665.1		.030000 x	74.734633 =	2.242039
		-----		
			T.E =	76.976672
4803.2	4803.2			
4665.2		1.000000 x	75.614007 =	75.614007
4665.2		.030000 x	75.614007 =	2.268420
		-----		
			T.E =	77.882427

4811.1	4811.1				
001		.225000 x	16.829739 =	3.786691	
4662.1		1.000000 x	26.002174 =	26.002174	
003		.250000 x	24.769248 =	6.192312	
		-----			
			T.E =	35.981177	
4811.2	4811.2				
001		.225000 x	16.829739 =	3.786691	
003		.250000 x	24.769248 =	6.192312	
4662.2		1.000000 x	26.424748 =	26.424748	
		-----			
			T.E =	36.403751	
4812.1	4812.1				
001		.475000 x	16.829739 =	7.994126	
003		.475000 x	24.769248 =	11.765393	
4664.1		1.000000 x	49.874011 =	49.874011	
		-----			
			T.E =	69.633530	
4812.2	4812.2				
001		.475000 x	16.829739 =	7.994126	
003		.475000 x	24.769248 =	11.765393	
4664.2		1.000000 x	50.708001 =	50.708001	
		-----			
			T.E =	70.467520	
4813.1	4813.1				
001		.750000 x	16.829739 =	12.622304	
4665.1		1.000000 x	74.734633 =	74.734633	
003		.650000 x	24.769248 =	16.100011	
		-----			
			T.E =	103.456948	
4813.2	4813.2				
001		.750000 x	16.829739 =	12.622304	
003		.650000 x	24.769248 =	16.100011	
4665.2		1.000000 x	75.614007 =	75.614007	
		-----			
			T.E =	104.336322	
4814.1	4814.1				
001		2.600000 x	16.829739 =	43.757321	
003		2.150000 x	24.769248 =	53.253883	
4666.1		1.000000 x	247.903413 =	247.903413	
		-----			
			T.E =	344.914618	

4814.2	4814.2			
001		2.600000 x	16.829739 =	43.757321
003		2.150000 x	24.769248 =	53.253883
4666.2		1.000000 x	253.044255 =	253.044255
		-----		
			T.E =	350.055460
4821.1	4821.1			
003		.450000 x	24.769248 =	11.146162
4662.1		1.000000 x	26.002174 =	26.002174
		-----		
			T.E =	37.148336
4821.2	4821.2			
003		.450000 x	24.769248 =	11.146162
4662.2		1.000000 x	26.424748 =	26.424748
		-----		
			T.E =	37.570910
4822.1	4822.1			
003		.807500 x	24.769248 =	20.001168
4664.1		1.000000 x	49.874011 =	49.874011
		-----		
			T.E =	69.875179
4822.2	4822.2			
003		.807500 x	24.769248 =	20.001168
4664.2		1.000000 x	50.708001 =	50.708001
		-----		
			T.E =	70.709169
4823.1	4823.1			
003		1.040000 x	24.769248 =	25.760018
4665.1		1.000000 x	74.734633 =	74.734633
		-----		
			T.E =	100.494651
4823.2	4823.2			
003		1.040000 x	24.769248 =	25.760018
4665.2		1.000000 x	75.614007 =	75.614007
		-----		
			T.E =	101.374025
4824.1	4824.1			
003		3.010000 x	24.769248 =	74.555436
4666.1		1.000000 x	247.903413 =	247.903413
		-----		
			T.E =	322.458849

4824.2	4824.2			
003		3.010000 x	24.769248 =	74.555436
4666.2		1.000000 x	253.044255 =	253.044255
-----				
			T.E =	327.599691
4831.1	4831.1			
003		1.200000 x	24.769248 =	29.723098
4661.1		1.000000 x	23.544375 =	23.544375
-----				
			T.E =	53.267473
4831.2	4831.2			
003		1.200000 x	24.769248 =	29.723098
4661.2		1.000000 x	23.812776 =	23.812776
-----				
			T.E =	53.535874
4832.1	4832.1			
003		1.600000 x	24.769248 =	39.630797
4662.1		1.000000 x	26.002174 =	26.002174
-----				
			T.E =	65.632971
4832.2	4832.2			
003		1.600000 x	24.769248 =	39.630797
4662.2		1.000000 x	26.424748 =	26.424748
-----				
			T.E =	66.055545
4833.1	4833.1			
002		2.000000 x	18.705943 =	37.411886
4664.1		1.000000 x	49.874011 =	49.874011
-----				
			T.E =	87.285897
4833.2	4833.2			
002		2.000000 x	18.705943 =	37.411886
4664.2		1.000000 x	50.708001 =	50.708001
-----				
			T.E =	88.119887
4834.1	4834.1			
003		2.300000 x	24.769248 =	56.969270
4665.1		1.000000 x	74.734633 =	74.734633
-----				
			T.E =	131.703903

4834.2 4834.2

003	2.300000 x	24.769248 =	56.969270
4665.2	1.000000 x	75.614007 =	75.614007

-----  
T.E = 132.583277

4835 4835

122	1.050000 x	.000000 =	.000000
1417	.005000 x	40.134450 =	.200672
003	1.000000 x	24.769248 =	24.769248
201	.010000 x	290.000000 =	2.900000
001	1.000000 x	16.829739 =	16.829739
265	2.000000 x	.691500 =	1.383000

-----  
T.E =

4835.2 4835.2

122	1.050000 x	.000000 =	.000000
001	1.000000 x	16.829739 =	16.829739
201	.010000 x	290.000000 =	2.900000
1447	.005000 x	58.635900 =	.293180
003	1.000000 x	24.769248 =	24.769248
265	2.000000 x	.691500 =	1.383000

-----  
T.E =

4836.1 4836.1

123	1.050000 x	.000000 =	.000000
1417	.005000 x	40.134450 =	.200672
003	1.000000 x	24.769248 =	24.769248
001	1.000000 x	16.829739 =	16.829739
265	2.000000 x	.691500 =	1.383000
201	.010000 x	290.000000 =	2.900000

-----  
T.E =

4836.2 4836.2

123	1.050000 x	.000000 =	.000000
201	.010000 x	290.000000 =	2.900000
265	2.000000 x	.691500 =	1.383000
1447	.005000 x	58.635900 =	.293180
003	1.000000 x	24.769248 =	24.769248
001	1.000000 x	16.829739 =	16.829739

-----  
T.E =

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
1417		.010000 x	40.134450 =	.401345
003		1.000000 x	24.769248 =	24.769248
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	16.829739 =	16.829739
265		2.000000 x	.691500 =	1.383000
		-----		
			T.E =	52.478332
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
201		.010000 x	290.000000 =	2.900000
1447		.010000 x	58.635900 =	.586359
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
265		2.000000 x	.691500 =	1.383000
		-----		
			T.E =	54.539550
4841	4841			
003		.700000 x	24.769248 =	17.338474
		-----		
			T.E =	17.338474
4842	4842			
003		1.000000 x	24.769248 =	24.769248
		-----		
			T.E =	24.769248
4843	4843			
003		.250000 x	24.769248 =	6.192312
		-----		
			T.E =	6.192312
4844	4844			
131		1,200.000000 x	.650000 =	780.000000
1401		.250000 x	234.711000 =	58.677750
003		25.000000 x	24.769248 =	619.231200
001		10.000000 x	16.829739 =	168.297390
		-----		
			T.E =	1,626.206340
4845	4845			
132		620.000000 x	.930000 =	576.600000
001		6.000000 x	16.829739 =	100.978434
1401		.180000 x	234.711000 =	42.247980
003		15.000000 x	24.769248 =	371.538720
		-----		
			T.E =	1,091.365134

4851	4851			
001		.100000 x	16.829739 =	1.682974
		-----		
			T.E =	1.682974
4852	4852			
001		.150000 x	16.829739 =	2.524461
		-----		
			T.E =	2.524461
4853	4853			
001		.200000 x	16.829739 =	3.365948
		-----		
			T.E =	3.365948
4854	4854			
001		.250000 x	16.829739 =	4.207435
		-----		
			T.E =	4.207435
4855	4855			
001		.300000 x	16.829739 =	5.048922
		-----		
			T.E =	5.048922
4856	4856			
001		.800000 x	16.829739 =	13.463791
		-----		
			T.E =	13.463791
4857	4857			
001		.200000 x	16.829739 =	3.365948
		-----		
			T.E =	3.365948
4858	4858			
001		.300000 x	16.829739 =	5.048922
		-----		
			T.E =	5.048922
4859	4859			
001		.400000 x	16.829739 =	6.731896
		-----		
			T.E =	6.731896
4860	4860			
001		.500000 x	16.829739 =	8.414870
		-----		
			T.E =	8.414870

4861	4861			
001		.600000 x	16.829739 =	10.097843
		-----		
			T.E =	10.097843
4862	4862			
001		1.700000 x	16.829739 =	28.610556
		-----		
			T.E =	28.610556
5101	5101			
214		1.100000 x	.000000 =	.000000
003		4.000000 x	24.769248 =	99.076992
001		1.000000 x	16.829739 =	16.829739
		-----		
			T.E =	
5102	5102			
483		1.800000 x	.165000 =	.297000
491		1.260000 x	.540000 =	.680400
488		.540000 x	5.000000 =	2.700000
489		.360000 x	.000000 =	.000000
001		1.000000 x	16.829739 =	16.829739
492		1.440000 x	.540000 =	.777600
		-----		
			T.E =	
5103	5103			
265		1.050000 x	.691500 =	.726075
003		.200000 x	24.769248 =	4.953850
002		.050000 x	18.705943 =	.935297
		-----		
			T.E =	6.615222
5104	5104			
001		2.000000 x	16.829739 =	33.659478
003		.150000 x	24.769248 =	3.715387
		-----		
			T.E =	37.374865
5105	5105			
214		.010000 x	.000000 =	.000000
003		.500000 x	24.769248 =	12.384624
001		2.000000 x	16.829739 =	33.659478
		-----		
			T.E =	



5106	5106			
214		.050000 x	.000000 =	.000000
001		2.000000 x	16.829739 =	33.659478
003		2.500000 x	24.769248 =	61.923120
-----				
			T.E =	
5201	5201			
201		1.100000 x	290.000000 =	319.000000
002		5.000000 x	18.705943 =	93.529715
251		6.000000 x	.695000 =	4.170000
003		10.000000 x	24.769248 =	247.692480
-----				
			T.E =	664.392195
5202	5202			
203.2		1.080000 x	335.000000 =	361.800000
251		6.000000 x	.695000 =	4.170000
003		9.000000 x	24.769248 =	222.923232
002		4.500000 x	18.705943 =	84.176744
-----				
			T.E =	673.069976
5203	5203			
201		1.120000 x	290.000000 =	324.800000
003		16.000000 x	24.769248 =	396.307968
002		8.000000 x	18.705943 =	149.647544
251		12.000000 x	.695000 =	8.340000
-----				
			T.E =	879.095512
5204	5204			
203.2		1.100000 x	335.000000 =	368.500000
002		7.000000 x	18.705943 =	130.941601
003		14.000000 x	24.769248 =	346.769472
251		12.000000 x	.695000 =	8.340000
-----				
			T.E =	854.551073
5211	5211			
201		1.100000 x	290.000000 =	319.000000
251		14.000000 x	.695000 =	9.730000
003		12.000000 x	24.769248 =	297.230976
002		6.000000 x	18.705943 =	112.235658
-----				
			T.E =	738.196634

5212	5212				
203.2		1.080000 x	335.000000 =	361.800000	
251		14.000000 x	.695000 =	9.730000	
003		10.000000 x	24.769248 =	247.692480	
002		5.000000 x	18.705943 =	93.529715	
		-----			
			T.E =	712.752195	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
003		9.000000 x	24.769248 =	222.923232	
002		4.500000 x	18.705943 =	84.176744	
251		8.000000 x	.695000 =	5.560000	
		-----			
			T.E =	631.659976	
5221	5221				
203.2		.014000 x	335.000000 =	4.690000	
251		.100000 x	.695000 =	.069500	
002		.050000 x	18.705943 =	.935297	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	10.648647	
5222	5222				
203.2		.018000 x	335.000000 =	6.030000	
251		.100000 x	.695000 =	.069500	
003		.200000 x	24.769248 =	4.953850	
002		.070000 x	18.705943 =	1.309416	
		-----			
			T.E =	12.362766	
5223	5223				
203.2		.026000 x	335.000000 =	8.710000	
251		.100000 x	.695000 =	.069500	
003		.200000 x	24.769248 =	4.953850	
002		.100000 x	18.705943 =	1.870594	
		-----			
			T.E =	15.603944	
5226	5226				
203.2		.016000 x	335.000000 =	5.360000	
003		.200000 x	24.769248 =	4.953850	
002		.050000 x	18.705943 =	.935297	
251		.100000 x	.695000 =	.069500	
		-----			
			T.E =	11.318647	

5227	5227				
203.2		.022000 x	335.000000 =	7.370000	
251		.100000 x	.695000 =	.069500	
002		.100000 x	18.705943 =	1.870594	
003		.200000 x	24.769248 =	4.953850	
-----					
			T.E =	14.263944	
5228	5228				
203.2		.030000 x	335.000000 =	10.050000	
251		.150000 x	.695000 =	.104250	
003		.200000 x	24.769248 =	4.953850	
002		.150000 x	18.705943 =	2.805891	
-----					
			T.E =	17.913991	
5231	5231				
203.2		.018000 x	335.000000 =	6.030000	
251		.150000 x	.695000 =	.104250	
003		.250000 x	24.769248 =	6.192312	
002		.100000 x	18.705943 =	1.870594	
-----					
			T.E =	14.197156	
5232	5232				
203.2		.025000 x	335.000000 =	8.375000	
003		.250000 x	24.769248 =	6.192312	
002		.120000 x	18.705943 =	2.244713	
251		.150000 x	.695000 =	.104250	
-----					
			T.E =	16.916275	
5233	5233				
203.2		.034000 x	335.000000 =	11.390000	
251		.200000 x	.695000 =	.139000	
002		.150000 x	18.705943 =	2.805891	
003		.250000 x	24.769248 =	6.192312	
-----					
			T.E =	20.527203	
5236	5236				
203.2		.016000 x	335.000000 =	5.360000	
251		.080000 x	.695000 =	.055600	
003		.350000 x	24.769248 =	8.669237	
002		.250000 x	18.705943 =	4.676486	
-----					
			T.E =	18.761323	

5237	5237				
203.2		.022000 x	335.000000 =		7.370000
251		.080000 x	.695000 =		.055600
003		.350000 x	24.769248 =		8.669237
002		.300000 x	18.705943 =		5.611783
		-----			
			T.E =		21.706620
5238	5238				
203.2		.030000 x	335.000000 =		10.050000
003		.350000 x	24.769248 =		8.669237
002		.350000 x	18.705943 =		6.547080
251		.100000 x	.695000 =		.069500
		-----			
			T.E =		25.335817
5241	5241				
203.2		.030000 x	335.000000 =		10.050000
002		.500000 x	18.705943 =		9.352972
003		.500000 x	24.769248 =		12.384624
251		.100000 x	.695000 =		.069500
		-----			
			T.E =		31.857096
5243	5243				
003		.150000 x	24.769248 =		3.715387
		-----			
			T.E =		3.715387
5244	5244				
003		.350000 x	24.769248 =		8.669237
		-----			
			T.E =		8.669237
5246	5246				
220		26.000000 x	.000000 =		.000000
002		.500000 x	18.705943 =		9.352972
251		.200000 x	.695000 =		.139000
		-----			
			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
283		.100000 x	1.036900 =		.103690
002		.600000 x	18.705943 =		11.223566
251		.100000 x	.695000 =		.069500
		-----			
			T.E =		

5251	5251				
243.3		1.050000 x	4.450000 =	4.672500	
003		.300000 x	24.769248 =	7.430774	
002		.300000 x	18.705943 =	5.611783	
251		.100000 x	.695000 =	.069500	
		-----			
			T.E =	17.784557	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
245		.110000 x	18.600000 =	2.046000	
002		2.500000 x	18.705943 =	46.764858	
003		2.500000 x	24.769248 =	61.923120	
		-----			
			T.E =	131.193978	
5252.2	5252.2				
246		1.100000 x	9.000000 =	9.900000	
246		.110000 x	9.000000 =	.990000	
003		2.500000 x	24.769248 =	61.923120	
002		2.500000 x	18.705943 =	46.764858	
		-----			
			T.E =	119.577978	
5252.3	5252.3				
249		1.100000 x	19.000000 =	20.900000	
249		.110000 x	19.000000 =	2.090000	
003		2.500000 x	24.769248 =	61.923120	
002		2.500000 x	18.705943 =	46.764858	
		-----			
			T.E =	131.677978	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
003		1.500000 x	24.769248 =	37.153872	
002		1.500000 x	18.705943 =	28.058915	
219		.060000 x	3.500000 =	.210000	
		-----			
			T.E =	69.622787	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
203.2		.025000 x	335.000000 =	8.375000	
251		.600000 x	.695000 =	.417000	
002		.800000 x	18.705943 =	14.964754	
003		.800000 x	24.769248 =	19.815398	
		-----			
			T.E =	49.372153	

5262	5262			
201		.030000 x	290.000000 =	8.700000
251		.300000 x	.695000 =	.208500
252		.200000 x	1.785000 =	.357000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
265		.300000 x	.691500 =	.207450
203.2		.025000 x	335.000000 =	8.375000
-----				
			T.E =	61.323141
5266	5266			
201		.020000 x	290.000000 =	5.800000
003		.600000 x	24.769248 =	14.861549
002		.600000 x	18.705943 =	11.223566
251		.600000 x	.695000 =	.417000
203.2		.015000 x	335.000000 =	5.025000
-----				
			T.E =	37.327115
5267	5267			
201		.030000 x	290.000000 =	8.700000
252		.300000 x	1.785000 =	.535500
003		.800000 x	24.769248 =	19.815398
002		.800000 x	18.705943 =	14.964754
265		.300000 x	.691500 =	.207450
203.2		.015000 x	335.000000 =	5.025000
251		.300000 x	.695000 =	.208500
-----				
			T.E =	49.456603
5271	5271			
201		.016000 x	290.000000 =	4.640000
251		.600000 x	.695000 =	.417000
003		.500000 x	24.769248 =	12.384624
002		.500000 x	18.705943 =	9.352972
203.2		.025000 x	335.000000 =	8.375000
-----				
			T.E =	35.169596
5272	5272			
201		.024000 x	290.000000 =	6.960000
203.2		.025000 x	335.000000 =	8.375000
251		.300000 x	.695000 =	.208500
002		.700000 x	18.705943 =	13.094160
003		.700000 x	24.769248 =	17.338474
265		.200000 x	.691500 =	.138300
252		.100000 x	1.785000 =	.178500
-----				
			T.E =	46.292934

5273	5273			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	24.769248 =	12.384624
002		.500000 x	18.705943 =	9.352972
203.2		.015000 x	335.000000 =	5.025000
251		.600000 x	.695000 =	.417000
-----				
			T.E =	31.819596
5274	5274			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	24.769248 =	17.338474
002		.700000 x	18.705943 =	13.094160
265		.200000 x	.691500 =	.138300
252		.100000 x	1.785000 =	.178500
251		.300000 x	.695000 =	.208500
203.2		.015000 x	335.000000 =	5.025000
-----				
			T.E =	42.942934
5276	5276			
201		1.080000 x	290.000000 =	313.200000
003		19.000000 x	24.769248 =	470.615712
002		19.000000 x	18.705943 =	355.412917
252		18.000000 x	1.785000 =	32.130000
251		6.000000 x	.695000 =	4.170000
-----				
			T.E =	1,175.528629
5277	5277			
203.2		1.080000 x	335.000000 =	361.800000
003		18.000000 x	24.769248 =	445.846464
002		18.000000 x	18.705943 =	336.706974
252		18.000000 x	1.785000 =	32.130000
251		6.000000 x	.695000 =	4.170000
-----				
			T.E =	1,180.653438
5279	5279			
201		1.080000 x	290.000000 =	313.200000
003		10.000000 x	24.769248 =	247.692480
002		5.000000 x	18.705943 =	93.529715
251		12.000000 x	.695000 =	8.340000
-----				
			T.E =	662.762195

5280	5280				
203.2		1.080000 x	335.000000 =	361.800000	
251		12.000000 x	.695000 =	8.340000	
002		5.000000 x	18.705943 =	93.529715	
003		10.000000 x	24.769248 =	247.692480	
		-----			
			T.E =	711.362195	
5281	5281				
203.2		.014000 x	335.000000 =	4.690000	
251		.040000 x	.695000 =	.027800	
002		.250000 x	18.705943 =	4.676486	
		-----			
			T.E =	9.394286	
5282	5282				
203.2		.020000 x	335.000000 =	6.700000	
251		.060000 x	.695000 =	.041700	
002		.350000 x	18.705943 =	6.547080	
		-----			
			T.E =	13.288780	
5283	5283				
203.2		.026000 x	335.000000 =	8.710000	
002		.400000 x	18.705943 =	7.482377	
251		.080000 x	.695000 =	.055600	
		-----			
			T.E =	16.247977	
5286	5286				
203.2		.008000 x	335.000000 =	2.680000	
251		.030000 x	.695000 =	.020850	
002		.120000 x	18.705943 =	2.244713	
003		.120000 x	24.769248 =	2.972310	
		-----			
			T.E =	7.917873	
5288	5288				
003		.300000 x	24.769248 =	7.430774	
		-----			
			T.E =	7.430774	
5289	5289				
003		1.000000 x	24.769248 =	24.769248	
		-----			
			T.E =	24.769248	



5291	5291			
203.2		.020000 x	335.000000 =	6.700000
220		26.000000 x	.000000 =	.000000
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377
251		.200000 x	.695000 =	.139000

-----  
T.E =

5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	24.769248 =	14.861549
002		.600000 x	18.705943 =	11.223566
220		26.000000 x	.000000 =	.000000
251		.200000 x	.695000 =	.139000
203.2		.010000 x	335.000000 =	3.350000

-----  
T.E =

5293	5293			
203.2		.020000 x	335.000000 =	6.700000
251		.150000 x	.695000 =	.104250
203.2		.016000 x	335.000000 =	5.360000
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377

-----  
T.E =

5294	5294			29.554326
203.2		.020000 x	335.000000 =	6.700000
203.2		.022000 x	335.000000 =	7.370000
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377
251		.100000 x	.695000 =	.069500

-----  
T.E =

5295	5295			31.529576
203.2		.020000 x	335.000000 =	6.700000
251		.050000 x	.695000 =	.034750
002		.250000 x	18.705943 =	4.676486
003		.250000 x	24.769248 =	6.192312

-----  
T.E =

5301	5301			17.603548
226		1.050000 x	11.500000 =	12.075000
251		.250000 x	.695000 =	.173750
003		.600000 x	24.769248 =	14.861549
002		.600000 x	18.705943 =	11.223566

-----  
T.E =

38.333865

5302	5302				
227		1.050000 x	11.500000 =	12.075000	
251		.200000 x	.695000 =	.139000	
003		.500000 x	24.769248 =	12.384624	
002		.500000 x	18.705943 =	9.352972	
-----					
			T.E =	33.951596	
5321	5321				
203.2		.012000 x	335.000000 =	4.020000	
003		.900000 x	24.769248 =	22.292323	
002		.900000 x	18.705943 =	16.835349	
251		.500000 x	.695000 =	.347500	
226		1.050000 x	11.500000 =	12.075000	
-----					
			T.E =	55.570172	
5322	5322				
203.2		.012000 x	335.000000 =	4.020000	
227		1.050000 x	11.500000 =	12.075000	
251		.450000 x	.695000 =	.312750	
003		.800000 x	24.769248 =	19.815398	
002		.800000 x	18.705943 =	14.964754	
-----					
			T.E =	51.187903	
5323	5323				
203.2		.012000 x	335.000000 =	4.020000	
003		1.000000 x	24.769248 =	24.769248	
228		1.050000 x	35.000000 =	36.750000	
002		1.000000 x	18.705943 =	18.705943	
251		.500000 x	.695000 =	.347500	
-----					
			T.E =	84.592691	
5324	5324				
203.2		.012000 x	335.000000 =	4.020000	
229		1.050000 x	.000000 =	.000000	
002		1.000000 x	18.705943 =	18.705943	
003		1.000000 x	24.769248 =	24.769248	
251		.500000 x	.695000 =	.347500	
-----					
			T.E =		
5325	5325				
203.2		.012000 x	335.000000 =	4.020000	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
251		.500000 x	.695000 =	.347500	
230		1.050000 x	.000000 =	.000000	
-----					
			T.E =		

5326	5326				
203.2		.012000 x	335.000000 =	4.020000	
231		1.050000 x	20.000000 =	21.000000	
251		.500000 x	.695000 =	.347500	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
-----					
			T.E =	68.842691	
5341	5341				
203.2		.037000 x	335.000000 =	12.395000	
003		1.100000 x	24.769248 =	27.246173	
232		1.050000 x	45.000000 =	47.250000	
002		1.100000 x	18.705943 =	20.576537	
251		.600000 x	.695000 =	.417000	
-----					
			T.E =	107.884710	
5342	5342				
203.2		.037000 x	335.000000 =	12.395000	
232		1.100000 x	45.000000 =	49.500000	
002		1.700000 x	18.705943 =	31.800103	
003		1.700000 x	24.769248 =	42.107722	
251		.600000 x	.695000 =	.417000	
-----					
			T.E =	136.219825	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
003		.800000 x	24.769248 =	19.815398	
002		.800000 x	18.705943 =	14.964754	
233		.084000 x	21.300000 =	1.789200	
-----					
			T.E =	58.934353	
5351	5351				
035		.200000 x	.116800 =	.023360	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
251		.100000 x	.695000 =	.069500	
236		1.060000 x	2.600000 =	2.756000	
-----					
			T.E =	11.543898	
5352	5352				
035		.200000 x	.116800 =	.023360	
251		.100000 x	.695000 =	.069500	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
237		1.060000 x	1.100000 =	1.166000	
-----					
			T.E =	9.953898	

5353	5353			
035		.200000 x	.116800 =	.023360
238		1.060000 x	2.600000 =	2.756000
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850
251		.100000 x	.695000 =	.069500
-----				
			T.E =	11.543898
5354	5354			
035		.200000 x	.116800 =	.023360
239		1.060000 x	.000000 =	.000000
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
251		.100000 x	.695000 =	.069500
-----				
			T.E =	
5355	5355			
035		.200000 x	.116800 =	.023360
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
251		.100000 x	.695000 =	.069500
240		1.060000 x	1.600000 =	1.696000
-----				
			T.E =	10.483898
5356	5356			
035		.200000 x	.116800 =	.023360
251		.100000 x	.695000 =	.069500
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850
241		1.060000 x	.000000 =	.000000
-----				
			T.E =	
5421	5421			
205		.055000 x	420.000000 =	23.100000
1471		1.000000 x	5.222128 =	5.222128
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
-----				
			T.E =	180.485297
5422	5422			
205		.035000 x	420.000000 =	14.700000
1472		1.000000 x	6.315176 =	6.315176
003		3.000000 x	24.769248 =	74.307744
002		3.000000 x	18.705943 =	56.117829
-----				
			T.E =	151.440749

5426	5426			
205		.095000 x	420.000000 =	39.900000
002		6.000000 x	18.705943 =	112.235658
003		6.000000 x	24.769248 =	148.615488
1473		1.000000 x	10.842734 =	10.842734
1471		1.000000 x	5.222128 =	5.222128

-----  
T.E = 316.816008

5427	5427			
205		.105000 x	420.000000 =	44.100000
002		7.000000 x	18.705943 =	130.941601
1474		1.000000 x	13.162302 =	13.162302
1471		1.000000 x	5.222128 =	5.222128
003		7.000000 x	24.769248 =	173.384736

-----  
T.E = 366.810767

5428	5428			
205		.075000 x	420.000000 =	31.500000
003		5.500000 x	24.769248 =	136.230864
1474		1.000000 x	13.162302 =	13.162302
1472		1.000000 x	6.315176 =	6.315176
002		5.500000 x	18.705943 =	102.882687

-----  
T.E = 290.091029

5431	5431			
205		.070000 x	420.000000 =	29.400000
1475		1.000000 x	37.470488 =	37.470488
208		.030000 x	1,239.000000 =	37.170000
1471		1.000000 x	5.222128 =	5.222128
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601

-----  
T.E = 413.588953

5432	5432			
205		.070000 x	420.000000 =	29.400000
1475		.800000 x	37.470488 =	29.976390
1471		1.000000 x	5.222128 =	5.222128
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715
380		1.000000 x	16.150000 =	16.150000

-----  
T.E = 298.124473

5436	5436				
205		.050000 x	420.000000 =	21.000000	
002		4.500000 x	18.705943 =	84.176744	
1476		1.000000 x	2.769630 =	2.769630	
003		4.500000 x	24.769248 =	111.461616	
-----					
			T.E =	219.407990	
5437	5437				
205		.065000 x	420.000000 =	27.300000	
002		5.000000 x	18.705943 =	93.529715	
003		5.000000 x	24.769248 =	123.846240	
1476		1.000000 x	2.769630 =	2.769630	
-----					
			T.E =	247.445585	
5438	5438				
205		.050000 x	420.000000 =	21.000000	
002		4.000000 x	18.705943 =	74.823772	
1476		1.000000 x	2.769630 =	2.769630	
003		4.000000 x	24.769248 =	99.076992	
-----					
			T.E =	197.670394	
5441.1	5441.1				
205		.065000 x	420.000000 =	27.300000	
1476		1.000000 x	2.769630 =	2.769630	
003		4.500000 x	24.769248 =	111.461616	
002		4.500000 x	18.705943 =	84.176744	
222.3		.004000 x	.000000 =	.000000	
-----					
			T.E =		
5441.2	5441.2				
205		.065000 x	420.000000 =	27.300000	
223.3		.004000 x	1,135.000000 =	4.540000	
002		4.500000 x	18.705943 =	84.176744	
1476		1.000000 x	2.769630 =	2.769630	
003		4.500000 x	24.769248 =	111.461616	
-----					
			T.E =	230.247990	
5441.3	5441.3				
205		.065000 x	420.000000 =	27.300000	
1476		1.000000 x	2.769630 =	2.769630	
243.1		.550000 x	2.660000 =	1.463000	
003		4.500000 x	24.769248 =	111.461616	
002		4.500000 x	18.705943 =	84.176744	
-----					
			T.E =	227.170990	

5442.1	5442.1			
205		.080000 x	420.000000 =	33.600000
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	24.769248 =	123.846240
1476		1.000000 x	2.769630 =	2.769630
002		5.000000 x	18.705943 =	93.529715

-----  
T.E =

5442.2	5442.2			
205		.080000 x	420.000000 =	33.600000
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715
223.3		.004000 x	1,135.000000 =	4.540000

-----  
T.E =

258.285585

5442.3	5442.3			
205		.080000 x	420.000000 =	33.600000
002		5.000000 x	18.705943 =	93.529715
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	24.769248 =	123.846240
243.1		.055000 x	2.660000 =	.146300

-----  
T.E =

253.891885

5443.1	5443.1			
205		.065000 x	420.000000 =	27.300000
003		4.000000 x	24.769248 =	99.076992
1476		1.000000 x	2.769630 =	2.769630
002		4.000000 x	18.705943 =	74.823772
222.3		.004000 x	.000000 =	.000000

-----  
T.E =

5443.2	5443.2			
205		.065000 x	420.000000 =	27.300000
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
223.3		.004000 x	1,135.000000 =	4.540000

-----  
T.E =

208.510394

5443.3	5443.3			
205		.065000 x	420.000000 =	27.300000
243.1		.550000 x	2.660000 =	1.463000
002		4.000000 x	18.705943 =	74.823772
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	24.769248 =	99.076992

-----  
T.E = 205.433394

5446.1	5446.1			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
222.2		.010000 x	.000000 =	.000000
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772

-----  
T.E =

5446.2	5446.2			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
223.2		.010000 x	1,450.000000 =	14.500000

-----  
T.E = 210.045394

5447.1	5447.1			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.769630 =	2.769630
003		4.500000 x	24.769248 =	111.461616
002		4.500000 x	18.705943 =	84.176744
205		.040000 x	420.000000 =	16.800000
222.2		.010000 x	.000000 =	.000000

-----  
T.E =

5447.2	5447.2			
203.2		.025000 x	335.000000 =	8.375000
002		4.500000 x	18.705943 =	84.176744
1476		1.000000 x	2.769630 =	2.769630
003		4.500000 x	24.769248 =	111.461616
223.2		.010000 x	1,450.000000 =	14.500000
205		.040000 x	420.000000 =	16.800000

-----  
T.E = 238.082990



5448.1	5448.1			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.769630 =	2.769630
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
205		.025000 x	420.000000 =	10.500000
222.2		.010000 x	.000000 =	.000000

T.E =

5448.2	5448.2			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
1476		1.000000 x	2.769630 =	2.769630
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
223.2		.010000 x	1,450.000000 =	14.500000

T.E =

188.307799

5449	5449			
205		.045000 x	420.000000 =	18.900000
002		3.000000 x	18.705943 =	56.117829
1476		1.000000 x	2.769630 =	2.769630
003		3.000000 x	24.769248 =	74.307744
243.5		.850000 x	6.250000 =	5.312500

T.E =

157.407703

5451.1	5451.1			
205		.090000 x	420.000000 =	37.800000
003		5.000000 x	24.769248 =	123.846240
1476		1.000000 x	2.769630 =	2.769630
002		5.000000 x	18.705943 =	93.529715
222.3		.004000 x	.000000 =	.000000

T.E =

5451.2	5451.2			
205		.090000 x	420.000000 =	37.800000
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715
223.3		.004000 x	1,135.000000 =	4.540000

T.E =

262.485585

5451.3	5451.3			
205		.090000 x	420.000000 =	37.800000
243.1		.550000 x	2.660000 =	1.463000
002		5.000000 x	18.705943 =	93.529715
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	24.769248 =	123.846240
-----				
			T.E =	259.408585
5456	5456			
205		.055000 x	420.000000 =	23.100000
1478		1.000000 x	3.007750 =	3.007750
002		4.000000 x	18.705943 =	74.823772
003		4.000000 x	24.769248 =	99.076992
-----				
			T.E =	200.008514
5457	5457			
205		.085000 x	420.000000 =	35.700000
003		7.000000 x	24.769248 =	173.384736
1476		1.500000 x	2.769630 =	4.154445
002		7.000000 x	18.705943 =	130.941601
261		2.200000 x	.560100 =	1.232220
-----				
			T.E =	345.413002
5461.1	5461.1			
205		.065000 x	420.000000 =	27.300000
222.2		.010000 x	.000000 =	.000000
1479		1.000000 x	34.249420 =	34.249420
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687
-----				
			T.E =	
5461.2	5461.2			
205		.065000 x	420.000000 =	27.300000
1479		1.000000 x	34.249420 =	34.249420
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687
223.2		.010000 x	1,450.000000 =	14.500000
-----				
			T.E =	315.162971
5462.1	5462.1			
205		.065000 x	420.000000 =	27.300000
1480		1.000000 x	33.131494 =	33.131494
222.2		.010000 x	.000000 =	.000000
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687
-----				
			T.E =	

5462.2	5462.2			
205		.065000 x	420.000000 =	27.300000
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687
1480		1.000000 x	33.131494 =	33.131494
223.2		.010000 x	1,450.000000 =	14.500000

-----  
T.E = 314.045045

5463.1	5463.1			
205		.055000 x	420.000000 =	23.100000
1479		.500000 x	34.249420 =	17.124710
003		6.000000 x	24.769248 =	148.615488
002		6.000000 x	18.705943 =	112.235658
222.2		.010000 x	.000000 =	.000000

-----  
T.E =

5463.2	5463.2			
205		.055000 x	420.000000 =	23.100000
223.2		.010000 x	1,450.000000 =	14.500000
002		6.000000 x	18.705943 =	112.235658
1479		.500000 x	34.249420 =	17.124710
003		6.000000 x	24.769248 =	148.615488

-----  
T.E = 315.575856

5464.1	5464.1			
205		.070000 x	420.000000 =	29.400000
1479		.500000 x	34.249420 =	17.124710
222.2		.010000 x	.000000 =	.000000
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601

-----  
T.E =

5464.2	5464.2			
205		.070000 x	420.000000 =	29.400000
223.2		.010000 x	1,450.000000 =	14.500000
003		7.000000 x	24.769248 =	173.384736
1479		.500000 x	34.249420 =	17.124710
002		7.000000 x	18.705943 =	130.941601

-----  
T.E = 365.351047

5465.1	5465.1			
203.2		.045000 x	335.000000 =	15.075000
1476		1.000000 x	2.769630 =	2.769630
003		5.500000 x	24.769248 =	136.230864
002		5.500000 x	18.705943 =	102.882687
222.2		.005000 x	.000000 =	.000000
208		.030000 x	1,239.000000 =	37.170000

T.E =

5465.2	5465.2			
203.2		.045000 x	335.000000 =	15.075000
002		5.500000 x	18.705943 =	102.882687
1476		1.000000 x	2.769630 =	2.769630
003		5.500000 x	24.769248 =	136.230864
223.2		.005000 x	1,450.000000 =	7.250000
208		.030000 x	1,239.000000 =	37.170000

T.E =

301.378181

5466.1	5466.1			
203.2		.025000 x	335.000000 =	8.375000
1479		.900000 x	34.249420 =	30.824478
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715
222.2		.010000 x	.000000 =	.000000

T.E =

5466.2	5466.2			
203.2		.025000 x	335.000000 =	8.375000
1479		.900000 x	34.249420 =	30.824478
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715
223.2		.010000 x	1,450.000000 =	14.500000

T.E =

271.075433

5467.1	5467.1			
203.2		.013000 x	335.000000 =	4.355000
203.2		.001040 x	335.000000 =	.348400
222.2		.012000 x	.000000 =	.000000
002		3.500000 x	18.705943 =	65.470801
003		3.500000 x	24.769248 =	86.692368
222.2		.000960 x	.000000 =	.000000

T.E =

5467.2	5467.2			
203.2		.013000 x	335.000000 =	4.355000
223.2		.000960 x	1,450.000000 =	1.392000
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
223.2		.012000 x	1,450.000000 =	17.400000
203.2		.001040 x	335.000000 =	.348400
-----				
			T.E =	175.658569
5468.1	5468.1			
203.2		.025000 x	335.000000 =	8.375000
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
222.2		.000800 x	.000000 =	.000000
222.2		.010000 x	.000000 =	.000000
203.2		.002000 x	335.000000 =	.670000
-----				
			T.E =	
5468.2	5468.2			
203.2		.025000 x	335.000000 =	8.375000
203.2		.002000 x	335.000000 =	.670000
223.2		.010000 x	1,450.000000 =	14.500000
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
223.2		.000800 x	1,450.000000 =	1.160000
-----				
			T.E =	198.605764
5469.1	5469.1			
203.2		.025000 x	335.000000 =	8.375000
1479		.500000 x	34.249420 =	17.124710
003		4.500000 x	24.769248 =	111.461616
002		4.500000 x	18.705943 =	84.176744
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5469.2	5469.2			
203.2		.025000 x	335.000000 =	8.375000
223.2		.010000 x	1,450.000000 =	14.500000
003		4.500000 x	24.769248 =	111.461616
1479		.500000 x	34.249420 =	17.124710
002		4.500000 x	18.705943 =	84.176744
-----				
			T.E =	235.638070

5471	5471				
203.2		.035000 x	335.000000 =		11.725000
251		3.000000 x	.695000 =		2.085000
003		3.500000 x	24.769248 =		86.692368
002		3.500000 x	18.705943 =		65.470801
		-----			
			T.E =		165.973169
5472.1	5472.1				
203.2		.026000 x	335.000000 =		8.710000
003		3.500000 x	24.769248 =		86.692368
002		3.500000 x	18.705943 =		65.470801
251		3.000000 x	.695000 =		2.085000
222.4		.010000 x	.000000 =		.000000
		-----			
			T.E =		
5472.2	5472.2				
203.2		.026000 x	335.000000 =		8.710000
003		3.500000 x	24.769248 =		86.692368
002		3.500000 x	18.705943 =		65.470801
251		3.000000 x	.695000 =		2.085000
223.4		.010000 x	1,440.000000 =		14.400000
		-----			
			T.E =		177.358169
5501.1	5501.1				
211		.040000 x	.000000 =		.000000
003		5.000000 x	24.769248 =		123.846240
002		2.500000 x	18.705943 =		46.764858
252		.100000 x	1.785000 =		.178500
251		.050000 x	.695000 =		.034750
		-----			
			T.E =		
5501.2	5501.2				
212		.040000 x	1,400.000000 =		56.000000
251		.050000 x	.695000 =		.034750
252		.100000 x	1.785000 =		.178500
003		5.000000 x	24.769248 =		123.846240
002		2.500000 x	18.705943 =		46.764858
		-----			
			T.E =		226.824348
5502	5502				
210		.040000 x	.000000 =		.000000
251		.050000 x	.695000 =		.034750
002		2.000000 x	18.705943 =		37.411886
003		4.000000 x	24.769248 =		99.076992
252		.100000 x	1.785000 =		.178500
		-----			
			T.E =		

5511.1	5511.1			
211		.020000 x	.000000 =	.000000
003		3.200000 x	24.769248 =	79.261594
002		1.600000 x	18.705943 =	29.929509
252		.100000 x	1.785000 =	.178500

T.E =

5511.2	5511.2			
212		.020000 x	1,400.000000 =	28.000000
003		3.200000 x	24.769248 =	79.261594
002		1.600000 x	18.705943 =	29.929509
252		.100000 x	1.785000 =	.178500

T.E =

137.369602

5512	5512			
205		.020000 x	420.000000 =	8.400000
252		.100000 x	1.785000 =	.178500
002		1.500000 x	18.705943 =	28.058915
003		3.000000 x	24.769248 =	74.307744

T.E =

110.945159

5513.1	5513.1			
211		.020000 x	.000000 =	.000000
252		.100000 x	1.785000 =	.178500
003		4.000000 x	24.769248 =	99.076992
002		2.000000 x	18.705943 =	37.411886

T.E =

5513.2	5513.2			
212		.020000 x	1,400.000000 =	28.000000
252		.100000 x	1.785000 =	.178500
003		4.000000 x	24.769248 =	99.076992
002		2.000000 x	18.705943 =	37.411886

T.E =

164.667378

5514	5514			
205		.020000 x	420.000000 =	8.400000
003		3.800000 x	24.769248 =	94.123142
002		1.800000 x	18.705943 =	33.670697
252		.100000 x	1.785000 =	.178500

T.E =

136.372340

5521	5521				
205		.030000 x	420.000000 =		12.600000
252		.150000 x	1.785000 =		.267750
002		.800000 x	18.705943 =		14.964754
003		2.000000 x	24.769248 =		49.538496
				T.E =	77.371000
5531.1	5531.1				
211		.010000 x	.000000 =		.000000
252		.020000 x	1.785000 =		.035700
003		2.200000 x	24.769248 =		54.492346
002		.700000 x	18.705943 =		13.094160
				T.E =	
5531.2	5531.2				
212		.010000 x	1,400.000000 =		14.000000
252		.020000 x	1.785000 =		.035700
003		2.200000 x	24.769248 =		54.492346
002		.700000 x	18.705943 =		13.094160
				T.E =	81.622206
5531.3	5531.3				
205		.010000 x	420.000000 =		4.200000
003		2.200000 x	24.769248 =		54.492346
002		.700000 x	18.705943 =		13.094160
252		.020000 x	1.785000 =		.035700
				T.E =	71.822206
5532.1	5532.1				
211		.010000 x	.000000 =		.000000
003		3.000000 x	24.769248 =		74.307744
002		1.000000 x	18.705943 =		18.705943
252		.020000 x	1.785000 =		.035700
				T.E =	
5532.2	5532.2				
212		.010000 x	1,400.000000 =		14.000000
252		.020000 x	1.785000 =		.035700
002		1.000000 x	18.705943 =		18.705943
003		3.000000 x	24.769248 =		74.307744
				T.E =	107.049387



5532.3	5532.3			
205		.010000 x	420.000000 =	4.200000
252		.020000 x	1.785000 =	.035700
003		3.000000 x	24.769248 =	74.307744
002		1.000000 x	18.705943 =	18.705943
		-----		
			T.E =	97.249387
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	24.769248 =	8.669237
		-----		
			T.E =	10.454237
5601	5601			
203.2		.028000 x	335.000000 =	9.380000
251		4.000000 x	.695000 =	2.780000
003		2.500000 x	24.769248 =	61.923120
002		2.500000 x	18.705943 =	46.764858
		-----		
			T.E =	120.847978
5602	5602			
203.2		.018000 x	335.000000 =	6.030000
002		2.300000 x	18.705943 =	43.023669
003		2.300000 x	24.769248 =	56.969270
251		3.000000 x	.695000 =	2.085000
		-----		
			T.E =	108.107939
5603	5603			
203.2		.013000 x	335.000000 =	4.355000
003		2.000000 x	24.769248 =	49.538496
002		2.000000 x	18.705943 =	37.411886
251		2.500000 x	.695000 =	1.737500
		-----		
			T.E =	93.042882
5604	5604			
243.5		1.100000 x	6.250000 =	6.875000
003		2.200000 x	24.769248 =	54.492346
002		2.200000 x	18.705943 =	41.153075
243.5		.165000 x	6.250000 =	1.031250
		-----		
			T.E =	103.551670

5605	5605			
243.3		1.100000 x	4.450000 =	4.895000
243.3		.187000 x	4.450000 =	.832150
002		2.000000 x	18.705943 =	37.411886
003		2.000000 x	24.769248 =	49.538496

-----  
T.E = 92.677532

5606	5606			
243.2		1.100000 x	3.650000 =	4.015000
003		1.800000 x	24.769248 =	44.584646
243.2		.220000 x	3.650000 =	.803000
002		1.800000 x	18.705943 =	33.670697

-----  
T.E = 83.073344

5607	5607			
205		.012000 x	420.000000 =	5.040000
003		2.500000 x	24.769248 =	61.923120
002		2.500000 x	18.705943 =	46.764858
242		.440000 x	1.300000 =	.572000
205		.002400 x	420.000000 =	1.008000
242		2.200000 x	1.300000 =	2.860000

-----  
T.E = 118.167978

5608.1	5608.1			
205		.012000 x	420.000000 =	5.040000
205		.002400 x	420.000000 =	1.008000
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
222.1		.001200 x	.000000 =	.000000
222.1		.006000 x	.000000 =	.000000

-----  
T.E =

5608.2	5608.2			
205		.012000 x	420.000000 =	5.040000
205		.002400 x	420.000000 =	1.008000
003		3.500000 x	24.769248 =	86.692368
002		3.500000 x	18.705943 =	65.470801
223.1		.006000 x	1,700.000000 =	10.200000
223.1		.001200 x	1,700.000000 =	2.040000

-----  
T.E = 170.451169

5611	5611			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	24.769248 =	173.384736
251		5.000000 x	.695000 =	3.475000
002		7.000000 x	18.705943 =	130.941601
-----				
			T.E =	333.001337
5612.1	5612.1			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601
251		5.000000 x	.695000 =	3.475000
222.1		.006000 x	.000000 =	.000000
-----				
			T.E =	
5612.2	5612.2			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601
251		5.000000 x	.695000 =	3.475000
223.1		.006000 x	1,700.000000 =	10.200000
-----				
			T.E =	343.201337
5613.1	5613.1			
205		.015000 x	420.000000 =	6.300000
205		.001500 x	420.000000 =	.630000
003		1.500000 x	24.769248 =	37.153872
002		1.500000 x	18.705943 =	28.058915
222.2		.003000 x	.000000 =	.000000
-----				
			T.E =	
5613.2	5613.2			
205		.015000 x	420.000000 =	6.300000
205		.001500 x	420.000000 =	.630000
002		1.500000 x	18.705943 =	28.058915
003		1.500000 x	24.769248 =	37.153872
223.2		.003000 x	1,450.000000 =	4.350000
-----				
			T.E =	76.492787
5614.1	5614.1			
205		.010000 x	420.000000 =	4.200000
222.2		.002000 x	.000000 =	.000000
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132
205		.001500 x	420.000000 =	.630000
-----				
			T.E =	

5614.2	5614.2			
205		.010000 x	420.000000 =	4.200000
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132
223.2		.002000 x	1,450.000000 =	2.900000
205		.001500 x	420.000000 =	.630000

-----  
T.E = 59.900229

5615.1	5615.1			
205		.008000 x	420.000000 =	3.360000
222.2		.000900 x	.000000 =	.000000
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
205		.001440 x	420.000000 =	.604800

-----  
T.E =

5615.2	5615.2			
205		.008000 x	420.000000 =	3.360000
003		1.000000 x	24.769248 =	24.769248
205		.001440 x	420.000000 =	.604800
002		1.000000 x	18.705943 =	18.705943
223.2		.000900 x	1,450.000000 =	1.305000

-----  
T.E = 48.744991

5616	5616			
205		.003000 x	420.000000 =	1.260000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
205		.007500 x	420.000000 =	3.150000

-----  
T.E = 47.885191

5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
521		.250000 x	2.390000 =	.597500

-----  
T.E = 48.472691

5619	5619			
205		.001400 x	420.000000 =	.588000
003		.200000 x	24.769248 =	4.953850

-----  
T.E = 5.541850

5620	5620			
203.2		.012000 x	335.000000 =	4.020000
251		.020000 x	.695000 =	.013900
003		.300000 x	24.769248 =	7.430774
002		.300000 x	18.705943 =	5.611783
220		4.200000 x	.000000 =	.000000

-----  
T.E =

5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.695000 =	11.120000
003		30.000000 x	24.769248 =	743.077440
002		30.000000 x	18.705943 =	561.178290

-----  
T.E =

5622	5622			
211		1.100000 x	.000000 =	.000000
003		30.000000 x	24.769248 =	743.077440
002		30.000000 x	18.705943 =	561.178290
251		16.000000 x	.695000 =	11.120000

-----  
T.E =

5626	5626			
205		.030000 x	420.000000 =	12.600000
003		1.500000 x	24.769248 =	37.153872
002		1.500000 x	18.705943 =	28.058915
251		1.000000 x	.695000 =	.695000

-----  
T.E = 78.507787

6101	6101			
267		1.050000 x	.744000 =	.781200
003		.050000 x	24.769248 =	1.238462

-----  
T.E = 2.019662

6102	6102			
252		.050000 x	1.785000 =	.089250
267		1.030000 x	.744000 =	.766320
003		.060000 x	24.769248 =	1.486155

-----  
T.E = 2.341725

6103	6103			
268		1.050000 x	.859000 =	.901950
003		.050000 x	24.769248 =	1.238462

-----  
T.E = 2.140412

6104	6104				
252		.050000 x	1.785000 =	.089250	
268		1.030000 x	.859000 =	.884770	
003		.060000 x	24.769248 =	1.486155	
		-----			
			T.E =	2.460175	
6111	6111				
266		1.100000 x	.553000 =	.608300	
003		.150000 x	24.769248 =	3.715387	
		-----			
			T.E =	4.323687	
6116	6116				
280		1.050000 x	1.000000 =	1.050000	
003		.100000 x	24.769248 =	2.476925	
		-----			
			T.E =	3.526925	
6117	6117				
281		1.050000 x	5.780000 =	6.069000	
003		.150000 x	24.769248 =	3.715387	
		-----			
			T.E =	9.784387	
6118	6118				
266		1.150000 x	.553000 =	.635950	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
		-----			
			T.E =	9.330988	
6119	6119				
293		1.100000 x	.000000 =	.000000	
003		.150000 x	24.769248 =	3.715387	
		-----			
			T.E =		
6120	6120				
289		1.050000 x	.659100 =	.692055	
003		.100000 x	24.769248 =	2.476925	
		-----			
			T.E =	3.168980	
6121	6121				
266		1.100000 x	.553000 =	.608300	
002		.200000 x	18.705943 =	3.741189	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	9.303338	

6122	6122				
265		1.050000 x	.691500 =		.726075
003		.200000 x	24.769248 =		4.953850
-----					
			T.E =		5.679925
6123	6123				
265		.900000 x	.691500 =		.622350
002		.150000 x	18.705943 =		2.805891
003		.150000 x	24.769248 =		3.715387
266		.100000 x	.553000 =		.055300
266		.010000 x	.553000 =		.005530
265		.090000 x	.691500 =		.062235
-----					
			T.E =		7.266694
6126	6126				
265		1.250000 x	.691500 =		.864375
003		.200000 x	24.769248 =		4.953850
003		.200000 x	24.769248 =		4.953850
-----					
			T.E =		10.772074
6127	6127				
290		4.800000 x	3.300000 =		15.840000
002		.800000 x	18.705943 =		14.964754
003		.800000 x	24.769248 =		19.815398
-----					
			T.E =		50.620153
6128	6128				
290		1.200000 x	3.300000 =		3.960000
002		.200000 x	18.705943 =		3.741189
003		.200000 x	24.769248 =		4.953850
-----					
			T.E =		12.655038
6201	6201				
264		1.400000 x	1.007900 =		1.411060
003		.250000 x	24.769248 =		6.192312
002		.250000 x	18.705943 =		4.676486
-----					
			T.E =		12.279858
6202	6202				
264		1.300000 x	1.007900 =		1.310270
002		.200000 x	18.705943 =		3.741189
003		.200000 x	24.769248 =		4.953850
-----					
			T.E =		10.005308

6203	6203			
282		1.200000 x	.786500 =	.943800
002		.350000 x	18.705943 =	6.547080
003		.350000 x	24.769248 =	8.669237
-----				
			T.E =	16.160117
6204	6204			
282		1.300000 x	.786500 =	1.022450
002		.400000 x	18.705943 =	7.482377
003		.400000 x	24.769248 =	9.907699
-----				
			T.E =	18.412526
6205	6205			
277		1.250000 x	.806500 =	1.008125
003		.500000 x	24.769248 =	12.384624
002		.500000 x	18.705943 =	9.352972
-----				
			T.E =	22.745721
6221	6221			
265		1.150000 x	.691500 =	.795225
002		.200000 x	18.705943 =	3.741189
003		.200000 x	24.769248 =	4.953850
-----				
			T.E =	9.490263
6222	6222			
265		1.200000 x	.691500 =	.829800
002		.350000 x	18.705943 =	6.547080
003		.350000 x	24.769248 =	8.669237
-----				
			T.E =	16.046117
6223	6223			
265		1.250000 x	.691500 =	.864375
002		.500000 x	18.705943 =	9.352972
003		.500000 x	24.769248 =	12.384624
-----				
			T.E =	22.601971
6224	6224			
271		.720000 x	.792500 =	.570600
003		.200000 x	24.769248 =	4.953850
002		.200000 x	18.705943 =	3.741189
282		.480000 x	.786500 =	.377520
-----				
			T.E =	9.643158



6225	6225			
271		.720000 x	.792500 =	.570600
003		.250000 x	24.769248 =	6.192312
282		.480000 x	.786500 =	.377520
002		.250000 x	18.705943 =	4.676486
		-----		
			T.E =	11.816918
6226	6226			
265		1.200000 x	.691500 =	.829800
003		.700000 x	24.769248 =	17.338474
002		.700000 x	18.705943 =	13.094160
		-----		
			T.E =	31.262434
6227	6227			
265		1.250000 x	.691500 =	.864375
003		.850000 x	24.769248 =	21.053861
002		.850000 x	18.705943 =	15.900052
		-----		
			T.E =	37.818287
6228	6228			
282		1.250000 x	.786500 =	.983125
002		.400000 x	18.705943 =	7.482377
003		.400000 x	24.769248 =	9.907699
		-----		
			T.E =	18.373201
6229	6229			
282		1.250000 x	.786500 =	.983125
003		.450000 x	24.769248 =	11.146162
002		.450000 x	18.705943 =	8.417674
		-----		
			T.E =	20.546961
6230	6230			
277		1.100000 x	.806500 =	.887150
002		.500000 x	18.705943 =	9.352972
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	22.624746
6231	6231			
265		1.150000 x	.691500 =	.795225
002		.250000 x	18.705943 =	4.676486
003		.250000 x	24.769248 =	6.192312
		-----		
			T.E =	11.664023

6232	6232			
265		1.150000 x	.691500 =	.795225
003		.400000 x	24.769248 =	9.907699
002		.400000 x	18.705943 =	7.482377
		-----		
			T.E =	18.185301
6236	6236			
253		.500000 x	2.244000 =	1.122000
266		2.000000 x	.553000 =	1.106000
386		.350000 x	28.630000 =	10.020500
390		2.100000 x	1.500000 =	3.150000
003		1.800000 x	24.769248 =	44.584646
002		1.800000 x	18.705943 =	33.670697
565.3		.350000 x	3.450000 =	1.207500
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
276		5.850000 x	.618100 =	3.615885
272		1.500000 x	.719000 =	1.078500
		-----		
			T.E =	125.385729
6237	6237			
253		.850000 x	2.244000 =	1.907400
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
565.5		.350000 x	5.150000 =	1.802500
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	.719000 =	3.595000
266		2.100000 x	.553000 =	1.161300
260		9.500000 x	.528700 =	5.022650
		-----		
			T.E =	223.240114
6238	6238			
253		.400000 x	2.244000 =	.897600
265		6.000000 x	.691500 =	4.149000
266		13.000000 x	.553000 =	7.189000
003		5.000000 x	24.769248 =	123.846240
002		5.000000 x	18.705943 =	93.529715
		-----		
			T.E =	229.611555
6239	6239			
277		1.100000 x	.806500 =	.887150
002		.300000 x	18.705943 =	5.611783
003		.300000 x	24.769248 =	7.430774
		-----		
			T.E =	13.929707

6301	6301				
266		1.250000 x	.553000 =	.691250	
002		.400000 x	18.705943 =	7.482377	
003		.400000 x	24.769248 =	9.907699	
		-----			
			T.E =	18.081326	
6302	6302				
266		9.000000 x	.553000 =	4.977000	
002		3.500000 x	18.705943 =	65.470801	
003		3.500000 x	24.769248 =	86.692368	
		-----			
			T.E =	157.140169	
6401	6401				
265		1.150000 x	.691500 =	.795225	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
		-----			
			T.E =	9.490263	
6402	6402				
265		1.200000 x	.691500 =	.829800	
002		.300000 x	18.705943 =	5.611783	
003		.300000 x	24.769248 =	7.430774	
		-----			
			T.E =	13.872357	
6403	6403				
265		1.250000 x	.691500 =	.864375	
002		.350000 x	18.705943 =	6.547080	
003		.350000 x	24.769248 =	8.669237	
		-----			
			T.E =	16.080692	
6406	6406				
265		1.200000 x	.691500 =	.829800	
002		.600000 x	18.705943 =	11.223566	
003		.600000 x	24.769248 =	14.861549	
		-----			
			T.E =	26.914915	
6407	6407				
265		1.250000 x	.691500 =	.864375	
003		.700000 x	24.769248 =	17.338474	
002		.700000 x	18.705943 =	13.094160	
		-----			
			T.E =	31.297009	

6411	6411				
565.3		1.650000 x	3.450000 =	5.692500	
002		.350000 x	18.705943 =	6.547080	
003		.350000 x	24.769248 =	8.669237	
				-----	
				T.E =	20.908817
6412	6412				
565.5		1.550000 x	5.150000 =	7.982500	
002		.450000 x	18.705943 =	8.417674	
003		.450000 x	24.769248 =	11.146162	
				-----	
				T.E =	27.546336
6413	6413				
565.6		1.450000 x	7.100000 =	10.295000	
002		.550000 x	18.705943 =	10.288269	
003		.550000 x	24.769248 =	13.623086	
				-----	
				T.E =	34.206355
6416	6416				
566.3		1.600000 x	4.600000 =	7.360000	
003		.350000 x	24.769248 =	8.669237	
002		.350000 x	18.705943 =	6.547080	
				-----	
				T.E =	22.576317
6417	6417				
566.5		1.500000 x	7.050000 =	10.575000	
002		.450000 x	18.705943 =	8.417674	
003		.450000 x	24.769248 =	11.146162	
				-----	
				T.E =	30.138836
6418	6418				
566.6		1.400000 x	9.400000 =	13.160000	
003		.550000 x	24.769248 =	13.623086	
002		.550000 x	18.705943 =	10.288269	
				-----	
				T.E =	37.071355
6421	6421				
565.3		1.050000 x	3.450000 =	3.622500	
003		.400000 x	24.769248 =	9.907699	
				-----	
				T.E =	13.530199

6422	6422				
565.5		1.050000 x	5.150000 =	5.407500	
003		.500000 x	24.769248 =	12.384624	
				-----	
				T.E =	17.792124
6423	6423				
565.6		1.050000 x	7.100000 =	7.455000	
003		.600000 x	24.769248 =	14.861549	
				-----	
				T.E =	22.316549
6426	6426				
566.3		1.050000 x	4.600000 =	4.830000	
003		.400000 x	24.769248 =	9.907699	
				-----	
				T.E =	14.737699
6427	6427				
566.5		1.050000 x	7.050000 =	7.402500	
003		.500000 x	24.769248 =	12.384624	
				-----	
				T.E =	19.787124
6428	6428				
566.6		1.050000 x	9.400000 =	9.870000	
003		.600000 x	24.769248 =	14.861549	
				-----	
				T.E =	24.731549
6431	6431				
278		1.100000 x	3.600000 =	3.960000	
003		.150000 x	24.769248 =	3.715387	
				-----	
				T.E =	7.675387
6432	6432				
251		.100000 x	.695000 =	.069500	
003		.250000 x	24.769248 =	6.192312	
279		1.080000 x	3.720000 =	4.017600	
002		.250000 x	18.705943 =	4.676486	
				-----	
				T.E =	14.955898
6441	6441				
266		1.100000 x	.553000 =	.608300	
002		.100000 x	18.705943 =	1.870594	
003		.100000 x	24.769248 =	2.476925	
				-----	
				T.E =	4.955819

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	24.769248 =	.990770
-----				
			T.E =	
6446.2	6446.2			
285		1.100000 x	.057500 =	.063250
003		.040000 x	24.769248 =	.990770
-----				
			T.E =	1.054020
6447	6447			
251		.050000 x	.695000 =	.034750
003		.100000 x	24.769248 =	2.476925
002		.100000 x	18.705943 =	1.870594
286		1.050000 x	1.626900 =	1.708245
-----				
			T.E =	6.090514
6448	6448			
251		.050000 x	.695000 =	.034750
003		.100000 x	24.769248 =	2.476925
288		1.050000 x	1.765800 =	1.854090
002		.100000 x	18.705943 =	1.870594
-----				
			T.E =	6.236359
6501	6501			
282		3.000000 x	.786500 =	2.359500
295		11.000000 x	5.649200 =	62.141200
296		1.000000 x	11.781900 =	11.781900
003		4.000000 x	24.769248 =	99.076992
002		4.000000 x	18.705943 =	74.823772
-----				
			T.E =	250.183364
6502	6502			
002		1.500000 x	18.705943 =	28.058915
003		1.500000 x	24.769248 =	37.153872
6501		1.000000 x	250.183364 =	250.183364
-----				
			T.E =	315.396151
6503	6503			
002		1.300000 x	18.705943 =	24.317726
003		1.300000 x	24.769248 =	32.200022
6501		.950000 x	250.183364 =	237.674196
-----				
			T.E =	294.191944

6504	6504			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		.910000 x	250.183364 =	227.666861
-----				
			T.E =	279.837090
6505	6505			
002		1.000000 x	18.705943 =	18.705943
6501		.870000 x	250.183364 =	217.659527
003		1.000000 x	24.769248 =	24.769248
-----				
			T.E =	261.134718
6506	6506			
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
6501		.810000 x	250.183364 =	202.648525
-----				
			T.E =	246.123716
6507	6507			
002		.900000 x	18.705943 =	16.835349
003		.900000 x	24.769248 =	22.292323
6501		.920000 x	250.183364 =	230.168695
-----				
			T.E =	269.296367
6508	6508			
002		1.300000 x	18.705943 =	24.317726
003		1.300000 x	24.769248 =	32.200022
6501		1.030000 x	250.183364 =	257.688865
-----				
			T.E =	314.206613
6509	6509			
002		1.000000 x	18.705943 =	18.705943
6501		1.010000 x	250.183364 =	252.685198
003		1.000000 x	24.769248 =	24.769248
-----				
			T.E =	296.160389
6510	6510			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.080000 x	250.183364 =	270.198033
-----				
			T.E =	322.368262

6511	6511			
002		1.500000 x	18.705943 =	28.058915
003		1.500000 x	24.769248 =	37.153872
6501		.920000 x	250.183364 =	230.168695
		-----		
			T.E =	295.381481
6512	6512			
002		1.400000 x	18.705943 =	26.188320
003		1.400000 x	24.769248 =	34.676947
6501		.820000 x	250.183364 =	205.150358
		-----		
			T.E =	266.015626
6513	6513			
002		1.300000 x	18.705943 =	24.317726
6501		.780000 x	250.183364 =	195.143024
003		1.300000 x	24.769248 =	32.200022
		-----		
			T.E =	251.660772
6514	6514			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		.760000 x	250.183364 =	190.139357
		-----		
			T.E =	242.309586
6515	6515			
002		1.000000 x	18.705943 =	18.705943
003		1.000000 x	24.769248 =	24.769248
6501		.800000 x	250.183364 =	200.146691
		-----		
			T.E =	243.621882
6516	6516			
002		1.300000 x	18.705943 =	24.317726
003		1.300000 x	24.769248 =	32.200022
6501		1.220000 x	250.183364 =	305.223704
		-----		
			T.E =	361.741452
6517	6517			
002		1.200000 x	18.705943 =	22.447132
6501		1.120000 x	250.183364 =	280.205368
003		1.200000 x	24.769248 =	29.723098
		-----		
			T.E =	332.375597



6518	6518			
002		1.100000 x	18.705943 =	20.576537
003		1.100000 x	24.769248 =	27.246173
6501		.670000 x	250.183364 =	167.622854
-----				
			T.E =	215.445564
6519	6519			
002		1.300000 x	18.705943 =	24.317726
003		1.300000 x	24.769248 =	32.200022
6501		1.280000 x	250.183364 =	320.234706
-----				
			T.E =	376.752454
6520	6520			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.120000 x	250.183364 =	280.205368
-----				
			T.E =	332.375597
6521	6521			
002		1.300000 x	18.705943 =	24.317726
6501		1.210000 x	250.183364 =	302.721870
003		1.300000 x	24.769248 =	32.200022
-----				
			T.E =	359.239619
6522	6522			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.190000 x	250.183364 =	297.718203
-----				
			T.E =	349.888432
6523	6523			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		1.280000 x	250.183364 =	320.234706
-----				
			T.E =	372.404935
6524	6524			
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
6501		.800000 x	250.183364 =	200.146691
-----				
			T.E =	252.316920

6525	6525				
002		1.200000 x	18.705943 =	22.447132	
6501		1.040000 x	250.183364 =	260.190699	
003		1.200000 x	24.769248 =	29.723098	
		-----			
			T.E =	312.360928	
6526	6526				
002		1.300000 x	18.705943 =	24.317726	
003		1.300000 x	24.769248 =	32.200022	
6501		.900000 x	250.183364 =	225.165028	
		-----			
			T.E =	281.682776	
6527	6527				
002		1.300000 x	18.705943 =	24.317726	
003		1.300000 x	24.769248 =	32.200022	
6501		1.120000 x	250.183364 =	280.205368	
		-----			
			T.E =	336.723116	
6528	6528				
002		1.200000 x	18.705943 =	22.447132	
003		1.200000 x	24.769248 =	29.723098	
6501		.840000 x	250.183364 =	210.154026	
		-----			
			T.E =	262.324255	
6529	6529				
002		1.200000 x	18.705943 =	22.447132	
6501		1.080000 x	250.183364 =	270.198033	
003		1.200000 x	24.769248 =	29.723098	
		-----			
			T.E =	322.368262	
6530	6530				
002		1.000000 x	18.705943 =	18.705943	
6501		.710000 x	250.183364 =	177.630188	
003		1.000000 x	24.769248 =	24.769248	
		-----			
			T.E =	221.105379	
6531	6531				
002		.600000 x	18.705943 =	11.223566	
003		.600000 x	24.769248 =	14.861549	
6501		.480000 x	250.183364 =	120.088015	
		-----			
			T.E =	146.173129	

6532	6532				
294		6.000000 x	3.149800 =	18.898800	
294		.300000 x	3.149800 =	.944940	
002		2.500000 x	18.705943 =	46.764858	
003		2.500000 x	24.769248 =	61.923120	
296		1.000000 x	11.781900 =	11.781900	
-----					
			T.E =	140.313618	
6541	6541				
282		.350000 x	.786500 =	.275275	
295		1.050000 x	5.649200 =	5.931660	
003		.500000 x	24.769248 =	12.384624	
002		.500000 x	18.705943 =	9.352972	
296		.120000 x	11.781900 =	1.413828	
-----					
			T.E =	29.358359	
6542	6542				
295		1.050000 x	5.649200 =	5.931660	
003		.800000 x	24.769248 =	19.815398	
002		.800000 x	18.705943 =	14.964754	
296		.100000 x	11.781900 =	1.178190	
-----					
			T.E =	41.890003	
6543	6543				
295		.400000 x	5.649200 =	2.259680	
003		.200000 x	24.769248 =	4.953850	
296		.130000 x	11.781900 =	1.531647	
-----					
			T.E =	8.745177	
7101	7101				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.496500 =	.614965	
003		.850000 x	24.769248 =	21.053861	
002		.500000 x	18.705943 =	9.352972	
-----					
			T.E =	31.166797	
7102	7102				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.496500 =	.614965	
003		.700000 x	24.769248 =	17.338474	
002		.400000 x	18.705943 =	7.482377	
-----					
			T.E =	25.580816	

7103	7103				
201		.000500 x	290.000000 =	.145000	
002		.300000 x	18.705943 =	5.611783	
003		.600000 x	24.769248 =	14.861549	
1445		.004000 x	61.496500 =	.245986	
-----					
			T.E =	20.864318	
7104	7104				
201		.000500 x	290.000000 =	.145000	
003		1.000000 x	24.769248 =	24.769248	
1445		.008000 x	61.496500 =	.491972	
002		.600000 x	18.705943 =	11.223566	
-----					
			T.E =	36.629786	
7111	7111				
201		.000500 x	290.000000 =	.145000	
003		.600000 x	24.769248 =	14.861549	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	16.829739 =	5.048922	
-----					
			T.E =	20.845601	
7116	7116				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	41.466750 =	1.119602	
003		.650000 x	24.769248 =	16.100011	
001		.350000 x	16.829739 =	5.890409	
-----					
			T.E =	23.255022	
7121	7121				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	61.496500 =	1.660406	
003		.800000 x	24.769248 =	19.815398	
001		.300000 x	16.829739 =	5.048922	
-----					
			T.E =	26.669726	
7122	7122				
201		.000500 x	290.000000 =	.145000	
1444		.027000 x	75.407500 =	2.036003	
001		.300000 x	16.829739 =	5.048922	
003		.800000 x	24.769248 =	19.815398	
-----					
			T.E =	27.045323	

7123	7123				
201		.000500 x	290.000000 =		.145000
1462		.015000 x	85.011250 =		1.275169
1446		.006000 x	52.530500 =		.315183
001		.300000 x	16.829739 =		5.048922
1445		.006000 x	61.496500 =		.368979
003		.900000 x	24.769248 =		22.292323
				T.E =	29.445576
7124.1	7124.1				
201		.000500 x	290.000000 =		.145000
001		.300000 x	16.829739 =		5.048922
1445		.012000 x	61.496500 =		.737958
1465		.015000 x	91.380150 =		1.370702
003		.900000 x	24.769248 =		22.292323
				T.E =	29.594905
7124.2	7124.2				
201		.000500 x	290.000000 =		.145000
1466		.015000 x	89.443950 =		1.341659
1445		.012000 x	61.496500 =		.737958
003		.900000 x	24.769248 =		22.292323
001		.300000 x	16.829739 =		5.048922
				T.E =	29.565862
7124.3	7124.3				
201		.000500 x	290.000000 =		.145000
1467		.015000 x	84.926150 =		1.273892
1445		.012000 x	61.496500 =		.737958
001		.300000 x	16.829739 =		5.048922
003		.900000 x	24.769248 =		22.292323
				T.E =	29.498095
7131	7131				
201		.000500 x	290.000000 =		.145000
1413		.021000 x	29.264100 =		.614546
1426		.006000 x	152.456250 =		.914738
001		.300000 x	16.829739 =		5.048922
003		.600000 x	24.769248 =		14.861549
				T.E =	21.584754

7132	7132				
201		.000500 x	290.000000 =		.145000
1427		.006000 x	163.154700 =		.978928
1418		.021000 x	41.466750 =		.870802
001		.350000 x	16.829739 =		5.890409
003		.650000 x	24.769248 =		16.100011
-----					
			T.E =		23.985150
7133	7133				
201		.000500 x	290.000000 =		.145000
1463		.015000 x	72.237750 =		1.083566
1427		.006000 x	163.154700 =		.978928
1418		.006000 x	41.466750 =		.248801
003		.600000 x	24.769248 =		14.861549
001		.350000 x	16.829739 =		5.890409
-----					
			T.E =		23.208252
7134	7134				
201		.000500 x	290.000000 =		.145000
001		.350000 x	16.829739 =		5.890409
003		.600000 x	24.769248 =		14.861549
1464		.015000 x	54.951600 =		.824274
1427		.006000 x	163.154700 =		.978928
1418		.006000 x	41.466750 =		.248801
-----					
			T.E =		22.948960
7136	7136				
201		.000500 x	290.000000 =		.145000
001		.250000 x	16.829739 =		4.207435
1418		.017000 x	41.466750 =		.704935
003		.400000 x	24.769248 =		9.907699
-----					
			T.E =		14.965069
7138	7138				
201		.000500 x	290.000000 =		.145000
001		.300000 x	16.829739 =		5.048922
1418		.027000 x	41.466750 =		1.119602
003		.800000 x	24.769248 =		19.815398
-----					
			T.E =		26.128922
7141	7141				
201		.000500 x	290.000000 =		.145000
1445		.027000 x	61.496500 =		1.660406
003		1.000000 x	24.769248 =		24.769248
001		.400000 x	16.829739 =		6.731896
-----					
			T.E =		33.306549

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
001		.350000 x	16.829739 =	5.890409
003		.650000 x	24.769248 =	16.100011

-----  
T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1421		.016000 x	.000000 =	.000000
001		.350000 x	16.829739 =	5.890409
1413		.007000 x	29.264100 =	.204849
003		.650000 x	24.769248 =	16.100011

-----  
T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1413		.014000 x	29.264100 =	.409697
001		.450000 x	16.829739 =	7.573383
1422		.016000 x	.000000 =	.000000
003		.600000 x	24.769248 =	14.861549

-----  
T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1422		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849
003		.600000 x	24.769248 =	14.861549
001		.450000 x	16.829739 =	7.573383

-----  
T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
001		.350000 x	16.829739 =	5.890409
1418		.014000 x	41.466750 =	.580535
003		.650000 x	24.769248 =	16.100011
1422		.016000 x	.000000 =	.000000

-----  
T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
003		.650000 x	24.769248 =	16.100011
1418		.007000 x	41.466750 =	.290267
1422		.016000 x	.000000 =	.000000
1427		.007000 x	163.154700 =	1.142083
001		.350000 x	16.829739 =	5.890409

-----  
T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
1447		.014000 x	58.635900 =	.820903
1448		.016000 x	.000000 =	.000000
003		.700000 x	24.769248 =	17.338474
001		.450000 x	16.829739 =	7.573383

-----  
T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
1448		.016000 x	.000000 =	.000000
1447		.007000 x	58.635900 =	.410451
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	24.769248 =	17.338474
001		.450000 x	16.829739 =	7.573383

-----  
T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1445		.022000 x	61.496500 =	1.352923
003		1.600000 x	24.769248 =	39.630797
1453		.020000 x	162.552750 =	3.251055
002		1.600000 x	18.705943 =	29.929509
001		.600000 x	16.829739 =	10.097843

-----  
T.E = 84.494127

7162	7162			
201		.000800 x	290.000000 =	.232000
1458		.020000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
001		.600000 x	16.829739 =	10.097843
003		1.600000 x	24.769248 =	39.630797
002		1.600000 x	18.705943 =	29.929509

-----  
T.E =



7163	7163			
201		.000800 x	290.000000 =	.232000
1454		.020000 x	186.807750 =	3.736155
003		1.600000 x	24.769248 =	39.630797
002		1.600000 x	18.705943 =	29.929509
1445		.022000 x	61.496500 =	1.352923
001		.600000 x	16.829739 =	10.097843

-----  
T.E = 84.979227

7164	7164			
201		.000800 x	290.000000 =	.232000
1455		.020000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
003		1.600000 x	24.769248 =	39.630797
002		1.600000 x	18.705943 =	29.929509
001		.600000 x	16.829739 =	10.097843

-----  
T.E =

7165	7165			
201		.000800 x	290.000000 =	.232000
001		.600000 x	16.829739 =	10.097843
002		1.600000 x	18.705943 =	29.929509
1459		.020000 x	203.307750 =	4.066155
1445		.022000 x	61.496500 =	1.352923
003		1.600000 x	24.769248 =	39.630797

-----  
T.E = 85.309227

7166	7166			
201		.000800 x	290.000000 =	.232000
1453		.017000 x	162.552750 =	2.763397
1445		.022000 x	61.496500 =	1.352923
001		.500000 x	16.829739 =	8.414870
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132

-----  
T.E = 64.933418

7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	16.829739 =	8.414870
003		1.200000 x	24.769248 =	29.723098
1458		.017000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
002		1.200000 x	18.705943 =	22.447132

-----  
T.E =

7168	7168			
201		.000800 x	290.000000 =	.232000
1454		.017000 x	186.807750 =	3.175732
1445		.022000 x	61.496500 =	1.352923
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132
001		.500000 x	16.829739 =	8.414870
		-----		
			T.E =	65.345753
7169	7169			
201		.000800 x	290.000000 =	.232000
001		.500000 x	16.829739 =	8.414870
002		1.200000 x	18.705943 =	22.447132
1455		.017000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
003		1.200000 x	24.769248 =	29.723098
		-----		
			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
1459		.017000 x	203.307750 =	3.456232
1445		.022000 x	61.496500 =	1.352923
001		.500000 x	16.829739 =	8.414870
002		1.200000 x	18.705943 =	22.447132
003		1.200000 x	24.769248 =	29.723098
		-----		
			T.E =	65.626253
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	16.829739 =	1.682974
		-----		
			T.E =	1.885974
7176	7176			
003		1.500000 x	24.769248 =	37.153872
		-----		
			T.E =	37.153872
7177	7177			
003		1.100000 x	24.769248 =	27.246173
		-----		
			T.E =	27.246173
7178	7178			
003		.900000 x	24.769248 =	22.292323
		-----		
			T.E =	22.292323

7179	7179			
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	12.384624
7181	7181			
003		.700000 x	24.769248 =	17.338474
		-----		
			T.E =	17.338474
7206	7206			
142		26.000000 x	.325000 =	8.450000
1412		.040000 x	27.931800 =	1.117272
003		.600000 x	24.769248 =	14.861549
002		.300000 x	18.705943 =	5.611783
		-----		
			T.E =	30.040604
7207	7207			
142		26.000000 x	.325000 =	8.450000
1412		.020000 x	27.931800 =	.558636
003		.500000 x	24.769248 =	12.384624
002		.250000 x	18.705943 =	4.676486
		-----		
			T.E =	26.069746
7208	7208			
142		26.000000 x	.325000 =	8.450000
002		.200000 x	18.705943 =	3.741189
003		.400000 x	24.769248 =	9.907699
1412		.025000 x	27.931800 =	.698295
		-----		
			T.E =	22.797183
7209	7209			
142		26.000000 x	.325000 =	8.450000
1412		.005000 x	27.931800 =	.139659
002		.150000 x	18.705943 =	2.805891
003		.300000 x	24.769248 =	7.430774
		-----		
			T.E =	18.826325
7211	7211			
146		15.000000 x	.340000 =	5.100000
1445		.001000 x	61.496500 =	.061497
003		.400000 x	24.769248 =	9.907699
283		.075000 x	1.036900 =	.077768
002		.200000 x	18.705943 =	3.741189
		-----		
			T.E =	18.888152

7221	7221				
203.2		.001500 x	335.000000 =	.502500	
254		.020000 x	2.780000 =	.055600	
492		.200000 x	.540000 =	.108000	
003		.200000 x	24.769248 =	4.953850	
002		.150000 x	18.705943 =	2.805891	
506		1.150000 x	1.149500 =	1.321925	
			T.E =	9.747766	
7222	7222				
254		.050000 x	2.780000 =	.139000	
492		.200000 x	.540000 =	.108000	
002		.150000 x	18.705943 =	2.805891	
003		.250000 x	24.769248 =	6.192312	
506		1.200000 x	1.149500 =	1.379400	
			T.E =	10.624603	
7223	7223				
254		.050000 x	2.780000 =	.139000	
493		.200000 x	.730000 =	.146000	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
508		1.200000 x	.860000 =	1.032000	
			T.E =	10.012038	
7231	7231				
274		1.200000 x	1.090400 =	1.308480	
003		.250000 x	24.769248 =	6.192312	
002		.250000 x	18.705943 =	4.676486	
274		.200000 x	1.090400 =	.218080	
			T.E =	12.395358	
7241	7241				
297.2		.051072 x	.000000 =	.000000	
495		.500000 x	.000000 =	.000000	
002		1.400000 x	18.705943 =	26.188320	
003		1.400000 x	24.769248 =	34.676947	
001		.200000 x	16.829739 =	3.365948	
			T.E =		

7242	7242				
297.2		.057000 x	.000000 =	.000000	
001		.200000 x	16.829739 =	3.365948	
003		2.800000 x	24.769248 =	69.353894	
002		2.800000 x	18.705943 =	52.376640	
495		1.000000 x	.000000 =	.000000	
			T.E =		
7243.1	7243.1				
179		1.200000 x	.000000 =	.000000	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
251		1.300000 x	.695000 =	.903500	
			T.E =		
7243.2	7243.2				
180		1.200000 x	.000000 =	.000000	
251		1.300000 x	.695000 =	.903500	
002		.200000 x	18.705943 =	3.741189	
003		.200000 x	24.769248 =	4.953850	
			T.E =		
7243.3	7243.3				
181		1.200000 x	.000000 =	.000000	
251		1.300000 x	.695000 =	.903500	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
			T.E =		
7244	7244				
251		1.200000 x	.695000 =	.834000	
273		1.200000 x	.884000 =	1.060800	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
			T.E =	45.369991	
7245	7245				
251		.500000 x	.695000 =	.347500	
003		.700000 x	24.769248 =	17.338474	
002		.700000 x	18.705943 =	13.094160	
273		1.200000 x	.884000 =	1.060800	
			T.E =	31.840934	

7246	7246			
265		.500000 x	.691500 =	.345750
003		1.000000 x	24.769248 =	24.769248
002		1.000000 x	18.705943 =	18.705943
298.1		6.700000 x	4.750000 =	31.825000
		-----		
			T.E =	75.645941
7301	7301			
096		1.050000 x	.000000 =	.000000
1444		.001500 x	75.407500 =	.113111
1445		.025000 x	61.496500 =	1.537413
003		.900000 x	24.769248 =	22.292323
001		.400000 x	16.829739 =	6.731896
		-----		
			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
1445		.025000 x	61.496500 =	1.537413
1444		.002000 x	75.407500 =	.150815
003		1.000000 x	24.769248 =	24.769248
001		.500000 x	16.829739 =	8.414870
		-----		
			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
001		1.000000 x	16.829739 =	16.829739
003		2.000000 x	24.769248 =	49.538496
1445		.025000 x	61.496500 =	1.537413
1444		.001000 x	75.407500 =	.075408
		-----		
			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	61.496500 =	1.537413
001		.800000 x	16.829739 =	13.463791
1444		.001500 x	75.407500 =	.113111
003		1.600000 x	24.769248 =	39.630797
		-----		
			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
001		.150000 x	16.829739 =	2.524461
1444		.000200 x	75.407500 =	.015082
1445		.004000 x	61.496500 =	.245986
003		.300000 x	24.769248 =	7.430774
		-----		
			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1445		.005000 x	61.496500 =	.307483
1417		.033000 x	40.134450 =	1.324437
003		2.200000 x	24.769248 =	54.492346
001		.600000 x	16.829739 =	10.097843
-----				
			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
001		.500000 x	16.829739 =	8.414870
003		1.100000 x	24.769248 =	27.246173
1417		.033000 x	40.134450 =	1.324437
1445		.005000 x	61.496500 =	.307483
-----				
			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	16.829739 =	6.731896
1417		.022000 x	40.134450 =	.882958
1445		.004000 x	61.496500 =	.245986
003		.900000 x	24.769248 =	22.292323
-----				
			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	16.829739 =	8.414870
1449		.030000 x	53.110700 =	1.593321
003		2.500000 x	24.769248 =	61.923120
-----				
			T.E =	
7315	7315			
155		1.050000 x	2.481600 =	2.605680
1449		.004000 x	53.110700 =	.212443
003		.300000 x	24.769248 =	7.430774
001		.100000 x	16.829739 =	1.682974
-----				
			T.E =	11.931871
7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	53.110700 =	1.327768
1444		.002000 x	75.407500 =	.150815
001		.300000 x	16.829739 =	5.048922
003		.600000 x	24.769248 =	14.861549
-----				
			T.E =	28.424053

7317	7317			
163		1.050000 x	6.900000 =	7.245000
1449		.025000 x	53.110700 =	1.327768
001		.300000 x	16.829739 =	5.048922
1444		.001500 x	75.407500 =	.113111
003		.800000 x	24.769248 =	19.815398

-----  
T.E = 33.550199

7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1444		.001000 x	75.407500 =	.075408
001		.100000 x	16.829739 =	1.682974
1449		.025000 x	53.110700 =	1.327768
003		1.300000 x	24.769248 =	32.200022

-----  
T.E =

7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	53.110700 =	1.327768
1444		.001000 x	75.407500 =	.075408
003		1.300000 x	24.769248 =	32.200022
001		.100000 x	16.829739 =	1.682974

-----  
T.E =

7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
003		1.500000 x	24.769248 =	37.153872
1449		.025000 x	53.110700 =	1.327768
1444		.001000 x	75.407500 =	.075408
001		.400000 x	16.829739 =	6.731896

-----  
T.E =

7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
1444		.001000 x	75.407500 =	.075408
1449		.025000 x	53.110700 =	1.327768
003		1.500000 x	24.769248 =	37.153872
001		.400000 x	16.829739 =	6.731896

-----  
T.E =



7324	7324			
166		1.050000 x	.000000 =	.000000
1449		.002000 x	53.110700 =	.106221
1444		.000100 x	75.407500 =	.007541
003		.200000 x	24.769248 =	4.953850
001		.040000 x	16.829739 =	.673190

-----  
T.E =

7326.1	7326.1			
029		.200000 x	.152800 =	.030560
173		48.000000 x	.281700 =	13.521600
003		3.000000 x	24.769248 =	74.307744
1449		.020000 x	53.110700 =	1.062214
1444		.005000 x	75.407500 =	.377038
001		.500000 x	16.829739 =	8.414870

-----  
T.E =

97.714025

7326.2	7326.2			
029		.200000 x	.152800 =	.030560
174		48.000000 x	.000000 =	.000000
1449		.020000 x	53.110700 =	1.062214
1444		.005000 x	75.407500 =	.377038
003		3.000000 x	24.769248 =	74.307744
001		.500000 x	16.829739 =	8.414870

-----  
T.E =

7327	7327			
029		.200000 x	.152800 =	.030560
1449		.020000 x	53.110700 =	1.062214
1444		.007000 x	75.407500 =	.527853
003		4.000000 x	24.769248 =	99.076992
001		.600000 x	16.829739 =	10.097843
175		95.000000 x	.000000 =	.000000

-----  
T.E =

7328.1	7328.1			
029		.300000 x	.152800 =	.045840
171		108.000000 x	.000000 =	.000000
001		.700000 x	16.829739 =	11.780817
1449		.020000 x	53.110700 =	1.062214
1444		.007000 x	75.407500 =	.527853
003		4.000000 x	24.769248 =	99.076992

-----  
T.E =

7328.2

7328.2

029	.300000 x	.152800 =	.045840
1449	.020000 x	53.110700 =	1.062214
1444	.007000 x	75.407500 =	.527853
172	108.000000 x	.000000 =	.000000
003	4.000000 x	24.769248 =	99.076992
001	.700000 x	16.829739 =	11.780817

-----  
T.E =

7331

7331

029	1.500000 x	.152800 =	.229200
169	54.000000 x	.000000 =	.000000
003	3.500000 x	24.769248 =	86.692368
1449	.020000 x	53.110700 =	1.062214
1444	.005000 x	75.407500 =	.377038
001	.500000 x	16.829739 =	8.414870

-----  
T.E =

7332

7332

029	2.000000 x	.152800 =	.305600
1449	.020000 x	53.110700 =	1.062214
1444	.005000 x	75.407500 =	.377038
003	4.500000 x	24.769248 =	111.461616
001	.800000 x	16.829739 =	13.463791
170	108.000000 x	.000000 =	.000000

-----  
T.E =

7333

7333

029	.300000 x	.152800 =	.045840
167	1.050000 x	.000000 =	.000000
003	2.500000 x	24.769248 =	61.923120
002	.500000 x	18.705943 =	9.352972
1449	.020000 x	53.110700 =	1.062214

-----  
T.E =

7334

7334

029	.300000 x	.152800 =	.045840
168	1.050000 x	.000000 =	.000000
003	3.000000 x	24.769248 =	74.307744
002	.600000 x	18.705943 =	11.223566
1449	.020000 x	53.110700 =	1.062214

-----  
T.E =

7335	7335				
001		.450000 x	16.829739 =	7.573383	
1444		.007000 x	75.407500 =	.527853	
1445		.026000 x	61.496500 =	1.598909	
003		1.000000 x	24.769248 =	24.769248	
		-----			
			T.E =	34.469392	
7336	7336				
001		.400000 x	16.829739 =	6.731896	
1445		.022000 x	61.496500 =	1.352923	
1444		.006000 x	75.407500 =	.452445	
003		.900000 x	24.769248 =	22.292323	
		-----			
			T.E =	30.829587	
7337	7337				
001		.350000 x	16.829739 =	5.890409	
003		.800000 x	24.769248 =	19.815398	
1445		.017000 x	61.496500 =	1.045441	
1444		.005000 x	75.407500 =	.377038	
		-----			
			T.E =	27.128285	
7338	7338				
026		.500000 x	.098900 =	.049450	
001		.300000 x	16.829739 =	5.048922	
1445		.017000 x	61.496500 =	1.045441	
003		.700000 x	24.769248 =	17.338474	
		-----			
			T.E =	23.482286	
7340	7340				
289		1.100000 x	.659100 =	.725010	
001		.400000 x	16.829739 =	6.731896	
1445		.026000 x	61.496500 =	1.598909	
1444		.007000 x	75.407500 =	.527853	
003		1.100000 x	24.769248 =	27.246173	
		-----			
			T.E =	36.829840	
7341	7341				
003		.200000 x	24.769248 =	4.953850	
1441		.003000 x	26.861000 =	.080583	
		-----			
			T.E =	5.034433	
7346	7346				
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	4.953850	

7347	7347				
001		.200000 x	16.829739 =	3.365948	
003		.500000 x	24.769248 =	12.384624	
1445		.009000 x	61.496500 =	.553469	
1444		.002000 x	75.407500 =	.150815	
-----					
			T.E =	16.454855	
7351	7351				
001		.200000 x	16.829739 =	3.365948	
003		.600000 x	24.769248 =	14.861549	
1444		.009000 x	75.407500 =	.678668	
-----					
			T.E =	18.906164	
7352	7352				
001		.200000 x	16.829739 =	3.365948	
1444		.012000 x	75.407500 =	.904890	
003		.700000 x	24.769248 =	17.338474	
-----					
			T.E =	21.609311	
7355	7355				
001		.150000 x	16.829739 =	2.524461	
003		.600000 x	24.769248 =	14.861549	
1444		.008000 x	75.407500 =	.603260	
-----					
			T.E =	17.989270	
7356	7356				
001		.100000 x	16.829739 =	1.682974	
003		.550000 x	24.769248 =	13.623086	
1444		.007000 x	75.407500 =	.527853	
-----					
			T.E =	15.833913	
7357	7357				
001		.050000 x	16.829739 =	.841487	
1444		.006000 x	75.407500 =	.452445	
003		.500000 x	24.769248 =	12.384624	
-----					
			T.E =	13.678556	
7359	7359				
021		.100000 x	2.670000 =	.267000	
026		20.000000 x	.098900 =	1.978000	
003		.900000 x	24.769248 =	22.292323	
002		.900000 x	18.705943 =	16.835349	
065		.040000 x	13.610000 =	.544400	
-----					
			T.E =	41.917072	

7360	7360			
021		.050000 x	2.670000 =	.133500
026		13.000000 x	.098900 =	1.285700
065		.027000 x	13.610000 =	.367470
003		.700000 x	24.769248 =	17.338474
002		.700000 x	18.705943 =	13.094160
		-----		
			T.E =	32.219304
7361	7361			
021		.050000 x	2.670000 =	.133500
026		14.000000 x	.098900 =	1.384600
002		1.000000 x	18.705943 =	18.705943
003		1.400000 x	24.769248 =	34.676947
346.1		30.000000 x	.057200 =	1.716000
065		.015000 x	13.610000 =	.204150
		-----		
			T.E =	56.821140
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	24.769248 =	34.676947
002		1.000000 x	18.705943 =	18.705943
348		8.000000 x	.103600 =	.828800
346.1		22.000000 x	.057200 =	1.258400
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.098900 =	1.384600
		-----		
			T.E =	57.192340
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
026		14.000000 x	.098900 =	1.384600
346.2		22.000000 x	.103600 =	2.279200
002		1.000000 x	18.705943 =	18.705943
003		1.400000 x	24.769248 =	34.676947
348		8.000000 x	.103600 =	.828800
065		.015000 x	13.610000 =	.204150
		-----		
			T.E =	58.213140
7363	7363			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	24.769248 =	39.630797
002		1.200000 x	18.705943 =	22.447132
026		17.000000 x	.098900 =	1.681300
346.1		35.000000 x	.057200 =	2.002000
065		.020000 x	13.610000 =	.272200
		-----		
			T.E =	66.166928

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	24.769248 =	39.630797
002		1.200000 x	18.705943 =	22.447132
348		11.000000 x	.103600 =	1.139600
346.1		24.000000 x	.057200 =	1.372800
026		17.000000 x	.098900 =	1.681300
065		.020000 x	13.610000 =	.272200
-----				
			T.E =	66.677328
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	24.769248 =	39.630797
002		1.200000 x	18.705943 =	22.447132
348		11.000000 x	.103600 =	1.139600
346.2		24.000000 x	.103600 =	2.486400
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.098900 =	1.681300
-----				
			T.E =	67.790928
7366	7366			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.098900 =	.989000
003		3.000000 x	24.769248 =	74.307744
1446		.010000 x	52.530500 =	.525305
002		2.000000 x	18.705943 =	37.411886
346.1		45.000000 x	.057200 =	2.574000
-----				
			T.E =	115.941435
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.530500 =	.525305
003		3.000000 x	24.769248 =	74.307744
002		2.000000 x	18.705943 =	37.411886
026		10.000000 x	.098900 =	.989000
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000
-----				
			T.E =	116.637435
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.098900 =	.989000
348		15.000000 x	.103600 =	1.554000
003		3.000000 x	24.769248 =	74.307744
1446		.010000 x	52.530500 =	.525305
002		2.000000 x	18.705943 =	37.411886
346.2		30.000000 x	.103600 =	3.108000
-----				
			T.E =	118.029435

7371.1	7371.1					
026	-	14.000000 x	.098900 =	-	1.384600	
7361		1.000000 x	56.821140 =		56.821140	
029		14.000000 x	.152800 =		2.139200	
-----						
			T.E =		57.575740	
7371.2	7371.2					
026	-	14.000000 x	.098900 =	-	1.384600	
7361		1.000000 x	56.821140 =		56.821140	
028		14.000000 x	.000000 =		.000000	
-----						
			T.E =			
7372.1	7372.1					
026	-	14.000000 x	.098900 =	-	1.384600	
7362.1		1.000000 x	57.192340 =		57.192340	
029		14.000000 x	.152800 =		2.139200	
-----						
			T.E =		57.946940	
7372.2	7372.2					
026	-	14.000000 x	.098900 =	-	1.384600	
7362.1		1.000000 x	57.192340 =		57.192340	
028		14.000000 x	.000000 =		.000000	
-----						
			T.E =			
7372.3	7372.3					
026	-	14.000000 x	.098900 =	-	1.384600	
029		14.000000 x	.152800 =		2.139200	
7362.2		1.000000 x	58.213140 =		58.213140	
-----						
			T.E =		58.967740	
7372.4	7372.4					
026	-	14.000000 x	.098900 =	-	1.384600	
028		14.000000 x	.000000 =		.000000	
7362.2		1.000000 x	58.213140 =		58.213140	
-----						
			T.E =			
7373.1	7373.1					
026	-	17.000000 x	.098900 =	-	1.681300	
029		17.000000 x	.152800 =		2.597600	
7363		1.000000 x	66.166928 =		66.166928	
-----						
			T.E =		67.083228	

7373.2	7373.2					
026	-	17.000000 x	.098900 =	-	1.681300	
7363		1.000000 x	66.166928 =		66.166928	
028		17.000000 x	.000000 =		.000000	
-----						
			T.E =			
7374.1	7374.1					
026	-	17.000000 x	.098900 =	-	1.681300	
7364.1		1.000000 x	66.677328 =		66.677328	
029		17.000000 x	.152800 =		2.597600	
-----						
			T.E =		67.593628	
7374.2	7374.2					
026	-	17.000000 x	.098900 =	-	1.681300	
028		17.000000 x	.000000 =		.000000	
7364.1		1.000000 x	66.677328 =		66.677328	
-----						
			T.E =			
7374.3	7374.3					
026	-	17.000000 x	.098900 =	-	1.681300	
029		17.000000 x	.152800 =		2.597600	
7364.2		1.000000 x	67.790928 =		67.790928	
-----						
			T.E =		68.707228	
7374.4	7374.4					
026	-	17.000000 x	.098900 =	-	1.681300	
028		17.000000 x	.000000 =		.000000	
7364.2		1.000000 x	67.790928 =		67.790928	
-----						
			T.E =			
7376.1	7376.1					
026	-	10.000000 x	.098900 =	-	.989000	
7366		1.000000 x	115.941435 =		115.941435	
029		10.000000 x	.152800 =		1.528000	
-----						
			T.E =		116.480435	
7376.2	7376.2					
026	-	10.000000 x	.098900 =	-	.989000	
028		10.000000 x	.000000 =		.000000	
7366		1.000000 x	115.941435 =		115.941435	
-----						
			T.E =			



7377.1	7377.1				
026	-	10.000000 x	.098900 =	-	.989000
7367.1		1.000000 x	116.637435 =		116.637435
029		10.000000 x	.152800 =		1.528000
-----					
			T.E =		117.176435
7377.2	7377.2				
026	-	10.000000 x	.098900 =	-	.989000
028		10.000000 x	.000000 =		.000000
7367.1		1.000000 x	116.637435 =		116.637435
-----					
			T.E =		
7377.3	7377.3				
026	-	10.000000 x	.098900 =	-	.989000
029		10.000000 x	.152800 =		1.528000
7367.2		1.000000 x	118.029435 =		118.029435
-----					
			T.E =		118.568435
7377.4	7377.4				
026	-	10.000000 x	.098900 =	-	.989000
7367.2		1.000000 x	118.029435 =		118.029435
028		10.000000 x	.000000 =		.000000
-----					
			T.E =		
7381	7381				
456		.100000 x	1.610000 =		.161000
-----					
			T.E =		.161000
7382	7382				
443		.150000 x	1.930000 =		.289500
447		.050000 x	4.393700 =		.219685
003		.300000 x	24.769248 =		7.430774
-----					
			T.E =		7.939959
7383	7383				
002		.250000 x	18.705943 =		4.676486
003		.150000 x	24.769248 =		3.715387
-----					
			T.E =		8.391873
7384	7384				
003		.500000 x	24.769248 =		12.384624
-----					
			T.E =		12.384624

7385	7385			
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	12.384624
7386	7386			
003		.600000 x	24.769248 =	14.861549
		-----		
			T.E =	14.861549
7387	7387			
261		1.500000 x	.560100 =	.840150
003		1.000000 x	24.769248 =	24.769248
7361		1.100000 x	56.821140 =	62.503254
		-----		
			T.E =	88.112652
7388	7388			
003		2.500000 x	24.769248 =	61.923120
7361		.600000 x	56.821140 =	34.092684
		-----		
			T.E =	96.015804
7389.1.1	7389.1.1			
7371.1		.300000 x	57.575740 =	17.272722
		-----		
			T.E =	17.272722
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	68.707228 =	20.612168
		-----		
			T.E =	20.612168
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	57.946940 =	17.384082
		-----		
			T.E =	17.384082
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	58.967740 =	17.690322
		-----		
			T.E =	17.690322
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	67.083228 =	20.124968
		-----		
			T.E =	20.124968
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	67.593628 =	20.278088
		-----		
			T.E =	20.278088
7389.2.1	7389.2.1			
7371.1		.500000 x	57.575740 =	28.787870
		-----		
			T.E =	28.787870
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	68.707228 =	34.353614
		-----		
			T.E =	34.353614

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	57.946940 =	28.973470
-----				
			T.E =	28.973470
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	58.967740 =	29.483870
-----				
			T.E =	29.483870
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	67.083228 =	33.541614
-----				
			T.E =	33.541614
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	67.593628 =	33.796814
-----				
			T.E =	33.796814
7391	7391			
003		.250000 x	24.769248 =	6.192312
-----				
			T.E =	6.192312

7392	7392				
298.1		1.081080 x	4.750000 =	5.135130	
003		.400000 x	24.769248 =	9.907699	
-----					
			T.E =	15.042829	
7393	7393				
294		.347760 x	3.149800 =	1.095374	
003		.300000 x	24.769248 =	7.430774	
-----					
			T.E =	8.526149	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	24.769248 =	9.907699	
-----					
			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	24.769248 =	7.430774	
-----					
			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	18.705943 =	6.547080	
003		.350000 x	24.769248 =	8.669237	
-----					
			T.E =	24.216317	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	24.769248 =	17.338474	
-----					
			T.E =	25.963474	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	18.705943 =	7.482377	
003		.400000 x	24.769248 =	9.907699	
-----					
			T.E =	25.778876	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	24.769248 =	6.192312	
-----					
			T.E =	7.732312	

7416	7416			
003		.800000 x	24.769248 =	19.815398
		-----		
			T.E =	19.815398
7417	7417			
003		1.800000 x	24.769248 =	44.584646
		-----		
			T.E =	44.584646
7418	7418			
003		2.600000 x	24.769248 =	64.400045
		-----		
			T.E =	64.400045
7419	7419			
003		.800000 x	24.769248 =	19.815398
		-----		
			T.E =	19.815398
7420	7420			
003		1.200000 x	24.769248 =	29.723098
		-----		
			T.E =	29.723098
7421	7421			
003		.800000 x	24.769248 =	19.815398
		-----		
			T.E =	19.815398
7422	7422			
003		.350000 x	24.769248 =	8.669237
		-----		
			T.E =	8.669237
7431	7431			
332		1.150000 x	88.540000 =	101.821000
003		4.000000 x	24.769248 =	99.076992
1445		.020000 x	61.496500 =	1.229930
1444		.001000 x	75.407500 =	.075408
		-----		
			T.E =	202.203330
7432	7432			
331		1.150000 x	85.390000 =	98.198500
1445		.020000 x	61.496500 =	1.229930
003		4.400000 x	24.769248 =	108.984691
1444		.001000 x	75.407500 =	.075408
		-----		
			T.E =	208.488529

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
003		5.100000 x	24.769248 =	126.323165	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
		-----			
			T.E =	225.827002	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
1444		.001000 x	75.407500 =	.075408	
1445		.020000 x	61.496500 =	1.229930	
003		6.100000 x	24.769248 =	151.092413	
		-----			
			T.E =	250.596250	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		4.200000 x	24.769248 =	104.030842	
		-----			
			T.E =	212.073679	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
003		4.600000 x	24.769248 =	113.938541	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
		-----			
			T.E =	221.981378	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		5.300000 x	24.769248 =	131.277014	
		-----			
			T.E =	239.319852	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		6.300000 x	24.769248 =	156.046262	
		-----			
			T.E =	264.089100	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
003		4.500000 x	24.769248 =	111.461616	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
		-----			
			T.E =	255.332454	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		4.900000 x	24.769248 =	121.369315	
		-----			
			T.E =	265.240153	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
003		5.600000 x	24.769248 =	138.707789	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
		-----			
			T.E =	282.578626	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
003		6.600000 x	24.769248 =	163.477037	
1444		.001000 x	75.407500 =	.075408	
1445		.020000 x	61.496500 =	1.229930	
		-----			
			T.E =	307.347874	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
003		4.900000 x	24.769248 =	121.369315	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
		-----			
			T.E =	277.637153	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		5.300000 x	24.769248 =	131.277014	
		-----			
			T.E =	287.544852	



7463	7463				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		6.000000 x	24.769248 =	148.615488	
		-----			
			T.E =	304.883326	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		7.000000 x	24.769248 =	173.384736	
		-----			
			T.E =	329.652574	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
003		.915000 x	24.769248 =	22.663862	
		-----			
			T.E =	32.614246	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
003		.945000 x	24.769248 =	23.406939	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
		-----			
			T.E =	34.211223	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
003		.990000 x	24.769248 =	24.521556	
		-----			
			T.E =	38.908639	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
003		1.050000 x	24.769248 =	26.007710	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
		-----			
			T.E =	41.634494	

7496	7496			
331		.057500 x	85.390000 =	4.909925
1445		.001000 x	61.496500 =	.061497
1444		.000050 x	75.407500 =	.003770
003		.488000 x	24.769248 =	12.087393
		-----		
			T.E =	17.062585
7497	7497			
331		.062500 x	85.390000 =	5.336875
1445		.001000 x	61.496500 =	.061497
1444		.000050 x	75.407500 =	.003770
003		.504000 x	24.769248 =	12.483701
		-----		
			T.E =	17.885843
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	24.769248 =	13.078163
1444		.000050 x	75.407500 =	.003770
1445		.001000 x	61.496500 =	.061497
		-----		
			T.E =	20.271705
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	24.769248 =	13.870779
1445		.001000 x	61.496500 =	.061497
1444		.000050 x	75.407500 =	.003770
		-----		
			T.E =	21.684171
7501	7501			
7433		1.000000 x	225.827002 =	225.827002
		-----		
			T.E =	225.827002
7503	7503			
7443		1.000000 x	239.319852 =	239.319852
		-----		
			T.E =	239.319852
7506	7506			
7453		1.000000 x	282.578626 =	282.578626
		-----		
			T.E =	282.578626
7508	7508			
7463		1.000000 x	304.883326 =	304.883326
		-----		
			T.E =	304.883326

7511	7511				
331		.115000 x	85.390000 =	9.819850	
003		.915000 x	24.769248 =	22.663862	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
		-----			
			T.E =	32.614246	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
003		.945000 x	24.769248 =	23.406939	
		-----			
			T.E =	34.211223	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	24.769248 =	141.184714	
1445		.020000 x	61.496500 =	1.229930	
		-----			
			T.E =	240.613144	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
003		4.800000 x	24.769248 =	118.892390	
1445		.020000 x	61.496500 =	1.229930	
		-----			
			T.E =	218.320820	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
003		6.100000 x	24.769248 =	151.092413	
1445		.020000 x	61.496500 =	1.229930	
		-----			
			T.E =	259.059843	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.496500 =	1.229930	
003		5.000000 x	24.769248 =	123.846240	
		-----			
			T.E =	231.813670	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	24.769248 =	128.800090	
1445		.020000 x	61.496500 =	1.229930	
		-----			
			T.E =	231.851020	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
003		5.400000 x	24.769248 =	133.753939	
1445		.020000 x	61.496500 =	1.229930	
				-----	
				T.E =	245.658869
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	24.769248 =	141.184714	
1445		.020000 x	61.496500 =	1.229930	
				-----	
				T.E =	295.169144
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	61.496500 =	1.229930	
003		6.100000 x	24.769248 =	151.092413	
				-----	
				T.E =	318.359843
7536	7536				
334		.300000 x	132.830000 =	39.849000	
003		3.000000 x	24.769248 =	74.307744	
1445		.010000 x	61.496500 =	.614965	
				-----	
				T.E =	114.771709
7537	7537				
336		.300000 x	.000000 =	.000000	
003		4.000000 x	24.769248 =	99.076992	
1445		.010000 x	61.496500 =	.614965	
				-----	
				T.E =	
7541	7541				
332		.170000 x	88.540000 =	15.051800	
334		.350000 x	132.830000 =	46.490500	
003		3.700000 x	24.769248 =	91.646218	
1445		.010000 x	61.496500 =	.614965	
				-----	
				T.E =	153.803483
7542	7542				
332		.170000 x	88.540000 =	15.051800	
336		.350000 x	.000000 =	.000000	
1445		.010000 x	61.496500 =	.614965	
003		4.200000 x	24.769248 =	104.030842	
				-----	
				T.E =	

7543	7543			
332		.170000 x	88.540000 =	15.051800
003		4.800000 x	24.769248 =	118.892390
1445		.010000 x	61.496500 =	.614965
338		.350000 x	.000000 =	.000000
-----				
			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.496500 =	1.229930
003		7.000000 x	24.769248 =	173.384736
-----				
			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
003		7.000000 x	24.769248 =	173.384736
1445		.020000 x	61.496500 =	1.229930
-----				
			T.E =	301.908166
7553	7553			
323		1.150000 x	126.500000 =	145.475000
1445		.020000 x	61.496500 =	1.229930
003		7.000000 x	24.769248 =	173.384736
-----				
			T.E =	320.089666
7554	7554			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.496500 =	1.229930
003		9.000000 x	24.769248 =	222.923232
-----				
			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
003		9.000000 x	24.769248 =	222.923232
1445		.020000 x	61.496500 =	1.229930
-----				
			T.E =	351.446662
7556	7556			
323		1.150000 x	126.500000 =	145.475000
003		9.000000 x	24.769248 =	222.923232
1445		.020000 x	61.496500 =	1.229930
-----				
			T.E =	369.628162

7558	7558				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	24.769248 =	37.153872	
1445		.003000 x	61.496500 =	.184490	
-----					
			T.E =	44.169562	
7559	7559				
331		.080000 x	85.390000 =	6.831200	
1445		.003000 x	61.496500 =	.184490	
003		1.500000 x	24.769248 =	37.153872	
-----					
			T.E =	44.169562	
7561	7561				
332		1.150000 x	88.540000 =	101.821000	
1445		.020000 x	61.496500 =	1.229930	
003		5.200000 x	24.769248 =	128.800090	
-----					
			T.E =	231.851020	
7562	7562				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	24.769248 =	141.184714	
1445		.020000 x	61.496500 =	1.229930	
-----					
			T.E =	295.169144	
7563	7563				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	61.496500 =	1.229930	
003		5.400000 x	24.769248 =	133.753939	
-----					
			T.E =	245.658869	
7564	7564				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	61.496500 =	1.229930	
003		6.100000 x	24.769248 =	151.092413	
-----					
			T.E =	318.359843	
7565	7565				
003		1.500000 x	24.769248 =	37.153872	
-----					
			T.E =	37.153872	
7566	7566				
7561		1.500000 x	231.851020 =	347.776530	
-----					
			T.E =	347.776530	

7567	7567			
7562		1.500000 x	295.169144 =	442.753716
		-----		
			T.E =	442.753716
7568	7568			
7563		1.500000 x	245.658869 =	368.488304
		-----		
			T.E =	368.488304
7569	7569			
7564		1.500000 x	318.359843 =	477.539765
		-----		
			T.E =	477.539765
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
327.1		.030000 x	.000000 =	.000000
003		3.000000 x	24.769248 =	74.307744
		-----		
			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	24.769248 =	74.307744
327.2		.030000 x	.000000 =	.000000
		-----		
			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
327.3		.030000 x	196.650000 =	5.899500
003		3.000000 x	24.769248 =	74.307744
		-----		
			T.E =	276.857244
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	24.769248 =	99.076992
328		.030000 x	.000000 =	.000000
		-----		
			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	24.769248 =	94.123142
		-----		
			T.E =	192.321642

7577	7577				
334		1.150000 x	132.830000 =	152.754500	
003		4.200000 x	24.769248 =	104.030842	
		-----			
			T.E =	256.785342	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	24.769248 =	116.415466	
		-----			
			T.E =		
7581	7581				
326		1.050000 x	63.530000 =	66.706500	
3211		.020000 x	144.934728 =	2.898695	
1445		.005000 x	61.496500 =	.307483	
003		2.300000 x	24.769248 =	56.969270	
		-----			
			T.E =	126.881947	
7601	7601				
401		1.100000 x	13.560000 =	14.916000	
457		.500000 x	.803800 =	.401900	
003		.500000 x	24.769248 =	12.384624	
		-----			
			T.E =	27.702524	
7602	7602				
403		1.100000 x	15.880000 =	17.468000	
457		.500000 x	.803800 =	.401900	
003		.550000 x	24.769248 =	13.623086	
		-----			
			T.E =	31.492986	
7603	7603				
406		1.100000 x	19.630000 =	21.593000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	24.769248 =	16.100011	
		-----			
			T.E =	38.094911	
7604.1	7604.1				
409		1.100000 x	23.370000 =	25.707000	
003		.750000 x	24.769248 =	18.576936	
457		.500000 x	.803800 =	.401900	
		-----			
			T.E =	44.685836	



7604.2	7604.2			
410		1.100000 x	31.790000 =	34.969000
003		.750000 x	24.769248 =	18.576936
457		.500000 x	.803800 =	.401900
			T.E =	53.947836
7606	7606			
401		1.100000 x	13.560000 =	14.916000
003		.600000 x	24.769248 =	14.861549
			T.E =	29.777549
7607	7607			
403		1.100000 x	15.880000 =	17.468000
003		.650000 x	24.769248 =	16.100011
			T.E =	33.568011
7608	7608			
406		1.100000 x	19.630000 =	21.593000
003		.750000 x	24.769248 =	18.576936
			T.E =	40.169936
7609.1	7609.1			
409		1.100000 x	23.370000 =	25.707000
003		.850000 x	24.769248 =	21.053861
			T.E =	46.760861
7609.2	7609.2			
410		1.100000 x	31.790000 =	34.969000
003		.850000 x	24.769248 =	21.053861
			T.E =	56.022861
7611	7611			
411		1.100000 x	29.680000 =	32.648000
457		.500000 x	.803800 =	.401900
003		.500000 x	24.769248 =	12.384624
			T.E =	45.434524
7612	7612			
412		1.100000 x	32.030000 =	35.233000
003		.550000 x	24.769248 =	13.623086
457		.500000 x	.803800 =	.401900
			T.E =	49.257986

7613	7613				
411		1.100000 x	29.680000 =	32.648000	
003		.600000 x	24.769248 =	14.861549	
			T.E =	47.509549	
7614	7614				
412		1.100000 x	32.030000 =	35.233000	
003		.650000 x	24.769248 =	16.100011	
			T.E =	51.333011	
7616	7616				
414		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.600000 x	24.769248 =	14.861549	
			T.E =	40.970449	
7617	7617				
415		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	24.769248 =	16.100011	
			T.E =	42.208911	
7618	7618				
414		1.100000 x	23.370000 =	25.707000	
003		.700000 x	24.769248 =	17.338474	
			T.E =	43.045474	
7619	7619				
415		1.100000 x	23.370000 =	25.707000	
003		.750000 x	24.769248 =	18.576936	
			T.E =	44.283936	
7621	7621				
418		1.100000 x	32.720000 =	35.992000	
457		.800000 x	.803800 =	.643040	
003		1.200000 x	24.769248 =	29.723098	
			T.E =	66.358138	
7622	7622				
419		1.100000 x	32.720000 =	35.992000	
003		1.400000 x	24.769248 =	34.676947	
457		.800000 x	.803800 =	.643040	
			T.E =	71.311987	

7626.1	7626.1			
298.2		18.000000 x	4.110000 =	73.980000
421		1.000000 x	108.710000 =	108.710000
002		7.000000 x	18.705943 =	130.941601
003		7.000000 x	24.769248 =	173.384736
		-----		
			T.E =	487.016337
7626.2	7626.2			
298.2		18.000000 x	4.110000 =	73.980000
422		1.000000 x	149.410000 =	149.410000
003		7.000000 x	24.769248 =	173.384736
002		7.000000 x	18.705943 =	130.941601
		-----		
			T.E =	527.716337
7627.1	7627.1			
298.2		16.000000 x	4.110000 =	65.760000
003		6.000000 x	24.769248 =	148.615488
002		6.000000 x	18.705943 =	112.235658
421		1.000000 x	108.710000 =	108.710000
		-----		
			T.E =	435.321146
7627.2	7627.2			
298.2		16.000000 x	4.110000 =	65.760000
003		6.000000 x	24.769248 =	148.615488
002		6.000000 x	18.705943 =	112.235658
422		1.000000 x	149.410000 =	149.410000
		-----		
			T.E =	476.021146
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	24.769248 =	1.238462
		-----		
			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	24.769248 =	1.486155
		-----		
			T.E =	6.315155
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	24.769248 =	1.981540
		-----		
			T.E =	7.910540

7638	7638				
430		1.100000 x	7.480000 =	8.228000	
003		.100000 x	24.769248 =	2.476925	
		-----			
			T.E =	10.704925	
7641	7641				
431		1.000000 x	.000000 =	.000000	
003		.060000 x	24.769248 =	1.486155	
		-----			
			T.E =		
7642	7642				
432		1.000000 x	.000000 =	.000000	
003		.060000 x	24.769248 =	1.486155	
		-----			
			T.E =		
7701	7701				
024		.001500 x	50.000000 =	.075000	
002		.050000 x	18.705943 =	.935297	
003		.120000 x	24.769248 =	2.972310	
		-----			
			T.E =	3.982607	
7702	7702				
024		.001800 x	50.000000 =	.090000	
003		.080000 x	24.769248 =	1.981540	
002		.050000 x	18.705943 =	.935297	
		-----			
			T.E =	3.006837	
7706	7706				
024		.002000 x	50.000000 =	.100000	
003		.150000 x	24.769248 =	3.715387	
002		.080000 x	18.705943 =	1.496475	
		-----			
			T.E =	5.311863	
7707	7707				
024		.002300 x	50.000000 =	.115000	
003		.090000 x	24.769248 =	2.229232	
002		.100000 x	18.705943 =	1.870594	
		-----			
			T.E =	4.214827	

7708	7708			
024		.002500 x	50.000000 =	.125000
003		.180000 x	24.769248 =	4.458465
002		.120000 x	18.705943 =	2.244713
-----				
			T.E =	6.828178
7709	7709			
024		.002800 x	50.000000 =	.140000
003		.120000 x	24.769248 =	2.972310
002		.150000 x	18.705943 =	2.805891
-----				
			T.E =	5.918201
7711	7711			
002		.050000 x	18.705943 =	.935297
1485		.200000 x	.834659 =	.166932
003		.200000 x	24.769248 =	4.953850
-----				
			T.E =	6.056079
7712	7712			
002		.080000 x	18.705943 =	1.496475
1485		.250000 x	.834659 =	.208665
003		.250000 x	24.769248 =	6.192312
-----				
			T.E =	7.897452
7713	7713			
002		.160000 x	18.705943 =	2.992951
003		.300000 x	24.769248 =	7.430774
1485		.280000 x	.834659 =	.233705
-----				
			T.E =	10.657430
7720	7720			
443		.080000 x	1.930000 =	.154400
003		.300000 x	24.769248 =	7.430774
002		.100000 x	18.705943 =	1.870594
1485		.200000 x	.834659 =	.166932
-----				
			T.E =	9.622701
7721	7721			
002		.070000 x	18.705943 =	1.309416
003		.200000 x	24.769248 =	4.953850
1485		.200000 x	.834659 =	.166932
-----				
			T.E =	6.430197

7722.1.1	7722.1.1			
7720		.300000 x	9.622701 =	2.886810
		-----		
			T.E =	2.886810
7722.1.2	7722.1.2			
7721		.300000 x	6.430197 =	1.929059
		-----		
			T.E =	1.929059
7722.2.1	7722.2.1			
7720		.400000 x	9.622701 =	3.849080
		-----		
			T.E =	3.849080
7722.2.2	7722.2.2			
7721		.400000 x	6.430197 =	2.572079
		-----		
			T.E =	2.572079
7725	7725			
471		.300000 x	4.100000 =	1.230000
003		.250000 x	24.769248 =	6.192312
002		.150000 x	18.705943 =	2.805891
		-----		
			T.E =	10.228203
7735	7735			
441		.350000 x	.075500 =	.026425
444		.150000 x	2.143200 =	.321480
003		.150000 x	24.769248 =	3.715387
		-----		
			T.E =	4.063292
7736	7736			
441		.500000 x	.075500 =	.037750
444		.085000 x	2.143200 =	.182172
445		.010000 x	1.553500 =	.015535
003		.250000 x	24.769248 =	6.192312
446		.005000 x	2.540000 =	.012700
		-----		
			T.E =	6.440469
7737	7737			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.876050 =	.175210
003		.300000 x	24.769248 =	7.430774
1488		.600000 x	.768615 =	.461169
		-----		
			T.E =	8.082253

7738	7738			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.876050 =	.175210
1488		.300000 x	.768615 =	.230585
003		.300000 x	24.769248 =	7.430774
-----				
			T.E =	7.851669
7739	7739			
441		.100000 x	.075500 =	.007550
467		.100000 x	3.380000 =	.338000
003		.150000 x	24.769248 =	3.715387
-----				
			T.E =	4.060937
7740	7740			
442		.250000 x	.118300 =	.029575
003		.250000 x	24.769248 =	6.192312
1492		.250000 x	2.756980 =	.689245
-----				
			T.E =	6.911132
7741	7741			
442		.250000 x	.118300 =	.029575
462		.250000 x	.000000 =	.000000
003		.250000 x	24.769248 =	6.192312
-----				
			T.E =	
7742	7742			
442		.250000 x	.118300 =	.029575
003		.200000 x	24.769248 =	4.953850
463		.125000 x	3.970000 =	.496250
-----				
			T.E =	5.479675
7743	7743			
442		.250000 x	.118300 =	.029575
003		.150000 x	24.769248 =	3.715387
464		.125000 x	3.720000 =	.465000
-----				
			T.E =	4.209962
7744	7744			
442		.250000 x	.118300 =	.029575
003		.150000 x	24.769248 =	3.715387
465		.125000 x	5.870000 =	.733750
-----				
			T.E =	4.478712

7745	7745			
442		.250000 x	.118300 =	.029575
1492		.250000 x	2.756980 =	.689245
003		.800000 x	24.769248 =	19.815398
1489		.200000 x	.876050 =	.175210
		-----		
			T.E =	20.709428
7746	7746			
441		.350000 x	.075500 =	.026425
003		.150000 x	24.769248 =	3.715387
443		.090000 x	1.930000 =	.173700
		-----		
			T.E =	3.915512
7747	7747			
441		.350000 x	.075500 =	.026425
003		.250000 x	24.769248 =	6.192312
443		.170000 x	1.930000 =	.328100
		-----		
			T.E =	6.546837
7748	7748			
443		.090000 x	1.930000 =	.173700
450		.060000 x	2.760000 =	.165600
003		.200000 x	24.769248 =	4.953850
002		.100000 x	18.705943 =	1.870594
445		.030000 x	1.553500 =	.046605
		-----		
			T.E =	7.210349
7749	7749			
443		.160000 x	1.930000 =	.308800
003		.250000 x	24.769248 =	6.192312
002		.150000 x	18.705943 =	2.805891
450		.100000 x	2.760000 =	.276000
445		.050000 x	1.553500 =	.077675
		-----		
			T.E =	9.660678
7751	7751			
003		.150000 x	24.769248 =	3.715387
1491		.125000 x	1.488894 =	.186112
		-----		
			T.E =	3.901499
7752	7752			
003		.250000 x	24.769248 =	6.192312
1491		.250000 x	1.488894 =	.372224
		-----		
			T.E =	6.564536



7753	7753				
441		1.000000 x	.075500 =		.075500
1491		.200000 x	1.488894 =		.297779
1490		.090000 x	1.546426 =		.139178
003		.650000 x	24.769248 =		16.100011
443		.080000 x	1.930000 =		.154400
		-----			
			T.E =		16.766868
7754	7754				
441		.800000 x	.075500 =		.060400
003		.800000 x	24.769248 =		19.815398
1487		.090000 x	.614606 =		.055315
1490		.090000 x	1.546426 =		.139178
1491		.200000 x	1.488894 =		.297779
		-----			
			T.E =		20.368070
7755	7755				
442		.250000 x	.118300 =		.029575
1492		.160000 x	2.756980 =		.441117
003		1.000000 x	24.769248 =		24.769248
1491		.200000 x	1.488894 =		.297779
		-----			
			T.E =		25.537719
7756	7756				
442		.300000 x	.118300 =		.035490
003		.350000 x	24.769248 =		8.669237
1492		.300000 x	2.756980 =		.827094
		-----			
			T.E =		9.531821
7761	7761				
441		.650000 x	.075500 =		.049075
467		.100000 x	3.380000 =		.338000
473		.100000 x	2.750000 =		.275000
1489		.200000 x	.876050 =		.175210
1488		.600000 x	.768615 =		.461169
003		.800000 x	24.769248 =		19.815398
		-----			
			T.E =		21.113852
7762	7762				
473		.100000 x	2.750000 =		.275000
003		.200000 x	24.769248 =		4.953850
		-----			
			T.E =		5.228850

7764	7764			
474		.125000 x	3.770000 =	.471250
003		.100000 x	24.769248 =	2.476925
				-----
			T.E =	2.948175
7765	7765			
475		.125000 x	6.230000 =	.778750
003		.200000 x	24.769248 =	4.953850
				-----
			T.E =	5.732600
7766	7766			
442		.275000 x	.118300 =	.032533
473		.110000 x	2.750000 =	.302500
003		.880000 x	24.769248 =	21.796938
1492		.275000 x	2.756980 =	.758170
				-----
			T.E =	22.890140
7767.1	7767.1			
7755		.150000 x	25.537719 =	3.830658
				-----
			T.E =	3.830658
7767.2	7767.2			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	24.769248 =	24.769248
				-----
			AΘΡΟΙΣΜΑ =	25.789940
	T.E =	.150000 x	25.789940 =	3.868491
				-----
7767.3	7767.3			
7755		.250000 x	25.537719 =	6.384430
				-----
			T.E =	6.384430
7767.4	7767.4			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	24.769248 =	24.769248
473		.200000 x	2.750000 =	.550000
				-----
			AΘΡΟΙΣΜΑ =	25.789940
	T.E =	.250000 x	25.789940 =	6.447485
				-----

7767.5	7767.5			
7755		.350000 x	25.537719 =	8.938202
		-----		
			T.E =	8.938202
7767.6	7767.6			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
003		1.000000 x	24.769248 =	24.769248
1492		.160000 x	2.756980 =	.441117
		-----		
			AΘΡΟΙΣΜΑ =	25.789940
	T.E =	.350000 x	25.789940 =	9.026479
		-----		
7767.7	7767.7			
7755		.450000 x	25.537719 =	11.491974
		-----		
			T.E =	11.491974
7767.8	7767.8			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
003		1.000000 x	24.769248 =	24.769248
1492		.160000 x	2.756980 =	.441117
		-----		
			AΘΡΟΙΣΜΑ =	25.789940
	T.E =	.450000 x	25.789940 =	11.605473
		-----		
7768	7768			
460		.200000 x	4.250000 =	.850000
460		.030000 x	4.250000 =	.127500
002		.450000 x	18.705943 =	8.417674
003		.450000 x	24.769248 =	11.146162
		-----		
			T.E =	20.541336
7769	7769			
460		.200000 x	4.250000 =	.850000
003		.200000 x	24.769248 =	4.953850
460		.030000 x	4.250000 =	.127500
002		.200000 x	18.705943 =	3.741189
		-----		
			T.E =	9.672538
7770	7770			
460		.090000 x	4.250000 =	.382500
003		.150000 x	24.769248 =	3.715387
002		.150000 x	18.705943 =	2.805891
460		.020000 x	4.250000 =	.085000
		-----		
			T.E =	6.988779

7771	7771			
441		1.000000 x	.075500 =	.075500
003		1.300000 x	24.769248 =	32.200022
1488		.160000 x	.768615 =	.122978
1487		.080000 x	.614606 =	.049168
467		.110000 x	3.380000 =	.371800
473		.100000 x	2.750000 =	.275000
		-----		
			T.E =	33.094469
7772	7772			
441		1.000000 x	.075500 =	.075500
003		.500000 x	24.769248 =	12.384624
443		.100000 x	1.930000 =	.193000
458		.100000 x	5.030000 =	.503000
		-----		
			T.E =	13.156124
7773	7773			
441		1.000000 x	.075500 =	.075500
443		.100000 x	1.930000 =	.193000
459		.100000 x	5.030000 =	.503000
003		.600000 x	24.769248 =	14.861549
		-----		
			T.E =	15.633049
7774	7774			
442		.250000 x	.118300 =	.029575
003		1.000000 x	24.769248 =	24.769248
1492		.160000 x	2.756980 =	.441117
473		.200000 x	2.750000 =	.550000
		-----		
			T.E =	25.789940
7785.1	7785.1			
441		.350000 x	.075500 =	.026425
003		.700000 x	24.769248 =	17.338474
477		.160000 x	.000000 =	.000000
476		.120000 x	2.366400 =	.283968
		-----		
			T.E =	
7785.2	7785.2			
441		.350000 x	.075500 =	.026425
003		.700000 x	24.769248 =	17.338474
478		.160000 x	2.937600 =	.470016
476		.120000 x	2.366400 =	.283968
		-----		
			T.E =	18.118883

7786.1	7786.1			
441		.350000 x	.075500 =	.026425
477		.110000 x	.000000 =	.000000
003		1.000000 x	24.769248 =	24.769248
1488		.600000 x	.768615 =	.461169
1489		.200000 x	.876050 =	.175210

-----  
T.E =

7786.2	7786.2			
441		.350000 x	.075500 =	.026425
478		.110000 x	2.937600 =	.323136
003		1.000000 x	24.769248 =	24.769248
1489		.200000 x	.876050 =	.175210
1488		.600000 x	.768615 =	.461169

-----  
T.E =

25.755188

7787	7787			
441		1.000000 x	.075500 =	.075500
477		.160000 x	.000000 =	.000000
476		.090000 x	2.366400 =	.212976
1488		.160000 x	.768615 =	.122978
1487		.080000 x	.614606 =	.049168
003		1.000000 x	24.769248 =	24.769248

-----  
T.E =

7788	7788			
441		.250000 x	.075500 =	.018875
003		.700000 x	24.769248 =	17.338474
479		1.000000 x	1.815600 =	1.815600

-----  
T.E =

19.172949

7791	7791			
441		1.000000 x	.075500 =	.075500
1487		.050000 x	.614606 =	.030730
1491		.200000 x	1.488894 =	.297779
003		.500000 x	24.769248 =	12.384624

-----  
T.E =

12.788633

7792	7792			
482		.150000 x	.961300 =	.144195
003		.500000 x	24.769248 =	12.384624

-----  
T.E =

12.528819

7793	7793				
480		.500000 x	3.366000 =	1.683000	
003		.200000 x	24.769248 =	4.953850	
				-----	
				T.E =	6.636850
7794	7794				
482		.150000 x	.961300 =	.144195	
003		.500000 x	24.769248 =	12.384624	
				-----	
				T.E =	12.528819
7797	7797				
201		.000500 x	290.000000 =	.145000	
002		.060000 x	18.705943 =	1.122357	
				-----	
				T.E =	1.267357
7798	7798				
201		.000600 x	290.000000 =	.174000	
002		.070000 x	18.705943 =	1.309416	
				-----	
				T.E =	1.483416
7801	7801				
496		1.200000 x	1.006100 =	1.207320	
003		.150000 x	24.769248 =	3.715387	
				-----	
				T.E =	4.922707
7806	7806				
498		1.150000 x	1.124000 =	1.292600	
003		.300000 x	24.769248 =	7.430774	
				-----	
				T.E =	8.723374
7807	7807				
499		1.150000 x	1.540900 =	1.772035	
003		.400000 x	24.769248 =	9.907699	
				-----	
				T.E =	11.679734
7808	7808				
500		1.150000 x	2.266200 =	2.606130	
003		.600000 x	24.769248 =	14.861549	
				-----	
				T.E =	17.467679

7809	7809				
501		1.200000 x	3.070000 =		3.684000
003		.800000 x	24.769248 =		19.815398
		-----			
			T.E =		23.499398
7810	7810				
502		1.200000 x	4.230000 =		5.076000
003		.900000 x	24.769248 =		22.292323
		-----			
			T.E =		27.368323
7811	7811				
503		1.200000 x	1.006100 =		1.207320
003		.800000 x	24.769248 =		19.815398
		-----			
			T.E =		21.022718
7812	7812				
504		1.300000 x	1.332400 =		1.732120
003		.900000 x	24.769248 =		22.292323
		-----			
			T.E =		24.024443
7813	7813				
505		1.000000 x	19.170000 =		19.170000
003		.600000 x	24.769248 =		14.861549
		-----			
			T.E =		34.031549
7901	7901				
490		1.080000 x	.730000 =		.788400
003		.200000 x	24.769248 =		4.953850
		-----			
			T.E =		5.742250
7902	7902				
527		1.050000 x	5.120000 =		5.376000
003		1.000000 x	24.769248 =		24.769248
		-----			
			T.E =		30.145248
7903	7903				
528		1.050000 x	6.910000 =		7.255500
003		.600000 x	24.769248 =		14.861549
		-----			
			T.E =		22.117049

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	18.138624
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.149500 =	1.264450
003		.150000 x	24.769248 =	3.715387
002		.300000 x	18.705943 =	5.611783
		-----		
			T.E =	11.467620
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	24.769248 =	3.715387
002		.350000 x	18.705943 =	6.547080
		-----		
			T.E =	13.206467
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	24.769248 =	3.715387
002		.400000 x	18.705943 =	7.482377
		-----		
			T.E =	13.019764
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	24.769248 =	1.981540
		-----		
			T.E =	2.432540
7915.1	7915.1			
7911		.850000 x	11.467620 =	9.747477
		-----		
			T.E =	9.747477
7915.2	7915.2			
7912		.850000 x	13.206467 =	11.225497
		-----		
			T.E =	11.225497
7915.3	7915.3			
7913		.850000 x	13.019764 =	11.066799
		-----		
			T.E =	11.066799



7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	18.705943 =	.748238
		-----		
			T.E =	2.190238
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	18.705943 =	.935297
		-----		
			T.E =	3.190997
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	18.705943 =	.935297
		-----		
			T.E =	2.150697
7931	7931			
519		1.050000 x	47.670000 =	50.053500
003		1.500000 x	24.769248 =	37.153872
		-----		
			T.E =	87.207372
7932.1	7932.1			
514		.000000 x	41.560000 =	.000000
003		.000000 x	24.769248 =	.000000
		-----		
			T.E =	.000000
7932.2	7932.2			
520		.000000 x	40.000000 =	.000000
003		.000000 x	24.769248 =	.000000
		-----		
			T.E =	.000000
7933.1	7933.1			
514		.000000 x	41.560000 =	.000000
003		.000000 x	24.769248 =	.000000
		-----		
			T.E =	.000000
7933.2	7933.2			
520		.000000 x	40.000000 =	.000000
003		.000000 x	24.769248 =	.000000
		-----		
			T.E =	.000000

7934	7934			
535		1.150000 x	6.000000 =	6.900000
002		.500000 x	18.705943 =	9.352972
003		.500000 x	24.769248 =	12.384624
		-----		
			T.E =	28.637596
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	24.769248 =	6.192312
		-----		
			T.E =	6.567312
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	24.769248 =	2.476925
		-----		
			T.E =	3.226925
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	18.705943 =	5.611783
003		.300000 x	24.769248 =	7.430774
251		.100000 x	.695000 =	.069500
		-----		
			T.E =	
7941	7941			
067		.040000 x	45.000000 =	1.800000
001		.100000 x	16.829739 =	1.682974
		-----		
			T.E =	3.482974
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	16.829739 =	1.682974
		-----		
			T.E =	9.232974