

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

1ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	15.741598
002	17.312112
003	20.419486
004	23.886192
005	21.778427
006	183.150721
007	183.150721
008	16.777917
009	.074800
011	53.630000
012	4.400000
013	26.580000
014	260.720000
015	200.790000
016	31.630000
017	369.270000
018.1	2.900000
018.2	4.400000
019.1	2.900000
019.2	4.400000
021	2.670000
022	.070000
024	50.000000
026	.098900
027	.119300
029	.152800
032	36.000000
035	.105100
036	.107500
040	.203400
051	15.400000
052	15.400000
053	.080000
054	.080000
055	.090000
056	10.580000
057	10.580000
058	9.090000
061	13.560000
062	13.560000
065	13.610000
066	35.000000
067	45.500000
081	11.010000
101	
102	
111	.078400
112	.087900
113	.570000
114	
116	.090300
117	
118	
124	5.900000
127	83.240000
128	90.430000
131	.650000
132	.930000
142	.325000

146	.340000
155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.255300
181	
201	290.000000
203.2	370.000000
203.4	240.000000
205	450.000000
208	1,363.000000
210	
211	750.000000
212	1,400.000000
214	850.000000
219	3.500000
223.1	1,870.000000
223.2	1,595.000000
223.3	1,305.000000
223.4	1,580.000000
225	4.000000
226	12.500000
227	12.500000
228	35.000000
229	
230	
231	22.000000
232	45.000000
233	21.300000
234	2.700000
236	2.600000
237	1.100000
238	2.600000
240	1.400000
241	
242	1.430000
243.1	2.700000
243.2	3.800000
243.3	4.500000
243.5	5.900000
244	
245	18.600000
246	10.500000
249	20.000000
251	.695000
252	1.785000
253	2.244000
254	2.780000
258	7.560000
259	24.497500
260	.559800
261	.591200
262	.559800
264	1.007900
265	.716500
266	.553000

267	.771500
268	.888000
271	.831500
272	.742500
273	.922500
274	1.137800
276	.645000
277	.843000
278	3.600000
279	3.720000
280	1.000000
281	5.780000
282	.813000
283	1.036900
284	
285	.057500
286	1.626900
288	1.765800
289	.659100
290	3.300000
291	5.000000
293	
294	3.407000
295	5.649200
296	11.781900
297.2	
298.1	5.590000
298.2	4.870000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.668400
352	1.030000
354	.895800
356	.601500
357	1.310300
358	3.035000
360	13.580000
361	1.136300
362	1.270000
363	1.617600
364	1.030000
366	4.545900
370	.267400
371	1.617600

372	2.246200
373	2.486800
375	3.155400
376	.200400
377	.842200
378	13.590000
379	26.780000
380	16.150000
381	67.970000
386	28.630000
388	48.870000
390	1.500000
392	24.930000
401	13.560000
403	15.880000
406	19.630000
409	23.370000
410	31.790000
411	29.680000
412	32.030000
414	23.370000
415	23.370000
418	32.720000
419	32.720000
421	108.710000
422	149.410000
428	4.390000
429	5.390000
430	7.480000
441	.075500
442	.118300
443	1.930000
444	2.143200
445	1.553500
446	2.540000
447	4.393700
450	2.760000
451	1.178800
453	.100000
455	3.000000
456	1.610000
457	.803800
458	5.030000
459	5.030000
460	4.250000
462	
463	3.970000
464	3.720000
465	5.870000
467	3.380000
471	4.100000
473	2.750000
474	3.770000
475	6.230000
476	2.366400
477	
478	2.937600
479	1.815600
480	3.366000

481	5.535000
482	.984000
483	.165000
484	3.490000
485	.865500
487	13.480000
488	5.000000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	1.905500
498	1.011600
499	1.386800
500	2.039600
501	2.763000
502	3.807000
503	.905500
504	1.199100
505	19.170000
506	1.149500
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.375000
514	36.950000
515	41.230000
519	47.670000
520	35.560000
521	2.390000
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.000000
536	2.500000
537	1.700000
565.3	3.450000
565.5	5.150000
565.6	7.100000
566.3	4.600000
566.5	7.050000
566.6	9.400000

1101	1101			
001		.500000 x	15.741598 =	7.870799

			B.T =	7.870799
1102	1102			
001		1.000000 x	15.741598 =	15.741598

			B.T =	15.741598
1103	1103			
001		.300000 x	15.741598 =	4.722479

			B.T =	4.722479
1104	1104			
015		1.000000 x	200.790000 =	200.790000
291		2.200000 x	5.000000 =	11.000000
004		7.000000 x	23.886192 =	167.203344
002		7.000000 x	17.312112 =	121.184784
484		5.250000 x	3.490000 =	18.322500
485		83.000000 x	.865500 =	71.836500

			AΘΡΟΙΣΜΑ =	590.337128
	B.T =	.004000 x	590.337128 =	2.361349

1111	1111			
006		.060000 x	183.150721 =	10.989043

			B.T =	10.989043
1112	1112			
006		.090000 x	183.150721 =	16.483565

			B.T =	16.483565
1116	1116			
007		.025000 x	183.150721 =	4.578768

			B.T =	4.578768
1117	1117			
007		.110000 x	183.150721 =	20.146579

			B.T =	20.146579
1121	1121			
009		4.000000 x	.074800 =	.299200

			B.T =	.299200

1122	1122			
009		5.000000 x	.074800 =	.374000

			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600

			B.T =	.149600
1126	1126			
001		.400000 x	15.741598 =	6.296639

			B.T =	6.296639
1127	1127			
001		.130000 x	15.741598 =	2.046408

			B.T =	2.046408
1128	1128			
006		.024000 x	183.150721 =	4.395617

			B.T =	4.395617
1131	1131			
007		.090000 x	183.150721 =	16.483565

			B.T =	16.483565
1136	1136			
009		1.000000 x	.074800 =	.074800

			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200

			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000

			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000

			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000

			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
1407		.320000 x	37.605000 =	12.033600

			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.360000 x	37.605000 =	13.537800

			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100

			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.098900 =	14.835000

			B.T =	39.554250
1417	1417			
021		.200000 x	2.670000 =	.534000
1407		.290000 x	37.605000 =	10.905450
051		.900000 x	15.400000 =	13.860000
026		150.000000 x	.098900 =	14.835000

			B.T =	40.134450

1418	1418				
021		.200000 x	2.670000 =	.534000	
026		150.000000 x	.098900 =	14.835000	
051		.840000 x	15.400000 =	12.936000	
1407		.350000 x	37.605000 =	13.161750	

			B.T =	41.466750	
1421	1421				
021		.200000 x	2.670000 =	.534000	
1407		.540000 x	37.605000 =	20.306700	
051		.540000 x	15.400000 =	8.316000	
039		4.000000 x	.000000 =	.000000	

			B.T =		
1422	1422				
021		.250000 x	2.670000 =	.667500	
1407		.620000 x	37.605000 =	23.315100	
051		.330000 x	15.400000 =	5.082000	
039		5.000000 x	.000000 =	.000000	
035		75.000000 x	.105100 =	7.882500	

			B.T =		
1426	1426				
021		.200000 x	2.670000 =	.534000	
055		1,500.000000 x	.090000 =	135.000000	
1407		.450000 x	37.605000 =	16.922250	

			B.T =	152.456250	
1427	1427				
021		.200000 x	2.670000 =	.534000	
1407		.340000 x	37.605000 =	12.785700	
055		1,500.000000 x	.090000 =	135.000000	
026		150.000000 x	.098900 =	14.835000	

			B.T =	163.154700	
1428	1428				
021		.200000 x	2.670000 =	.534000	
055		1,200.000000 x	.090000 =	108.000000	
051		.200000 x	15.400000 =	3.080000	
1407		.400000 x	37.605000 =	15.042000	

			B.T =	126.656000	

1429	1429				
021		.200000 x	2.670000 =	.534000	
035		200.000000 x	.105100 =	21.020000	
055		1,200.000000 x	.090000 =	108.000000	
1407		.400000 x	37.605000 =	15.042000	

			B.T =	144.596000	
1431	1431				
021		.300000 x	2.670000 =	.801000	
032		.960000 x	36.000000 =	34.560000	
1407		.320000 x	37.605000 =	12.033600	

			B.T =	47.394600	
1432	1432				
021		.300000 x	2.670000 =	.801000	
1407		.320000 x	37.605000 =	12.033600	
051		.640000 x	15.400000 =	9.856000	
032		.320000 x	36.000000 =	11.520000	

			B.T =	34.210600	
1436	1436				
021		.350000 x	2.670000 =	.934500	
035		1,100.000000 x	.105100 =	115.610000	

			B.T =	116.544500	
1437	1437				
021		.200000 x	2.670000 =	.534000	
035		75.000000 x	.105100 =	7.882500	
051		.380000 x	15.400000 =	5.852000	
1407		.620000 x	37.605000 =	23.315100	

			B.T =	37.583600	
1441	1441				
021		.800000 x	2.670000 =	2.136000	
026		250.000000 x	.098900 =	24.725000	

			B.T =	26.861000	
1442	1442				
021		.250000 x	2.670000 =	.667500	
051		.740000 x	15.400000 =	11.396000	
026		900.000000 x	.098900 =	89.010000	

			B.T =	101.073500	

1443	1443				
021		.250000 x	2.670000 =	.667500	
026		700.000000 x	.098900 =	69.230000	
051		.860000 x	15.400000 =	13.244000	

			B.T =	83.141500	
1444	1444				
021		.250000 x	2.670000 =	.667500	
026		600.000000 x	.098900 =	59.340000	
051		1.000000 x	15.400000 =	15.400000	

			B.T =	75.407500	
1445	1445				
021		.250000 x	2.670000 =	.667500	
051		1.060000 x	15.400000 =	16.324000	
026		450.000000 x	.098900 =	44.505000	

			B.T =	61.496500	
1446	1446				
021		.250000 x	2.670000 =	.667500	
051		1.120000 x	15.400000 =	17.248000	
026		350.000000 x	.098900 =	34.615000	

			B.T =	52.530500	
1447	1447				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	15.400000 =	15.400000	
026		400.000000 x	.098900 =	39.560000	

			B.T =	58.635900	
1448	1448				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
039		5.000000 x	.000000 =	.000000	
026		400.000000 x	.098900 =	39.560000	
051		1.000000 x	15.400000 =	15.400000	

			B.T =		
1449	1449				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.098900 =	34.615000	
1407		.040000 x	37.605000 =	1.504200	
051		1.060000 x	15.400000 =	16.324000	

			B.T =	53.110700	

1451	1451			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.080000 =	120.000000
026		600.000000 x	.098900 =	59.340000

			B.T =	181.887750
1452	1452			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.152800 =	91.680000
053		1,500.000000 x	.080000 =	120.000000
1407		.050000 x	37.605000 =	1.880250

			B.T =	214.227750
1453	1453			
021		.250000 x	2.670000 =	.667500
026		450.000000 x	.098900 =	44.505000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.080000 =	132.000000

			B.T =	179.052750
1454	1454			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.152800 =	68.760000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.080000 =	132.000000

			B.T =	203.307750
1455	1455			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.080000 =	132.000000
028		450.000000 x	.000000 =	.000000

			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
026		600.000000 x	.098900 =	59.340000
054		1,500.000000 x	.080000 =	120.000000

			B.T =	181.887750

1457	1457			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.152800 =	91.680000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.080000 =	120.000000

			B.T =	214.227750
1458	1458			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.080000 =	132.000000

			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.080000 =	132.000000
029		450.000000 x	.152800 =	68.760000

			B.T =	203.307750
1461	1461			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
053		1,500.000000 x	.080000 =	120.000000
026		500.000000 x	.098900 =	49.450000

			B.T =	173.125900
1462	1462			
021		.300000 x	2.670000 =	.801000
515		1.000000 x	41.230000 =	41.230000
1407		.050000 x	37.605000 =	1.880250
051		.100000 x	15.400000 =	1.540000
026		400.000000 x	.098900 =	39.560000

			B.T =	85.011250
1463	1463			
021		.300000 x	2.670000 =	.801000
1407		.050000 x	37.605000 =	1.880250
026		250.000000 x	.098900 =	24.725000
515		1.050000 x	41.230000 =	43.291500
051		.100000 x	15.400000 =	1.540000

			B.T =	72.237750

1464	1464			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.098900 =	14.835000
1407		.120000 x	37.605000 =	4.512600
519		.600000 x	47.670000 =	28.602000
051		.420000 x	15.400000 =	6.468000

			B.T =	54.951600
1465	1465			
021		.200000 x	2.670000 =	.534000
051		.150000 x	15.400000 =	2.310000
519		.900000 x	47.670000 =	42.903000
1407		.030000 x	37.605000 =	1.128150
026		450.000000 x	.098900 =	44.505000

			B.T =	91.380150
1466	1466			
021		.200000 x	2.670000 =	.534000
051		.210000 x	15.400000 =	3.234000
1407		.030000 x	37.605000 =	1.128150
519		.840000 x	47.670000 =	40.042800
026		450.000000 x	.098900 =	44.505000

			B.T =	89.443950
1467	1467			
021		.200000 x	2.670000 =	.534000
1407		.030000 x	37.605000 =	1.128150
519		.700000 x	47.670000 =	33.369000
026		450.000000 x	.098900 =	44.505000
051		.350000 x	15.400000 =	5.390000

			B.T =	84.926150
1471	1471			
251		1.000000 x	.695000 =	.695000
351		4.000000 x	.668400 =	2.673600
370		6.000000 x	.267400 =	1.604400
372		.400000 x	2.246200 =	.898480
364		2.000000 x	1.030000 =	2.060000
358		1.000000 x	3.035000 =	3.035000

			ΑΘΡΟΙΣΜΑ =	10.966480
	B.T =	.476190 x	10.966480 =	5.222128

1472	1472			
251		.600000 x	.695000 =	.417000
361		1.000000 x	1.136300 =	1.136300
363		2.000000 x	1.617600 =	3.235200
372		.300000 x	2.246200 =	.673860
351		4.000000 x	.668400 =	2.673600
351		2.000000 x	.668400 =	1.336800

			ΑΘΡΟΙΣΜΑ =	9.472760
	B.T =	.666667 x	9.472760 =	6.315176

1473	1473			
251		.500000 x	.695000 =	.347500
360		1.000000 x	13.580000 =	13.580000
372		.700000 x	2.246200 =	1.572340
370		4.000000 x	.267400 =	1.069600
364		2.000000 x	1.030000 =	2.060000
361		1.000000 x	1.136300 =	1.136300
354		4.000000 x	.895800 =	3.583200
351		4.000000 x	.668400 =	2.673600

			ΑΘΡΟΙΣΜΑ =	26.022540
	B.T =	.416667 x	26.022540 =	10.842734

1474	1474			
251		.500000 x	.695000 =	.347500
372		.500000 x	2.246200 =	1.123100
370		4.000000 x	.267400 =	1.069600
366		2.000000 x	4.545900 =	9.091800
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
357		4.000000 x	1.310300 =	5.241200

			ΑΘΡΟΙΣΜΑ =	31.589500
	B.T =	.416667 x	31.589500 =	13.162302

1475	1475			
251		.300000 x	.695000 =	.208500
379		1.000000 x	26.780000 =	26.780000
371		2.000000 x	1.617600 =	3.235200
376		160.000000 x	.200400 =	32.064000
377		6.000000 x	.842200 =	5.053200
378		1.000000 x	13.590000 =	13.590000
375		2.000000 x	3.155400 =	6.310800
354		3.000000 x	.895800 =	2.687400

			ΑΘΡΟΙΣΜΑ =	89.929100
	B.T =	.416667 x	89.929100 =	37.470488

1476	1476			
251		.500000 x	.695000 =	.347500
373		.200000 x	2.486800 =	.497360
370		6.000000 x	.267400 =	1.604400
352		3.000000 x	1.030000 =	3.090000

			ΑΘΡΟΙΣΜΑ =	5.539260
	B.T =	.500000 x	5.539260 =	2.769630

1478	1478			
251		3.000000 x	.695000 =	2.085000
372		.500000 x	2.246200 =	1.123100
356		2.000000 x	.601500 =	1.203000
370		6.000000 x	.267400 =	1.604400

			ΑΘΡΟΙΣΜΑ =	6.015500
	B.T =	.500000 x	6.015500 =	3.007750

1479	1479			
251		6.000000 x	.695000 =	4.170000
370		12.000000 x	.267400 =	3.208800
381		1.000000 x	67.970000 =	67.970000

			ΑΘΡΟΙΣΜΑ =	75.348800
	B.T =	.454545 x	75.348800 =	34.249420

1480	1480			
251		8.000000 x	.695000 =	5.560000
381		2.000000 x	67.970000 =	135.940000
370		16.000000 x	.267400 =	4.278400

			ΑΘΡΟΙΣΜΑ =	145.778400
	B.T =	.227273 x	145.778400 =	33.131494

1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.100000 =	.023000
487		.040000 x	13.480000 =	.539200
451		.230000 x	1.178800 =	.271124

			B.T =	.834659
1487	1487			
443		.120000 x	1.930000 =	.231600
451		.170000 x	1.178800 =	.200396
453		.640000 x	.100000 =	.064000
446		.010000 x	2.540000 =	.025400
445		.060000 x	1.553500 =	.093210

			B.T =	.614606

1488	1488			
444		.170000 x	2.143200 =	.364344
453		.500000 x	.100000 =	.050000
451		.170000 x	1.178800 =	.200396
446		.030000 x	2.540000 =	.076200
445		.050000 x	1.553500 =	.077675

			B.T =	.768615
1489	1489			
444		.100000 x	2.143200 =	.214320
453		.430000 x	.100000 =	.043000
451		.350000 x	1.178800 =	.412580
446		.020000 x	2.540000 =	.050800
445		.100000 x	1.553500 =	.155350

			B.T =	.876050
1490	1490			
444		.300000 x	2.143200 =	.642960
445		.100000 x	1.553500 =	.155350
446		.030000 x	2.540000 =	.076200
451		.570000 x	1.178800 =	.671916

			B.T =	1.546426
1491	1491			
444		.270000 x	2.143200 =	.578664
445		.060000 x	1.553500 =	.093210
451		.650000 x	1.178800 =	.766220
446		.020000 x	2.540000 =	.050800

			B.T =	1.488894
1492	1492			
444		.200000 x	2.143200 =	.428640
446		.030000 x	2.540000 =	.076200
445		.040000 x	1.553500 =	.062140
455		.730000 x	3.000000 =	2.190000

			B.T =	2.756980
1501	1501			
011		1.000000 x	53.630000 =	53.630000
012		2.000000 x	4.400000 =	8.800000
005		3.500000 x	21.778427 =	76.224495
005		14.000000 x	21.778427 =	304.897978
485		15.000000 x	.865500 =	12.982500
484		1.750000 x	3.490000 =	6.107500

			B.T =	462.642473

1502	1502				
013		1.000000 x	26.580000 =	26.580000	
005		3.500000 x	21.778427 =	76.224495	
484		.900000 x	3.490000 =	3.141000	
001		26.000000 x	15.741598 =	409.281548	
482		15.000000 x	.984000 =	14.760000	

			B.T =	529.987043	
1503	1503				
014		1.000000 x	260.720000 =	260.720000	
485		44.000000 x	.865500 =	38.082000	
484		2.600000 x	3.490000 =	9.074000	
004		7.000000 x	23.886192 =	167.203344	
002		2.600000 x	17.312112 =	45.011491	

			B.T =	520.090835	
1504	1504				
015		1.000000 x	200.790000 =	200.790000	
291		2.200000 x	5.000000 =	11.000000	
484		5.250000 x	3.490000 =	18.322500	
002		7.000000 x	17.312112 =	121.184784	
004		7.000000 x	23.886192 =	167.203344	
485		83.000000 x	.865500 =	71.836500	

			B.T =	590.337128	
1505	1505				
016		1.000000 x	31.630000 =	31.630000	
485		17.500000 x	.865500 =	15.146250	
004		7.000000 x	23.886192 =	167.203344	
002		1.750000 x	17.312112 =	30.296196	
484		1.750000 x	3.490000 =	6.107500	

			B.T =	250.383290	
1506	1506				
017		1.000000 x	369.270000 =	369.270000	
004		7.000000 x	23.886192 =	167.203344	
002		3.500000 x	17.312112 =	60.592392	
485		70.000000 x	.865500 =	60.585000	
484		6.000000 x	3.490000 =	20.940000	

			B.T =	678.590736	
2101	2101				
002		.300000 x	17.312112 =	5.193634	

			T.E =	5.193634	

2102	2102			
002		.400000 x	17.312112 =	6.924845

			T.E =	6.924845
2103	2103			
002		.400000 x	17.312112 =	6.924845

			T.E =	6.924845
2104A	2104A			
002		.900000 x	17.312112 =	15.580901

			T.E =	15.580901
2104B	2104B			
002		1.400000 x	17.312112 =	24.236957

			T.E =	24.236957
2104E	2104E			
002		2.900000 x	17.312112 =	50.205125

			T.E =	50.205125
2104H	2104H			
002		4.400000 x	17.312112 =	76.173293

			T.E =	76.173293
2104Z	2104Z			
002		3.900000 x	17.312112 =	67.517237

			T.E =	67.517237
2104Γ	2104Γ			
002		1.900000 x	17.312112 =	32.893013

			T.E =	32.893013
2104Δ	2104Δ			
002		2.400000 x	17.312112 =	41.549069

			T.E =	41.549069
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.312112 =	58.861181

			T.E =	58.861181

2105A	2105A			
002		.900000 x	17.312112 =	15.580901

			T.E =	15.580901
2105B	2105B			
002		1.400000 x	17.312112 =	24.236957

			T.E =	24.236957
2105E	2105E			
002		2.900000 x	17.312112 =	50.205125

			T.E =	50.205125
2105H	2105H			
002		4.400000 x	17.312112 =	76.173293

			T.E =	76.173293
2105Z	2105Z			
002		3.900000 x	17.312112 =	67.517237

			T.E =	67.517237
2105Γ	2105Γ			
002		1.900000 x	17.312112 =	32.893013

			T.E =	32.893013
2105Δ	2105Δ			
002		2.400000 x	17.312112 =	41.549069

			T.E =	41.549069
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.312112 =	58.861181

			T.E =	58.861181
2106A	2106A			
002		5.900000 x	17.312112 =	102.141461

			T.E =	102.141461
2106B	2106B			
002		7.400000 x	17.312112 =	128.109629

			T.E =	128.109629

2106E	2106E			
002		11.900000 x	17.312112 =	206.014133

			T.E =	206.014133
2106H	2106H			
002		16.400000 x	17.312112 =	283.918637

			T.E =	283.918637
2106I	2106I			
002		19.400000 x	17.312112 =	335.854973

			T.E =	335.854973
2106Z	2106Z			
002		14.900000 x	17.312112 =	257.950469

			T.E =	257.950469
2106Γ	2106Γ			
002		8.900000 x	17.312112 =	154.077797

			T.E =	154.077797
2106Δ	2106Δ			
002		10.400000 x	17.312112 =	180.045965

			T.E =	180.045965
2106Θ	2106Θ			
002		17.900000 x	17.312112 =	309.886805

			T.E =	309.886805
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.312112 =	231.982301

			T.E =	231.982301
2107A	2107A			
002		5.900000 x	17.312112 =	102.141461

			T.E =	102.141461
2107B	2107B			
002		7.400000 x	17.312112 =	128.109629

			T.E =	128.109629

2107E	2107E			
002		11.900000 x	17.312112 =	206.014133

			T.E =	206.014133
2107H	2107H			
002		16.400000 x	17.312112 =	283.918637

			T.E =	283.918637
2107I	2107I			
002		19.400000 x	17.312112 =	335.854973

			T.E =	335.854973
2107Z	2107Z			
002		14.900000 x	17.312112 =	257.950469

			T.E =	257.950469
2107Γ	2107Γ			
002		8.900000 x	17.312112 =	154.077797

			T.E =	154.077797
2107Δ	2107Δ			
002		10.400000 x	17.312112 =	180.045965

			T.E =	180.045965
2107Θ	2107Θ			
002		17.900000 x	17.312112 =	309.886805

			T.E =	309.886805
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.312112 =	231.982301

			T.E =	231.982301
2108A	2108A			
002		.700000 x	17.312112 =	12.118478

			T.E =	12.118478
2108B	2108B			
002		1.600000 x	17.312112 =	27.699379

			T.E =	27.699379

2108E	2108E			
002		4.600000 x	17.312112 =	79.635715

			T.E =	79.635715
2108H	2108H			
002		7.600000 x	17.312112 =	131.572051

			T.E =	131.572051
2108Z	2108Z			
002		6.600000 x	17.312112 =	114.259939

			T.E =	114.259939
2108Γ	2108Γ			
002		2.600000 x	17.312112 =	45.011491

			T.E =	45.011491
2108Δ	2108Δ			
002		3.600000 x	17.312112 =	62.323603

			T.E =	62.323603
2108Θ	2108Θ			
002		8.600000 x	17.312112 =	148.884163

			T.E =	148.884163
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.312112 =	96.947827

			T.E =	96.947827
2109	2109			
002		.030000 x	17.312112 =	.519363
1503		.001000 x	520.090835 =	.520091
1506		.004000 x	678.590736 =	2.714363

			T.E =	3.753817
2110	2110			
002		.040000 x	17.312112 =	.692484
1506		.004000 x	678.590736 =	2.714363
1501		.005000 x	462.642473 =	2.313212
1503		.001000 x	520.090835 =	.520091

			T.E =	6.240151

2111	2111				
002		.100000 x	17.312112 =	1.731211	
1504		.005000 x	590.337128 =	2.951686	

			T.E =	4.682897	
2112	2112				
002		.120000 x	17.312112 =	2.077453	
1501		.004000 x	462.642473 =	1.850570	
1504		.005500 x	590.337128 =	3.246854	

			T.E =	7.174878	
2113	2113				
002		1.400000 x	17.312112 =	24.236957	
002		.300000 x	17.312112 =	5.193634	

			T.E =	29.430590	
2114	2114				
002		1.500000 x	17.312112 =	25.968168	
1501		.005000 x	462.642473 =	2.313212	
002		.400000 x	17.312112 =	6.924845	

			T.E =	35.206225	
2115	2115				
481		.300000 x	5.535000 =	1.660500	
1501		.011000 x	462.642473 =	5.089067	
002		.600000 x	17.312112 =	10.387267	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	41.640218	
2116	2116				
2115		1.300000 x	41.640218 =	54.132283	

			T.E =	54.132283	
2117	2117				
002		.600000 x	17.312112 =	10.387267	
1501		.125000 x	462.642473 =	57.830309	

			T.E =	68.217576	
2118	2118				
2117		1.300000 x	68.217576 =	88.682849	

			T.E =	88.682849	

2121	2121				
001		.400000 x	15.741598 =	6.296639	
002		1.800000 x	17.312112 =	31.161802	

			T.E =	37.458441	
2122	2122				
001		.500000 x	15.741598 =	7.870799	
002		2.000000 x	17.312112 =	34.624224	
1501		.005000 x	462.642473 =	2.313212	

			T.E =	44.808235	
2123	2123				
002		.200000 x	17.312112 =	3.462422	
1504		.008300 x	590.337128 =	4.899798	

			T.E =	8.362221	
2124	2124				
002		.200000 x	17.312112 =	3.462422	
1501		.005000 x	462.642473 =	2.313212	
1504		.010000 x	590.337128 =	5.903371	

			T.E =	11.679006	
2125	2125				
481		.400000 x	5.535000 =	2.214000	
1501		.020000 x	462.642473 =	9.252849	
003		1.500000 x	20.419486 =	30.629229	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	59.408190	
2126	2126				
2125		1.300000 x	59.408190 =	77.230647	

			T.E =	77.230647	
2127	2127				
002		1.000000 x	17.312112 =	17.312112	
1501		.166600 x	462.642473 =	77.076236	

			T.E =	94.388348	
2128	2128				
2127		1.300000 x	94.388348 =	122.704852	

			T.E =	122.704852	

2131	2131			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
2132	2132			
1504		.001600 x	590.337128 =	.944539

			T.E =	.944539
2133	2133			
002		.100000 x	17.312112 =	1.731211
002		.600000 x	17.312112 =	10.387267

			T.E =	12.118478
2134	2134			
1504		.002500 x	590.337128 =	1.475843

			T.E =	1.475843
2135.1	2135.1			
2121		1.300000 x	37.458441 =	48.695973

			T.E =	48.695973
2135.2	2135.2			
2122		1.300000 x	44.808235 =	58.250706

			T.E =	58.250706
2135.3	2135.3			
2127		1.300000 x	94.388348 =	122.704852

			T.E =	122.704852
2135.4	2135.4			
2128		1.300000 x	122.704852 =	159.516308

			T.E =	159.516308
2141	2141			
001		2.000000 x	15.741598 =	31.483196
003		2.500000 x	20.419486 =	51.048715

			T.E =	82.531911

2142	2142				
001		2.000000 x	15.741598 =	31.483196	
003		3.000000 x	20.419486 =	61.258458	
1501		.005000 x	462.642473 =	2.313212	

			T.E =	95.054866	
2143	2143				
481		.500000 x	5.535000 =	2.767500	
001		2.000000 x	15.741598 =	31.483196	
1501		.025000 x	462.642473 =	11.566062	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	107.075216	
2144	2144				
2143		1.300000 x	107.075216 =	139.197781	

			T.E =	139.197781	
2145	2145				
001		2.000000 x	15.741598 =	31.483196	
003		1.000000 x	20.419486 =	20.419486	
1501		.200000 x	462.642473 =	92.528495	

			T.E =	144.431177	
2146	2146				
2145		1.300000 x	144.431177 =	187.760530	

			T.E =	187.760530	
2151	2151				
001		1.200000 x	15.741598 =	18.889918	
003		.800000 x	20.419486 =	16.335589	

			T.E =	35.225506	
2152	2152				
001		1.500000 x	15.741598 =	23.612397	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	44.031883	
2161	2161				
1505		.003300 x	250.383290 =	.826265	

			T.E =	.826265	

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.741598 =	12.593278

			T.E =	12.860278
2163	2163			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	590.337128 =	2.361349

			T.E =	2.510949
2172	2172			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278
2173	2173			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2174	2174			
007		.050000 x	183.150721 =	9.157536

			T.E =	9.157536
2175	2175			
009		5.500000 x	.074800 =	.411400

			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2177	2177			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278

2178	2178			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
2179	2179			
007		.018000 x	183.150721 =	3.296713

			T.E =	3.296713
2180	2180			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2185	2185			
018.1		.142800 x	2.900000 =	.414120
005		.400000 x	21.778427 =	8.711371
484		.100000 x	3.490000 =	.349000
482		.700000 x	.984000 =	.688800
018.1		.042800 x	2.900000 =	.124120

			T.E =	10.287411
2186	2186			
018.2		.142800 x	4.400000 =	.628320
005		.400000 x	21.778427 =	8.711371
018.2		.042800 x	4.400000 =	.188320
482		1.400000 x	.984000 =	1.377600
484		.200000 x	3.490000 =	.698000

			T.E =	11.603611
2187	2187			
019.1		.142800 x	2.900000 =	.414120
485		1.100000 x	.865500 =	.952050
019.1		.428000 x	2.900000 =	1.241200
005		.400000 x	21.778427 =	8.711371
484		.100000 x	3.490000 =	.349000

			T.E =	11.667741
2188	2188			
019.2		.142800 x	4.400000 =	.628320
005		.400000 x	21.778427 =	8.711371
485		1.800000 x	.865500 =	1.557900
484		.200000 x	3.490000 =	.698000
019.2		.042800 x	4.400000 =	.188320

			T.E =	11.783911

ΑΤΟΕ	1ο Τρίμηνο του 2010	Σελ. Ημ/νία	31 15/07/2011
2201	2201		
001	1.000000 x	15.741598 =	15.741598
002	2.000000 x	17.312112 =	34.624224

		T.E =	50.365822
2202	2202		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560

		T.E =	102.302158
2203	2203		
001	1.000000 x	15.741598 =	15.741598
002	2.500000 x	17.312112 =	43.280280

		T.E =	59.021878
2204	2204		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560

		T.E =	102.302158
2206	2206		
001	1.000000 x	15.741598 =	15.741598
003	3.000000 x	20.419486 =	61.258458

		T.E =	77.000056
2207	2207		
001	1.000000 x	15.741598 =	15.741598
003	6.000000 x	20.419486 =	122.516916

		T.E =	138.258514
2211	2211		
001	2.000000 x	15.741598 =	31.483196

		T.E =	31.483196
2212	2212		
001	1.000000 x	15.741598 =	15.741598

		T.E =	15.741598
2213	2213		
001	2.000000 x	15.741598 =	31.483196

		T.E =	31.483196

2214	2214			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2221	2221			
001		1.200000 x	15.741598 =	18.889918
002		1.600000 x	17.312112 =	27.699379

			T.E =	46.589297
2222	2222			
001		1.200000 x	15.741598 =	18.889918
002		2.500000 x	17.312112 =	43.280280

			T.E =	62.170198
2223	2223			
001		3.000000 x	15.741598 =	47.224794

			T.E =	47.224794
2224	2224			
001		5.000000 x	15.741598 =	78.707990

			T.E =	78.707990
2226	2226			
001		1.500000 x	15.741598 =	23.612397
002		5.000000 x	17.312112 =	86.560560

			T.E =	110.172957
2227	2227			
001		1.500000 x	15.741598 =	23.612397
002		12.000000 x	17.312112 =	207.745344

			T.E =	231.357741
2231	2231			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2232	2232			
003		.020000 x	20.419486 =	.408390

			T.E =	.408390

2236	2236				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	

				T.E =	6.767793
2237	2237				
001		.200000 x	15.741598 =	3.148320	
003		.700000 x	20.419486 =	14.293640	

				T.E =	17.441960
2238	2238				
001		.100000 x	15.741598 =	1.574160	
002		.400000 x	17.312112 =	6.924845	

				T.E =	8.499005
2239	2239				
001		.200000 x	15.741598 =	3.148320	
003		.800000 x	20.419486 =	16.335589	

				T.E =	19.483908
2241	2241				
001		.300000 x	15.741598 =	4.722479	
003		.100000 x	20.419486 =	2.041949	

				T.E =	6.764428
2242	2242				
001		.400000 x	15.741598 =	6.296639	
003		.150000 x	20.419486 =	3.062923	

				T.E =	9.359562
2243	2243				
001		.500000 x	15.741598 =	7.870799	
003		.250000 x	20.419486 =	5.104872	

				T.E =	12.975671
2246	2246				
001		.250000 x	15.741598 =	3.935400	
003		.050000 x	20.419486 =	1.020974	

				T.E =	4.956374

2247	2247				
001		.350000 x	15.741598 =	5.509559	
003		.100000 x	20.419486 =	2.041949	

			T.E =	7.551508	
2248	2248				
001		.450000 x	15.741598 =	7.083719	
003		.200000 x	20.419486 =	4.083897	

			T.E =	11.167616	
2251	2251				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	

			T.E =	6.767793	
2252	2252				
001		.100000 x	15.741598 =	1.574160	
002		.600000 x	17.312112 =	10.387267	

			T.E =	11.961427	
2261A	2261A				
003		.400000 x	20.419486 =	8.167794	

			T.E =	8.167794	
2261B	2261B				
003		.700000 x	20.419486 =	14.293640	

			T.E =	14.293640	
2261Γ	2261Γ				
003		.900000 x	20.419486 =	18.377537	

			T.E =	18.377537	
2261Δ	2261Δ				
003		1.200000 x	20.419486 =	24.503383	

			T.E =	24.503383	
2262A	2262A				
003		.550000 x	20.419486 =	11.230717	

			T.E =	11.230717	

2262B	2262B			
003		.900000 x	20.419486 =	18.377537

			T.E =	18.377537
2262Γ	2262Γ			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
2262Δ	2262Δ			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2263A	2263A			
003		.700000 x	20.419486 =	14.293640

			T.E =	14.293640
2263B	2263B			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
2263Γ	2263Γ			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2263Δ	2263Δ			
003		2.100000 x	20.419486 =	42.880921

			T.E =	42.880921
2264.1A	2264.1A			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2264.1B	2264.1B			
003		1.850000 x	20.419486 =	37.776049

			T.E =	37.776049
2264.1Γ	2264.1Γ			
003		2.100000 x	20.419486 =	42.880921

			T.E =	42.880921

2264.1Δ	2264.1Δ			
003		2.300000 x	20.419486 =	46.964818

			T.E =	46.964818
2264.2Α	2264.2Α			
003		2.000000 x	20.419486 =	40.838972

			T.E =	40.838972
2264.2Β	2264.2Β			
003		2.400000 x	20.419486 =	49.006766

			T.E =	49.006766
2264.2Γ	2264.2Γ			
003		2.800000 x	20.419486 =	57.174561

			T.E =	57.174561
2264.2Δ	2264.2Δ			
003		3.200000 x	20.419486 =	65.342355

			T.E =	65.342355
2264.3Α	2264.3Α			
003		2.400000 x	20.419486 =	49.006766

			T.E =	49.006766
2264.3Β	2264.3Β			
003		2.850000 x	20.419486 =	58.195535

			T.E =	58.195535
2264.3Γ	2264.3Γ			
003		3.300000 x	20.419486 =	67.384304

			T.E =	67.384304
2264.3Δ	2264.3Δ			
003		3.750000 x	20.419486 =	76.573073

			T.E =	76.573073
2265Α	2265Α			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743

2265B	2265B			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
2266.1	2266.1			
2261A		1.000000 x	8.167794 =	8.167794
2261A		.350000 x	8.167794 =	2.858728

			T.E =	11.026522
2266.10	2266.10			
2263B		1.000000 x	24.503383 =	24.503383
2263B		.350000 x	24.503383 =	8.576184

			T.E =	33.079567
2266.11	2266.11			
2263Γ		1.000000 x	32.671178 =	32.671178
2263Γ		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.12	2266.12			
2263Δ		1.000000 x	42.880921 =	42.880921
2263Δ		.350000 x	42.880921 =	15.008322

			T.E =	57.889243
2266.13	2266.13			
2264.1A		1.000000 x	32.671178 =	32.671178
2264.1A		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.14	2266.14			
2264.1B		1.000000 x	37.776049 =	37.776049
2264.1B		.350000 x	37.776049 =	13.221617

			T.E =	50.997666
2266.15	2266.15			
2264.1Γ		1.000000 x	42.880921 =	42.880921
2264.1Γ		.350000 x	42.880921 =	15.008322

			T.E =	57.889243

2266.16	2266.16			
2264.1Δ		1.000000 x	46.964818 =	46.964818
2264.1Δ		.350000 x	46.964818 =	16.437686

			T.E =	63.402504
2266.17	2266.17			
2264.2A		1.000000 x	40.838972 =	40.838972
2264.2A		.350000 x	40.838972 =	14.293640

			T.E =	55.132612
2266.18	2266.18			
2264.2B		1.000000 x	49.006766 =	49.006766
2264.2B		.350000 x	49.006766 =	17.152368

			T.E =	66.159134
2266.19	2266.19			
2264.2Γ		1.000000 x	57.174561 =	57.174561
2264.2Γ		.350000 x	57.174561 =	20.011096

			T.E =	77.185657
2266.2	2266.2			
2261B		1.000000 x	14.293640 =	14.293640
2261B		.350000 x	14.293640 =	5.002774

			T.E =	19.296414
2266.20	2266.20			
2264.2Δ		1.000000 x	65.342355 =	65.342355
2264.2Δ		.350000 x	65.342355 =	22.869824

			T.E =	88.212179
2266.21	2266.21			
2264.3A		1.000000 x	49.006766 =	49.006766
2264.3A		.350000 x	49.006766 =	17.152368

			T.E =	66.159134
2266.22	2266.22			
2264.3B		1.000000 x	58.195535 =	58.195535
2264.3B		.350000 x	58.195535 =	20.368437

			T.E =	78.563972

2266.23	2266.23				
2264.3Γ		1.000000 x	67.384304 =		67.384304
2264.3Γ		.350000 x	67.384304 =		23.584506
				T.E =	90.968810
2266.24	2266.24				
2264.3Δ		1.000000 x	76.573073 =		76.573073
2264.3Δ		.350000 x	76.573073 =		26.800576
				T.E =	103.373649
2266.25	2266.25				
2265A		1.000000 x	10.209743 =		10.209743
2265A		.350000 x	10.209743 =		3.573410
				T.E =	13.783153
2266.26	2266.26				
2265B		1.000000 x	16.335589 =		16.335589
2265B		.350000 x	16.335589 =		5.717456
				T.E =	22.053045
2266.3	2266.3				
2261Γ		1.000000 x	18.377537 =		18.377537
2261Γ		.350000 x	18.377537 =		6.432138
				T.E =	24.809675
2266.4	2266.4				
2261Δ		1.000000 x	24.503383 =		24.503383
2261Δ		.350000 x	24.503383 =		8.576184
				T.E =	33.079567
2266.5	2266.5				
2262A		1.000000 x	11.230717 =		11.230717
2262A		.350000 x	11.230717 =		3.930751
				T.E =	15.161468
2266.6	2266.6				
2262B		1.000000 x	18.377537 =		18.377537
2262B		.350000 x	18.377537 =		6.432138
				T.E =	24.809675

2266.7	2266.7			
2262Γ		1.000000 x	24.503383 =	24.503383
2262Γ		.350000 x	24.503383 =	8.576184

			T.E =	33.079567
2266.8	2266.8			
2262Δ		1.000000 x	32.671178 =	32.671178
2262Δ		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.9	2266.9			
2263A		1.000000 x	14.293640 =	14.293640
2263A		.350000 x	14.293640 =	5.002774

			T.E =	19.296414
2267	2267			
003		3.500000 x	20.419486 =	71.468201

			T.E =	71.468201
2268A	2268A			
003		5.000000 x	20.419486 =	102.097430

			T.E =	102.097430
2268B	2268B			
003		5.900000 x	20.419486 =	120.474967

			T.E =	120.474967
2268Γ	2268Γ			
003		6.400000 x	20.419486 =	130.684710

			T.E =	130.684710
2268Δ	2268Δ			
003		6.900000 x	20.419486 =	140.894453

			T.E =	140.894453
2269A	2269A			
003		2.000000 x	20.419486 =	40.838972

			T.E =	40.838972

2269B	2269B			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458
2269Γ	2269Γ			
003		4.000000 x	20.419486 =	81.677944

			T.E =	81.677944
2270.1	2270.1			
2267		1.000000 x	71.468201 =	71.468201
2267		.600000 x	71.468201 =	42.880921

			T.E =	114.349122
2270.2	2270.2			
2268A		1.000000 x	102.097430 =	102.097430
2268A		.600000 x	102.097430 =	61.258458

			T.E =	163.355888
2270.3	2270.3			
2268B		1.000000 x	120.474967 =	120.474967
2268B		.600000 x	120.474967 =	72.284980

			T.E =	192.759947
2270.4	2270.4			
2268Γ		1.000000 x	130.684710 =	130.684710
2268Γ		.600000 x	130.684710 =	78.410826

			T.E =	209.095536
2270.5	2270.5			
2268Δ		1.000000 x	140.894453 =	140.894453
2268Δ		.600000 x	140.894453 =	84.536672

			T.E =	225.431125
2271A	2271A			
003		2.500000 x	20.419486 =	51.048715

			T.E =	51.048715
2271B	2271B			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458

2271E	2271E			
003		4.500000 x	20.419486 =	91.887687

			T.E =	91.887687
2271H	2271H			
003		6.000000 x	20.419486 =	122.516916

			T.E =	122.516916
2271I	2271I			
003		7.000000 x	20.419486 =	142.936402

			T.E =	142.936402
2271Z	2271Z			
003		5.500000 x	20.419486 =	112.307173

			T.E =	112.307173
2271Γ	2271Γ			
003		3.500000 x	20.419486 =	71.468201

			T.E =	71.468201
2271Δ	2271Δ			
003		4.000000 x	20.419486 =	81.677944

			T.E =	81.677944
2271Θ	2271Θ			
003		6.500000 x	20.419486 =	132.726659

			T.E =	132.726659
2271ΣΤ	2271ΣΤ			
003		5.000000 x	20.419486 =	102.097430

			T.E =	102.097430
2272A	2272A			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458
2272B	2272B			
003		3.700000 x	20.419486 =	75.552098

			T.E =	75.552098

2272E	2272E			
003		5.800000 x	20.419486 =	118.433019

			T.E =	118.433019
2272H	2272H			
003		7.900000 x	20.419486 =	161.313939

			T.E =	161.313939
2272I	2272I			
003		9.300000 x	20.419486 =	189.901220

			T.E =	189.901220
2272Z	2272Z			
003		7.200000 x	20.419486 =	147.020299

			T.E =	147.020299
2272Γ	2272Γ			
003		4.400000 x	20.419486 =	89.845738

			T.E =	89.845738
2272Δ	2272Δ			
003		5.100000 x	20.419486 =	104.139379

			T.E =	104.139379
2272Θ	2272Θ			
003		8.600000 x	20.419486 =	175.607580

			T.E =	175.607580
2272ΣΤ	2272ΣΤ			
003		6.500000 x	20.419486 =	132.726659

			T.E =	132.726659
2273A	2273A			
003		8.500000 x	20.419486 =	173.565631

			T.E =	173.565631
2273B	2273B			
003		10.000000 x	20.419486 =	204.194860

			T.E =	204.194860

2273Γ	2273Γ			
003		11.500000 x	20.419486 =	234.824089

			T.E =	234.824089
2273Δ	2273Δ			
003		13.000000 x	20.419486 =	265.453318

			T.E =	265.453318
2274.1	2274.1			
2271A		1.300000 x	51.048715 =	66.363330

			T.E =	66.363330
2274.10	2274.10			
2271I		1.300000 x	142.936402 =	185.817323

			T.E =	185.817323
2274.11	2274.11			
2272A		1.300000 x	61.258458 =	79.635995

			T.E =	79.635995
2274.12	2274.12			
2272B		1.300000 x	75.552098 =	98.217727

			T.E =	98.217727
2274.13	2274.13			
2272Γ		1.300000 x	89.845738 =	116.799459

			T.E =	116.799459
2274.14	2274.14			
2272Δ		1.300000 x	104.139379 =	135.381193

			T.E =	135.381193
2274.15	2274.15			
2272Ε		1.300000 x	118.433019 =	153.962925

			T.E =	153.962925
2274.16	2274.16			
2272ΣΤ		1.300000 x	132.726659 =	172.544657

			T.E =	172.544657

2274.17	2274.17			
2272Z		1.300000 x	147.020299 =	191.126389

			T.E =	191.126389
2274.18	2274.18			
2272H		1.300000 x	161.313939 =	209.708121

			T.E =	209.708121
2274.19	2274.19			
2272Θ		1.300000 x	175.607580 =	228.289854

			T.E =	228.289854
2274.2	2274.2			
2271B		1.300000 x	61.258458 =	79.635995

			T.E =	79.635995
2274.20	2274.20			
2272I		1.300000 x	189.901220 =	246.871586

			T.E =	246.871586
2274.21	2274.21			
2273A		1.300000 x	173.565631 =	225.635320

			T.E =	225.635320
2274.22	2274.22			
2273B		1.300000 x	204.194860 =	265.453318

			T.E =	265.453318
2274.23	2274.23			
2273Γ		1.300000 x	234.824089 =	305.271316

			T.E =	305.271316
2274.24	2274.24			
2273Δ		1.300000 x	265.453318 =	345.089313

			T.E =	345.089313
2274.3	2274.3			
2271Γ		1.300000 x	71.468201 =	92.908661

			T.E =	92.908661

2274.4	2274.4			
2271Δ		1.300000 x	81.677944 =	106.181327

			T.E =	106.181327
2274.5	2274.5			
2271Ε		1.300000 x	91.887687 =	119.453993

			T.E =	119.453993
2274.6	2274.6			
2271ΣΤ		1.300000 x	102.097430 =	132.726659

			T.E =	132.726659
2274.7	2274.7			
2271Ζ		1.300000 x	112.307173 =	145.999325

			T.E =	145.999325
2274.8	2274.8			
2271Η		1.300000 x	122.516916 =	159.271991

			T.E =	159.271991
2274.9	2274.9			
2271Θ		1.300000 x	132.726659 =	172.544657

			T.E =	172.544657
2275	2275			
003		1.000000 x	20.419486 =	20.419486

			T.E =	20.419486
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	240.000000 =	7.920000
251		6.000000 x	.695000 =	4.170000
003		5.000000 x	20.419486 =	102.097430
001		9.000000 x	15.741598 =	141.674382

			T.E =	264.561812
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.312112 =	5.193634

			T.E =	5.483634

2303	2303				
001		.250000 x	15.741598 =	3.935400	
003		.250000 x	20.419486 =	5.104872	

			T.E =	9.040271	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	17.312112 =	1.731211	

			T.E =	1.847211	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	240.000000 =	9.600000	
003		7.000000 x	20.419486 =	142.936402	
001		9.000000 x	15.741598 =	141.674382	
251		6.000000 x	.695000 =	4.170000	

			T.E =	309.980784	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	240.000000 =	.480000	
251		.250000 x	.695000 =	.173750	
001		.250000 x	15.741598 =	3.935400	
003		.150000 x	20.419486 =	3.062923	

			T.E =	8.232072	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.695000 =	.139000	
203.4		.001000 x	240.000000 =	.240000	
003		.100000 x	20.419486 =	2.041949	
001		.200000 x	15.741598 =	3.148320	

			T.E =	6.149268	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	20.419486 =	.612585	

			T.E =	1.102085	
2314.2	2314.2				
512		1.000000 x	.375000 =	.375000	
003		.030000 x	20.419486 =	.612585	

			T.E =	.987585	

3101	3101			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.098900 =	17.307500
052		.430000 x	15.400000 =	6.622000
056		.860000 x	10.580000 =	9.098800

			T.E =	103.085033
3102	3102			
021		.250000 x	2.670000 =	.667500
052		.420000 x	15.400000 =	6.468000
056		.840000 x	10.580000 =	8.887200
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		200.000000 x	.098900 =	19.780000

			T.E =	105.191933
3103	3103			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
056		.820000 x	10.580000 =	8.675600
052		.410000 x	15.400000 =	6.314000
026		250.000000 x	.098900 =	24.725000

			T.E =	109.771333
3104	3104			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.098900 =	29.670000
052		.400000 x	15.400000 =	6.160000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000

			T.E =	114.350733
3111	3111			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
026		200.000000 x	.098900 =	19.780000
057		.840000 x	10.580000 =	8.887200
052		.420000 x	15.400000 =	6.468000

			T.E =	129.398321

3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	529.987043 =	26.499352
026		250.000000 x	.098900 =	24.725000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.410000 x	15.400000 =	6.314000

			T.E =	128.993877
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.098900 =	29.670000

			T.E =	159.524618
3131	3131			
021		.300000 x	2.670000 =	.801000
026		150.000000 x	.098900 =	14.835000
052		.420000 x	15.400000 =	6.468000
001		5.000000 x	15.741598 =	78.707990
1407		.200000 x	37.605000 =	7.521000
056		.840000 x	10.580000 =	8.887200

			T.E =	117.220190
3201	3201			
021		.250000 x	2.670000 =	.667500
026		175.000000 x	.098900 =	17.307500
001		3.500000 x	15.741598 =	55.095593
003		.700000 x	20.419486 =	14.293640
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000

			T.E =	107.668233
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.098900 =	19.780000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000

			T.E =	109.851133

3203	3203			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.820000 x	13.560000 =	11.119200
052		.540000 x	15.400000 =	8.316000
026		250.000000 x	.098900 =	24.725000

T.E = 114.216933

3204	3204			
021		.250000 x	2.670000 =	.667500
061		.800000 x	13.560000 =	10.848000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.098900 =	29.670000

T.E = 118.736733

3205	3205			
021		.250000 x	2.670000 =	.667500
003		5.500000 x	20.419486 =	112.307173
065		.750000 x	13.610000 =	10.207500
001		7.000000 x	15.741598 =	110.191186
052		.430000 x	15.400000 =	6.622000
026		200.000000 x	.098900 =	19.780000

T.E = 259.775359

3206	3206			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.098900 =	24.725000
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
065		.730000 x	13.610000 =	9.935300
052		.410000 x	15.400000 =	6.314000

T.E = 264.140159

3207	3207			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.098900 =	19.780000
065		.750000 x	13.610000 =	10.207500
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
052		.430000 x	15.400000 =	6.622000

T.E = 192.985046

3208	3208			
021		.250000 x	2.670000 =	.667500
052		.430000 x	15.400000 =	6.622000
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
065		.730000 x	13.610000 =	9.935300
026		250.000000 x	.098900 =	24.725000

			T.E =	197.657846
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
062		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		200.000000 x	.098900 =	19.780000

			T.E =	134.057521
3212	3212			
021		.250000 x	2.670000 =	.667500
052		.540000 x	15.400000 =	8.316000
001		2.000000 x	15.741598 =	31.483196
1502		.050000 x	529.987043 =	26.499352
003		1.500000 x	20.419486 =	30.629229
062		.820000 x	13.560000 =	11.119200
026		250.000000 x	.098900 =	24.725000

			T.E =	133.439477
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972
062		.800000 x	13.560000 =	10.848000
001		3.000000 x	15.741598 =	47.224794
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.098900 =	29.670000

			T.E =	163.910618
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.270000 x	13.610000 =	3.674700
062		.600000 x	13.560000 =	8.136000
052		.400000 x	15.400000 =	6.160000
026		350.000000 x	.098900 =	34.615000

			T.E =	175.687117

3215	3215			
021		.250000 x	2.670000 =	.667500
027		350.000000 x	.119300 =	41.755000
062		.560000 x	13.560000 =	7.593600
001		3.500000 x	15.741598 =	55.095593
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972
065		.250000 x	13.610000 =	3.402500
052		.420000 x	15.400000 =	6.468000

			T.E =	182.320517
3216	3216			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972
001		4.000000 x	15.741598 =	62.966392
065		.270000 x	13.610000 =	3.674700
027		425.000000 x	.119300 =	50.702500
062		.550000 x	13.560000 =	7.458000
052		.350000 x	15.400000 =	5.390000

			T.E =	198.197416
3217	3217			
001		2.500000 x	15.741598 =	39.353995

			T.E =	39.353995
3218	3218			
001		5.000000 x	15.741598 =	78.707990

			T.E =	78.707990
3219	3219			
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944

			T.E =	128.902738
3220	3220			
001		5.000000 x	15.741598 =	78.707990
003		4.000000 x	20.419486 =	81.677944

			T.E =	160.385934
3221	3221			
001		3.000000 x	15.741598 =	47.224794
003		6.000000 x	20.419486 =	122.516916

			T.E =	169.741710

3222	3222				
001		5.000000 x	15.741598 =		78.707990
003		6.000000 x	20.419486 =		122.516916

			T.E =		201.224906
3223A.1	3223A.1				
001		2.000000 x	15.741598 =		31.483196
1502		.050000 x	529.987043 =		26.499352
003		1.500000 x	20.419486 =		30.629229

			AΘΡΟΙΣΜΑ =		88.611777
	T.E =	.500000 x	88.611777 =		44.305889

3223A.2	3223A.2				
001		3.000000 x	15.741598 =		47.224794
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	529.987043 =		26.499352

			AΘΡΟΙΣΜΑ =		114.563118
	T.E =	.500000 x	114.563118 =		57.281559

3223A.3	3223A.3				
001		2.000000 x	15.741598 =		31.483196
003		1.500000 x	20.419486 =		30.629229
1502		.050000 x	529.987043 =		26.499352

			AΘΡΟΙΣΜΑ =		88.611777
	T.E =	.500000 x	88.611777 =		44.305889

3223A.4	3223A.4				
001		3.000000 x	15.741598 =		47.224794
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	529.987043 =		26.499352

			AΘΡΟΙΣΜΑ =		114.563118
	T.E =	.500000 x	114.563118 =		57.281559

3223A.5	3223A.5				
001		3.500000 x	15.741598 =		55.095593
1502		.050000 x	529.987043 =		26.499352
003		2.000000 x	20.419486 =		40.838972

			AΘΡΟΙΣΜΑ =		122.433917
	T.E =	.500000 x	122.433917 =		61.216959

3223A.6	3223A.6			
001		3.500000 x	15.741598 =	55.095593
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972

			ΑΘΡΟΙΣΜΑ =	122.433917
	T.E =	.500000 x	122.433917 =	61.216959

3223A.7	3223A.7			
001		4.000000 x	15.741598 =	62.966392
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972

			ΑΘΡΟΙΣΜΑ =	130.304716
	T.E =	.500000 x	130.304716 =	65.152358

3223B.1	3223B.1			
001		2.000000 x	15.741598 =	31.483196
1502		.050000 x	529.987043 =	26.499352
003		1.500000 x	20.419486 =	30.629229

			ΑΘΡΟΙΣΜΑ =	88.611777
	T.E =	.250000 x	88.611777 =	22.152944

3223B.2	3223B.2			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	529.987043 =	26.499352

			ΑΘΡΟΙΣΜΑ =	114.563118
	T.E =	.250000 x	114.563118 =	28.640780

3223B.3	3223B.3			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	529.987043 =	26.499352

			ΑΘΡΟΙΣΜΑ =	88.611777
	T.E =	.250000 x	88.611777 =	22.152944

3223B.4	3223B.4			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	529.987043 =	26.499352

			ΑΘΡΟΙΣΜΑ =	114.563118
	T.E =	.250000 x	114.563118 =	28.640780

3223B.5	3223B.5			
001		3.500000 x	15.741598 =	55.095593
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972

			ΑΘΡΟΙΣΜΑ =	122.433917
	T.E =	.250000 x	122.433917 =	30.608479

3223B.6	3223B.6			
001		3.500000 x	15.741598 =	55.095593
1502		.050000 x	529.987043 =	26.499352
003		2.000000 x	20.419486 =	40.838972

			ΑΘΡΟΙΣΜΑ =	122.433917
	T.E =	.250000 x	122.433917 =	30.608479

3223B.7	3223B.7			
001		4.000000 x	15.741598 =	62.966392
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	529.987043 =	26.499352

			ΑΘΡΟΙΣΜΑ =	130.304716
	T.E =	.250000 x	130.304716 =	32.576179

3231	3231			
021		.300000 x	2.670000 =	.801000
061		.840000 x	13.560000 =	11.390400
001		5.000000 x	15.741598 =	78.707990
1407		.200000 x	37.605000 =	7.521000
026		150.000000 x	.098900 =	14.835000
052		.560000 x	15.400000 =	8.624000

			T.E =	121.879390
3301	3301			
021		.200000 x	2.670000 =	.534000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
051		.300000 x	15.400000 =	4.620000
032		.150000 x	36.000000 =	5.400000

			T.E =	96.089932

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
051		.200000 x	15.400000 =	3.080000
056		.800000 x	10.580000 =	8.464000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593

			T.E =	98.230182
3303	3303			
021		.200000 x	2.670000 =	.534000
056		.800000 x	10.580000 =	8.464000
032		.400000 x	36.000000 =	14.400000
001		3.500000 x	15.741598 =	55.095593
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589

			T.E =	102.350182
3304	3304			
021		.200000 x	2.670000 =	.534000
056		.800000 x	10.580000 =	8.464000
032		.400000 x	36.000000 =	14.400000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
026		100.000000 x	.098900 =	9.890000

			T.E =	117.399576
3311	3311			
021		.200000 x	2.670000 =	.534000
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400
051		.320000 x	15.400000 =	4.928000
032		.160000 x	36.000000 =	5.760000

			T.E =	100.060382
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	36.000000 =	7.560000
051		.210000 x	15.400000 =	3.234000
061		.840000 x	13.560000 =	11.390400
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593

			T.E =	110.214426

3313	3313			
021		.200000 x	2.670000 =	.534000
061		.840000 x	13.560000 =	11.390400
032		.420000 x	36.000000 =	15.120000
001		3.500000 x	15.741598 =	55.095593
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383

			T.E =	114.540426
3314	3314			
021		.200000 x	2.670000 =	.534000
061		.840000 x	13.560000 =	11.390400
032		.420000 x	36.000000 =	15.120000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
026		100.000000 x	.098900 =	9.890000

			T.E =	121.422026
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	9.090000 =	4.545000
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600
026		140.000000 x	.098900 =	13.846000

			T.E =	91.422320
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.098900 =	13.846000
052		.392000 x	15.400000 =	6.036800
058		.500000 x	9.090000 =	4.545000
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.588000 x	13.560000 =	7.973280

			T.E =	94.683760
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.098900 =	17.307500
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
058		.500000 x	9.090000 =	4.545000

			T.E =	94.627900

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.098900 =	17.307500
003		1.100000 x	20.419486 =	22.461435
061		.574000 x	13.560000 =	7.783440
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	9.090000 =	4.545000
052		.378000 x	15.400000 =	5.821200

			T.E =	97.739820
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600
026		140.000000 x	.098900 =	13.846000

			T.E =	92.382320
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.098900 =	13.846000
061		.588000 x	13.560000 =	7.973280
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
052		.392000 x	15.400000 =	6.036800

			T.E =	95.643760
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
026		175.000000 x	.098900 =	17.307500
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800

			T.E =	95.587900

3407.2	3407.2			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.098900 =	17.307500
061		.574000 x	13.560000 =	7.783440
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
052		.378000 x	15.400000 =	5.821200

			T.E =	98.699820
3501	3501			
021		.200000 x	2.670000 =	.534000
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
067		1.050000 x	45.500000 =	47.775000
032		.200000 x	36.000000 =	7.200000

			T.E =	181.824862
3502	3502			
021		.200000 x	2.670000 =	.534000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
067		1.050000 x	45.500000 =	47.775000
032		.200000 x	36.000000 =	7.200000
026		100.000000 x	.098900 =	9.890000

			T.E =	188.706462
3503	3503			
021		.200000 x	2.670000 =	.534000
1407		.080000 x	37.605000 =	3.008400
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
026		150.000000 x	.098900 =	14.835000
067		1.000000 x	45.500000 =	45.500000
032		.200000 x	36.000000 =	7.200000

			T.E =	190.624362
3504	3504			
021		.200000 x	2.670000 =	.534000
517		4.000000 x	.000000 =	.000000
055		180.000000 x	.090000 =	16.200000
003		3.200000 x	20.419486 =	65.342355
001		5.000000 x	15.741598 =	78.707990
026		250.000000 x	.098900 =	24.725000

			T.E =	

3505	3505			
021		.200000 x	2.670000 =	.534000
003		5.000000 x	20.419486 =	102.097430
001		5.500000 x	15.741598 =	86.578789
517		4.000000 x	.000000 =	.000000
055		420.000000 x	.090000 =	37.800000
026		250.000000 x	.098900 =	24.725000

T.E =

3506	3506			
021		.300000 x	2.670000 =	.801000
026		200.000000 x	.098900 =	19.780000
001		5.000000 x	15.741598 =	78.707990
003		2.500000 x	20.419486 =	51.048715
515		1.150000 x	41.230000 =	47.414500

T.E =

197.752205

3511	3511			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
003		2.000000 x	20.419486 =	40.838972
1407		.180000 x	37.605000 =	6.768900
069		1.050000 x	.000000 =	.000000
001		5.000000 x	15.741598 =	78.707990

T.E =

3512	3512			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.098900 =	9.890000
032		.200000 x	36.000000 =	7.200000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
069		1.050000 x	.000000 =	.000000

T.E =

3513	3513			
001		2.500000 x	15.741598 =	39.353995

T.E =

39.353995

3514	3514			
001		5.000000 x	15.741598 =	78.707990

T.E =

78.707990

3801	3801				
201		.001500 x	290.000000 =		.435000
001		.400000 x	15.741598 =		6.296639
251		.300000 x	.695000 =		.208500
203.4		.002500 x	240.000000 =		.600000
003		.500000 x	20.419486 =		10.209743
				T.E =	17.749882
3802	3802				
3801		.050000 x	17.749882 =		.887494
				T.E =	.887494
3811	3811				
203.4		.004000 x	240.000000 =		.960000
003		.800000 x	20.419486 =		16.335589
251		.100000 x	.695000 =		.069500
001		.200000 x	15.741598 =		3.148320
				T.E =	20.513408
3816	3816				
201		.002500 x	290.000000 =		.725000
003		.600000 x	20.419486 =		12.251692
203.4		.003000 x	240.000000 =		.720000
001		.400000 x	15.741598 =		6.296639
251		.200000 x	.695000 =		.139000
				T.E =	20.132331
3817	3817				
3816		.150000 x	20.132331 =		3.019850
				T.E =	3.019850
3821	3821				
201		.014000 x	290.000000 =		4.060000
203.4		.018000 x	240.000000 =		4.320000
003		2.400000 x	20.419486 =		49.006766
001		.600000 x	15.741598 =		9.444959
251		.600000 x	.695000 =		.417000
				T.E =	67.248725
3822	3822				
3821		.150000 x	67.248725 =		10.087309
				T.E =	10.087309

3823	3823			
201		.020000 x	290.000000 =	5.800000
251		.180000 x	.695000 =	.125100
001		.600000 x	15.741598 =	9.444959
003		3.000000 x	20.419486 =	61.258458
203.4		.025000 x	240.000000 =	6.000000

			T.E =	82.628517
3824	3824			
3823		.200000 x	82.628517 =	16.525703

			T.E =	16.525703
3831	3831			
201		.020000 x	290.000000 =	5.800000
203.4		.024000 x	240.000000 =	5.760000
003		4.500000 x	20.419486 =	91.887687
001		1.100000 x	15.741598 =	17.315758
251		.800000 x	.695000 =	.556000

			T.E =	121.319445
3832	3832			
3831		.150000 x	121.319445 =	18.197917

			T.E =	18.197917
3833	3833			
201		.022000 x	290.000000 =	6.380000
003		6.000000 x	20.419486 =	122.516916
001		1.100000 x	15.741598 =	17.315758
251		1.000000 x	.695000 =	.695000
203.4		.025000 x	240.000000 =	6.000000

			T.E =	152.907674
3834	3834			
3833		.200000 x	152.907674 =	30.581535

			T.E =	30.581535
3841	3841			
203.4		.001500 x	240.000000 =	.360000
003		.500000 x	20.419486 =	10.209743

			T.E =	10.569743

3851	3851			
203.4		.052000 x	240.000000 =	12.480000
003		1.300000 x	20.419486 =	26.545332
251		1.100000 x	.695000 =	.764500

			T.E =	39.789832
3852	3852			
001		.300000 x	15.741598 =	4.722479
003		.100000 x	20.419486 =	2.041949

			T.E =	6.764428
3871	3871			
260		1.030000 x	.559800 =	.576594
003		.050000 x	20.419486 =	1.020974

			T.E =	1.597568
3872	3872			
261		1.030000 x	.591200 =	.608936
003		.040000 x	20.419486 =	.816779

			T.E =	1.425715
3873	3873			
262		1.030000 x	.559800 =	.576594
003		.050000 x	20.419486 =	1.020974

			T.E =	1.597568
3874	3874			
258		1.450000 x	7.560000 =	10.962000
003		.150000 x	20.419486 =	3.062923

			T.E =	14.024923
3875	3875			
259		1.000000 x	24.497500 =	24.497500
003		.300000 x	20.419486 =	6.125846

			T.E =	30.623346
3876	3876			
003		.060000 x	20.419486 =	1.225169

			T.E =	1.225169

3881.1	3881.1			
111		1,023.391800 x	.078400 =	80.233917
001		5.000000 x	15.741598 =	78.707990

			T.E =	158.941907
3881.2	3881.2			
112		627.989998 x	.087900 =	55.200321
001		5.000000 x	15.741598 =	78.707990

			T.E =	133.908311
3882	3882			
127		1.050000 x	83.240000 =	87.402000
001		4.000000 x	15.741598 =	62.966392

			T.E =	150.368392
4101	4101			
081		1.150000 x	11.010000 =	12.661500
003		2.000000 x	20.419486 =	40.838972
001		1.300000 x	15.741598 =	20.464077

			T.E =	73.964549
4102	4102			
081		1.200000 x	11.010000 =	13.212000
003		3.500000 x	20.419486 =	71.468201
001		1.700000 x	15.741598 =	26.760717

			T.E =	111.440918
4103	4103			
081		1.150000 x	11.010000 =	12.661500
003		4.000000 x	20.419486 =	81.677944
001		3.000000 x	15.741598 =	47.224794

			T.E =	141.564238
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	15.741598 =	47.224794

			T.E =	58.785294
4105	4105			
081		.350000 x	11.010000 =	3.853500
001		1.000000 x	15.741598 =	15.741598
003		.900000 x	20.419486 =	18.377537

			T.E =	37.972635

4106	4106			
081		.320000 x	11.010000 =	3.523200
003		.900000 x	20.419486 =	18.377537
001		.700000 x	15.741598 =	11.019119

			T.E =	32.919856
4107	4107			
081		1.200000 x	11.010000 =	13.212000
003		3.000000 x	20.419486 =	61.258458
001		2.000000 x	15.741598 =	31.483196

			T.E =	105.953654
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944

			T.E =	149.766208
4205	4205			
081		1.150000 x	11.010000 =	12.661500
003		2.500000 x	20.419486 =	51.048715
1417		.350000 x	40.134450 =	14.047058
001		2.900000 x	15.741598 =	45.650634

			T.E =	123.407907
4206	4206			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.741598 =	45.650634
1417		.350000 x	40.134450 =	14.047058
003		3.100000 x	20.419486 =	63.300407

			T.E =	135.659598
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.741598 =	45.650634
1417		.350000 x	40.134450 =	14.047058
003		4.000000 x	20.419486 =	81.677944

			T.E =	154.037136

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	58.635900 =	20.522565	
003		2.500000 x	20.419486 =	51.048715	
001		2.900000 x	15.741598 =	45.650634	

			T.E =	129.883414	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	15.741598 =	45.650634	
1447		.350000 x	58.635900 =	20.522565	
003		3.100000 x	20.419486 =	63.300407	

			T.E =	142.135106	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	58.635900 =	20.522565	
001		2.900000 x	15.741598 =	45.650634	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	160.512643	
4221	4221				
001		.800000 x	15.741598 =	12.593278	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	33.012764	
4222	4222				
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	

			T.E =	14.464434	
4226	4226				
003		1.300000 x	20.419486 =	26.545332	

			T.E =	26.545332	
4251	4251				
083		32.000000 x	.000000 =	.000000	
1412		.200000 x	27.931800 =	5.586360	
003		4.000000 x	20.419486 =	81.677944	
001		2.900000 x	15.741598 =	45.650634	

			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1417		.200000 x	40.134450 =	8.026890
003		4.000000 x	20.419486 =	81.677944

T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	61.496500 =	12.299300
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
1447		.200000 x	58.635900 =	11.727180
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944

T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

T.E =

4301	4301			16.176598
081		1.020000 x	11.010000 =	11.230200
1412		.350000 x	27.931800 =	9.776130
003		4.200000 x	20.419486 =	85.761841
001		2.900000 x	15.741598 =	45.650634
083		5.000000 x	.000000 =	.000000

T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1417		.350000 x	40.134450 =	14.047058
003		2.700000 x	20.419486 =	55.132612

T.E =

4306	4306			
081		1.050000 x	11.010000 =	11.560500
1417		.350000 x	40.134450 =	14.047058
083		3.000000 x	.000000 =	.000000
003		3.300000 x	20.419486 =	67.384304
001		2.900000 x	15.741598 =	45.650634

T.E =

4307	4307			
081		1.020000 x	11.010000 =	11.230200
083		5.000000 x	.000000 =	.000000
003		4.200000 x	20.419486 =	85.761841
1417		.350000 x	40.134450 =	14.047058
001		2.900000 x	15.741598 =	45.650634

T.E =

4311	4311			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	58.635900 =	20.522565
003		2.700000 x	20.419486 =	55.132612
001		2.900000 x	15.741598 =	45.650634
083		2.000000 x	.000000 =	.000000

T.E =

4312	4312			
081		1.050000 x	11.010000 =	11.560500
083		3.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
003		3.300000 x	20.419486 =	67.384304
1447		.350000 x	58.635900 =	20.522565

T.E =

4313	4313			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
003		2.700000 x	20.419486 =	55.132612
1447		.350000 x	58.635900 =	20.522565
001		2.900000 x	15.741598 =	45.650634

T.E =

4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

T.E = 16.176598

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
251		4.000000 x	.695000 =	2.780000
1446		.100000 x	52.530500 =	5.253050
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980

T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
251		4.000000 x	.695000 =	2.780000
003		25.000000 x	20.419486 =	510.487150
1446		.100000 x	52.530500 =	5.253050
001		10.000000 x	15.741598 =	157.415980

T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
001		10.000000 x	15.741598 =	157.415980
1446		.100000 x	52.530500 =	5.253050
003		25.000000 x	20.419486 =	510.487150
251		4.000000 x	.695000 =	2.780000

T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
1446		.200000 x	52.530500 =	10.506100
003		32.000000 x	20.419486 =	653.423552
251		8.000000 x	.695000 =	5.560000
001		11.000000 x	15.741598 =	173.157578

T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
251		8.000000 x	.695000 =	5.560000
003		32.000000 x	20.419486 =	653.423552
1446		.200000 x	52.530500 =	10.506100
001		11.000000 x	15.741598 =	173.157578

T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.530500 =	10.506100
251		8.000000 x	.695000 =	5.560000
003		32.000000 x	20.419486 =	653.423552
001		11.000000 x	15.741598 =	173.157578

			T.E =	
4401	4401			
001		1.200000 x	15.741598 =	18.889918

			T.E =	18.889918
4402	4402			
001		3.000000 x	15.741598 =	47.224794

			T.E =	47.224794
4501	4501			
081		.050000 x	11.010000 =	.550500
003		1.000000 x	20.419486 =	20.419486
002		.500000 x	17.312112 =	8.656056

			T.E =	29.626042
4502	4502			
081		.050000 x	11.010000 =	.550500
003		1.300000 x	20.419486 =	26.545332
002		.500000 x	17.312112 =	8.656056

			T.E =	35.751888
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.400000 x	20.419486 =	28.587280

			T.E =	37.793836
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.300000 x	20.419486 =	46.964818

			T.E =	52.708951

4505	4505			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.700000 x	20.419486 =	55.132612

			T.E =	60.876746
4506	4506			
081		.050000 x	11.010000 =	.550500
003		3.600000 x	20.419486 =	73.510150
002		.300000 x	17.312112 =	5.193634

			T.E =	79.254283
4507	4507			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.200000 x	20.419486 =	65.342355

			T.E =	71.086489
4508	4508			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.000000 x	20.419486 =	61.258458

			T.E =	67.002592
4511	4511			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.800000 x	20.419486 =	77.594047

			T.E =	83.338180
4512	4512			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	20.419486 =	81.677944
002		.300000 x	17.312112 =	5.193634

			T.E =	87.422078
4515	4515			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.000000 x	20.419486 =	102.097430

			T.E =	107.841564

4516	4516			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687

			T.E =	97.631821
4517	4517			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		6.500000 x	20.419486 =	132.726659

			T.E =	138.470793
4518	4518			
081		.050000 x	11.010000 =	.550500
003		5.700000 x	20.419486 =	116.391070
002		.300000 x	17.312112 =	5.193634

			T.E =	122.135204
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327

			T.E =	111.925461
4521	4521			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.500000 x	20.419486 =	71.468201

			T.E =	77.212335
4522	4522			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.700000 x	20.419486 =	55.132612

			T.E =	60.876746
4525	4525			
081		.050000 x	11.010000 =	.550500
003		4.500000 x	20.419486 =	91.887687
002		.300000 x	17.312112 =	5.193634

			T.E =	97.631821

4526	4526			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	20.419486 =	81.677944
002		.300000 x	17.312112 =	5.193634

			T.E =	87.422078
4527	4527			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		6.000000 x	20.419486 =	122.516916

			T.E =	128.261050
4528	4528			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327

			T.E =	111.925461
4529	4529			
081		.050000 x	11.010000 =	.550500
003		4.700000 x	20.419486 =	95.971584
002		.300000 x	17.312112 =	5.193634

			T.E =	101.715718
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715

			T.E =	51.599215
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972

			T.E =	41.389472
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	20.419486 =	77.594047

			T.E =	78.144547
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	20.419486 =	63.300407

			T.E =	63.850907

4537	4537				
081		.050000 x	11.010000 =	.550500	
003		5.500000 x	20.419486 =	112.307173	

			T.E =	112.857673	
4538	4538				
081		.050000 x	11.010000 =	.550500	
003		4.600000 x	20.419486 =	93.929636	

			T.E =	94.480136	
4539	4539				
081		.050000 x	11.010000 =	.550500	
003		4.200000 x	20.419486 =	85.761841	

			T.E =	86.312341	
4541	4541				
081		.050000 x	11.010000 =	.550500	
003		2.500000 x	20.419486 =	51.048715	

			T.E =	51.599215	
4542	4542				
081		.050000 x	11.010000 =	.550500	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	41.389472	
4543	4543				
081		.050000 x	11.010000 =	.550500	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	82.228444	
4544	4544				
081		.050000 x	11.010000 =	.550500	
003		6.000000 x	20.419486 =	122.516916	

			T.E =	123.067416	
4601.1	4601.1				
101		105.000000 x	.000000 =	.000000	
1417		.023000 x	40.134450 =	.923092	
003		.700000 x	20.419486 =	14.293640	
001		.600000 x	15.741598 =	9.444959	

			T.E =		

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
001		.600000 x	15.741598 =	9.444959
1447		.023000 x	58.635900 =	1.348626
003		.700000 x	20.419486 =	14.293640

T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.741598 =	20.464077
1417		.056000 x	40.134450 =	2.247529
003		1.300000 x	20.419486 =	26.545332

T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.741598 =	20.464077
1447		.056000 x	58.635900 =	3.283610
003		1.300000 x	20.419486 =	26.545332

T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
1417		.089000 x	40.134450 =	3.571966
003		1.800000 x	20.419486 =	36.755075
001		1.900000 x	15.741598 =	29.909036

T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	15.741598 =	29.909036
1447		.089000 x	58.635900 =	5.218595
003		1.800000 x	20.419486 =	36.755075

T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.741598 =	99.172067
1417		.332000 x	40.134450 =	13.324637
003		5.500000 x	20.419486 =	112.307173

T.E =

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.741598 =	99.172067
1447		.332000 x	58.635900 =	19.467119
003		5.500000 x	20.419486 =	112.307173

T.E =

4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	40.134450 =	1.204034
003		.700000 x	20.419486 =	14.293640
001		.700000 x	15.741598 =	11.019119

T.E =

4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
001		.700000 x	15.741598 =	11.019119
1447		.030000 x	58.635900 =	1.759077
003		.700000 x	20.419486 =	14.293640

T.E =

4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	15.741598 =	22.038237
1417		.070000 x	40.134450 =	2.809412
003		1.300000 x	20.419486 =	26.545332

T.E =

4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	15.741598 =	22.038237
1447		.070000 x	58.635900 =	4.104513
003		1.300000 x	20.419486 =	26.545332

T.E =

4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
1417		.110000 x	40.134450 =	4.414790
003		1.800000 x	20.419486 =	36.755075
001		2.100000 x	15.741598 =	33.057356

T.E =

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	15.741598 =	33.057356
1447		.110000 x	58.635900 =	6.449949
003		1.800000 x	20.419486 =	36.755075

T.E =

4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.741598 =	102.320387
1417		.404000 x	40.134450 =	16.214318
003		5.500000 x	20.419486 =	112.307173

T.E =

4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.741598 =	102.320387
1447		.404000 x	58.635900 =	23.688904
003		5.500000 x	20.419486 =	112.307173

T.E =

4621.1	4621.1			
111		53.000000 x	.078400 =	4.155200
1417		.010000 x	40.134450 =	.401345
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639

T.E = 21.062927

4621.2	4621.2			
111		53.000000 x	.078400 =	4.155200
001		.400000 x	15.741598 =	6.296639
1447		.010000 x	58.635900 =	.586359
003		.500000 x	20.419486 =	10.209743

T.E = 21.247941

4622.1	4622.1			
111		75.000000 x	.078400 =	5.880000
1417		.020000 x	40.134450 =	.802689
003		.500000 x	20.419486 =	10.209743
001		.450000 x	15.741598 =	7.083719

T.E = 23.976151

4622.2	4622.2			
111		75.000000 x	.078400 =	5.880000
1447		.020000 x	58.635900 =	1.172718
003		.500000 x	20.419486 =	10.209743
001		.450000 x	15.741598 =	7.083719

			T.E =	24.346180
4623.1	4623.1			
111		150.000000 x	.078400 =	11.760000
1417		.050000 x	40.134450 =	2.006723
003		.950000 x	20.419486 =	19.398512
001		.950000 x	15.741598 =	14.954518

			T.E =	48.119752
4623.2	4623.2			
111		150.000000 x	.078400 =	11.760000
001		.950000 x	15.741598 =	14.954518
1447		.050000 x	58.635900 =	2.931795
003		.950000 x	20.419486 =	19.398512

			T.E =	49.044825
4624.1	4624.1			
111		225.000000 x	.078400 =	17.640000
001		1.500000 x	15.741598 =	23.612397
1417		.085000 x	40.134450 =	3.411428
003		1.300000 x	20.419486 =	26.545332

			T.E =	71.209157
4624.2	4624.2			
111		225.000000 x	.078400 =	17.640000
001		1.500000 x	15.741598 =	23.612397
1447		.085000 x	58.635900 =	4.984052
003		1.300000 x	20.419486 =	26.545332

			T.E =	72.781780
4625.1	4625.1			
111		750.000000 x	.078400 =	58.800000
1417		.320000 x	40.134450 =	12.843024
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310

			T.E =	241.303123

4625.2	4625.2			
111		750.000000 x	.078400 =	58.800000
001		5.200000 x	15.741598 =	81.856310
1447		.320000 x	58.635900 =	18.763488
003		4.300000 x	20.419486 =	87.803790

			T.E =	247.223587
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000

			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000

			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000

			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000

			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000

			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000

			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	23.976151 =	52.747532

			T.E =	52.747532
4633.2	4633.2			
4622.2		2.200000 x	24.346180 =	53.561596

			T.E =	53.561596
4634.1	4634.1			
4622.1		1.200000 x	23.976151 =	28.771381
4623.1		1.000000 x	48.119752 =	48.119752

			T.E =	76.891133
4634.2	4634.2			
4622.2		1.200000 x	24.346180 =	29.215416
4623.2		1.000000 x	49.044825 =	49.044825

			T.E =	78.260241
4661.1	4661.1			
112		43.750000 x	.087900 =	3.845625
1417		.014507 x	40.134450 =	.582230
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639

			T.E =	20.934238
4661.2	4661.2			
112		43.750000 x	.087900 =	3.845625
1447		.014507 x	58.635900 =	.850631
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639

			T.E =	21.202638
4662.1	4662.1			
112		58.333300 x	.087900 =	5.127497
1417		.022840 x	40.134450 =	.916671
003		.500000 x	20.419486 =	10.209743
001		.450000 x	15.741598 =	7.083719

			T.E =	23.337630

4662.2	4662.2			
112		58.333300 x	.087900 =	5.127497
001		.450000 x	15.741598 =	7.083719
1447		.022840 x	58.635900 =	1.339244
003		.500000 x	20.419486 =	10.209743

			T.E =	23.760203
4663.1	4663.1			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	15.741598 =	14.167438
1417		.043218 x	40.134450 =	1.734531
003		.900000 x	20.419486 =	18.377537

			T.E =	43.509006
4663.2	4663.2			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	15.741598 =	14.167438
1447		.043218 x	58.635900 =	2.534126
003		.900000 x	20.419486 =	18.377537

			T.E =	44.308602
4664.1	4664.1			
112		97.222221 x	.087900 =	8.545833
1417		.045077 x	40.134450 =	1.809141
003		.950000 x	20.419486 =	19.398512
001		.950000 x	15.741598 =	14.954518

			T.E =	44.708004
4664.2	4664.2			
112		97.222221 x	.087900 =	8.545833
001		.950000 x	15.741598 =	14.954518
1447		.045077 x	58.635900 =	2.643130
003		.950000 x	20.419486 =	19.398512

			T.E =	45.541993
4665.1	4665.1			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	15.741598 =	23.612397
1417		.047530 x	40.134450 =	1.907590
003		1.300000 x	20.419486 =	26.545332

			T.E =	67.447731

4665.2	4665.2			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	15.741598 =	23.612397
1447		.047530 x	58.635900 =	2.786964
003		1.300000 x	20.419486 =	26.545332

			T.E =	68.327105
4666.1	4666.1			
112		486.111099 x	.087900 =	42.729166
1417		.277862 x	40.134450 =	11.151839
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310

			T.E =	223.541104
4666.2	4666.2			
112		486.111000 x	.087900 =	42.729157
001		5.200000 x	15.741598 =	81.856310
1447		.277862 x	58.635900 =	16.292688
003		4.300000 x	20.419486 =	87.803790

			T.E =	228.681945
4701	4701			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.741598 =	7.870799
1417		.020000 x	40.134450 =	.802689
003		.400000 x	20.419486 =	8.167794

			T.E =	24.251282
4702	4702			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.741598 =	7.870799
1447		.020000 x	58.635900 =	1.172718
003		.400000 x	20.419486 =	8.167794

			T.E =	24.621311
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	40.134450 =	.602017
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639

			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	58.635900 =	.879539
003		.350000 x	20.419486 =	7.146820

T.E =

4711	4711			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1417		.020000 x	40.134450 =	.802689
003		.400000 x	20.419486 =	8.167794

T.E =

4712	4712			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1447		.020000 x	58.635900 =	1.172718
003		.400000 x	20.419486 =	8.167794

T.E =

4713	4713			
118		13.000000 x	.000000 =	.000000
1417		.015000 x	40.134450 =	.602017
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639

T.E =

4714	4714			
118		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	58.635900 =	.879539
003		.350000 x	20.419486 =	7.146820

T.E =

4721.1	4721.1			
128		.080000 x	90.430000 =	7.234400
001		.300000 x	15.741598 =	4.722479
1417		.004000 x	40.134450 =	.160538
003		.350000 x	20.419486 =	7.146820

T.E =

19.264237

4721.2	4721.2				
128		.080000 x	90.430000 =	7.234400	
001		.300000 x	15.741598 =	4.722479	
1447		.004000 x	58.635900 =	.234544	
003		.350000 x	20.419486 =	7.146820	

			T.E =	19.338243	
4722.1	4722.1				
128		.100000 x	90.430000 =	9.043000	
1417		.005000 x	40.134450 =	.200672	
003		.350000 x	20.419486 =	7.146820	
001		.350000 x	15.741598 =	5.509559	

			T.E =	21.900052	
4722.2	4722.2				
128		.100000 x	90.430000 =	9.043000	
001		.350000 x	15.741598 =	5.509559	
1447		.005000 x	58.635900 =	.293180	
003		.350000 x	20.419486 =	7.146820	

			T.E =	21.992559	
4723	4723				
128		.120000 x	90.430000 =	10.851600	
001		.400000 x	15.741598 =	6.296639	
1417		.006000 x	40.134450 =	.240807	
003		.350000 x	20.419486 =	7.146820	

			T.E =	24.535866	
4724.1	4724.1				
128		.150000 x	90.430000 =	13.564500	
1417		.008000 x	40.134450 =	.321076	
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	

			T.E =	28.350009	
4724.2	4724.2				
128		.150000 x	90.430000 =	13.564500	
1447		.008000 x	58.635900 =	.469087	
003		.400000 x	20.419486 =	8.167794	
001		.400000 x	15.741598 =	6.296639	

			T.E =	28.498021	

4725.1	4725.1			
128		.180000 x	90.430000 =	16.277400
1417		.009000 x	40.134450 =	.361210
001		.450000 x	15.741598 =	7.083719
003		.400000 x	20.419486 =	8.167794

			T.E =	31.890124
4725.2	4725.2			
128		.180000 x	90.430000 =	16.277400
001		.450000 x	15.741598 =	7.083719
1447		.009000 x	58.635900 =	.527723
003		.400000 x	20.419486 =	8.167794

			T.E =	32.056637
4801.1	4801.1			
4662.1		1.000000 x	23.337630 =	23.337630
4662.1		.100000 x	23.337630 =	2.333763

			T.E =	25.671393
4801.2	4801.2			
4662.2		1.000000 x	23.760203 =	23.760203
4662.2		.100000 x	23.760203 =	2.376020

			T.E =	26.136223
4802.1	4802.1			
4664.1		1.000000 x	44.708004 =	44.708004
4664.1		.050000 x	44.708004 =	2.235400

			T.E =	46.943404
4802.2	4802.2			
4664.2		1.000000 x	45.541993 =	45.541993
4664.2		.050000 x	45.541993 =	2.277100

			T.E =	47.819093
4803.1	4803.1			
4665.1		1.000000 x	67.447731 =	67.447731
4665.1		.030000 x	67.447731 =	2.023432

			T.E =	69.471163
4803.2	4803.2			
4665.2		1.000000 x	68.327105 =	68.327105
4665.2		.030000 x	68.327105 =	2.049813

			T.E =	70.376918

4811.1	4811.1				
001		.225000 x	15.741598 =	3.541860	
003		.250000 x	20.419486 =	5.104872	
4662.1		1.000000 x	23.337630 =	23.337630	

			T.E =	31.984361	
4811.2	4811.2				
001		.225000 x	15.741598 =	3.541860	
003		.250000 x	20.419486 =	5.104872	
4662.2		1.000000 x	23.760203 =	23.760203	

			T.E =	32.406934	
4812.1	4812.1				
001		.475000 x	15.741598 =	7.477259	
4664.1		1.000000 x	44.708004 =	44.708004	
003		.475000 x	20.419486 =	9.699256	

			T.E =	61.884519	
4812.2	4812.2				
001		.475000 x	15.741598 =	7.477259	
003		.475000 x	20.419486 =	9.699256	
4664.2		1.000000 x	45.541993 =	45.541993	

			T.E =	62.718508	
4813.1	4813.1				
001		.750000 x	15.741598 =	11.806199	
003		.650000 x	20.419486 =	13.272666	
4665.1		1.000000 x	67.447731 =	67.447731	

			T.E =	92.526595	
4813.2	4813.2				
001		.750000 x	15.741598 =	11.806199	
003		.650000 x	20.419486 =	13.272666	
4665.2		1.000000 x	68.327105 =	68.327105	

			T.E =	93.405969	
4814.1	4814.1				
001		2.600000 x	15.741598 =	40.928155	
4666.1		1.000000 x	223.541104 =	223.541104	
003		2.150000 x	20.419486 =	43.901895	

			T.E =	308.371154	

4814.2	4814.2			
001		2.600000 x	15.741598 =	40.928155
4666.2		1.000000 x	228.681945 =	228.681945
003		2.150000 x	20.419486 =	43.901895

			T.E =	313.511995
4821.1	4821.1			
003		.450000 x	20.419486 =	9.188769
4662.1		1.000000 x	23.337630 =	23.337630

			T.E =	32.526399
4821.2	4821.2			
003		.450000 x	20.419486 =	9.188769
4662.2		1.000000 x	23.760203 =	23.760203

			T.E =	32.948972
4822.1	4822.1			
003		.807500 x	20.419486 =	16.488735
4664.1		1.000000 x	44.708004 =	44.708004

			T.E =	61.196739
4822.2	4822.2			
003		.807500 x	20.419486 =	16.488735
4664.2		1.000000 x	45.541993 =	45.541993

			T.E =	62.030728
4823.1	4823.1			
003		1.040000 x	20.419486 =	21.236265
4665.1		1.000000 x	67.447731 =	67.447731

			T.E =	88.683996
4823.2	4823.2			
003		1.040000 x	20.419486 =	21.236265
4665.2		1.000000 x	68.327105 =	68.327105

			T.E =	89.563370
4824.1	4824.1			
003		3.010000 x	20.419486 =	61.462653
4666.1		1.000000 x	223.541104 =	223.541104

			T.E =	285.003757

4824.2	4824.2			
003		3.010000 x	20.419486 =	61.462653
4666.2		1.000000 x	228.681945 =	228.681945

			T.E =	290.144598
4831.1	4831.1			
003		1.200000 x	20.419486 =	24.503383
4661.1		1.000000 x	20.934238 =	20.934238

			T.E =	45.437621
4831.2	4831.2			
003		1.200000 x	20.419486 =	24.503383
4661.2		1.000000 x	21.202638 =	21.202638

			T.E =	45.706021
4832.1	4832.1			
003		1.600000 x	20.419486 =	32.671178
4662.1		1.000000 x	23.337630 =	23.337630

			T.E =	56.008808
4832.2	4832.2			
003		1.600000 x	20.419486 =	32.671178
4662.2		1.000000 x	23.760203 =	23.760203

			T.E =	56.431381
4833.1	4833.1			
002		2.000000 x	17.312112 =	34.624224
4664.1		1.000000 x	44.708004 =	44.708004

			T.E =	79.332228
4833.2	4833.2			
002		2.000000 x	17.312112 =	34.624224
4664.2		1.000000 x	45.541993 =	45.541993

			T.E =	80.166217
4834.1	4834.1			
003		2.300000 x	20.419486 =	46.964818
4665.1		1.000000 x	67.447731 =	67.447731

			T.E =	114.412549

4834.2	4834.2			
003		2.300000 x	20.419486 =	46.964818
4665.2		1.000000 x	68.327105 =	68.327105

T.E = 115.291923

4835	4835			
122		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
1417		.005000 x	40.134450 =	.200672
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.716500 =	1.433000

T.E =

4835.2	4835.2			
122		1.050000 x	.000000 =	.000000
1447		.005000 x	58.635900 =	.293180
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.716500 =	1.433000
201		.010000 x	290.000000 =	2.900000

T.E =

4836.1	4836.1			
123		1.050000 x	.000000 =	.000000
001		1.000000 x	15.741598 =	15.741598
1417		.005000 x	40.134450 =	.200672
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.716500 =	1.433000
201		.010000 x	290.000000 =	2.900000

T.E =

4836.2	4836.2			
123		1.050000 x	.000000 =	.000000
1447		.005000 x	58.635900 =	.293180
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.716500 =	1.433000
201		.010000 x	290.000000 =	2.900000

T.E =

4837.1	4837.1				
124		1.050000 x	5.900000 =	6.195000	
201		.010000 x	290.000000 =	2.900000	
1417		.010000 x	40.134450 =	.401345	
003		1.000000 x	20.419486 =	20.419486	
001		1.000000 x	15.741598 =	15.741598	
265		2.000000 x	.716500 =	1.433000	

			T.E =	47.090429	
4837.2	4837.2				
124		1.050000 x	5.900000 =	6.195000	
265		2.000000 x	.716500 =	1.433000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
201		.010000 x	290.000000 =	2.900000	
1447		.010000 x	58.635900 =	.586359	

			T.E =	48.845957	
4841	4841				
003		.700000 x	20.419486 =	14.293640	

			T.E =	14.293640	
4842	4842				
003		1.000000 x	20.419486 =	20.419486	

			T.E =	20.419486	
4843	4843				
003		.250000 x	20.419486 =	5.104872	

			T.E =	5.104872	
4844	4844				
131		1,200.000000 x	.650000 =	780.000000	
001		10.000000 x	15.741598 =	157.415980	
1401		.250000 x	234.711000 =	58.677750	
003		25.000000 x	20.419486 =	510.487150	

			T.E =	1,506.580880	
4845	4845				
132		620.000000 x	.930000 =	576.600000	
1401		.180000 x	234.711000 =	42.247980	
003		15.000000 x	20.419486 =	306.292290	
001		6.000000 x	15.741598 =	94.449588	

			T.E =	1,019.589858	

4851	4851			
001		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
4852	4852			
001		.150000 x	15.741598 =	2.361240

			T.E =	2.361240
4853	4853			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
4854	4854			
001		.250000 x	15.741598 =	3.935400

			T.E =	3.935400
4855	4855			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
4856	4856			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278
4857	4857			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
4858	4858			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
4859	4859			
001		.400000 x	15.741598 =	6.296639

			T.E =	6.296639
4860	4860			
001		.500000 x	15.741598 =	7.870799

			T.E =	7.870799

4861	4861			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
4862	4862			
001		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
5101	5101			
214		1.100000 x	850.000000 =	935.000000
003		4.000000 x	20.419486 =	81.677944
001		1.000000 x	15.741598 =	15.741598

			T.E =	1,032.419542
5102	5102			
483		1.800000 x	.165000 =	.297000
001		1.000000 x	15.741598 =	15.741598
489		.360000 x	.000000 =	.000000
491		1.260000 x	.540000 =	.680400
488		.540000 x	5.000000 =	2.700000
492		1.440000 x	.540000 =	.777600

			T.E =	
5103	5103			
265		1.050000 x	.716500 =	.752325
003		.200000 x	20.419486 =	4.083897
002		.050000 x	17.312112 =	.865606

			T.E =	5.701828
5104	5104			
001		2.000000 x	15.741598 =	31.483196
003		.150000 x	20.419486 =	3.062923

			T.E =	34.546119
5105	5105			
214		.010000 x	850.000000 =	8.500000
003		.500000 x	20.419486 =	10.209743
001		2.000000 x	15.741598 =	31.483196

			T.E =	50.192939

5106	5106				
214		.050000 x	850.000000 =	42.500000	
003		2.500000 x	20.419486 =	51.048715	
001		2.000000 x	15.741598 =	31.483196	

			T.E =	125.031911	
5201	5201				
201		1.100000 x	290.000000 =	319.000000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	
251		6.000000 x	.695000 =	4.170000	

			T.E =	613.925420	
5202	5202				
203.2		1.080000 x	370.000000 =	399.600000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	
251		6.000000 x	.695000 =	4.170000	

			T.E =	665.449878	
5203	5203				
201		1.120000 x	290.000000 =	324.800000	
251		12.000000 x	.695000 =	8.340000	
002		8.000000 x	17.312112 =	138.496896	
003		16.000000 x	20.419486 =	326.711776	

			T.E =	798.348672	
5204	5204				
203.2		1.100000 x	370.000000 =	407.000000	
003		14.000000 x	20.419486 =	285.872804	
002		7.000000 x	17.312112 =	121.184784	
251		12.000000 x	.695000 =	8.340000	

			T.E =	822.397588	
5211	5211				
201		1.100000 x	290.000000 =	319.000000	
003		12.000000 x	20.419486 =	245.033832	
002		6.000000 x	17.312112 =	103.872672	
251		14.000000 x	.695000 =	9.730000	

			T.E =	677.636504	

5212	5212				
203.2		1.080000 x	370.000000 =	399.600000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	
251		14.000000 x	.695000 =	9.730000	

			T.E =	700.085420	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	
251		8.000000 x	.695000 =	5.560000	

			T.E =	586.239878	
5221	5221				
203.2		.014000 x	370.000000 =	5.180000	
251		.100000 x	.695000 =	.069500	
002		.050000 x	17.312112 =	.865606	
003		.200000 x	20.419486 =	4.083897	

			T.E =	10.199003	
5222	5222				
203.2		.018000 x	370.000000 =	6.660000	
251		.100000 x	.695000 =	.069500	
003		.200000 x	20.419486 =	4.083897	
002		.070000 x	17.312112 =	1.211848	

			T.E =	12.025245	
5223	5223				
203.2		.026000 x	370.000000 =	9.620000	
251		.100000 x	.695000 =	.069500	
003		.200000 x	20.419486 =	4.083897	
002		.100000 x	17.312112 =	1.731211	

			T.E =	15.504608	
5226	5226				
203.2		.016000 x	370.000000 =	5.920000	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	
251		.100000 x	.695000 =	.069500	

			T.E =	10.939003	

5227	5227				
203.2		.022000 x	370.000000 =	8.140000	
251		.100000 x	.695000 =	.069500	
002		.100000 x	17.312112 =	1.731211	
003		.200000 x	20.419486 =	4.083897	

			T.E =	14.024608	
5228	5228				
203.2		.030000 x	370.000000 =	11.100000	
251		.150000 x	.695000 =	.104250	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	

			T.E =	17.884964	
5231	5231				
203.2		.018000 x	370.000000 =	6.660000	
251		.150000 x	.695000 =	.104250	
003		.250000 x	20.419486 =	5.104872	
002		.100000 x	17.312112 =	1.731211	

			T.E =	13.600333	
5232	5232				
203.2		.025000 x	370.000000 =	9.250000	
003		.250000 x	20.419486 =	5.104872	
002		.120000 x	17.312112 =	2.077453	
251		.150000 x	.695000 =	.104250	

			T.E =	16.536575	
5233	5233				
203.2		.034000 x	370.000000 =	12.580000	
002		.150000 x	17.312112 =	2.596817	
003		.250000 x	20.419486 =	5.104872	
251		.200000 x	.695000 =	.139000	

			T.E =	20.420688	
5236	5236				
203.2		.016000 x	370.000000 =	5.920000	
003		.350000 x	20.419486 =	7.146820	
002		.250000 x	17.312112 =	4.328028	
251		.080000 x	.695000 =	.055600	

			T.E =	17.450448	

5237	5237				
203.2		.022000 x	370.000000 =		8.140000
003		.350000 x	20.419486 =		7.146820
002		.300000 x	17.312112 =		5.193634
251		.080000 x	.695000 =		.055600

			T.E =		20.536054
5238	5238				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.695000 =		.069500
002		.350000 x	17.312112 =		6.059239
003		.350000 x	20.419486 =		7.146820

			T.E =		24.375559
5241	5241				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.695000 =		.069500
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056

			T.E =		30.035299
5243	5243				
003		.150000 x	20.419486 =		3.062923

			T.E =		3.062923
5244	5244				
003		.350000 x	20.419486 =		7.146820

			T.E =		7.146820
5246	5246				
220		26.000000 x	.000000 =		.000000
251		.200000 x	.695000 =		.139000
002		.500000 x	17.312112 =		8.656056

			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
002		.600000 x	17.312112 =		10.387267
283		.100000 x	1.036900 =		.103690
251		.100000 x	.695000 =		.069500

			T.E =		

5251	5251				
243.3		1.050000 x	4.500000 =	4.725000	
003		.300000 x	20.419486 =	6.125846	
251		.100000 x	.695000 =	.069500	
002		.300000 x	17.312112 =	5.193634	

			T.E =	16.113979	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
245		.110000 x	18.600000 =	2.046000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	

			T.E =	116.834995	
5252.2	5252.2				
246		1.100000 x	10.500000 =	11.550000	
246		.110000 x	10.500000 =	1.155000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	

			T.E =	107.033995	
5252.3	5252.3				
249		1.100000 x	20.000000 =	22.000000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	
249		.110000 x	20.000000 =	2.200000	

			T.E =	118.528995	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
003		1.500000 x	20.419486 =	30.629229	
002		1.500000 x	17.312112 =	25.968168	
219		.060000 x	3.500000 =	.210000	

			T.E =	61.007397	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
251		.600000 x	.695000 =	.417000	
203.2		.025000 x	370.000000 =	9.250000	

			T.E =	45.652278	

5262	5262			
201		.030000 x	290.000000 =	8.700000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
252		.200000 x	1.785000 =	.357000
265		.300000 x	.716500 =	.214950
203.2		.025000 x	370.000000 =	9.250000
251		.300000 x	.695000 =	.208500

			T.E =	56.462048
5266	5266			
201		.020000 x	290.000000 =	5.800000
251		.600000 x	.695000 =	.417000
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
203.2		.015000 x	370.000000 =	5.550000

			T.E =	34.405959
5267	5267			
201		.030000 x	290.000000 =	8.700000
003		.800000 x	20.419486 =	16.335589
002		.800000 x	17.312112 =	13.849690
265		.300000 x	.716500 =	.214950
252		.300000 x	1.785000 =	.535500
251		.300000 x	.695000 =	.208500
203.2		.015000 x	370.000000 =	5.550000

			T.E =	45.394228
5271	5271			
201		.016000 x	290.000000 =	4.640000
203.2		.025000 x	370.000000 =	9.250000
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
251		.600000 x	.695000 =	.417000

			T.E =	33.172799
5272	5272			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
203.2		.025000 x	370.000000 =	9.250000
252		.100000 x	1.785000 =	.178500
251		.300000 x	.695000 =	.208500
265		.200000 x	.716500 =	.143300

			T.E =	43.152419

5273

5273

201	.016000 x	290.000000 =	4.640000
203.2	.015000 x	370.000000 =	5.550000
003	.500000 x	20.419486 =	10.209743
002	.500000 x	17.312112 =	8.656056
251	.600000 x	.695000 =	.417000

T.E =

29.472799

5274

5274

201	.024000 x	290.000000 =	6.960000
003	.700000 x	20.419486 =	14.293640
002	.700000 x	17.312112 =	12.118478
265	.200000 x	.716500 =	.143300
252	.100000 x	1.785000 =	.178500
251	.300000 x	.695000 =	.208500
203.2	.015000 x	370.000000 =	5.550000

T.E =

39.452419

5276

5276

201	1.080000 x	290.000000 =	313.200000
003	19.000000 x	20.419486 =	387.970234
002	19.000000 x	17.312112 =	328.930128
252	18.000000 x	1.785000 =	32.130000
251	6.000000 x	.695000 =	4.170000

T.E =

1,066.400362

5277

5277

203.2	1.080000 x	370.000000 =	399.600000
003	18.000000 x	20.419486 =	367.550748
002	18.000000 x	17.312112 =	311.618016
252	18.000000 x	1.785000 =	32.130000
251	6.000000 x	.695000 =	4.170000

T.E =

1,115.068764

5279

5279

201	1.080000 x	290.000000 =	313.200000
003	10.000000 x	20.419486 =	204.194860
002	5.000000 x	17.312112 =	86.560560
251	12.000000 x	.695000 =	8.340000

T.E =

612.295420

5280	5280			
203.2		1.080000 x	370.000000 =	399.600000
251		12.000000 x	.695000 =	8.340000
002		5.000000 x	17.312112 =	86.560560
003		10.000000 x	20.419486 =	204.194860

			T.E =	698.695420
5281	5281			
203.2		.014000 x	370.000000 =	5.180000
251		.040000 x	.695000 =	.027800
002		.250000 x	17.312112 =	4.328028

			T.E =	9.535828
5282	5282			
203.2		.020000 x	370.000000 =	7.400000
251		.060000 x	.695000 =	.041700
002		.350000 x	17.312112 =	6.059239

			T.E =	13.500939
5283	5283			
203.2		.026000 x	370.000000 =	9.620000
002		.400000 x	17.312112 =	6.924845
251		.080000 x	.695000 =	.055600

			T.E =	16.600445
5286	5286			
203.2		.008000 x	370.000000 =	2.960000
251		.030000 x	.695000 =	.020850
002		.120000 x	17.312112 =	2.077453
003		.120000 x	20.419486 =	2.450338

			T.E =	7.508642
5288	5288			
003		.300000 x	20.419486 =	6.125846

			T.E =	6.125846
5289	5289			
003		1.000000 x	20.419486 =	20.419486

			T.E =	20.419486

5291	5291			
203.2		.020000 x	370.000000 =	7.400000
220		26.000000 x	.000000 =	.000000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.200000 x	.695000 =	.139000

			T.E =	
5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
220		26.000000 x	.000000 =	.000000
251		.200000 x	.695000 =	.139000
203.2		.010000 x	370.000000 =	3.700000

			T.E =	
5293	5293			
203.2		.020000 x	370.000000 =	7.400000
251		.150000 x	.695000 =	.104250
203.2		.016000 x	370.000000 =	5.920000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845

			T.E =	28.516889
5294	5294			
203.2		.020000 x	370.000000 =	7.400000
203.2		.022000 x	370.000000 =	8.140000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.100000 x	.695000 =	.069500

			T.E =	30.702139
5295	5295			
203.2		.020000 x	370.000000 =	7.400000
002		.250000 x	17.312112 =	4.328028
003		.250000 x	20.419486 =	5.104872
251		.050000 x	.695000 =	.034750

			T.E =	16.867650
5301	5301			
226		1.050000 x	12.500000 =	13.125000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
251		.250000 x	.695000 =	.173750

			T.E =	35.937709

5302	5302			
227		1.050000 x	12.500000 =	13.125000
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
251		.200000 x	.695000 =	.139000

			T.E =	32.129799
5321	5321			
203.2		.012000 x	370.000000 =	4.440000
226		1.050000 x	12.500000 =	13.125000
002		.900000 x	17.312112 =	15.580901
003		.900000 x	20.419486 =	18.377537
251		.500000 x	.695000 =	.347500

			T.E =	51.870938
5322	5322			
203.2		.012000 x	370.000000 =	4.440000
227		1.050000 x	12.500000 =	13.125000
003		.800000 x	20.419486 =	16.335589
002		.800000 x	17.312112 =	13.849690
251		.450000 x	.695000 =	.312750

			T.E =	48.063028
5323	5323			
203.2		.012000 x	370.000000 =	4.440000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
251		.500000 x	.695000 =	.347500
228		1.050000 x	35.000000 =	36.750000

			T.E =	79.269098
5324	5324			
203.2		.012000 x	370.000000 =	4.440000
251		.500000 x	.695000 =	.347500
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
229		1.050000 x	.000000 =	.000000

			T.E =	
5325	5325			
203.2		.012000 x	370.000000 =	4.440000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
251		.500000 x	.695000 =	.347500
230		1.050000 x	.000000 =	.000000

			T.E =	

5326	5326				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.695000 =	.347500	
231		1.050000 x	22.000000 =	23.100000	

			T.E =	65.619098	
5341	5341				
203.2		.037000 x	370.000000 =	13.690000	
232		1.050000 x	45.000000 =	47.250000	
251		.600000 x	.695000 =	.417000	
002		1.100000 x	17.312112 =	19.043323	
003		1.100000 x	20.419486 =	22.461435	

			T.E =	102.861758	
5342	5342				
203.2		.037000 x	370.000000 =	13.690000	
232		1.100000 x	45.000000 =	49.500000	
251		.600000 x	.695000 =	.417000	
003		1.700000 x	20.419486 =	34.713126	
002		1.700000 x	17.312112 =	29.430590	

			T.E =	127.750717	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
233		.084000 x	21.300000 =	1.789200	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	

			T.E =	54.339478	
5351	5351				
035		.200000 x	.105100 =	.021020	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
251		.100000 x	.695000 =	.069500	
236		1.060000 x	2.600000 =	2.756000	

			T.E =	10.392840	
5352	5352				
035		.200000 x	.105100 =	.021020	
251		.100000 x	.695000 =	.069500	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
237		1.060000 x	1.100000 =	1.166000	

			T.E =	8.802840	

5353	5353			
035		.200000 x	.105100 =	.021020
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
251		.100000 x	.695000 =	.069500
238		1.060000 x	2.600000 =	2.756000

			T.E =	10.392840
5354	5354			
035		.200000 x	.105100 =	.021020
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.695000 =	.069500
239		1.060000 x	.000000 =	.000000

			T.E =	
5355	5355			
035		.200000 x	.105100 =	.021020
240		1.060000 x	1.400000 =	1.484000
251		.100000 x	.695000 =	.069500
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422

			T.E =	9.120840
5356	5356			
035		.200000 x	.105100 =	.021020
003		.200000 x	20.419486 =	4.083897
241		1.060000 x	.000000 =	.000000
251		.100000 x	.695000 =	.069500
002		.200000 x	17.312112 =	3.462422

			T.E =	
5421	5421			
205		.055000 x	450.000000 =	24.750000
1471		1.000000 x	5.222128 =	5.222128
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201

			T.E =	162.032721
5422	5422			
205		.035000 x	450.000000 =	15.750000
1472		1.000000 x	6.315176 =	6.315176
003		3.000000 x	20.419486 =	61.258458
002		3.000000 x	17.312112 =	51.936336

			T.E =	135.259970

5426	5426			
205		.095000 x	450.000000 =	42.750000
1473		1.000000 x	10.842734 =	10.842734
1471		1.000000 x	5.222128 =	5.222128
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672

			T.E =	285.204450
5427	5427			
205		.105000 x	450.000000 =	47.250000
002		7.000000 x	17.312112 =	121.184784
003		7.000000 x	20.419486 =	142.936402
1474		1.000000 x	13.162302 =	13.162302
1471		1.000000 x	5.222128 =	5.222128

			T.E =	329.755616
5428	5428			
205		.075000 x	450.000000 =	33.750000
002		5.500000 x	17.312112 =	95.216616
003		5.500000 x	20.419486 =	112.307173
1474		1.000000 x	13.162302 =	13.162302
1472		1.000000 x	6.315176 =	6.315176

			T.E =	260.751267
5431	5431			
205		.070000 x	450.000000 =	31.500000
002		7.000000 x	17.312112 =	121.184784
208		.030000 x	1,363.000000 =	40.890000
1475		1.000000 x	37.470488 =	37.470488
1471		1.000000 x	5.222128 =	5.222128
003		7.000000 x	20.419486 =	142.936402

			T.E =	379.203802
5432	5432			
205		.070000 x	450.000000 =	31.500000
003		5.000000 x	20.419486 =	102.097430
1475		.800000 x	37.470488 =	29.976390
1471		1.000000 x	5.222128 =	5.222128
002		5.000000 x	17.312112 =	86.560560
380		1.000000 x	16.150000 =	16.150000

			T.E =	271.506508

5436	5436			
205		.050000 x	450.000000 =	22.500000
003		4.500000 x	20.419486 =	91.887687
1476		1.000000 x	2.769630 =	2.769630
002		4.500000 x	17.312112 =	77.904504

			T.E =	195.061821
5437	5437			
205		.065000 x	450.000000 =	29.250000
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	20.419486 =	102.097430

			T.E =	220.677620
5438	5438			
205		.050000 x	450.000000 =	22.500000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	20.419486 =	81.677944

			T.E =	176.196022
5441.1	5441.1			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	2.769630 =	2.769630
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
223.3		.004000 x	.000000 =	.000000

			T.E =	
5441.2	5441.2			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	2.769630 =	2.769630
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
223.3		.004000 x	1,305.000000 =	5.220000

			T.E =	207.031821
5441.3	5441.3			
205		.065000 x	450.000000 =	29.250000
243.1		.550000 x	2.700000 =	1.485000
002		4.500000 x	17.312112 =	77.904504
1476		1.000000 x	2.769630 =	2.769630
003		4.500000 x	20.419486 =	91.887687

			T.E =	203.296821

5442.1	5442.1			
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
222.3		.004000 x	.000000 =	.000000

T.E =

5442.2	5442.2			
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,305.000000 =	5.220000

T.E =

232.647620

5442.3	5442.3			
205		.080000 x	450.000000 =	36.000000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	2.769630 =	2.769630
243.1		.055000 x	2.700000 =	.148500

T.E =

227.576120

5443.1	5443.1			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
222.3		.004000 x	.000000 =	.000000

T.E =

5443.2	5443.2			
205		.065000 x	450.000000 =	29.250000
223.3		.004000 x	1,305.000000 =	5.220000
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448

T.E =

188.166022

5443.3	5443.3			
205		.065000 x	450.000000 =	29.250000
003		4.000000 x	20.419486 =	81.677944
1476		1.000000 x	2.769630 =	2.769630
243.1		.550000 x	2.700000 =	1.485000
002		4.000000 x	17.312112 =	69.248448

T.E = 184.431022

5446.1	5446.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	20.419486 =	81.677944
205		.025000 x	450.000000 =	11.250000
002		4.000000 x	17.312112 =	69.248448
222.2		.010000 x	.000000 =	.000000

T.E =

5446.2	5446.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,595.000000 =	15.950000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	2.769630 =	2.769630
003		4.000000 x	20.419486 =	81.677944
205		.025000 x	450.000000 =	11.250000

T.E = 190.146022

5447.1	5447.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.769630 =	2.769630
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
222.2		.010000 x	.000000 =	.000000
205		.040000 x	450.000000 =	18.000000

T.E =

5447.2	5447.2			
203.2		.025000 x	370.000000 =	9.250000
205		.040000 x	450.000000 =	18.000000
223.2		.010000 x	1,595.000000 =	15.950000
1476		1.000000 x	2.769630 =	2.769630
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504

T.E = 215.761821

5448.1	5448.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.769630 =	2.769630
003		3.500000 x	20.419486 =	71.468201
205		.025000 x	450.000000 =	11.250000
002		3.500000 x	17.312112 =	60.592392
222.2		.010000 x	.000000 =	.000000

T.E =

5448.2	5448.2			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	450.000000 =	11.250000
002		3.500000 x	17.312112 =	60.592392
1476		1.000000 x	2.769630 =	2.769630
003		3.500000 x	20.419486 =	71.468201
223.2		.010000 x	1,595.000000 =	15.950000

T.E =

171.280223

5449	5449			
205		.045000 x	450.000000 =	20.250000
1476		1.000000 x	2.769630 =	2.769630
003		3.000000 x	20.419486 =	61.258458
002		3.000000 x	17.312112 =	51.936336
243.5		.850000 x	5.900000 =	5.015000

T.E =

141.229424

5451.1	5451.1			
205		.090000 x	450.000000 =	40.500000
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	2.769630 =	2.769630
002		5.000000 x	17.312112 =	86.560560

T.E =

5451.2	5451.2			
205		.090000 x	450.000000 =	40.500000
223.3		.004000 x	1,305.000000 =	5.220000
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560

T.E =

237.147620

5451.3	5451.3			
205		.090000 x	450.000000 =	40.500000
243.1		.550000 x	2.700000 =	1.485000
1476		1.000000 x	2.769630 =	2.769630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560

			T.E =	233.412620
5456	5456			
205		.055000 x	450.000000 =	24.750000
1478		1.000000 x	3.007750 =	3.007750
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448

			T.E =	178.684142
5457	5457			
205		.085000 x	450.000000 =	38.250000
261		2.200000 x	.591200 =	1.300640
003		7.000000 x	20.419486 =	142.936402
1476		1.500000 x	2.769630 =	4.154445
002		7.000000 x	17.312112 =	121.184784

			T.E =	307.826271
5461.1	5461.1			
205		.065000 x	450.000000 =	29.250000
222.2		.010000 x	.000000 =	.000000
002		5.500000 x	17.312112 =	95.216616
1479		1.000000 x	34.249420 =	34.249420
003		5.500000 x	20.419486 =	112.307173

			T.E =	
5461.2	5461.2			
205		.065000 x	450.000000 =	29.250000
223.2		.010000 x	1,595.000000 =	15.950000
1479		1.000000 x	34.249420 =	34.249420
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616

			T.E =	286.973209
5462.1	5462.1			
205		.065000 x	450.000000 =	29.250000
1480		1.000000 x	33.131494 =	33.131494
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
222.2		.010000 x	.000000 =	.000000

			T.E =	

5462.2	5462.2			
205		.065000 x	450.000000 =	29.250000
1480		1.000000 x	33.131494 =	33.131494
003		5.500000 x	20.419486 =	112.307173
223.2		.010000 x	1,595.000000 =	15.950000
002		5.500000 x	17.312112 =	95.216616

T.E = 285.855283

5463.1	5463.1			
205		.055000 x	450.000000 =	24.750000
002		6.000000 x	17.312112 =	103.872672
1479		.500000 x	34.249420 =	17.124710
003		6.000000 x	20.419486 =	122.516916
222.2		.010000 x	.000000 =	.000000

T.E =

5463.2	5463.2			
205		.055000 x	450.000000 =	24.750000
223.2		.010000 x	1,595.000000 =	15.950000
003		6.000000 x	20.419486 =	122.516916
1479		.500000 x	34.249420 =	17.124710
002		6.000000 x	17.312112 =	103.872672

T.E = 284.214298

5464.1	5464.1			
205		.070000 x	450.000000 =	31.500000
222.2		.010000 x	.000000 =	.000000
1479		.500000 x	34.249420 =	17.124710
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

T.E =

5464.2	5464.2			
205		.070000 x	450.000000 =	31.500000
1479		.500000 x	34.249420 =	17.124710
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
223.2		.010000 x	1,595.000000 =	15.950000

T.E = 328.695896

5465.1	5465.1			
203.2		.045000 x	370.000000 =	16.650000
003		5.500000 x	20.419486 =	112.307173
1476		1.000000 x	2.769630 =	2.769630
002		5.500000 x	17.312112 =	95.216616
222.2		.005000 x	.000000 =	.000000
208		.030000 x	1,363.000000 =	40.890000

T.E =

5465.2	5465.2			
203.2		.045000 x	370.000000 =	16.650000
002		5.500000 x	17.312112 =	95.216616
1476		1.000000 x	2.769630 =	2.769630
003		5.500000 x	20.419486 =	112.307173
223.2		.005000 x	1,595.000000 =	7.975000
208		.030000 x	1,363.000000 =	40.890000

T.E =

275.808419

5466.1	5466.1			
203.2		.025000 x	370.000000 =	9.250000
002		5.000000 x	17.312112 =	86.560560
1479		.900000 x	34.249420 =	30.824478
003		5.000000 x	20.419486 =	102.097430
222.2		.010000 x	.000000 =	.000000

T.E =

5466.2	5466.2			
203.2		.025000 x	370.000000 =	9.250000
003		5.000000 x	20.419486 =	102.097430
1479		.900000 x	34.249420 =	30.824478
002		5.000000 x	17.312112 =	86.560560
223.2		.010000 x	1,595.000000 =	15.950000

T.E =

244.682468

5467.1	5467.1			
203.2		.013000 x	370.000000 =	4.810000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
222.2		.000960 x	.000000 =	.000000
222.2		.012000 x	.000000 =	.000000
203.2		.001040 x	370.000000 =	.384800

T.E =

5467.2	5467.2			
203.2		.013000 x	370.000000 =	4.810000
203.2		.001040 x	370.000000 =	.384800
223.2		.000960 x	1,595.000000 =	1.531200
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.012000 x	1,595.000000 =	19.140000

T.E = 157.926593

5468.1	5468.1			
203.2		.025000 x	370.000000 =	9.250000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
203.2		.002000 x	370.000000 =	.740000
222.2		.010000 x	.000000 =	.000000
222.2		.000800 x	.000000 =	.000000

T.E =

5468.2	5468.2			
203.2		.025000 x	370.000000 =	9.250000
203.2		.002000 x	370.000000 =	.740000
223.2		.000800 x	1,595.000000 =	1.276000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.010000 x	1,595.000000 =	15.950000

T.E = 178.142392

5469.1	5469.1			
203.2		.025000 x	370.000000 =	9.250000
1479		.500000 x	34.249420 =	17.124710
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
222.2		.010000 x	.000000 =	.000000

T.E =

5469.2	5469.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,595.000000 =	15.950000
002		4.500000 x	17.312112 =	77.904504
1479		.500000 x	34.249420 =	17.124710
003		4.500000 x	20.419486 =	91.887687

T.E = 212.116901

5471	5471				
203.2		.035000 x	370.000000 =		12.950000
251		3.000000 x	.695000 =		2.085000
002		3.500000 x	17.312112 =		60.592392
003		3.500000 x	20.419486 =		71.468201

			T.E =		147.095593
5472.1	5472.1				
203.2		.026000 x	370.000000 =		9.620000
251		3.000000 x	.695000 =		2.085000
222.4		.010000 x	.000000 =		.000000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392

			T.E =		
5472.2	5472.2				
203.2		.026000 x	370.000000 =		9.620000
251		3.000000 x	.695000 =		2.085000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
223.4		.010000 x	1,580.000000 =		15.800000

			T.E =		159.565593
5501.1	5501.1				
211		.040000 x	750.000000 =		30.000000
251		.050000 x	.695000 =		.034750
002		2.500000 x	17.312112 =		43.280280
003		5.000000 x	20.419486 =		102.097430
252		.100000 x	1.785000 =		.178500

			T.E =		175.590960
5501.2	5501.2				
212		.040000 x	1,400.000000 =		56.000000
251		.050000 x	.695000 =		.034750
252		.100000 x	1.785000 =		.178500
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280

			T.E =		201.590960
5502	5502				
210		.040000 x	.000000 =		.000000
251		.050000 x	.695000 =		.034750
003		4.000000 x	20.419486 =		81.677944
002		2.000000 x	17.312112 =		34.624224
252		.100000 x	1.785000 =		.178500

			T.E =		

5511.1	5511.1				
211		.020000 x	750.000000 =	15.000000	
003		3.200000 x	20.419486 =	65.342355	
002		1.600000 x	17.312112 =	27.699379	
252		.100000 x	1.785000 =	.178500	

			T.E =	108.220234	
5511.2	5511.2				
212		.020000 x	1,400.000000 =	28.000000	
252		.100000 x	1.785000 =	.178500	
002		1.600000 x	17.312112 =	27.699379	
003		3.200000 x	20.419486 =	65.342355	

			T.E =	121.220234	
5512	5512				
205		.020000 x	450.000000 =	9.000000	
252		.100000 x	1.785000 =	.178500	
003		3.000000 x	20.419486 =	61.258458	
002		1.500000 x	17.312112 =	25.968168	

			T.E =	96.405126	
5513.1	5513.1				
211		.020000 x	750.000000 =	15.000000	
252		.100000 x	1.785000 =	.178500	
003		4.000000 x	20.419486 =	81.677944	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	131.480668	
5513.2	5513.2				
212		.020000 x	1,400.000000 =	28.000000	
003		4.000000 x	20.419486 =	81.677944	
002		2.000000 x	17.312112 =	34.624224	
252		.100000 x	1.785000 =	.178500	

			T.E =	144.480668	
5514	5514				
205		.020000 x	450.000000 =	9.000000	
003		3.800000 x	20.419486 =	77.594047	
252		.100000 x	1.785000 =	.178500	
002		1.800000 x	17.312112 =	31.161802	

			T.E =	117.934348	

5521	5521				
205		.030000 x	450.000000 =		13.500000
002		.800000 x	17.312112 =		13.849690
003		2.000000 x	20.419486 =		40.838972
252		.150000 x	1.785000 =		.267750

			T.E =		68.456412
5531.1	5531.1				
211		.010000 x	750.000000 =		7.500000
252		.020000 x	1.785000 =		.035700
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478

			T.E =		64.577048
5531.2	5531.2				
212		.010000 x	1,400.000000 =		14.000000
252		.020000 x	1.785000 =		.035700
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478

			T.E =		71.077048
5531.3	5531.3				
205		.010000 x	450.000000 =		4.500000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
252		.020000 x	1.785000 =		.035700

			T.E =		61.577048
5532.1	5532.1				
211		.010000 x	750.000000 =		7.500000
252		.020000 x	1.785000 =		.035700
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112

			T.E =		86.106270
5532.2	5532.2				
212		.010000 x	1,400.000000 =		14.000000
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112
252		.020000 x	1.785000 =		.035700

			T.E =		92.606270

5532.3	5532.3			
205		.010000 x	450.000000 =	4.500000
003		3.000000 x	20.419486 =	61.258458
252		.020000 x	1.785000 =	.035700
002		1.000000 x	17.312112 =	17.312112

			T.E =	83.106270
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	20.419486 =	7.146820

			T.E =	8.931820
5601	5601			
203.2		.028000 x	370.000000 =	10.360000
251		4.000000 x	.695000 =	2.780000
003		2.500000 x	20.419486 =	51.048715
002		2.500000 x	17.312112 =	43.280280

			T.E =	107.468995
5602	5602			
203.2		.018000 x	370.000000 =	6.660000
003		2.300000 x	20.419486 =	46.964818
002		2.300000 x	17.312112 =	39.817858
251		3.000000 x	.695000 =	2.085000

			T.E =	95.527675
5603	5603			
203.2		.013000 x	370.000000 =	4.810000
003		2.000000 x	20.419486 =	40.838972
002		2.000000 x	17.312112 =	34.624224
251		2.500000 x	.695000 =	1.737500

			T.E =	82.010696
5604	5604			
243.5		1.100000 x	5.900000 =	6.490000
003		2.200000 x	20.419486 =	44.922869
002		2.200000 x	17.312112 =	38.086646
243.5		.165000 x	5.900000 =	.973500

			T.E =	90.473016

5605	5605				
243.3		1.100000 x	4.500000 =	4.950000	
243.3		.187000 x	4.500000 =	.841500	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	81.254696	
5606	5606				
243.2		1.100000 x	3.800000 =	4.180000	
003		1.800000 x	20.419486 =	36.755075	
002		1.800000 x	17.312112 =	31.161802	
243.2		.220000 x	3.800000 =	.836000	

			T.E =	72.932876	
5607	5607				
205		.012000 x	450.000000 =	5.400000	
002		2.500000 x	17.312112 =	43.280280	
205		.002400 x	450.000000 =	1.080000	
242		2.200000 x	1.430000 =	3.146000	
003		2.500000 x	20.419486 =	51.048715	
242		.440000 x	1.430000 =	.629200	

			T.E =	104.584195	
5608.1	5608.1				
205		.012000 x	450.000000 =	5.400000	
205		.002400 x	450.000000 =	1.080000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
222.1		.001200 x	.000000 =	.000000	
222.1		.006000 x	.000000 =	.000000	

			T.E =		
5608.2	5608.2				
205		.012000 x	450.000000 =	5.400000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
223.1		.006000 x	1,870.000000 =	11.220000	
223.1		.001200 x	1,870.000000 =	2.244000	
205		.002400 x	450.000000 =	1.080000	

			T.E =	152.004593	

5611	5611			
205		.060000 x	450.000000 =	27.000000
251		5.000000 x	.695000 =	3.475000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

			T.E =	294.596186
5612.1	5612.1			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
222.1		.006000 x	.000000 =	.000000
251		5.000000 x	.695000 =	3.475000

			T.E =	
5612.2	5612.2			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.695000 =	3.475000
223.1		.006000 x	1,870.000000 =	11.220000

			T.E =	305.816186
5613.1	5613.1			
205		.015000 x	450.000000 =	6.750000
002		1.500000 x	17.312112 =	25.968168
205		.001500 x	450.000000 =	.675000
003		1.500000 x	20.419486 =	30.629229
222.2		.003000 x	.000000 =	.000000

			T.E =	
5613.2	5613.2			
205		.015000 x	450.000000 =	6.750000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
223.2		.003000 x	1,595.000000 =	4.785000
205		.001500 x	450.000000 =	.675000

			T.E =	68.807397
5614.1	5614.1			
205		.010000 x	450.000000 =	4.500000
222.2		.002000 x	.000000 =	.000000
205		.001500 x	450.000000 =	.675000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534

			T.E =	

5614.2	5614.2			
205		.010000 x	450.000000 =	4.500000
003		1.200000 x	20.419486 =	24.503383
205		.001500 x	450.000000 =	.675000
002		1.200000 x	17.312112 =	20.774534
223.2		.002000 x	1,595.000000 =	3.190000

			T.E =	53.642918
5615.1	5615.1			
205		.008000 x	450.000000 =	3.600000
222.2		.000900 x	.000000 =	.000000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
205		.001440 x	450.000000 =	.648000

			T.E =	
5615.2	5615.2			
205		.008000 x	450.000000 =	3.600000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
223.2		.000900 x	1,595.000000 =	1.435500
205		.001440 x	450.000000 =	.648000

			T.E =	43.415098
5616	5616			
205		.003000 x	450.000000 =	1.350000
205		.007500 x	450.000000 =	3.375000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112

			T.E =	42.456598
5617	5617			
225		1.100000 x	4.000000 =	4.400000
521		.250000 x	2.390000 =	.597500
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486

			T.E =	42.729098
5619	5619			
205		.001400 x	450.000000 =	.630000
003		.200000 x	20.419486 =	4.083897

			T.E =	4.713897

5620	5620			
203.2		.012000 x	370.000000 =	4.440000
220		4.200000 x	.000000 =	.000000
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
251		.020000 x	.695000 =	.013900

T.E =

5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.695000 =	11.120000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360

T.E =

5622	5622			
211		1.100000 x	750.000000 =	825.000000
251		16.000000 x	.695000 =	11.120000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360

T.E =

1,968.067940

5626	5626			
205		.030000 x	450.000000 =	13.500000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
251		1.000000 x	.695000 =	.695000

T.E =

70.792397

6101	6101			
267		1.050000 x	.771500 =	.810075
003		.050000 x	20.419486 =	1.020974

T.E =

1.831049

6102	6102			
252		.050000 x	1.785000 =	.089250
003		.060000 x	20.419486 =	1.225169
267		1.030000 x	.771500 =	.794645

T.E =

2.109064

6103	6103			
268		1.050000 x	.888000 =	.932400
003		.050000 x	20.419486 =	1.020974

T.E =

1.953374

6104	6104				
252		.050000 x	1.785000 =	.089250	
003		.060000 x	20.419486 =	1.225169	
268		1.030000 x	.888000 =	.914640	

			T.E =	2.229059	
6111	6111				
266		1.100000 x	.553000 =	.608300	
003		.150000 x	20.419486 =	3.062923	

			T.E =	3.671223	
6116	6116				
280		1.050000 x	1.000000 =	1.050000	
003		.100000 x	20.419486 =	2.041949	

			T.E =	3.091949	
6117	6117				
281		1.050000 x	5.780000 =	6.069000	
003		.150000 x	20.419486 =	3.062923	

			T.E =	9.131923	
6118	6118				
266		1.150000 x	.553000 =	.635950	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.182270	
6119	6119				
293		1.100000 x	.000000 =	.000000	
003		.150000 x	20.419486 =	3.062923	

			T.E =		
6120	6120				
289		1.050000 x	.659100 =	.692055	
003		.100000 x	20.419486 =	2.041949	

			T.E =	2.734004	
6121	6121				
266		1.100000 x	.553000 =	.608300	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.154620	

6122	6122				
265		1.050000 x	.716500 =	.752325	
003		.200000 x	20.419486 =	4.083897	

				T.E =	4.836222
6123	6123				
265		.900000 x	.716500 =	.644850	
266		.010000 x	.553000 =	.005530	
265		.090000 x	.716500 =	.064485	
003		.150000 x	20.419486 =	3.062923	
002		.150000 x	17.312112 =	2.596817	
266		.100000 x	.553000 =	.055300	

				T.E =	6.429905
6126	6126				
265		1.250000 x	.716500 =	.895625	
003		.200000 x	20.419486 =	4.083897	
003		.200000 x	20.419486 =	4.083897	

				T.E =	9.063419
6127	6127				
290		4.800000 x	3.300000 =	15.840000	
002		.800000 x	17.312112 =	13.849690	
003		.800000 x	20.419486 =	16.335589	

				T.E =	46.025278
6128	6128				
290		1.200000 x	3.300000 =	3.960000	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

				T.E =	11.506320
6201	6201				
264		1.400000 x	1.007900 =	1.411060	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	

				T.E =	10.843960
6202	6202				
264		1.300000 x	1.007900 =	1.310270	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	

				T.E =	8.856590

6203	6203				
282		1.200000 x	.813000 =	.975600	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	14.181659	
6204	6204				
282		1.300000 x	.813000 =	1.056900	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	16.149539	
6205	6205				
277		1.250000 x	.843000 =	1.053750	
002		.500000 x	17.312112 =	8.656056	
003		.500000 x	20.419486 =	10.209743	

			T.E =	19.919549	
6221	6221				
265		1.150000 x	.716500 =	.823975	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	

			T.E =	8.370295	
6222	6222				
265		1.200000 x	.716500 =	.859800	
003		.350000 x	20.419486 =	7.146820	
002		.350000 x	17.312112 =	6.059239	

			T.E =	14.065859	
6223	6223				
265		1.250000 x	.716500 =	.895625	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	

			T.E =	19.761424	
6224	6224				
271		.720000 x	.831500 =	.598680	
003		.200000 x	20.419486 =	4.083897	
282		.480000 x	.813000 =	.390240	
002		.200000 x	17.312112 =	3.462422	

			T.E =	8.535240	

6225	6225			
271		.720000 x	.831500 =	.598680
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028
282		.480000 x	.813000 =	.390240

			T.E =	10.421820
6226	6226			
265		1.200000 x	.716500 =	.859800
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478

			T.E =	27.271919
6227	6227			
265		1.250000 x	.716500 =	.895625
003		.850000 x	20.419486 =	17.356563
002		.850000 x	17.312112 =	14.715295

			T.E =	32.967483
6228	6228			
282		1.250000 x	.813000 =	1.016250
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845

			T.E =	16.108889
6229	6229			
282		1.250000 x	.813000 =	1.016250
002		.450000 x	17.312112 =	7.790450
003		.450000 x	20.419486 =	9.188769

			T.E =	17.995469
6230	6230			
277		1.100000 x	.843000 =	.927300
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743

			T.E =	19.793099
6231	6231			
265		1.150000 x	.716500 =	.823975
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028

			T.E =	10.256875

6232	6232			
265		1.150000 x	.716500 =	.823975
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794

			T.E =	15.916614
6236	6236			
253		.500000 x	2.244000 =	1.122000
392		.350000 x	24.930000 =	8.725500
003		1.800000 x	20.419486 =	36.755075
002		1.800000 x	17.312112 =	31.161802
565.3		.350000 x	3.450000 =	1.207500
390		2.100000 x	1.500000 =	3.150000
276		5.850000 x	.645000 =	3.773250
266		2.000000 x	.553000 =	1.106000
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		1.500000 x	.742500 =	1.113750

			T.E =	115.239876
6237	6237			
253		.850000 x	2.244000 =	1.907400
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
565.5		.350000 x	5.150000 =	1.802500
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	.742500 =	3.712500
266		2.100000 x	.553000 =	1.161300
260		9.500000 x	.559800 =	5.318100

			T.E =	200.678692
6238	6238			
253		.400000 x	2.244000 =	.897600
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
266		13.000000 x	.553000 =	7.189000
265		6.000000 x	.716500 =	4.299000

			T.E =	201.043590
6239	6239			
277		1.100000 x	.843000 =	.927300
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634

			T.E =	12.246779

6301	6301			
266		1.250000 x	.553000 =	.691250
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845

			T.E =	15.783889
6302	6302			
266		9.000000 x	.553000 =	4.977000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201

			T.E =	137.037593
6401	6401			
265		1.150000 x	.716500 =	.823975
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897

			T.E =	8.370295
6402	6402			
265		1.200000 x	.716500 =	.859800
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846

			T.E =	12.179279
6403	6403			
265		1.250000 x	.716500 =	.895625
003		.350000 x	20.419486 =	7.146820
002		.350000 x	17.312112 =	6.059239

			T.E =	14.101684
6406	6406			
265		1.200000 x	.716500 =	.859800
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692

			T.E =	23.498759
6407	6407			
265		1.250000 x	.716500 =	.895625
002		.700000 x	17.312112 =	12.118478
003		.700000 x	20.419486 =	14.293640

			T.E =	27.307744

6411	6411				
565.3		1.650000 x	3.450000 =	5.692500	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	18.898559	
6412	6412				
565.5		1.550000 x	5.150000 =	7.982500	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	

			T.E =	24.961719	
6413	6413				
565.6		1.450000 x	7.100000 =	10.295000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	

			T.E =	31.047379	
6416	6416				
566.3		1.600000 x	4.600000 =	7.360000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	20.566059	
6417	6417				
566.5		1.500000 x	7.050000 =	10.575000	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	

			T.E =	27.554219	
6418	6418				
566.6		1.400000 x	9.400000 =	13.160000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	

			T.E =	33.912379	
6421	6421				
565.3		1.050000 x	3.450000 =	3.622500	
003		.400000 x	20.419486 =	8.167794	

			T.E =	11.790294	

6422	6422				
565.5		1.050000 x	5.150000 =	5.407500	
003		.500000 x	20.419486 =	10.209743	

			T.E =	15.617243	
6423	6423				
565.6		1.050000 x	7.100000 =	7.455000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	19.706692	
6426	6426				
566.3		1.050000 x	4.600000 =	4.830000	
003		.400000 x	20.419486 =	8.167794	

			T.E =	12.997794	
6427	6427				
566.5		1.050000 x	7.050000 =	7.402500	
003		.500000 x	20.419486 =	10.209743	

			T.E =	17.612243	
6428	6428				
566.6		1.050000 x	9.400000 =	9.870000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	22.121692	
6431	6431				
278		1.100000 x	3.600000 =	3.960000	
003		.150000 x	20.419486 =	3.062923	

			T.E =	7.022923	
6432	6432				
251		.100000 x	.695000 =	.069500	
279		1.080000 x	3.720000 =	4.017600	
002		.250000 x	17.312112 =	4.328028	
003		.250000 x	20.419486 =	5.104872	

			T.E =	13.520000	
6441	6441				
266		1.100000 x	.553000 =	.608300	
002		.100000 x	17.312112 =	1.731211	
003		.100000 x	20.419486 =	2.041949	

			T.E =	4.381460	

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	20.419486 =	.816779

			T.E =	
6446.2	6446.2			
285		1.100000 x	.057500 =	.063250
003		.040000 x	20.419486 =	.816779

			T.E =	.880029
6447	6447			
251		.050000 x	.695000 =	.034750
286		1.050000 x	1.626900 =	1.708245
002		.100000 x	17.312112 =	1.731211
003		.100000 x	20.419486 =	2.041949

			T.E =	5.516155
6448	6448			
251		.050000 x	.695000 =	.034750
288		1.050000 x	1.765800 =	1.854090
002		.100000 x	17.312112 =	1.731211
003		.100000 x	20.419486 =	2.041949

			T.E =	5.662000
6501	6501			
282		3.000000 x	.813000 =	2.439000
296		1.000000 x	11.781900 =	11.781900
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
295		11.000000 x	5.649200 =	62.141200

			T.E =	227.288492
6502	6502			
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229
6501		1.000000 x	227.288492 =	227.288492

			T.E =	283.885889
6503	6503			
002		1.300000 x	17.312112 =	22.505746
6501		.950000 x	227.288492 =	215.924067
003		1.300000 x	20.419486 =	26.545332

			T.E =	264.975145

6504	6504				
002		1.200000 x	17.312112 =	20.774534	
6501		.910000 x	227.288492 =	206.832528	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	252.110445	
6505	6505				
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
6501		.870000 x	227.288492 =	197.740988	

			T.E =	235.472586	
6506	6506				
002		1.000000 x	17.312112 =	17.312112	
6501		.810000 x	227.288492 =	184.103679	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	221.835277	
6507	6507				
002		.900000 x	17.312112 =	15.580901	
6501		.920000 x	227.288492 =	209.105413	
003		.900000 x	20.419486 =	18.377537	

			T.E =	243.063851	
6508	6508				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.030000 x	227.288492 =	234.107147	

			T.E =	283.158224	
6509	6509				
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
6501		1.010000 x	227.288492 =	229.561377	

			T.E =	267.292975	
6510	6510				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.080000 x	227.288492 =	245.471571	

			T.E =	290.749489	

6511	6511				
002		1.500000 x	17.312112 =	25.968168	
6501		.920000 x	227.288492 =	209.105413	
003		1.500000 x	20.419486 =	30.629229	

			T.E =	265.702810	
6512	6512				
002		1.400000 x	17.312112 =	24.236957	
003		1.400000 x	20.419486 =	28.587280	
6501		.820000 x	227.288492 =	186.376563	

			T.E =	239.200801	
6513	6513				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		.780000 x	227.288492 =	177.285024	

			T.E =	226.336101	
6514	6514				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		.760000 x	227.288492 =	172.739254	

			T.E =	218.017172	
6515	6515				
002		1.000000 x	17.312112 =	17.312112	
6501		.800000 x	227.288492 =	181.830794	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	219.562392	
6516	6516				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.220000 x	227.288492 =	277.291960	

			T.E =	326.343038	
6517	6517				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.120000 x	227.288492 =	254.563111	

			T.E =	299.841029	

6518	6518				
002		1.100000 x	17.312112 =	19.043323	
003		1.100000 x	20.419486 =	22.461435	
6501		.670000 x	227.288492 =	152.283290	

			T.E =	193.788047	
6519	6519				
002		1.300000 x	17.312112 =	22.505746	
6501		1.280000 x	227.288492 =	290.929270	
003		1.300000 x	20.419486 =	26.545332	

			T.E =	339.980347	
6520	6520				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.120000 x	227.288492 =	254.563111	

			T.E =	299.841029	
6521	6521				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.210000 x	227.288492 =	275.019075	

			T.E =	324.070153	
6522	6522				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.190000 x	227.288492 =	270.473305	

			T.E =	315.751223	
6523	6523				
002		1.200000 x	17.312112 =	20.774534	
6501		1.280000 x	227.288492 =	290.929270	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	336.207187	
6524	6524				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		.800000 x	227.288492 =	181.830794	

			T.E =	227.108711	

6525	6525				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.040000 x	227.288492 =	236.380032	

			T.E =	281.657949	
6526	6526				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		.900000 x	227.288492 =	204.559643	

			T.E =	253.610720	
6527	6527				
002		1.300000 x	17.312112 =	22.505746	
6501		1.120000 x	227.288492 =	254.563111	
003		1.300000 x	20.419486 =	26.545332	

			T.E =	303.614188	
6528	6528				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		.840000 x	227.288492 =	190.922333	

			T.E =	236.200251	
6529	6529				
002		1.200000 x	17.312112 =	20.774534	
6501		1.080000 x	227.288492 =	245.471571	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	290.749489	
6530	6530				
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
6501		.710000 x	227.288492 =	161.374829	

			T.E =	199.106427	
6531	6531				
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	
6501		.480000 x	227.288492 =	109.098476	

			T.E =	131.737435	

6532	6532				
294		6.000000 x	3.407000 =	20.442000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
296		1.000000 x	11.781900 =	11.781900	
294		.300000 x	3.407000 =	1.022100	

			T.E =	127.574995	
6541	6541				
282		.350000 x	.813000 =	.284550	
295		1.050000 x	5.649200 =	5.931660	
296		.120000 x	11.781900 =	1.413828	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	

			T.E =	26.495837	
6542	6542				
295		1.050000 x	5.649200 =	5.931660	
003		.800000 x	20.419486 =	16.335589	
296		.100000 x	11.781900 =	1.178190	
002		.800000 x	17.312112 =	13.849690	

			T.E =	37.295128	
6543	6543				
295		.400000 x	5.649200 =	2.259680	
296		.130000 x	11.781900 =	1.531647	
003		.200000 x	20.419486 =	4.083897	

			T.E =	7.875224	
7101	7101				
201		.000500 x	290.000000 =	.145000	
002		.500000 x	17.312112 =	8.656056	
1445		.010000 x	61.496500 =	.614965	
003		.850000 x	20.419486 =	17.356563	

			T.E =	26.772584	
7102	7102				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.496500 =	.614965	
002		.400000 x	17.312112 =	6.924845	
003		.700000 x	20.419486 =	14.293640	

			T.E =	21.978450	

7103	7103				
201		.000500 x	290.000000 =	.145000	
1445		.004000 x	61.496500 =	.245986	
003		.600000 x	20.419486 =	12.251692	
002		.300000 x	17.312112 =	5.193634	

			T.E =	17.836311	
7104	7104				
201		.000500 x	290.000000 =	.145000	
002		.600000 x	17.312112 =	10.387267	
1445		.008000 x	61.496500 =	.491972	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	31.443725	
7111	7111				
201		.000500 x	290.000000 =	.145000	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	15.741598 =	4.722479	
003		.600000 x	20.419486 =	12.251692	

			T.E =	17.909302	
7116	7116				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	41.466750 =	1.119602	
001		.350000 x	15.741598 =	5.509559	
003		.650000 x	20.419486 =	13.272666	

			T.E =	20.046827	
7121	7121				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	61.496500 =	1.660406	
003		.800000 x	20.419486 =	16.335589	
001		.300000 x	15.741598 =	4.722479	

			T.E =	22.863474	
7122	7122				
201		.000500 x	290.000000 =	.145000	
1444		.027000 x	75.407500 =	2.036003	
001		.300000 x	15.741598 =	4.722479	
003		.800000 x	20.419486 =	16.335589	

			T.E =	23.239071	

7123	7123				
201		.000500 x	290.000000 =		.145000
1462		.015000 x	85.011250 =		1.275169
1446		.006000 x	52.530500 =		.315183
001		.300000 x	15.741598 =		4.722479
1445		.006000 x	61.496500 =		.368979
003		.900000 x	20.419486 =		18.377537
				T.E =	25.204348
7124.1	7124.1				
201		.000500 x	290.000000 =		.145000
001		.300000 x	15.741598 =		4.722479
1445		.012000 x	61.496500 =		.737958
1465		.015000 x	91.380150 =		1.370702
003		.900000 x	20.419486 =		18.377537
				T.E =	25.353677
7124.2	7124.2				
201		.000500 x	290.000000 =		.145000
1466		.015000 x	89.443950 =		1.341659
1445		.012000 x	61.496500 =		.737958
003		.900000 x	20.419486 =		18.377537
001		.300000 x	15.741598 =		4.722479
				T.E =	25.324634
7124.3	7124.3				
201		.000500 x	290.000000 =		.145000
1467		.015000 x	84.926150 =		1.273892
1445		.012000 x	61.496500 =		.737958
001		.300000 x	15.741598 =		4.722479
003		.900000 x	20.419486 =		18.377537
				T.E =	25.256867
7131	7131				
201		.000500 x	290.000000 =		.145000
1413		.021000 x	29.264100 =		.614546
1426		.006000 x	152.456250 =		.914738
001		.300000 x	15.741598 =		4.722479
003		.600000 x	20.419486 =		12.251692
				T.E =	18.648455

7132	7132				
201		.000500 x	290.000000 =	.145000	
1427		.006000 x	163.154700 =	.978928	
1418		.021000 x	41.466750 =	.870802	
001		.350000 x	15.741598 =	5.509559	
003		.650000 x	20.419486 =	13.272666	

			T.E =	20.776955	
7133	7133				
201		.000500 x	290.000000 =	.145000	
1463		.015000 x	72.237750 =	1.083566	
1427		.006000 x	163.154700 =	.978928	
1418		.006000 x	41.466750 =	.248801	
003		.600000 x	20.419486 =	12.251692	
001		.350000 x	15.741598 =	5.509559	

			T.E =	20.217546	
7134	7134				
201		.000500 x	290.000000 =	.145000	
001		.350000 x	15.741598 =	5.509559	
003		.600000 x	20.419486 =	12.251692	
1464		.015000 x	54.951600 =	.824274	
1427		.006000 x	163.154700 =	.978928	
1418		.006000 x	41.466750 =	.248801	

			T.E =	19.958254	
7136	7136				
201		.000500 x	290.000000 =	.145000	
001		.250000 x	15.741598 =	3.935400	
1418		.017000 x	41.466750 =	.704935	
003		.400000 x	20.419486 =	8.167794	

			T.E =	12.953129	
7138	7138				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.741598 =	4.722479	
1418		.027000 x	41.466750 =	1.119602	
003		.800000 x	20.419486 =	16.335589	

			T.E =	22.322670	
7141	7141				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	61.496500 =	1.660406	
003		1.000000 x	20.419486 =	20.419486	
001		.400000 x	15.741598 =	6.296639	

			T.E =	28.521531	

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666

T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1421		.016000 x	.000000 =	.000000
001		.350000 x	15.741598 =	5.509559
1413		.007000 x	29.264100 =	.204849
003		.650000 x	20.419486 =	13.272666

T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1413		.014000 x	29.264100 =	.409697
001		.450000 x	15.741598 =	7.083719
1422		.016000 x	.000000 =	.000000
003		.600000 x	20.419486 =	12.251692

T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1422		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849
003		.600000 x	20.419486 =	12.251692
001		.450000 x	15.741598 =	7.083719

T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
1418		.014000 x	41.466750 =	.580535
003		.650000 x	20.419486 =	13.272666
1422		.016000 x	.000000 =	.000000

T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
003		.650000 x	20.419486 =	13.272666
1418		.007000 x	41.466750 =	.290267
1422		.016000 x	.000000 =	.000000
1427		.007000 x	163.154700 =	1.142083
001		.350000 x	15.741598 =	5.509559

T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
1447		.014000 x	58.635900 =	.820903
1448		.016000 x	.000000 =	.000000
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719

T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
1448		.016000 x	.000000 =	.000000
1447		.007000 x	58.635900 =	.410451
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719

T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1445		.022000 x	61.496500 =	1.352923
003		1.600000 x	20.419486 =	32.671178
1453		.020000 x	179.052750 =	3.581055
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

T.E = 74.981494

7162	7162			
201		.000800 x	290.000000 =	.232000
1458		.020000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
001		.600000 x	15.741598 =	9.444959
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379

T.E =

7163	7163			
201		.000800 x	290.000000 =	.232000
1454		.020000 x	203.307750 =	4.066155
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
1445		.022000 x	61.496500 =	1.352923
001		.600000 x	15.741598 =	9.444959

T.E = 75.466594

7164	7164			
201		.000800 x	290.000000 =	.232000
1455		.020000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

T.E =

7165	7165			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.741598 =	9.444959
002		1.600000 x	17.312112 =	27.699379
1459		.020000 x	203.307750 =	4.066155
1445		.022000 x	61.496500 =	1.352923
003		1.600000 x	20.419486 =	32.671178

T.E = 75.466594

7166	7166			
201		.000800 x	290.000000 =	.232000
1453		.017000 x	179.052750 =	3.043897
1445		.022000 x	61.496500 =	1.352923
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534

T.E = 57.777536

7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
1458		.017000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
002		1.200000 x	17.312112 =	20.774534

T.E =

7168	7168			
201		.000800 x	290.000000 =	.232000
1454		.017000 x	203.307750 =	3.456232
1445		.022000 x	61.496500 =	1.352923
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799

			T.E =	58.189871
7169	7169			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
002		1.200000 x	17.312112 =	20.774534
1455		.017000 x	.000000 =	.000000
1445		.022000 x	61.496500 =	1.352923
003		1.200000 x	20.419486 =	24.503383

			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
1459		.017000 x	203.307750 =	3.456232
1445		.022000 x	61.496500 =	1.352923
001		.500000 x	15.741598 =	7.870799
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383

			T.E =	58.189871
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.741598 =	1.574160

			T.E =	1.777160
7176	7176			
003		1.500000 x	20.419486 =	30.629229

			T.E =	30.629229
7177	7177			
003		1.100000 x	20.419486 =	22.461435

			T.E =	22.461435
7178	7178			
003		.900000 x	20.419486 =	18.377537

			T.E =	18.377537

7179	7179			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743
7181	7181			
003		.700000 x	20.419486 =	14.293640

			T.E =	14.293640
7206	7206			
142		26.000000 x	.325000 =	8.450000
1412		.040000 x	27.931800 =	1.117272
003		.600000 x	20.419486 =	12.251692
002		.300000 x	17.312112 =	5.193634

			T.E =	27.012597
7207	7207			
142		26.000000 x	.325000 =	8.450000
1412		.020000 x	27.931800 =	.558636
003		.500000 x	20.419486 =	10.209743
002		.250000 x	17.312112 =	4.328028

			T.E =	23.546407
7208	7208			
142		26.000000 x	.325000 =	8.450000
002		.200000 x	17.312112 =	3.462422
003		.400000 x	20.419486 =	8.167794
1412		.025000 x	27.931800 =	.698295

			T.E =	20.778512
7209	7209			
142		26.000000 x	.325000 =	8.450000
1412		.005000 x	27.931800 =	.139659
002		.150000 x	17.312112 =	2.596817
003		.300000 x	20.419486 =	6.125846

			T.E =	17.312322
7211	7211			
146		15.000000 x	.340000 =	5.100000
1445		.001000 x	61.496500 =	.061497
003		.400000 x	20.419486 =	8.167794
283		.075000 x	1.036900 =	.077768
002		.200000 x	17.312112 =	3.462422

			T.E =	16.869481

7221	7221				
203.2		.001500 x	370.000000 =	.555000	
254		.020000 x	2.780000 =	.055600	
492		.200000 x	.540000 =	.108000	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	
506		1.150000 x	1.149500 =	1.321925	

			T.E =	8.721239	
7222	7222				
254		.050000 x	2.780000 =	.139000	
492		.200000 x	.540000 =	.108000	
002		.150000 x	17.312112 =	2.596817	
003		.250000 x	20.419486 =	5.104872	
506		1.200000 x	1.149500 =	1.379400	

			T.E =	9.328088	
7223	7223				
254		.050000 x	2.780000 =	.139000	
493		.200000 x	.730000 =	.146000	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
508		1.200000 x	.860000 =	1.032000	

			T.E =	8.863320	
7231	7231				
274		1.200000 x	1.137800 =	1.365360	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	
274		.200000 x	1.137800 =	.227560	

			T.E =	11.025820	
7241	7241				
297.2		.051072 x	.000000 =	.000000	
495		.500000 x	.000000 =	.000000	
002		1.400000 x	17.312112 =	24.236957	
003		1.400000 x	20.419486 =	28.587280	
001		.200000 x	15.741598 =	3.148320	

			T.E =		

7242	7242			
297.2		.057000 x	.000000 =	.000000
001		.200000 x	15.741598 =	3.148320
003		2.800000 x	20.419486 =	57.174561
002		2.800000 x	17.312112 =	48.473914
495		1.000000 x	.000000 =	.000000

			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.695000 =	.903500

			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.695000 =	.903500

			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
251		1.300000 x	.695000 =	.903500
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897

			T.E =	
7244	7244			
251		1.200000 x	.695000 =	.834000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
273		1.200000 x	.922500 =	1.107000

			T.E =	39.672598
7245	7245			
251		.500000 x	.695000 =	.347500
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
273		1.200000 x	.922500 =	1.107000

			T.E =	27.866619

7246 7246

265	.500000 x	.716500 =	.358250
003	1.000000 x	20.419486 =	20.419486
002	1.000000 x	17.312112 =	17.312112
298.1	6.700000 x	5.590000 =	37.453000

T.E = 75.542848

7301 7301

096	1.050000 x	.000000 =	.000000
1445	.025000 x	61.496500 =	1.537413
1444	.001500 x	75.407500 =	.113111
003	.900000 x	20.419486 =	18.377537
001	.400000 x	15.741598 =	6.296639

T.E =

7302 7302

097	1.050000 x	.000000 =	.000000
001	.500000 x	15.741598 =	7.870799
003	1.000000 x	20.419486 =	20.419486
1445	.025000 x	61.496500 =	1.537413
1444	.002000 x	75.407500 =	.150815

T.E =

7303 7303

096	1.100000 x	.000000 =	.000000
1445	.025000 x	61.496500 =	1.537413
001	1.000000 x	15.741598 =	15.741598
1444	.001000 x	75.407500 =	.075408
003	2.000000 x	20.419486 =	40.838972

T.E =

7304 7304

096	1.100000 x	.000000 =	.000000
001	.800000 x	15.741598 =	12.593278
1444	.001500 x	75.407500 =	.113111
1445	.025000 x	61.496500 =	1.537413
003	1.600000 x	20.419486 =	32.671178

T.E =

7305 7305

096	.160000 x	.000000 =	.000000
1445	.004000 x	61.496500 =	.245986
1444	.000200 x	75.407500 =	.015082
003	.300000 x	20.419486 =	6.125846
001	.150000 x	15.741598 =	2.361240

T.E =

7311	7311			
098		1.150000 x	.000000 =	.000000
1417		.033000 x	40.134450 =	1.324437
001		.600000 x	15.741598 =	9.444959
1445		.005000 x	61.496500 =	.307483
003		2.200000 x	20.419486 =	44.922869

			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
1445		.005000 x	61.496500 =	.307483
001		.500000 x	15.741598 =	7.870799
1417		.033000 x	40.134450 =	1.324437
003		1.100000 x	20.419486 =	22.461435

			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
1417		.022000 x	40.134450 =	.882958
001		.400000 x	15.741598 =	6.296639
1445		.004000 x	61.496500 =	.245986
003		.900000 x	20.419486 =	18.377537

			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
1449		.030000 x	53.110700 =	1.593321
003		2.500000 x	20.419486 =	51.048715
001		.500000 x	15.741598 =	7.870799

			T.E =	
7315	7315			
155		1.050000 x	2.481600 =	2.605680
001		.100000 x	15.741598 =	1.574160
1449		.004000 x	53.110700 =	.212443
003		.300000 x	20.419486 =	6.125846

			T.E =	10.518128
7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	53.110700 =	1.327768
1444		.002000 x	75.407500 =	.150815
001		.300000 x	15.741598 =	4.722479
003		.600000 x	20.419486 =	12.251692

			T.E =	25.487754

7317	7317			
163		1.050000 x	6.900000 =	7.245000
1444		.001500 x	75.407500 =	.113111
001		.300000 x	15.741598 =	4.722479
1449		.025000 x	53.110700 =	1.327768
003		.800000 x	20.419486 =	16.335589

			T.E =	29.743947
7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1449		.025000 x	53.110700 =	1.327768
1444		.001000 x	75.407500 =	.075408
003		1.300000 x	20.419486 =	26.545332
001		.100000 x	15.741598 =	1.574160

			T.E =	
7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	53.110700 =	1.327768
1444		.001000 x	75.407500 =	.075408
003		1.300000 x	20.419486 =	26.545332
001		.100000 x	15.741598 =	1.574160

			T.E =	
7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
003		1.500000 x	20.419486 =	30.629229
1449		.025000 x	53.110700 =	1.327768
1444		.001000 x	75.407500 =	.075408

			T.E =	
7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1449		.025000 x	53.110700 =	1.327768
1444		.001000 x	75.407500 =	.075408
003		1.500000 x	20.419486 =	30.629229

			T.E =	

7324	7324			
166		1.050000 x	.000000 =	.000000
1444		.000100 x	75.407500 =	.007541
1449		.002000 x	53.110700 =	.106221
003		.200000 x	20.419486 =	4.083897
001		.040000 x	15.741598 =	.629664

T.E =

7326.1	7326.1			
029		.200000 x	.152800 =	.030560
1449		.020000 x	53.110700 =	1.062214
173		48.000000 x	.255300 =	12.254400
1444		.005000 x	75.407500 =	.377038
003		3.000000 x	20.419486 =	61.258458
001		.500000 x	15.741598 =	7.870799

T.E = 82.853469

7326.2	7326.2			
029		.200000 x	.152800 =	.030560
1449		.020000 x	53.110700 =	1.062214
1444		.005000 x	75.407500 =	.377038
003		3.000000 x	20.419486 =	61.258458
001		.500000 x	15.741598 =	7.870799
174		48.000000 x	.000000 =	.000000

T.E =

7327	7327			
029		.200000 x	.152800 =	.030560
175		95.000000 x	.000000 =	.000000
001		.600000 x	15.741598 =	9.444959
1449		.020000 x	53.110700 =	1.062214
1444		.007000 x	75.407500 =	.527853
003		4.000000 x	20.419486 =	81.677944

T.E =

7328.1	7328.1			
029		.300000 x	.152800 =	.045840
1449		.020000 x	53.110700 =	1.062214
1444		.007000 x	75.407500 =	.527853
171		108.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
001		.700000 x	15.741598 =	11.019119

T.E =

7328.2	7328.2			
029		.300000 x	.152800 =	.045840
172		108.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
1449		.020000 x	53.110700 =	1.062214
1444		.007000 x	75.407500 =	.527853
001		.700000 x	15.741598 =	11.019119

T.E =

7331	7331			
029		1.500000 x	.152800 =	.229200
1449		.020000 x	53.110700 =	1.062214
1444		.005000 x	75.407500 =	.377038
003		3.500000 x	20.419486 =	71.468201
001		.500000 x	15.741598 =	7.870799
169		54.000000 x	.000000 =	.000000

T.E =

7332	7332			
029		2.000000 x	.152800 =	.305600
1449		.020000 x	53.110700 =	1.062214
1444		.005000 x	75.407500 =	.377038
003		4.500000 x	20.419486 =	91.887687
170		108.000000 x	.000000 =	.000000
001		.800000 x	15.741598 =	12.593278

T.E =

7333	7333			
029		.300000 x	.152800 =	.045840
002		.500000 x	17.312112 =	8.656056
1449		.020000 x	53.110700 =	1.062214
003		2.500000 x	20.419486 =	51.048715
167		1.050000 x	.000000 =	.000000

T.E =

7334	7334			
029		.300000 x	.152800 =	.045840
1449		.020000 x	53.110700 =	1.062214
002		.600000 x	17.312112 =	10.387267
003		3.000000 x	20.419486 =	61.258458
168		1.050000 x	.000000 =	.000000

T.E =

7335	7335				
001		.450000 x	15.741598 =	7.083719	
003		1.000000 x	20.419486 =	20.419486	
1445		.026000 x	61.496500 =	1.598909	
1444		.007000 x	75.407500 =	.527853	

			T.E =	29.629967	
7336	7336				
001		.400000 x	15.741598 =	6.296639	
003		.900000 x	20.419486 =	18.377537	
1445		.022000 x	61.496500 =	1.352923	
1444		.006000 x	75.407500 =	.452445	

			T.E =	26.479545	
7337	7337				
001		.350000 x	15.741598 =	5.509559	
1444		.005000 x	75.407500 =	.377038	
1445		.017000 x	61.496500 =	1.045441	
003		.800000 x	20.419486 =	16.335589	

			T.E =	23.267626	
7338	7338				
026		.500000 x	.098900 =	.049450	
1445		.017000 x	61.496500 =	1.045441	
003		.700000 x	20.419486 =	14.293640	
001		.300000 x	15.741598 =	4.722479	

			T.E =	20.111010	
7340	7340				
289		1.100000 x	.659100 =	.725010	
003		1.100000 x	20.419486 =	22.461435	
1445		.026000 x	61.496500 =	1.598909	
1444		.007000 x	75.407500 =	.527853	
001		.400000 x	15.741598 =	6.296639	

			T.E =	31.609845	
7341	7341				
003		.200000 x	20.419486 =	4.083897	
1441		.003000 x	26.861000 =	.080583	

			T.E =	4.164480	
7346	7346				
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.083897	

7347	7347				
001		.200000 x	15.741598 =	3.148320	
1445		.009000 x	61.496500 =	.553469	
1444		.002000 x	75.407500 =	.150815	
003		.500000 x	20.419486 =	10.209743	

			T.E =	14.062346	
7351	7351				
001		.200000 x	15.741598 =	3.148320	
1444		.009000 x	75.407500 =	.678668	
003		.600000 x	20.419486 =	12.251692	

			T.E =	16.078679	
7352	7352				
001		.200000 x	15.741598 =	3.148320	
1444		.012000 x	75.407500 =	.904890	
003		.700000 x	20.419486 =	14.293640	

			T.E =	18.346850	
7355	7355				
001		.150000 x	15.741598 =	2.361240	
1444		.008000 x	75.407500 =	.603260	
003		.600000 x	20.419486 =	12.251692	

			T.E =	15.216191	
7356	7356				
001		.100000 x	15.741598 =	1.574160	
003		.550000 x	20.419486 =	11.230717	
1444		.007000 x	75.407500 =	.527853	

			T.E =	13.332730	
7357	7357				
001		.050000 x	15.741598 =	.787080	
003		.500000 x	20.419486 =	10.209743	
1444		.006000 x	75.407500 =	.452445	

			T.E =	11.449268	
7359	7359				
021		.100000 x	2.670000 =	.267000	
026		20.000000 x	.098900 =	1.978000	
065		.040000 x	13.610000 =	.544400	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	

			T.E =	36.747838	

7360	7360				
021		.050000 x	2.670000 =	.133500	
002		.700000 x	17.312112 =	12.118478	
065		.027000 x	13.610000 =	.367470	
026		13.000000 x	.098900 =	1.285700	
003		.700000 x	20.419486 =	14.293640	

			T.E =	28.198789	
7361	7361				
021		.050000 x	2.670000 =	.133500	
002		1.000000 x	17.312112 =	17.312112	
346.1		30.000000 x	.057200 =	1.716000	
003		1.400000 x	20.419486 =	28.587280	
065		.015000 x	13.610000 =	.204150	
026		14.000000 x	.098900 =	1.384600	

			T.E =	49.337642	
7362.1	7362.1				
021		.050000 x	2.670000 =	.133500	
003		1.400000 x	20.419486 =	28.587280	
002		1.000000 x	17.312112 =	17.312112	
348		8.000000 x	.103600 =	.828800	
346.1		22.000000 x	.057200 =	1.258400	
065		.015000 x	13.610000 =	.204150	
026		14.000000 x	.098900 =	1.384600	

			T.E =	49.708842	
7362.2	7362.2				
021		.050000 x	2.670000 =	.133500	
003		1.400000 x	20.419486 =	28.587280	
002		1.000000 x	17.312112 =	17.312112	
348		8.000000 x	.103600 =	.828800	
346.2		22.000000 x	.103600 =	2.279200	
065		.015000 x	13.610000 =	.204150	
026		14.000000 x	.098900 =	1.384600	

			T.E =	50.729642	
7363	7363				
021		.050000 x	2.670000 =	.133500	
026		17.000000 x	.098900 =	1.681300	
065		.020000 x	13.610000 =	.272200	
003		1.600000 x	20.419486 =	32.671178	
002		1.200000 x	17.312112 =	20.774534	
346.1		35.000000 x	.057200 =	2.002000	

			T.E =	57.534712	

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
346.1		24.000000 x	.057200 =	1.372800
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.098900 =	1.681300

			T.E =	58.045112
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
346.2		24.000000 x	.103600 =	2.486400
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.098900 =	1.681300

			T.E =	59.158712
7366	7366			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.098900 =	.989000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.530500 =	.525305
002		2.000000 x	17.312112 =	34.624224
346.1		45.000000 x	.057200 =	2.574000

			T.E =	100.104487
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.530500 =	.525305
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000
026		10.000000 x	.098900 =	.989000

			T.E =	100.800487
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
346.2		30.000000 x	.103600 =	3.108000
348		15.000000 x	.103600 =	1.554000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.530500 =	.525305
002		2.000000 x	17.312112 =	34.624224
026		10.000000 x	.098900 =	.989000

			T.E =	102.192487

7371.1	7371.1					
026	-	14.000000 x	.098900 =	-	1.384600	
7361		1.000000 x	49.337642 =		49.337642	
029		14.000000 x	.152800 =		2.139200	

			T.E =		50.092242	
7371.2	7371.2					
026	-	14.000000 x	.098900 =	-	1.384600	
028		14.000000 x	.000000 =		.000000	
7361		1.000000 x	49.337642 =		49.337642	

			T.E =			
7372.1	7372.1					
026	-	14.000000 x	.098900 =	-	1.384600	
029		14.000000 x	.152800 =		2.139200	
7362.1		1.000000 x	49.708842 =		49.708842	

			T.E =		50.463442	
7372.2	7372.2					
026	-	14.000000 x	.098900 =	-	1.384600	
028		14.000000 x	.000000 =		.000000	
7362.1		1.000000 x	49.708842 =		49.708842	

			T.E =			
7372.3	7372.3					
026	-	14.000000 x	.098900 =	-	1.384600	
7362.2		1.000000 x	50.729642 =		50.729642	
029		14.000000 x	.152800 =		2.139200	

			T.E =		51.484242	
7372.4	7372.4					
026	-	14.000000 x	.098900 =	-	1.384600	
7362.2		1.000000 x	50.729642 =		50.729642	
028		14.000000 x	.000000 =		.000000	

			T.E =			
7373.1	7373.1					
026	-	17.000000 x	.098900 =	-	1.681300	
029		17.000000 x	.152800 =		2.597600	
7363		1.000000 x	57.534712 =		57.534712	

			T.E =		58.451012	

7373.2	7373.2					
026	-	17.000000 x	.098900 =	-	1.681300	
7363		1.000000 x	57.534712 =		57.534712	
028		17.000000 x	.000000 =		.000000	

			T.E =			
7374.1	7374.1					
026	-	17.000000 x	.098900 =	-	1.681300	
7364.1		1.000000 x	58.045112 =		58.045112	
029		17.000000 x	.152800 =		2.597600	

			T.E =		58.961412	
7374.2	7374.2					
026	-	17.000000 x	.098900 =	-	1.681300	
7364.1		1.000000 x	58.045112 =		58.045112	
028		17.000000 x	.000000 =		.000000	

			T.E =			
7374.3	7374.3					
026	-	17.000000 x	.098900 =	-	1.681300	
7364.2		1.000000 x	59.158712 =		59.158712	
029		17.000000 x	.152800 =		2.597600	

			T.E =		60.075012	
7374.4	7374.4					
026	-	17.000000 x	.098900 =	-	1.681300	
7364.2		1.000000 x	59.158712 =		59.158712	
028		17.000000 x	.000000 =		.000000	

			T.E =			
7376.1	7376.1					
026	-	10.000000 x	.098900 =	-	.989000	
029		10.000000 x	.152800 =		1.528000	
7366		1.000000 x	100.104487 =		100.104487	

			T.E =		100.643487	
7376.2	7376.2					
026	-	10.000000 x	.098900 =	-	.989000	
7366		1.000000 x	100.104487 =		100.104487	
028		10.000000 x	.000000 =		.000000	

			T.E =			

7377.1	7377.1				
026	-	10.000000 x	.098900 =	-	.989000
7367.1		1.000000 x	100.800487 =		100.800487
029		10.000000 x	.152800 =		1.528000

			T.E =		101.339487
7377.2	7377.2				
026	-	10.000000 x	.098900 =	-	.989000
7367.1		1.000000 x	100.800487 =		100.800487
028		10.000000 x	.000000 =		.000000

			T.E =		
7377.3	7377.3				
026	-	10.000000 x	.098900 =	-	.989000
7367.2		1.000000 x	102.192487 =		102.192487
029		10.000000 x	.152800 =		1.528000

			T.E =		102.731487
7377.4	7377.4				
026	-	10.000000 x	.098900 =	-	.989000
028		10.000000 x	.000000 =		.000000
7367.2		1.000000 x	102.192487 =		102.192487

			T.E =		
7381	7381				
456		.100000 x	1.610000 =		.161000

			T.E =		.161000
7382	7382				
443		.150000 x	1.930000 =		.289500
447		.050000 x	4.393700 =		.219685
003		.300000 x	20.419486 =		6.125846

			T.E =		6.635031
7383	7383				
002		.250000 x	17.312112 =		4.328028
003		.150000 x	20.419486 =		3.062923

			T.E =		7.390951
7384	7384				
003		.500000 x	20.419486 =		10.209743

			T.E =		10.209743

7385	7385			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743
7386	7386			
003		.600000 x	20.419486 =	12.251692

			T.E =	12.251692
7387	7387			
261		1.500000 x	.591200 =	.886800
003		1.000000 x	20.419486 =	20.419486
7361		1.100000 x	49.337642 =	54.271406

			T.E =	75.577692
7388	7388			
003		2.500000 x	20.419486 =	51.048715
7361		.600000 x	49.337642 =	29.602585

			T.E =	80.651300
7389.1.1	7389.1.1			
7371.1		.300000 x	50.092242 =	15.027673

			T.E =	15.027673
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	60.075012 =	18.022504

			T.E =	18.022504
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000

			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	50.463442 =	15.139033

			T.E =	15.139033
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	51.484242 =	15.445273

			T.E =	15.445273
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	58.451012 =	17.535304

			T.E =	17.535304
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	58.961412 =	17.688424

			T.E =	17.688424
7389.2.1	7389.2.1			
7371.1		.500000 x	50.092242 =	25.046121

			T.E =	25.046121
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	60.075012 =	30.037506

			T.E =	30.037506

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	50.463442 =	25.231721

			T.E =	25.231721
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	51.484242 =	25.742121

			T.E =	25.742121
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	58.451012 =	29.225506

			T.E =	29.225506
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	58.961412 =	29.480706

			T.E =	29.480706
7391	7391			
003		.250000 x	20.419486 =	5.104872

			T.E =	5.104872

7392	7392				
298.1		1.081080 x	5.590000 =	6.043237	
003		.400000 x	20.419486 =	8.167794	

			T.E =	14.211032	
7393	7393				
294		.347760 x	3.407000 =	1.184818	
003		.300000 x	20.419486 =	6.125846	

			T.E =	7.310664	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	20.419486 =	8.167794	

			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	20.419486 =	6.125846	

			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	22.206059	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	20.419486 =	14.293640	

			T.E =	22.918640	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	23.481439	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	20.419486 =	5.104872	

			T.E =	6.644872	

7416	7416			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7417	7417			
003		1.800000 x	20.419486 =	36.755075

			T.E =	36.755075
7418	7418			
003		2.600000 x	20.419486 =	53.090664

			T.E =	53.090664
7419	7419			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7420	7420			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
7421	7421			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7422	7422			
003		.350000 x	20.419486 =	7.146820

			T.E =	7.146820
7431	7431			
332		1.150000 x	88.540000 =	101.821000
1445		.020000 x	61.496500 =	1.229930
003		4.000000 x	20.419486 =	81.677944
1444		.001000 x	75.407500 =	.075408

			T.E =	184.804282
7432	7432			
331		1.150000 x	85.390000 =	98.198500
1445		.020000 x	61.496500 =	1.229930
1444		.001000 x	75.407500 =	.075408
003		4.400000 x	20.419486 =	89.845738

			T.E =	189.349576

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		5.100000 x	20.419486 =	104.139379	

			T.E =	203.643216	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	

			T.E =	224.062702	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
003		4.200000 x	20.419486 =	85.761841	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	

			T.E =	193.804679	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		4.600000 x	20.419486 =	93.929636	

			T.E =	201.972473	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		5.300000 x	20.419486 =	108.223276	

			T.E =	216.266113	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
003		6.300000 x	20.419486 =	128.642762	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	

			T.E =	236.685599	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
003		4.500000 x	20.419486 =	91.887687	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	

			T.E =	235.758525	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		4.900000 x	20.419486 =	100.055481	

			T.E =	243.926319	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		5.600000 x	20.419486 =	114.349122	

			T.E =	258.219959	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
003		6.600000 x	20.419486 =	134.768608	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	

			T.E =	278.639445	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
003		4.900000 x	20.419486 =	100.055481	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	

			T.E =	256.323319	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		5.300000 x	20.419486 =	108.223276	

			T.E =	264.491113	

7463	7463				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	
003		6.000000 x	20.419486 =	122.516916	

			T.E =	278.784754	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
003		7.000000 x	20.419486 =	142.936402	
1445		.020000 x	61.496500 =	1.229930	
1444		.001000 x	75.407500 =	.075408	

			T.E =	299.204240	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
003		.915000 x	20.419486 =	18.683830	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	

			T.E =	28.634213	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
003		.945000 x	20.419486 =	19.296414	

			T.E =	30.100698	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
003		.990000 x	20.419486 =	20.215291	
1444		.000100 x	75.407500 =	.007541	
1445		.002000 x	61.496500 =	.122993	

			T.E =	34.602375	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
003		1.050000 x	20.419486 =	21.440460	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	

			T.E =	37.067244	

7496	7496			
331		.057500 x	85.390000 =	4.909925
003		.488000 x	20.419486 =	9.964709
1445		.001000 x	61.496500 =	.061497
1444		.000050 x	75.407500 =	.003770

			T.E =	14.939901
7497	7497			
331		.062500 x	85.390000 =	5.336875
1445		.001000 x	61.496500 =	.061497
1444		.000050 x	75.407500 =	.003770
003		.504000 x	20.419486 =	10.291421

			T.E =	15.693563
7498	7498			
333		.057500 x	123.970000 =	7.128275
1445		.001000 x	61.496500 =	.061497
1444		.000050 x	75.407500 =	.003770
003		.528000 x	20.419486 =	10.781489

			T.E =	17.975030
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	20.419486 =	11.434912
1444		.000050 x	75.407500 =	.003770
1445		.001000 x	61.496500 =	.061497

			T.E =	19.248304
7501	7501			
7433		1.000000 x	203.643216 =	203.643216

			T.E =	203.643216
7503	7503			
7443		1.000000 x	216.266113 =	216.266113

			T.E =	216.266113
7506	7506			
7453		1.000000 x	258.219959 =	258.219959

			T.E =	258.219959
7508	7508			
7463		1.000000 x	278.784754 =	278.784754

			T.E =	278.784754

7511	7511				
331		.115000 x	85.390000 =	9.819850	
1445		.002000 x	61.496500 =	.122993	
1444		.000100 x	75.407500 =	.007541	
003		.915000 x	20.419486 =	18.683830	

			T.E =	28.634213	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
1444		.000100 x	75.407500 =	.007541	
003		.945000 x	20.419486 =	19.296414	
1445		.002000 x	61.496500 =	.122993	

			T.E =	30.100698	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.496500 =	1.229930	

			T.E =	215.819500	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	61.496500 =	1.229930	
003		4.800000 x	20.419486 =	98.013533	

			T.E =	197.441963	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.496500 =	1.229930	

			T.E =	232.526295	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.496500 =	1.229930	
003		5.000000 x	20.419486 =	102.097430	

			T.E =	210.064860	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
1445		.020000 x	61.496500 =	1.229930	
003		5.200000 x	20.419486 =	106.181327	

			T.E =	209.232257	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
003		5.400000 x	20.419486 =	110.265224	
1445		.020000 x	61.496500 =	1.229930	

			T.E =	222.170154	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.496500 =	1.229930	

			T.E =	270.375500	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.496500 =	1.229930	

			T.E =	291.826295	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
1445		.010000 x	61.496500 =	.614965	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	101.722423	
7537	7537				
336		.300000 x	.000000 =	.000000	
1445		.010000 x	61.496500 =	.614965	
003		4.000000 x	20.419486 =	81.677944	

			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
334		.350000 x	132.830000 =	46.490500	
1445		.010000 x	61.496500 =	.614965	
003		3.700000 x	20.419486 =	75.552098	

			T.E =	137.709363	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
336		.350000 x	.000000 =	.000000	
003		4.200000 x	20.419486 =	85.761841	
1445		.010000 x	61.496500 =	.614965	

			T.E =		

7543	7543			
332		.170000 x	88.540000 =	15.051800
338		.350000 x	.000000 =	.000000
1445		.010000 x	61.496500 =	.614965
003		4.800000 x	20.419486 =	98.013533

			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.496500 =	1.229930
003		7.000000 x	20.419486 =	142.936402

			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.496500 =	1.229930

			T.E =	271.459832
7553	7553			
323		1.150000 x	126.500000 =	145.475000
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.496500 =	1.229930

			T.E =	289.641332
7554	7554			
321		1.150000 x	.000000 =	.000000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.496500 =	1.229930

			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	61.496500 =	1.229930
003		9.000000 x	20.419486 =	183.775374

			T.E =	312.298804
7556	7556			
323		1.150000 x	126.500000 =	145.475000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.496500 =	1.229930

			T.E =	330.480304

7558	7558				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	20.419486 =	30.629229	
1445		.003000 x	61.496500 =	.184490	

			T.E =	37.644919	
7559	7559				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	20.419486 =	30.629229	
1445		.003000 x	61.496500 =	.184490	

			T.E =	37.644919	
7561	7561				
332		1.150000 x	88.540000 =	101.821000	
1445		.020000 x	61.496500 =	1.229930	
003		5.200000 x	20.419486 =	106.181327	

			T.E =	209.232257	
7562	7562				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.496500 =	1.229930	

			T.E =	270.375500	
7563	7563				
332		1.250000 x	88.540000 =	110.675000	
003		5.400000 x	20.419486 =	110.265224	
1445		.020000 x	61.496500 =	1.229930	

			T.E =	222.170154	
7564	7564				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	61.496500 =	1.229930	
003		6.100000 x	20.419486 =	124.558865	

			T.E =	291.826295	
7565	7565				
003		1.500000 x	20.419486 =	30.629229	

			T.E =	30.629229	
7566	7566				
7561		1.500000 x	209.232257 =	313.848386	

			T.E =	313.848386	

7567	7567			
7562		1.500000 x	270.375500 =	405.563250

			T.E =	405.563250
7568	7568			
7563		1.500000 x	222.170154 =	333.255231

			T.E =	333.255231
7569	7569			
7564		1.500000 x	291.826295 =	437.739443

			T.E =	437.739443
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
327.1		.030000 x	.000000 =	.000000

			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
327.2		.030000 x	.000000 =	.000000

			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
003		3.000000 x	20.419486 =	61.258458
327.3		.030000 x	196.650000 =	5.899500

			T.E =	263.807958
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
328		.030000 x	.000000 =	.000000

			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	20.419486 =	77.594047

			T.E =	175.792547

7577	7577				
334		1.150000 x	132.830000 =	152.754500	
003		4.200000 x	20.419486 =	85.761841	

			T.E =	238.516341	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	20.419486 =	95.971584	

			T.E =		
7581	7581				
326		1.050000 x	63.530000 =	66.706500	
3211		.020000 x	134.057521 =	2.681150	
1445		.005000 x	61.496500 =	.307483	
003		2.300000 x	20.419486 =	46.964818	

			T.E =	116.659951	
7601	7601				
401		1.100000 x	13.560000 =	14.916000	
457		.500000 x	.803800 =	.401900	
003		.500000 x	20.419486 =	10.209743	

			T.E =	25.527643	
7602	7602				
403		1.100000 x	15.880000 =	17.468000	
457		.500000 x	.803800 =	.401900	
003		.550000 x	20.419486 =	11.230717	

			T.E =	29.100617	
7603	7603				
406		1.100000 x	19.630000 =	21.593000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	20.419486 =	13.272666	

			T.E =	35.267566	
7604.1	7604.1				
409		1.100000 x	23.370000 =	25.707000	
003		.750000 x	20.419486 =	15.314615	
457		.500000 x	.803800 =	.401900	

			T.E =	41.423515	

7604.2	7604.2			
410		1.100000 x	31.790000 =	34.969000
003		.750000 x	20.419486 =	15.314615
457		.500000 x	.803800 =	.401900

			T.E =	50.685515
7606	7606			
401		1.100000 x	13.560000 =	14.916000
003		.600000 x	20.419486 =	12.251692

			T.E =	27.167692
7607	7607			
403		1.100000 x	15.880000 =	17.468000
003		.650000 x	20.419486 =	13.272666

			T.E =	30.740666
7608	7608			
406		1.100000 x	19.630000 =	21.593000
003		.750000 x	20.419486 =	15.314615

			T.E =	36.907615
7609.1	7609.1			
409		1.100000 x	23.370000 =	25.707000
003		.850000 x	20.419486 =	17.356563

			T.E =	43.063563
7609.2	7609.2			
410		1.100000 x	31.790000 =	34.969000
003		.850000 x	20.419486 =	17.356563

			T.E =	52.325563
7611	7611			
411		1.100000 x	29.680000 =	32.648000
457		.500000 x	.803800 =	.401900
003		.500000 x	20.419486 =	10.209743

			T.E =	43.259643
7612	7612			
412		1.100000 x	32.030000 =	35.233000
003		.550000 x	20.419486 =	11.230717
457		.500000 x	.803800 =	.401900

			T.E =	46.865617

7613	7613				
411		1.100000 x	29.680000 =	32.648000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	44.899692	
7614	7614				
412		1.100000 x	32.030000 =	35.233000	
003		.650000 x	20.419486 =	13.272666	

			T.E =	48.505666	
7616	7616				
414		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.600000 x	20.419486 =	12.251692	

			T.E =	38.360592	
7617	7617				
415		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	20.419486 =	13.272666	

			T.E =	39.381566	
7618	7618				
414		1.100000 x	23.370000 =	25.707000	
003		.700000 x	20.419486 =	14.293640	

			T.E =	40.000640	
7619	7619				
415		1.100000 x	23.370000 =	25.707000	
003		.750000 x	20.419486 =	15.314615	

			T.E =	41.021615	
7621	7621				
418		1.100000 x	32.720000 =	35.992000	
457		.800000 x	.803800 =	.643040	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	61.138423	
7622	7622				
419		1.100000 x	32.720000 =	35.992000	
003		1.400000 x	20.419486 =	28.587280	
457		.800000 x	.803800 =	.643040	

			T.E =	65.222320	

7626.1	7626.1			
298.2		18.000000 x	4.870000 =	87.660000
421		1.000000 x	108.710000 =	108.710000
002		7.000000 x	17.312112 =	121.184784
003		7.000000 x	20.419486 =	142.936402

			T.E =	460.491186
7626.2	7626.2			
298.2		18.000000 x	4.870000 =	87.660000
422		1.000000 x	149.410000 =	149.410000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

			T.E =	501.191186
7627.1	7627.1			
298.2		16.000000 x	4.870000 =	77.920000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
421		1.000000 x	108.710000 =	108.710000

			T.E =	413.019588
7627.2	7627.2			
298.2		16.000000 x	4.870000 =	77.920000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
422		1.000000 x	149.410000 =	149.410000

			T.E =	453.719588
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	20.419486 =	1.020974

			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	20.419486 =	1.225169

			T.E =	6.054169
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	20.419486 =	1.633559

			T.E =	7.562559

7638	7638			
430		1.100000 x	7.480000 =	8.228000
003		.100000 x	20.419486 =	2.041949

			T.E =	10.269949
7641	7641			
431		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169

			T.E =	
7642	7642			
432		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169

			T.E =	
7701	7701			
024		.001500 x	50.000000 =	.075000
002		.050000 x	17.312112 =	.865606
003		.120000 x	20.419486 =	2.450338

			T.E =	3.390944
7702	7702			
024		.001800 x	50.000000 =	.090000
003		.080000 x	20.419486 =	1.633559
002		.050000 x	17.312112 =	.865606

			T.E =	2.589164
7706	7706			
024		.002000 x	50.000000 =	.100000
003		.150000 x	20.419486 =	3.062923
002		.080000 x	17.312112 =	1.384969

			T.E =	4.547892
7707	7707			
024		.002300 x	50.000000 =	.115000
003		.090000 x	20.419486 =	1.837754
002		.100000 x	17.312112 =	1.731211

			T.E =	3.683965

7708	7708			
024		.002500 x	50.000000 =	.125000
003		.180000 x	20.419486 =	3.675507
002		.120000 x	17.312112 =	2.077453

			T.E =	5.877961
7709	7709			
024		.002800 x	50.000000 =	.140000
003		.120000 x	20.419486 =	2.450338
002		.150000 x	17.312112 =	2.596817

			T.E =	5.187155
7711	7711			
002		.050000 x	17.312112 =	.865606
1485		.200000 x	.834659 =	.166932
003		.200000 x	20.419486 =	4.083897

			T.E =	5.116435
7712	7712			
002		.080000 x	17.312112 =	1.384969
1485		.250000 x	.834659 =	.208665
003		.250000 x	20.419486 =	5.104872

			T.E =	6.698505
7713	7713			
002		.160000 x	17.312112 =	2.769938
003		.300000 x	20.419486 =	6.125846
1485		.280000 x	.834659 =	.233705

			T.E =	9.129488
7720	7720			
443		.080000 x	1.930000 =	.154400
003		.300000 x	20.419486 =	6.125846
002		.100000 x	17.312112 =	1.731211
1485		.200000 x	.834659 =	.166932

			T.E =	8.178389
7721	7721			
002		.070000 x	17.312112 =	1.211848
003		.200000 x	20.419486 =	4.083897
1485		.200000 x	.834659 =	.166932

			T.E =	5.462677

7722.1.1	7722.1.1			
7720		.300000 x	8.178389 =	2.453517

			T.E =	2.453517
7722.1.2	7722.1.2			
7721		.300000 x	5.462677 =	1.638803

			T.E =	1.638803
7722.2.1	7722.2.1			
7720		.400000 x	8.178389 =	3.271356

			T.E =	3.271356
7722.2.2	7722.2.2			
7721		.400000 x	5.462677 =	2.185071

			T.E =	2.185071
7725	7725			
471		.300000 x	4.100000 =	1.230000
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817

			T.E =	8.931688
7735	7735			
441		.350000 x	.075500 =	.026425
444		.150000 x	2.143200 =	.321480
003		.150000 x	20.419486 =	3.062923

			T.E =	3.410828
7736	7736			
441		.500000 x	.075500 =	.037750
444		.085000 x	2.143200 =	.182172
445		.010000 x	1.553500 =	.015535
003		.250000 x	20.419486 =	5.104872
446		.005000 x	2.540000 =	.012700

			T.E =	5.353029
7737	7737			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.876050 =	.175210
003		.300000 x	20.419486 =	6.125846
1488		.600000 x	.768615 =	.461169

			T.E =	6.777325

7738	7738			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.876050 =	.175210
1488		.300000 x	.768615 =	.230585
003		.300000 x	20.419486 =	6.125846

			T.E =	6.546740
7739	7739			
441		.100000 x	.075500 =	.007550
467		.100000 x	3.380000 =	.338000
003		.150000 x	20.419486 =	3.062923

			T.E =	3.408473
7740	7740			
442		.250000 x	.118300 =	.029575
003		.250000 x	20.419486 =	5.104872
1492		.250000 x	2.756980 =	.689245

			T.E =	5.823692
7741	7741			
442		.250000 x	.118300 =	.029575
462		.250000 x	.000000 =	.000000
003		.250000 x	20.419486 =	5.104872

			T.E =	
7742	7742			
442		.250000 x	.118300 =	.029575
003		.200000 x	20.419486 =	4.083897
463		.125000 x	3.970000 =	.496250

			T.E =	4.609722
7743	7743			
442		.250000 x	.118300 =	.029575
003		.150000 x	20.419486 =	3.062923
464		.125000 x	3.720000 =	.465000

			T.E =	3.557498
7744	7744			
442		.250000 x	.118300 =	.029575
003		.150000 x	20.419486 =	3.062923
465		.125000 x	5.870000 =	.733750

			T.E =	3.826248

7745	7745			
442		.250000 x	.118300 =	.029575
1492		.250000 x	2.756980 =	.689245
003		.800000 x	20.419486 =	16.335589
1489		.200000 x	.876050 =	.175210

			T.E =	17.229619
7746	7746			
441		.350000 x	.075500 =	.026425
003		.150000 x	20.419486 =	3.062923
443		.090000 x	1.930000 =	.173700

			T.E =	3.263048
7747	7747			
441		.350000 x	.075500 =	.026425
443		.170000 x	1.930000 =	.328100
003		.250000 x	20.419486 =	5.104872

			T.E =	5.459397
7748	7748			
443		.090000 x	1.930000 =	.173700
002		.100000 x	17.312112 =	1.731211
445		.030000 x	1.553500 =	.046605
003		.200000 x	20.419486 =	4.083897
450		.060000 x	2.760000 =	.165600

			T.E =	6.201013
7749	7749			
443		.160000 x	1.930000 =	.308800
445		.050000 x	1.553500 =	.077675
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
450		.100000 x	2.760000 =	.276000

			T.E =	8.364163
7751	7751			
003		.150000 x	20.419486 =	3.062923
1491		.125000 x	1.488894 =	.186112

			T.E =	3.249035
7752	7752			
003		.250000 x	20.419486 =	5.104872
1491		.250000 x	1.488894 =	.372224

			T.E =	5.477095

7753	7753				
441		1.000000 x	.075500 =	.075500	
003		.650000 x	20.419486 =	13.272666	
443		.080000 x	1.930000 =	.154400	
1491		.200000 x	1.488894 =	.297779	
1490		.090000 x	1.546426 =	.139178	

			T.E =	13.939523	
7754	7754				
441		.800000 x	.075500 =	.060400	
1487		.090000 x	.614606 =	.055315	
003		.800000 x	20.419486 =	16.335589	
1490		.090000 x	1.546426 =	.139178	
1491		.200000 x	1.488894 =	.297779	

			T.E =	16.888260	
7755	7755				
442		.250000 x	.118300 =	.029575	
003		1.000000 x	20.419486 =	20.419486	
1491		.200000 x	1.488894 =	.297779	
1492		.160000 x	2.756980 =	.441117	

			T.E =	21.187957	
7756	7756				
442		.300000 x	.118300 =	.035490	
003		.350000 x	20.419486 =	7.146820	
1492		.300000 x	2.756980 =	.827094	

			T.E =	8.009404	
7761	7761				
441		.650000 x	.075500 =	.049075	
1489		.200000 x	.876050 =	.175210	
1488		.600000 x	.768615 =	.461169	
003		.800000 x	20.419486 =	16.335589	
467		.100000 x	3.380000 =	.338000	
473		.100000 x	2.750000 =	.275000	

			T.E =	17.634043	
7762	7762				
473		.100000 x	2.750000 =	.275000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.358897	

7764	7764				
474		.125000 x	3.770000 =	.471250	
003		.100000 x	20.419486 =	2.041949	

			T.E =	2.513199	
7765	7765				
475		.125000 x	6.230000 =	.778750	
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.862647	
7766	7766				
442		.275000 x	.118300 =	.032533	
473		.110000 x	2.750000 =	.302500	
1492		.275000 x	2.756980 =	.758170	
003		.880000 x	20.419486 =	17.969148	

			T.E =	19.062350	
7767.1	7767.1				
7755		.150000 x	21.187957 =	3.178194	

			T.E =	3.178194	
7767.2	7767.2				
442		.250000 x	.118300 =	.029575	
1492		.160000 x	2.756980 =	.441117	
003		1.000000 x	20.419486 =	20.419486	
473		.200000 x	2.750000 =	.550000	

			AΘΡΟΙΣΜΑ =	21.440178	
	T.E =	.150000 x	21.440178 =	3.216027	

7767.3	7767.3				
7755		.250000 x	21.187957 =	5.296989	

			T.E =	5.296989	
7767.4	7767.4				
442		.250000 x	.118300 =	.029575	
473		.200000 x	2.750000 =	.550000	
003		1.000000 x	20.419486 =	20.419486	
1492		.160000 x	2.756980 =	.441117	

			AΘΡΟΙΣΜΑ =	21.440178	
	T.E =	.250000 x	21.440178 =	5.360044	

7767.5	7767.5			
7755		.350000 x	21.187957 =	7.415785

			T.E =	7.415785
7767.6	7767.6			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.350000 x	21.440178 =	7.504062

7767.7	7767.7			
7755		.450000 x	21.187957 =	9.534581

			T.E =	9.534581
7767.8	7767.8			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.450000 x	21.440178 =	9.648080

7768	7768			
460		.200000 x	4.250000 =	.850000
003		.450000 x	20.419486 =	9.188769
460		.030000 x	4.250000 =	.127500
002		.450000 x	17.312112 =	7.790450

			T.E =	17.956719
7769	7769			
460		.200000 x	4.250000 =	.850000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
460		.030000 x	4.250000 =	.127500

			T.E =	8.523820
7770	7770			
460		.090000 x	4.250000 =	.382500
003		.150000 x	20.419486 =	3.062923
002		.150000 x	17.312112 =	2.596817
460		.020000 x	4.250000 =	.085000

			T.E =	6.127240

7771	7771				
441		1.000000 x	.075500 =	.075500	
1488		.160000 x	.768615 =	.122978	
1487		.080000 x	.614606 =	.049168	
003		1.300000 x	20.419486 =	26.545332	
473		.100000 x	2.750000 =	.275000	
467		.110000 x	3.380000 =	.371800	

			T.E =	27.439779	
7772	7772				
441		1.000000 x	.075500 =	.075500	
458		.100000 x	5.030000 =	.503000	
443		.100000 x	1.930000 =	.193000	
003		.500000 x	20.419486 =	10.209743	

			T.E =	10.981243	
7773	7773				
441		1.000000 x	.075500 =	.075500	
459		.100000 x	5.030000 =	.503000	
443		.100000 x	1.930000 =	.193000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	13.023192	
7774	7774				
442		.250000 x	.118300 =	.029575	
473		.200000 x	2.750000 =	.550000	
1492		.160000 x	2.756980 =	.441117	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	21.440178	
7785.1	7785.1				
441		.350000 x	.075500 =	.026425	
003		.700000 x	20.419486 =	14.293640	
477		.160000 x	.000000 =	.000000	
476		.120000 x	2.366400 =	.283968	

			T.E =	15.074049	
7785.2	7785.2				
441		.350000 x	.075500 =	.026425	
476		.120000 x	2.366400 =	.283968	
478		.160000 x	2.937600 =	.470016	
003		.700000 x	20.419486 =	14.293640	

			T.E =	15.074049	

7786.1	7786.1			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.876050 =	.175210
003		1.000000 x	20.419486 =	20.419486
1488		.600000 x	.768615 =	.461169
477		.110000 x	.000000 =	.000000

			T.E =	
7786.2	7786.2			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.876050 =	.175210
1488		.600000 x	.768615 =	.461169
003		1.000000 x	20.419486 =	20.419486
478		.110000 x	2.937600 =	.323136

			T.E =	21.405426
7787	7787			
441		1.000000 x	.075500 =	.075500
476		.090000 x	2.366400 =	.212976
1488		.160000 x	.768615 =	.122978
1487		.080000 x	.614606 =	.049168
003		1.000000 x	20.419486 =	20.419486
477		.160000 x	.000000 =	.000000

			T.E =	
7788	7788			
441		.250000 x	.075500 =	.018875
479		1.000000 x	1.815600 =	1.815600
003		.700000 x	20.419486 =	14.293640

			T.E =	16.128115
7791	7791			
441		1.000000 x	.075500 =	.075500
1487		.050000 x	.614606 =	.030730
1491		.200000 x	1.488894 =	.297779
003		.500000 x	20.419486 =	10.209743

			T.E =	10.613752
7792	7792			
482		.150000 x	.984000 =	.147600
003		.500000 x	20.419486 =	10.209743

			T.E =	10.357343

7793	7793				
480		.500000 x	3.366000 =	1.683000	
003		.200000 x	20.419486 =	4.083897	
			T.E =	5.766897	
7794	7794				
482		.150000 x	.984000 =	.147600	
003		.500000 x	20.419486 =	10.209743	
			T.E =	10.357343	
7797	7797				
201		.000500 x	290.000000 =	.145000	
002		.060000 x	17.312112 =	1.038727	
			T.E =	1.183727	
7798	7798				
201		.000600 x	290.000000 =	.174000	
002		.070000 x	17.312112 =	1.211848	
			T.E =	1.385848	
7801	7801				
496		1.200000 x	1.905500 =	2.286600	
003		.150000 x	20.419486 =	3.062923	
			T.E =	5.349523	
7806	7806				
498		1.150000 x	1.011600 =	1.163340	
003		.300000 x	20.419486 =	6.125846	
			T.E =	7.289186	
7807	7807				
499		1.150000 x	1.386800 =	1.594820	
003		.400000 x	20.419486 =	8.167794	
			T.E =	9.762614	
7808	7808				
500		1.150000 x	2.039600 =	2.345540	
003		.600000 x	20.419486 =	12.251692	
			T.E =	14.597232	

7809	7809			
501		1.200000 x	2.763000 =	3.315600
003		.800000 x	20.419486 =	16.335589

			T.E =	19.651189
7810	7810			
502		1.200000 x	3.807000 =	4.568400
003		.900000 x	20.419486 =	18.377537

			T.E =	22.945937
7811	7811			
503		1.200000 x	.905500 =	1.086600
003		.800000 x	20.419486 =	16.335589

			T.E =	17.422189
7812	7812			
504		1.300000 x	1.199100 =	1.558830
003		.900000 x	20.419486 =	18.377537

			T.E =	19.936367
7813	7813			
505		1.000000 x	19.170000 =	19.170000
003		.600000 x	20.419486 =	12.251692

			T.E =	31.421692
7901	7901			
490		1.080000 x	.730000 =	.788400
003		.200000 x	20.419486 =	4.083897

			T.E =	4.872297
7902	7902			
527		1.050000 x	5.120000 =	5.376000
003		1.000000 x	20.419486 =	20.419486

			T.E =	25.795486
7903	7903			
528		1.050000 x	6.910000 =	7.255500
003		.600000 x	20.419486 =	12.251692

			T.E =	19.507192

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	20.419486 =	10.209743

			T.E =	15.963743
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.149500 =	1.264450
002		.300000 x	17.312112 =	5.193634
003		.150000 x	20.419486 =	3.062923

			T.E =	10.397007
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	20.419486 =	3.062923
002		.350000 x	17.312112 =	6.059239

			T.E =	12.066162
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	20.419486 =	3.062923
002		.400000 x	17.312112 =	6.924845

			T.E =	11.809768
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	20.419486 =	1.633559

			T.E =	2.084559
7915.1	7915.1			
7911		.850000 x	10.397007 =	8.837456

			T.E =	8.837456
7915.2	7915.2			
7912		.850000 x	12.066162 =	10.256238

			T.E =	10.256238
7915.3	7915.3			
7913		.850000 x	11.809768 =	10.038303

			T.E =	10.038303

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	17.312112 =	.692484

			T.E =	2.134484
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	17.312112 =	.865606

			T.E =	3.121306
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	17.312112 =	.865606

			T.E =	2.081006
7931	7931			
519		1.050000 x	47.670000 =	50.053500
003		1.500000 x	20.419486 =	30.629229

			T.E =	80.682729
7932.1	7932.1			
514		.000000 x	36.950000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7932.2	7932.2			
520		.000000 x	35.560000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7933.1	7933.1			
514		.000000 x	36.950000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7933.2	7933.2			
520		.000000 x	35.560000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000

7934	7934			
535		1.150000 x	6.000000 =	6.900000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743

			T.E =	25.765799
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	20.419486 =	5.104872

			T.E =	5.479872
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	20.419486 =	2.041949

			T.E =	2.791949
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
251		.100000 x	.695000 =	.069500

			T.E =	
7941	7941			
067		.040000 x	45.500000 =	1.820000
001		.100000 x	15.741598 =	1.574160

			T.E =	3.394160
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.741598 =	1.574160

			T.E =	9.124160