

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

2ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.023100
212	1.245400
213	1.949500
214	3.930000
221	.099900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.775000
232	1.900000
233	.570200
233.1	.570200
233.2	.603700
233.3	7.700000
234	.823000
234.1	.988500
234.2	.888000
234.3	.930000
235	.613000
236	.603000
237	1.110000
237.1	1.260000
241	7.050000
242	5.000000
243	2.100000
244	2.590000
251	290.000000
252	270.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.220000
361.1	12.320000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	15.940000
361.3	20.220000
361.4	
361.5	38.600000
361.6	51.610000
361.7	79.690000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	8.000000
372.2	12.580000
372.3	16.500000
372.4	25.550000
372.5	32.410000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.500000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.270000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	88.960000
376.10	487.600000
376.11	528.600000
376.12	88.960000
376.13	98.960000
376.14	109.782000
376.15	140.650000
376.16	176.880000
376.17	224.520000
376.18	302.640000
376.19	336.580000
376.2	98.960000
376.20	400.990000
376.21	487.600000
376.22	528.600000
376.3	109.780000
376.4	140.650000
376.5	176.880000
376.6	224.520000
376.7	302.840000
376.8	336.580000
376.9	400.990000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	108,702.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	73,850.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	128,861.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	147,712.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	24,668.000000
387.1	
387.2	
387.3	20,690.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	6,406.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	5,412.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	7,871.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	14,767.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.560000
396.12	3.680000
396.13	1.770000
396.14	38.800000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.320000
397.4	.165000
398.1	.225000
398.10	138.730000
398.11	136.770000
398.12	176.880000
398.13	9.400000
398.14	58.610000
398.15	75.690000
398.16	62.420000
398.17	93.000000
398.2	39.000000
398.3	47.000000
398.4	63.000000
398.5	5.780000

398.6	330.000000
398.7	1,360.000000
398.8	30.750000
398.9	128.000000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
413	4.400000
414	6.070000
415	8.530000
416	13.150000
417	130.670000
419	4.400000
420	94.500000
421	31.630000
428	425.280000
429	75.360000
450	81.440000
451	4.730000
452	100.100000
453	.000000
454	94.500000
455	30.380000
456	34.030000
457	444.570000
458	276.840000
459	409.940000
460	506.910000
461	232.170000
462	338.520000
463	42.540000
464	372.560000
465	99.670000
466	46.490000
467	338.520000
468	84.780000
469	84.780000
470	68.370000
471	59.250000
472	25.750000
473	16.560000
474	34.030000
475	1,913.860000
476	82.950000
477	6.750000
478	111.820000
479	179.890000
480	26.440000
481	789.180000

501	501				
401		1.000000 x	260.720000 =	260.720000	
211		50.000000 x	1.023100 =	51.155000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.930000 =	11.790000	

			ΑΘΡΟΙΣΜΑ =	544.757593	

			Η.Δ. =	599.233352	
502	502				
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.930000 =	27.510000	
211		80.000000 x	1.023100 =	81.848000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

			ΑΘΡΟΙΣΜΑ =	709.721612	

			Η.Δ. =	780.693773	
503	503				
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.930000 =	39.300000	
114		8.000000 x	23.886192 =	191.089536	
211		110.000000 x	1.023100 =	112.541000	
118		4.000000 x	10.001019 =	40.004076	

			ΑΘΡΟΙΣΜΑ =	808.214612	

			Η.Δ. =	889.036073	
504	504				
403		1.000000 x	100.390000 =	100.390000	
214		2.000000 x	3.930000 =	7.860000	
114		8.000000 x	23.886192 =	191.089536	
211		40.000000 x	1.023100 =	40.924000	

			ΑΘΡΟΙΣΜΑ =	340.263536	

			Η.Δ. =	374.289890	
505	505				
404		1.000000 x	206.630000 =	206.630000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		10.000000 x	3.930000 =	39.300000	
211		200.000000 x	1.023100 =	204.620000	

			ΑΘΡΟΙΣΜΑ =	721.647688	

			Η.Δ. =	793.812457	

506	506				
405		1.000000 x	200.790000 =	200.790000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		2.500000 x	5.000000 =	12.500000	
214		6.000000 x	3.930000 =	23.580000	
211		95.000000 x	1.023100 =	97.194500	

			ΑΘΡΟΙΣΜΑ =	605.162188	

			Η.Δ. =	665.678407	
507	507				
406		1.000000 x	311.770000 =	311.770000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		7.000000 x	5.000000 =	35.000000	
214		10.000000 x	3.930000 =	39.300000	
211		165.000000 x	1.023100 =	168.811500	

			ΑΘΡΟΙΣΜΑ =	825.979188	

			Η.Δ. =	908.577107	
508	508				
407		1.000000 x	53.630000 =	53.630000	
116		16.000000 x	20.419486 =	326.711776	
211		40.000000 x	1.023100 =	40.924000	
214		2.000000 x	3.930000 =	7.860000	
115		4.000000 x	21.778427 =	87.113708	
408		2.000000 x	4.400000 =	8.800000	

			ΑΘΡΟΙΣΜΑ =	525.039484	

			Η.Δ. =	577.543432	
509	509				
409		1.000000 x	122.460000 =	122.460000	
117		8.000000 x	16.777917 =	134.223336	
214		5.000000 x	3.930000 =	19.650000	
211		80.000000 x	1.023100 =	81.848000	

			ΑΘΡΟΙΣΜΑ =	358.181336	

			Η.Δ. =	393.999470	
510	510				
410		1.000000 x	113.190000 =	113.190000	
117		8.000000 x	16.777917 =	134.223336	
211		80.000000 x	1.023100 =	81.848000	
214		5.000000 x	3.930000 =	19.650000	

			ΑΘΡΟΙΣΜΑ =	348.911336	

			Η.Δ. =	383.802470	

511	511				
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	3.930000 =	3.930000	
112		30.000000 x	17.312112 =	519.363360	
115		4.000000 x	21.778427 =	87.113708	
212		17.000000 x	1.245400 =	21.171800	

			ΑΘΡΟΙΣΜΑ =	658.158868	

			Η.Δ. =	723.974755	
512	512				
412		1.000000 x	2.900000 =	2.900000	
214		1.000000 x	3.930000 =	3.930000	
115		2.000000 x	21.778427 =	43.556854	
112		2.000000 x	17.312112 =	34.624224	
211		10.000000 x	1.023100 =	10.231000	

			ΑΘΡΟΙΣΜΑ =	95.242078	

			Η.Δ. =	104.766286	
513	513				
413		1.000000 x	4.400000 =	4.400000	
211		15.000000 x	1.023100 =	15.346500	
115		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
214		1.500000 x	3.930000 =	5.895000	

			ΑΘΡΟΙΣΜΑ =	142.913117	

			Η.Δ. =	157.204429	
514	514				
414		1.000000 x	6.070000 =	6.070000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		2.000000 x	3.930000 =	7.860000	
211		21.000000 x	1.023100 =	21.485100	

			ΑΘΡΟΙΣΜΑ =	191.777256	

			Η.Δ. =	210.954982	
515	515				
415		1.000000 x	8.530000 =	8.530000	
112		6.000000 x	17.312112 =	103.872672	
115		5.000000 x	21.778427 =	108.892135	
214		2.500000 x	3.930000 =	9.825000	
211		27.000000 x	1.023100 =	27.623700	

			ΑΘΡΟΙΣΜΑ =	258.743507	

			Η.Δ. =	284.617858	

516	516				
416		1.000000 x	13.150000 =	13.150000	
115		6.000000 x	21.778427 =	130.670562	
112		8.000000 x	17.312112 =	138.496896	
214		3.500000 x	3.930000 =	13.755000	
211		33.000000 x	1.023100 =	33.762300	
			ΑΘΡΟΙΣΜΑ =	329.834758	
			Η.Δ. =	362.818234	
517	517				
406		1.000000 x	311.770000 =	311.770000	
406		.400000 x	311.770000 =	124.708000	
116		8.000000 x	20.419486 =	163.355888	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
113		2.000000 x	20.419486 =	40.838972	
112		16.000000 x	17.312112 =	276.993792	
111		16.000000 x	15.741598 =	251.865568	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	3.930000 =	31.440000	
211		240.000000 x	1.023100 =	245.544000	
407		2.000000 x	53.630000 =	107.260000	
			ΑΘΡΟΙΣΜΑ =	1,962.593172	
			Η.Δ. =	2,158.852489	
518	518				
417		1.000000 x	130.670000 =	130.670000	
118		8.000000 x	10.001019 =	80.008152	
112		8.000000 x	17.312112 =	138.496896	
212		5.000000 x	1.245400 =	6.227000	
214		12.000000 x	3.930000 =	47.160000	
114		8.000000 x	23.886192 =	191.089536	
211		180.000000 x	1.023100 =	184.158000	
			ΑΘΡΟΙΣΜΑ =	777.809584	
			Η.Δ. =	855.590542	
520	520				
419		1.000000 x	4.400000 =	4.400000	
211		80.000000 x	1.023100 =	81.848000	
212		2.000000 x	1.245400 =	2.490800	
118		4.000000 x	10.001019 =	40.004076	
115		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	3.930000 =	19.650000	
			ΑΘΡΟΙΣΜΑ =	391.868740	
			Η.Δ. =	431.055614	

521	521				
420		1.000000 x	94.500000 =	94.500000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.930000 =	11.790000	
211		40.000000 x	1.023100 =	40.924000	

		ΑΘΡΟΙΣΜΑ =		378.307612	

		H.Δ. =		416.138373	
522	522				
421		1.000000 x	31.630000 =	31.630000	
114		8.000000 x	23.886192 =	191.089536	
118		2.000000 x	10.001019 =	20.002038	
214		2.000000 x	3.930000 =	7.860000	
211		20.000000 x	1.023100 =	20.462000	

		ΑΘΡΟΙΣΜΑ =		271.043574	

		H.Δ. =		298.147931	
529	529				
429		1.000000 x	75.360000 =	75.360000	
211		70.000000 x	1.023100 =	71.617000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	3.930000 =	15.720000	

		ΑΘΡΟΙΣΜΑ =		393.790612	

		H.Δ. =		433.169673	
550	550				
450		1.000000 x	81.440000 =	81.440000	
451		4.000000 x	4.730000 =	18.920000	
116		32.000000 x	20.419486 =	653.423552	
115		4.000000 x	21.778427 =	87.113708	
214		4.000000 x	3.930000 =	15.720000	
211		90.000000 x	1.023100 =	92.079000	

		ΑΘΡΟΙΣΜΑ =		948.696260	

		H.Δ. =		1,043.565886	
551	551				
405		1.000000 x	200.790000 =	200.790000	
211		95.000000 x	1.023100 =	97.194500	
214		6.000000 x	3.930000 =	23.580000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
452		1.000000 x	100.100000 =	100.100000	

		ΑΘΡΟΙΣΜΑ =		692.762188	

		H.Δ. =		762.038407	

552	552				
453		1.000000 x	.000000 =	.000000	
115		8.000000 x	21.778427 =	174.227416	
214		1.000000 x	3.930000 =	3.930000	
211		18.000000 x	1.023100 =	18.415800	

		ΑΘΡΟΙΣΜΑ =		196.573216	

		H.Δ. =			
553	553				
454		1.000000 x	94.500000 =	94.500000	
214		4.000000 x	3.930000 =	15.720000	
211		100.000000 x	1.023100 =	102.310000	

		ΑΘΡΟΙΣΜΑ =		212.530000	

		H.Δ. =		233.783000	
554	554				
455		1.000000 x	30.380000 =	30.380000	

		ΑΘΡΟΙΣΜΑ =		30.380000	

		H.Δ. =		33.418000	
555	555				
456		1.000000 x	34.030000 =	34.030000	
212		17.000000 x	1.245400 =	21.171800	
112		32.000000 x	17.312112 =	553.987584	
115		4.000000 x	21.778427 =	87.113708	
214		1.000000 x	3.930000 =	3.930000	

		ΑΘΡΟΙΣΜΑ =		700.233092	

		H.Δ. =		770.256401	
556	556				
457		1.000000 x	444.570000 =	444.570000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
214		18.000000 x	3.930000 =	70.740000	
211		200.000000 x	1.023100 =	204.620000	

		ΑΘΡΟΙΣΜΑ =		991.027688	

		H.Δ. =		1,090.130457	
557	557				
458		1.000000 x	276.840000 =	276.840000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		11.000000 x	3.930000 =	43.230000	
211		130.000000 x	1.023100 =	133.003000	

		ΑΘΡΟΙΣΜΑ =		724.170688	

		H.Δ. =		796.587757	

558	558				
459		1.000000 x	409.940000 =	409.940000	
214		12.000000 x	3.930000 =	47.160000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		9.500000 x	5.000000 =	47.500000	
211		200.000000 x	1.023100 =	204.620000	
			ΑΘΡΟΙΣΜΑ =	980.317688	
			Η.Δ. =	1,078.349457	
559	559				
460		1.000000 x	506.910000 =	506.910000	
211		250.000000 x	1.023100 =	255.775000	
214		15.000000 x	3.930000 =	58.950000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		12.000000 x	5.000000 =	60.000000	
			ΑΘΡΟΙΣΜΑ =	1,152.732688	
			Η.Δ. =	1,268.005957	
560	560				
461		1.000000 x	232.170000 =	232.170000	
114		8.000000 x	23.886192 =	191.089536	
211		160.000000 x	1.023100 =	163.696000	
214		8.000000 x	3.930000 =	31.440000	
			ΑΘΡΟΙΣΜΑ =	618.395536	
			Η.Δ. =	680.235090	
561	561				
462		1.000000 x	338.520000 =	338.520000	
214		12.000000 x	3.930000 =	47.160000	
114		8.000000 x	23.886192 =	191.089536	
211		230.000000 x	1.023100 =	235.313000	
			ΑΘΡΟΙΣΜΑ =	812.082536	
			Η.Δ. =	893.290790	
562	562				
463		1.000000 x	42.540000 =	42.540000	
214		2.400000 x	3.930000 =	9.432000	
211		50.000000 x	1.023100 =	51.155000	
			ΑΘΡΟΙΣΜΑ =	103.127000	
			Η.Δ. =	113.439700	

563	563				
211.1		640.000000 x	.000000 =	.000000	
114		16.000000 x	23.886192 =	382.179072	
112		24.000000 x	17.312112 =	415.490688	
214		16.000000 x	3.930000 =	62.880000	
464		1.000000 x	372.560000 =	372.560000	

		ΑΘΡΟΙΣΜΑ =		1,233.109760	

		H.Δ. =			
564	564				
465		1.000000 x	99.670000 =	99.670000	
567		3.000000 x	380.161272 =	1,140.483816	
111		8.000000 x	15.741598 =	125.932784	
115		8.000000 x	21.778427 =	174.227416	
115		8.000000 x	21.778427 =	174.227416	

		ΑΘΡΟΙΣΜΑ =		1,714.541432	

		H.Δ. =		1,885.995575	
565	565				
450		3.000000 x	81.440000 =	244.320000	
465		1.000000 x	99.670000 =	99.670000	
115		8.000000 x	21.778427 =	174.227416	
115		12.000000 x	21.778427 =	261.341124	

		H.Δ. =		779.558540	
566	566				
211.1		680.000000 x	.000000 =	.000000	
466		1.000000 x	46.490000 =	46.490000	
112		1.000000 x	17.312112 =	17.312112	
115		2.000000 x	21.778427 =	43.556854	

		ΑΘΡΟΙΣΜΑ =		107.358966	

		H.Δ. =			
567	567				
450		1.000000 x	81.440000 =	81.440000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		4.000000 x	3.930000 =	15.720000	
211		90.000000 x	1.023100 =	92.079000	

		ΑΘΡΟΙΣΜΑ =		345.601156	

		H.Δ. =		380.161272	

568.1	568.1				
467		1.000000 x	338.520000 =	338.520000	
567		2.000000 x	380.161272 =	760.322544	
512		.240000 x	104.766286 =	25.143909	
510		.072000 x	383.802470 =	27.633778	
118		32.000000 x	10.001019 =	320.032608	
114		8.000000 x	23.886192 =	191.089536	
113		32.000000 x	20.419486 =	653.423552	
214		16.000000 x	3.930000 =	62.880000	

				AΘΡΟΙΣΜΑ =	2,379.045926

				H.Δ. =	2,616.950519
568.2	568.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.778427 =	174.227416	
467		1.000000 x	338.520000 =	338.520000	
114		8.000000 x	23.886192 =	191.089536	

				H.Δ. =	866.716952
569.1	569.1				
468		1.000000 x	84.780000 =	84.780000	
214		16.000000 x	3.930000 =	62.880000	
567		2.000000 x	380.161272 =	760.322544	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

				AΘΡΟΙΣΜΑ =	1,179.080232

				H.Δ. =	1,296.988255
569.2	569.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
468		1.000000 x	84.780000 =	84.780000	

				H.Δ. =	612.976952
570.1	570.1				
469		1.000000 x	84.780000 =	84.780000	
211		135.000000 x	1.023100 =	138.118500	
114		8.000000 x	23.886192 =	191.089536	
118		4.000000 x	10.001019 =	40.004076	
214		16.000000 x	3.930000 =	62.880000	

				AΘΡΟΙΣΜΑ =	516.872112

				H.Δ. =	568.559323

570.2	570.2				
469		1.000000 x	84.780000 =		84.780000
118		4.000000 x	10.001019 =		40.004076
				H.Δ. =	124.784076
571.1	571.1				
470		1.000000 x	68.370000 =		68.370000
114		8.000000 x	23.886192 =		191.089536
214		4.000000 x	3.930000 =		15.720000
211		114.000000 x	1.023100 =		116.633400
				AΘΡΟΙΣΜΑ =	391.812936
				H.Δ. =	430.994230
571.2	571.2				
470		1.000000 x	68.370000 =		68.370000
114		8.000000 x	23.886192 =		191.089536
				H.Δ. =	259.459536
572	572				
407		1.000000 x	53.630000 =		53.630000
471		1.000000 x	59.250000 =		59.250000
114		8.000000 x	23.886192 =		191.089536
214		8.000000 x	3.930000 =		31.440000
111		24.000000 x	15.741598 =		377.798352
211		54.000000 x	1.023100 =		55.247400
				AΘΡΟΙΣΜΑ =	768.455288
				H.Δ. =	845.300817
573	573				
407		1.000000 x	53.630000 =		53.630000
473		.250000 x	16.560000 =		4.140000
474		.250000 x	34.030000 =		8.507500
474		1.000000 x	34.030000 =		34.030000
473		1.000000 x	16.560000 =		16.560000
115		16.000000 x	21.778427 =		348.454832
111		24.000000 x	15.741598 =		377.798352
214		8.000000 x	3.930000 =		31.440000
211		54.000000 x	1.023100 =		55.247400
407		.250000 x	53.630000 =		13.407500
472		.250000 x	25.750000 =		6.437500
472		1.000000 x	25.750000 =		25.750000
				AΘΡΟΙΣΜΑ =	975.403084
				H.Δ. =	1,072.943392

574	574				
475		1.000000 x	1,913.860000 =		1,913.860000
214		30.000000 x	3.930000 =		117.900000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
111		16.000000 x	15.741598 =		251.865568
242		7.000000 x	5.000000 =		35.000000
211		590.000000 x	1.023100 =		603.629000
				ΑΘΡΟΙΣΜΑ =	3,193.352256
				H.Δ. =	3,512.687482
574.1	574.1				
475		1.000000 x	1,913.860000 =		1,913.860000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
				H.Δ. =	2,184.957688
575	575				
476		1.000000 x	82.950000 =		82.950000
214		23.000000 x	3.930000 =		90.390000
115		8.000000 x	21.778427 =		174.227416
211		470.000000 x	1.023100 =		480.857000
				ΑΘΡΟΙΣΜΑ =	828.424416
				H.Δ. =	911.266858
575.1	575.1				
476		1.000000 x	82.950000 =		82.950000
115		8.000000 x	21.778427 =		174.227416
				H.Δ. =	257.177416
576	576				
477		1.000000 x	6.750000 =		6.750000
				ΑΘΡΟΙΣΜΑ =	6.750000
				H.Δ. =	7.425000
576.1	576.1				
477		1.000000 x	6.750000 =		6.750000
				H.Δ. =	6.750000

577	577				
478		1.000000 x	111.820000 =	111.820000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
111		8.000000 x	15.741598 =	125.932784	
214		4.000000 x	3.930000 =	15.720000	
211		70.000000 x	1.023100 =	71.617000	

				ΑΘΡΟΙΣΜΑ =	606.187472

				Η.Δ. =	666.806219
577.1	577.1				
478		1.000000 x	111.820000 =	111.820000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

				Η.Δ. =	382.917688
578	578				
479		1.000000 x	179.890000 =	179.890000	
211		50.000000 x	1.023100 =	51.155000	
242		5.000000 x	5.000000 =	25.000000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	3.930000 =	19.650000	

				ΑΘΡΟΙΣΜΑ =	576.037060

				Η.Δ. =	633.640766
579	579				
480		1.000000 x	26.440000 =	26.440000	
212		28.000000 x	1.245400 =	34.871200	
117		8.000000 x	16.777917 =	134.223336	
214		1.000000 x	3.930000 =	3.930000	

				ΑΘΡΟΙΣΜΑ =	199.464536

				Η.Δ. =	219.410990
580	580				
481		1.000000 x	789.180000 =	789.180000	
211		168.000000 x	1.023100 =	171.880800	
242		2.000000 x	5.000000 =	10.000000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
111		16.000000 x	15.741598 =	251.865568	
214		8.000000 x	3.930000 =	31.440000	

				ΑΘΡΟΙΣΜΑ =	1,525.464056

				Η.Δ. =	1,678.010462

581	581			
481		1.000000 x	789.180000 =	789.180000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
			H.Δ. =	1,060.277688
7020.2	7020.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.150000 x	259.459536 =	38.918930
571.1		.350000 x	430.994230 =	150.847981
570.2		.350000 x	124.784076 =	43.674427
570.1		.150000 x	568.559323 =	85.283898
569.2		.670000 x	612.976952 =	410.694558
569.1		.330000 x	1,296.988255 =	428.006124
568.2		.550000 x	866.716952 =	476.694324
568.1		.450000 x	2,616.950519 =	1,177.627734
567		1.000000 x	380.161272 =	380.161272
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	3,481.197919
7021.2	7021.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.240000 x	259.459536 =	62.270289
571.1		.260000 x	430.994230 =	112.058500
570.2		.390000 x	124.784076 =	48.665790
570.1		.110000 x	568.559323 =	62.541526
569.2		.750000 x	612.976952 =	459.732714
116		8.000000 x	20.419486 =	163.355888
567		1.000000 x	380.161272 =	380.161272
568.1		.250000 x	2,616.950519 =	654.237630
569.1		.250000 x	1,296.988255 =	324.247064
568.2		.750000 x	866.716952 =	650.037714
			H.Δ. =	3,043.241169
7022.2	7022.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.310000 x	259.459536 =	80.432456
571.1		.190000 x	430.994230 =	81.888904
570.2		.420000 x	124.784076 =	52.409312
570.1		.080000 x	568.559323 =	45.484746
569.2		.820000 x	612.976952 =	502.641101
569.1		.180000 x	1,296.988255 =	233.457886
568.2		.850000 x	866.716952 =	736.709409
568.1		.150000 x	2,616.950519 =	392.542578
567		1.000000 x	380.161272 =	380.161272
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	2,795.016335

613	613				
111		.140000 x	15.741598 =	2.203824	
503		.000770 x	889.036073 =	.684558	
520		.003500 x	431.055614 =	1.508695	
504		.002800 x	374.289890 =	1.048012	

			B.T =	5.445088	
614	614				
112		.070000 x	17.312112 =	1.211848	
509		.004375 x	393.999470 =	1.723748	
518		.004375 x	855.590542 =	3.743209	
504		.002800 x	374.289890 =	1.048012	
503		.000700 x	889.036073 =	.622325	

			B.T =	8.349141	
621.1	621.1				
213		.100000 x	1.949500 =	.194950	
111		.560000 x	15.741598 =	8.815295	
504		.003500 x	374.289890 =	1.310015	
508		.003500 x	577.543432 =	2.021402	
116		.140000 x	20.419486 =	2.858728	

			B.T =	15.200390	
622	622				
213		.100000 x	1.949500 =	.194950	
116		.140000 x	20.419486 =	2.858728	
508		.003500 x	577.543432 =	2.021402	
504		.003500 x	374.289890 =	1.310015	
518		.004340 x	855.590542 =	3.713263	
509		.003500 x	393.999470 =	1.378998	
112		.070000 x	17.312112 =	1.211848	

			B.T =	12.689204	
6360.1 A1	6360.1 A1				
6304		9.800000 x	5.646099 =	55.331770	
6330		.038000 x	181.012507 =	6.878475	
6330		.190000 x	181.012507 =	34.392376	
6314		.382500 x	2.022410 =	.773572	
6314		7.650000 x	2.022410 =	15.471437	

			B.T =	112.847630	
6360.1 A2	6360.1 A2				
6304		.450000 x	5.646099 =	2.540745	
6310		2.142000 x	1.466538 =	3.141324	
6330		.013000 x	181.012507 =	2.353163	

			B.T =	8.035232	

6360.1 A3	6360.1 A3			
6304		.960000 x	5.646099 =	5.420255
6329.2		.037000 x	166.507722 =	6.160786
6310		1.974000 x	1.466538 =	2.894946

			B.T =	14.475987
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.646099 =	14.058787
6329.2		.109000 x	166.507722 =	18.149342

			B.T =	32.208128
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
113		2.975000 x	20.419486 =	60.747971
6069.1		.056400 x	11.358201 =	.640603
113		.425000 x	20.419486 =	8.678282

			B.T =	99.497445
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.646099 =	60.130954
6330		.041000 x	181.012507 =	7.421513
6330		.205000 x	181.012507 =	37.107564
6314		.392500 x	2.022410 =	.793796
6314		7.850000 x	2.022410 =	15.875919

			B.T =	121.329745
6360.2 A2	6360.2 A2			
6304		.750000 x	5.646099 =	4.234574
6330		.019000 x	181.012507 =	3.439238
6310		2.383500 x	1.466538 =	3.495493

			B.T =	11.169305
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.646099 =	6.436553
6310		2.341500 x	1.466538 =	3.433899
6329.2		.054000 x	166.507722 =	8.991417

			B.T =	18.861869
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.646099 =	15.809077
6329.2		.118000 x	166.507722 =	19.647911

			B.T =	35.456988

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
113		2.975000 x	20.419486 =	60.747971
6069.1		.059400 x	11.358201 =	.674677
113		.382500 x	20.419486 =	7.810453

			B.T =	113.378987
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.646099 =	78.480776
6314		11.150000 x	2.022410 =	22.549872
6330		.270000 x	181.012507 =	48.873377
6330		.054000 x	181.012507 =	9.774675
6314		.557500 x	2.022410 =	1.127494

			B.T =	160.806193
6360.3 A2	6360.3 A2			
6304		.940000 x	5.646099 =	5.307333
6310		3.360000 x	1.466538 =	4.927568
6330		.031000 x	181.012507 =	5.611388

			B.T =	15.846288
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.646099 =	10.332361
6329.2		.099000 x	166.507722 =	16.484264
6310		10.678500 x	1.466538 =	15.660426

			B.T =	42.477052
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.646099 =	19.309659
6329.2		.139000 x	166.507722 =	23.144573

			B.T =	42.454232
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
113		2.975000 x	20.419486 =	60.747971
6069.1		.073800 x	11.358201 =	.838235
113		.340000 x	20.419486 =	6.942625

			B.T =	156.820603

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.646099 =	91.749109
6330		.375000 x	181.012507 =	67.879690
6330		.075000 x	181.012507 =	13.575938
6314		17.700000 x	2.022410 =	35.796657
6314		.885000 x	2.022410 =	1.789833

			B.T =	210.791227
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.646099 =	5.984865
6330		.048000 x	181.012507 =	8.688600
6310		4.641000 x	1.466538 =	6.806203

			B.T =	21.479668
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.646099 =	12.816645
6329.2		.125000 x	166.507722 =	20.813465
6310		20.454000 x	1.466538 =	29.996568

			B.T =	63.626678
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.646099 =	15.809077
6329.2		.118000 x	166.507722 =	19.647911

			B.T =	35.456988
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
113		4.250000 x	20.419486 =	86.782816
113		.297500 x	20.419486 =	6.074797
6069.1		.091800 x	11.358201 =	1.042683

			B.T =	211.622657
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.646099 =	101.347477
6330		.088000 x	181.012507 =	15.929101
6330		.440000 x	181.012507 =	79.645503
6314		1.050000 x	2.022410 =	2.123531
6314		21.000000 x	2.022410 =	42.470610

			B.T =	241.516221
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.646099 =	6.888241
6310		6.048000 x	1.466538 =	8.869622
6330		.061000 x	181.012507 =	11.041763

			B.T =	26.799626

6360.5 A3	6360.5 A3			
6304		2.480000 x	5.646099 =	14.002326
6310		22.291500 x	1.466538 =	32.691332
6329.2		.144000 x	166.507722 =	23.977112

			B.T =	70.670769
6360.5 A4	6360.5 A4			
6304		3.200000 x	5.646099 =	18.067517
6329.2		.112000 x	166.507722 =	18.648865

			B.T =	36.716382
6360.5 A5	6360.5 A5			
112		9.350000 x	17.312112 =	161.868247
113		5.950000 x	20.419486 =	121.495942
6069.1		.090600 x	11.358201 =	1.029053
113		.255000 x	20.419486 =	5.206969

			B.T =	289.600211
6360.6 A1	6360.6 A1			
6304		20.350000 x	5.646099 =	114.898115
6314		24.900000 x	2.022410 =	50.358009
6330		.580000 x	181.012507 =	104.987254
6330		.116000 x	181.012507 =	20.997451
6314		1.245000 x	2.022410 =	2.517900

			B.T =	293.758729
6360.6 A2	6360.6 A2			
6304		1.530000 x	5.646099 =	8.638531
6330		.092000 x	181.012507 =	16.653151
6310		10.206000 x	1.466538 =	14.967487

			B.T =	40.259169
6360.6 A3	6360.6 A3			
6304		2.670000 x	5.646099 =	15.075084
6329.2		.181000 x	166.507722 =	30.137898
6310		25.798500 x	1.466538 =	37.834481

			B.T =	83.047463
6360.6 A4	6360.6 A4			
6304		2.800000 x	5.646099 =	15.809077
6329.2		.118000 x	166.507722 =	19.647911

			B.T =	35.456988

6360.6 A5

6360.6 A5

112	12.750000 x	17.312112 =	220.729428
113	7.650000 x	20.419486 =	156.209068
6069.1	.120000 x	11.358201 =	1.362984
113	.212500 x	20.419486 =	4.339141

B.T = 382.640621

641

641

231	.200000 x	.775000 =	.155000
111	.170000 x	15.741598 =	2.676072
251	.001500 x	290.000000 =	.435000
113	.127500 x	20.419486 =	2.603484
252	.002500 x	270.000000 =	.675000

B.T = 6.544556

651

651

221	150.000000 x	.099900 =	14.985000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	393.999470 =	3.717385
509	.003060 x	393.999470 =	1.205638
T 630	.600000 x	1.781027 =	1.068616
T 625	.850000 x	21.257285 =	18.068692
511	.042500 x	723.974755 =	30.768927
112	.425000 x	17.312112 =	7.357648
111	1.275000 x	15.741598 =	20.070537

B.T = 105.642444

652

652

221	650.000000 x	.099900 =	64.935000
T 630	.320000 x	1.781027 =	.569929
T 625	1.000000 x	21.257285 =	21.257285
511	.042500 x	723.974755 =	30.768927
509	.001632 x	393.999470 =	.643007
509	.009435 x	393.999470 =	3.717385
111	1.275000 x	15.741598 =	20.070537
112	.425000 x	17.312112 =	7.357648

B.T = 149.319718

652.1

652.1

221	450.000000 x	.099900 =	44.955000
111	1.275000 x	15.741598 =	20.070537
509	.010001 x	393.999470 =	3.940389
T 630	.320000 x	1.781027 =	.569929
T 625	1.060000 x	21.257285 =	22.532722
511	.042500 x	723.974755 =	30.768927
510	.001632 x	383.802470 =	.626366
112	.425000 x	17.312112 =	7.357648

B.T = 130.821517

652.2	652.2			
221		900.000000 x	.099900 =	89.910000
509		.007548 x	393.999470 =	2.973908
T 630		.320000 x	1.781027 =	.569929
T 625		.800000 x	21.257285 =	17.005828
511		.042500 x	723.974755 =	30.768927
510		.001632 x	383.802470 =	.626366
112		.425000 x	17.312112 =	7.357648
111		1.275000 x	15.741598 =	20.070537
			B.T =	169.283142
700	700			
397.4		4.000000 x	.165000 =	.660000
397.5		2.150000 x	.000000 =	.000000
324		7.650000 x	.580000 =	4.437000
221		13.000000 x	.099900 =	1.298700
113		.935000 x	20.419486 =	19.092219
			B.T =	
7001 A	7001 A			
502		.000365 x	780.693773 =	.284953
557		.001094 x	796.587757 =	.871467
			AΘΡΟΙΣΜΑ =	1.156420
	B.T =	.200000 x	1.156420 =	.231284
7001 B	7001 B			
558		.000700 x	1,078.349457 =	.754845
			B.T =	.754845
7001 E	7001 E			
503		.000875 x	889.036073 =	.777907
554		.000875 x	33.418000 =	.029241
			B.T =	.807147
7001 Γ	7001 Γ			
501		.000700 x	599.233352 =	.419463
502		.000700 x	780.693773 =	.546486
			B.T =	.965949

7001 Δ	7001 Δ			
502		.000292 x	780.693773 =	.227963
510		.000292 x	383.802470 =	.112070
X 630.1		.060000 x	1.611970 =	.096718
X 630		.060000 x	1.466728 =	.088004

			AΘΡΟΙΣΜΑ =	.524755
	B.T =	.600000 x	.524755 =	.314853

7003 Α	7003 Α			
502		.000365 x	780.693773 =	.284953
557		.001094 x	796.587757 =	.871467

			AΘΡΟΙΣΜΑ =	1.156420
	B.T =	.100000 x	1.156420 =	.115642

7003 Β	7003 Β			
559		.000464 x	1,268.005957 =	.588355

			B.T =	.588355
7003 Γ	7003 Γ			
502		.000700 x	780.693773 =	.546486

			B.T =	.546486
7003 Δ	7003 Δ			
502		.000875 x	780.693773 =	.683107
562		.000875 x	113.439700 =	.099260

			B.T =	.782367
7005 Α	7005 Α			
502		.000365 x	780.693773 =	.284953
557		.001094 x	796.587757 =	.871467

			AΘΡΟΙΣΜΑ =	1.156420
	B.T =	.100000 x	1.156420 =	.115642

7005 Β	7005 Β			
559		.000812 x	1,268.005957 =	1.029621

			B.T =	1.029621
7005 Ε	7005 Ε			
502		.000875 x	780.693773 =	.683107
562		.000875 x	113.439700 =	.099260

			B.T =	.782367

7005 Γ	7005 Γ			
559		.000232 x	1,268.005957 =	.294177

			B.T =	.294177
7005 Δ	7005 Δ			
502		.000700 x	780.693773 =	.546486

			B.T =	.546486
7010 Α	7010 Α			
558		.000315 x	1,078.349457 =	.339680

			B.T =	.339680
7010 Β	7010 Β			
558		.000473 x	1,078.349457 =	.510059

			B.T =	.510059
7010 Ε	7010 Ε			
503		.000875 x	889.036073 =	.777907
553		.000875 x	233.783000 =	.204560

			B.T =	.982467
7010 Γ	7010 Γ			
502		.000700 x	780.693773 =	.546486

			B.T =	.546486
7010 Δ	7010 Δ			
502		.000292 x	780.693773 =	.227963
X 630		.060000 x	1.466728 =	.088004
X 630.1		.060000 x	1.611970 =	.096718
510		.000292 x	383.802470 =	.112070

			AΘΡΟΙΣΜΑ =	.524755
	B.T =	.600000 x	.524755 =	.314853

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.830000 x	18.130101 =	15.047984
T 617		.500000 x	6.258384 =	3.129192
509		.007831 x	393.999470 =	3.085410
509		.004718 x	393.999470 =	1.858889
223		350.000000 x	.119300 =	41.755000

			B.T =	78.201080

7016.2	7016.2			
570.1		.586500 x	568.559323 =	333.460043
570.2		1.113500 x	124.784076 =	138.947069
571.2		1.113500 x	259.459536 =	288.908193
571.1		.586500 x	430.994230 =	252.778116

			ΑΘΡΟΙΣΜΑ =	1,014.093421
	B.T =	.025000 x	1,014.093421 =	25.352336

7016.3	7016.3			
564		.212500 x	1,885.995575 =	400.774060
565		.637500 x	779.558540 =	496.968569

			ΑΘΡΟΙΣΜΑ =	897.742629
	B.T =	.025000 x	897.742629 =	22.443566

7016.4	7016.4			
7016.1		1.000000 x	78.201080 =	78.201080
7016.2		1.000000 x	25.352336 =	25.352336
7016.3		1.000000 x	22.443566 =	22.443566

			B.T =	125.996982
7016.5	7016.5			
7016.4		.200000 x	125.996982 =	25.199396

			B.T =	25.199396
7016.6	7016.6			
7016.4		.250000 x	125.996982 =	31.499246
7016.5		.250000 x	25.199396 =	6.299849

			B.T =	37.799095
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379

			B.T =	104.139379

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.830000 x	18.130101 =	15.047984
T 617		.500000 x	6.258384 =	3.129192
509		.007831 x	393.999470 =	3.085410
509		.004718 x	393.999470 =	1.858889
223		350.000000 x	.119300 =	41.755000

			B.T =	78.201080
7017.2	7017.2			
564		.425000 x	1,885.995575 =	801.548119
565		.425000 x	779.558540 =	331.312380

			ΑΘΡΟΙΣΜΑ =	1,132.860499
	B.T =	.012500 x	1,132.860499 =	14.160756

7017.3	7017.3			
7017.1		1.000000 x	78.201080 =	78.201080
7017.2		1.000000 x	14.160756 =	14.160756

			B.T =	92.361836
7017.4	7017.4			
7017.3		.200000 x	92.361836 =	18.472367

			B.T =	18.472367
7017.5	7017.5			
7017.3		.300000 x	92.361836 =	27.708551
7017.4		.300000 x	18.472367 =	5.541710

			B.T =	33.250261
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689

			B.T =	52.069689

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
509		.004718 x	393.999470 =	1.858889
509		.007548 x	393.999470 =	2.973908
223		350.000000 x	.119300 =	41.755000

			B.T =	78.555126
7019 A2	7019 A2			
555		.012143 x	770.256401 =	9.353223

			B.T =	9.353223
7019 A3	7019 A3			
570.1		.850000 x	568.559323 =	483.275425
571.1		.850000 x	430.994230 =	366.345096
571.2		.850000 x	259.459536 =	220.540606
570.2		.850000 x	124.784076 =	106.066465

			ΑΘΡΟΙΣΜΑ =	1,176.227590
	B.T =	.014286 x	1,176.227590 =	16.803587

7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563

			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	78.555126 =	78.555126
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A2		1.000000 x	9.353223 =	9.353223
7019 A3		1.000000 x	16.803587 =	16.803587
7019 A5		1.000000 x	17.356563 =	17.356563

			B.T =	191.305953
7019 A7	7019 A7			
7019 A6		.100000 x	191.305953 =	19.130595

			B.T =	19.130595

710	710			
397.3		.006660 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
113		.170000 x	20.419486 =	3.471313
252		.001000 x	270.000000 =	.270000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	374.289890 =	1.880807
509		.003750 x	393.999470 =	1.477498

			B.T =	3.358305
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
520		.005270 x	431.055614 =	2.271663
504		.004250 x	374.289890 =	1.590732
503		.001190 x	889.036073 =	1.057953

			B.T =	6.258384
T 621	T 621			
213		.100000 x	1.949500 =	.194950
508		.004250 x	577.543432 =	2.454560
116		.170000 x	20.419486 =	3.471313
111		.680000 x	15.741598 =	10.704287

			B.T =	16.825109
T 623	T 623			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
509		.004250 x	393.999470 =	1.674498
518		.008500 x	855.590542 =	7.272520
508		.004250 x	577.543432 =	2.454560
504		.004250 x	374.289890 =	1.590732
116		.170000 x	20.419486 =	3.471313

			B.T =	18.130101

T 625	T 625			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
116		.170000 x	20.419486 =	3.471313
518		.012155 x	855.590542 =	10.399703
509		.004250 x	393.999470 =	1.674498
508		.004250 x	577.543432 =	2.454560
504		.004250 x	374.289890 =	1.590732

			B.T =	21.257285
T 630	T 630			
512		.017000 x	104.766286 =	1.781027

			B.T =	1.781027
T 630.1	T 630.1			
510		.005100 x	383.802470 =	1.957393

			B.T =	1.957393
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678

			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
503		.000980 x	889.036073 =	.871255
520		.004340 x	431.055614 =	1.870781
504		.003500 x	374.289890 =	1.310015

			B.T =	5.153963
X 621	X 621			
213		.100000 x	1.949500 =	.194950
508		.003500 x	577.543432 =	2.021402
116		.140000 x	20.419486 =	2.858728
111		.560000 x	15.741598 =	8.815295

			B.T =	13.890375
X 623	X 623			
213		.100000 x	1.949500 =	.194950
508		.003500 x	577.543432 =	2.021402
518		.007000 x	855.590542 =	5.989134
509		.003500 x	393.999470 =	1.378998
504		.003500 x	374.289890 =	1.310015
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	14.965074

X 625	X 625			
213		.100000 x	1.949500 =	.194950
518		.010010 x	855.590542 =	8.564461
509		.003500 x	393.999470 =	1.378998
508		.003500 x	577.543432 =	2.021402
504		.003500 x	374.289890 =	1.310015
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	17.540402
X 630	X 630			
512		.014000 x	104.766286 =	1.466728

			B.T =	1.466728
X 630.1	X 630.1			
510		.004200 x	383.802470 =	1.611970

			B.T =	1.611970
2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	393.999470 =	1.858889
T 623		.800000 x	18.130101 =	14.504081
511		.034000 x	723.974755 =	24.615142
509		.007548 x	393.999470 =	2.973908
509		.001275 x	393.999470 =	.502349
T 625		.500000 x	21.257285 =	10.628643
641		3.000000 x	6.544556 =	19.633668
T 630		.250000 x	1.781027 =	.445257

			T.E =	153.503851
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	393.999470 =	7.635710

			T.E =	74.537501
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	393.999470 =	3.181546

			T.E =	43.322621
6051	6051			
502		.000175 x	780.693773 =	.136621

			T.E =	.136621

6052	6052			
501		.000117 x	599.233352 =	.070110
502		.000088 x	780.693773 =	.068701
521		.000088 x	416.138373 =	.036620

			T.E =	.175432
6053	6053			
502		.000318 x	780.693773 =	.248261
507		.001000 x	908.577107 =	.908577

			T.E =	1.156838
6054	6054			
112		.004900 x	17.312112 =	.084829
509		.002975 x	393.999470 =	1.172148
507		.001077 x	908.577107 =	.978538

			T.E =	2.235515
6055	6055			
213		.400000 x	1.949500 =	.779800
503		.001167 x	889.036073 =	1.037505
508		.007000 x	577.543432 =	4.042804
504		.001400 x	374.289890 =	.524006
112		.490000 x	17.312112 =	8.482935
116		.280000 x	20.419486 =	5.717456

			T.E =	20.584506
6056	6056			
507		.001750 x	908.577107 =	1.590010

			T.E =	1.590010
6057	6057			
506		.087500 x	665.678407 =	58.246861

			T.E =	58.246861
6058	6058			
507		.087500 x	908.577107 =	79.500497

			T.E =	79.500497
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
507		.001077 x	908.577107 =	.978538
509		.002975 x	393.999470 =	1.172148
501		.000583 x	599.233352 =	.349353
502		.001400 x	780.693773 =	1.092971

			T.E =	3.714195
6062	6062			
213		.400000 x	1.949500 =	.779800
509		.002800 x	393.999470 =	1.103199
508		.002800 x	577.543432 =	1.617122
507		.001400 x	908.577107 =	1.272008
502		.002000 x	780.693773 =	1.561388
116		.175000 x	20.419486 =	3.573410
112		.175000 x	17.312112 =	3.029620

			T.E =	12.936545
6063	6063			
112		.700000 x	17.312112 =	12.118478
112		.070000 x	17.312112 =	1.211848
509		.003641 x	393.999470 =	1.434552
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696

			T.E =	18.400422
6064	6064			
112		.140000 x	17.312112 =	2.423696
509		.003641 x	393.999470 =	1.434552
507		.014000 x	908.577107 =	12.720079
112		.070000 x	17.312112 =	1.211848

			T.E =	17.790175
6065	6065			
506		.002800 x	665.678407 =	1.863900
506		.002100 x	665.678407 =	1.397925

			T.E =	3.261824

6066	6066			
111		.070000 x	15.741598 =	1.101912
502		.000700 x	780.693773 =	.546486

			T.E =	1.648398
6067	6067			
111		.980000 x	15.741598 =	15.426766
X 630		.100000 x	1.466728 =	.146673
X 630.1		.100000 x	1.611970 =	.161197

			T.E =	15.734636
6068	6068			
111		.560000 x	15.741598 =	8.815295
622		1.351351 x	12.689204 =	17.147569
X 630.1		.200000 x	1.611970 =	.322394
X 630		.200000 x	1.466728 =	.293346
112		.560000 x	17.312112 =	9.694783
509		.016497 x	393.999470 =	6.499809

			T.E =	42.773195
6068.1	6068.1			
111		.560000 x	15.741598 =	8.815295
X 630.1		.200000 x	1.611970 =	.322394
X 630		.200000 x	1.466728 =	.293346
614		1.351351 x	8.349141 =	11.282620
509		.016497 x	393.999470 =	6.499809
112		.560000 x	17.312112 =	9.694783

			T.E =	36.908246
6069	6069			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	393.999470 =	4.734692
X 625		1.050000 x	17.540402 =	18.417422

			T.E =	24.363962
6069.1	6069.1			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	393.999470 =	4.734692
X 617		1.050000 x	5.153963 =	5.411661

			T.E =	11.358201
6070	6070			
501		.000467 x	599.233352 =	.279842

			T.E =	.279842

6071	6071			
504		.002333 x	374.289890 =	.873218
509		.002975 x	393.999470 =	1.172148

			T.E =	2.045367
6072	6072			
504		.003500 x	374.289890 =	1.310015
509		.002800 x	393.999470 =	1.103199

			T.E =	2.413213
6073	6073			
509		.000833 x	393.999470 =	.328202

			T.E =	.328202
6074	6074			
509		.000784 x	393.999470 =	.308896

			T.E =	.308896
6075	6075			
509		.001096 x	393.999470 =	.431823

			T.E =	.431823
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	889.036073 =	.622325
509		.003914 x	393.999470 =	1.542114
507		.000840 x	908.577107 =	.763205

			T.E =	3.012473
6077	6077			
503		.001400 x	889.036073 =	1.244651

			T.E =	1.244651
6078	6078			
112		.004900 x	17.312112 =	.084829
505		.001400 x	793.812457 =	1.111337
501		.000056 x	599.233352 =	.033557
503		.000350 x	889.036073 =	.311163

			T.E =	1.540886

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
501		.000056 x	599.233352 =	.033557
503		.000350 x	889.036073 =	.311163
556		.001400 x	1,090.130457 =	1.526183

			T.E =	1.955732
6079	6079			
112		.014000 x	17.312112 =	.242370
501		.000700 x	599.233352 =	.419463
529		.000980 x	433.169673 =	.424506
X 630		.150000 x	1.466728 =	.220009
509		.000630 x	393.999470 =	.248220
502		.000350 x	780.693773 =	.273243

			T.E =	1.827811
6080	6080			
112		.014000 x	17.312112 =	.242370
X 630.1		.100000 x	1.611970 =	.161197
X 630		.100000 x	1.466728 =	.146673
529		.000700 x	433.169673 =	.303219
502		.000292 x	780.693773 =	.227963
501		.000583 x	599.233352 =	.349353

			T.E =	1.430774
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
112		.280000 x	17.312112 =	4.847391
112		.420000 x	17.312112 =	7.271087
506		.007000 x	665.678407 =	4.659749

			T.E =	23.389698
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
112		.070000 x	17.312112 =	1.211848
6081.1		1.000000 x	23.389698 =	23.389698

			T.E =	35.620664
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
6081.1		1.000000 x	23.389698 =	23.389698
112		.140000 x	17.312112 =	2.423696

			T.E =	47.851631

6081.4	6081.4			
111		2.100000 x	15.741598 =	33.057356
6081.1		1.000000 x	23.389698 =	23.389698
112		.210000 x	17.312112 =	3.635544

			T.E =	60.082597
6082.1	6082.1			
213		.400000 x	1.949500 =	.779800
111		1.400000 x	15.741598 =	22.038237
116		.700000 x	20.419486 =	14.293640
508		.070000 x	577.543432 =	40.428040
116		1.400000 x	20.419486 =	28.587280

			T.E =	106.126998
6082.2	6082.2			
111		.700000 x	15.741598 =	11.019119
6082.1		1.000000 x	106.126998 =	106.126998
112		.140000 x	17.312112 =	2.423696

			T.E =	119.569812
6082.3	6082.3			
111		1.400000 x	15.741598 =	22.038237
6082.1		1.000000 x	106.126998 =	106.126998
112		.280000 x	17.312112 =	4.847391

			T.E =	133.012627
6082.4	6082.4			
111		2.100000 x	15.741598 =	33.057356
112		.420000 x	17.312112 =	7.271087
6082.1		1.000000 x	106.126998 =	106.126998

			T.E =	146.455441
6083.1	6083.1			
111		.280000 x	15.741598 =	4.407647
112		.280000 x	17.312112 =	4.847391
506		.005833 x	665.678407 =	3.882902
112		.140000 x	17.312112 =	2.423696

			T.E =	15.561637
6083.2	6083.2			
111		.560000 x	15.741598 =	8.815295
6083.1		1.000000 x	15.561637 =	15.561637
112		.070000 x	17.312112 =	1.211848

			T.E =	25.588780

6083.3	6083.3			
111		1.120000 x	15.741598 =	17.630590
112		.140000 x	17.312112 =	2.423696
6083.1		1.000000 x	15.561637 =	15.561637

			T.E =	35.615922
6083.4	6083.4			
111		1.680000 x	15.741598 =	26.445885
112		.210000 x	17.312112 =	3.635544
6083.1		1.000000 x	15.561637 =	15.561637

			T.E =	45.643065
6084.1	6084.1			
213		.400000 x	1.949500 =	.779800
111		1.470000 x	15.741598 =	23.140149
116		.700000 x	20.419486 =	14.293640
508		.035000 x	577.543432 =	20.214020
116		1.050000 x	20.419486 =	21.440460

			T.E =	79.868070
6084.2	6084.2			
111		.560000 x	15.741598 =	8.815295
112		.105000 x	17.312112 =	1.817772
6084.1		1.000000 x	79.868070 =	79.868070

			T.E =	90.501137
6084.3	6084.3			
111		1.120000 x	15.741598 =	17.630590
112		.210000 x	17.312112 =	3.635544
6084.1		1.000000 x	79.868070 =	79.868070

			T.E =	101.134203
6084.4	6084.4			
111		1.680000 x	15.741598 =	26.445885
6084.1		1.000000 x	79.868070 =	79.868070
112		.315000 x	17.312112 =	5.453315

			T.E =	111.767270
6085.1	6085.1			
111		.140000 x	15.741598 =	2.203824
506		.004666 x	665.678407 =	3.106055
502		.001400 x	780.693773 =	1.092971
112		.140000 x	17.312112 =	2.423696

			T.E =	8.826546

6085.2	6085.2			
111		.350000 x	15.741598 =	5.509559
112		.070000 x	17.312112 =	1.211848
6085.1		1.000000 x	8.826546 =	8.826546

			T.E =	15.547953
6085.3	6085.3			
111		.700000 x	15.741598 =	11.019119
112		.140000 x	17.312112 =	2.423696
6085.1		1.000000 x	8.826546 =	8.826546

			T.E =	22.269360
6085.4	6085.4			
111		1.050000 x	15.741598 =	16.528678
112		.210000 x	17.312112 =	3.635544
6085.1		1.000000 x	8.826546 =	8.826546

			T.E =	28.990767
6086.1	6086.1			
213		.400000 x	1.949500 =	.779800
508		.008750 x	577.543432 =	5.053505
111		1.120000 x	15.741598 =	17.630590
116		.490000 x	20.419486 =	10.005548
116		.280000 x	20.419486 =	5.717456

			T.E =	39.186899
6086.2	6086.2			
111		.350000 x	15.741598 =	5.509559
112		.105000 x	17.312112 =	1.817772
6086.1		1.000000 x	39.186899 =	39.186899

			T.E =	46.514230
6086.3	6086.3			
111		.700000 x	15.741598 =	11.019119
6086.1		1.000000 x	39.186899 =	39.186899
112		.210000 x	17.312112 =	3.635544

			T.E =	53.841561
6086.4	6086.4			
111		1.050000 x	15.741598 =	16.528678
6086.1		1.000000 x	39.186899 =	39.186899
112		.315000 x	17.312112 =	5.453315

			T.E =	61.168892

6087	6087				
252		.001000 x	270.000000 =		.270000
113		.210000 x	20.419486 =		4.288092
112		.350000 x	17.312112 =		6.059239
111		.210000 x	15.741598 =		3.305736

			T.E =		13.923067
6088	6088				
6081.1		1.000000 x	23.389698 =		23.389698
6081.1		.900000 x	23.389698 =		21.050728

			T.E =		44.440426
6089	6089				
6082.1		1.000000 x	106.126998 =		106.126998
6082.1		.900000 x	106.126998 =		95.514298

			T.E =		201.641296
6090	6090				
6083.1		1.000000 x	15.561637 =		15.561637
6083.1		1.300000 x	15.561637 =		20.230128

			T.E =		35.791765
6091	6091				
6084.1		1.000000 x	79.868070 =		79.868070
6084.1		1.300000 x	79.868070 =		103.828491

			T.E =		183.696561
6100	6100				
231		.200000 x	.775000 =		.155000
111		.175000 x	15.741598 =		2.754780
251		.002000 x	290.000000 =		.580000
113		.105000 x	20.419486 =		2.144046
252.1		.002000 x	.000000 =		.000000

			T.E =		
6101	6101				
231		15.000000 x	.775000 =		11.625000
252		.018000 x	270.000000 =		4.860000
113		3.500000 x	20.419486 =		71.468201
112		3.500000 x	17.312112 =		60.592392
252.1		.020000 x	.000000 =		.000000
251		.068000 x	290.000000 =		19.720000

			T.E =		

6102	6102			
244		1.000000 x	2.590000 =	2.590000
112		.002100 x	17.312112 =	.036355
506		.000070 x	665.678407 =	.046597
506		.000070 x	665.678407 =	.046597
509		.000051 x	393.999470 =	.020094
112		.001400 x	17.312112 =	.024237

			T.E =	2.763881
6103	6103			
244		.125000 x	2.590000 =	.323750
112		.002800 x	17.312112 =	.048474
509		.000102 x	393.999470 =	.040188
506		.000140 x	665.678407 =	.093195
506		.000140 x	665.678407 =	.093195
112		.004200 x	17.312112 =	.072711

			T.E =	.671513
6104	6104			
236		3.000000 x	.603000 =	1.809000
111		.280000 x	15.741598 =	4.407647
517		.017500 x	2,158.852489 =	37.779919
113		.280000 x	20.419486 =	5.717456

			T.E =	49.714022
6105	6105			
111		.210000 x	15.741598 =	3.305736
517		.014000 x	2,158.852489 =	30.223935
113		.140000 x	20.419486 =	2.858728

			T.E =	36.388398
6106	6106			
512		.087500 x	104.766286 =	9.167050

			T.E =	9.167050
6107	6107			
513		.087500 x	157.204429 =	13.755388

			T.E =	13.755388
6108	6108			
514		.087500 x	210.954982 =	18.458561

			T.E =	18.458561

6109	6109			
515		.087500 x	284.617858 =	24.904063

			T.E =	24.904063
6110	6110			
516		.087500 x	362.818234 =	31.746595

			T.E =	31.746595
6120	6120			
112		.004200 x	17.312112 =	.072711
501		.000070 x	599.233352 =	.041946
502		.001750 x	780.693773 =	1.366214

			T.E =	1.480871
6121	6121			
112		.004200 x	17.312112 =	.072711
501		.000049 x	599.233352 =	.029362
509		.003113 x	393.999470 =	1.226520
507		.000875 x	908.577107 =	.795005
505		.000420 x	793.812457 =	.333401
502		.000315 x	780.693773 =	.245919

			T.E =	2.702918
6151	6151			
243		1.020000 x	2.100000 =	2.142000
243		.080000 x	2.100000 =	.168000

			T.E =	2.310000
6152	6152			
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	3.207186
6153	6153			
111		.425000 x	15.741598 =	6.690179
112		.425000 x	17.312112 =	7.357648
509		.003570 x	393.999470 =	1.406578
T 611		1.050000 x	20.070537 =	21.074064

			T.E =	36.528469

6154	6154				
111		.425000 x	15.741598 =	6.690179	
112		.425000 x	17.312112 =	7.357648	
T 621		1.050000 x	16.825109 =	17.666364	
509		.003570 x	393.999470 =	1.406578	
			T.E =	33.120769	
6155	6155				
111		.680000 x	15.741598 =	10.704287	
652		.100000 x	149.319718 =	14.931972	
113		1.275000 x	20.419486 =	26.034845	
T 621		.350000 x	16.825109 =	5.888788	
509		.003220 x	393.999470 =	1.268678	
			T.E =	58.828570	
6156	6156				
251		.000500 x	290.000000 =	.145000	
652		.010000 x	149.319718 =	1.493197	
113		.680000 x	20.419486 =	13.885250	
112		.425000 x	17.312112 =	7.357648	
			T.E =	22.881095	
6157	6157				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	393.999470 =	1.158358	
112		.420000 x	17.312112 =	7.271087	
X 621		1.050000 x	13.890375 =	14.584894	
			T.E =	29.625810	
6157.1	6157.1				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	393.999470 =	1.158358	
X 611		1.050000 x	16.528678 =	17.355112	
112		.420000 x	17.312112 =	7.271087	
			T.E =	32.396029	
6158	6158				
111		.560000 x	15.741598 =	8.815295	
621.1		1.050000 x	15.200390 =	15.960410	
509		.002940 x	393.999470 =	1.158358	
504		.001400 x	374.289890 =	.524006	
			T.E =	26.458069	

6201.1	6201.1			
261.1		1.000000 x	13.500000 =	13.500000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	23.191284
6201.2	6201.2			
261		1.000000 x	15.100000 =	15.100000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	24.791284
6201.3	6201.3			
261.2		1.000000 x	20.700000 =	20.700000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	30.391284
6201.4	6201.4			
262		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6201.5	6201.5			
263		1.000000 x	32.400000 =	32.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	58.797781
6201.6	6201.6			
263.2		1.000000 x	46.700000 =	46.700000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	73.097781
6201.7	6201.7			
264		1.000000 x	64.100000 =	64.100000
113		.637500 x	20.419486 =	13.017422
111		.850000 x	15.741598 =	13.380358

			T.E =	90.497781

6202.1	6202.1				
281.1		1.000000 x	17.600000 =	17.600000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	27.291284	
6202.2	6202.2				
281		1.000000 x	21.300000 =	21.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	30.991284	
6202.3	6202.3				
281.2		1.000000 x	26.300000 =	26.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	35.991284	
6202.4	6202.4				
282		1.000000 x	30.000000 =	30.000000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	39.691284	
6202.5	6202.5				
283		1.000000 x	36.300000 =	36.300000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	62.697781	
6202.6	6202.6				
283.1		1.000000 x	55.500000 =	55.500000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	81.897781	
6202.7	6202.7				
284		1.000000 x	75.400000 =	75.400000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	101.797781	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.255000 x	15.741598 =	4.014107

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	17.540402 =	12.278281
X 623		.400000 x	14.965074 =	5.986030
509		.005439 x	393.999470 =	2.142963
509		.003108 x	393.999470 =	1.224550
112		.420000 x	17.312112 =	7.271087

			T.E =	32.208647
6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
509		.008702 x	393.999470 =	3.428583
613		1.050000 x	5.445088 =	5.717342

			T.E =	19.722748

6205	6205				
111		.210000 x	15.741598 =	3.305736	
112		.070000 x	17.312112 =	1.211848	
509		.002800 x	393.999470 =	1.103199	
613		1.000000 x	5.445088 =	5.445088	

			T.E =	11.065870	
6251	6251				
509		.002800 x	393.999470 =	1.103199	
613		1.000000 x	5.445088 =	5.445088	

			T.E =	6.548287	
6252	6252				
509		.000784 x	393.999470 =	.308896	

			T.E =	.308896	
6253	6253				
112		.210000 x	17.312112 =	3.635544	
501		.002917 x	599.233352 =	1.747964	
X 630		.200000 x	1.466728 =	.293346	
X 630.1		.200000 x	1.611970 =	.322394	
521		.007000 x	416.138373 =	2.912969	

			T.E =	8.912215	
6301	6301				
231		.200000 x	.775000 =	.155000	
113		.127500 x	20.419486 =	2.603484	
111		.170000 x	15.741598 =	2.676072	
252		.002500 x	270.000000 =	.675000	
251		.001500 x	290.000000 =	.435000	

			T.E =	6.544556	
6302	6302				
231		.300000 x	.775000 =	.232500	
251		.002000 x	290.000000 =	.580000	
111		.212500 x	15.741598 =	3.345090	
113		1.232500 x	20.419486 =	25.167016	
252		.004000 x	270.000000 =	1.080000	

			T.E =	30.404606	
6303	6303				
6302		.666660 x	30.404606 =	20.269535	

			T.E =	20.269535	

6304	6304				
234.2		.018000 x	.888000 =	.015984	
113		.085000 x	20.419486 =	1.735656	
113		.010200 x	20.419486 =	.208279	
112		.212500 x	17.312112 =	3.678824	
235		.012000 x	.613000 =	.007356	

			T.E =	5.646099	
6310	6310				
233		1.050000 x	.570200 =	.598710	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.466538	
6311	6311				
233.1		1.050000 x	.570200 =	.598710	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.466538	
6312	6312				
233.3		1.010000 x	7.700000 =	7.777000	
113		.085000 x	20.419486 =	1.735656	
233.3		.303000 x	7.700000 =	2.333100	
113		.085000 x	20.419486 =	1.735656	

			T.E =	13.581413	
6313	6313				
233.2		1.050000 x	.603700 =	.633885	
113		.025500 x	20.419486 =	.520697	

			T.E =	1.154582	
6314	6314				
233.2		1.050000 x	.603700 =	.633885	
113		.068000 x	20.419486 =	1.388525	

			T.E =	2.022410	
6320.1	6320.1				
396.1		1.000000 x	1.400000 =	1.400000	
113		.000850 x	20.419486 =	.017357	

			T.E =	1.417357	

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	20.419486 =	.017357

			T.E =	.787357
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	20.419486 =	.017357

			T.E =	1.697357
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	20.419486 =	.017357

			T.E =	.997357
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	20.419486 =	.017357

			T.E =	1.197357
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	20.419486 =	.017357

			T.E =	1.597357
6321	6321			
221		140.000000 x	.099900 =	13.986000
112		.714000 x	17.312112 =	12.360848
113		.595000 x	20.419486 =	12.149594
509		.003302 x	393.999470 =	1.300986
509		.003019 x	393.999470 =	1.189484
T 630.1		.175000 x	1.957393 =	.342544
T 630		.175000 x	1.781027 =	.311680
T 625		.350000 x	21.257285 =	7.440050
T 623		.560000 x	18.130101 =	10.152857
T 621		.300000 x	16.825109 =	5.047533
511		.023800 x	723.974755 =	17.230599
509		.005284 x	393.999470 =	2.081893
111		.765000 x	15.741598 =	12.042322

			T.E =	95.636390

6322	6322			
221		140.000000 x	.099900 =	13.986000
509		.003019 x	393.999470 =	1.189484
T 623		.560000 x	18.130101 =	10.152857
T 630.1		.175000 x	1.957393 =	.342544
T 630		.175000 x	1.781027 =	.311680
T 625		.350000 x	21.257285 =	7.440050
511		.023800 x	723.974755 =	17.230599
T 611		.300000 x	20.070537 =	6.021161
509		.003302 x	393.999470 =	1.300986
509		.005284 x	393.999470 =	2.081893
113		.595000 x	20.419486 =	12.149594
111		.765000 x	15.741598 =	12.042322
112		.714000 x	17.312112 =	12.360848

T.E = 96.610019

6323	6323			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
511		.034000 x	723.974755 =	24.615142
509		.004718 x	393.999470 =	1.858889
509		.007548 x	393.999470 =	2.973908
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 105.515185

6323.1	6323.1			
221		150.000000 x	.099900 =	14.985000
T 617		.500000 x	6.258384 =	3.129192
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.800000 x	18.130101 =	14.504081
511		.034000 x	723.974755 =	24.615142
509		.007548 x	393.999470 =	2.973908
509		.004718 x	393.999470 =	1.858889
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 98.015734

6324	6324			
221		200.000000 x	.099900 =	19.980000
113		.850000 x	20.419486 =	17.356563
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
511		.034000 x	723.974755 =	24.615142
509		.007548 x	393.999470 =	2.973908
509		.004718 x	393.999470 =	1.858889
112		1.020000 x	17.312112 =	17.658354

T.E = 110.510185

6324.1	6324.1			
221		200.000000 x	.099900 =	19.980000
112		1.020000 x	17.312112 =	17.658354
113		.850000 x	20.419486 =	17.356563
509		.004718 x	393.999470 =	1.858889
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.800000 x	18.130101 =	14.504081
T 617		.500000 x	6.258384 =	3.129192
511		.034000 x	723.974755 =	24.615142
509		.007548 x	393.999470 =	2.973908

T.E = 103.010734

6325	6325			
221		250.000000 x	.099900 =	24.975000
T 623		.800000 x	18.130101 =	14.504081
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 625		.500000 x	21.257285 =	10.628643
509		.007548 x	393.999470 =	2.973908
511		.034000 x	723.974755 =	24.615142
509		.004718 x	393.999470 =	1.858889
112		1.020000 x	17.312112 =	17.658354
113		.850000 x	20.419486 =	17.356563

T.E = 115.505185

6325.1

6325.1

221	250.000000 x	.099900 =	24.975000
T 630.1	.250000 x	1.957393 =	.489348
T 630	.250000 x	1.781027 =	.445257
T 623	.800000 x	18.130101 =	14.504081
T 617	.500000 x	6.258384 =	3.129192
511	.034000 x	723.974755 =	24.615142
509	.004718 x	393.999470 =	1.858889
509	.007548 x	393.999470 =	2.973908
113	.850000 x	20.419486 =	17.356563
112	1.020000 x	17.312112 =	17.658354

T.E =

108.005734

6326

6326

221	300.000000 x	.099900 =	29.970000
T 630.1	.250000 x	1.957393 =	.489348
T 630	.250000 x	1.781027 =	.445257
112	1.190000 x	17.312112 =	20.601413
509	.007548 x	393.999470 =	2.973908
511	.034000 x	723.974755 =	24.615142
T 625	.500000 x	21.257285 =	10.628643
T 623	.800000 x	18.130101 =	14.504081
509	.004718 x	393.999470 =	1.858889
113	1.360000 x	20.419486 =	27.770501

T.E =

133.857182

6326.1

6326.1

221	300.000000 x	.099900 =	29.970000
T 630.1	.250000 x	1.957393 =	.489348
T 630	.250000 x	1.781027 =	.445257
T 623	.800000 x	18.130101 =	14.504081
T 617	.500000 x	6.258384 =	3.129192
511	.034000 x	723.974755 =	24.615142
112	1.190000 x	17.312112 =	20.601413
509	.007548 x	393.999470 =	2.973908
113	1.360000 x	20.419486 =	27.770501
509	.004718 x	393.999470 =	1.858889

T.E =

126.357731

6327	6327			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	393.999470 =	2.973908
511		.034000 x	723.974755 =	24.615142
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
509		.004718 x	393.999470 =	1.858889
113		1.275000 x	20.419486 =	26.034845

T.E = 156.141409

6327.1	6327.1			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.800000 x	18.130101 =	14.504081
T 617		.500000 x	6.258384 =	3.129192
511		.034000 x	723.974755 =	24.615142
509		.004718 x	393.999470 =	1.858889
509		.007548 x	393.999470 =	2.973908
113		1.275000 x	20.419486 =	26.034845
112		2.295000 x	17.312112 =	39.731297

T.E = 148.641959

6328	6328			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	393.999470 =	2.973908
511		.034000 x	723.974755 =	24.615142
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
509		.004718 x	393.999470 =	1.858889
113		1.445000 x	20.419486 =	29.506157

T.E = 159.717722

6328.1	6328.1			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.800000 x	18.130101 =	14.504081
T 617		.500000 x	6.258384 =	3.129192
511		.034000 x	723.974755 =	24.615142
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	393.999470 =	2.973908
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	393.999470 =	1.858889

T.E = 152.218271

6329	6329			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	393.999470 =	1.858889
511		.034000 x	723.974755 =	24.615142
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
509		.007548 x	393.999470 =	2.973908
112		2.295000 x	17.312112 =	39.731297

T.E = 165.422722

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.800000 x	18.130101 =	14.504081
T 617		.500000 x	6.258384 =	3.129192
511		.034000 x	723.974755 =	24.615142
509		.007548 x	393.999470 =	2.973908
509		.004718 x	393.999470 =	1.858889
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 157.923271

6329.2

6329.2

223	350.000000 x	.119300 =	41.755000
T 630.1	.250000 x	1.957393 =	.489348
T 630	.250000 x	1.781027 =	.445257
T 625	.500000 x	21.257285 =	10.628643
511	.034000 x	723.974755 =	24.615142
509	.007548 x	393.999470 =	2.973908
113	1.445000 x	20.419486 =	29.506157
T 623	.800000 x	18.130101 =	14.504081
112	2.295000 x	17.312112 =	39.731297
509	.004718 x	393.999470 =	1.858889

T.E =

166.507722

6329.3

6329.3

223	350.000000 x	.119300 =	41.755000
113	1.445000 x	20.419486 =	29.506157
T 630.1	.250000 x	1.957393 =	.489348
T 630	.250000 x	1.781027 =	.445257
T 623	.800000 x	18.130101 =	14.504081
T 617	.500000 x	6.258384 =	3.129192
511	.034000 x	723.974755 =	24.615142
509	.007548 x	393.999470 =	2.973908
509	.004718 x	393.999470 =	1.858889
112	2.295000 x	17.312112 =	39.731297

T.E =

159.008271

6330

6330

223	420.000000 x	.119300 =	50.106000
113	1.445000 x	20.419486 =	29.506157
112	2.295000 x	17.312112 =	39.731297
509	.007548 x	393.999470 =	2.973908
T 630.1	.250000 x	1.957393 =	.489348
T 630	.250000 x	1.781027 =	.445257
T 625	.500000 x	21.257285 =	10.628643
T 623	.800000 x	18.130101 =	14.504081
511	.042500 x	723.974755 =	30.768927
509	.004718 x	393.999470 =	1.858889

T.E =

181.012507

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
112		2.295000 x	17.312112 =	39.731297
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 617		.500000 x	6.258384 =	3.129192
T 623		.800000 x	18.130101 =	14.504081
511		.042500 x	723.974755 =	30.768927
509		.007548 x	393.999470 =	2.973908
509		.004718 x	393.999470 =	1.858889
113		1.445000 x	20.419486 =	29.506157

T.E = 173.513057

6331	6331			
222		450.000000 x	.116200 =	52.290000
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
511		.042500 x	723.974755 =	30.768927
509		.004718 x	393.999470 =	1.858889
509		.007548 x	393.999470 =	2.973908
113		5.525000 x	20.419486 =	112.817660
112		3.400000 x	17.312112 =	58.861181
111		3.825000 x	15.741598 =	60.211612

T.E = 345.849506

6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
509		.004718 x	393.999470 =	1.858889
509		.007548 x	393.999470 =	2.973908
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.800000 x	18.130101 =	14.504081
T 617		.500000 x	6.258384 =	3.129192
511		.042500 x	723.974755 =	30.768927
113		5.525000 x	20.419486 =	112.817660
111		3.825000 x	15.741598 =	60.211612
112		3.400000 x	17.312112 =	58.861181

T.E = 338.350056

6351	6351			
221		120.000000 x	.099900 =	11.988000
6301		1.000000 x	6.544556 =	6.544556
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 625		.450000 x	21.257285 =	9.565778
511		.034000 x	723.974755 =	24.615142
509		.008020 x	393.999470 =	3.159876
113		1.275000 x	20.419486 =	26.034845
T 623		.850000 x	18.130101 =	15.410586
509		.004246 x	393.999470 =	1.672922
112		1.275000 x	17.312112 =	22.072943

T.E = 121.999252

6351.1	6351.1			
221		120.000000 x	.099900 =	11.988000
6301		1.000000 x	6.544556 =	6.544556
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 623		.850000 x	18.130101 =	15.410586
T 617		.450000 x	6.258384 =	2.816273
511		.034000 x	723.974755 =	24.615142
509		.008020 x	393.999470 =	3.159876
509		.004246 x	393.999470 =	1.672922
113		1.275000 x	20.419486 =	26.034845
112		1.275000 x	17.312112 =	22.072943

T.E = 115.249746

6352	6352			
221		300.000000 x	.099900 =	29.970000
6301		1.000000 x	6.544556 =	6.544556
T 630.1		.250000 x	1.957393 =	.489348
T 630		.250000 x	1.781027 =	.445257
T 625		.500000 x	21.257285 =	10.628643
T 623		.800000 x	18.130101 =	14.504081
511		.034000 x	723.974755 =	24.615142
509		.004718 x	393.999470 =	1.858889
509		.007548 x	393.999470 =	2.973908
113		2.550000 x	20.419486 =	52.069689
112		2.125000 x	17.312112 =	36.788238

T.E = 180.887751

6352.1	6352.1				
221		300.000000 x	.099900 =		29.970000
112		2.125000 x	17.312112 =		36.788238
113		2.550000 x	20.419486 =		52.069689
6301		1.000000 x	6.544556 =		6.544556
T 630.1		.250000 x	1.957393 =		.489348
T 630		.250000 x	1.781027 =		.445257
T 623		.800000 x	18.130101 =		14.504081
T 617		.500000 x	6.258384 =		3.129192
511		.034000 x	723.974755 =		24.615142
509		.007548 x	393.999470 =		2.973908
509		.004718 x	393.999470 =		1.858889
				T.E =	173.388300
6360.1	6360.1				
6360.1 A1		1.000000 x	112.847630 =		112.847630
6360.1 A5		1.000000 x	99.497445 =		99.497445
6360.1 A4		1.000000 x	32.208128 =		32.208128
6360.1 A3		1.000000 x	14.475987 =		14.475987
6360.1 A2		1.000000 x	8.035232 =		8.035232
			AΘΡΟΙΣΜΑ =		267.064422
	T.E =	.200000 x	267.064422 =		53.412884
6360.2	6360.2				
6360.2 A1		1.000000 x	121.329745 =		121.329745
6360.2 A2		1.000000 x	11.169305 =		11.169305
6360.2 A3		1.000000 x	18.861869 =		18.861869
6360.2 A5		1.000000 x	113.378987 =		113.378987
6360.2 A4		1.000000 x	35.456988 =		35.456988
			AΘΡΟΙΣΜΑ =		300.196894
	T.E =	.200000 x	300.196894 =		60.039379
6360.3	6360.3				
6360.3 A1		1.000000 x	160.806193 =		160.806193
6360.3 A2		1.000000 x	15.846288 =		15.846288
6360.3 A3		1.000000 x	42.477052 =		42.477052
6360.3 A5		1.000000 x	156.820603 =		156.820603
6360.3 A4		1.000000 x	42.454232 =		42.454232
			AΘΡΟΙΣΜΑ =		418.404368
	T.E =	.200000 x	418.404368 =		83.680874

6360.4	6360.4			
6360.4 A1		1.000000 x	210.791227 =	210.791227
6360.4 A3		1.000000 x	63.626678 =	63.626678
6360.4 A2		1.000000 x	21.479668 =	21.479668
6360.4 A4		1.000000 x	35.456988 =	35.456988
6360.4 A5		1.000000 x	211.622657 =	211.622657

			AΘΡΟΙΣΜΑ =	542.977218
	T.E =	.200000 x	542.977218 =	108.595444

6360.5	6360.5			
6360.5 A1		1.000000 x	241.516221 =	241.516221
6360.5 A2		1.000000 x	26.799626 =	26.799626
6360.5 A5		1.000000 x	289.600211 =	289.600211
6360.5 A4		1.000000 x	36.716382 =	36.716382
6360.5 A3		1.000000 x	70.670769 =	70.670769

			AΘΡΟΙΣΜΑ =	665.303209
	T.E =	.200000 x	665.303209 =	133.060642

6360.6	6360.6			
6360.6 A1		1.000000 x	293.758729 =	293.758729
6360.6 A5		1.000000 x	382.640621 =	382.640621
6360.6 A4		1.000000 x	35.456988 =	35.456988
6360.6 A3		1.000000 x	83.047463 =	83.047463
6360.6 A2		1.000000 x	40.259169 =	40.259169

			AΘΡΟΙΣΜΑ =	835.162970
	T.E =	.200000 x	835.162970 =	167.032594

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	20.419486 =	.347131
111		.085000 x	15.741598 =	1.338036

			T.E =	2.065167
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143
396.14		.003000 x	38.800000 =	.116400

			T.E =	16.922169
6371	6371			
326		.500000 x	1.310000 =	.655000
111		.212500 x	15.741598 =	3.345090
113		.212500 x	20.419486 =	4.339141

			T.E =	8.339230

6372	6372				
396.11		1.050000 x	2.560000 =	2.688000	
396.13		.700000 x	1.770000 =	1.239000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	

			T.E =	16.221769	
6373	6373				
396.12		1.050000 x	3.680000 =	3.864000	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	20.419486 =	8.678282	
111		.425000 x	15.741598 =	6.690179	

			T.E =	20.471461	
6401	6401				
327		.500000 x	.540000 =	.270000	
113		.212500 x	20.419486 =	4.339141	

			T.E =	4.609141	
6402	6402				
252		.000500 x	270.000000 =	.135000	
652.2		.005500 x	169.283142 =	.931057	
111		.595000 x	15.741598 =	9.366251	
113		.595000 x	20.419486 =	12.149594	
652		.011500 x	149.319718 =	1.717177	

			T.E =	24.299079	
6403	6403				
251		.000500 x	290.000000 =	.145000	
111		.850000 x	15.741598 =	13.380358	
652.2		.005500 x	169.283142 =	.931057	
652		.016500 x	149.319718 =	2.463775	
113		.850000 x	20.419486 =	17.356563	

			T.E =	34.276754	
6404	6404				
111		1.275000 x	15.741598 =	20.070537	
652		.020000 x	149.319718 =	2.986394	
113		1.700000 x	20.419486 =	34.713126	

			T.E =	57.770058	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	57.770058 =	57.770058	

			T.E =		

6405	6405			
111		.425000 x	15.741598 =	6.690179
652		.020000 x	149.319718 =	2.986394
113		.850000 x	20.419486 =	17.356563

			T.E =	27.033137
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	24,668.000000 =	24,668.000000
386.9		.150000 x	24,668.000000 =	3,700.200000

			T.E =	28,368.200000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	73,850.000000 =	73,850.000000
386.40		.150000 x	73,850.000000 =	11,077.500000

			T.E =	84,927.500000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	108,702.000000 =	108,702.000000
386.30		.150000 x	108,702.000000 =	16,305.300000

			T.E =	125,007.300000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17				
386.64		1.000000 x	147,712.000000 =		147,712.000000
386.64		.150000 x	147,712.000000 =		22,156.800000
				T.E =	169,868.800000
6453.18	6453.18				
386.65		1.000000 x	.000000 =		.000000
386.65		.150000 x	.000000 =		.000000
				T.E =	
6453.19	6453.19				
386.66		1.000000 x	.000000 =		.000000
386.66		.150000 x	.000000 =		.000000
				T.E =	
6453.2	6453.2				
386.49		1.000000 x	.000000 =		.000000
386.49		.150000 x	.000000 =		.000000
				T.E =	
6453.20	6453.20				
386.67		1.000000 x	.000000 =		.000000
386.67		.150000 x	.000000 =		.000000
				T.E =	
6453.3	6453.3				
386.50		1.000000 x	.000000 =		.000000
386.50		.150000 x	.000000 =		.000000
				T.E =	
6453.4	6453.4				
386.51		1.000000 x	.000000 =		.000000
386.51		.150000 x	.000000 =		.000000
				T.E =	
6453.5	6453.5				
386.52		1.000000 x	.000000 =		.000000
386.52		.150000 x	.000000 =		.000000
				T.E =	

6453.6	6453.6				
386.53		1.000000 x	128,861.000000 =		128,861.000000
386.53		.150000 x	128,861.000000 =		19,329.150000
				T.E =	148,190.150000
6453.7	6453.7				
386.54		1.000000 x	.000000 =		.000000
386.54		.150000 x	.000000 =		.000000
				T.E =	
6453.8	6453.8				
386.55		1.000000 x	.000000 =		.000000
386.55		.150000 x	.000000 =		.000000
				T.E =	
6453.9	6453.9				
386.56		1.000000 x	.000000 =		.000000
386.56		.150000 x	.000000 =		.000000
				T.E =	
6454.1	6454.1				
386.68		1.000000 x	.000000 =		.000000
386.68		.150000 x	.000000 =		.000000
				T.E =	
6454.10	6454.10				
386.77		1.000000 x	.000000 =		.000000
386.77		.150000 x	.000000 =		.000000
				T.E =	
6454.11	6454.11				
386.78		1.000000 x	.000000 =		.000000
386.78		.150000 x	.000000 =		.000000
				T.E =	
6454.12	6454.12				
386.79		1.000000 x	.000000 =		.000000
386.79		.150000 x	.000000 =		.000000
				T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	20,690.000000 =	20,690.000000
387.3		.100000 x	20,690.000000 =	2,069.000000

			T.E =	22,759.000000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	.888000 =	184.704000
113		154.700001 x	20.419486 =	3,158.894505
235		338.000000 x	.613000 =	207.194000

			AΘΡΟΙΣΜΑ =	3,550.792505

			T.E =	5,326.188757
6456.2	6456.2			
234.2		336.000000 x	.888000 =	298.368000
113		249.900000 x	20.419486 =	5,102.829551
235		546.000000 x	.613000 =	334.698000

			AΘΡΟΙΣΜΑ =	5,735.895551

			T.E =	8,030.253772
6456.3	6456.3			
234.2		384.000000 x	.888000 =	340.992000
235		624.000000 x	.613000 =	382.512000
113		285.599998 x	20.419486 =	5,831.805161

			AΘΡΟΙΣΜΑ =	6,555.309161

			T.E =	9,177.432825
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	6,406.000000 =	6,406.000000
389.4		.200000 x	6,406.000000 =	1,281.200000

			T.E =	7,687.200000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	5,412.000000 =	5,412.000000
390.14		.150000 x	5,412.000000 =	811.800000

			T.E =	6,223.800000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	7,871.000000 =	7,871.000000
390.31		.150000 x	7,871.000000 =	1,180.650000

			T.E =	9,051.650000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	14,767.000000 =	14,767.000000
393.1		.150000 x	14,767.000000 =	2,215.050000

			T.E =	16,982.050000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.320000 =	6.320000

			T.E =	6.320000
6501	6501			
237		1.000000 x	1.110000 =	1.110000
113		.850000 x	20.419486 =	17.356563

			T.E =	18.466563
6502	6502			
112		.170000 x	17.312112 =	2.943059
517		.042500 x	2,158.852489 =	91.751231

			T.E =	94.694290
6505	6505			
233		1.050000 x	.570200 =	.598710
113		.042500 x	20.419486 =	.867828

			T.E =	1.466538

6506	6506				
233.1		1.050000 x	.570200 =	.598710	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.466538	
6551.1	6551.1				
221		6.000000 x	.099900 =	.599400	
113		.255000 x	20.419486 =	5.206969	
111		.255000 x	15.741598 =	4.014107	
261		1.000000 x	15.100000 =	15.100000	

			T.E =	24.920476	
6551.2	6551.2				
221		8.000000 x	.099900 =	.799200	
262		1.000000 x	26.300000 =	26.300000	
111		.297500 x	15.741598 =	4.683125	
113		.297500 x	20.419486 =	6.074797	

			T.E =	37.857122	
6551.3	6551.3				
221		10.000000 x	.099900 =	.999000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	

			T.E =	45.693769	
6551.4	6551.4				
221		13.000000 x	.099900 =	1.298700	
263.2		1.000000 x	46.700000 =	46.700000	
113		.510000 x	20.419486 =	10.413938	
111		.510000 x	15.741598 =	8.028215	

			T.E =	66.440853	
6551.5	6551.5				
221		16.000000 x	.099900 =	1.598400	
113		.595000 x	20.419486 =	12.149594	
111		.595000 x	15.741598 =	9.366251	
264		1.000000 x	64.100000 =	64.100000	

			T.E =	87.214245	

6551.6	6551.6			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

T.E = 147.834921

6551.7	6551.7			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

T.E = 255.002782

6552	6552			
221		26.000000 x	.099900 =	2.597400
6304		6.890000 x	5.646099 =	38.901622
6310		32.020000 x	1.466538 =	46.958547
6329.2		.418000 x	166.507722 =	69.600228
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

T.E = 210.853358

6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.022410 =	27.767689
6329.2		.478000 x	166.507722 =	79.590691
6304		9.290000 x	5.646099 =	52.452260

T.E = 177.167203

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

			T.E =	
6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

			T.E =	
6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

			T.E =	
6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

			T.E =	
6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

			T.E =	

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.400350 x	20.419486 =	8.174941
112		.612850 x	17.312112 =	10.609728

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

T.E =

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

T.E =

6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

T.E =

6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

T.E =

6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

T.E =

6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

T.E =

6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

T.E =

6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

T.E =

6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

T.E =

6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

T.E =

6610	6610				
360.1		1.000000 x	.000000 =	.000000	
113		.085000 x	20.419486 =	1.735656	
113		.025500 x	20.419486 =	.520697	
112		.042500 x	17.312112 =	.735765	
111		.042500 x	15.741598 =	.669018	

			T.E =		
6611.1	6611.1				
361.1		1.000000 x	12.320000 =	12.320000	
113		.212500 x	20.419486 =	4.339141	
112		.510000 x	17.312112 =	8.829177	
111		.085000 x	15.741598 =	1.338036	

			T.E =	26.826354	
6611.10	6611.10				
361.10		1.000000 x	.000000 =	.000000	
111		.510000 x	15.741598 =	8.028215	
112		2.125000 x	17.312112 =	36.788238	
113		.765000 x	20.419486 =	15.620907	

			T.E =		
6611.11	6611.11				
361.11		1.000000 x	.000000 =	.000000	
111		.637500 x	15.741598 =	10.035269	
113		.935000 x	20.419486 =	19.092219	
112		2.550000 x	17.312112 =	44.145886	

			T.E =		
6611.12	6611.12				
361.12		1.000000 x	.000000 =	.000000	
111		.765000 x	15.741598 =	12.042322	
113		1.105000 x	20.419486 =	22.563532	
112		2.975000 x	17.312112 =	51.503533	

			T.E =		
6611.13	6611.13				
361.13		1.000000 x	.000000 =	.000000	
113		1.275000 x	20.419486 =	26.034845	
112		3.400000 x	17.312112 =	58.861181	
111		.892500 x	15.741598 =	14.049376	

			T.E =		

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
112		3.825000 x	17.312112 =	66.218828
113		1.445000 x	20.419486 =	29.506157

			T.E =	
6611.2	6611.2			
361.2		1.000000 x	15.940000 =	15.940000
111		.085000 x	15.741598 =	1.338036
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942

			T.E =	31.182118
6611.3	6611.3			
361.3		1.000000 x	20.220000 =	20.220000
111		.127500 x	15.741598 =	2.007054
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471

			T.E =	38.470494
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072

			T.E =	
6611.5	6611.5			
361.5		1.000000 x	38.600000 =	38.600000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453

			T.E =	65.942368
6611.6	6611.6			
361.6		1.000000 x	51.610000 =	51.610000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884

			T.E =	83.432273

6611.7	6611.7			
361.7		1.000000 x	79.690000 =	79.690000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

			T.E =	117.529024
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

			T.E =	11.019393
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

			T.E =	16.398814
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

			T.E =	20.616330

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424

			T.E =	30.493845
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414

			T.E =	37.634580
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563

			T.E =	56.514929
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299

			T.E =	70.886112
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
113		.568650 x	20.419486 =	11.611541
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817

			T.E =	88.635713
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709

			T.E =	110.023068

6621.1	6621.1			
372.1		1.020000 x	8.000000 =	8.160000
113		.205700 x	20.419486 =	4.200288
111		.080750 x	15.741598 =	1.271134
112		.088400 x	17.312112 =	1.530391

			T.E =	15.161813
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.680736
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.836897
6621.4	6621.4			
372.4		1.020000 x	25.550000 =	26.061000
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	42.902521
6621.5	6621.5			
372.5		1.020000 x	32.410000 =	33.058200
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	53.332089
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	80.949300

6621.7	6621.7				
372.7		1.020000 x	65.050000 =	66.351000	
111		.662150 x	15.741598 =	10.423299	
112		.710600 x	17.312112 =	12.301987	
113		.589050 x	20.419486 =	12.028098	

			T.E =	101.104384	
6621.8	6621.8				
372.8		1.020000 x	82.710000 =	84.364200	
111		.841500 x	15.741598 =	13.246555	
113		.663850 x	20.419486 =	13.555476	
112		.901000 x	17.312112 =	15.598213	

			T.E =	126.764443	
6621.9	6621.9				
372.9		1.020000 x	104.700000 =	106.794000	
111		1.068450 x	15.741598 =	16.819110	
113		.748000 x	20.419486 =	15.273776	
112		1.145800 x	17.312112 =	19.836218	

			T.E =	158.723104	
6622.1	6622.1				
373.1		1.020000 x	11.900000 =	12.138000	
113		.235450 x	20.419486 =	4.807768	
112		.131750 x	17.312112 =	2.280871	
111		.080750 x	15.741598 =	1.271134	

			T.E =	20.497773	
6622.2	6622.2				
373.2		1.020000 x	18.780000 =	19.155600	
111		.130900 x	15.741598 =	2.060575	
112		.212500 x	17.312112 =	3.678824	
113		.299200 x	20.419486 =	6.109510	

			T.E =	31.004509	
6622.3	6622.3				
373.3		1.020000 x	24.500000 =	24.990000	
111		.170850 x	15.741598 =	2.689452	
113		.341700 x	20.419486 =	6.977338	
112		.277950 x	17.312112 =	4.811902	

			T.E =	39.468692	

6623	6623				
360.2		1.000000 x	2.220000 =	2.220000	
113		.085000 x	20.419486 =	1.735656	
111		.042500 x	15.741598 =	.669018	
113		.025500 x	20.419486 =	.520697	
112		.042500 x	17.312112 =	.735765	

			T.E =	5.881136	
6630.1	6630.1				
376.12		1.000000 x	88.960000 =	88.960000	
113		2.550000 x	20.419486 =	52.069689	
113		.610300 x	20.419486 =	12.462012	
113		1.067600 x	20.419486 =	21.799843	
112		2.439500 x	17.312112 =	42.232897	
111		.855100 x	15.741598 =	13.460640	

			T.E =	230.985083	
6630.10	6630.10				
376.21		1.000000 x	487.600000 =	487.600000	
111		7.690800 x	15.741598 =	121.065482	
113		3.349000 x	20.419486 =	68.384859	
113		3.203650 x	20.419486 =	65.416886	
113		2.550000 x	20.419486 =	52.069689	
112		13.396000 x	17.312112 =	231.913052	

			T.E =	1,026.449968	
6630.11	6630.11				
376.22		1.000000 x	528.600000 =	528.600000	
111		9.025300 x	15.741598 =	142.072644	
113		3.471400 x	20.419486 =	70.884204	
113		3.629500 x	20.419486 =	74.112524	
113		2.550000 x	20.419486 =	52.069689	
112		14.518000 x	17.312112 =	251.337242	

			T.E =	1,119.076304	
6630.2	6630.2				
376.13		1.000000 x	98.960000 =	98.960000	
113		2.550000 x	20.419486 =	52.069689	
113		1.201050 x	20.419486 =	24.524824	
113		.680000 x	20.419486 =	13.885250	
111		1.081200 x	15.741598 =	17.019816	
112		2.720000 x	17.312112 =	47.088945	

			T.E =	253.548524	

6630.3	6630.3				
376.14		1.000000 x	109.782000 =	109.782000	
113		1.334500 x	20.419486 =	27.249804	
113		2.550000 x	20.419486 =	52.069689	
113		.760750 x	20.419486 =	15.534124	
112		3.043000 x	17.312112 =	52.680757	
111		1.334500 x	15.741598 =	21.007163	

			T.E =	278.323537	
6630.4	6630.4				
376.15		1.000000 x	140.650000 =	140.650000	
111		1.922700 x	15.741598 =	30.266370	
113		.892500 x	20.419486 =	18.224391	
113		1.602250 x	20.419486 =	32.717121	
113		2.550000 x	20.419486 =	52.069689	
112		3.570000 x	17.312112 =	61.804240	

			T.E =	335.731812	
6630.5	6630.5				
376.16		1.000000 x	176.880000 =	176.880000	
111		2.617150 x	15.741598 =	41.198123	
113		1.164500 x	20.419486 =	23.778491	
113		2.550000 x	20.419486 =	52.069689	
113		1.869150 x	20.419486 =	38.167082	
112		4.658000 x	17.312112 =	80.639818	

			T.E =	412.733204	
6630.6	6630.6				
376.17		1.000000 x	224.520000 =	224.520000	
113		2.550000 x	20.419486 =	52.069689	
113		2.136050 x	20.419486 =	43.617043	
113		1.470500 x	20.419486 =	30.026854	
111		3.418700 x	15.741598 =	53.815801	
112		5.882000 x	17.312112 =	101.829843	

			T.E =	505.879230	
6630.7	6630.7				
376.18		1.000000 x	302.640000 =	302.640000	
113		2.402950 x	20.419486 =	49.067004	
113		2.550000 x	20.419486 =	52.069689	
113		2.031500 x	20.419486 =	41.482186	
112		8.126000 x	17.312112 =	140.678222	
111		4.326500 x	15.741598 =	68.106024	

			T.E =	654.043125	

6630.8	6630.8			
376.19		1.000000 x	336.580000 =	336.580000
111		5.340550 x	15.741598 =	84.068791
113		2.261000 x	20.419486 =	46.168458
113		2.669850 x	20.419486 =	54.516965
113		2.550000 x	20.419486 =	52.069689
112		9.044000 x	17.312112 =	156.570741

T.E = 729.974644

6630.9	6630.9			
376.20		1.000000 x	400.990000 =	400.990000
111		6.461700 x	15.741598 =	101.717484
113		2.737000 x	20.419486 =	55.888133
113		2.550000 x	20.419486 =	52.069689
113		2.936750 x	20.419486 =	59.966926
112		10.948000 x	17.312112 =	189.533002

T.E = 860.165234

6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		1.667700 x	20.419486 =	34.053577
111		1.334500 x	15.741598 =	21.007163
112		3.043000 x	17.312112 =	52.680757

T.E =

6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		2.002600 x	20.419486 =	40.892063
112		3.570000 x	17.312112 =	61.804240
111		1.922700 x	15.741598 =	30.266370

T.E =

6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
111		2.617150 x	15.741598 =	41.198123
112		4.658000 x	17.312112 =	80.639818
113		2.550000 x	20.419486 =	52.069689
113		2.336650 x	20.419486 =	47.713192

T.E =

6640.4 6640.4

377.4	1.000000 x	.000000 =	.000000
111	3.418700 x	15.741598 =	53.815801
112	5.882000 x	17.312112 =	101.829843
113	2.669850 x	20.419486 =	54.516965
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.5 6640.5

377.5	1.000000 x	.000000 =	.000000
111	4.326500 x	15.741598 =	68.106024
113	3.003900 x	20.419486 =	61.338094
113	2.550000 x	20.419486 =	52.069689
112	8.126000 x	17.312112 =	140.678222

T.E =

6640.6 6640.6

377.6	1.000000 x	.000000 =	.000000
113	2.550000 x	20.419486 =	52.069689
113	3.337100 x	20.419486 =	68.141867
112	9.044000 x	17.312112 =	156.570741
111	5.340550 x	15.741598 =	84.068791

T.E =

6640.7 6640.7

377.7	1.000000 x	.000000 =	.000000
111	6.461700 x	15.741598 =	101.717484
112	10.948000 x	17.312112 =	189.533002
113	3.671150 x	20.419486 =	74.962996
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.8 6640.8

377.8	1.000000 x	.000000 =	.000000
111	7.690800 x	15.741598 =	121.065482
112	13.396000 x	17.312112 =	231.913052
113	2.550000 x	20.419486 =	52.069689
113	4.004350 x	20.419486 =	81.766769

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.741598 =	142.072644
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242

			T.E =	
6641	6641			
233.3		1.000000 x	7.700000 =	7.700000

			T.E =	7.700000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		.050000 x	724.000000 =	36.200000
378.9		1.000000 x	724.000000 =	724.000000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		.100000 x	583.000000 =	58.300000
380.3		1.000000 x	583.000000 =	583.000000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7 6662.7

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.5	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.8	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.8 6662.8

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.6	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.1 6663.1

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.4	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.2 6663.2

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6701.1 6701.1

368.1	1.020000 x	.000000 =	.000000
369.1	.224000 x	.000000 =	.000000
113	.068000 x	20.419486 =	1.388525
111	.382500 x	15.741598 =	6.021161

T.E =

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

T.E =

6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

T.E =

6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

T.E =

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

T.E =

6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

T.E =

6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625

T.E =

6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
369.14		.224000 x	.000000 =	.000000

			T.E =	
6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

			T.E =	
6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

			T.E =	
6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251
369.18		.224000 x	.000000 =	.000000

			T.E =	

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
111		.680000 x	15.741598 =	10.704287

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
369.27		.224000 x	.000000 =	.000000

T.E =

6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
369.28		.224000 x	.000000 =	.000000
111		.595000 x	15.741598 =	9.366251
113		.238000 x	20.419486 =	4.859838

T.E =

6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
369.29		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525

			T.E =	
6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.24		1.000000 x	.000000 =	.000000

			T.E =	
6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

			T.E =	

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
6326		.327500 x	133.857182 =	43.838227
113		.026350 x	20.419486 =	.538053
111		.085000 x	15.741598 =	1.338036

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
111		.119000 x	15.741598 =	1.873250
113		.040800 x	20.419486 =	.833115
6326		.352500 x	133.857182 =	47.184657

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
111		.161500 x	15.741598 =	2.542268
6326		.372500 x	133.857182 =	49.861800
113		.051000 x	20.419486 =	1.041394

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
6326		.382500 x	133.857182 =	51.200372
113		.063750 x	20.419486 =	1.301742

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	133.857182 =	52.371622
113		.068000 x	20.419486 =	1.388525
111		.187000 x	15.741598 =	2.943679

T.E =

6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
113		.076500 x	20.419486 =	1.562091
6327		.393750 x	156.141409 =	61.480680

T.E =

6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	15.741598 =	4.549322
6327		.431250 x	156.141409 =	67.335983
113		.093500 x	20.419486 =	1.909222

T.E =

6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	156.141409 =	78.070705
113		.119000 x	20.419486 =	2.429919

T.E =

6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	24.363962 =	9.014666
113		.017000 x	20.419486 =	.347131
111		.161500 x	15.741598 =	2.542268

T.E = 20.584265

6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	15.741598 =	2.943679
6069		.390000 x	24.363962 =	9.501945
113		.021250 x	20.419486 =	.433914

T.E = 26.476138

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	15.741598 =	3.211286
6069		.400000 x	24.363962 =	9.745585
113		.026350 x	20.419486 =	.538053

			T.E =	34.700724
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.741598 =	3.880304
6069		.420000 x	24.363962 =	10.232864
113		.040800 x	20.419486 =	.833115

			T.E =	49.269283
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	24.363962 =	10.476504
113		.051000 x	20.419486 =	1.041394
111		.289000 x	15.741598 =	4.549322

			T.E =	59.723219
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	24.363962 =	10.720143
113		.063750 x	20.419486 =	1.301742
111		.297500 x	15.741598 =	4.683125

			T.E =	72.019611
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	24.363962 =	12.669260
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750

			T.E =	109.519301
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	39.738563

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	43.245563
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	48.674063
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	56.171063
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	10.160000 =	10.160000

			T.E =	63.804563
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
113		.021250 x	20.419486 =	.433914
111		.187000 x	15.741598 =	2.943679
375.14		1.000000 x	17.510000 =	17.510000

			T.E =	31.047593
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	105.515185 =	9.496367
112		1.190000 x	17.312112 =	20.601413
113		.255000 x	20.419486 =	5.206969

			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	115.505185 =	25.526646
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	115.505185 =	27.028213
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	115.505185 =	27.836750
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	105.515185 =	11.606670
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	105.515185 =	13.822489
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6720.4 6720.4

394.5	1.050000 x	.000000 =	.000000
112	1.360000 x	17.312112 =	23.544472
113	.510000 x	20.419486 =	10.413938
6323	.154000 x	105.515185 =	16.249338
700	.350000 x	.000000 =	.000000

T.E =

6720.5 6720.5

394.6	1.050000 x	.000000 =	.000000
6323	.166000 x	105.515185 =	17.515521
112	1.445000 x	17.312112 =	25.016002
700	.380000 x	.000000 =	.000000
113	.595000 x	20.419486 =	12.149594

T.E =

6720.6 6720.6

394.7	1.050000 x	.000000 =	.000000
112	1.487500 x	17.312112 =	25.751767
700	.400000 x	.000000 =	.000000
6323	.173000 x	105.515185 =	18.254127
113	.637500 x	20.419486 =	13.017422

T.E =

6720.7 6720.7

394.2	1.050000 x	.000000 =	.000000
6325	.138000 x	115.505185 =	15.939716
700	.200000 x	.000000 =	.000000
113	.255000 x	20.419486 =	5.206969
112	1.190000 x	17.312112 =	20.601413

T.E =

6720.8 6720.8

394.3	1.050000 x	.000000 =	.000000
112	1.275000 x	17.312112 =	22.072943
113	.340000 x	20.419486 =	6.942625
6325	.165000 x	115.505185 =	19.058356
700	.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	115.505185 =	22.292501
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	105.515185 =	6.330911
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	115.505185 =	15.015674
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	115.505185 =	16.170726
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	115.505185 =	17.325778
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	105.515185 =	7.386063
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	105.515185 =	8.441215
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	105.515185 =	9.496367
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	105.515185 =	10.551519
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	105.515185 =	11.606670
113		.637500 x	20.419486 =	13.017422

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	115.505185 =	11.550519
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	115.505185 =	12.705570
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	115.505185 =	13.860622
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	105.515185 =	9.496367
652		.002500 x	149.319718 =	.373299
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E = 39.493825

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	115.505185 =	28.760791
652		.004500 x	149.319718 =	.671939
113		.340000 x	20.419486 =	6.942625

			T.E =	82.436128
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	115.505185 =	35.806607
652		.005000 x	149.319718 =	.746599
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

			T.E =	110.919229
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	115.505185 =	42.736918
652		.006500 x	149.319718 =	.970578
112		.680000 x	17.312112 =	11.772236

			T.E =	141.624506
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	105.515185 =	11.606670
652		.003000 x	149.319718 =	.447959
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

			T.E =	47.558788
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	105.515185 =	13.822489
652		.003500 x	149.319718 =	.522619
113		.297500 x	20.419486 =	6.074797

			T.E =	58.001878

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	105.515185 =	17.937581
652		.004500 x	149.319718 =	.671939
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

			T.E =	71.612918
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	105.515185 =	23.846432
652		.005000 x	149.319718 =	.746599
112		.552500 x	17.312112 =	9.564942

			T.E =	98.959053
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	105.515185 =	28.911161
652		.006500 x	149.319718 =	.970578
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

			T.E =	127.798748
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	115.505185 =	15.939716
652		.002500 x	149.319718 =	.373299
113		.255000 x	20.419486 =	5.206969

			T.E =	45.937173
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	115.505185 =	19.058356
652		.003000 x	149.319718 =	.447959
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

			T.E =	55.010473

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	115.505185 =	22.292501
652		.003500 x	149.319718 =	.522619
112		.382500 x	17.312112 =	6.621883

T.E = 66.471889

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	105.515185 =	9.496367
652		.002500 x	149.319718 =	.373299
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	115.505185 =	28.760791
652		.004500 x	149.319718 =	.671939
113		.340000 x	20.419486 =	6.942625

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	115.505185 =	35.806607
652		.005000 x	149.319718 =	.746599
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	115.505185 =	42.736918
652		.006500 x	149.319718 =	.970578
112		.680000 x	17.312112 =	11.772236

T.E =

6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	105.515185 =	11.606670
652		.003000 x	149.319718 =	.447959
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	105.515185 =	13.822489
652		.003500 x	149.319718 =	.522619
113		.297500 x	20.419486 =	6.074797

T.E =

6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	105.515185 =	17.937581
652		.004500 x	149.319718 =	.671939
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

T.E =

6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	105.515185 =	23.846432
652		.005000 x	149.319718 =	.746599
112		.552500 x	17.312112 =	9.564942

T.E =

6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	105.515185 =	28.911161
652		.006500 x	149.319718 =	.970578
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	115.505185 =	15.939716
652		.002500 x	149.319718 =	.373299
113		.255000 x	20.419486 =	5.206969

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	115.505185 =	19.058356
652		.003000 x	149.319718 =	.447959
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	115.505185 =	22.292501
652		.003500 x	149.319718 =	.522619
112		.382500 x	17.312112 =	6.621883

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	133.857182 =	125.825751
6303		1.880000 x	20.269535 =	38.106726

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	133.857182 =	97.715743

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	133.857182 =	125.825751

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	133.857182 =	97.715743

			T.E =	
6742.1	6742.1			
6303		3.040000 x	20.269535 =	61.619386
6328		.400000 x	159.717722 =	63.887089

			T.E =	125.506475
6742.10	6742.10			
6303		7.520000 x	20.269535 =	152.426903
6328		2.110000 x	159.717722 =	337.004393

			T.E =	489.431297
6742.11	6742.11			
6303		8.030000 x	20.269535 =	162.764366
6328		2.430000 x	159.717722 =	388.114064

			T.E =	550.878431
6742.2	6742.2			
6303		3.500000 x	20.269535 =	70.943373
6328		.500000 x	159.717722 =	79.858861

			T.E =	150.802234
6742.3	6742.3			
6303		4.020000 x	20.269535 =	81.483531
6328		.630000 x	159.717722 =	100.622165

			T.E =	182.105696
6742.4	6742.4			
6303		4.530000 x	20.269535 =	91.820994
6328		.800000 x	159.717722 =	127.774178

			T.E =	219.595171

6742.5	6742.5			
6303		5.000000 x	20.269535 =	101.347675
6328		.950000 x	159.717722 =	151.731836

			T.E =	253.079511
6742.6	6742.6			
6303		5.530000 x	20.269535 =	112.090529
6328		1.170000 x	159.717722 =	186.869735

			T.E =	298.960263
6742.7	6742.7			
6303		6.040000 x	20.269535 =	122.427991
6328		1.410000 x	159.717722 =	225.201988

			T.E =	347.629979
6742.8	6742.8			
6303		6.520000 x	20.269535 =	132.157368
6328		1.610000 x	159.717722 =	257.145532

			T.E =	389.302901
6742.9	6742.9			
6303		7.040000 x	20.269535 =	142.697526
6328		1.880000 x	159.717722 =	300.269317

			T.E =	442.966844
6743.1	6743.1			
6303		3.040000 x	20.269535 =	61.619386
6328		.440000 x	159.717722 =	70.275798

			T.E =	131.895184
6743.10	6743.10			
6303		7.520000 x	20.269535 =	152.426903
6328		2.240000 x	159.717722 =	357.767697

			T.E =	510.194600
6743.11	6743.11			
6303		8.030000 x	20.269535 =	162.764366
6328		2.570000 x	159.717722 =	410.474546

			T.E =	573.238912

6743.12	6743.12			
6303		3.040000 x	20.269535 =	61.619386
6328		.750000 x	159.717722 =	119.788292

			T.E =	181.407678
6743.13	6743.13			
6303		3.500000 x	20.269535 =	70.943373
6328		.910000 x	159.717722 =	145.343127

			T.E =	216.286500
6743.14	6743.14			
6303		4.020000 x	20.269535 =	81.483531
6328		1.090000 x	159.717722 =	174.092317

			T.E =	255.575848
6743.15	6743.15			
6303		4.530000 x	20.269535 =	91.820994
6328		1.300000 x	159.717722 =	207.633039

			T.E =	299.454032
6743.16	6743.16			
6303		5.000000 x	20.269535 =	101.347675
6328		1.550000 x	159.717722 =	247.562469

			T.E =	348.910144
6743.17	6743.17			
6303		5.530000 x	20.269535 =	112.090529
6328		1.850000 x	159.717722 =	295.477786

			T.E =	407.568314
6743.2	6743.2			
6303		3.500000 x	20.269535 =	70.943373
6328		.550000 x	159.717722 =	87.844747

			T.E =	158.788120
6743.3	6743.3			
6303		4.020000 x	20.269535 =	81.483531
6328		.690000 x	159.717722 =	110.205228

			T.E =	191.688759

6743.4	6743.4			
6303		4.530000 x	20.269535 =	91.820994
6328		.860000 x	159.717722 =	137.357241

			T.E =	229.178234
6743.5	6743.5			
6303		5.000000 x	20.269535 =	101.347675
6328		1.020000 x	159.717722 =	162.912076

			T.E =	264.259751
6743.6	6743.6			
6303		5.530000 x	20.269535 =	112.090529
6328		1.260000 x	159.717722 =	201.244330

			T.E =	313.334858
6743.7	6743.7			
6303		6.040000 x	20.269535 =	122.427991
6328		1.500000 x	159.717722 =	239.576583

			T.E =	362.004574
6743.8	6743.8			
6303		6.520000 x	20.269535 =	132.157368
6328		1.720000 x	159.717722 =	274.714482

			T.E =	406.871850
6743.9	6743.9			
6303		7.040000 x	20.269535 =	142.697526
6328		2.000000 x	159.717722 =	319.435444

			T.E =	462.132970
6744	6744			
111		2.125000 x	15.741598 =	33.450896
111		4.250000 x	15.741598 =	66.901792
112		2.125000 x	17.312112 =	36.788238
113		2.125000 x	20.419486 =	43.391408
113		2.125000 x	20.419486 =	43.391408

			T.E =	223.923741

6751	6751				
234.2		.400000 x	.888000 =	.355200	
235		.650000 x	.613000 =	.398450	
113		.170000 x	20.419486 =	3.471313	
113		.051000 x	20.419486 =	1.041394	

			T.E =	5.266356	
6752	6752				
237		1.050000 x	1.110000 =	1.165500	
113		.017000 x	20.419486 =	.347131	
111		.025500 x	15.741598 =	.401411	

			T.E =	1.914042	
6753	6753				
237		1.050000 x	1.110000 =	1.165500	
112		.085000 x	17.312112 =	1.471530	
113		.085000 x	20.419486 =	1.735656	

			T.E =	4.372686	
6754	6754				
237.1		1.000000 x	1.260000 =	1.260000	
112		.017000 x	17.312112 =	.294306	
111		.051000 x	15.741598 =	.802821	
113		.212500 x	20.419486 =	4.339141	

			T.E =	6.696268	
6801	6801				
232		.700000 x	1.900000 =	1.330000	
251		.008000 x	290.000000 =	2.320000	
113		2.550000 x	20.419486 =	52.069689	
112		1.700000 x	17.312112 =	29.430590	
111		.850000 x	15.741598 =	13.380358	

			T.E =	98.530638	
6802	6802				
231		15.000000 x	.775000 =	11.625000	
251		.050000 x	290.000000 =	14.500000	
113		2.550000 x	20.419486 =	52.069689	
252.1		.050000 x	.000000 =	.000000	
111		4.250000 x	15.741598 =	66.901792	

			T.E =		

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	149.319718 =	1.791837
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250

			T.E =	30.539302
6804	6804			
111		.510000 x	15.741598 =	8.028215
652		.120000 x	149.319718 =	17.918366
113		.680000 x	20.419486 =	13.885250

			T.E =	39.831832
6805	6805			
301		1.000000 x	4.060000 =	4.060000
652		.002000 x	149.319718 =	.298639
2522		.005000 x	153.503851 =	.767519
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143

			T.E =	17.420927
6806	6806			
111		.340000 x	15.741598 =	5.352143
113		.340000 x	20.419486 =	6.942625
6326		.005000 x	133.857182 =	.669286
652		.002000 x	149.319718 =	.298639

			T.E =	13.262694
6807	6807			
111		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179

			T.E =	6.690179
6810	6810			
241		2.600000 x	7.050000 =	18.330000
113		1.062500 x	20.419486 =	21.695704
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448
241		1.300000 x	7.050000 =	9.165000

			T.E =	83.272715

6811	6811			
236		6.430000 x	.603000 =	3.877290
113		.850000 x	20.419486 =	17.356563
113		3.400000 x	20.419486 =	69.426252
241		3.150000 x	7.050000 =	22.207500

			T.E =	112.867606
6812	6812			
397.1		2.100000 x	7.050000 =	14.805000
243		11.900000 x	2.100000 =	24.990000
6324		.250000 x	110.510185 =	27.627546
113		4.250000 x	20.419486 =	86.782816
111		.425000 x	15.741598 =	6.690179

			AΘΡΟΙΣΜΑ =	160.895541
	T.E =	.262500 x	160.895541 =	42.235079

7001	7001			
7001 Α		1.000000 x	.231284 =	.231284
7001 Β		1.000000 x	.754845 =	.754845
7001 Ε		1.000000 x	.807147 =	.807147
7001 Δ		1.000000 x	.314853 =	.314853
7001 Γ		1.000000 x	.965949 =	.965949

			AΘΡΟΙΣΜΑ =	3.074078

			T.E =	3.535190
7002	7002			
560		.005104 x	680.235090 =	3.471920

			T.E =	3.471920
7003	7003			
7003 Α		1.000000 x	.115642 =	.115642
7003 Β		1.000000 x	.588355 =	.588355
7003 Δ		1.000000 x	.782367 =	.782367
7003 Γ		1.000000 x	.546486 =	.546486

			AΘΡΟΙΣΜΑ =	2.032850

			T.E =	2.236135
7004	7004			
561		.003250 x	893.290790 =	2.903195

			T.E =	2.903195

7005	7005			
7005 Α		1.000000 x	.115642 =	.115642
7005 Γ		1.000000 x	.294177 =	.294177
7005 Ε		1.000000 x	.782367 =	.782367
7005 Δ		1.000000 x	.546486 =	.546486
7005 Β		1.000000 x	1.029621 =	1.029621

			ΑΘΡΟΙΣΜΑ =	2.768293

			T.E =	3.045122
7006	7006			
561		.001723 x	893.290790 =	1.539140
561		.000862 x	893.290790 =	.770017
561		.000812 x	893.290790 =	.725352

			T.E =	3.034509
7007	7007			
213		.100000 x	1.949500 =	.194950
116		.280000 x	20.419486 =	5.717456
550		.003500 x	1,043.565886 =	3.652481
518		.001750 x	855.590542 =	1.497283
502		.000583 x	780.693773 =	.455144

			T.E =	11.517315
7008	7008			
111		.021000 x	15.741598 =	.330574
112		.210000 x	17.312112 =	3.635544
503		.001750 x	889.036073 =	1.555813
507		.000875 x	908.577107 =	.795005
558		.000972 x	1,078.349457 =	1.048156
7007		1.100000 x	11.517315 =	12.669047

			T.E =	20.034137
7009	7009			
560		.006417 x	680.235090 =	4.365069

			T.E =	4.365069
7010	7010			
7010 Α		1.000000 x	.339680 =	.339680
7010 Β		1.000000 x	.510059 =	.510059
7010 Ε		1.000000 x	.982467 =	.982467
7010 Δ		1.000000 x	.314853 =	.314853
7010 Γ		1.000000 x	.546486 =	.546486

			ΑΘΡΟΙΣΜΑ =	2.693545

			T.E =	3.097577

7011	7011			
502		.001367 x	780.693773 =	1.067208
563		.001367 x	.000000 =	.000000
558		.000729 x	1,078.349457 =	.786117
558		.000729 x	1,078.349457 =	.786117
554		.000438 x	33.418000 =	.014637
502		.000700 x	780.693773 =	.546486
503		.000438 x	889.036073 =	.389398

			ΑΘΡΟΙΣΜΑ =	3.589962

			T.E =	
7012	7012			
7008		1.000000 x	20.034137 =	20.034137

			ΑΘΡΟΙΣΜΑ =	20.034137

			T.E =	22.037551
7013	7013			
7003		1.000000 x	2.236135 =	2.236135

			ΑΘΡΟΙΣΜΑ =	2.236135

			T.E =	2.459749
7014	7014			
7005		1.000000 x	3.045122 =	3.045122

			ΑΘΡΟΙΣΜΑ =	3.045122

			T.E =	3.349634
7015	7015			
111		.056000 x	15.741598 =	.881529
X 630.1		.300000 x	1.611970 =	.483591
7001		.900000 x	3.535190 =	3.181671
X 630		.300000 x	1.466728 =	.440018

			T.E =	4.986810
7016.9	7016.9			
7016.4		1.000000 x	125.996982 =	125.996982
7016.6		1.000000 x	37.799095 =	37.799095
7016.7		1.000000 x	80.282150 =	80.282150
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	25.199396 =	25.199396

			T.E =	373.417002

7017.8	7017.8				
7017.3		1.000000 x	92.361836 =		92.361836
7017.4		1.000000 x	18.472367 =		18.472367
7017.5		1.000000 x	33.250261 =		33.250261
7017.7		1.000000 x	52.069689 =		52.069689
7017.6		1.000000 x	80.282150 =		80.282150

			T.E =		276.436303
7018	7018				
233.2		1.150000 x	.603700 =		.694255
113		.051000 x	20.419486 =		1.041394

			AΘΡΟΙΣΜΑ =		1.735649

			T.E =		1.909214
7019	7019				
7019 A6		1.000000 x	191.305953 =		191.305953
7019 A7		1.000000 x	19.130595 =		19.130595

			T.E =		210.436548
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	210.436548 =		210.436548

			T.E =		204.536548
7020	7020				
213		.150000 x	1.949500 =		.292425
116		.980000 x	20.419486 =		20.011096
7020.2		.010938 x	3,481.197919 =		38.077343

			T.E =		58.380864
7020.1	7020.1				
570.2		.350000 x	124.784076 =		43.674427
571.2		.070000 x	259.459536 =		18.162168
571.1		.280000 x	430.994230 =		120.678384

			AΘΡΟΙΣΜΑ =		182.514979
	T.E =	.015625 x	182.514979 =		2.851797

7021	7021				
213		.150000 x	1.949500 =		.292425
116		1.120000 x	20.419486 =		22.869824
7021.2		.014583 x	3,043.241169 =		44.379586

			T.E =		67.541835

7021.1	7021.1			
570.2		.350000 x	124.784076 =	43.674427
571.2		.070000 x	259.459536 =	18.162168
571.1		.280000 x	430.994230 =	120.678384
			AΘΡΟΙΣΜΑ =	182.514979
	T.E =	.020833 x	182.514979 =	3.802335
7022	7022			
213		.150000 x	1.949500 =	.292425
116		1.400000 x	20.419486 =	28.587280
7022.2		.020000 x	2,795.016335 =	55.900327
			T.E =	84.780032
7022.1	7022.1			
570.2		.350000 x	124.784076 =	43.674427
571.2		.070000 x	259.459536 =	18.162168
571.1		.280000 x	430.994230 =	120.678384
			AΘΡΟΙΣΜΑ =	182.514979
	T.E =	.028571 x	182.514979 =	5.214635
7023	7023			
398.2		1.050000 x	39.000000 =	40.950000
111		.425000 x	15.741598 =	6.690179
116		.850000 x	20.419486 =	17.356563
550		.012143 x	1,043.565886 =	12.672021
			T.E =	77.668763
7024	7024			
398.3		1.050000 x	47.000000 =	49.350000
116		.850000 x	20.419486 =	17.356563
550		.020238 x	1,043.565886 =	21.119686
111		.425000 x	15.741598 =	6.690179
			T.E =	94.516429
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	149.319718 =	.149320
550		.020238 x	1,043.565886 =	21.119686
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
111		.425000 x	15.741598 =	6.690179
233		6.180000 x	.570200 =	3.523836
398.4		1.000000 x	63.000000 =	63.000000
			T.E =	119.207852

7026	7026				
398.5		125.400000 x	5.780000 =	724.812000	
236		16.808000 x	.603000 =	10.135224	
113		.909160 x	20.419486 =	18.564580	
113		3.400000 x	20.419486 =	69.426252	
6310		12.350000 x	1.466538 =	18.111744	
			AΘΡΟΙΣΜΑ =	841.049801	
	T.E =	.007259 x	841.049801 =	6.105181	
7027	7027				
236		1.100000 x	.603000 =	.663300	
113		.059500 x	20.419486 =	1.214959	
			T.E =	1.878259	
7028	7028				
111		.144500 x	15.741598 =	2.274661	
6751		.120000 x	5.266356 =	.631963	
6751		.600000 x	5.266356 =	3.159814	
111		.425000 x	15.741598 =	6.690179	
112		.144500 x	17.312112 =	2.501600	
			AΘΡΟΙΣΜΑ =	15.258217	
			T.E =	17.546949	
7029	7029				
568.1		.021250 x	2,616.950519 =	55.610199	
569.2		.021250 x	612.976952 =	13.025760	
570.2		.021250 x	124.784076 =	2.651662	
571.2		.021250 x	259.459536 =	5.513515	
			T.E =	76.801136	
7030	7030				
398.6		.015385 x	330.000000 =	5.077050	
572		.026563 x	845.300817 =	22.453726	
			AΘΡΟΙΣΜΑ =	27.530776	
			T.E =	38.543086	
7031	7031				
573		.106250 x	1,072.943392 =	114.000235	
			AΘΡΟΙΣΜΑ =	114.000235	
			T.E =	131.100271	
7032	7032				
573		.212500 x	1,072.943392 =	228.000471	
			AΘΡΟΙΣΜΑ =	228.000471	
			T.E =	296.400612	

7101.1	7101.1			
398.1		15.000000 x	.225000 =	3.375000
574		.132813 x	3,512.687482 =	466.530563
T 630		.105000 x	1.781027 =	.187008
T 630.1		.105000 x	1.957393 =	.205526
567		.132813 x	380.161272 =	50.490359

ΑΘΡΟΙΣΜΑ =				520.788456

T.E =				536.412109
7101.2	7101.2			
398.1		15.000000 x	.225000 =	3.375000
574		.148750 x	3,512.687482 =	522.512263
T 630.1		.105000 x	1.957393 =	.205526
T 630		.105000 x	1.781027 =	.187008
567		.148750 x	380.161272 =	56.548989

ΑΘΡΟΙΣΜΑ =				582.828786

T.E =				600.313650
7101.3	7101.3			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.957393 =	.205526
T 630		.105000 x	1.781027 =	.187008
574		.159375 x	3,512.687482 =	559.834567
567		.159375 x	380.161272 =	60.588203

ΑΘΡΟΙΣΜΑ =				624.190304

T.E =				642.916013
7101.4	7101.4			
398.1		15.000000 x	.225000 =	3.375000
567		.170000 x	380.161272 =	64.627416
574		.170000 x	3,512.687482 =	597.156872
T 630.1		.105000 x	1.957393 =	.205526
T 630		.105000 x	1.781027 =	.187008

ΑΘΡΟΙΣΜΑ =				665.551822

T.E =				685.518377
7101.5	7101.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.957393 =	.205526
567		.191250 x	380.161272 =	72.705843
T 630		.105000 x	1.781027 =	.187008
574		.191250 x	3,512.687482 =	671.801481

ΑΘΡΟΙΣΜΑ =				748.274858

T.E =				770.723104

7102.1	7102.1			
398.1		15.000000 x	.225000 =	3.375000
567		.302813 x	380.161272 =	115.117775
T 630		.105000 x	1.781027 =	.187008
T 630.1		.105000 x	1.957393 =	.205526
574		.302813 x	3,512.687482 =	1,063.687434

			AΘΡΟΙΣΜΑ =	1,182.572744

			T.E =	1,218.049926
7102.2	7102.2			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.957393 =	.205526
T 630		.105000 x	1.781027 =	.187008
574		.329375 x	3,512.687482 =	1,156.991439
567		.329375 x	380.161272 =	125.215619

			AΘΡΟΙΣΜΑ =	1,285.974592

			T.E =	1,324.553830
7102.3	7102.3			
398.1		15.000000 x	.225000 =	3.375000
567		.361250 x	380.161272 =	137.333260
T 630		.105000 x	1.781027 =	.187008
T 630.1		.105000 x	1.957393 =	.205526
574		.361250 x	3,512.687482 =	1,268.958353

			AΘΡΟΙΣΜΑ =	1,410.059146

			T.E =	1,452.360921
7102.4	7102.4			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.957393 =	.205526
T 630		.105000 x	1.781027 =	.187008
574		.403750 x	3,512.687482 =	1,418.247571
567		.403750 x	380.161272 =	153.490114

			AΘΡΟΙΣΜΑ =	1,575.505219

			T.E =	1,622.770375
7102.5	7102.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.957393 =	.205526
T 630		.105000 x	1.781027 =	.187008
567		.446250 x	380.161272 =	169.646968
574		.446250 x	3,512.687482 =	1,567.536789

			AΘΡΟΙΣΜΑ =	1,740.951291

			T.E =	1,793.179829

7103	7103			
113		3.400000 x	20.419486 =	69.426252
113		.283333 x	20.419486 =	5.785514
115		.070833 x	21.778427 =	1.542631
575		.106250 x	911.266858 =	96.822104

			T.E =	173.576502
7104	7104			
113		1.700000 x	20.419486 =	34.713126
576		.106250 x	7.425000 =	.788906
567		.106250 x	380.161272 =	40.392135

			T.E =	75.894168
7105	7105			
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563
576		.106250 x	7.425000 =	.788906
567		.106250 x	380.161272 =	40.392135

			T.E =	71.917963
7106.1	7106.1			
577		.265625 x	666.806219 =	177.120402

			AΘΡΟΙΣΜΑ =	177.120402

			T.E =	185.976422
7106.2	7106.2			
577		.297500 x	666.806219 =	198.374850

			AΘΡΟΙΣΜΑ =	198.374850

			T.E =	208.293593
7106.3	7106.3			
577		.350625 x	666.806219 =	233.798931

			AΘΡΟΙΣΜΑ =	233.798931

			T.E =	245.488877
7106.4	7106.4			
577		.425000 x	666.806219 =	283.392643

			AΘΡΟΙΣΜΑ =	283.392643

			T.E =	297.562275

7106.5	7106.5			
577		.531250 x	666.806219 =	354.240804

			ΑΘΡΟΙΣΜΑ =	354.240804

			T.E =	371.952844
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	185.976422 =	185.976422

			T.E =	226.776422
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	208.293593 =	208.293593

			T.E =	249.093593
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	245.488877 =	245.488877

			T.E =	286.288877
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	297.562275 =	297.562275

			T.E =	338.362275
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	371.952844 =	371.952844

			T.E =	412.752844
7108	7108			
398.11		1.000000 x	136.770000 =	136.770000
574		.053125 x	3,512.687482 =	186.611522

			T.E =	323.381522
7109	7109			
398.12		1.000000 x	176.880000 =	176.880000
574		.053125 x	3,512.687482 =	186.611522

			T.E =	363.491522

7110	7110				
398.10		1.170000 x	138.730000 =		162.314100
574		.053125 x	3,512.687482 =		186.611522

			T.E =		348.925622
7111	7111				
398.9		1.170000 x	128.000000 =		149.760000
574		.053125 x	3,512.687482 =		186.611522

			T.E =		336.371522
7112	7112				
398.13		1.300000 x	9.400000 =		12.220000
577		.010625 x	666.806219 =		7.084816

			T.E =		19.304816
7113	7113				
241		1.200000 x	7.050000 =		8.460000
574		.001063 x	3,512.687482 =		3.733987

			T.E =		12.193987
7114	7114				
398.8		.120000 x	30.750000 =		3.690000
577		.053125 x	666.806219 =		35.424080

			T.E =		39.114080
7115	7115				
574		.026563 x	3,512.687482 =		93.307518

			T.E =		93.307518
7116	7116				
577		.170000 x	666.806219 =		113.357057

			T.E =		113.357057
7117	7117				
574		.001063 x	3,512.687482 =		3.733987

			T.E =		3.733987

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
578		.850000 x	633.640766 =	538.594651
574.1		.425000 x	2,184.957688 =	928.607017

			T.E =	1,895.373134
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
574.1		.850000 x	2,184.957688 =	1,857.214035
578		.850000 x	633.640766 =	538.594651

			T.E =	3,038.065884
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	382.917688 =	97.644010

			T.E =	311.729743
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	382.917688 =	227.836024

			T.E =	441.921757
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
575.1		.425000 x	257.177416 =	109.300402
578		.425000 x	633.640766 =	269.297326

			T.E =	539.162027
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	633.640766 =	807.891977
575.1		1.275000 x	257.177416 =	327.901205

			T.E =	1,403.400348
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	633.640766 =	269.297326

			T.E =	379.208942

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	633.640766 =	269.297326

			T.E =	379.208942
7122	7122			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.781027 =	.187008
T 630.1		.105000 x	1.957393 =	.205526
567		.122188 x	380.161272 =	46.451146
580		.122188 x	1,678.010462 =	205.032742

			AΘΡΟΙΣΜΑ =	255.251422

			T.E =	262.908965
7123	7123			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.957393 =	.205526
T 630		.105000 x	1.781027 =	.187008
580		.286875 x	1,678.010462 =	481.379251
567		.286875 x	380.161272 =	109.058765

			AΘΡΟΙΣΜΑ =	594.205550

			T.E =	612.031717
7124	7124			
398.1		15.000000 x	.225000 =	3.375000
567		.063750 x	380.161272 =	24.235281
T 630		.105000 x	1.781027 =	.187008
T 630.1		.105000 x	1.957393 =	.205526
580		.063750 x	1,678.010462 =	106.973167

			T.E =	134.975982
7125	7125			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.957393 =	.205526
567		.127500 x	380.161272 =	48.470562
T 630		.105000 x	1.781027 =	.187008
580		.127500 x	1,678.010462 =	213.946334

			T.E =	266.184430
7126	7126			
398.16		1.000000 x	62.420000 =	62.420000
580		.053125 x	1,678.010462 =	89.144306

			T.E =	151.564306

7127	7127				
398.15		1.170000 x	75.690000 =		88.557300
580		.015938 x	1,678.010462 =		26.744131

			T.E =		115.301431
7128	7128				
398.14		1.170000 x	58.610000 =		68.573700
580		.015938 x	1,678.010462 =		26.744131

			T.E =		95.317831
7129	7129				
6751		1.000000 x	5.266356 =		5.266356

			T.E =		5.266356