

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

2ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.218700
212	1.421100
213	1.949500
214	4.160000
221	.099900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.861000
232	2.100000
233	.545500
233.1	.545500
233.2	.598400
233.3	8.100000
234	.954000
234.1	1.111500
234.2	1.001500
234.3	1.048400
235	.713000
236	.683000
237	1.218000
237.1	1.380000
241	7.750000
242	5.000000
243	2.400000
244	2.700000
251	290.000000
252	290.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.440000
361.1	13.520000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	17.490000
361.3	22.200000
361.4	
361.5	42.370000
361.6	56.540000
361.7	87.480000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	7.990000
372.2	12.580000
372.3	16.500000
372.4	25.540000
372.5	32.500000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.490000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.260000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	91.600000
376.10	502.070000
376.11	544.290000
376.12	91.600000
376.13	101.900000
376.14	113.040000
376.15	144.820000
376.16	182.130000
376.17	231.180000
376.18	311.830000
376.19	346.570000
376.2	101.900000
376.20	412.890000
376.21	502.070000
376.22	544.290000
376.3	113.040000
376.4	144.820000
376.5	182.130000
376.6	231.180000
376.7	311.830000
376.8	346.570000
376.9	412.890000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	113,082.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	76,825.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	134,053.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	153,664.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	25,662.000000
387.1	
387.2	
387.3	21,523.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	6,664.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	5,629.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	8,188.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	15,362.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.960000
396.12	4.250000
396.13	1.770000
396.14	42.680000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.950000
397.4	.167500
398.1	.225000
398.10	142.840000
398.11	140.870000
398.12	182.180000
398.13	10.300000
398.14	60.360000
398.15	77.960000
398.16	64.290000
398.17	107.000000
398.2	39.000000
398.3	47.000000
398.4	63.000000
398.5	6.400000

398.6	330.000000
398.7	1,360.000000
398.8	31.620000
398.9	131.840000
401	268.420000
402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
413	4.530000
414	6.250000
415	8.780000
416	13.540000
417	134.530000
419	4.530000
420	97.290000
421	32.560000
428	437.840000
429	77.590000
450	83.850000
451	4.870000
452	103.060000
453	
454	97.290000
455	31.280000
456	35.040000
457	457.700000
458	285.020000
459	422.050000
460	521.890000
461	239.030000
462	348.520000
463	43.800000
464	383.570000
465	102.610000
466	47.860000
467	348.520000
468	87.280000
469	87.280000
470	70.390000
471	61.000000
472	26.510000
473	17.050000
474	35.040000
475	1,970.400000
476	85.400000
477	6.950000
478	115.120000
479	185.200000
480	27.220000
481	812.490000

501	501				
401		1.000000 x	268.420000 =	268.420000	
211		50.000000 x	1.218700 =	60.935000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	

			ΑΘΡΟΙΣΜΑ =	562.927593	

			Η.Δ. =	619.220352	
502	502				
402		1.000000 x	380.180000 =	380.180000	
214		7.000000 x	4.160000 =	29.120000	
211		80.000000 x	1.218700 =	97.496000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

			ΑΘΡΟΙΣΜΑ =	737.889612	

			Η.Δ. =	811.678573	
503	503				
428		1.000000 x	437.840000 =	437.840000	
214		10.000000 x	4.160000 =	41.600000	
114		8.000000 x	23.886192 =	191.089536	
211		110.000000 x	1.218700 =	134.057000	
118		4.000000 x	10.001019 =	40.004076	

			ΑΘΡΟΙΣΜΑ =	844.590612	

			Η.Δ. =	929.049673	
504	504				
403		1.000000 x	103.360000 =	103.360000	
114		8.000000 x	23.886192 =	191.089536	
211		40.000000 x	1.218700 =	48.748000	
214		2.000000 x	4.160000 =	8.320000	

			ΑΘΡΟΙΣΜΑ =	351.517536	

			Η.Δ. =	386.669290	
505	505				
404		1.000000 x	212.730000 =	212.730000	
211		200.000000 x	1.218700 =	243.740000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		10.000000 x	4.160000 =	41.600000	

			ΑΘΡΟΙΣΜΑ =	769.167688	

			Η.Δ. =	846.084457	

506	506				
405		1.000000 x	206.720000 =	206.720000	
211		95.000000 x	1.218700 =	115.776500	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		2.500000 x	5.000000 =	12.500000	
214		6.000000 x	4.160000 =	24.960000	

				ΑΘΡΟΙΣΜΑ =	631.054188

				Η.Δ. =	694.159607
507	507				
406		1.000000 x	320.980000 =	320.980000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
242		7.000000 x	5.000000 =	35.000000	
214		10.000000 x	4.160000 =	41.600000	
211		165.000000 x	1.218700 =	201.085500	

				ΑΘΡΟΙΣΜΑ =	869.763188

				Η.Δ. =	956.739507
508	508				
407		1.000000 x	55.210000 =	55.210000	
116		16.000000 x	20.419486 =	326.711776	
115		4.000000 x	21.778427 =	87.113708	
214		2.000000 x	4.160000 =	8.320000	
408		2.000000 x	4.530000 =	9.060000	
211		40.000000 x	1.218700 =	48.748000	

				ΑΘΡΟΙΣΜΑ =	535.163484

				Η.Δ. =	588.679832
509	509				
409		1.000000 x	126.080000 =	126.080000	
117		8.000000 x	16.777917 =	134.223336	
214		5.000000 x	4.160000 =	20.800000	
211		80.000000 x	1.218700 =	97.496000	

				ΑΘΡΟΙΣΜΑ =	378.599336

				Η.Δ. =	416.459270
510	510				
410		1.000000 x	116.530000 =	116.530000	
117		8.000000 x	16.777917 =	134.223336	
211		80.000000 x	1.218700 =	97.496000	
214		5.000000 x	4.160000 =	20.800000	

				ΑΘΡΟΙΣΜΑ =	369.049336

				Η.Δ. =	405.954270

511	511				
411		1.000000 x	27.370000 =	27.370000	
214		1.000000 x	4.160000 =	4.160000	
112		30.000000 x	17.312112 =	519.363360	
115		4.000000 x	21.778427 =	87.113708	
212		17.000000 x	1.421100 =	24.158700	

			ΑΘΡΟΙΣΜΑ =	662.165768	

			Η.Δ. =	728.382345	
512	512				
412		1.000000 x	2.990000 =	2.990000	
214		1.000000 x	4.160000 =	4.160000	
115		2.000000 x	21.778427 =	43.556854	
112		2.000000 x	17.312112 =	34.624224	
211		10.000000 x	1.218700 =	12.187000	

			ΑΘΡΟΙΣΜΑ =	97.518078	

			Η.Δ. =	107.269886	
513	513				
413		1.000000 x	4.530000 =	4.530000	
211		15.000000 x	1.218700 =	18.280500	
115		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
214		1.500000 x	4.160000 =	6.240000	

			ΑΘΡΟΙΣΜΑ =	146.322117	

			Η.Δ. =	160.954329	
514	514				
414		1.000000 x	6.250000 =	6.250000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		2.000000 x	4.160000 =	8.320000	
211		21.000000 x	1.218700 =	25.592700	

			ΑΘΡΟΙΣΜΑ =	196.524856	

			Η.Δ. =	216.177342	
515	515				
415		1.000000 x	8.780000 =	8.780000	
112		6.000000 x	17.312112 =	103.872672	
115		5.000000 x	21.778427 =	108.892135	
214		2.500000 x	4.160000 =	10.400000	
211		27.000000 x	1.218700 =	32.904900	

			ΑΘΡΟΙΣΜΑ =	264.849707	

			Η.Δ. =	291.334678	

516	516				
416		1.000000 x	13.540000 =	13.540000	
115		6.000000 x	21.778427 =	130.670562	
112		8.000000 x	17.312112 =	138.496896	
214		3.500000 x	4.160000 =	14.560000	
211		33.000000 x	1.218700 =	40.217100	
			ΑΘΡΟΙΣΜΑ =	337.484558	
			Η.Δ. =	371.233014	
517	517				
406		1.000000 x	320.980000 =	320.980000	
406		.400000 x	320.980000 =	128.392000	
116		8.000000 x	20.419486 =	163.355888	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
113		2.000000 x	20.419486 =	40.838972	
112		16.000000 x	17.312112 =	276.993792	
111		16.000000 x	15.741598 =	251.865568	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	4.160000 =	33.280000	
211		240.000000 x	1.218700 =	292.488000	
407		2.000000 x	55.210000 =	110.420000	
			ΑΘΡΟΙΣΜΑ =	2,027.431172	
			Η.Δ. =	2,230.174289	
518	518				
417		1.000000 x	134.530000 =	134.530000	
211		180.000000 x	1.218700 =	219.366000	
112		8.000000 x	17.312112 =	138.496896	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
212		5.000000 x	1.421100 =	7.105500	
214		12.000000 x	4.160000 =	49.920000	
			ΑΘΡΟΙΣΜΑ =	820.516084	
			Η.Δ. =	902.567692	
520	520				
419		1.000000 x	4.530000 =	4.530000	
211		80.000000 x	1.218700 =	97.496000	
118		4.000000 x	10.001019 =	40.004076	
115		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	4.160000 =	20.800000	
212		2.000000 x	1.421100 =	2.842200	
			ΑΘΡΟΙΣΜΑ =	409.148140	
			Η.Δ. =	450.062954	

521	521				
420		1.000000 x	97.290000 =	97.290000	
211		40.000000 x	1.218700 =	48.748000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	

		ΑΘΡΟΙΣΜΑ =		389.611612	

		H.Δ. =		428.572773	
522	522				
421		1.000000 x	32.560000 =	32.560000	
118		2.000000 x	10.001019 =	20.002038	
114		8.000000 x	23.886192 =	191.089536	
214		2.000000 x	4.160000 =	8.320000	
211		20.000000 x	1.218700 =	24.374000	

		ΑΘΡΟΙΣΜΑ =		276.345574	

		H.Δ. =		303.980131	
529	529				
429		1.000000 x	77.590000 =	77.590000	
114		8.000000 x	23.886192 =	191.089536	
118		4.000000 x	10.001019 =	40.004076	
211		70.000000 x	1.218700 =	85.309000	
214		4.000000 x	4.160000 =	16.640000	

		ΑΘΡΟΙΣΜΑ =		410.632612	

		H.Δ. =		451.695873	
550	550				
450		1.000000 x	83.850000 =	83.850000	
115		4.000000 x	21.778427 =	87.113708	
116		32.000000 x	20.419486 =	653.423552	
211		90.000000 x	1.218700 =	109.683000	
214		4.000000 x	4.160000 =	16.640000	
451		4.000000 x	4.870000 =	19.480000	

		ΑΘΡΟΙΣΜΑ =		970.190260	

		H.Δ. =		1,067.209286	
551	551				
405		1.000000 x	206.720000 =	206.720000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		6.000000 x	4.160000 =	24.960000	
211		95.000000 x	1.218700 =	115.776500	
452		1.000000 x	103.060000 =	103.060000	

		ΑΘΡΟΙΣΜΑ =		721.614188	

		H.Δ. =		793.775607	

552	552				
453		1.000000 x	.000000 =	.000000	
115		8.000000 x	21.778427 =	174.227416	
214		1.000000 x	4.160000 =	4.160000	
211		18.000000 x	1.218700 =	21.936600	

			ΑΘΡΟΙΣΜΑ =	200.324016	

			Η.Δ. =		
553	553				
454		1.000000 x	97.290000 =	97.290000	
214		4.000000 x	4.160000 =	16.640000	
211		100.000000 x	1.218700 =	121.870000	

			ΑΘΡΟΙΣΜΑ =	235.800000	

			Η.Δ. =	259.380000	
554	554				
455		1.000000 x	31.280000 =	31.280000	

			ΑΘΡΟΙΣΜΑ =	31.280000	

			Η.Δ. =	34.408000	
555	555				
456		1.000000 x	35.040000 =	35.040000	
212		17.000000 x	1.421100 =	24.158700	
112		32.000000 x	17.312112 =	553.987584	
115		4.000000 x	21.778427 =	87.113708	
214		1.000000 x	4.160000 =	4.160000	

			ΑΘΡΟΙΣΜΑ =	704.459992	

			Η.Δ. =	774.905991	
556	556				
457		1.000000 x	457.700000 =	457.700000	
214		18.000000 x	4.160000 =	74.880000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
211		200.000000 x	1.218700 =	243.740000	

			ΑΘΡΟΙΣΜΑ =	1,047.417688	

			Η.Δ. =	1,152.159457	
557	557				
458		1.000000 x	285.020000 =	285.020000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
214		11.000000 x	4.160000 =	45.760000	
211		130.000000 x	1.218700 =	158.431000	

			ΑΘΡΟΙΣΜΑ =	760.308688	

			Η.Δ. =	836.339557	

558	558				
459		1.000000 x	422.050000 =	422.050000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		9.500000 x	5.000000 =	47.500000	
214		12.000000 x	4.160000 =	49.920000	
211		200.000000 x	1.218700 =	243.740000	

			ΑΘΡΟΙΣΜΑ =	1,034.307688	

			Η.Δ. =	1,137.738457	
559	559				
460		1.000000 x	521.890000 =	521.890000	
211		250.000000 x	1.218700 =	304.675000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
242		12.000000 x	5.000000 =	60.000000	
214		15.000000 x	4.160000 =	62.400000	

			ΑΘΡΟΙΣΜΑ =	1,220.062688	

			Η.Δ. =	1,342.068957	
560	560				
461		1.000000 x	239.030000 =	239.030000	
114		8.000000 x	23.886192 =	191.089536	
214		8.000000 x	4.160000 =	33.280000	
211		160.000000 x	1.218700 =	194.992000	

			ΑΘΡΟΙΣΜΑ =	658.391536	

			Η.Δ. =	724.230690	
561	561				
462		1.000000 x	348.520000 =	348.520000	
114		8.000000 x	23.886192 =	191.089536	
214		12.000000 x	4.160000 =	49.920000	
211		230.000000 x	1.218700 =	280.301000	

			ΑΘΡΟΙΣΜΑ =	869.830536	

			Η.Δ. =	956.813590	
562	562				
463		1.000000 x	43.800000 =	43.800000	
211		50.000000 x	1.218700 =	60.935000	
214		2.400000 x	4.160000 =	9.984000	

			ΑΘΡΟΙΣΜΑ =	114.719000	

			Η.Δ. =	126.190900	

563	563				
211.1		640.000000 x	.000000 =	.000000	
464		1.000000 x	383.570000 =	383.570000	
214		16.000000 x	4.160000 =	66.560000	
112		24.000000 x	17.312112 =	415.490688	
114		16.000000 x	23.886192 =	382.179072	

		ΑΘΡΟΙΣΜΑ =		1,247.799760	

		H.Δ. =			
564	564				
465		1.000000 x	102.610000 =	102.610000	
567		3.000000 x	403.188672 =	1,209.566016	
111		8.000000 x	15.741598 =	125.932784	
115		8.000000 x	21.778427 =	174.227416	
115		8.000000 x	21.778427 =	174.227416	

		ΑΘΡΟΙΣΜΑ =		1,786.563632	

		H.Δ. =		1,965.219995	
565	565				
450		3.000000 x	83.850000 =	251.550000	
115		8.000000 x	21.778427 =	174.227416	
115		12.000000 x	21.778427 =	261.341124	
465		1.000000 x	102.610000 =	102.610000	

		H.Δ. =		789.728540	
566	566				
211.1		680.000000 x	.000000 =	.000000	
466		1.000000 x	47.860000 =	47.860000	
115		2.000000 x	21.778427 =	43.556854	
112		1.000000 x	17.312112 =	17.312112	

		ΑΘΡΟΙΣΜΑ =		108.728966	

		H.Δ. =			
567	567				
450		1.000000 x	83.850000 =	83.850000	
211		90.000000 x	1.218700 =	109.683000	
112		4.000000 x	17.312112 =	69.248448	
214		4.000000 x	4.160000 =	16.640000	
115		4.000000 x	21.778427 =	87.113708	

		ΑΘΡΟΙΣΜΑ =		366.535156	

		H.Δ. =		403.188672	

568.1	568.1			
467		1.000000 x	348.520000 =	348.520000
214		16.000000 x	4.160000 =	66.560000
113		32.000000 x	20.419486 =	653.423552
114		8.000000 x	23.886192 =	191.089536
510		.072000 x	405.954270 =	29.228707
567		2.000000 x	403.188672 =	806.377344
512		.240000 x	107.269886 =	25.744773
118		32.000000 x	10.001019 =	320.032608

			ΑΘΡΟΙΣΜΑ =	2,440.976520

			Η.Δ. =	2,685.074172
568.2	568.2			
450		2.000000 x	83.850000 =	167.700000
114		8.000000 x	23.886192 =	191.089536
115		8.000000 x	21.778427 =	174.227416
467		1.000000 x	348.520000 =	348.520000

			Η.Δ. =	881.536952
569.1	569.1			
468		1.000000 x	87.280000 =	87.280000
567		2.000000 x	403.188672 =	806.377344
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
214		16.000000 x	4.160000 =	66.560000

			ΑΘΡΟΙΣΜΑ =	1,231.315032

			Η.Δ. =	1,354.446535
569.2	569.2			
450		2.000000 x	83.850000 =	167.700000
114		8.000000 x	23.886192 =	191.089536
115		8.000000 x	21.778427 =	174.227416
468		1.000000 x	87.280000 =	87.280000

			Η.Δ. =	620.296952
570.1	570.1			
469		1.000000 x	87.280000 =	87.280000
211		135.000000 x	1.218700 =	164.524500
114		8.000000 x	23.886192 =	191.089536
118		4.000000 x	10.001019 =	40.004076
214		16.000000 x	4.160000 =	66.560000

			ΑΘΡΟΙΣΜΑ =	549.458112

			Η.Δ. =	604.403923

570.2	570.2				
469		1.000000 x	87.280000 =	87.280000	
118		4.000000 x	10.001019 =	40.004076	
			H.Δ. =	127.284076	
571.1	571.1				
470		1.000000 x	70.390000 =	70.390000	
211		114.000000 x	1.218700 =	138.931800	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	4.160000 =	16.640000	
			AΘΡΟΙΣΜΑ =	417.051336	
			H.Δ. =	458.756470	
571.2	571.2				
470		1.000000 x	70.390000 =	70.390000	
114		8.000000 x	23.886192 =	191.089536	
			H.Δ. =	261.479536	
572	572				
407		1.000000 x	55.210000 =	55.210000	
471		1.000000 x	61.000000 =	61.000000	
114		8.000000 x	23.886192 =	191.089536	
111		24.000000 x	15.741598 =	377.798352	
214		8.000000 x	4.160000 =	33.280000	
211		54.000000 x	1.218700 =	65.809800	
			AΘΡΟΙΣΜΑ =	784.187688	
			H.Δ. =	862.606457	
573	573				
407		1.000000 x	55.210000 =	55.210000	
472		.250000 x	26.510000 =	6.627500	
473		1.000000 x	17.050000 =	17.050000	
474		1.000000 x	35.040000 =	35.040000	
474		.250000 x	35.040000 =	8.760000	
473		.250000 x	17.050000 =	4.262500	
407		.250000 x	55.210000 =	13.802500	
472		1.000000 x	26.510000 =	26.510000	
115		16.000000 x	21.778427 =	348.454832	
111		24.000000 x	15.741598 =	377.798352	
214		8.000000 x	4.160000 =	33.280000	
211		54.000000 x	1.218700 =	65.809800	
			AΘΡΟΙΣΜΑ =	992.605484	
			H.Δ. =	1,091.866032	

574	574				
475		1.000000 x	1,970.400000 =		1,970.400000
242		7.000000 x	5.000000 =		35.000000
211		590.000000 x	1.218700 =		719.033000
214		30.000000 x	4.160000 =		124.800000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
111		16.000000 x	15.741598 =		251.865568
				ΑΘΡΟΙΣΜΑ =	3,372.196256
				H.Δ. =	3,709.415882
574.1	574.1				
475		1.000000 x	1,970.400000 =		1,970.400000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
				H.Δ. =	2,241.497688
575	575				
476		1.000000 x	85.400000 =		85.400000
115		8.000000 x	21.778427 =		174.227416
211		470.000000 x	1.218700 =		572.789000
214		23.000000 x	4.160000 =		95.680000
				ΑΘΡΟΙΣΜΑ =	928.096416
				H.Δ. =	1,020.906058
575.1	575.1				
476		1.000000 x	85.400000 =		85.400000
115		8.000000 x	21.778427 =		174.227416
				H.Δ. =	259.627416
576	576				
477		1.000000 x	6.950000 =		6.950000
				ΑΘΡΟΙΣΜΑ =	6.950000
				H.Δ. =	7.645000
576.1	576.1				
477		1.000000 x	6.950000 =		6.950000
				H.Δ. =	6.950000

577	577				
478		1.000000 x	115.120000 =	115.120000	
211		70.000000 x	1.218700 =	85.309000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
111		8.000000 x	15.741598 =	125.932784	
214		4.000000 x	4.160000 =	16.640000	

		ΑΘΡΟΙΣΜΑ =		624.099472	

		H.Δ. =		686.509419	
577.1	577.1				
478		1.000000 x	115.120000 =	115.120000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

		H.Δ. =		386.217688	
578	578				
479		1.000000 x	185.200000 =	185.200000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
242		5.000000 x	5.000000 =	25.000000	
211		50.000000 x	1.218700 =	60.935000	
214		5.000000 x	4.160000 =	20.800000	

		ΑΘΡΟΙΣΜΑ =		592.277060	

		H.Δ. =		651.504766	
579	579				
480		1.000000 x	27.220000 =	27.220000	
214		1.000000 x	4.160000 =	4.160000	
117		8.000000 x	16.777917 =	134.223336	
212		28.000000 x	1.421100 =	39.790800	

		ΑΘΡΟΙΣΜΑ =		205.394136	

		H.Δ. =		225.933550	
580	580				
481		1.000000 x	812.490000 =	812.490000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
111		16.000000 x	15.741598 =	251.865568	
242		2.000000 x	5.000000 =	10.000000	
214		8.000000 x	4.160000 =	33.280000	
211		168.000000 x	1.218700 =	204.741600	

		ΑΘΡΟΙΣΜΑ =		1,583.474856	

		H.Δ. =		1,741.822342	

581	581			
481		1.000000 x	812.490000 =	812.490000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
			H.Δ. =	1,083.587688
7020.2	7020.2			
111		8.000000 x	15.741598 =	125.932784
570.1		.150000 x	604.403923 =	90.660588
571.2		.150000 x	261.479536 =	39.221930
571.1		.350000 x	458.756470 =	160.564765
570.2		.350000 x	127.284076 =	44.549427
569.2		.670000 x	620.296952 =	415.598958
567		1.000000 x	403.188672 =	403.188672
568.1		.450000 x	2,685.074172 =	1,208.283377
569.1		.330000 x	1,354.446535 =	446.967357
568.2		.550000 x	881.536952 =	484.845324
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	3,583.169069
7021.2	7021.2			
111		8.000000 x	15.741598 =	125.932784
568.1		.250000 x	2,685.074172 =	671.268543
569.1		.250000 x	1,354.446535 =	338.611634
570.1		.110000 x	604.403923 =	66.484432
571.2		.240000 x	261.479536 =	62.755089
571.1		.260000 x	458.756470 =	119.276682
570.2		.390000 x	127.284076 =	49.640790
569.2		.750000 x	620.296952 =	465.222714
568.2		.750000 x	881.536952 =	661.152714
567		1.000000 x	403.188672 =	403.188672
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	3,126.889941
7022.2	7022.2			
111		8.000000 x	15.741598 =	125.932784
568.1		.150000 x	2,685.074172 =	402.761126
569.1		.180000 x	1,354.446535 =	243.800376
570.1		.080000 x	604.403923 =	48.352314
571.2		.310000 x	261.479536 =	81.058656
571.1		.190000 x	458.756470 =	87.163729
570.2		.420000 x	127.284076 =	53.459312
569.2		.820000 x	620.296952 =	508.643501
568.2		.850000 x	881.536952 =	749.306409
567		1.000000 x	403.188672 =	403.188672
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	2,867.022767

613	613			
111		.140000 x	15.741598 =	2.203824
520		.003500 x	450.062954 =	1.575220
504		.002800 x	386.669290 =	1.082674
503		.000770 x	929.049673 =	.715368

			B.T =	5.577086
614	614			
112		.070000 x	17.312112 =	1.211848
509		.004375 x	416.459270 =	1.822009
518		.004375 x	902.567692 =	3.948734
504		.002800 x	386.669290 =	1.082674
503		.000700 x	929.049673 =	.650335

			B.T =	8.715600
621.1	621.1			
213		.100000 x	1.949500 =	.194950
116		.140000 x	20.419486 =	2.858728
504		.003500 x	386.669290 =	1.353343
508		.003500 x	588.679832 =	2.060379
111		.560000 x	15.741598 =	8.815295

			B.T =	15.282695
622	622			
213		.100000 x	1.949500 =	.194950
112		.070000 x	17.312112 =	1.211848
116		.140000 x	20.419486 =	2.858728
509		.003500 x	416.459270 =	1.457607
508		.003500 x	588.679832 =	2.060379
518		.004340 x	902.567692 =	3.917144
504		.003500 x	386.669290 =	1.353343

			B.T =	13.053999
6360.1 A1	6360.1 A1			
6304		9.800000 x	5.649342 =	55.363552
6330		.038000 x	182.373169 =	6.930180
6330		.190000 x	182.373169 =	34.650902
6314		7.650000 x	2.016845 =	15.428864
6314		.382500 x	2.016845 =	.771443

			B.T =	113.144942
6360.1 A2	6360.1 A2			
6304		.450000 x	5.649342 =	2.542204
6310		2.142000 x	1.440603 =	3.085772
6330		.013000 x	182.373169 =	2.370851

			B.T =	7.998827

6360.1 A3	6360.1 A3			
6304		.960000 x	5.649342 =	5.423368
6310		1.974000 x	1.440603 =	2.843750
6329.2		.037000 x	167.830919 =	6.209744

			B.T =	14.476863
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.649342 =	14.066862
6329.2		.109000 x	167.830919 =	18.293570

			B.T =	32.360432
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
6069.1		.056400 x	11.801385 =	.665598
113		.425000 x	20.419486 =	8.678282
113		2.975000 x	20.419486 =	60.747971

			B.T =	99.522441
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.649342 =	60.165492
6314		.392500 x	2.016845 =	.791612
6314		7.850000 x	2.016845 =	15.832233
6330		.205000 x	182.373169 =	37.386500
6330		.041000 x	182.373169 =	7.477300

			B.T =	121.653137
6360.2 A2	6360.2 A2			
6304		.750000 x	5.649342 =	4.237007
6330		.019000 x	182.373169 =	3.465090
6310		2.383500 x	1.440603 =	3.433677

			B.T =	11.135774
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.649342 =	6.440250
6329.2		.054000 x	167.830919 =	9.062870
6310		2.341500 x	1.440603 =	3.373172

			B.T =	18.876291
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.649342 =	15.818158
6329.2		.118000 x	167.830919 =	19.804048

			B.T =	35.622206

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
6069.1		.059400 x	11.801385 =	.701002
113		.382500 x	20.419486 =	7.810453
113		2.975000 x	20.419486 =	60.747971

			B.T =	113.405312
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.649342 =	78.525854
6330		.270000 x	182.373169 =	49.240756
6330		.054000 x	182.373169 =	9.848151
6314		.557500 x	2.016845 =	1.124391
6314		11.150000 x	2.016845 =	22.487822

			B.T =	161.226973
6360.3 A2	6360.3 A2			
6304		.940000 x	5.649342 =	5.310381
6310		3.360000 x	1.440603 =	4.840426
6330		.031000 x	182.373169 =	5.653568

			B.T =	15.804376
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.649342 =	10.338296
6310		10.678500 x	1.440603 =	15.383479
6329.2		.099000 x	167.830919 =	16.615261

			B.T =	42.337036
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.649342 =	19.320750
6329.2		.139000 x	167.830919 =	23.328498

			B.T =	42.649247
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
6069.1		.073800 x	11.801385 =	.870942
113		.340000 x	20.419486 =	6.942625
113		2.975000 x	20.419486 =	60.747971

			B.T =	156.853310

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.649342 =	91.801808
6330		.075000 x	182.373169 =	13.677988
6330		.375000 x	182.373169 =	68.389938
6314		17.700000 x	2.016845 =	35.698157
6314		.885000 x	2.016845 =	1.784908

			B.T =	211.352798
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.649342 =	5.988303
6310		4.641000 x	1.440603 =	6.685839
6330		.048000 x	182.373169 =	8.753912

			B.T =	21.428053
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.649342 =	12.824006
6310		20.454000 x	1.440603 =	29.466094
6329.2		.125000 x	167.830919 =	20.978865

			B.T =	63.268965
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.649342 =	15.818158
6329.2		.118000 x	167.830919 =	19.804048

			B.T =	35.622206
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
6069.1		.091800 x	11.801385 =	1.083367
113		.297500 x	20.419486 =	6.074797
113		4.250000 x	20.419486 =	86.782816

			B.T =	211.663341
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.649342 =	101.405689
6314		21.000000 x	2.016845 =	42.353745
6330		.440000 x	182.373169 =	80.244194
6330		.088000 x	182.373169 =	16.048839
6314		1.050000 x	2.016845 =	2.117687

			B.T =	242.170154
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.649342 =	6.892197
6330		.061000 x	182.373169 =	11.124763
6310		6.048000 x	1.440603 =	8.712767

			B.T =	26.729727

ΑΤΥΞ	2ο Τρίμηνο του 2011	Σελ. Ημ/νία	31 22/12/2011
6360.5 A3	6360.5 A3		
6304	2.480000 x	5.649342 =	14.010368
6329.2	.144000 x	167.830919 =	24.167652
6310	22.291500 x	1.440603 =	32.113202

		B.T =	70.291222
6360.5 A4	6360.5 A4		
6304	3.200000 x	5.649342 =	18.077894
6329.2	.112000 x	167.830919 =	18.797063

		B.T =	36.874957
6360.5 A5	6360.5 A5		
112	9.350000 x	17.312112 =	161.868247
113	5.950000 x	20.419486 =	121.495942
6069.1	.090600 x	11.801385 =	1.069205
113	.255000 x	20.419486 =	5.206969

		B.T =	289.640363
6360.6 A1	6360.6 A1		
6304	20.350000 x	5.649342 =	114.964110
6314	24.900000 x	2.016845 =	50.219441
6330	.580000 x	182.373169 =	105.776438
6330	.116000 x	182.373169 =	21.155288
6314	1.245000 x	2.016845 =	2.510972

		B.T =	294.626248
6360.6 A2	6360.6 A2		
6304	1.530000 x	5.649342 =	8.643493
6330	.092000 x	182.373169 =	16.778332
6310	10.206000 x	1.440603 =	14.702794

		B.T =	40.124619
6360.6 A3	6360.6 A3		
6304	2.670000 x	5.649342 =	15.083743
6329.2	.181000 x	167.830919 =	30.377396
6310	25.798500 x	1.440603 =	37.165396

		B.T =	82.626536
6360.6 A4	6360.6 A4		
6304	2.800000 x	5.649342 =	15.818158
6329.2	.118000 x	167.830919 =	19.804048

		B.T =	35.622206

6360.6 A5

6360.6 A5

112	12.750000 x	17.312112 =	220.729428
113	.212500 x	20.419486 =	4.339141
6069.1	.120000 x	11.801385 =	1.416166
113	7.650000 x	20.419486 =	156.209068

B.T = 382.693803

641

641

231	.200000 x	.861000 =	.172200
251	.001500 x	290.000000 =	.435000
113	.127500 x	20.419486 =	2.603484
111	.170000 x	15.741598 =	2.676072
252	.002500 x	290.000000 =	.725000

B.T = 6.611756

651

651

221	150.000000 x	.099900 =	14.985000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	416.459270 =	3.929293
509	.003060 x	416.459270 =	1.274365
T 630	.600000 x	1.823588 =	1.094153
T 625	.850000 x	22.023688 =	18.720135
511	.042500 x	728.382345 =	30.956250
112	.425000 x	17.312112 =	7.357648
111	1.275000 x	15.741598 =	20.070537

B.T = 106.787381

652

652

221	650.000000 x	.099900 =	64.935000
T 630	.320000 x	1.823588 =	.583548
T 625	1.000000 x	22.023688 =	22.023688
511	.042500 x	728.382345 =	30.956250
509	.001632 x	416.459270 =	.679662
509	.009435 x	416.459270 =	3.929293
111	1.275000 x	15.741598 =	20.070537
112	.425000 x	17.312112 =	7.357648

B.T = 150.535626

652.1

652.1

221	450.000000 x	.099900 =	44.955000
111	1.275000 x	15.741598 =	20.070537
509	.010001 x	416.459270 =	4.165009
T 630	.320000 x	1.823588 =	.583548
T 625	1.060000 x	22.023688 =	23.345109
511	.042500 x	728.382345 =	30.956250
510	.001632 x	405.954270 =	.662517
112	.425000 x	17.312112 =	7.357648

B.T = 132.095619

652.2	652.2			
221		900.000000 x	.099900 =	89.910000
509		.007548 x	416.459270 =	3.143435
T 630		.320000 x	1.823588 =	.583548
T 625		.800000 x	22.023688 =	17.618950
511		.042500 x	728.382345 =	30.956250
510		.001632 x	405.954270 =	.662517
112		.425000 x	17.312112 =	7.357648
111		1.275000 x	15.741598 =	20.070537

			B.T =	170.302885
700	700			
397.4		4.000000 x	.167500 =	.670000
113		.935000 x	20.419486 =	19.092219
397.5		2.150000 x	.000000 =	.000000
221		13.000000 x	.099900 =	1.298700
324		7.650000 x	.580000 =	4.437000

			B.T =	
7001 A	7001 A			
502		.000365 x	811.678573 =	.296263
557		.001094 x	836.339557 =	.914955

			AΘΡΟΙΣΜΑ =	1.211218
	B.T =	.200000 x	1.211218 =	.242244

7001 B	7001 B			
558		.000700 x	1,137.738457 =	.796417

			B.T =	.796417
7001 E	7001 E			
503		.000875 x	929.049673 =	.812918
554		.000875 x	34.408000 =	.030107

			B.T =	.843025
7001 Γ	7001 Γ			
501		.000700 x	619.220352 =	.433454
502		.000700 x	811.678573 =	.568175

			B.T =	1.001629

7001 Δ	7001 Δ			
502		.000292 x	811.678573 =	.237010
510		.000292 x	405.954270 =	.118539
X 630.1		.060000 x	1.705008 =	.102300
X 630		.060000 x	1.501778 =	.090107

			AΘΡΟΙΣΜΑ =	.547956
	B.T =	.600000 x	.547956 =	.328774

7003 Α	7003 Α			
502		.000365 x	811.678573 =	.296263
557		.001094 x	836.339557 =	.914955

			AΘΡΟΙΣΜΑ =	1.211218
	B.T =	.100000 x	1.211218 =	.121122

7003 Β	7003 Β			
559		.000464 x	1,342.068957 =	.622720

			B.T =	.622720
7003 Γ	7003 Γ			
502		.000700 x	811.678573 =	.568175

			B.T =	.568175
7003 Δ	7003 Δ			
502		.000875 x	811.678573 =	.710219
562		.000875 x	126.190900 =	.110417

			B.T =	.820636
7005 Α	7005 Α			
502		.000365 x	811.678573 =	.296263
557		.001094 x	836.339557 =	.914955

			AΘΡΟΙΣΜΑ =	1.211218
	B.T =	.100000 x	1.211218 =	.121122

7005 Β	7005 Β			
559		.000812 x	1,342.068957 =	1.089760

			B.T =	1.089760
7005 Ε	7005 Ε			
502		.000875 x	811.678573 =	.710219
562		.000875 x	126.190900 =	.110417

			B.T =	.820636

7005 Γ	7005 Γ			
559		.000232 x	1,342.068957 =	.311360

			B.T =	.311360
7005 Δ	7005 Δ			
502		.000700 x	811.678573 =	.568175

			B.T =	.568175
7010 Α	7010 Α			
558		.000315 x	1,137.738457 =	.358388

			B.T =	.358388
7010 Β	7010 Β			
558		.000473 x	1,137.738457 =	.538150

			B.T =	.538150
7010 Ε	7010 Ε			
503		.000875 x	929.049673 =	.812918
553		.000875 x	259.380000 =	.226958

			B.T =	1.039876
7010 Γ	7010 Γ			
502		.000700 x	811.678573 =	.568175

			B.T =	.568175
7010 Δ	7010 Δ			
502		.000292 x	811.678573 =	.237010
X 630.1		.060000 x	1.705008 =	.102300
X 630		.060000 x	1.501778 =	.090107
510		.000292 x	405.954270 =	.118539

			AΘΡΟΙΣΜΑ =	.547956
	B.T =	.600000 x	.547956 =	.328774

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.830000 x	18.724803 =	15.541586
T 617		.500000 x	6.458781 =	3.229391
509		.004718 x	416.459270 =	1.964855
509		.007831 x	416.459270 =	3.261293
223		350.000000 x	.119300 =	41.755000

			B.T =	79.115613

7016.2	7016.2			
570.1		.586500 x	604.403923 =	354.482901
570.2		1.113500 x	127.284076 =	141.730819
571.1		.586500 x	458.756470 =	269.060670
571.2		1.113500 x	261.479536 =	291.157463
			AΘΡΟΙΣΜΑ =	1,056.431852
	B.T =	.025000 x	1,056.431852 =	26.410796
7016.3	7016.3			
564		.212500 x	1,965.219995 =	417.609249
565		.637500 x	789.728540 =	503.451944
			AΘΡΟΙΣΜΑ =	921.061193
	B.T =	.025000 x	921.061193 =	23.026530
7016.4	7016.4			
7016.1		1.000000 x	79.115613 =	79.115613
7016.3		1.000000 x	23.026530 =	23.026530
7016.2		1.000000 x	26.410796 =	26.410796
			B.T =	128.552939
7016.5	7016.5			
7016.4		.200000 x	128.552939 =	25.710588
			B.T =	25.710588
7016.6	7016.6			
7016.4		.250000 x	128.552939 =	32.138235
7016.5		.250000 x	25.710588 =	6.427647
			B.T =	38.565882
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150
			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379
			B.T =	104.139379

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
223		350.000000 x	.119300 =	41.755000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.830000 x	18.724803 =	15.541586
T 617		.500000 x	6.458781 =	3.229391
509		.007831 x	416.459270 =	3.261293
509		.004718 x	416.459270 =	1.964855
			B.T =	79.115613
7017.2	7017.2			
564		.425000 x	1,965.219995 =	835.218498
565		.425000 x	789.728540 =	335.634630
			AΘΡΟΙΣΜΑ =	1,170.853127
	B.T =	.012500 x	1,170.853127 =	14.635664
7017.3	7017.3			
7017.1		1.000000 x	79.115613 =	79.115613
7017.2		1.000000 x	14.635664 =	14.635664
			B.T =	93.751277
7017.4	7017.4			
7017.3		.200000 x	93.751277 =	18.750255
			B.T =	18.750255
7017.5	7017.5			
7017.3		.300000 x	93.751277 =	28.125383
7017.4		.300000 x	18.750255 =	5.625077
			B.T =	33.750460
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150
			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689
			B.T =	52.069689

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
509		.007548 x	416.459270 =	3.143435
T 623		.800000 x	18.724803 =	14.979842
509		.004718 x	416.459270 =	1.964855
223		350.000000 x	.119300 =	41.755000
T 625		.500000 x	22.023688 =	11.011844
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
			B.T =	79.728465
7019 A2	7019 A2			
555		.012143 x	774.905991 =	9.409683
			B.T =	9.409683
7019 A3	7019 A3			
570.1		.850000 x	604.403923 =	513.743335
571.1		.850000 x	458.756470 =	389.943000
571.2		.850000 x	261.479536 =	222.257606
570.2		.850000 x	127.284076 =	108.191465
			AΘΡΟΙΣΜΑ =	1,234.135404
	B.T =	.014286 x	1,234.135404 =	17.630858
7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563
			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	79.728465 =	79.728465
7019 A5		1.000000 x	17.356563 =	17.356563
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A3		1.000000 x	17.630858 =	17.630858
7019 A2		1.000000 x	9.409683 =	9.409683
			B.T =	193.363023
7019 A7	7019 A7			
7019 A6		.100000 x	193.363023 =	19.336302
			B.T =	19.336302

710	710			
397.3		.006660 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
113		.170000 x	20.419486 =	3.471313
252		.001000 x	290.000000 =	.290000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	386.669290 =	1.943013
509		.003750 x	416.459270 =	1.561722

			B.T =	3.504735
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
520		.005270 x	450.062954 =	2.371832
504		.004250 x	386.669290 =	1.643344
503		.001190 x	929.049673 =	1.105569

			B.T =	6.458781
T 621	T 621			
213		.100000 x	1.949500 =	.194950
508		.004250 x	588.679832 =	2.501889
116		.170000 x	20.419486 =	3.471313
111		.680000 x	15.741598 =	10.704287

			B.T =	16.872439
T 623	T 623			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
116		.170000 x	20.419486 =	3.471313
504		.004250 x	386.669290 =	1.643344
509		.004250 x	416.459270 =	1.769952
518		.008500 x	902.567692 =	7.671825
508		.004250 x	588.679832 =	2.501889

			B.T =	18.724803

T 625	T 625			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
504		.004250 x	386.669290 =	1.643344
509		.004250 x	416.459270 =	1.769952
518		.012155 x	902.567692 =	10.970710
508		.004250 x	588.679832 =	2.501889
116		.170000 x	20.419486 =	3.471313

			B.T =	22.023688
T 630	T 630			
512		.017000 x	107.269886 =	1.823588

			B.T =	1.823588
T 630.1	T 630.1			
510		.005100 x	405.954270 =	2.070367

			B.T =	2.070367
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678

			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
520		.004340 x	450.062954 =	1.953273
504		.003500 x	386.669290 =	1.353343
503		.000980 x	929.049673 =	.910469

			B.T =	5.318996
X 621	X 621			
213		.100000 x	1.949500 =	.194950
508		.003500 x	588.679832 =	2.060379
111		.560000 x	15.741598 =	8.815295
116		.140000 x	20.419486 =	2.858728

			B.T =	13.929352
X 623	X 623			
213		.100000 x	1.949500 =	.194950
504		.003500 x	386.669290 =	1.353343
518		.007000 x	902.567692 =	6.317974
509		.003500 x	416.459270 =	1.457607
508		.003500 x	588.679832 =	2.060379
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	15.454829

X 625	X 625			
213		.100000 x	1.949500 =	.194950
509		.003500 x	416.459270 =	1.457607
518		.010010 x	902.567692 =	9.034703
504		.003500 x	386.669290 =	1.353343
508		.003500 x	588.679832 =	2.060379
112		.070000 x	17.312112 =	1.211848
116		.140000 x	20.419486 =	2.858728
			B.T =	18.171558
X 630	X 630			
512		.014000 x	107.269886 =	1.501778
			B.T =	1.501778
X 630.1	X 630.1			
510		.004200 x	405.954270 =	1.705008
			B.T =	1.705008
2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	416.459270 =	1.964855
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
509		.007548 x	416.459270 =	3.143435
509		.001275 x	416.459270 =	.530986
T 625		.500000 x	22.023688 =	11.011844
641		3.000000 x	6.611756 =	19.835268
T 630		.250000 x	1.823588 =	.455897
			T.E =	155.029040
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	416.459270 =	8.070981
			T.E =	74.972772
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	416.459270 =	3.362909
			T.E =	43.503984
6051	6051			
502		.000175 x	811.678573 =	.142044
			T.E =	.142044

6052	6052			
501		.000117 x	619.220352 =	.072449
521		.000088 x	428.572773 =	.037714
502		.000088 x	811.678573 =	.071428

			T.E =	.181591
6053	6053			
502		.000318 x	811.678573 =	.258114
507		.001000 x	956.739507 =	.956740

			T.E =	1.214853
6054	6054			
112		.004900 x	17.312112 =	.084829
507		.001077 x	956.739507 =	1.030408
509		.002975 x	416.459270 =	1.238966

			T.E =	2.354204
6055	6055			
213		.400000 x	1.949500 =	.779800
508		.007000 x	588.679832 =	4.120759
504		.001400 x	386.669290 =	.541337
503		.001167 x	929.049673 =	1.084201
116		.280000 x	20.419486 =	5.717456
112		.490000 x	17.312112 =	8.482935

			T.E =	20.726488
6056	6056			
507		.001750 x	956.739507 =	1.674294

			T.E =	1.674294
6057	6057			
506		.087500 x	694.159607 =	60.738966

			T.E =	60.738966
6058	6058			
507		.087500 x	956.739507 =	83.714707

			T.E =	83.714707
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
502		.001400 x	811.678573 =	1.136350
509		.002975 x	416.459270 =	1.238966
507		.001077 x	956.739507 =	1.030408
501		.000583 x	619.220352 =	.361005

			T.E =	3.887915
6062	6062			
213		.400000 x	1.949500 =	.779800
509		.002800 x	416.459270 =	1.166086
508		.002800 x	588.679832 =	1.648304
502		.002000 x	811.678573 =	1.623357
116		.175000 x	20.419486 =	3.573410
507		.001400 x	956.739507 =	1.339435
112		.175000 x	17.312112 =	3.029620

			T.E =	13.160012
6063	6063			
112		.700000 x	17.312112 =	12.118478
509		.003641 x	416.459270 =	1.516328
112		.070000 x	17.312112 =	1.211848
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696

			T.E =	18.482198
6064	6064			
112		.140000 x	17.312112 =	2.423696
112		.070000 x	17.312112 =	1.211848
509		.003641 x	416.459270 =	1.516328
507		.014000 x	956.739507 =	13.394353

			T.E =	18.546225
6065	6065			
506		.002800 x	694.159607 =	1.943647
506		.002100 x	694.159607 =	1.457735

			T.E =	3.401382

6066	6066			
111		.070000 x	15.741598 =	1.101912
502		.000700 x	811.678573 =	.568175

			T.E =	1.670087
6067	6067			
111		.980000 x	15.741598 =	15.426766
X 630.1		.100000 x	1.705008 =	.170501
X 630		.100000 x	1.501778 =	.150178

			T.E =	15.747445
6068	6068			
111		.560000 x	15.741598 =	8.815295
X 630.1		.200000 x	1.705008 =	.341002
X 630		.200000 x	1.501778 =	.300356
622		1.351351 x	13.053999 =	17.640535
509		.016497 x	416.459270 =	6.870329
112		.560000 x	17.312112 =	9.694783

			T.E =	43.662298
6068.1	6068.1			
111		.560000 x	15.741598 =	8.815295
614		1.351351 x	8.715600 =	11.777835
112		.560000 x	17.312112 =	9.694783
X 630.1		.200000 x	1.705008 =	.341002
X 630		.200000 x	1.501778 =	.300356
509		.016497 x	416.459270 =	6.870329

			T.E =	37.799598
6069	6069			
112		.070000 x	17.312112 =	1.211848
X 625		1.050000 x	18.171558 =	19.080136
509		.012017 x	416.459270 =	5.004591

			T.E =	25.296575
6069.1	6069.1			
112		.070000 x	17.312112 =	1.211848
X 617		1.050000 x	5.318996 =	5.584946
509		.012017 x	416.459270 =	5.004591

			T.E =	11.801385
6070	6070			
501		.000467 x	619.220352 =	.289176

			T.E =	.289176

6071	6071			
504		.002333 x	386.669290 =	.902099
509		.002975 x	416.459270 =	1.238966

			T.E =	2.141066
6072	6072			
504		.003500 x	386.669290 =	1.353343
509		.002800 x	416.459270 =	1.166086

			T.E =	2.519428
6073	6073			
509		.000833 x	416.459270 =	.346911

			T.E =	.346911
6074	6074			
509		.000784 x	416.459270 =	.326504

			T.E =	.326504
6075	6075			
509		.001096 x	416.459270 =	.456439

			T.E =	.456439
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	929.049673 =	.650335
509		.003914 x	416.459270 =	1.630022
507		.000840 x	956.739507 =	.803661

			T.E =	3.168847
6077	6077			
503		.001400 x	929.049673 =	1.300670

			T.E =	1.300670
6078	6078			
112		.004900 x	17.312112 =	.084829
501		.000056 x	619.220352 =	.034676
505		.001400 x	846.084457 =	1.184518
503		.000350 x	929.049673 =	.325167

			T.E =	1.629191

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
556		.001400 x	1,152.159457 =	1.613023
503		.000350 x	929.049673 =	.325167
501		.000056 x	619.220352 =	.034676

			T.E =	2.057696
6079	6079			
112		.014000 x	17.312112 =	.242370
509		.000630 x	416.459270 =	.262369
X 630		.150000 x	1.501778 =	.225267
529		.000980 x	451.695873 =	.442662
502		.000350 x	811.678573 =	.284088
501		.000700 x	619.220352 =	.433454

			T.E =	1.890209
6080	6080			
112		.014000 x	17.312112 =	.242370
501		.000583 x	619.220352 =	.361005
X 630.1		.100000 x	1.705008 =	.170501
X 630		.100000 x	1.501778 =	.150178
529		.000700 x	451.695873 =	.316187
502		.000292 x	811.678573 =	.237010

			T.E =	1.477251
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
112		.420000 x	17.312112 =	7.271087
112		.280000 x	17.312112 =	4.847391
506		.007000 x	694.159607 =	4.859117

			T.E =	23.589067
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
112		.070000 x	17.312112 =	1.211848
6081.1		1.000000 x	23.589067 =	23.589067

			T.E =	35.820033
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
6081.1		1.000000 x	23.589067 =	23.589067
112		.140000 x	17.312112 =	2.423696

			T.E =	48.051000

6081.4	6081.4			
111		2.100000 x	15.741598 =	33.057356
6081.1		1.000000 x	23.589067 =	23.589067
112		.210000 x	17.312112 =	3.635544

			T.E =	60.281966
6082.1	6082.1			
213		.400000 x	1.949500 =	.779800
116		.700000 x	20.419486 =	14.293640
508		.070000 x	588.679832 =	41.207588
116		1.400000 x	20.419486 =	28.587280
111		1.400000 x	15.741598 =	22.038237

			T.E =	106.906546
6082.2	6082.2			
111		.700000 x	15.741598 =	11.019119
112		.140000 x	17.312112 =	2.423696
6082.1		1.000000 x	106.906546 =	106.906546

			T.E =	120.349360
6082.3	6082.3			
111		1.400000 x	15.741598 =	22.038237
6082.1		1.000000 x	106.906546 =	106.906546
112		.280000 x	17.312112 =	4.847391

			T.E =	133.792175
6082.4	6082.4			
111		2.100000 x	15.741598 =	33.057356
6082.1		1.000000 x	106.906546 =	106.906546
112		.420000 x	17.312112 =	7.271087

			T.E =	147.234989
6083.1	6083.1			
111		.280000 x	15.741598 =	4.407647
112		.140000 x	17.312112 =	2.423696
112		.280000 x	17.312112 =	4.847391
506		.005833 x	694.159607 =	4.049033

			T.E =	15.727767
6083.2	6083.2			
111		.560000 x	15.741598 =	8.815295
6083.1		1.000000 x	15.727767 =	15.727767
112		.070000 x	17.312112 =	1.211848

			T.E =	25.754910

6083.3	6083.3			
111		1.120000 x	15.741598 =	17.630590
112		.140000 x	17.312112 =	2.423696
6083.1		1.000000 x	15.727767 =	15.727767

			T.E =	35.782052
6083.4	6083.4			
111		1.680000 x	15.741598 =	26.445885
6083.1		1.000000 x	15.727767 =	15.727767
112		.210000 x	17.312112 =	3.635544

			T.E =	45.809195
6084.1	6084.1			
213		.400000 x	1.949500 =	.779800
508		.035000 x	588.679832 =	20.603794
116		.700000 x	20.419486 =	14.293640
116		1.050000 x	20.419486 =	21.440460
111		1.470000 x	15.741598 =	23.140149

			T.E =	80.257844
6084.2	6084.2			
111		.560000 x	15.741598 =	8.815295
6084.1		1.000000 x	80.257844 =	80.257844
112		.105000 x	17.312112 =	1.817772

			T.E =	90.890911
6084.3	6084.3			
111		1.120000 x	15.741598 =	17.630590
112		.210000 x	17.312112 =	3.635544
6084.1		1.000000 x	80.257844 =	80.257844

			T.E =	101.523977
6084.4	6084.4			
111		1.680000 x	15.741598 =	26.445885
112		.315000 x	17.312112 =	5.453315
6084.1		1.000000 x	80.257844 =	80.257844

			T.E =	112.157044
6085.1	6085.1			
111		.140000 x	15.741598 =	2.203824
506		.004666 x	694.159607 =	3.238949
502		.001400 x	811.678573 =	1.136350
112		.140000 x	17.312112 =	2.423696

			T.E =	9.002818

6085.2	6085.2			
111		.350000 x	15.741598 =	5.509559
112		.070000 x	17.312112 =	1.211848
6085.1		1.000000 x	9.002818 =	9.002818

			T.E =	15.724225
6085.3	6085.3			
111		.700000 x	15.741598 =	11.019119
112		.140000 x	17.312112 =	2.423696
6085.1		1.000000 x	9.002818 =	9.002818

			T.E =	22.445632
6085.4	6085.4			
111		1.050000 x	15.741598 =	16.528678
112		.210000 x	17.312112 =	3.635544
6085.1		1.000000 x	9.002818 =	9.002818

			T.E =	29.167039
6086.1	6086.1			
213		.400000 x	1.949500 =	.779800
508		.008750 x	588.679832 =	5.150949
116		.490000 x	20.419486 =	10.005548
116		.280000 x	20.419486 =	5.717456
111		1.120000 x	15.741598 =	17.630590

			T.E =	39.284343
6086.2	6086.2			
111		.350000 x	15.741598 =	5.509559
6086.1		1.000000 x	39.284343 =	39.284343
112		.105000 x	17.312112 =	1.817772

			T.E =	46.611674
6086.3	6086.3			
111		.700000 x	15.741598 =	11.019119
112		.210000 x	17.312112 =	3.635544
6086.1		1.000000 x	39.284343 =	39.284343

			T.E =	53.939005
6086.4	6086.4			
111		1.050000 x	15.741598 =	16.528678
112		.315000 x	17.312112 =	5.453315
6086.1		1.000000 x	39.284343 =	39.284343

			T.E =	61.266336

6087	6087				
252		.001000 x	290.000000 =	.290000	
113		.210000 x	20.419486 =	4.288092	
112		.350000 x	17.312112 =	6.059239	
111		.210000 x	15.741598 =	3.305736	

			T.E =	13.943067	
6088	6088				
6081.1		1.000000 x	23.589067 =	23.589067	
6081.1		.900000 x	23.589067 =	21.230160	

			T.E =	44.819227	
6089	6089				
6082.1		1.000000 x	106.906546 =	106.906546	
6082.1		.900000 x	106.906546 =	96.215891	

			T.E =	203.122437	
6090	6090				
6083.1		1.000000 x	15.727767 =	15.727767	
6083.1		1.300000 x	15.727767 =	20.446097	

			T.E =	36.173864	
6091	6091				
6084.1		1.000000 x	80.257844 =	80.257844	
6084.1		1.300000 x	80.257844 =	104.335197	

			T.E =	184.593041	
6100	6100				
231		.200000 x	.861000 =	.172200	
252.1		.002000 x	.000000 =	.000000	
113		.105000 x	20.419486 =	2.144046	
251		.002000 x	290.000000 =	.580000	
111		.175000 x	15.741598 =	2.754780	

			T.E =		
6101	6101				
231		15.000000 x	.861000 =	12.915000	
251		.068000 x	290.000000 =	19.720000	
252.1		.020000 x	.000000 =	.000000	
113		3.500000 x	20.419486 =	71.468201	
112		3.500000 x	17.312112 =	60.592392	
252		.018000 x	290.000000 =	5.220000	

			T.E =		

6102	6102			
244		1.000000 x	2.700000 =	2.700000
506		.000070 x	694.159607 =	.048591
509		.000051 x	416.459270 =	.021239
506		.000070 x	694.159607 =	.048591
112		.001400 x	17.312112 =	.024237
112		.002100 x	17.312112 =	.036355

			T.E =	2.879014
6103	6103			
244		.125000 x	2.700000 =	.337500
112		.004200 x	17.312112 =	.072711
112		.002800 x	17.312112 =	.048474
509		.000102 x	416.459270 =	.042479
506		.000140 x	694.159607 =	.097182
506		.000140 x	694.159607 =	.097182

			T.E =	.695528
6104	6104			
236		3.000000 x	.683000 =	2.049000
517		.017500 x	2,230.174289 =	39.028050
111		.280000 x	15.741598 =	4.407647
113		.280000 x	20.419486 =	5.717456

			T.E =	51.202154
6105	6105			
111		.210000 x	15.741598 =	3.305736
113		.140000 x	20.419486 =	2.858728
517		.014000 x	2,230.174289 =	31.222440

			T.E =	37.386904
6106	6106			
512		.087500 x	107.269886 =	9.386115

			T.E =	9.386115
6107	6107			
513		.087500 x	160.954329 =	14.083504

			T.E =	14.083504
6108	6108			
514		.087500 x	216.177342 =	18.915517

			T.E =	18.915517

6109	6109			
515		.087500 x	291.334678 =	25.491784

			T.E =	25.491784
6110	6110			
516		.087500 x	371.233014 =	32.482889

			T.E =	32.482889
6120	6120			
112		.004200 x	17.312112 =	.072711
502		.001750 x	811.678573 =	1.420438
501		.000070 x	619.220352 =	.043345

			T.E =	1.536494
6121	6121			
112		.004200 x	17.312112 =	.072711
501		.000049 x	619.220352 =	.030342
507		.000875 x	956.739507 =	.837147
509		.003113 x	416.459270 =	1.296438
505		.000420 x	846.084457 =	.355355
502		.000315 x	811.678573 =	.255679

			T.E =	2.847672
6151	6151			
243		1.020000 x	2.400000 =	2.448000
243		.080000 x	2.400000 =	.192000

			T.E =	2.640000
6152	6152			
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	3.207186
6153	6153			
111		.425000 x	15.741598 =	6.690179
509		.003570 x	416.459270 =	1.486760
T 611		1.050000 x	20.070537 =	21.074064
112		.425000 x	17.312112 =	7.357648

			T.E =	36.608650

6154	6154				
111		.425000 x	15.741598 =	6.690179	
T 621		1.050000 x	16.872439 =	17.716061	
509		.003570 x	416.459270 =	1.486760	
112		.425000 x	17.312112 =	7.357648	
			T.E =	33.250647	
6155	6155				
111		.680000 x	15.741598 =	10.704287	
652		.100000 x	150.535626 =	15.053563	
T 621		.350000 x	16.872439 =	5.905354	
509		.003220 x	416.459270 =	1.340999	
113		1.275000 x	20.419486 =	26.034845	
			T.E =	59.039046	
6156	6156				
251		.000500 x	290.000000 =	.145000	
652		.010000 x	150.535626 =	1.505356	
113		.680000 x	20.419486 =	13.885250	
112		.425000 x	17.312112 =	7.357648	
			T.E =	22.893254	
6157	6157				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	416.459270 =	1.224390	
112		.420000 x	17.312112 =	7.271087	
X 621		1.050000 x	13.929352 =	14.625820	
			T.E =	29.732768	
6157.1	6157.1				
111		.420000 x	15.741598 =	6.611471	
112		.420000 x	17.312112 =	7.271087	
509		.002940 x	416.459270 =	1.224390	
X 611		1.050000 x	16.528678 =	17.355112	
			T.E =	32.462060	
6158	6158				
111		.560000 x	15.741598 =	8.815295	
504		.001400 x	386.669290 =	.541337	
621.1		1.050000 x	15.282695 =	16.046830	
509		.002940 x	416.459270 =	1.224390	
			T.E =	26.627852	

6201.1	6201.1				
261.1		1.000000 x	13.500000 =	13.500000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	23.191284	
6201.2	6201.2				
261		1.000000 x	15.100000 =	15.100000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	24.791284	
6201.3	6201.3				
261.2		1.000000 x	20.700000 =	20.700000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	30.391284	
6201.4	6201.4				
262		1.000000 x	26.300000 =	26.300000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	35.991284	
6201.5	6201.5				
263		1.000000 x	32.400000 =	32.400000	
113		.637500 x	20.419486 =	13.017422	
111		.850000 x	15.741598 =	13.380358	

			T.E =	58.797781	
6201.6	6201.6				
263.2		1.000000 x	46.700000 =	46.700000	
113		.637500 x	20.419486 =	13.017422	
111		.850000 x	15.741598 =	13.380358	

			T.E =	73.097781	
6201.7	6201.7				
264		1.000000 x	64.100000 =	64.100000	
113		.637500 x	20.419486 =	13.017422	
111		.850000 x	15.741598 =	13.380358	

			T.E =	90.497781	

6202.1	6202.1			
281.1		1.000000 x	17.600000 =	17.600000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	27.291284
6202.2	6202.2			
281		1.000000 x	21.300000 =	21.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	30.991284
6202.3	6202.3			
281.2		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6202.4	6202.4			
282		1.000000 x	30.000000 =	30.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	39.691284
6202.5	6202.5			
283		1.000000 x	36.300000 =	36.300000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	62.697781
6202.6	6202.6			
283.1		1.000000 x	55.500000 =	55.500000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	81.897781
6202.7	6202.7			
284		1.000000 x	75.400000 =	75.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	101.797781

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.255000 x	15.741598 =	4.014107

T.E =

6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

T.E =

6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

T.E =

6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

T.E =

6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	18.171558 =	12.720091
X 623		.400000 x	15.454829 =	6.181932
509		.005439 x	416.459270 =	2.265122
509		.003108 x	416.459270 =	1.294355
112		.420000 x	17.312112 =	7.271087

T.E = 33.038322

6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
509		.008702 x	416.459270 =	3.624029
613		1.050000 x	5.577086 =	5.855940

T.E = 20.056791

6205	6205			
111		.210000 x	15.741598 =	3.305736
112		.070000 x	17.312112 =	1.211848
509		.002800 x	416.459270 =	1.166086
613		1.000000 x	5.577086 =	5.577086

			T.E =	11.260755
6251	6251			
509		.002800 x	416.459270 =	1.166086
613		1.000000 x	5.577086 =	5.577086

			T.E =	6.743172
6252	6252			
509		.000784 x	416.459270 =	.326504

			T.E =	.326504
6253	6253			
112		.210000 x	17.312112 =	3.635544
X 630.1		.200000 x	1.705008 =	.341002
501		.002917 x	619.220352 =	1.806266
521		.007000 x	428.572773 =	3.000009
X 630		.200000 x	1.501778 =	.300356

			T.E =	9.083176
6301	6301			
231		.200000 x	.861000 =	.172200
252		.002500 x	290.000000 =	.725000
113		.127500 x	20.419486 =	2.603484
111		.170000 x	15.741598 =	2.676072
251		.001500 x	290.000000 =	.435000

			T.E =	6.611756
6302	6302			
231		.300000 x	.861000 =	.258300
251		.002000 x	290.000000 =	.580000
111		.212500 x	15.741598 =	3.345090
252		.004000 x	290.000000 =	1.160000
113		1.232500 x	20.419486 =	25.167016

			T.E =	30.510406
6303	6303			
6302		.666660 x	30.510406 =	20.340067

			T.E =	20.340067

6304	6304			
234.2		.018000 x	1.001500 =	.018027
112		.212500 x	17.312112 =	3.678824
113		.010200 x	20.419486 =	.208279
113		.085000 x	20.419486 =	1.735656
235		.012000 x	.713000 =	.008556

			T.E =	5.649342
6310	6310			
233		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603
6311	6311			
233.1		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603
6312	6312			
233.3		1.010000 x	8.100000 =	8.181000
233.3		.303000 x	8.100000 =	2.454300
113		.085000 x	20.419486 =	1.735656
113		.085000 x	20.419486 =	1.735656

			T.E =	14.106613
6313	6313			
233.2		1.050000 x	.598400 =	.628320
113		.025500 x	20.419486 =	.520697

			T.E =	1.149017
6314	6314			
233.2		1.050000 x	.598400 =	.628320
113		.068000 x	20.419486 =	1.388525

			T.E =	2.016845
6320.1	6320.1			
396.1		1.000000 x	1.400000 =	1.400000
113		.000850 x	20.419486 =	.017357

			T.E =	1.417357

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	20.419486 =	.017357

			T.E =	.787357
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	20.419486 =	.017357

			T.E =	1.697357
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	20.419486 =	.017357

			T.E =	.997357
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	20.419486 =	.017357

			T.E =	1.197357
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	20.419486 =	.017357

			T.E =	1.597357
6321	6321			
221		140.000000 x	.099900 =	13.986000
111		.765000 x	15.741598 =	12.042322
113		.595000 x	20.419486 =	12.149594
509		.003302 x	416.459270 =	1.375149
509		.003019 x	416.459270 =	1.257291
T 630.1		.175000 x	2.070367 =	.362314
T 630		.175000 x	1.823588 =	.319128
T 625		.350000 x	22.023688 =	7.708291
T 623		.560000 x	18.724803 =	10.485890
T 621		.300000 x	16.872439 =	5.061732
511		.023800 x	728.382345 =	17.335500
509		.005284 x	416.459270 =	2.200571
112		.714000 x	17.312112 =	12.360848

			T.E =	96.644629

6322	6322			
221		140.000000 x	.099900 =	13.986000
509		.003019 x	416.459270 =	1.257291
T 623		.560000 x	18.724803 =	10.485890
T 630.1		.175000 x	2.070367 =	.362314
T 630		.175000 x	1.823588 =	.319128
T 625		.350000 x	22.023688 =	7.708291
511		.023800 x	728.382345 =	17.335500
T 611		.300000 x	20.070537 =	6.021161
509		.003302 x	416.459270 =	1.375149
509		.005284 x	416.459270 =	2.200571
113		.595000 x	20.419486 =	12.149594
111		.765000 x	15.741598 =	12.042322
112		.714000 x	17.312112 =	12.360848

T.E = 97.604058

6323	6323			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
509		.007548 x	416.459270 =	3.143435
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 106.838382

6323.1	6323.1			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	416.459270 =	3.143435
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
113		.850000 x	20.419486 =	17.356563

T.E = 99.055928

6324	6324			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
112		1.020000 x	17.312112 =	17.658354
509		.004718 x	416.459270 =	1.964855
113		.850000 x	20.419486 =	17.356563
509		.007548 x	416.459270 =	3.143435

T.E = 111.833382

6324.1	6324.1			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	416.459270 =	3.143435
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
113		.850000 x	20.419486 =	17.356563

T.E = 104.050928

6325	6325			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
509		.007548 x	416.459270 =	3.143435
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 116.828382

6325.1	6325.1			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	416.459270 =	3.143435
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
113		.850000 x	20.419486 =	17.356563

T.E = 109.045928

6326	6326			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
509		.007548 x	416.459270 =	3.143435
113		1.360000 x	20.419486 =	27.770501
112		1.190000 x	17.312112 =	20.601413

T.E = 135.180379

6326.1	6326.1			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
112		1.190000 x	17.312112 =	20.601413
509		.007548 x	416.459270 =	3.143435
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
113		1.360000 x	20.419486 =	27.770501

T.E = 127.397925

6327	6327			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
509		.007548 x	416.459270 =	3.143435
113		1.275000 x	20.419486 =	26.034845
112		2.295000 x	17.312112 =	39.731297

T.E = 157.464606

6327.1	6327.1			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	416.459270 =	3.143435
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
113		1.275000 x	20.419486 =	26.034845

T.E = 149.682152

6328	6328			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	416.459270 =	3.143435
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	416.459270 =	1.964855

T.E = 161.040919

6328.1	6328.1			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	416.459270 =	3.143435
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855
113		1.445000 x	20.419486 =	29.506157

T.E = 153.258465

6329	6329			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.034000 x	728.382345 =	24.765000
509		.007548 x	416.459270 =	3.143435
509		.004718 x	416.459270 =	1.964855
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 166.745919

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
509		.007548 x	416.459270 =	3.143435
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
511		.034000 x	728.382345 =	24.765000
509		.004718 x	416.459270 =	1.964855

T.E = 158.963465

6329.2	6329.2			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
T 625		.500000 x	22.023688 =	11.011844
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
113		1.445000 x	20.419486 =	29.506157
511		.034000 x	728.382345 =	24.765000
509		.007548 x	416.459270 =	3.143435
509		.004718 x	416.459270 =	1.964855

T.E = 167.830919

6329.3	6329.3			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
511		.034000 x	728.382345 =	24.765000
509		.007548 x	416.459270 =	3.143435
509		.004718 x	416.459270 =	1.964855
113		1.445000 x	20.419486 =	29.506157

T.E = 160.048465

6330	6330			
223		420.000000 x	.119300 =	50.106000
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	416.459270 =	3.143435
509		.004718 x	416.459270 =	1.964855
113		1.445000 x	20.419486 =	29.506157
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
511		.042500 x	728.382345 =	30.956250

T.E = 182.373169

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	416.459270 =	1.964855
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	416.459270 =	3.143435
511		.042500 x	728.382345 =	30.956250
T 617		.500000 x	6.458781 =	3.229391
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842

T.E = 174.590715

6331	6331			
222		450.000000 x	.116200 =	52.290000
113		5.525000 x	20.419486 =	112.817660
111		3.825000 x	15.741598 =	60.211612
T 623		.800000 x	18.724803 =	14.979842
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.500000 x	22.023688 =	11.011844
509		.004718 x	416.459270 =	1.964855
511		.042500 x	728.382345 =	30.956250
509		.007548 x	416.459270 =	3.143435
112		3.400000 x	17.312112 =	58.861181

T.E = 347.210168

6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
511		.042500 x	728.382345 =	30.956250
509		.007548 x	416.459270 =	3.143435
509		.004718 x	416.459270 =	1.964855
113		5.525000 x	20.419486 =	112.817660
112		3.400000 x	17.312112 =	58.861181
111		3.825000 x	15.741598 =	60.211612
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897

T.E = 339.427714

6351	6351			
221		120.000000 x	.099900 =	11.988000
112		1.275000 x	17.312112 =	22.072943
509		.004246 x	416.459270 =	1.768286
T 623		.850000 x	18.724803 =	15.916083
6301		1.000000 x	6.611756 =	6.611756
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 625		.450000 x	22.023688 =	9.910660
511		.034000 x	728.382345 =	24.765000
509		.008020 x	416.459270 =	3.340003
113		1.275000 x	20.419486 =	26.034845

T.E = 123.381063

6351.1	6351.1			
221		120.000000 x	.099900 =	11.988000
6301		1.000000 x	6.611756 =	6.611756
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.850000 x	18.724803 =	15.916083
T 617		.450000 x	6.458781 =	2.906451
511		.034000 x	728.382345 =	24.765000
509		.008020 x	416.459270 =	3.340003
509		.004246 x	416.459270 =	1.768286
112		1.275000 x	17.312112 =	22.072943
113		1.275000 x	20.419486 =	26.034845

T.E = 116.376855

6352	6352			
221		300.000000 x	.099900 =	29.970000
6301		1.000000 x	6.611756 =	6.611756
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
511		.034000 x	728.382345 =	24.765000
509		.007548 x	416.459270 =	3.143435
509		.004718 x	416.459270 =	1.964855
T 625		.500000 x	22.023688 =	11.011844
T 623		.800000 x	18.724803 =	14.979842
113		2.550000 x	20.419486 =	52.069689
112		2.125000 x	17.312112 =	36.788238

T.E = 182.278148

6352.1	6352.1			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.070367 =	.517592
T 630		.250000 x	1.823588 =	.455897
T 623		.800000 x	18.724803 =	14.979842
T 617		.500000 x	6.458781 =	3.229391
511		.034000 x	728.382345 =	24.765000
509		.007548 x	416.459270 =	3.143435
509		.004718 x	416.459270 =	1.964855
113		2.550000 x	20.419486 =	52.069689
6301		1.000000 x	6.611756 =	6.611756
112		2.125000 x	17.312112 =	36.788238
			T.E =	174.495694
6360.1	6360.1			
6360.1 A1		1.000000 x	113.144942 =	113.144942
6360.1 A2		1.000000 x	7.998827 =	7.998827
6360.1 A3		1.000000 x	14.476863 =	14.476863
6360.1 A5		1.000000 x	99.522441 =	99.522441
6360.1 A4		1.000000 x	32.360432 =	32.360432
			AΘΡΟΙΣΜΑ =	267.503505
	T.E =	.200000 x	267.503505 =	53.500701
6360.2	6360.2			
6360.2 A1		1.000000 x	121.653137 =	121.653137
6360.2 A5		1.000000 x	113.405312 =	113.405312
6360.2 A4		1.000000 x	35.622206 =	35.622206
6360.2 A2		1.000000 x	11.135774 =	11.135774
6360.2 A3		1.000000 x	18.876291 =	18.876291
			AΘΡΟΙΣΜΑ =	300.692720
	T.E =	.200000 x	300.692720 =	60.138544
6360.3	6360.3			
6360.3 A1		1.000000 x	161.226973 =	161.226973
6360.3 A3		1.000000 x	42.337036 =	42.337036
6360.3 A5		1.000000 x	156.853310 =	156.853310
6360.3 A4		1.000000 x	42.649247 =	42.649247
6360.3 A2		1.000000 x	15.804376 =	15.804376
			AΘΡΟΙΣΜΑ =	418.870942
	T.E =	.200000 x	418.870942 =	83.774188

6360.4	6360.4			
6360.4 A1		1.000000 x	211.352798 =	211.352798
6360.4 A2		1.000000 x	21.428053 =	21.428053
6360.4 A4		1.000000 x	35.622206 =	35.622206
6360.4 A5		1.000000 x	211.663341 =	211.663341
6360.4 A3		1.000000 x	63.268965 =	63.268965

			AΘΡΟΙΣΜΑ =	543.335363
	T.E =	.200000 x	543.335363 =	108.667073

6360.5	6360.5			
6360.5 A1		1.000000 x	242.170154 =	242.170154
6360.5 A5		1.000000 x	289.640363 =	289.640363
6360.5 A4		1.000000 x	36.874957 =	36.874957
6360.5 A3		1.000000 x	70.291222 =	70.291222
6360.5 A2		1.000000 x	26.729727 =	26.729727

			AΘΡΟΙΣΜΑ =	665.706423
	T.E =	.200000 x	665.706423 =	133.141285

6360.6	6360.6			
6360.6 A1		1.000000 x	294.626248 =	294.626248
6360.6 A2		1.000000 x	40.124619 =	40.124619
6360.6 A4		1.000000 x	35.622206 =	35.622206
6360.6 A3		1.000000 x	82.626536 =	82.626536
6360.6 A5		1.000000 x	382.693803 =	382.693803

			AΘΡΟΙΣΜΑ =	835.693412
	T.E =	.200000 x	835.693412 =	167.138682

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	20.419486 =	.347131
111		.085000 x	15.741598 =	1.338036

			T.E =	2.065167
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143
396.14		.003000 x	42.680000 =	.128040

			T.E =	16.933809
6371	6371			
326		.500000 x	1.310000 =	.655000
113		.212500 x	20.419486 =	4.339141
111		.212500 x	15.741598 =	3.345090

			T.E =	8.339230

6372	6372				
396.11		1.050000 x	2.960000 =	3.108000	
396.13		.700000 x	1.770000 =	1.239000	
111		.340000 x	15.741598 =	5.352143	
113		.340000 x	20.419486 =	6.942625	

			T.E =	16.641769	
6373	6373				
396.12		1.050000 x	4.250000 =	4.462500	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	20.419486 =	8.678282	
111		.425000 x	15.741598 =	6.690179	

			T.E =	21.069961	
6401	6401				
327		.500000 x	.540000 =	.270000	
113		.212500 x	20.419486 =	4.339141	

			T.E =	4.609141	
6402	6402				
252		.000500 x	290.000000 =	.145000	
111		.595000 x	15.741598 =	9.366251	
113		.595000 x	20.419486 =	12.149594	
652		.011500 x	150.535626 =	1.731160	
652.2		.005500 x	170.302885 =	.936666	

			T.E =	24.328671	
6403	6403				
251		.000500 x	290.000000 =	.145000	
111		.850000 x	15.741598 =	13.380358	
113		.850000 x	20.419486 =	17.356563	
652.2		.005500 x	170.302885 =	.936666	
652		.016500 x	150.535626 =	2.483838	

			T.E =	34.302425	
6404	6404				
111		1.275000 x	15.741598 =	20.070537	
113		1.700000 x	20.419486 =	34.713126	
652		.020000 x	150.535626 =	3.010713	

			T.E =	57.794376	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	57.794376 =	57.794376	

			T.E =		

6405	6405			
111		.425000 x	15.741598 =	6.690179
113		.850000 x	20.419486 =	17.356563
652		.020000 x	150.535626 =	3.010713

			T.E =	27.057455
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	25,662.000000 =	25,662.000000
386.9		.150000 x	25,662.000000 =	3,849.300000

			T.E =	29,511.300000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	76,825.000000 =	76,825.000000
386.40		.150000 x	76,825.000000 =	11,523.750000

			T.E =	88,348.750000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	113,082.000000 =	113,082.000000
386.30		.150000 x	113,082.000000 =	16,962.300000

			T.E =	130,044.300000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17				
386.64		1.000000 x	153,664.000000 =		153,664.000000
386.64		.150000 x	153,664.000000 =		23,049.600000
				T.E =	176,713.600000
6453.18	6453.18				
386.65		1.000000 x	.000000 =		.000000
386.65		.150000 x	.000000 =		.000000
				T.E =	
6453.19	6453.19				
386.66		1.000000 x	.000000 =		.000000
386.66		.150000 x	.000000 =		.000000
				T.E =	
6453.2	6453.2				
386.49		1.000000 x	.000000 =		.000000
386.49		.150000 x	.000000 =		.000000
				T.E =	
6453.20	6453.20				
386.67		1.000000 x	.000000 =		.000000
386.67		.150000 x	.000000 =		.000000
				T.E =	
6453.3	6453.3				
386.50		1.000000 x	.000000 =		.000000
386.50		.150000 x	.000000 =		.000000
				T.E =	
6453.4	6453.4				
386.51		1.000000 x	.000000 =		.000000
386.51		.150000 x	.000000 =		.000000
				T.E =	
6453.5	6453.5				
386.52		1.000000 x	.000000 =		.000000
386.52		.150000 x	.000000 =		.000000
				T.E =	

6453.6	6453.6				
386.53		1.000000 x	134,053.000000 =		134,053.000000
386.53		.150000 x	134,053.000000 =		20,107.950000
				T.E =	154,160.950000
6453.7	6453.7				
386.54		1.000000 x	.000000 =		.000000
386.54		.150000 x	.000000 =		.000000
				T.E =	
6453.8	6453.8				
386.55		1.000000 x	.000000 =		.000000
386.55		.150000 x	.000000 =		.000000
				T.E =	
6453.9	6453.9				
386.56		1.000000 x	.000000 =		.000000
386.56		.150000 x	.000000 =		.000000
				T.E =	
6454.1	6454.1				
386.68		1.000000 x	.000000 =		.000000
386.68		.150000 x	.000000 =		.000000
				T.E =	
6454.10	6454.10				
386.77		1.000000 x	.000000 =		.000000
386.77		.150000 x	.000000 =		.000000
				T.E =	
6454.11	6454.11				
386.78		1.000000 x	.000000 =		.000000
386.78		.150000 x	.000000 =		.000000
				T.E =	
6454.12	6454.12				
386.79		1.000000 x	.000000 =		.000000
386.79		.150000 x	.000000 =		.000000
				T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	21,523.000000 =	21,523.000000
387.3		.100000 x	21,523.000000 =	2,152.300000

			T.E =	23,675.300000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	1.001500 =	208.312000
113		154.700001 x	20.419486 =	3,158.894505
235		338.000000 x	.713000 =	240.994000

			AΘΡΟΙΣΜΑ =	3,608.200505

			T.E =	5,412.300757
6456.2	6456.2			
234.2		336.000000 x	1.001500 =	336.504000
113		249.900000 x	20.419486 =	5,102.829551
235		546.000000 x	.713000 =	389.298000

			AΘΡΟΙΣΜΑ =	5,828.631551

			T.E =	8,160.084172
6456.3	6456.3			
234.2		384.000000 x	1.001500 =	384.576000
235		624.000000 x	.713000 =	444.912000
113		285.599998 x	20.419486 =	5,831.805161

			AΘΡΟΙΣΜΑ =	6,661.293161

			T.E =	9,325.810425
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	6,664.000000 =	6,664.000000
389.4		.200000 x	6,664.000000 =	1,332.800000

			T.E =	7,996.800000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	5,629.000000 =	5,629.000000
390.14		.150000 x	5,629.000000 =	844.350000

			T.E =	6,473.350000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	8,188.000000 =	8,188.000000
390.31		.150000 x	8,188.000000 =	1,228.200000

			T.E =	9,416.200000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		.150000 x	.000000 =	.000000
391.50		1.000000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	15,362.000000 =	15,362.000000
393.1		.150000 x	15,362.000000 =	2,304.300000

			T.E =	17,666.300000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.950000 =	6.950000

			T.E =	6.950000
6501	6501			
237		1.000000 x	1.218000 =	1.218000
113		.850000 x	20.419486 =	17.356563

			T.E =	18.574563
6502	6502			
112		.170000 x	17.312112 =	2.943059
517		.042500 x	2,230.174289 =	94.782407

			T.E =	97.725466
6505	6505			
233		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603

6506	6506				
233.1		1.050000 x	.545500 =	.572775	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.440603	
6551.1	6551.1				
221		6.000000 x	.099900 =	.599400	
113		.255000 x	20.419486 =	5.206969	
111		.255000 x	15.741598 =	4.014107	
261		1.000000 x	15.100000 =	15.100000	

			T.E =	24.920476	
6551.2	6551.2				
221		8.000000 x	.099900 =	.799200	
262		1.000000 x	26.300000 =	26.300000	
111		.297500 x	15.741598 =	4.683125	
113		.297500 x	20.419486 =	6.074797	

			T.E =	37.857122	
6551.3	6551.3				
221		10.000000 x	.099900 =	.999000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	

			T.E =	45.693769	
6551.4	6551.4				
221		13.000000 x	.099900 =	1.298700	
263.2		1.000000 x	46.700000 =	46.700000	
113		.510000 x	20.419486 =	10.413938	
111		.510000 x	15.741598 =	8.028215	

			T.E =	66.440853	
6551.5	6551.5				
221		16.000000 x	.099900 =	1.598400	
113		.595000 x	20.419486 =	12.149594	
111		.595000 x	15.741598 =	9.366251	
264		1.000000 x	64.100000 =	64.100000	

			T.E =	87.214245	

6551.6	6551.6			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

T.E = 147.834921

6551.7	6551.7			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

T.E = 255.002782

6552	6552			
221		26.000000 x	.099900 =	2.597400
6304		6.890000 x	5.649342 =	38.923966
6310		32.020000 x	1.440603 =	46.128108
6329.2		.418000 x	167.830919 =	70.153324
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

T.E = 210.598360

6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.016845 =	27.691282
6329.2		.478000 x	167.830919 =	80.223179
6304		9.290000 x	5.649342 =	52.482387

T.E = 177.753411

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
112		.612850 x	17.312112 =	10.609728
365.3		.224000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
111		.150450 x	15.741598 =	2.368323

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
365.6		.224000 x	.000000 =	.000000
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

T.E =

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

T.E =

6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

T.E =

6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

T.E =

6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

T.E =

6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

T.E =

6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

T.E =

6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

T.E =

6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

T.E =

6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

T.E =

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
113		.025500 x	20.419486 =	.520697
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

			T.E =	
6611.1	6611.1			
361.1		1.000000 x	13.520000 =	13.520000
113		.212500 x	20.419486 =	4.339141
112		.510000 x	17.312112 =	8.829177
111		.085000 x	15.741598 =	1.338036

			T.E =	28.026354
6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
112		2.125000 x	17.312112 =	36.788238
113		.765000 x	20.419486 =	15.620907

			T.E =	
6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.935000 x	20.419486 =	19.092219
112		2.550000 x	17.312112 =	44.145886

			T.E =	
6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.741598 =	12.042322
113		1.105000 x	20.419486 =	22.563532
112		2.975000 x	17.312112 =	51.503533

			T.E =	
6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	20.419486 =	26.034845
112		3.400000 x	17.312112 =	58.861181
111		.892500 x	15.741598 =	14.049376

			T.E =	

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
112		3.825000 x	17.312112 =	66.218828
113		1.445000 x	20.419486 =	29.506157

T.E =

6611.2	6611.2			
361.2		1.000000 x	17.490000 =	17.490000
111		.085000 x	15.741598 =	1.338036
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942

T.E =

32.732118

6611.3	6611.3			
361.3		1.000000 x	22.200000 =	22.200000
111		.127500 x	15.741598 =	2.007054
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471

T.E =

40.450494

6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072

T.E =

6611.5	6611.5			
361.5		1.000000 x	42.370000 =	42.370000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453

T.E =

69.712368

6611.6	6611.6			
361.6		1.000000 x	56.540000 =	56.540000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884

T.E =

88.362273

6611.7	6611.7			
361.7		1.000000 x	87.480000 =	87.480000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

			T.E =	125.319024
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

			T.E =	11.019393
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

			T.E =	16.398814
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

			T.E =	20.616330

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424

			T.E =	30.493845
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414

			T.E =	37.634580
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563

			T.E =	56.514929
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299

			T.E =	70.886112
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817
113		.568650 x	20.419486 =	11.611541

			T.E =	88.635713
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709

			T.E =	110.023068

6621.1	6621.1			
372.1		1.020000 x	7.990000 =	8.149800
111		.080750 x	15.741598 =	1.271134
113		.205700 x	20.419486 =	4.200288
112		.088400 x	17.312112 =	1.530391

			T.E =	15.151613
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.680736
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.836897
6621.4	6621.4			
372.4		1.020000 x	25.540000 =	26.050800
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	42.892321
6621.5	6621.5			
372.5		1.020000 x	32.500000 =	33.150000
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	53.423889
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	80.949300

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
111		.662150 x	15.741598 =	10.423299
112		.710600 x	17.312112 =	12.301987
113		.589050 x	20.419486 =	12.028098

			T.E =	101.104384
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
111		.841500 x	15.741598 =	13.246555
113		.663850 x	20.419486 =	13.555476
112		.901000 x	17.312112 =	15.598213

			T.E =	126.764443
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
111		1.068450 x	15.741598 =	16.819110
113		.748000 x	20.419486 =	15.273776
112		1.145800 x	17.312112 =	19.836218

			T.E =	158.723104
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
113		.235450 x	20.419486 =	4.807768
112		.131750 x	17.312112 =	2.280871
111		.080750 x	15.741598 =	1.271134

			T.E =	20.497773
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	15.741598 =	2.060575
112		.212500 x	17.312112 =	3.678824
113		.299200 x	20.419486 =	6.109510

			T.E =	31.004509
6622.3	6622.3			
373.3		1.020000 x	24.490000 =	24.979800
111		.170850 x	15.741598 =	2.689452
113		.341700 x	20.419486 =	6.977338
112		.277950 x	17.312112 =	4.811902

			T.E =	39.458492

6623	6623				
360.2		1.000000 x	2.440000 =	2.440000	
113		.085000 x	20.419486 =	1.735656	
111		.042500 x	15.741598 =	.669018	
113		.025500 x	20.419486 =	.520697	
112		.042500 x	17.312112 =	.735765	

			T.E =	6.101136	
6630.1	6630.1				
376.12		1.000000 x	91.600000 =	91.600000	
113		2.550000 x	20.419486 =	52.069689	
113		.610300 x	20.419486 =	12.462012	
113		1.067600 x	20.419486 =	21.799843	
112		2.439500 x	17.312112 =	42.232897	
111		.855100 x	15.741598 =	13.460640	

			T.E =	233.625083	
6630.10	6630.10				
376.21		1.000000 x	502.070000 =	502.070000	
111		7.690800 x	15.741598 =	121.065482	
113		3.349000 x	20.419486 =	68.384859	
113		3.203650 x	20.419486 =	65.416886	
113		2.550000 x	20.419486 =	52.069689	
112		13.396000 x	17.312112 =	231.913052	

			T.E =	1,040.919968	
6630.11	6630.11				
376.22		1.000000 x	544.290000 =	544.290000	
111		9.025300 x	15.741598 =	142.072644	
113		3.471400 x	20.419486 =	70.884204	
113		3.629500 x	20.419486 =	74.112524	
113		2.550000 x	20.419486 =	52.069689	
112		14.518000 x	17.312112 =	251.337242	

			T.E =	1,134.766304	
6630.2	6630.2				
376.13		1.000000 x	101.900000 =	101.900000	
113		2.550000 x	20.419486 =	52.069689	
113		1.201050 x	20.419486 =	24.524824	
113		.680000 x	20.419486 =	13.885250	
111		1.081200 x	15.741598 =	17.019816	
112		2.720000 x	17.312112 =	47.088945	

			T.E =	256.488524	

6630.3	6630.3				
376.14		1.000000 x	113.040000 =	113.040000	
113		1.334500 x	20.419486 =	27.249804	
113		2.550000 x	20.419486 =	52.069689	
113		.760750 x	20.419486 =	15.534124	
112		3.043000 x	17.312112 =	52.680757	
111		1.334500 x	15.741598 =	21.007163	

			T.E =	281.581537	
6630.4	6630.4				
376.15		1.000000 x	144.820000 =	144.820000	
111		1.922700 x	15.741598 =	30.266370	
113		.892500 x	20.419486 =	18.224391	
113		1.602250 x	20.419486 =	32.717121	
113		2.550000 x	20.419486 =	52.069689	
112		3.570000 x	17.312112 =	61.804240	

			T.E =	339.901812	
6630.5	6630.5				
376.16		1.000000 x	182.130000 =	182.130000	
111		2.617150 x	15.741598 =	41.198123	
113		1.164500 x	20.419486 =	23.778491	
113		2.550000 x	20.419486 =	52.069689	
113		1.869150 x	20.419486 =	38.167082	
112		4.658000 x	17.312112 =	80.639818	

			T.E =	417.983204	
6630.6	6630.6				
376.17		1.000000 x	231.180000 =	231.180000	
113		2.550000 x	20.419486 =	52.069689	
113		2.136050 x	20.419486 =	43.617043	
113		1.470500 x	20.419486 =	30.026854	
111		3.418700 x	15.741598 =	53.815801	
112		5.882000 x	17.312112 =	101.829843	

			T.E =	512.539230	
6630.7	6630.7				
376.18		1.000000 x	311.830000 =	311.830000	
113		2.402950 x	20.419486 =	49.067004	
113		2.550000 x	20.419486 =	52.069689	
113		2.031500 x	20.419486 =	41.482186	
112		8.126000 x	17.312112 =	140.678222	
111		4.326500 x	15.741598 =	68.106024	

			T.E =	663.233125	

6630.8	6630.8			
376.19		1.000000 x	346.570000 =	346.570000
111		5.340550 x	15.741598 =	84.068791
113		2.261000 x	20.419486 =	46.168458
113		2.669850 x	20.419486 =	54.516965
113		2.550000 x	20.419486 =	52.069689
112		9.044000 x	17.312112 =	156.570741

			T.E =	739.964644
6630.9	6630.9			
376.20		1.000000 x	412.890000 =	412.890000
111		6.461700 x	15.741598 =	101.717484
113		2.737000 x	20.419486 =	55.888133
113		2.550000 x	20.419486 =	52.069689
113		2.936750 x	20.419486 =	59.966926
112		10.948000 x	17.312112 =	189.533002

			T.E =	872.065234
6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		1.667700 x	20.419486 =	34.053577
111		1.334500 x	15.741598 =	21.007163
112		3.043000 x	17.312112 =	52.680757

			T.E =	
6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		2.002600 x	20.419486 =	40.892063
112		3.570000 x	17.312112 =	61.804240
111		1.922700 x	15.741598 =	30.266370

			T.E =	
6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
111		2.617150 x	15.741598 =	41.198123
112		4.658000 x	17.312112 =	80.639818
113		2.550000 x	20.419486 =	52.069689
113		2.336650 x	20.419486 =	47.713192

			T.E =	

6640.4 6640.4

377.4	1.000000 x	.000000 =	.000000
111	3.418700 x	15.741598 =	53.815801
112	5.882000 x	17.312112 =	101.829843
113	2.669850 x	20.419486 =	54.516965
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.5 6640.5

377.5	1.000000 x	.000000 =	.000000
111	4.326500 x	15.741598 =	68.106024
113	3.003900 x	20.419486 =	61.338094
113	2.550000 x	20.419486 =	52.069689
112	8.126000 x	17.312112 =	140.678222

T.E =

6640.6 6640.6

377.6	1.000000 x	.000000 =	.000000
113	2.550000 x	20.419486 =	52.069689
113	3.337100 x	20.419486 =	68.141867
112	9.044000 x	17.312112 =	156.570741
111	5.340550 x	15.741598 =	84.068791

T.E =

6640.7 6640.7

377.7	1.000000 x	.000000 =	.000000
111	6.461700 x	15.741598 =	101.717484
112	10.948000 x	17.312112 =	189.533002
113	3.671150 x	20.419486 =	74.962996
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.8 6640.8

377.8	1.000000 x	.000000 =	.000000
111	7.690800 x	15.741598 =	121.065482
112	13.396000 x	17.312112 =	231.913052
113	2.550000 x	20.419486 =	52.069689
113	4.004350 x	20.419486 =	81.766769

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.741598 =	142.072644
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242

			T.E =	
6641	6641			
233.3		1.000000 x	8.100000 =	8.100000

			T.E =	8.100000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

T.E =				
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

T.E =				
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

T.E =				
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

T.E =				
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

T.E =				
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

T.E =				
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

T.E =				
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

T.E =				

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7	6662.7			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.8		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6662.8	6662.8			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.6		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.1	6663.1			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.4		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.2	6663.2			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6701.1	6701.1			
368.1		1.020000 x	.000000 =	.000000
369.1		.224000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

		T.E =		

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

T.E =

6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

T.E =

6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

T.E =

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

T.E =

6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

T.E =

6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625

T.E =

6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
369.14		.224000 x	.000000 =	.000000

T.E =

6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251
369.18		.224000 x	.000000 =	.000000

T.E =

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
111		.680000 x	15.741598 =	10.704287

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
369.27		.224000 x	.000000 =	.000000

T.E =

6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
369.28		.224000 x	.000000 =	.000000
111		.595000 x	15.741598 =	9.366251
113		.238000 x	20.419486 =	4.859838

T.E =

6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
369.29		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.16		1.000000 x	.000000 =	.000000

T.E =

6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525

T.E =

6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.24		1.000000 x	.000000 =	.000000

T.E =

6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
6326		.327500 x	135.180379 =	44.271574
113		.026350 x	20.419486 =	.538053
111		.085000 x	15.741598 =	1.338036

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
111		.119000 x	15.741598 =	1.873250
113		.040800 x	20.419486 =	.833115
6326		.352500 x	135.180379 =	47.651084

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
111		.161500 x	15.741598 =	2.542268
6326		.372500 x	135.180379 =	50.354691
113		.051000 x	20.419486 =	1.041394

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
6326		.382500 x	135.180379 =	51.706495
113		.063750 x	20.419486 =	1.301742

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	135.180379 =	52.889323
113		.068000 x	20.419486 =	1.388525
111		.187000 x	15.741598 =	2.943679

T.E =

6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
113		.076500 x	20.419486 =	1.562091
6327		.393750 x	157.464606 =	62.001689

T.E =

6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	15.741598 =	4.549322
6327		.431250 x	157.464606 =	67.906611
113		.093500 x	20.419486 =	1.909222

T.E =

6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	157.464606 =	78.732303
113		.119000 x	20.419486 =	2.429919

T.E =

6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	25.296575 =	9.359733
113		.017000 x	20.419486 =	.347131
111		.161500 x	15.741598 =	2.542268

T.E = 20.929332

6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	15.741598 =	2.943679
6069		.390000 x	25.296575 =	9.865664
113		.021250 x	20.419486 =	.433914

T.E = 26.839857

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	15.741598 =	3.211286
6069		.400000 x	25.296575 =	10.118630
113		.026350 x	20.419486 =	.538053

			T.E =	35.073769
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.741598 =	3.880304
6069		.420000 x	25.296575 =	10.624562
113		.040800 x	20.419486 =	.833115

			T.E =	49.660980
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	25.296575 =	10.877527
113		.051000 x	20.419486 =	1.041394
111		.289000 x	15.741598 =	4.549322

			T.E =	60.124243
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	25.296575 =	11.130493
113		.063750 x	20.419486 =	1.301742
111		.297500 x	15.741598 =	4.683125

			T.E =	72.429961
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	25.296575 =	13.154219
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750

			T.E =	110.004260
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	39.738563

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	43.245563
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	48.674063
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	56.171063
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	10.160000 =	10.160000

			T.E =	63.804563
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
113		.021250 x	20.419486 =	.433914
111		.187000 x	15.741598 =	2.943679
375.14		1.000000 x	17.510000 =	17.510000

			T.E =	31.047593
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	106.838382 =	9.615454
112		1.190000 x	17.312112 =	20.601413
113		.255000 x	20.419486 =	5.206969

			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	116.828382 =	25.819072
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	116.828382 =	27.337841
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	116.828382 =	28.155640
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	106.838382 =	11.752222
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	106.838382 =	13.995828
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.154000 x	106.838382 =	16.453111
700		.350000 x	.000000 =	.000000

T.E =

6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	106.838382 =	17.735171
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.173000 x	106.838382 =	18.483040
113		.637500 x	20.419486 =	13.017422

T.E =

6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	116.828382 =	16.122317
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.165000 x	116.828382 =	19.276683
700		.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	116.828382 =	22.547878
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	106.838382 =	6.410303
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	116.828382 =	15.187690
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	116.828382 =	16.355973
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	116.828382 =	17.524257
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	106.838382 =	7.478687
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	106.838382 =	8.547071
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	106.838382 =	9.615454
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	106.838382 =	10.683838
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	106.838382 =	11.752222
113		.637500 x	20.419486 =	13.017422

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	116.828382 =	11.682838
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	116.828382 =	12.851122
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	116.828382 =	14.019406
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	106.838382 =	9.615454
652		.002500 x	150.535626 =	.376339
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E = 39.615952

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	116.828382 =	29.090267
652		.004500 x	150.535626 =	.677410
113		.340000 x	20.419486 =	6.942625
			T.E =	82.771076
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	116.828382 =	36.216798
652		.005000 x	150.535626 =	.752678
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942
			T.E =	111.335500
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	116.828382 =	43.226501
652		.006500 x	150.535626 =	.978482
112		.680000 x	17.312112 =	11.772236
			T.E =	142.121992
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	106.838382 =	11.752222
652		.003000 x	150.535626 =	.451607
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072
			T.E =	47.707988
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	106.838382 =	13.995828
652		.003500 x	150.535626 =	.526875
113		.297500 x	20.419486 =	6.074797
			T.E =	58.179472

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	106.838382 =	18.162525
652		.004500 x	150.535626 =	.677410
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648
			T.E =	71.843334
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	106.838382 =	24.145474
652		.005000 x	150.535626 =	.752678
112		.552500 x	17.312112 =	9.564942
			T.E =	99.264176
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	106.838382 =	29.273717
652		.006500 x	150.535626 =	.978482
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179
			T.E =	128.169208
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.828382 =	16.122317
652		.002500 x	150.535626 =	.376339
113		.255000 x	20.419486 =	5.206969
			T.E =	46.122814
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	116.828382 =	19.276683
652		.003000 x	150.535626 =	.451607
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
			T.E =	55.232449

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	116.828382 =	22.547878
652		.003500 x	150.535626 =	.526875
112		.382500 x	17.312112 =	6.621883

T.E = 66.731522

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	106.838382 =	9.615454
652		.002500 x	150.535626 =	.376339
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	116.828382 =	29.090267
652		.004500 x	150.535626 =	.677410
113		.340000 x	20.419486 =	6.942625

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	116.828382 =	36.216798
652		.005000 x	150.535626 =	.752678
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	116.828382 =	43.226501
652		.006500 x	150.535626 =	.978482
112		.680000 x	17.312112 =	11.772236

T.E =

6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	106.838382 =	11.752222
652		.003000 x	150.535626 =	.451607
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	106.838382 =	13.995828
652		.003500 x	150.535626 =	.526875
113		.297500 x	20.419486 =	6.074797

T.E =

6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	106.838382 =	18.162525
652		.004500 x	150.535626 =	.677410
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

T.E =

6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	106.838382 =	24.145474
652		.005000 x	150.535626 =	.752678
112		.552500 x	17.312112 =	9.564942

T.E =

6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	106.838382 =	29.273717
652		.006500 x	150.535626 =	.978482
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.828382 =	16.122317
652		.002500 x	150.535626 =	.376339
113		.255000 x	20.419486 =	5.206969

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	116.828382 =	19.276683
652		.003000 x	150.535626 =	.451607
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	116.828382 =	22.547878
652		.003500 x	150.535626 =	.526875
112		.382500 x	17.312112 =	6.621883

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	135.180379 =	127.069556
6303		1.880000 x	20.340067 =	38.239326

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	135.180379 =	98.681677

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	135.180379 =	127.069556

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	135.180379 =	98.681677

			T.E =	
6742.1	6742.1			
6303		3.040000 x	20.340067 =	61.833804
6328		.400000 x	161.040919 =	64.416368

			T.E =	126.250171
6742.10	6742.10			
6303		7.520000 x	20.340067 =	152.957304
6328		2.110000 x	161.040919 =	339.796339

			T.E =	492.753643
6742.11	6742.11			
6303		8.030000 x	20.340067 =	163.330738
6328		2.430000 x	161.040919 =	391.329433

			T.E =	554.660171
6742.2	6742.2			
6303		3.500000 x	20.340067 =	71.190235
6328		.500000 x	161.040919 =	80.520460

			T.E =	151.710694
6742.3	6742.3			
6303		4.020000 x	20.340067 =	81.767069
6328		.630000 x	161.040919 =	101.455779

			T.E =	183.222848
6742.4	6742.4			
6303		4.530000 x	20.340067 =	92.140504
6328		.800000 x	161.040919 =	128.832735

			T.E =	220.973239

6742.5	6742.5			
6303		5.000000 x	20.340067 =	101.700335
6328		.950000 x	161.040919 =	152.988873

			T.E =	254.689208
6742.6	6742.6			
6303		5.530000 x	20.340067 =	112.480571
6328		1.170000 x	161.040919 =	188.417875

			T.E =	300.898446
6742.7	6742.7			
6303		6.040000 x	20.340067 =	122.854005
6328		1.410000 x	161.040919 =	227.067696

			T.E =	349.921700
6742.8	6742.8			
6303		6.520000 x	20.340067 =	132.617237
6328		1.610000 x	161.040919 =	259.275880

			T.E =	391.893116
6742.9	6742.9			
6303		7.040000 x	20.340067 =	143.194072
6328		1.880000 x	161.040919 =	302.756928

			T.E =	445.950999
6743.1	6743.1			
6303		3.040000 x	20.340067 =	61.833804
6328		.440000 x	161.040919 =	70.858004

			T.E =	132.691808
6743.10	6743.10			
6303		7.520000 x	20.340067 =	152.957304
6328		2.240000 x	161.040919 =	360.731659

			T.E =	513.688962
6743.11	6743.11			
6303		8.030000 x	20.340067 =	163.330738
6328		2.570000 x	161.040919 =	413.875162

			T.E =	577.205900

6743.12	6743.12			
6303		3.040000 x	20.340067 =	61.833804
6328		.750000 x	161.040919 =	120.780689

			T.E =	182.614493
6743.13	6743.13			
6303		3.500000 x	20.340067 =	71.190235
6328		.910000 x	161.040919 =	146.547236

			T.E =	217.737471
6743.14	6743.14			
6303		4.020000 x	20.340067 =	81.767069
6328		1.090000 x	161.040919 =	175.534602

			T.E =	257.301671
6743.15	6743.15			
6303		4.530000 x	20.340067 =	92.140504
6328		1.300000 x	161.040919 =	209.353195

			T.E =	301.493698
6743.16	6743.16			
6303		5.000000 x	20.340067 =	101.700335
6328		1.550000 x	161.040919 =	249.613424

			T.E =	351.313759
6743.17	6743.17			
6303		5.530000 x	20.340067 =	112.480571
6328		1.850000 x	161.040919 =	297.925700

			T.E =	410.406271
6743.2	6743.2			
6303		3.500000 x	20.340067 =	71.190235
6328		.550000 x	161.040919 =	88.572505

			T.E =	159.762740
6743.3	6743.3			
6303		4.020000 x	20.340067 =	81.767069
6328		.690000 x	161.040919 =	111.118234

			T.E =	192.885303

6743.4	6743.4			
6303		4.530000 x	20.340067 =	92.140504
6328		.860000 x	161.040919 =	138.495190

			T.E =	230.635694
6743.5	6743.5			
6303		5.000000 x	20.340067 =	101.700335
6328		1.020000 x	161.040919 =	164.261737

			T.E =	265.962072
6743.6	6743.6			
6303		5.530000 x	20.340067 =	112.480571
6328		1.260000 x	161.040919 =	202.911558

			T.E =	315.392128
6743.7	6743.7			
6303		6.040000 x	20.340067 =	122.854005
6328		1.500000 x	161.040919 =	241.561379

			T.E =	364.415383
6743.8	6743.8			
6303		6.520000 x	20.340067 =	132.617237
6328		1.720000 x	161.040919 =	276.990381

			T.E =	409.607618
6743.9	6743.9			
6303		7.040000 x	20.340067 =	143.194072
6328		2.000000 x	161.040919 =	322.081838

			T.E =	465.275910
6744	6744			
111		2.125000 x	15.741598 =	33.450896
113		2.125000 x	20.419486 =	43.391408
113		2.125000 x	20.419486 =	43.391408
112		2.125000 x	17.312112 =	36.788238
111		4.250000 x	15.741598 =	66.901792

			T.E =	223.923741

6751	6751			
234.2		.400000 x	1.001500 =	.400600
113		.170000 x	20.419486 =	3.471313
113		.051000 x	20.419486 =	1.041394
235		.650000 x	.713000 =	.463450

			T.E =	5.376756
6752	6752			
237		1.050000 x	1.218000 =	1.278900
111		.025500 x	15.741598 =	.401411
113		.017000 x	20.419486 =	.347131

			T.E =	2.027442
6753	6753			
237		1.050000 x	1.218000 =	1.278900
113		.085000 x	20.419486 =	1.735656
112		.085000 x	17.312112 =	1.471530

			T.E =	4.486086
6754	6754			
237.1		1.000000 x	1.380000 =	1.380000
111		.051000 x	15.741598 =	.802821
112		.017000 x	17.312112 =	.294306
113		.212500 x	20.419486 =	4.339141

			T.E =	6.816268
6801	6801			
232		.700000 x	2.100000 =	1.470000
251		.008000 x	290.000000 =	2.320000
113		2.550000 x	20.419486 =	52.069689
112		1.700000 x	17.312112 =	29.430590
111		.850000 x	15.741598 =	13.380358

			T.E =	98.670638
6802	6802			
231		15.000000 x	.861000 =	12.915000
113		2.550000 x	20.419486 =	52.069689
111		4.250000 x	15.741598 =	66.901792
251		.050000 x	290.000000 =	14.500000
252.1		.050000 x	.000000 =	.000000

			T.E =	

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	150.535626 =	1.806428
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250

			T.E =	30.553893
6804	6804			
111		.510000 x	15.741598 =	8.028215
652		.120000 x	150.535626 =	18.064275
113		.680000 x	20.419486 =	13.885250

			T.E =	39.977741
6805	6805			
301		1.000000 x	4.060000 =	4.060000
111		.340000 x	15.741598 =	5.352143
2522		.005000 x	155.029040 =	.775145
652		.002000 x	150.535626 =	.301071
113		.340000 x	20.419486 =	6.942625

			T.E =	17.430985
6806	6806			
111		.340000 x	15.741598 =	5.352143
113		.340000 x	20.419486 =	6.942625
6326		.005000 x	135.180379 =	.675902
652		.002000 x	150.535626 =	.301071

			T.E =	13.271742
6807	6807			
111		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179

			T.E =	6.690179
6810	6810			
241		2.600000 x	7.750000 =	20.150000
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448
241		1.300000 x	7.750000 =	10.075000
113		1.062500 x	20.419486 =	21.695704

			T.E =	86.002715

6811	6811			
236		6.430000 x	.683000 =	4.391690
113		.850000 x	20.419486 =	17.356563
241		3.150000 x	7.750000 =	24.412500
113		3.400000 x	20.419486 =	69.426252

			T.E =	115.587006
6812	6812			
397.1		2.100000 x	7.050000 =	14.805000
6324		.250000 x	111.833382 =	27.958346
113		4.250000 x	20.419486 =	86.782816
111		.425000 x	15.741598 =	6.690179
243		11.900000 x	2.400000 =	28.560000

			AΘΡΟΙΣΜΑ =	164.796340
	T.E =	.262500 x	164.796340 =	43.259039

7001	7001			
7001 A		1.000000 x	.242244 =	.242244
7001 B		1.000000 x	.796417 =	.796417
7001 Γ		1.000000 x	1.001629 =	1.001629
7001 Ε		1.000000 x	.843025 =	.843025
7001 Δ		1.000000 x	.328774 =	.328774

			AΘΡΟΙΣΜΑ =	3.212089

			T.E =	3.693902
7002	7002			
560		.005104 x	724.230690 =	3.696473

			T.E =	3.696473
7003	7003			
7003 A		1.000000 x	.121122 =	.121122
7003 B		1.000000 x	.622720 =	.622720
7003 Δ		1.000000 x	.820636 =	.820636
7003 Γ		1.000000 x	.568175 =	.568175

			AΘΡΟΙΣΜΑ =	2.132653

			T.E =	2.345918
7004	7004			
561		.003250 x	956.813590 =	3.109644

			T.E =	3.109644

7005	7005			
7005 Α		1.000000 x	.121122 =	.121122
7005 Γ		1.000000 x	.311360 =	.311360
7005 Ε		1.000000 x	.820636 =	.820636
7005 Δ		1.000000 x	.568175 =	.568175
7005 Β		1.000000 x	1.089760 =	1.089760

			ΑΘΡΟΙΣΜΑ =	2.911053

			T.E =	3.202158
7006	7006			
561		.001723 x	956.813590 =	1.648590
561		.000812 x	956.813590 =	.776933
561		.000862 x	956.813590 =	.824773

			T.E =	3.250296
7007	7007			
213		.100000 x	1.949500 =	.194950
550		.003500 x	1,067.209286 =	3.735233
518		.001750 x	902.567692 =	1.579493
502		.000583 x	811.678573 =	.473209
116		.280000 x	20.419486 =	5.717456

			T.E =	11.700341
7008	7008			
111		.021000 x	15.741598 =	.330574
112		.210000 x	17.312112 =	3.635544
507		.000875 x	956.739507 =	.837147
503		.001750 x	929.049673 =	1.625837
7007		1.100000 x	11.700341 =	12.870375
558		.000972 x	1,137.738457 =	1.105882

			T.E =	20.405358
7009	7009			
560		.006417 x	724.230690 =	4.647388

			T.E =	4.647388
7010	7010			
7010 Α		1.000000 x	.358388 =	.358388
7010 Δ		1.000000 x	.328774 =	.328774
7010 Ε		1.000000 x	1.039876 =	1.039876
7010 Γ		1.000000 x	.568175 =	.568175
7010 Β		1.000000 x	.538150 =	.538150

			ΑΘΡΟΙΣΜΑ =	2.833363

			T.E =	3.258367

7011	7011			
502		.001367 x	811.678573 =	1.109565
563		.001367 x	.000000 =	.000000
558		.000729 x	1,137.738457 =	.829411
558		.000729 x	1,137.738457 =	.829411
554		.000438 x	34.408000 =	.015071
503		.000438 x	929.049673 =	.406924
502		.000700 x	811.678573 =	.568175

			ΑΘΡΟΙΣΜΑ =	3.758557

			T.E =	
7012	7012			
7008		1.000000 x	20.405358 =	20.405358

			ΑΘΡΟΙΣΜΑ =	20.405358

			T.E =	22.445894
7013	7013			
7003		1.000000 x	2.345918 =	2.345918

			ΑΘΡΟΙΣΜΑ =	2.345918

			T.E =	2.580510
7014	7014			
7005		1.000000 x	3.202158 =	3.202158

			ΑΘΡΟΙΣΜΑ =	3.202158

			T.E =	3.522374
7015	7015			
111		.056000 x	15.741598 =	.881529
X 630.1		.300000 x	1.705008 =	.511502
7001		.900000 x	3.693902 =	3.324512
X 630		.300000 x	1.501778 =	.450533

			T.E =	5.168077
7016.9	7016.9			
7016.4		1.000000 x	128.552939 =	128.552939
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	25.710588 =	25.710588
7016.6		1.000000 x	38.565882 =	38.565882
7016.7		1.000000 x	80.282150 =	80.282150

			T.E =	377.250938

7017.8	7017.8				
7017.3		1.000000 x	93.751277 =		93.751277
7017.5		1.000000 x	33.750460 =		33.750460
7017.6		1.000000 x	80.282150 =		80.282150
7017.7		1.000000 x	52.069689 =		52.069689
7017.4		1.000000 x	18.750255 =		18.750255

			T.E =		278.603831
7018	7018				
233.2		1.150000 x	.598400 =		.688160
113		.051000 x	20.419486 =		1.041394

			AΘΡΟΙΣΜΑ =		1.729554

			T.E =		1.902509
7019	7019				
7019 A6		1.000000 x	193.363023 =		193.363023
7019 A7		1.000000 x	19.336302 =		19.336302

			T.E =		212.699325
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	212.699325 =		212.699325

			T.E =		206.799325
7020	7020				
213		.150000 x	1.949500 =		.292425
7020.2		.010938 x	3,583.169069 =		39.192703
116		.980000 x	20.419486 =		20.011096

			T.E =		59.496225
7020.1	7020.1				
570.2		.350000 x	127.284076 =		44.549427
571.1		.280000 x	458.756470 =		128.451812
571.2		.070000 x	261.479536 =		18.303568

			AΘΡΟΙΣΜΑ =		191.304806
	T.E =	.015625 x	191.304806 =		2.989138

7021	7021				
213		.150000 x	1.949500 =		.292425
7021.2		.014583 x	3,126.889941 =		45.599436
116		1.120000 x	20.419486 =		22.869824

			T.E =		68.761685

7021.1	7021.1			
570.2		.350000 x	127.284076 =	44.549427
571.1		.280000 x	458.756470 =	128.451812
571.2		.070000 x	261.479536 =	18.303568
			AΘΡΟΙΣΜΑ =	191.304806
	T.E =	.020833 x	191.304806 =	3.985453
7022	7022			
213		.150000 x	1.949500 =	.292425
7022.2		.020000 x	2,867.022767 =	57.340455
116		1.400000 x	20.419486 =	28.587280
			T.E =	86.220161
7022.1	7022.1			
570.2		.350000 x	127.284076 =	44.549427
571.1		.280000 x	458.756470 =	128.451812
571.2		.070000 x	261.479536 =	18.303568
			AΘΡΟΙΣΜΑ =	191.304806
	T.E =	.028571 x	191.304806 =	5.465770
7023	7023			
398.2		1.050000 x	39.000000 =	40.950000
111		.425000 x	15.741598 =	6.690179
550		.012143 x	1,067.209286 =	12.959122
116		.850000 x	20.419486 =	17.356563
			T.E =	77.955865
7024	7024			
398.3		1.050000 x	47.000000 =	49.350000
111		.425000 x	15.741598 =	6.690179
550		.020238 x	1,067.209286 =	21.598182
116		.850000 x	20.419486 =	17.356563
			T.E =	94.994924
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	150.535626 =	.150536
550		.020238 x	1,067.209286 =	21.598182
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
111		.425000 x	15.741598 =	6.690179
233		6.180000 x	.545500 =	3.371190
398.4		1.000000 x	63.000000 =	63.000000
			T.E =	119.534917

7026	7026				
398.5		125.400000 x	6.400000 =	802.560000	
236		16.808000 x	.683000 =	11.479864	
113		.909160 x	20.419486 =	18.564580	
113		3.400000 x	20.419486 =	69.426252	
6310		12.350000 x	1.440603 =	17.791447	
			AΘΡΟΙΣΜΑ =	919.822143	
	T.E =	.007259 x	919.822143 =	6.676989	
7027	7027				
236		1.100000 x	.683000 =	.751300	
113		.059500 x	20.419486 =	1.214959	
			T.E =	1.966259	
7028	7028				
111		.144500 x	15.741598 =	2.274661	
6751		.120000 x	5.376756 =	.645211	
6751		.600000 x	5.376756 =	3.226054	
111		.425000 x	15.741598 =	6.690179	
112		.144500 x	17.312112 =	2.501600	
			AΘΡΟΙΣΜΑ =	15.337705	
			T.E =	17.638360	
7029	7029				
568.1		.021250 x	2,685.074172 =	57.057826	
569.2		.021250 x	620.296952 =	13.181310	
570.2		.021250 x	127.284076 =	2.704787	
571.2		.021250 x	261.479536 =	5.556440	
			T.E =	78.500363	
7030	7030				
398.6		.015385 x	330.000000 =	5.077050	
572		.026563 x	862.606457 =	22.913415	
			AΘΡΟΙΣΜΑ =	27.990465	
			T.E =	39.186651	
7031	7031				
573		.106250 x	1,091.866032 =	116.010766	
			AΘΡΟΙΣΜΑ =	116.010766	
			T.E =	133.412381	
7032	7032				
573		.212500 x	1,091.866032 =	232.021532	
			AΘΡΟΙΣΜΑ =	232.021532	
			T.E =	301.627991	

7101.1	7101.1			
398.1		15.000000 x	.225000 =	3.375000
574		.132813 x	3,709.415882 =	492.658652
T 630		.105000 x	1.823588 =	.191477
T 630.1		.105000 x	2.070367 =	.217389
567		.132813 x	403.188672 =	53.548697

			AΘΡΟΙΣΜΑ =	549.991214

			T.E =	566.490950
7101.2	7101.2			
398.1		15.000000 x	.225000 =	3.375000
574		.148750 x	3,709.415882 =	551.775612
T 630.1		.105000 x	2.070367 =	.217389
T 630		.105000 x	1.823588 =	.191477
567		.148750 x	403.188672 =	59.974315

			AΘΡΟΙΣΜΑ =	615.533793

			T.E =	633.999806
7101.3	7101.3			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	2.070367 =	.217389
T 630		.105000 x	1.823588 =	.191477
574		.159375 x	3,709.415882 =	591.188156
567		.159375 x	403.188672 =	64.258195

			AΘΡΟΙΣΜΑ =	659.230216

			T.E =	679.007123
7101.4	7101.4			
398.1		15.000000 x	.225000 =	3.375000
567		.170000 x	403.188672 =	68.542074
574		.170000 x	3,709.415882 =	630.600700
T 630.1		.105000 x	2.070367 =	.217389
T 630		.105000 x	1.823588 =	.191477

			AΘΡΟΙΣΜΑ =	702.926639

			T.E =	724.014439
7101.5	7101.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	2.070367 =	.217389
567		.191250 x	403.188672 =	77.109834
T 630		.105000 x	1.823588 =	.191477
574		.191250 x	3,709.415882 =	709.425787

			AΘΡΟΙΣΜΑ =	790.319486

			T.E =	814.029071

7102.1	7102.1				
398.1		15.000000 x	.225000 =		3.375000
567		.302813 x	403.188672 =		122.090771
T 630		.105000 x	1.823588 =		.191477
T 630.1		.105000 x	2.070367 =		.217389
574		.302813 x	3,709.415882 =		1,123.259351

			AΘΡΟΙΣΜΑ =		1,249.133988

			T.E =		1,286.608008
7102.2	7102.2				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.070367 =		.217389
T 630		.105000 x	1.823588 =		.191477
574		.329375 x	3,709.415882 =		1,221.788856
567		.329375 x	403.188672 =		132.800269

			AΘΡΟΙΣΜΑ =		1,358.372990

			T.E =		1,399.124180
7102.3	7102.3				
398.1		15.000000 x	.225000 =		3.375000
567		.361250 x	403.188672 =		145.651908
T 630		.105000 x	1.823588 =		.191477
T 630.1		.105000 x	2.070367 =		.217389
574		.361250 x	3,709.415882 =		1,340.026487

			AΘΡΟΙΣΜΑ =		1,489.462260

			T.E =		1,534.146128
7102.4	7102.4				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.070367 =		.217389
T 630		.105000 x	1.823588 =		.191477
574		.403750 x	3,709.415882 =		1,497.676662
567		.403750 x	403.188672 =		162.787426

			AΘΡΟΙΣΜΑ =		1,664.247954

			T.E =		1,714.175393
7102.5	7102.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.070367 =		.217389
T 630		.105000 x	1.823588 =		.191477
567		.446250 x	403.188672 =		179.922945
574		.446250 x	3,709.415882 =		1,655.326837

			AΘΡΟΙΣΜΑ =		1,839.033647

			T.E =		1,894.204657

7103	7103			
113		3.400000 x	20.419486 =	69.426252
113		.283333 x	20.419486 =	5.785514
115		.070833 x	21.778427 =	1.542631
575		.106250 x	1,020.906058 =	108.471269

			T.E =	185.225667
7104	7104			
113		1.700000 x	20.419486 =	34.713126
576		.106250 x	7.645000 =	.812281
567		.106250 x	403.188672 =	42.838796

			T.E =	78.364204
7105	7105			
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563
576		.106250 x	7.645000 =	.812281
567		.106250 x	403.188672 =	42.838796

			T.E =	74.387999
7106.1	7106.1			
577		.265625 x	686.509419 =	182.354064

			AΘΡΟΙΣΜΑ =	182.354064

			T.E =	191.471768
7106.2	7106.2			
577		.297500 x	686.509419 =	204.236552

			AΘΡΟΙΣΜΑ =	204.236552

			T.E =	214.448380
7106.3	7106.3			
577		.350625 x	686.509419 =	240.707365

			AΘΡΟΙΣΜΑ =	240.707365

			T.E =	252.742733
7106.4	7106.4			
577		.425000 x	686.509419 =	291.766503

			AΘΡΟΙΣΜΑ =	291.766503

			T.E =	306.354828

7106.5	7106.5			
577		.531250 x	686.509419 =	364.708129

			ΑΘΡΟΙΣΜΑ =	364.708129

			T.E =	382.943535
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	191.471768 =	191.471768

			T.E =	232.271768
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	214.448380 =	214.448380

			T.E =	255.248380
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	252.742733 =	252.742733

			T.E =	293.542733
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	306.354828 =	306.354828

			T.E =	347.154828
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	382.943535 =	382.943535

			T.E =	423.743535
7108	7108			
398.11		1.000000 x	140.870000 =	140.870000
574		.053125 x	3,709.415882 =	197.062719

			T.E =	337.932719
7109	7109			
398.12		1.000000 x	182.180000 =	182.180000
574		.053125 x	3,709.415882 =	197.062719

			T.E =	379.242719

7110	7110				
398.10		1.170000 x	142.840000 =		167.122800
574		.053125 x	3,709.415882 =		197.062719

			T.E =		364.185519
7111	7111				
398.9		1.170000 x	131.840000 =		154.252800
574		.053125 x	3,709.415882 =		197.062719

			T.E =		351.315519
7112	7112				
398.13		1.300000 x	10.300000 =		13.390000
577		.010625 x	686.509419 =		7.294163

			T.E =		20.684163
7113	7113				
241		1.200000 x	7.750000 =		9.300000
574		.001063 x	3,709.415882 =		3.943109

			T.E =		13.243109
7114	7114				
398.8		.120000 x	31.620000 =		3.794400
577		.053125 x	686.509419 =		36.470813

			T.E =		40.265213
7115	7115				
574		.026563 x	3,709.415882 =		98.533214

			T.E =		98.533214
7116	7116				
577		.170000 x	686.509419 =		116.706601

			T.E =		116.706601
7117	7117				
574		.001063 x	3,709.415882 =		3.943109

			T.E =		3.943109

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
578		.850000 x	651.504766 =	553.779051
574.1		.425000 x	2,241.497688 =	952.636517

			T.E =	1,934.587034
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
578		.850000 x	651.504766 =	553.779051
574.1		.850000 x	2,241.497688 =	1,905.273035

			T.E =	3,101.309284
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	386.217688 =	98.485510

			T.E =	312.571243
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	386.217688 =	229.799524

			T.E =	443.885257
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
578		.425000 x	651.504766 =	276.889526
575.1		.425000 x	259.627416 =	110.341652

			T.E =	547.795477
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	651.504766 =	830.668577
575.1		1.275000 x	259.627416 =	331.024955

			T.E =	1,429.300698
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.950000 =	2.953750
578		.425000 x	651.504766 =	276.889526

			T.E =	386.886142

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.950000 =	2.953750
578		.425000 x	651.504766 =	276.889526

			T.E =	386.886142
7122	7122			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.823588 =	.191477
T 630.1		.105000 x	2.070367 =	.217389
567		.122188 x	403.188672 =	49.264817
580		.122188 x	1,741.822342 =	212.829788

			AΘΡΟΙΣΜΑ =	265.878471

			T.E =	273.854825
7123	7123			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	2.070367 =	.217389
T 630		.105000 x	1.823588 =	.191477
580		.286875 x	1,741.822342 =	499.685284
567		.286875 x	403.188672 =	115.664750

			AΘΡΟΙΣΜΑ =	619.133900

			T.E =	637.707917
7124	7124			
398.1		15.000000 x	.225000 =	3.375000
567		.063750 x	403.188672 =	25.703278
T 630		.105000 x	1.823588 =	.191477
T 630.1		.105000 x	2.070367 =	.217389
580		.063750 x	1,741.822342 =	111.041174

			T.E =	140.528317
7125	7125			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	2.070367 =	.217389
567		.127500 x	403.188672 =	51.406556
T 630		.105000 x	1.823588 =	.191477
580		.127500 x	1,741.822342 =	222.082349

			T.E =	277.272770
7126	7126			
398.16		1.000000 x	64.290000 =	64.290000
580		.053125 x	1,741.822342 =	92.534312

			T.E =	156.824312

7127	7127				
398.15		1.170000 x	77.960000 =	91.213200	
580		.015938 x	1,741.822342 =	27.761164	

			T.E =	118.974364	
7128	7128				
398.14		1.170000 x	60.360000 =	70.621200	
580		.015938 x	1,741.822342 =	27.761164	

			T.E =	98.382364	
7129	7129				
6751		1.000000 x	5.376756 =	5.376756	

			T.E =	5.376756	