

ΑΤΕΟ (ΝΕΟ)

Αναλυτικά Τιμολόγια Έργων Οδοποιίας

3ο Τρίμηνο του 2010

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
211	1.047200
212	1.300000
213	1.949500
214	3.930000
215	.824400
221	.099900
222	.116200
223	.119300
224	.070000
231	.775000
232	1.900000
233	.583300
234	.835300
235	.643000
236	.612000
237	1.110000
238	.583300
239	7.950000
241	7.050000
242	5.000000
243	2.100000
244	2.590000
251	290.000000
252	290.000000
261	15.100000
262	26.300000
263	32.400000
264	64.100000
265	115.100000
271	206.300000
281	21.300000
282	30.000000
283	36.300000
284	75.400000
301	4.060000
302	6.700000
321	.396200
322	
323	.580000
324	.580000
325	2.780000
326	1.310000
327	.540000
328	1.840000
329	.730000
351	745.000000
352	1,010.000000
353	3.720000
354	4.780000
355	.118300
401	260.720000

402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
413	4.400000
414	6.070000
415	8.530000
416	13.150000
417	130.670000
418	43.600000
419	4.400000
420	94.500000
421	31.630000
422	36.920000
423	12.180000
424	40.720000
425	160.590000
426	1,199.420000
427	180.510000
428	425.280000
429	75.360000
501.1M	281.740000
501.2M	358.050000
501.3M	281.740000
501.4M	181.960000
502.1M	325.640000
502.2M	421.350000
502.3M	652.530000
502.4M	872.520000
502.5M	1,510.130000
502.6M	664.960000
504.1M	277.220000
504.2M	400.680000
504.3M	220.140000
504.4M	269.060000
505.1M	598.870000
505.2M	843.860000
506.10M	383.030000
506.1M	123.390000
506.2M	130.900000
506.3M	174.350000
506.4M	199.400000
506.5M	171.670000
506.6M	203.850000
506.7M	305.780000
506.8M	247.840000
506.9M	297.410000
508.1M	18.310000
508.2M	21.970000
508.3M	21.970000
508.4M	30.520000
509.1M	92.080000

509.2M	92.080000
509.3M	96.230000
509.4M	99.910000
511.1M	11.180000
511.2M	11.180000
511.3M	14.900000
511.4M	14.900000
511.5M	16.890000
511.6M	15.650000
512.1M	1.530000
512.2M	1.980000
512.3M	1.980000
512.4M	2.590000
512.5M	2.590000
512.6M	4.420000
512.7M	4.420000
512.8M	15.260000
512.9M	21.360000
514.1M	243.560000
514.2M	249.800000
514.3M	319.750000
514.4M	337.230000
514.5M	395.930000
515.1M	140.980000
515.2M	201.400000
515.3M	302.090000
515.4M	302.090000
515.5M	332.300000
515.6M	443.070000
515.7M	634.400000
515.8M	538.730000
517.1M	509.760000
517.2M	1,372.420000
517.3M	1,568.480000
517.4M	490.150000
517.5M	509.760000
517.6M	637.190000
518.1M	958.880000
518.2M	1,917.760000
518.3M	1,917.760000
518.4M	1,917.760000
519.1M	259.330000
519.2M	324.160000
519.3M	319.840000
519.4M	283.100000
519.5M	399.800000
519.6M	259.330000
521.1M	75.040000
521.2M	75.040000
521.3M	61.910000
521.4M	74.100000
521.5M	87.230000
521.6M	98.490000
521.7M	98.490000
523.1M	93.690000
525.1M	28.730000
526.1M	156.130000
527.1M	1,282.330000
527.2M	2,369.530000

528.1M	312.250000
528.2M	349.720000
528.3M	349.720000
528.4M	374.700000
529.1M	112.410000

501	501				
501.1		.100000 x	553.112899 =	55.311290	
501.4		.150000 x	494.494824 =	74.174224	
501.2		.600000 x	695.242378 =	417.145427	
501.3		.150000 x	553.112899 =	82.966935	
			H.Δ. =	629.597875	
501.1	501.1				
211		146.190706 x	1.047200 =	153.090907	
114		6.670000 x	23.886192 =	159.320901	
501.1M		.800000 x	281.740000 =	225.392000	
211		14.619071 x	1.047200 =	15.309091	
			H.Δ. =	553.112899	
501.2	501.2				
211		216.578823 x	1.047200 =	226.801343	
211		21.657882 x	1.047200 =	22.680134	
501.2M		.800000 x	358.050000 =	286.440000	
114		6.670000 x	23.886192 =	159.320901	
			H.Δ. =	695.242378	
501.3	501.3				
211		14.619071 x	1.047200 =	15.309091	
211		146.190706 x	1.047200 =	153.090907	
114		6.670000 x	23.886192 =	159.320901	
501.3M		.800000 x	281.740000 =	225.392000	
			H.Δ. =	553.112899	
501.4	501.4				
211		164.599905 x	1.047200 =	172.369021	
211		16.459991 x	1.047200 =	17.236903	
114		6.670000 x	23.886192 =	159.320901	
501.4M		.800000 x	181.960000 =	145.568000	
			H.Δ. =	494.494824	
502	502				
502.1		.200000 x	720.501602 =	144.100320	
502.3		.400000 x	1,178.480267 =	471.392107	
502.2		.400000 x	851.643675 =	340.657470	
			H.Δ. =	956.149897	

502.1	502.1			
211		24.365118 x	1.047200 =	25.515152
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.1M		.800000 x	325.640000 =	260.512000
211		243.651176 x	1.047200 =	255.151512
		-----		
			H.Δ. =	720.501602
502.2	502.2			
211		291.027794 x	1.047200 =	304.764306
211		29.102779 x	1.047200 =	30.476430
502.2M		.800000 x	421.350000 =	337.080000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	851.643675
502.3	502.3			
211		414.207001 x	1.047200 =	433.757571
118		2.000000 x	10.001019 =	20.002038
211		41.420700 x	1.047200 =	43.375757
114		6.670000 x	23.886192 =	159.320901
502.3M		.800000 x	652.530000 =	522.024000
		-----		
			H.Δ. =	1,178.480267
503	503			
502.3		.150000 x	1,178.480267 =	176.772040
503.4		.400000 x	1,454.264856 =	581.705942
503.6		.100000 x	1,225.846490 =	122.584649
503.5		.350000 x	2,198.241748 =	769.384612
		-----		
			H.Δ. =	1,650.447243
503.4	503.4			
211		50.083853 x	1.047200 =	52.447811
211		500.838528 x	1.047200 =	524.478107
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.4M		.800000 x	872.520000 =	698.016000
		-----		
			H.Δ. =	1,454.264856
503.5	503.5			
211		703.881180 x	1.047200 =	737.104372
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.5M		.800000 x	1,510.130000 =	1,208.104000
211		70.388118 x	1.047200 =	73.710437
		-----		
			H.Δ. =	2,198.241748

503.6	503.6			
211		44.669383 x	1.047200 =	46.777778
211		446.693825 x	1.047200 =	467.777774
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.6M		.800000 x	664.960000 =	531.968000
-----				
			H.Δ. =	1,225.846490
504	504			
504.1		.350000 x	674.237638 =	235.983173
504.4		.100000 x	647.751120 =	64.775112
504.2		.450000 x	847.850082 =	381.532537
504.3		.100000 x	628.573638 =	62.857364
-----				
			H.Δ. =	745.148186
504.1	504.1			
211		254.480118 x	1.047200 =	266.491580
114		6.670000 x	23.886192 =	159.320901
211		25.448012 x	1.047200 =	26.649158
504.1M		.800000 x	277.220000 =	221.776000
-----				
			H.Δ. =	674.237638
504.2	504.2			
211		319.453766 x	1.047200 =	334.531984
114		6.670000 x	23.886192 =	159.320901
211		31.945376 x	1.047200 =	33.453198
504.2M		.800000 x	400.680000 =	320.544000
-----				
			H.Δ. =	847.850082
504.3	504.3			
211		25.448012 x	1.047200 =	26.649158
114		6.670000 x	23.886192 =	159.320901
504.3M		.800000 x	220.140000 =	176.112000
211		254.480118 x	1.047200 =	266.491580
-----				
			H.Δ. =	628.573638
504.4	504.4			
211		237.153812 x	1.047200 =	248.347472
211		23.715381 x	1.047200 =	24.834747
504.4M		.800000 x	269.060000 =	215.248000
114		6.670000 x	23.886192 =	159.320901
-----				
			H.Δ. =	647.751120



505	505				
505.1		.500000 x	1,090.065418 =	545.032709	
505.2		.500000 x	1,286.057418 =	643.028709	
-----					
			H.Δ. =	1,188.061418	
505.1	505.1				
211		35.735506 x	1.047200 =	37.422222	
118		4.000000 x	10.001019 =	40.004076	
505.1M		.800000 x	598.870000 =	479.096000	
114		6.670000 x	23.886192 =	159.320901	
211		357.355061 x	1.047200 =	374.222220	
-----					
			H.Δ. =	1,090.065418	
505.2	505.2				
211		35.735506 x	1.047200 =	37.422222	
505.2M		.800000 x	843.860000 =	675.088000	
114		6.670000 x	23.886192 =	159.320901	
118		4.000000 x	10.001019 =	40.004076	
211		357.355061 x	1.047200 =	374.222220	
-----					
			H.Δ. =	1,286.057418	
506	506				
506.1		.100000 x	401.008517 =	40.100852	
506.4		.350000 x	503.708615 =	176.298015	
506.2		.200000 x	438.097751 =	87.619550	
506.3		.350000 x	453.938739 =	158.878559	
-----					
			H.Δ. =	462.896976	
506.1	506.1				
211		10.675531 x	1.047200 =	11.179416	
118		2.000000 x	10.001019 =	20.002038	
114		6.670000 x	23.886192 =	159.320901	
506.1M		.800000 x	123.390000 =	98.712000	
211		106.755312 x	1.047200 =	111.794163	
-----					
			H.Δ. =	401.008517	
506.2	506.2				
211		13.373742 x	1.047200 =	14.004983	
211		133.737423 x	1.047200 =	140.049829	
506.2M		.800000 x	130.900000 =	104.720000	
118		2.000000 x	10.001019 =	20.002038	
114		6.670000 x	23.886192 =	159.320901	
-----					
			H.Δ. =	438.097751	

506.3	506.3			
211		117.313529 x	1.047200 =	122.850728
118		2.000000 x	10.001019 =	20.002038
211		11.731353 x	1.047200 =	12.285073
114		6.670000 x	23.886192 =	159.320901
506.3M		.800000 x	174.350000 =	139.480000
		-----		
			H.Δ. =	453.938739
506.4	506.4			
211		14.312251 x	1.047200 =	14.987789
211		143.122505 x	1.047200 =	149.877887
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
506.4M		.800000 x	199.400000 =	159.520000
		-----		
			H.Δ. =	503.708615
507	507			
507.5		.100000 x	532.876220 =	53.287622
507.8		.100000 x	597.866293 =	59.786629
507.10		.250000 x	870.883971 =	217.720993
507.9		.350000 x	692.927971 =	242.524790
507.6		.100000 x	646.458490 =	64.645849
507.7		.100000 x	741.516070 =	74.151607
		-----		
			H.Δ. =	712.117490
507.10	507.10			
211		334.343559 x	1.047200 =	350.124575
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.10M		.800000 x	383.030000 =	306.424000
211		33.434356 x	1.047200 =	35.012458
		-----		
			H.Δ. =	870.883971
507.5	507.5			
211		187.701647 x	1.047200 =	196.561165
506.5M		.800000 x	171.670000 =	137.336000
211		18.770165 x	1.047200 =	19.656117
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	532.876220

507.6	507.6			
211		263.955441 x	1.047200 =	276.414138
118		2.000000 x	10.001019 =	20.002038
211		26.395544 x	1.047200 =	27.641414
114		6.670000 x	23.886192 =	159.320901
506.6M		.800000 x	203.850000 =	163.080000
		-----		
			H.Δ. =	646.458490
507.7	507.7			
211		27.568679 x	1.047200 =	28.869921
506.7M		.800000 x	305.780000 =	244.624000
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
211		275.686794 x	1.047200 =	288.699211
		-----		
			H.Δ. =	741.516070
507.8	507.8			
211		191.221052 x	1.047200 =	200.246686
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.8M		.800000 x	247.840000 =	198.272000
211		19.122105 x	1.047200 =	20.024668
		-----		
			H.Δ. =	597.866293
507.9	507.9			
211		23.931960 x	1.047200 =	25.061549
211		239.319599 x	1.047200 =	250.615484
506.9M		.800000 x	297.410000 =	237.928000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	692.927971
508	508			
508.1		.250000 x	363.033390 =	90.758348
508.4		.250000 x	441.720648 =	110.430162
508.2		.250000 x	406.502130 =	101.625533
508.3		.250000 x	406.502130 =	101.625533
		-----		
			H.Δ. =	404.439575
508.1	508.1			
211		28.155247 x	1.047200 =	29.484175
116		13.340000 x	20.419486 =	272.395943
211		2.815525 x	1.047200 =	2.948418
115		2.000000 x	21.778427 =	43.556854
508.1M		.800000 x	18.310000 =	14.648000
		-----		
			H.Δ. =	363.033390

508.2	508.2				
211		6.334931 x	1.047200 =	6.633940	
211		63.349306 x	1.047200 =	66.339393	
115		2.000000 x	21.778427 =	43.556854	
116		13.340000 x	20.419486 =	272.395943	
508.2M		.800000 x	21.970000 =	17.576000	
-----					
			H.Δ. =	406.502130	
508.3	508.3				
211		6.334931 x	1.047200 =	6.633940	
116		13.340000 x	20.419486 =	272.395943	
115		2.000000 x	21.778427 =	43.556854	
508.3M		.800000 x	21.970000 =	17.576000	
211		63.349306 x	1.047200 =	66.339393	
-----					
			H.Δ. =	406.502130	
508.4	508.4				
211		87.985147 x	1.047200 =	92.138046	
211		8.798515 x	1.047200 =	9.213805	
508.4M		.800000 x	30.520000 =	24.416000	
116		13.340000 x	20.419486 =	272.395943	
115		2.000000 x	21.778427 =	43.556854	
-----					
			H.Δ. =	441.720648	
509	509				
509.1		.100000 x	513.017146 =	51.301715	
509.2		.200000 x	466.239369 =	93.247874	
509.4		.500000 x	547.347814 =	273.673907	
509.3		.200000 x	567.792703 =	113.558541	
-----					
			H.Δ. =	531.782036	
509.1	509.1				
211		284.259705 x	1.047200 =	297.676763	
211		28.425971 x	1.047200 =	29.767677	
509.1M		.800000 x	92.080000 =	73.664000	
117		6.670000 x	16.777917 =	111.908706	
-----					
			H.Δ. =	513.017146	
509.2	509.2				
211		243.651176 x	1.047200 =	255.151512	
211		24.365118 x	1.047200 =	25.515152	
117		6.670000 x	16.777917 =	111.908706	
509.2M		.800000 x	92.080000 =	73.664000	
-----					
			H.Δ. =	466.239369	

509.3	509.3			
211		32.892909 x	1.047200 =	34.445454
117		6.670000 x	16.777917 =	111.908706
509.3M		.800000 x	96.230000 =	76.984000
211		328.929089 x	1.047200 =	344.454542
		-----		
			H.Δ. =	567.792703
509.4	509.4			
211		308.624825 x	1.047200 =	323.191917
117		6.670000 x	16.777917 =	111.908706
211		30.862482 x	1.047200 =	32.319191
509.4M		.800000 x	99.910000 =	79.928000
		-----		
			H.Δ. =	547.347814
511	511			
511.1		.150000 x	390.866966 =	58.630045
511.2		.150000 x	389.494818 =	58.424223
511.3		.225000 x	393.842966 =	88.614667
511.4		.225000 x	394.186003 =	88.691851
511.6		.125000 x	394.442966 =	49.305371
511.5		.125000 x	395.778003 =	49.472250
		-----		
			H.Δ. =	393.138407
511.1	511.1			
211		.496326 x	1.047200 =	.519753
112		13.340000 x	17.312112 =	230.943574
115		6.670000 x	21.778427 =	145.262108
211		4.963265 x	1.047200 =	5.197531
511.1M		.800000 x	11.180000 =	8.944000
		-----		
			H.Δ. =	390.866966
511.2	511.2			
211		.377208 x	1.047200 =	.395012
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
211		3.772081 x	1.047200 =	3.950123
511.2M		.800000 x	11.180000 =	8.944000
		-----		
			H.Δ. =	389.494818
511.3	511.3			
211		4.963265 x	1.047200 =	5.197531
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.3M		.800000 x	14.900000 =	11.920000
211		.496326 x	1.047200 =	.519753
		-----		
			H.Δ. =	393.842966

511.4	511.4			
211		5.261061 x	1.047200 =	5.509383
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.4M		.800000 x	14.900000 =	11.920000
211		.526106 x	1.047200 =	.550938
		-----		
			H.Δ. =	394.186003
511.5	511.5			
211		5.261061 x	1.047200 =	5.509383
211		.526106 x	1.047200 =	.550938
511.5M		.800000 x	16.890000 =	13.512000
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
		-----		
			H.Δ. =	395.778003
511.6	511.6			
211		4.963265 x	1.047200 =	5.197531
115		6.670000 x	21.778427 =	145.262108
511.6M		.800000 x	15.650000 =	12.520000
112		13.340000 x	17.312112 =	230.943574
211		.496326 x	1.047200 =	.519753
		-----		
			H.Δ. =	394.442966
512	512			
512.1		.200000 x	105.573099 =	21.114620
512.4		.200000 x	154.024708 =	30.804942
512.5		.200000 x	156.103721 =	31.220744
512.3		.200000 x	112.170136 =	22.434027
512.2		.200000 x	109.051618 =	21.810324
		-----		
			H.Δ. =	127.384656
512.1	512.1			
211		1.804824 x	1.047200 =	1.890012
117		3.000000 x	16.777917 =	50.333751
512.1M		.800000 x	1.530000 =	1.224000
112		3.000000 x	17.312112 =	51.936336
211		.180482 x	1.047200 =	.189001
		-----		
			H.Δ. =	105.573099

512.2	512.2			
211		4.512059 x	1.047200 =	4.725028
112		3.000000 x	17.312112 =	51.936336
512.2M		.800000 x	1.980000 =	1.584000
117		3.000000 x	16.777917 =	50.333751
211		.451206 x	1.047200 =	.472503
		-----		
			H.Δ. =	109.051618
512.3	512.3			
211		.721929 x	1.047200 =	.756004
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
512.3M		.800000 x	1.980000 =	1.584000
211		7.219294 x	1.047200 =	7.560045
		-----		
			H.Δ. =	112.170136
512.4	512.4			
211		1.353618 x	1.047200 =	1.417509
211		13.536176 x	1.047200 =	14.175084
512.4M		.800000 x	2.590000 =	2.072000
117		4.000000 x	16.777917 =	67.111668
112		4.000000 x	17.312112 =	69.248448
		-----		
			H.Δ. =	154.024708
512.5	512.5			
211		15.341000 x	1.047200 =	16.065095
117		4.000000 x	16.777917 =	67.111668
211		1.534100 x	1.047200 =	1.606510
112		4.000000 x	17.312112 =	69.248448
512.5M		.800000 x	2.590000 =	2.072000
		-----		
			H.Δ. =	156.103721
512A	512A			
512.1		.333333 x	105.573099 =	35.190998
512.2		.333333 x	109.051618 =	36.350503
512.3		.333333 x	112.170136 =	37.390008
		-----		
			H.Δ. =	108.931509
512B	512B			
512.4		.500000 x	154.024708 =	77.012354
512.5		.500000 x	156.103721 =	78.051861
		-----		
			H.Δ. =	155.064215

513	513				
513.6		.250000 x	205.171330 =	51.292833	
513.9		.250000 x	271.495654 =	67.873914	
513.8		.250000 x	259.339110 =	64.834778	
513.7		.250000 x	215.566391 =	53.891598	
		-----			
			H.Δ. =	237.893121	
513.6	513.6				
211		2.707235 x	1.047200 =	2.835016	
211		27.072353 x	1.047200 =	28.350168	
112		5.000000 x	17.312112 =	86.560560	
117		5.000000 x	16.777917 =	83.889585	
512.6M		.800000 x	4.420000 =	3.536000	
		-----			
			H.Δ. =	205.171330	
513.7	513.7				
211		3.609647 x	1.047200 =	3.780022	
117		5.000000 x	16.777917 =	83.889585	
112		5.000000 x	17.312112 =	86.560560	
512.7M		.800000 x	4.420000 =	3.536000	
211		36.096470 x	1.047200 =	37.800223	
		-----			
			H.Δ. =	215.566391	
513.8	513.8				
211		1.714582 x	1.047200 =	1.795510	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
512.8M		.800000 x	15.260000 =	12.208000	
211		17.145823 x	1.047200 =	17.955106	
		-----			
			H.Δ. =	259.339110	
513.9	513.9				
211		23.462706 x	1.047200 =	24.570146	
211		2.346271 x	1.047200 =	2.457015	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
512.9M		.800000 x	21.360000 =	17.088000	
		-----			
			H.Δ. =	271.495654	
513A	513A				
513.6		.500000 x	205.171330 =	102.585665	
513.7		.500000 x	215.566391 =	107.783196	
		-----			
			H.Δ. =	210.368861	



513B	513B				
513.9		1.000000 x	271.495654 =	271.495654	
			H.Δ. =	271.495654	
514	514				
514.1		.150000 x	581.057701 =	87.158655	
514.5		.300000 x	843.287033 =	252.986110	
514.2		.150000 x	595.405257 =	89.310789	
514.4		.250000 x	718.364072 =	179.591018	
514.3		.150000 x	657.602294 =	98.640344	
			H.Δ. =	707.686916	
514.1	514.1				
211		5.865676 x	1.047200 =	6.142536	
211		58.656765 x	1.047200 =	61.425364	
114		13.340000 x	23.886192 =	318.641801	
514.1M		.800000 x	243.560000 =	194.848000	
			H.Δ. =	581.057701	
514.2	514.2				
211		66.778471 x	1.047200 =	69.930415	
211		6.677847 x	1.047200 =	6.993041	
114		13.340000 x	23.886192 =	318.641801	
514.2M		.800000 x	249.800000 =	199.840000	
			H.Δ. =	595.405257	
514.3	514.3				
211		7.219294 x	1.047200 =	7.560045	
114		13.340000 x	23.886192 =	318.641801	
514.3M		.800000 x	319.750000 =	255.800000	
211		72.192941 x	1.047200 =	75.600448	
			H.Δ. =	657.602294	
514.4	514.4				
211		112.801471 x	1.047200 =	118.125700	
114		13.340000 x	23.886192 =	318.641801	
514.4M		.800000 x	337.230000 =	269.784000	
211		11.280147 x	1.047200 =	11.812570	
			H.Δ. =	718.364072	

514.5	514.5				
211		18.048235 x	1.047200 =	18.900112	
211		180.482353 x	1.047200 =	189.001120	
514.5M		.800000 x	395.930000 =	316.744000	
114		13.340000 x	23.886192 =	318.641801	
		-----			
			H.Δ. =	843.287033	
515	515				
515.1		.200000 x	365.244652 =	73.048930	
515.2		.200000 x	445.181640 =	89.036328	
515.5		.200000 x	649.694230 =	129.938846	
515.4		.200000 x	588.104010 =	117.620802	
515.3		.200000 x	587.272405 =	117.454481	
		-----			
			H.Δ. =	527.099387	
515.1	515.1				
211		8.085609 x	1.047200 =	8.467250	
211		80.856094 x	1.047200 =	84.672502	
515.1M		.800000 x	140.980000 =	112.784000	
114		6.670000 x	23.886192 =	159.320901	
		-----			
			H.Δ. =	365.244652	
515.2	515.2				
211		10.828941 x	1.047200 =	11.340067	
211		108.289412 x	1.047200 =	113.400672	
114		6.670000 x	23.886192 =	159.320901	
515.2M		.800000 x	201.400000 =	161.120000	
		-----			
			H.Δ. =	445.181640	
515.3	515.3				
211		16.171219 x	1.047200 =	16.934501	
114		6.670000 x	23.886192 =	159.320901	
515.3M		.800000 x	302.090000 =	241.672000	
211		161.712189 x	1.047200 =	169.345004	
		-----			
			H.Δ. =	587.272405	
515.4	515.4				
211		16.243412 x	1.047200 =	17.010101	
114		6.670000 x	23.886192 =	159.320901	
211		162.434118 x	1.047200 =	170.101008	
515.4M		.800000 x	302.090000 =	241.672000	
		-----			
			H.Δ. =	588.104010	

515.5	515.5			
211		194.920940 x	1.047200 =	204.121208
515.5M		.800000 x	332.300000 =	265.840000
114		6.670000 x	23.886192 =	159.320901
211		19.492094 x	1.047200 =	20.412121
		-----		
			H.Δ. =	649.694230
516	516			
515.5		.150000 x	649.694230 =	97.454135
516.8		.350000 x	896.335515 =	313.717430
516.7		.350000 x	978.692749 =	342.542462
516.6		.150000 x	754.942330 =	113.241350
		-----		
			H.Δ. =	866.955376
516.6	516.6			
211		209.359530 x	1.047200 =	219.241300
211		20.935953 x	1.047200 =	21.924130
515.6M		.800000 x	443.070000 =	354.456000
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	754.942330
516.7	516.7			
211		27.072353 x	1.047200 =	28.350168
211		270.723530 x	1.047200 =	283.501681
114		6.670000 x	23.886192 =	159.320901
515.7M		.800000 x	634.400000 =	507.520000
		-----		
			H.Δ. =	978.692749
516.8	516.8			
211		265.670025 x	1.047200 =	278.209650
114		6.670000 x	23.886192 =	159.320901
515.8M		.800000 x	538.730000 =	430.984000
211		26.567002 x	1.047200 =	27.820964
		-----		
			H.Δ. =	896.335515
517	517			
517.1		.100000 x	1,223.352755 =	122.335276
517.2		.250000 x	2,152.567173 =	538.141793
517.3		.250000 x	2,454.946033 =	613.736508
517.5		.100000 x	1,197.365101 =	119.736510
517.6		.200000 x	1,377.272062 =	275.454412
517.4		.100000 x	1,129.701794 =	112.970179
		-----		
			H.Δ. =	1,782.374679

517.1	517.1			
211		15.792206 x	1.047200 =	16.537598
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
211		157.922058 x	1.047200 =	165.375979
517.1M		.800000 x	509.760000 =	407.808000
-----				
			H.Δ. =	1,223.352755
517.2	517.2			
211		365.476765 x	1.047200 =	382.727268
114		13.340000 x	23.886192 =	318.641801
211		36.547677 x	1.047200 =	38.272727
111		20.010000 x	15.741598 =	314.989376
517.2M		.800000 x	1,372.420000 =	1,097.936000
-----				
			H.Δ. =	2,152.567173
517.3	517.3			
211		49.181441 x	1.047200 =	51.502805
111		20.010000 x	15.741598 =	314.989376
211		491.814411 x	1.047200 =	515.028051
114		13.340000 x	23.886192 =	318.641801
517.3M		.800000 x	1,568.480000 =	1,254.784000
-----				
			H.Δ. =	2,454.946033
517.4	517.4			
211		9.024118 x	1.047200 =	9.450056
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.4M		.800000 x	490.150000 =	392.120000
211		90.241177 x	1.047200 =	94.500561
-----				
			H.Δ. =	1,129.701794
517.5	517.5			
211		135.361765 x	1.047200 =	141.750840
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.5M		.800000 x	509.760000 =	407.808000
211		13.536176 x	1.047200 =	14.175084
-----				
			H.Δ. =	1,197.365101

517.6	517.6			
211		20.304265 x	1.047200 =	21.262626
211		203.042646 x	1.047200 =	212.626259
517.6M		.800000 x	637.190000 =	509.752000
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
		-----		
			H.Δ. =	1,377.272062
518	518			
518.1		.250000 x	1,889.784253 =	472.446063
518.4		.250000 x	2,715.100596 =	678.775149
518.2		.250000 x	2,656.888253 =	664.222063
518.3		.250000 x	2,685.994425 =	671.498606
		-----		
			H.Δ. =	2,486.941882
518.1	518.1			
211		265.309059 x	1.047200 =	277.831647
116		13.340000 x	20.419486 =	272.395943
118		6.670000 x	10.001019 =	66.706797
114		20.010000 x	23.886192 =	477.962702
518.1M		.800000 x	958.880000 =	767.104000
211		26.530906 x	1.047200 =	27.783165
		-----		
			H.Δ. =	1,889.784253
518.2	518.2			
211		26.530906 x	1.047200 =	27.783165
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
518.2M		.800000 x	1,917.760000 =	1,534.208000
211		265.309059 x	1.047200 =	277.831647
		-----		
			H.Δ. =	2,656.888253
518.3	518.3			
211		290.576588 x	1.047200 =	304.291803
114		20.010000 x	23.886192 =	477.962702
518.3M		.800000 x	1,917.760000 =	1,534.208000
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
211		29.057659 x	1.047200 =	30.429181
		-----		
			H.Δ. =	2,685.994425

518.4	518.4			
211		31.584412 x	1.047200 =	33.075196
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
518.4M		.800000 x	1,917.760000 =	1,534.208000
211		315.844116 x	1.047200 =	330.751958
		-----		
			H.Δ. =	2,715.100596
519	519			
519.1		.050000 x	720.715067 =	36.035753
519.3		.300000 x	773.819731 =	232.145919
519.5		.100000 x	972.923531 =	97.292353
519.6		.300000 x	680.816918 =	204.245075
519.4		.200000 x	737.670942 =	147.534188
519.2		.050000 x	811.059681 =	40.552984
		-----		
			H.Δ. =	757.806274
519.1	519.1			
211		171.277754 x	1.047200 =	179.362064
519.1M		.800000 x	259.330000 =	207.464000
211		17.127775 x	1.047200 =	17.936206
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
		-----		
			H.Δ. =	720.715067
519.2	519.2			
211		234.627058 x	1.047200 =	245.701455
116		6.670000 x	20.419486 =	136.197972
211		23.462706 x	1.047200 =	24.570146
115		6.670000 x	21.778427 =	145.262108
519.2M		.800000 x	324.160000 =	259.328000
		-----		
			H.Δ. =	811.059681
519.3	519.3			
211		20.529868 x	1.047200 =	21.498878
519.3M		.800000 x	319.840000 =	255.872000
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
211		205.298676 x	1.047200 =	214.988774
		-----		
			H.Δ. =	773.819731

519.4	519.4			
211		199.433001 x	1.047200 =	208.846239
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
519.4M		.800000 x	283.100000 =	226.480000
211		19.943300 x	1.047200 =	20.884624

-----  
 Η.Δ. = 737.670942

519.5	519.5			
211		32.261220 x	1.047200 =	33.783950
211		322.612206 x	1.047200 =	337.839502
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.5M		.800000 x	399.800000 =	319.840000

-----  
 Η.Δ. = 972.923531

519.6	519.6			
211		16.658521 x	1.047200 =	17.444803
211		166.585213 x	1.047200 =	174.448035
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
519.6M		.800000 x	259.330000 =	207.464000

-----  
 Η.Δ. = 680.816918

521	521			
521.1		.250000 x	315.425029 =	78.856257
521.2		.250000 x	321.662068 =	80.415517
521.4		.150000 x	362.074511 =	54.311177
521.5		.150000 x	372.578511 =	55.886777
521.3		.200000 x	307.415845 =	61.483169

-----  
 Η.Δ. = 330.952897

521.1	521.1			
211		7.471969 x	1.047200 =	7.824646
521.1M		.800000 x	75.040000 =	60.032000
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
211		74.719694 x	1.047200 =	78.246464

-----  
 Η.Δ. = 315.425029

521.2	521.2			
211		80.134165 x	1.047200 =	83.916498
211		8.013417 x	1.047200 =	8.391650
114		6.670000 x	23.886192 =	159.320901
118		1.000000 x	10.001019 =	10.001019
521.2M		.800000 x	75.040000 =	60.032000
		-----		
			H.Δ. =	321.662068
521.3	521.3			
211		76.885483 x	1.047200 =	80.514478
211		7.688548 x	1.047200 =	8.051447
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.3M		.800000 x	61.910000 =	49.528000
		-----		
			H.Δ. =	307.415845
521.4	521.4			
211		11.586967 x	1.047200 =	12.133872
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.4M		.800000 x	74.100000 =	59.280000
211		115.869671 x	1.047200 =	121.338719
		-----		
			H.Δ. =	362.074511
521.5	521.5			
211		115.869671 x	1.047200 =	121.338719
211		11.586967 x	1.047200 =	12.133872
521.5M		.800000 x	87.230000 =	69.784000
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	372.578511
522	522			
522.6		.500000 x	455.205307 =	227.602654
522.7		.500000 x	450.215676 =	225.107838
		-----		
			H.Δ. =	452.710492
522.6	522.6			
211		17.109727 x	1.047200 =	17.917306
118		2.000000 x	10.001019 =	20.002038
211		171.097271 x	1.047200 =	179.173062
114		6.670000 x	23.886192 =	159.320901
521.6M		.800000 x	98.490000 =	78.792000
		-----		
			H.Δ. =	455.205307



522.7	522.7			
211		16.676569 x	1.047200 =	17.463703
211		166.765694 x	1.047200 =	174.637035
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
521.7M		.800000 x	98.490000 =	78.792000
		-----		
			H.Δ. =	450.215676
523	523			
523.1		1.000000 x	354.227535 =	354.227535
		-----		
			H.Δ. =	354.227535
523.1	523.1			
211		54.144706 x	1.047200 =	56.700336
117		6.670000 x	16.777917 =	111.908706
111		6.670000 x	15.741598 =	104.996459
523.1M		.800000 x	93.690000 =	74.952000
211		5.414471 x	1.047200 =	5.670034
		-----		
			H.Δ. =	354.227535
525	525			
525.1		1.000000 x	246.662563 =	246.662563
		-----		
			H.Δ. =	246.662563
525.1	525.1			
211		4.512059 x	1.047200 =	4.725028
118		6.670000 x	10.001019 =	66.706797
111		6.670000 x	15.741598 =	104.996459
525.1M		.800000 x	28.730000 =	22.984000
211		45.120588 x	1.047200 =	47.250280
		-----		
			H.Δ. =	246.662563
526	526			
526.1		1.000000 x	547.482426 =	547.482426
		-----		
			H.Δ. =	547.482426
526.1	526.1			
211		243.651176 x	1.047200 =	255.151512
526.1M		.800000 x	156.130000 =	124.904000
118		3.000000 x	10.001019 =	30.003057
117		6.670000 x	16.777917 =	111.908706
211		24.365118 x	1.047200 =	25.515152
		-----		
			H.Δ. =	547.482426

527	527				
527.1		.400000 x	2,105.427222 =		842.170889
527.2		.600000 x	3,099.927964 =		1,859.956778
-----					
			H.Δ. =		2,702.127667
527.1	527.1				
211		433.157646 x	1.047200 =		453.602687
211		43.315765 x	1.047200 =		45.360269
527.1M		.800000 x	1,282.330000 =		1,025.864000
112		6.670000 x	17.312112 =		115.471787
118		6.670000 x	10.001019 =		66.706797
114		16.680000 x	23.886192 =		398.421683
-----					
			H.Δ. =		2,105.427222
527.2	527.2				
211		54.144706 x	1.047200 =		56.700336
211		541.447060 x	1.047200 =		567.003361
114		16.680000 x	23.886192 =		398.421683
118		6.670000 x	10.001019 =		66.706797
112		6.670000 x	17.312112 =		115.471787
527.2M		.800000 x	2,369.530000 =		1,895.624000
-----					
			H.Δ. =		3,099.927964
528	528				
528.1		.250000 x	798.247814 =		199.561954
528.4		.250000 x	912.657195 =		228.164299
528.3		.250000 x	846.934925 =		211.733731
528.2		.250000 x	857.329986 =		214.332497
-----					
			H.Δ. =		853.792480
528.1	528.1				
211		79.412235 x	1.047200 =		83.160492
118		6.670000 x	10.001019 =		66.706797
114		6.670000 x	23.886192 =		159.320901
112		13.340000 x	17.312112 =		230.943574
528.1M		.800000 x	312.250000 =		249.800000
211		7.941224 x	1.047200 =		8.316050
-----					
			H.Δ. =		798.247814

528.2	528.2			
211		10.467976 x	1.047200 =	10.962064
211		104.679765 x	1.047200 =	109.620650
528.2M		.800000 x	349.720000 =	279.776000
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
		-----		
			H.Δ. =	857.329986
528.3	528.3			
211		9.565565 x	1.047200 =	10.017060
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
211		95.655647 x	1.047200 =	100.170594
112		13.340000 x	17.312112 =	230.943574
528.3M		.800000 x	349.720000 =	279.776000
		-----		
			H.Δ. =	846.934925
528.4	528.4			
211		135.361765 x	1.047200 =	141.750840
211		13.536176 x	1.047200 =	14.175084
112		13.340000 x	17.312112 =	230.943574
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
528.4M		.800000 x	374.700000 =	299.760000
		-----		
			H.Δ. =	912.657195
529	529			
529.1		1.000000 x	713.446944 =	713.446944
		-----		
			H.Δ. =	713.446944
529.1	529.1			
211		243.651176 x	1.047200 =	255.151512
117		6.670000 x	16.777917 =	111.908706
112		13.340000 x	17.312112 =	230.943574
529.1M		.800000 x	112.410000 =	89.928000
211		24.365118 x	1.047200 =	25.515152
		-----		
			H.Δ. =	713.446944

2730A	2730A			
234		48.000000 x	.835300 =	40.094400
513		.250000 x	237.893121 =	59.473280
511		.150000 x	393.138407 =	58.970761
517		1.000000 x	1,782.374679 =	1,782.374679
504		.400000 x	745.148186 =	298.059274
509		.200000 x	531.782036 =	106.356407
509		.400000 x	531.782036 =	212.712814
113		13.340000 x	20.419486 =	272.395943
112		6.670000 x	17.312112 =	115.471787
111		6.670000 x	15.741598 =	104.996459
251		.040000 x	290.000000 =	11.600000
235		24.000000 x	.643000 =	15.432000

-----  
 B.T = 3,077.937805

2730B	2730B			
234		1,000.000000 x	.835300 =	835.300000
113		140.000000 x	20.419486 =	2,858.728040
112		360.000000 x	17.312112 =	6,232.360320
506		2.500000 x	462.896976 =	1,157.242440
517		9.000000 x	1,782.374679 =	16,041.372111
515		7.000000 x	527.099387 =	3,689.695709
509		5.000000 x	531.782036 =	2,658.910180
509		2.209627 x	531.782036 =	1,175.039945
111		360.000000 x	15.741598 =	5,666.975280
252		2.000000 x	290.000000 =	580.000000
235		500.000000 x	.643000 =	321.500000
251		2.000000 x	290.000000 =	580.000000

-----  
 B.T = 41,797.124025

2730Γ	2730Γ			
222		350.000000 x	.116200 =	40.670000
625		.500000 x	16.044945 =	8.022473
630		.200000 x	.542022 =	.108404
623		.800000 x	14.536107 =	11.628886

-----  
 B.T = 60.429763

611	611			
111		1.400000 x	15.741598 =	22.038237

-----  
 B.T = 22.038237

612	612			
111		.250000 x	15.741598 =	3.935400
504		.000833 x	745.148186 =	.620708
503		.000588 x	1,650.447243 =	.970463

-----  
 B.T = 5.526571

613	613			
111		.200000 x	15.741598 =	3.148320
518		.000500 x	2,486.941882 =	1.243471
504		.001000 x	745.148186 =	.745148
503		.000667 x	1,650.447243 =	1.100848
-----				
			B.T =	6.237787
614	614			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,486.941882 =	6.217355
504		.001000 x	745.148186 =	.745148
509		.001950 x	531.782036 =	1.036975
503		.000909 x	1,650.447243 =	1.500257
-----				
			B.T =	10.884703
615	615			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,486.941882 =	6.217355
503		.000909 x	1,650.447243 =	1.500257
504		.001000 x	745.148186 =	.745148
509		.001950 x	531.782036 =	1.036975
-----				
			B.T =	10.884703
616	616			
112		.080000 x	17.312112 =	1.384969
504		.001000 x	745.148186 =	.745148
509		.001950 x	531.782036 =	1.036975
518		.002500 x	2,486.941882 =	6.217355
503		.000909 x	1,650.447243 =	1.500257
-----				
			B.T =	10.884703
617	617			
111		.100000 x	15.741598 =	1.574160
518		.000625 x	2,486.941882 =	1.554339
504		.001000 x	745.148186 =	.745148
503		.001000 x	1,650.447243 =	1.650447
-----				
			B.T =	5.524094
621	621			
213		1.000000 x	1.949500 =	1.949500
519		.002500 x	757.806274 =	1.894516
116		.060000 x	20.419486 =	1.225169
111		.650000 x	15.741598 =	10.232039
-----				
			B.T =	15.301224

622	622			
213		1.000000 x	1.949500 =	1.949500
518		.001515 x	2,486.941882 =	3.767717
504		.001111 x	745.148186 =	.827860
519		.002500 x	757.806274 =	1.894516
509		.001950 x	531.782036 =	1.036975
112		.100000 x	17.312112 =	1.731211
116		.100000 x	20.419486 =	2.041949
503		.000909 x	1,650.447243 =	1.500257
-----				
			B.T =	14.749984
623	623			
213		1.000000 x	1.949500 =	1.949500
116		.100000 x	20.419486 =	2.041949
518		.001429 x	2,486.941882 =	3.553840
504		.001111 x	745.148186 =	.827860
519		.002500 x	757.806274 =	1.894516
509		.001950 x	531.782036 =	1.036975
503		.000909 x	1,650.447243 =	1.500257
112		.100000 x	17.312112 =	1.731211
-----				
			B.T =	14.536107
624	624			
213		1.000000 x	1.949500 =	1.949500
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
503		.000909 x	1,650.447243 =	1.500257
509		.001950 x	531.782036 =	1.036975
518		.001515 x	2,486.941882 =	3.767717
504		.001111 x	745.148186 =	.827860
519		.002500 x	757.806274 =	1.894516
-----				
			B.T =	14.749984
625	625			
213		1.000000 x	1.949500 =	1.949500
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
509		.001950 x	531.782036 =	1.036975
518		.002119 x	2,486.941882 =	5.269830
504		.000833 x	745.148186 =	.620708
519		.002500 x	757.806274 =	1.894516
503		.000909 x	1,650.447243 =	1.500257
-----				
			B.T =	16.044945
626	626			
509		.001786 x	531.782036 =	.949763
504		.002000 x	745.148186 =	1.490296
-----				
			B.T =	2.440059

630	630			
512		.004255 x	127.384656 =	.542022
-----				
			B.T =	.542022
641	641			
231		.200000 x	.775000 =	.155000
252		.002500 x	290.000000 =	.725000
113		.150000 x	20.419486 =	3.062923
111		.200000 x	15.741598 =	3.148320
251		.001500 x	290.000000 =	.435000
-----				
			B.T =	7.526243
642	642			
231		.300000 x	.775000 =	.232500
113		.250000 x	20.419486 =	5.104872
111		.250000 x	15.741598 =	3.935400
252		.005000 x	290.000000 =	1.450000
251		.003000 x	290.000000 =	.870000
-----				
			B.T =	11.592771
651	651			
221		150.000000 x	.099900 =	14.985000
224		120.000000 x	.070000 =	8.400000
511		.040000 x	393.138407 =	15.725536
509		.007516 x	531.782036 =	3.996874
509		.002166 x	531.782036 =	1.151840
630		.600000 x	.542022 =	.325213
625		1.000000 x	16.044945 =	16.044945
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397
-----				
			B.T =	92.897861
652	652			
221		650.000000 x	.099900 =	64.935000
625		1.000000 x	16.044945 =	16.044945
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397
630		.320000 x	.542022 =	.173447
511		.040000 x	393.138407 =	15.725536
509		.007516 x	531.782036 =	3.996874
509		.002166 x	531.782036 =	1.151840
-----				
			B.T =	134.296095

661	661			
353		.160000 x	3.720000 =	.595200
113		1.100000 x	20.419486 =	22.461435
354		.220000 x	4.780000 =	1.051600
355		.250000 x	.118300 =	.029575
-----				
			B.T =	24.137810
671	671			
215		.562500 x	.824400 =	.463725
525		.000067 x	246.662563 =	.016526
111		.002000 x	15.741598 =	.031483
321		.550000 x	.396200 =	.217910
-----				
			B.T =	.729645
671.1	671.1			
215		.562500 x	.824400 =	.463725
525		.000067 x	246.662563 =	.016526
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.511735
672	672			
215		.075000 x	.824400 =	.061830
111		.002000 x	15.741598 =	.031483
525		.000067 x	246.662563 =	.016526
321		.940000 x	.396200 =	.372428
-----				
			B.T =	.482268
672.1	672.1			
215		.075000 x	.824400 =	.061830
525		.000067 x	246.662563 =	.016526
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.109840
4311A	4311A			
321		80.000000 x	.396200 =	31.696000
616		.200000 x	10.884703 =	2.176941
615		.370000 x	10.884703 =	4.027340
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
626		.030000 x	2.440059 =	.073202
625		.500000 x	16.044945 =	8.022473
-----				
			B.T =	52.152790



4311A.1	4311A.1			
625		.500000 x	16.044945 =	8.022473
626		.030000 x	2.440059 =	.073202
504		.001786 x	745.148186 =	1.330835
527		.001786 x	2,702.127667 =	4.826000
616		.200000 x	10.884703 =	2.176941
615		.370000 x	10.884703 =	4.027340

-----  
 B.T = 20.456790

4311B	4311B			
321		80.000000 x	.396200 =	31.696000
626		.030000 x	2.440059 =	.073202
625		.500000 x	16.044945 =	8.022473
623		.370000 x	14.536107 =	5.378360
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
624		.200000 x	14.749984 =	2.949997

-----  
 B.T = 54.276865

4311B.1	4311B.1			
623		.370000 x	14.536107 =	5.378360
625		.500000 x	16.044945 =	8.022473
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
626		.030000 x	2.440059 =	.073202
624		.200000 x	14.749984 =	2.949997

-----  
 B.T = 22.580865

4312	4312			
509		.001622 x	531.782036 =	.862550
504		.001000 x	745.148186 =	.745148

-----  
 B.T = 1.607699

4411A	4411A			
321		80.000000 x	.396200 =	31.696000
616		.200000 x	10.884703 =	2.176941
615		.370000 x	10.884703 =	4.027340
626		.030000 x	2.440059 =	.073202
625		.500000 x	16.044945 =	8.022473
504		.001786 x	745.148186 =	1.330835
527		.001786 x	2,702.127667 =	4.826000

-----  
 B.T = 52.152790

4411A.1	4411A.1			
625		.500000 x	16.044945 =	8.022473
626		.030000 x	2.440059 =	.073202
527		.001786 x	2,702.127667 =	4.826000
616		.200000 x	10.884703 =	2.176941
615		.370000 x	10.884703 =	4.027340
504		.001786 x	745.148186 =	1.330835
-----				
			B.T =	20.456790
4411B	4411B			
321		80.000000 x	.396200 =	31.696000
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
625		.500000 x	16.044945 =	8.022473
623		.370000 x	14.536107 =	5.378360
624		.200000 x	14.749984 =	2.949997
626		.030000 x	2.440059 =	.073202
-----				
			B.T =	54.276865
4411B.1	4411B.1			
623		.370000 x	14.536107 =	5.378360
624		.200000 x	14.749984 =	2.949997
626		.030000 x	2.440059 =	.073202
625		.500000 x	16.044945 =	8.022473
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
-----				
			B.T =	22.580865
4412	4412			
509		.001622 x	531.782036 =	.862550
504		.001000 x	745.148186 =	.745148
-----				
			B.T =	1.607699
4511A	4511A			
321		90.000000 x	.396200 =	35.658000
616		.300000 x	10.884703 =	3.265411
615		.370000 x	10.884703 =	4.027340
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
626		.050000 x	2.440059 =	.122003
625		.450000 x	16.044945 =	7.220225
-----				
			B.T =	56.449814

4511A.1	4511A.1			
625		.450000 x	16.044945 =	7.220225
616		.300000 x	10.884703 =	3.265411
615		.370000 x	10.884703 =	4.027340
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
626		.050000 x	2.440059 =	.122003
		-----		
			B.T =	20.791814
4511B	4511B			
321		90.000000 x	.396200 =	35.658000
625		.450000 x	16.044945 =	7.220225
623		.370000 x	14.536107 =	5.378360
624		.300000 x	14.749984 =	4.424995
527		.001786 x	2,702.127667 =	4.826000
504		.001786 x	745.148186 =	1.330835
626		.050000 x	2.440059 =	.122003
		-----		
			B.T =	58.960418
4511B.1	4511B.1			
623		.370000 x	14.536107 =	5.378360
624		.300000 x	14.749984 =	4.424995
625		.450000 x	16.044945 =	7.220225
504		.001786 x	745.148186 =	1.330835
527		.001786 x	2,702.127667 =	4.826000
626		.050000 x	2.440059 =	.122003
		-----		
			B.T =	23.302418
4512	4512			
509		.001622 x	531.782036 =	.862550
504		.001000 x	745.148186 =	.745148
		-----		
			B.T =	1.607699
1110	1110			
503		.000455 x	1,650.447243 =	.750953
501		.000250 x	629.597875 =	.157399
		-----		
			T.E =	.908353
1121	1121			
112		.005000 x	17.312112 =	.086561
501		.000083 x	629.597875 =	.052257
503		.000714 x	1,650.447243 =	1.178419
		-----		
			T.E =	1.317237

1122	1122			
112		.005000 x	17.312112 =	.086561
509		.002000 x	531.782036 =	1.063564
507		.000385 x	712.117490 =	.274165
501		.000080 x	629.597875 =	.050368
505		.000316 x	1,188.061418 =	.375427
503		.000100 x	1,650.447243 =	.165045
		-----		
			T.E =	2.015130
1123.A	1123.A			
112		.005000 x	17.312112 =	.086561
503		.000500 x	1,650.447243 =	.825224
509		.001429 x	531.782036 =	.759917
507		.000769 x	712.117490 =	.547618
501		.000080 x	629.597875 =	.050368
		-----		
			T.E =	2.269687
1123.B	1123.B			
509		.000870 x	531.782036 =	.462650
		-----		
			T.E =	.462650
1131	1131			
213		1.000000 x	1.949500 =	1.949500
519		.000952 x	757.806274 =	.721432
112		.030000 x	17.312112 =	.519363
503		.000909 x	1,650.447243 =	1.500257
		-----		
			T.E =	4.690551
1132	1132			
213		1.000000 x	1.949500 =	1.949500
504		.001000 x	745.148186 =	.745148
503		.000909 x	1,650.447243 =	1.500257
112		.120000 x	17.312112 =	2.077453
519		.000952 x	757.806274 =	.721432
509		.002000 x	531.782036 =	1.063564
		-----		
			T.E =	8.057354
1133.A	1133.A			
213		1.000000 x	1.949500 =	1.949500
112		.120000 x	17.312112 =	2.077453
504		.001000 x	745.148186 =	.745148
519		.000952 x	757.806274 =	.721432
509		.001176 x	531.782036 =	.625376
503		.000909 x	1,650.447243 =	1.500257
		-----		
			T.E =	7.619165

1133.B	1133.B			
509		.000870 x	531.782036 =	.462650
<hr/>				
			T.E =	.462650
1140	1140			
112		.006000 x	17.312112 =	.103873
522		.000133 x	452.710492 =	.060210
501		.000050 x	629.597875 =	.031480
<hr/>				
			T.E =	.195563
1211	1211			
112		.200000 x	17.312112 =	3.462422
501		.001538 x	629.597875 =	.968322
507		.001538 x	712.117490 =	1.095237
<hr/>				
			T.E =	5.525981
1212	1212			
112		.200000 x	17.312112 =	3.462422
507		.001538 x	712.117490 =	1.095237
501		.001538 x	629.597875 =	.968322
509		.002298 x	531.782036 =	1.222035
<hr/>				
			T.E =	6.748016
1220	1220			
213		1.000000 x	1.949500 =	1.949500
116		.060000 x	20.419486 =	1.225169
519		.002222 x	757.806274 =	1.683846
111		.500000 x	15.741598 =	7.870799
112		.060000 x	17.312112 =	1.038727
<hr/>				
			T.E =	13.768040
1310	1310			
112		.070000 x	17.312112 =	1.211848
501		.000385 x	629.597875 =	.242395
<hr/>				
			T.E =	1.454243
1320	1320			
112		1.500000 x	17.312112 =	25.968168
<hr/>				
			T.E =	25.968168

1410	1410			
112		.005000 x	17.312112 =	.086561
501		.000083 x	629.597875 =	.052257
503		.000833 x	1,650.447243 =	1.374823
-----				
			T.E =	1.513640
1420	1420			
112		.006000 x	17.312112 =	.103873
509		.001826 x	531.782036 =	.971034
503		.000208 x	1,650.447243 =	.343293
501		.000050 x	629.597875 =	.031480
507		.000385 x	712.117490 =	.274165
505		.000316 x	1,188.061418 =	.375427
-----				
			T.E =	2.099272
1510	1510			
112		.007000 x	17.312112 =	.121185
509		.001429 x	531.782036 =	.759917
504		.000714 x	745.148186 =	.532036
503		.000385 x	1,650.447243 =	.635422
-----				
			T.E =	2.048559
1520	1520			
509		.000833 x	531.782036 =	.442974
-----				
			T.E =	.442974
1530	1530			
630		.150000 x	.542022 =	.081303
502		.000208 x	956.149897 =	.198879
501		.000250 x	629.597875 =	.157399
509		.000413 x	531.782036 =	.219626
522		.000556 x	452.710492 =	.251707
-----				
			T.E =	.908915
1610	1610			
111		.040000 x	15.741598 =	.629664
503		.000111 x	1,650.447243 =	.183200
507		.000118 x	712.117490 =	.084030
1122		.200000 x	2.015130 =	.403026
501		.000050 x	629.597875 =	.031480
-----				
			T.E =	1.331399

1620	1620			
112		.200000 x	17.312112 =	3.462422
1122		1.000000 x	2.015130 =	2.015130
501		.000714 x	629.597875 =	.449533
-----				
			T.E =	5.927085
2111	2111			
112		.010000 x	17.312112 =	.173121
503		.001053 x	1,650.447243 =	1.737921
507		.000667 x	712.117490 =	.474982
501		.000500 x	629.597875 =	.314799
509		.002124 x	531.782036 =	1.129505
-----				
			T.E =	3.830328
2112	2112			
213		1.000000 x	1.949500 =	1.949500
112		.250000 x	17.312112 =	4.328028
507		.000667 x	712.117490 =	.474982
519		.002041 x	757.806274 =	1.546683
509		.002124 x	531.782036 =	1.129505
503		.001613 x	1,650.447243 =	2.662171
116		.060000 x	20.419486 =	1.225169
-----				
			T.E =	13.316039
2151	2151			
213		.300000 x	1.949500 =	.584850
112		.100000 x	17.312112 =	1.731211
112		.200000 x	17.312112 =	3.462422
113		.030000 x	20.419486 =	.612585
112		.100000 x	17.312112 =	1.731211
507		.003333 x	712.117490 =	2.373488
519		.001200 x	757.806274 =	.909368
509		.002124 x	531.782036 =	1.129505
-----				
			T.E =	12.534640
2152	2152			
112		.100000 x	17.312112 =	1.731211
507		.006667 x	712.117490 =	4.747687
509		.003196 x	531.782036 =	1.699575
112		.200000 x	17.312112 =	3.462422
-----				
			T.E =	11.640896

2211	2211				
244		1.000000 x	2.590000 =	2.590000	
515		.000004 x	527.099387 =	.002108	
515		.000004 x	527.099387 =	.002108	
509		.000051 x	531.782036 =	.027121	
112		.002000 x	17.312112 =	.034624	
112		.003000 x	17.312112 =	.051936	
-----					
			T.E =	2.707898	
2212	2212				
244		.125000 x	2.590000 =	.323750	
112		.007000 x	17.312112 =	.121185	
515		.000008 x	527.099387 =	.004217	
509		.000051 x	531.782036 =	.027121	
-----					
			T.E =	.476272	
2213	2213				
236		3.000000 x	.612000 =	1.836000	
517		.016667 x	1,782.374679 =	29.706839	
515		.016667 x	527.099387 =	8.785165	
113		.300000 x	20.419486 =	6.125846	
111		.300000 x	15.741598 =	4.722479	
-----					
			T.E =	51.176329	
2214	2214				
111		.200000 x	15.741598 =	3.148320	
515		.016667 x	527.099387 =	8.785165	
113		.110000 x	20.419486 =	2.246143	
111		.170000 x	15.741598 =	2.676072	
113		.200000 x	20.419486 =	4.083897	
-----					
			T.E =	20.939597	
2251	2251				
111		.450000 x	15.741598 =	7.083719	
112		.450000 x	17.312112 =	7.790450	
509		.007516 x	531.782036 =	3.996874	
621		1.050000 x	15.301224 =	16.066285	
-----					
			T.E =	34.937328	
2252	2252				
111		1.250000 x	15.741598 =	19.676998	
621		1.050000 x	15.301224 =	16.066285	
509		.007516 x	531.782036 =	3.996874	
113		1.250000 x	20.419486 =	25.524358	
-----					
			T.E =	65.264514	



2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	15.301224 =	16.066285
652		.020000 x	134.296095 =	2.685922
509		.007891 x	531.782036 =	4.196292
651		.250000 x	92.897861 =	23.224465
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	124.296499
2254	2254			
111		.750000 x	15.741598 =	11.806199
652		.100000 x	134.296095 =	13.429610
113		1.450000 x	20.419486 =	29.608255
509		.002630 x	531.782036 =	1.398587
621		.350000 x	15.301224 =	5.355428
		-----		
			T.E =	61.598078
2311	2311			
243		1.020000 x	2.100000 =	2.142000
243		.080000 x	2.100000 =	.168000
		-----		
			T.E =	2.310000
2312	2312			
112		.080000 x	17.312112 =	1.384969
113		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	3.018528
2313	2313			
111		.400000 x	15.741598 =	6.296639
509		.003326 x	531.782036 =	1.768707
611		1.050000 x	22.038237 =	23.140149
112		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	38.130340
2350	2350			
112		.100000 x	17.312112 =	1.731211
652		.022000 x	134.296095 =	2.954514
113		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	9.790597
2411	2411			
327		.500000 x	.540000 =	.270000
113		.180000 x	20.419486 =	3.675507
		-----		
			T.E =	3.945507

2412	2412			
328		2.200000 x	1.840000 =	4.048000
111		.150000 x	15.741598 =	2.361240
329		2.000000 x	.730000 =	1.460000
2350		1.000000 x	9.790597 =	9.790597
113		.300000 x	20.419486 =	6.125846

-----  
 T.E = 23.785683

2511	2511			
221		200.000000 x	.099900 =	19.980000
623		.800000 x	14.536107 =	11.628886
625		.500000 x	16.044945 =	8.022473
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.016667 x	531.782036 =	8.863211
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.006012 x	531.782036 =	3.197074
630		.250000 x	.542022 =	.135506
112		.400000 x	17.312112 =	6.924845
113		.250000 x	20.419486 =	5.104872

-----  
 T.E = 69.496761

2512	2512			
221		250.000000 x	.099900 =	24.975000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
630		.250000 x	.542022 =	.135506
641		2.000000 x	7.526243 =	15.052486
625		.500000 x	16.044945 =	8.022473
509		.018182 x	531.782036 =	9.668861
623		.800000 x	14.536107 =	11.628886
112		.500000 x	17.312112 =	8.656056
113		.500000 x	20.419486 =	10.209743

-----  
 T.E = 97.185979

2521	2521			
221		50.000000 x	.099900 =	4.995000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
509		.006012 x	531.782036 =	3.197074
641		2.000000 x	7.526243 =	15.052486
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		.500000 x	20.419486 =	10.209743
112		.500000 x	17.312112 =	8.656056
221		250.000000 x	.099900 =	24.975000

T.E = 102.180979

2522	2522			
221		300.000000 x	.099900 =	29.970000
113		.800000 x	20.419486 =	16.335589
625		.500000 x	16.044945 =	8.022473
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		3.000000 x	7.526243 =	22.578729
630		.250000 x	.542022 =	.135506
623		.800000 x	14.536107 =	11.628886
112		.600000 x	17.312112 =	10.387267

T.E = 117.564279

2523	2523			
221		300.000000 x	.099900 =	29.970000
641		3.000000 x	7.526243 =	22.578729
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
509		.001444 x	531.782036 =	.767893
509		.003758 x	531.782036 =	1.998437
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.018182 x	531.782036 =	9.668861
509		.006012 x	531.782036 =	3.197074
623		.800000 x	14.536107 =	11.628886
113		1.050000 x	20.419486 =	21.440460
112		.750000 x	17.312112 =	12.984084

T.E = 125.265968

2524	2524			
221		300.000000 x	.099900 =	29.970000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		1.300000 x	7.526243 =	9.784116
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		.800000 x	20.419486 =	16.335589
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 115.156933

2531	2531			
222		300.000000 x	.116200 =	34.860000
112		1.300000 x	17.312112 =	22.505746
113		.900000 x	20.419486 =	18.377537
630		.250000 x	.542022 =	.135506
509		.018182 x	531.782036 =	9.668861
509		.003758 x	531.782036 =	1.998437
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.001444 x	531.782036 =	.767893
509		.006012 x	531.782036 =	3.197074
641		1.300000 x	7.526243 =	9.784116
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886

-----  
 T.E = 123.820093

2532	2532			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		4.000000 x	7.526243 =	30.104972
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
112		1.600000 x	17.312112 =	27.699379
623		.800000 x	14.536107 =	11.628886
113		.900000 x	20.419486 =	18.377537
509		.006012 x	531.782036 =	3.197074

-----  
 T.E = 149.334583

2533	2533			
222		300.000000 x	.116200 =	34.860000
112		1.800000 x	17.312112 =	31.161802
623		.800000 x	14.536107 =	11.628886
509		.018182 x	531.782036 =	9.668861
509		.003758 x	531.782036 =	1.998437
504		.001143 x	745.148186 =	.851704
514		.002857 x	707.686916 =	2.021862
509		.006012 x	531.782036 =	3.197074
509		.001444 x	531.782036 =	.767893
630		.250000 x	.542022 =	.135506
641		8.000000 x	7.526243 =	60.209944
625		.500000 x	16.044945 =	8.022473
113		1.200000 x	20.419486 =	24.503383

-----  
 T.E = 189.027823

2541	2541			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.018182 x	531.782036 =	9.668861
509		.001444 x	531.782036 =	.767893
509		.006012 x	531.782036 =	3.197074
641		4.500000 x	7.526243 =	33.868094
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		1.200000 x	20.419486 =	24.503383
112		1.600000 x	17.312112 =	27.699379
509		.003758 x	531.782036 =	1.998437

-----  
 T.E = 159.223550

2542	2542			
222		300.000000 x	.116200 =	34.860000
112		1.650000 x	17.312112 =	28.564985
623		.800000 x	14.536107 =	11.628886
509		.018182 x	531.782036 =	9.668861
509		.003758 x	531.782036 =	1.998437
504		.001143 x	745.148186 =	.851704
514		.002857 x	707.686916 =	2.021862
509		.006012 x	531.782036 =	3.197074
509		.001444 x	531.782036 =	.767893
630		.250000 x	.542022 =	.135506
642		4.500000 x	11.592771 =	52.167470
625		.500000 x	16.044945 =	8.022473
113		1.250000 x	20.419486 =	25.524358

-----  
 T.E = 179.409506

2543	2543			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
509		.006012 x	531.782036 =	3.197074
641		5.000000 x	7.526243 =	37.631215
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
112		1.550000 x	17.312112 =	26.833774
113		1.250000 x	20.419486 =	25.524358
113		.500000 x	20.419486 =	10.209743

-----  
 T.E = 173.351783

2544	2544			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.003758 x	531.782036 =	1.998437
509		.018182 x	531.782036 =	9.668861
509		.001444 x	531.782036 =	.767893
509		.006012 x	531.782036 =	3.197074
113		.700000 x	20.419486 =	14.293640
112		1.650000 x	17.312112 =	28.564985
625		.500000 x	16.044945 =	8.022473
642		5.000000 x	11.592771 =	57.963855
630		.250000 x	.542022 =	.135506
623		.800000 x	14.536107 =	11.628886
113		1.250000 x	20.419486 =	25.524358

-----  
 T.E = 199.499532

2545	2545			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		6.000000 x	7.526243 =	45.157458
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		1.900000 x	20.419486 =	38.797023
112		1.650000 x	17.312112 =	28.564985
509		.006012 x	531.782036 =	3.197074

-----  
 T.E = 185.672160

2546	2546			
222		300.000000 x	.116200 =	34.860000
112		1.850000 x	17.312112 =	32.027407
113		1.900000 x	20.419486 =	38.797023
509		.018182 x	531.782036 =	9.668861
509		.003758 x	531.782036 =	1.998437
504		.001143 x	745.148186 =	.851704
514		.002857 x	707.686916 =	2.021862
509		.006012 x	531.782036 =	3.197074
509		.001444 x	531.782036 =	.767893
630		.250000 x	.542022 =	.135506
641		6.000000 x	7.526243 =	45.157458
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886

-----  
 T.E = 189.134583

2547	2547			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.018182 x	531.782036 =	9.668861
509		.001444 x	531.782036 =	.767893
509		.006012 x	531.782036 =	3.197074
641		5.000000 x	7.526243 =	37.631215
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
112		1.550000 x	17.312112 =	26.833774
623		.800000 x	14.536107 =	11.628886
113		1.900000 x	20.419486 =	38.797023
509		.003758 x	531.782036 =	1.998437

-----  
 T.E = 176.414706

2548	2548			
222		300.000000 x	.116200 =	34.860000
112		1.950000 x	17.312112 =	33.758618
623		.800000 x	14.536107 =	11.628886
509		.018182 x	531.782036 =	9.668861
509		.003758 x	531.782036 =	1.998437
504		.001143 x	745.148186 =	.851704
514		.002857 x	707.686916 =	2.021862
509		.006012 x	531.782036 =	3.197074
509		.001444 x	531.782036 =	.767893
630		.250000 x	.542022 =	.135506
641		5.000000 x	7.526243 =	37.631215
625		.500000 x	16.044945 =	8.022473
113		2.400000 x	20.419486 =	49.006766

-----  
 T.E = 193.549294

2551	2551			
222		360.000000 x	.116200 =	41.832000
514		.002857 x	707.686916 =	2.021862
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		4.500000 x	7.526243 =	33.868094
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		1.050000 x	20.419486 =	21.440460
112		1.550000 x	17.312112 =	26.833774

-----  
 T.E = 162.267022

2561	2561			
222		450.000000 x	.116200 =	52.290000
111		1.250000 x	15.741598 =	19.676998
112		1.800000 x	17.312112 =	31.161802
623		.800000 x	14.536107 =	11.628886
514		.003704 x	707.686916 =	2.621272
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		4.500000 x	7.526243 =	33.868094
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
113		2.800000 x	20.419486 =	57.174561

-----  
 T.E = 233.063558

2562	2562			
222		450.000000 x	.116200 =	52.290000
111		1.950000 x	15.741598 =	30.696116
514		.003704 x	707.686916 =	2.621272
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
509		.003758 x	531.782036 =	1.998437
642		4.500000 x	11.592771 =	52.167470
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
113		2.800000 x	20.419486 =	57.174561
623		.800000 x	14.536107 =	11.628886
112		1.800000 x	17.312112 =	31.161802

-----  
 T.E = 262.382053



2563	2563			
222		450.000000 x	.116200 =	52.290000
111		1.950000 x	15.741598 =	30.696116
514		.003704 x	707.686916 =	2.621272
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		5.000000 x	7.526243 =	37.631215
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		.900000 x	20.419486 =	18.377537
113		3.900000 x	20.419486 =	79.635995
112		1.800000 x	17.312112 =	31.161802

T.E = 288.684771

2564	2564			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	707.686916 =	2.621272
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
642		5.000000 x	11.592771 =	57.963855
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		.900000 x	20.419486 =	18.377537
112		1.800000 x	17.312112 =	31.161802
113		3.900000 x	20.419486 =	79.635995
111		1.950000 x	15.741598 =	30.696116

T.E = 309.017411

2565	2565			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	707.686916 =	2.621272
504		.001143 x	745.148186 =	.851704
509		.006012 x	531.782036 =	3.197074
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
641		6.000000 x	7.526243 =	45.157458
630		.250000 x	.542022 =	.135506
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		4.700000 x	20.419486 =	95.971584
112		2.350000 x	17.312112 =	40.683463
111		2.350000 x	15.741598 =	36.992755

T.E = 309.987366

2566	2566			
222		450.000000 x	.116200 =	52.290000
630		.250000 x	.542022 =	.135506
514		.003704 x	707.686916 =	2.621272
504		.001143 x	745.148186 =	.851704
509		.003758 x	531.782036 =	1.998437
509		.001444 x	531.782036 =	.767893
509		.018182 x	531.782036 =	9.668861
509		.006012 x	531.782036 =	3.197074
642		6.000000 x	11.592771 =	69.556626
625		.500000 x	16.044945 =	8.022473
623		.800000 x	14.536107 =	11.628886
113		4.700000 x	20.419486 =	95.971584
112		2.350000 x	17.312112 =	40.683463
111		2.350000 x	15.741598 =	36.992755
-----				
			T.E =	334.386534
2611	2611			
233		1.050000 x	.583300 =	.612465
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.327147
2612	2612			
238		1.050000 x	.583300 =	.612465
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.327147
2620	2620			
239		1.010000 x	7.950000 =	8.029500
113		.080000 x	20.419486 =	1.633559
113		.080000 x	20.419486 =	1.633559
239		.303000 x	7.950000 =	2.408850
-----				
			T.E =	13.705468
2651	2651			
235		1.050000 x	.643000 =	.675150
113		.100000 x	20.419486 =	2.041949
-----				
			T.E =	2.717099
2652	2652			
235		1.050000 x	.643000 =	.675150
661		.050000 x	24.137810 =	1.206891
113		.120000 x	20.419486 =	2.450338
-----				
			T.E =	4.332379

2653	2653			
241		1.050000 x	7.050000 =	7.402500
661		.120000 x	24.137810 =	2.896537
113		.800000 x	20.419486 =	16.335589
-----				
			T.E =	26.634626
2671	2671			
237		1.000000 x	1.110000 =	1.110000
113		.015000 x	20.419486 =	.306292
-----				
			T.E =	1.416292
2672	2672			
235		1.050000 x	.643000 =	.675150
661		.050000 x	24.137810 =	1.206891
113		.120000 x	20.419486 =	2.450338
-----				
			T.E =	4.332379
2711	2711			
2551		1.000000 x	162.267022 =	162.267022
-----				
			T.E =	162.267022
2712	2712			
2611		1.000000 x	1.327147 =	1.327147
-----				
			T.E =	1.327147
2713	2713			
237		1.000000 x	1.110000 =	1.110000
113		.070000 x	20.419486 =	1.429364
-----				
			T.E =	2.539364
2714	2714			
112		1.900000 x	17.312112 =	32.893013
517		.015385 x	1,782.374679 =	27.421834
516		.015385 x	866.955376 =	13.338108
-----				
			T.E =	73.652956
2731	2731			
2730A		.149925 x	3,077.937805 =	461.459825
2730B		.000667 x	41,797.124025 =	27.878682
2730Γ		1.000000 x	60.429763 =	60.429763
-----				
			T.E =	549.768270

2732	2732			
2730Α		.179910 x	3,077.937805 =	553.751790
2730Β		.000667 x	41,797.124025 =	27.878682
2730Γ		1.000000 x	60.429763 =	60.429763
		-----		
			T.E =	642.060235
2733	2733			
233		1.050000 x	.583300 =	.612465
113		.035000 x	20.419486 =	.714682
		-----		
			T.E =	1.327147
2734	2734			
238		1.050000 x	.583300 =	.612465
113		.035000 x	20.419486 =	.714682
		-----		
			T.E =	1.327147
2811	2811			
112		.170000 x	17.312112 =	2.943059
509		.002217 x	531.782036 =	1.178961
507		.001538 x	712.117490 =	1.095237
501		.000500 x	629.597875 =	.314799
		-----		
			T.E =	5.532055
2815	2815			
111		.250000 x	15.741598 =	3.935400
509		.003006 x	531.782036 =	1.598537
112		.350000 x	17.312112 =	6.059239
623		.400000 x	14.536107 =	5.814443
509		.005261 x	531.782036 =	2.797705
625		.700000 x	16.044945 =	11.231462
		-----		
			T.E =	31.436785
2861	2861			
221		6.000000 x	.099900 =	.599400
281		1.000000 x	21.300000 =	21.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	29.918697
2862	2862			
221		8.000000 x	.099900 =	.799200
282		1.000000 x	30.000000 =	30.000000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	38.818497

2863	2863			
221		8.000000 x	.099900 =	.799200
283		1.000000 x	36.300000 =	36.300000
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
		-----		
			T.E =	58.561956
2864	2864			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
284		1.000000 x	75.400000 =	75.400000
		-----		
			T.E =	99.248236
2881	2881			
221		6.000000 x	.099900 =	.599400
261		1.000000 x	15.100000 =	15.100000
111		.250000 x	15.741598 =	3.935400
113		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	23.718697
2882	2882			
221		8.000000 x	.099900 =	.799200
262		1.000000 x	26.300000 =	26.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	35.118497
2883	2883			
221		10.000000 x	.099900 =	.999000
263		1.000000 x	32.400000 =	32.400000
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
		-----		
			T.E =	54.861756
2884	2884			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
264		1.000000 x	64.100000 =	64.100000
		-----		
			T.E =	87.948236

2885	2885			
221		20.000000 x	.099900 =	1.998000
113		.750000 x	20.419486 =	15.314615
265		1.000000 x	115.100000 =	115.100000
111		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	148.154213
2888	2888			
221		26.000000 x	.099900 =	2.597400
111		1.400000 x	15.741598 =	22.038237
271		1.000000 x	206.300000 =	206.300000
113		1.100000 x	20.419486 =	22.461435
-----				
			T.E =	253.397072
2911	2911			
351		1.050000 x	745.000000 =	782.250000
113		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	884.347430
2912	2912			
352		1.050000 x	1,010.000000 =	1,060.500000
113		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	1,162.597430
2921	2921			
301		1.000000 x	4.060000 =	4.060000
113		.250000 x	20.419486 =	5.104872
652		.002000 x	134.296095 =	.268592
2522		.005000 x	117.564279 =	.587821
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	13.956685
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.015000 x	134.296095 =	2.014441
113		.600000 x	20.419486 =	12.251692
111		.350000 x	15.741598 =	5.509559
-----				
			T.E =	26.609692
2951	2951			
512A		.150000 x	108.931509 =	16.339726
-----				
			T.E =	16.339726

2952	2952			
512B		.150000 x	155.064215 =	23.259632
-----				
			T.E =	23.259632
2953	2953			
513A		.150000 x	210.368861 =	31.555329
-----				
			T.E =	31.555329
2954	2954			
513B		.150000 x	271.495654 =	40.724348
-----				
			T.E =	40.724348
3111A	3111A			
112		.020000 x	17.312112 =	.346242
522		.000263 x	452.710492 =	.119063
509		.000193 x	531.782036 =	.102634
509		.000072 x	531.782036 =	.038288
630		.020000 x	.542022 =	.010840
501		.000182 x	629.597875 =	.114587
614		.135000 x	10.884703 =	1.469435
-----				
			T.E =	2.201089
3111B	3111B			
112		.020000 x	17.312112 =	.346242
630		.020000 x	.542022 =	.010840
509		.000072 x	531.782036 =	.038288
501		.000182 x	629.597875 =	.114587
509		.000193 x	531.782036 =	.102634
522		.000263 x	452.710492 =	.119063
622		.135000 x	14.749984 =	1.991248
-----				
			T.E =	2.722902
3112	3112			
509		.000094 x	531.782036 =	.049988
-----				
			T.E =	.049988
3121A	3121A			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	629.597875 =	1.144609
614		1.350000 x	10.884703 =	14.694349
509		.001929 x	531.782036 =	1.025808
509		.000722 x	531.782036 =	.383947
522		.002632 x	452.710492 =	1.191534
630		.200000 x	.542022 =	.108404
-----				
			T.E =	22.011073

3121B	3121B			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	629.597875 =	1.144609
509		.000722 x	531.782036 =	.383947
509		.001929 x	531.782036 =	1.025808
522		.002632 x	452.710492 =	1.191534
630		.200000 x	.542022 =	.108404
622		1.350000 x	14.749984 =	19.912478
-----				
			T.E =	27.229202
3122	3122			
509		.000940 x	531.782036 =	.499875
-----				
			T.E =	.499875
3211A	3211A			
112		.025000 x	17.312112 =	.432803
522		.000263 x	452.710492 =	.119063
501		.000182 x	629.597875 =	.114587
614		.135000 x	10.884703 =	1.469435
509		.000072 x	531.782036 =	.038288
509		.000193 x	531.782036 =	.102634
630		.020000 x	.542022 =	.010840
-----				
			T.E =	2.287650
3211B	3211B			
112		.025000 x	17.312112 =	.432803
622		.135000 x	14.749984 =	1.991248
509		.000072 x	531.782036 =	.038288
509		.000193 x	531.782036 =	.102634
522		.000263 x	452.710492 =	.119063
501		.000182 x	629.597875 =	.114587
630		.020000 x	.542022 =	.010840
-----				
			T.E =	2.809463
3212	3212			
509		.000141 x	531.782036 =	.074981
-----				
			T.E =	.074981



3221	3221			
622		.202500 x	14.749984 =	2.986872
509		.000286 x	531.782036 =	.152090
501		.000250 x	629.597875 =	.157399
509		.000250 x	531.782036 =	.132946
509		.000469 x	531.782036 =	.249406
509		.000250 x	531.782036 =	.132946
522		.000500 x	452.710492 =	.226355
630		.100000 x	.542022 =	.054202
		-----		
			T.E =	4.092215
3222	3222			
221		1.000000 x	.099900 =	.099900
		-----		
			T.E =	.099900
3223	3223			
509		.000141 x	531.782036 =	.074981
		-----		
			T.E =	.074981
3231	3231			
112		.025000 x	17.312112 =	.432803
509		.000054 x	531.782036 =	.028716
630		.015000 x	.542022 =	.008130
501		.000213 x	629.597875 =	.134104
522		.000286 x	452.710492 =	.129475
		-----		
			T.E =	.733229
3232A	3232A			
630		.200000 x	.542022 =	.108404
614		1.350000 x	10.884703 =	14.694349
509		.001929 x	531.782036 =	1.025808
		-----		
			T.E =	15.828561
3232B	3232B			
622		1.350000 x	14.749984 =	19.912478
509		.001929 x	531.782036 =	1.025808
630		.200000 x	.542022 =	.108404
		-----		
			T.E =	21.046690
3233	3233			
509		.000940 x	531.782036 =	.499875
		-----		
			T.E =	.499875

3241A	3241A			
112		.025000 x	17.312112 =	.432803
614		.135000 x	10.884703 =	1.469435
501		.000213 x	629.597875 =	.134104
509		.000193 x	531.782036 =	.102634
522		.000286 x	452.710492 =	.129475
509		.000072 x	531.782036 =	.038288
630		.020000 x	.542022 =	.010840
-----				
			T.E =	2.317580
3241B	3241B			
112		.025000 x	17.312112 =	.432803
501		.000213 x	629.597875 =	.134104
509		.000072 x	531.782036 =	.038288
509		.000193 x	531.782036 =	.102634
522		.000286 x	452.710492 =	.129475
630		.020000 x	.542022 =	.010840
622		.135000 x	14.749984 =	1.991248
-----				
			T.E =	2.839393
3242	3242			
509		.000094 x	531.782036 =	.049988
-----				
			T.E =	.049988
3311A	3311A			
112		.025000 x	17.312112 =	.432803
630		.020000 x	.542022 =	.010840
509		.000193 x	531.782036 =	.102634
509		.000072 x	531.782036 =	.038288
501		.000213 x	629.597875 =	.134104
614		.135000 x	10.884703 =	1.469435
522		.000286 x	452.710492 =	.129475
-----				
			T.E =	2.317580
3311B	3311B			
112		.025000 x	17.312112 =	.432803
522		.000286 x	452.710492 =	.129475
501		.000213 x	629.597875 =	.134104
509		.000072 x	531.782036 =	.038288
509		.000193 x	531.782036 =	.102634
630		.020000 x	.542022 =	.010840
622		.135000 x	14.749984 =	1.991248
-----				
			T.E =	2.839393

3312	3312			
509		.000094 x	531.782036 =	.049988
				-----
			T.E =	.049988
3321A	3321A			
112		.030000 x	17.312112 =	.519363
509		.000193 x	531.782036 =	.102634
509		.000072 x	531.782036 =	.038288
501		.000213 x	629.597875 =	.134104
614		.135000 x	10.884703 =	1.469435
630		.020000 x	.542022 =	.010840
522		.000286 x	452.710492 =	.129475
				-----
			T.E =	2.404140
3321B	3321B			
112		.030000 x	17.312112 =	.519363
509		.000193 x	531.782036 =	.102634
501		.000213 x	629.597875 =	.134104
509		.000072 x	531.782036 =	.038288
622		.135000 x	14.749984 =	1.991248
522		.000286 x	452.710492 =	.129475
630		.020000 x	.542022 =	.010840
				-----
			T.E =	2.925953
3322	3322			
509		.000094 x	531.782036 =	.049988
				-----
			T.E =	.049988
3401	3401			
111		1.300000 x	15.741598 =	20.464077
509		.000361 x	531.782036 =	.191973
521		.014286 x	330.952897 =	4.727993
630		.100000 x	.542022 =	.054202
112		.900000 x	17.312112 =	15.580901
				-----
			T.E =	41.019147
3402A	3402A			
509		.001929 x	531.782036 =	1.025808
614		1.350000 x	10.884703 =	14.694349
				-----
			T.E =	15.720157
3402B	3402B			
622		1.350000 x	14.749984 =	19.912478
509		.001929 x	531.782036 =	1.025808
				-----
			T.E =	20.938286

3403	3403			
509		.000940 x	531.782036 =	.499875
-----				
			T.E =	.499875
4110	4110			
112		.008000 x	17.312112 =	.138497
526		.000100 x	547.482426 =	.054748
523		.000143 x	354.227535 =	.050655
671		1.200000 x	.729645 =	.875574
-----				
			T.E =	1.119474
4110.1	4110.1			
112		.008000 x	17.312112 =	.138497
671.1		1.200000 x	.511735 =	.614082
526		.000100 x	547.482426 =	.054748
523		.000143 x	354.227535 =	.050655
-----				
			T.E =	.857982
4120	4120			
321		.500000 x	.396200 =	.198100
525		.000067 x	246.662563 =	.016526
526		.000100 x	547.482426 =	.054748
523		.000143 x	354.227535 =	.050655
112		.006000 x	17.312112 =	.103873
-----				
			T.E =	.423902
4120.1	4120.1			
112		.006000 x	17.312112 =	.103873
526		.000100 x	547.482426 =	.054748
523		.000143 x	354.227535 =	.050655
525		.000067 x	246.662563 =	.016526
-----				
			T.E =	.225802
4131A	4131A			
321		1.000000 x	.396200 =	.396200
112		.008000 x	17.312112 =	.138497
616		.015000 x	10.884703 =	.163271
525		.000067 x	246.662563 =	.016526
526		.000143 x	547.482426 =	.078290
523		.000143 x	354.227535 =	.050655
504		.000143 x	745.148186 =	.106556
509		.000014 x	531.782036 =	.007445
509		.000028 x	531.782036 =	.014890
509		.000143 x	531.782036 =	.076045
522		.000143 x	452.710492 =	.064738
-----				
			T.E =	1.113112

4131A.1	4131A.1			
112		.008000 x	17.312112 =	.138497
522		.000143 x	452.710492 =	.064738
509		.000028 x	531.782036 =	.014890
509		.000014 x	531.782036 =	.007445
616		.015000 x	10.884703 =	.163271
525		.000067 x	246.662563 =	.016526
526		.000143 x	547.482426 =	.078290
523		.000143 x	354.227535 =	.050655
504		.000143 x	745.148186 =	.106556
509		.000143 x	531.782036 =	.076045

T.E = .716912

4131B	4131B			
321		1.000000 x	.396200 =	.396200
522		.000143 x	452.710492 =	.064738
509		.000028 x	531.782036 =	.014890
526		.000143 x	547.482426 =	.078290
525		.000067 x	246.662563 =	.016526
523		.000143 x	354.227535 =	.050655
504		.000143 x	745.148186 =	.106556
509		.000143 x	531.782036 =	.076045
509		.000014 x	531.782036 =	.007445
624		.015000 x	14.749984 =	.221250
112		.008000 x	17.312112 =	.138497

T.E = 1.171091

4131B.1	4131B.1			
112		.008000 x	17.312112 =	.138497
624		.015000 x	14.749984 =	.221250
525		.000067 x	246.662563 =	.016526
526		.000143 x	547.482426 =	.078290
523		.000143 x	354.227535 =	.050655
504		.000143 x	745.148186 =	.106556
509		.000143 x	531.782036 =	.076045
509		.000028 x	531.782036 =	.014890
509		.000014 x	531.782036 =	.007445
522		.000143 x	452.710492 =	.064738

T.E = .774891

4132	4132			
509		.000009 x	531.782036 =	.004786

T.E = .004786

4141A	4141A			
112		.013000 x	17.312112 =	.225057
671		1.200000 x	.729645 =	.875574
509		.000038 x	531.782036 =	.020208
616		.012000 x	10.884703 =	.130616
615		.015000 x	10.884703 =	.163271
526		.000244 x	547.482426 =	.133586
523		.000143 x	354.227535 =	.050655
504		.000244 x	745.148186 =	.181816
509		.000244 x	531.782036 =	.129755
509		.000024 x	531.782036 =	.012763
672		1.500000 x	.482268 =	.723402
522		.000244 x	452.710492 =	.110461

-----  
 T.E = 2.757164

4141A.1	4141A.1			
112		.013000 x	17.312112 =	.225057
509		.000024 x	531.782036 =	.012763
616		.012000 x	10.884703 =	.130616
615		.015000 x	10.884703 =	.163271
526		.000244 x	547.482426 =	.133586
523		.000143 x	354.227535 =	.050655
504		.000244 x	745.148186 =	.181816
509		.000244 x	531.782036 =	.129755
509		.000038 x	531.782036 =	.020208
672.1		1.500000 x	.109840 =	.164760
671.1		1.200000 x	.511735 =	.614082
522		.000244 x	452.710492 =	.110461

-----  
 T.E = 1.937030

4141B	4141B			
112		.013000 x	17.312112 =	.225057
623		.015000 x	14.536107 =	.218042
526		.000244 x	547.482426 =	.133586
523		.000143 x	354.227535 =	.050655
504		.000244 x	745.148186 =	.181816
509		.000244 x	531.782036 =	.129755
509		.000024 x	531.782036 =	.012763
509		.000038 x	531.782036 =	.020208
522		.000244 x	452.710492 =	.110461
672		1.500000 x	.482268 =	.723402
671		1.200000 x	.729645 =	.875574
624		.012000 x	14.749984 =	.177000

-----  
 T.E = 2.858318

4141B.1	4141B.1			
112		.013000 x	17.312112 =	.225057
671.1		1.200000 x	.511735 =	.614082
522		.000244 x	452.710492 =	.110461
672.1		1.500000 x	.109840 =	.164760
526		.000244 x	547.482426 =	.133586
523		.000143 x	354.227535 =	.050655
504		.000244 x	745.148186 =	.181816
509		.000244 x	531.782036 =	.129755
509		.000024 x	531.782036 =	.012763
509		.000038 x	531.782036 =	.020208
624		.012000 x	14.749984 =	.177000
623		.015000 x	14.536107 =	.218042
			-----	
			T.E =	2.038184
4142	4142			
509		.000017 x	531.782036 =	.009040
			-----	
			T.E =	.009040
4211A	4211A			
672		25.000000 x	.482268 =	12.056700
522		.003846 x	452.710492 =	1.741125
615		.700000 x	10.884703 =	7.619292
501		.007024 x	629.597875 =	4.422295
616		.300000 x	10.884703 =	3.265411
526		.002857 x	547.482426 =	1.564157
509		.001429 x	531.782036 =	.759917
			-----	
			T.E =	31.428897
4211A.1	4211A.1			
672.1		25.000000 x	.109840 =	2.746000
509		.001429 x	531.782036 =	.759917
522		.003846 x	452.710492 =	1.741125
615		.700000 x	10.884703 =	7.619292
501		.007024 x	629.597875 =	4.422295
616		.300000 x	10.884703 =	3.265411
526		.002857 x	547.482426 =	1.564157
			-----	
			T.E =	22.118197
4211B	4211B			
623		.700000 x	14.536107 =	10.175275
624		.300000 x	14.749984 =	4.424995
501		.007024 x	629.597875 =	4.422295
526		.002857 x	547.482426 =	1.564157
509		.001429 x	531.782036 =	.759917
522		.003846 x	452.710492 =	1.741125
672		25.000000 x	.482268 =	12.056700
			-----	
			T.E =	35.144464

4211B.1	4211B.1			
623		.700000 x	14.536107 =	10.175275
624		.300000 x	14.749984 =	4.424995
522		.003846 x	452.710492 =	1.741125
509		.001429 x	531.782036 =	.759917
672.1		25.000000 x	.109840 =	2.746000
501		.007024 x	629.597875 =	4.422295
526		.002857 x	547.482426 =	1.564157
-----				
			T.E =	25.833764
4212	4212			
509		.000614 x	531.782036 =	.326514
-----				
			T.E =	.326514
4221A	4221A			
672		37.000000 x	.482268 =	17.843916
522		.004348 x	452.710492 =	1.968385
509		.001429 x	531.782036 =	.759917
526		.004000 x	547.482426 =	2.189930
615		.600000 x	10.884703 =	6.530822
616		.400000 x	10.884703 =	4.353881
501		.008226 x	629.597875 =	5.179072
-----				
			T.E =	38.825923
4221A.1	4221A.1			
672.1		37.000000 x	.109840 =	4.064080
522		.004348 x	452.710492 =	1.968385
615		.600000 x	10.884703 =	6.530822
501		.008226 x	629.597875 =	5.179072
616		.400000 x	10.884703 =	4.353881
526		.004000 x	547.482426 =	2.189930
509		.001429 x	531.782036 =	.759917
-----				
			T.E =	25.046087
4221B	4221B			
623		.600000 x	14.536107 =	8.721664
501		.008226 x	629.597875 =	5.179072
526		.004000 x	547.482426 =	2.189930
509		.001429 x	531.782036 =	.759917
624		.400000 x	14.749984 =	5.899994
522		.004348 x	452.710492 =	1.968385
672		37.000000 x	.482268 =	17.843916
-----				
			T.E =	42.562877



4221B.1	4221B.1			
623		.600000 x	14.536107 =	8.721664
501		.008226 x	629.597875 =	5.179072
526		.004000 x	547.482426 =	2.189930
509		.001429 x	531.782036 =	.759917
522		.004348 x	452.710492 =	1.968385
672.1		37.000000 x	.109840 =	4.064080
624		.400000 x	14.749984 =	5.899994
-----				
			T.E =	28.783041
4222	4222			
509		.000614 x	531.782036 =	.326514
-----				
			T.E =	.326514
4231A	4231A			
112		.005000 x	17.312112 =	.086561
112		.030000 x	17.312112 =	.519363
616		.006000 x	10.884703 =	.065308
615		.025000 x	10.884703 =	.272118
526		.000222 x	547.482426 =	.121541
523		.000143 x	354.227535 =	.050655
509		.000357 x	531.782036 =	.189846
509		.000036 x	531.782036 =	.019144
509		.000044 x	531.782036 =	.023398
522		.000357 x	452.710492 =	.161618
672		2.500000 x	.482268 =	1.205670
-----				
			T.E =	2.715222
4231A.1	4231A.1			
112		.005000 x	17.312112 =	.086561
509		.000044 x	531.782036 =	.023398
616		.006000 x	10.884703 =	.065308
615		.025000 x	10.884703 =	.272118
526		.000222 x	547.482426 =	.121541
523		.000143 x	354.227535 =	.050655
509		.000036 x	531.782036 =	.019144
509		.000357 x	531.782036 =	.189846
112		.030000 x	17.312112 =	.519363
522		.000357 x	452.710492 =	.161618
672.1		2.500000 x	.109840 =	.274600
-----				
			T.E =	1.784152

4231B	4231B			
112		.005000 x	17.312112 =	.086561
623		.025000 x	14.536107 =	.363403
624		.006000 x	14.749984 =	.088500
526		.000222 x	547.482426 =	.121541
523		.000143 x	354.227535 =	.050655
509		.000357 x	531.782036 =	.189846
509		.000044 x	531.782036 =	.023398
509		.000036 x	531.782036 =	.019144
522		.000357 x	452.710492 =	.161618
672		2.500000 x	.482268 =	1.205670
112		.030000 x	17.312112 =	.519363

-----  
 T.E = 2.829699

4231B.1	4231B.1			
112		.005000 x	17.312112 =	.086561
509		.000357 x	531.782036 =	.189846
526		.000222 x	547.482426 =	.121541
523		.000143 x	354.227535 =	.050655
509		.000036 x	531.782036 =	.019144
522		.000357 x	452.710492 =	.161618
623		.025000 x	14.536107 =	.363403
672.1		2.500000 x	.109840 =	.274600
509		.000044 x	531.782036 =	.023398
624		.006000 x	14.749984 =	.088500
112		.030000 x	17.312112 =	.519363

-----  
 T.E = 1.898629

4232	4232			
509		.000024 x	531.782036 =	.012763

-----  
 T.E = .012763

4321A	4321A			
521		.000128 x	330.952897 =	.042362
523		.000143 x	354.227535 =	.050655
4312		.071000 x	1.607699 =	.114147
4311A		.071000 x	52.152790 =	3.702848
528		.000128 x	853.792480 =	.109285
509		.000101 x	531.782036 =	.053710
522		.000128 x	452.710492 =	.057947

-----  
 T.E = 4.130954

4321A.1	4321A.1			
521		.000128 x	330.952897 =	.042362
4312		.071000 x	1.607699 =	.114147
4311A.1		.071000 x	20.456790 =	1.452432
528		.000128 x	853.792480 =	.109285
522		.000128 x	452.710492 =	.057947
523		.000143 x	354.227535 =	.050655
509		.000101 x	531.782036 =	.053710
-----				
			T.E =	1.880538
4321B	4321B			
521		.000128 x	330.952897 =	.042362
522		.000128 x	452.710492 =	.057947
4312		.071000 x	1.607699 =	.114147
4311B		.071000 x	54.276865 =	3.853657
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
509		.000101 x	531.782036 =	.053710
-----				
			T.E =	4.281763
4321B.1	4321B.1			
521		.000128 x	330.952897 =	.042362
4312		.071000 x	1.607699 =	.114147
4311B.1		.071000 x	22.580865 =	1.603241
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
509		.000101 x	531.782036 =	.053710
522		.000128 x	452.710492 =	.057947
-----				
			T.E =	2.031347
4322	4322			
509		.000049 x	531.782036 =	.026057
-----				
			T.E =	.026057
4421A	4421A			
521		.000128 x	330.952897 =	.042362
528		.000128 x	853.792480 =	.109285
4411A		.071000 x	52.152790 =	3.702848
4312		.071000 x	1.607699 =	.114147
523		.000143 x	354.227535 =	.050655
509		.000101 x	531.782036 =	.053710
522		.000128 x	452.710492 =	.057947
-----				
			T.E =	4.130954

4421A.1	4421A.1			
521		.000128 x	330.952897 =	.042362
509		.000101 x	531.782036 =	.053710
522		.000128 x	452.710492 =	.057947
4412		.071000 x	1.607699 =	.114147
4411A.1		.071000 x	20.456790 =	1.452432
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
-----				
			T.E =	1.880538
4421B	4421B			
521		.000128 x	330.952897 =	.042362
522		.000128 x	452.710492 =	.057947
509		.000101 x	531.782036 =	.053710
523		.000143 x	354.227535 =	.050655
4411B		.071000 x	54.276865 =	3.853657
4412		.071000 x	1.607699 =	.114147
528		.000128 x	853.792480 =	.109285
-----				
			T.E =	4.281763
4421B.1	4421B.1			
521		.000128 x	330.952897 =	.042362
522		.000128 x	452.710492 =	.057947
509		.000101 x	531.782036 =	.053710
4412		.071000 x	1.607699 =	.114147
4411B.1		.071000 x	22.580865 =	1.603241
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
-----				
			T.E =	2.031347
4422	4422			
509		.000049 x	531.782036 =	.026057
-----				
			T.E =	.026057
4521A	4521A			
521		.000128 x	330.952897 =	.042362
4511A		.071000 x	56.449814 =	4.007937
4512		.071000 x	1.607699 =	.114147
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
509		.000101 x	531.782036 =	.053710
522		.000128 x	452.710492 =	.057947
-----				
			T.E =	4.436042

4521A.1	4521A.1			
521		.000128 x	330.952897 =	.042362
4512		.071000 x	1.607699 =	.114147
4511A.1		.071000 x	20.791814 =	1.476219
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
509		.000101 x	531.782036 =	.053710
522		.000128 x	452.710492 =	.057947
-----				
			T.E =	1.904324
4521B	4521B			
521		.000128 x	330.952897 =	.042362
4512		.071000 x	1.607699 =	.114147
4511B		.071000 x	58.960418 =	4.186190
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
509		.000101 x	531.782036 =	.053710
522		.000128 x	452.710492 =	.057947
-----				
			T.E =	4.614295
4521B.1	4521B.1			
521		.000128 x	330.952897 =	.042362
522		.000128 x	452.710492 =	.057947
509		.000101 x	531.782036 =	.053710
4512		.071000 x	1.607699 =	.114147
4511B.1		.071000 x	23.302418 =	1.654472
528		.000128 x	853.792480 =	.109285
523		.000143 x	354.227535 =	.050655
-----				
			T.E =	2.082577
4522	4522			
509		.000049 x	531.782036 =	.026057
-----				
			T.E =	.026057
4611.1	4611.1			
326		45.000000 x	1.310000 =	58.950000
617		.013000 x	5.524094 =	.071813
4120.1		1.000000 x	.225802 =	.225802
529		.002857 x	713.446944 =	2.038318
525		.000286 x	246.662563 =	.070545
509		.000046 x	531.782036 =	.024462
623		.033000 x	14.536107 =	.479692
522		.000667 x	452.710492 =	.301958
113		.100000 x	20.419486 =	2.041949
-----				
			T.E =	64.204539

4611A	4611A			
321		3.000000 x	.396200 =	1.188600
529		.002857 x	713.446944 =	2.038318
525		.000286 x	246.662563 =	.070545
509		.000046 x	531.782036 =	.024462
522		.000667 x	452.710492 =	.301958
617		.013000 x	5.524094 =	.071813
113		.100000 x	20.419486 =	2.041949
326		45.000000 x	1.310000 =	58.950000
623		.033000 x	14.536107 =	.479692
4120		1.000000 x	.423902 =	.423902

-----  
 T.E = 65.591239

4612	4612			
509		.000040 x	531.782036 =	.021271

-----  
 T.E = .021271

4710A	4710A			
111		1.900000 x	15.741598 =	29.909036
112		1.200000 x	17.312112 =	20.774534
509		.005305 x	531.782036 =	2.821104
613		1.000000 x	6.237787 =	6.237787
509		.000361 x	531.782036 =	.191973
630		.200000 x	.542022 =	.108404
112		2.400000 x	17.312112 =	41.549069

-----  
 T.E = 101.591908

4710A.1	4710A.1			
111		1.900000 x	15.741598 =	29.909036
614		1.000000 x	10.884703 =	10.884703
509		.000361 x	531.782036 =	.191973
509		.005305 x	531.782036 =	2.821104
630		.200000 x	.542022 =	.108404
112		1.200000 x	17.312112 =	20.774534
112		2.400000 x	17.312112 =	41.549069

-----  
 T.E = 106.238824

4710B	4710B			
111		1.900000 x	15.741598 =	29.909036
509		.005305 x	531.782036 =	2.821104
509		.000361 x	531.782036 =	.191973
112		2.400000 x	17.312112 =	41.549069
630		.200000 x	.542022 =	.108404
622		1.000000 x	14.749984 =	14.749984
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 110.104105

4720A	4720A			
111		1.900000 x	15.741598 =	29.909036
112		2.000000 x	17.312112 =	34.624224
111		1.000000 x	15.741598 =	15.741598
4522		140.000000 x	.026057 =	3.647980
4512		1.000000 x	1.607699 =	1.607699
4511B		1.000000 x	58.960418 =	58.960418
671		20.000000 x	.729645 =	14.592900
112		2.400000 x	17.312112 =	41.549069
-----				
			T.E =	200.632924
4720A.1	4720A.1			
111		1.900000 x	15.741598 =	29.909036
112		2.400000 x	17.312112 =	41.549069
671.1		20.000000 x	.511735 =	10.234700
112		2.000000 x	17.312112 =	34.624224
4511B.1		1.000000 x	23.302418 =	23.302418
4522		140.000000 x	.026057 =	3.647980
4512		1.000000 x	1.607699 =	1.607699
111		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	160.616724
4800	4800			
325		1.000000 x	2.780000 =	2.780000
112		.010000 x	17.312112 =	.173121
-----				
			T.E =	2.953121