

ΑΤΕΟ (ΝΕΟ)

Αναλυτικά Τιμολόγια Έργων Οδοποιίας

4ο Τρίμηνο του 2010

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
211	1.056100
212	1.291000
213	1.949500
214	3.930000
215	.835000
221	.099900
222	.116200
223	.119300
224	.070000
231	.825000
232	2.020000
233	.538600
234	.869000
235	.633000
236	.613000
237	1.110000
238	.538600
239	7.950000
241	7.050000
242	5.000000
243	2.250000
244	2.590000
251	290.000000
252	290.000000
261	15.100000
262	26.300000
263	32.400000
264	64.100000
265	115.100000
271	206.300000
281	21.300000
282	30.000000
283	36.300000
284	75.400000
301	4.060000
302	6.700000
321	.392000
322	
323	.580000
324	.580000
325	2.780000
326	1.310000
327	.540000
328	1.840000
329	.730000
351	745.000000
352	1,010.000000
353	3.720000
354	4.780000
355	.118300
401	260.720000

402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
413	4.400000
414	6.070000
415	8.530000
416	13.150000
417	130.670000
418	43.600000
419	4.400000
420	94.500000
421	31.630000
422	36.920000
423	12.180000
424	40.720000
425	160.590000
426	1,199.420000
427	180.510000
428	425.280000
429	75.360000
501.1M	281.740000
501.2M	358.050000
501.3M	281.740000
501.4M	181.960000
502.1M	325.640000
502.2M	421.350000
502.3M	652.530000
502.4M	872.520000
502.5M	1,510.130000
502.6M	664.960000
504.1M	277.220000
504.2M	400.680000
504.3M	220.140000
504.4M	269.060000
505.1M	598.870000
505.2M	843.860000
506.10M	383.030000
506.1M	123.390000
506.2M	130.900000
506.3M	174.350000
506.4M	199.400000
506.5M	171.670000
506.6M	203.850000
506.7M	305.780000
506.8M	247.840000
506.9M	297.410000
508.1M	18.310000
508.2M	21.970000
508.3M	21.970000
508.4M	30.520000
509.1M	92.080000

509.2M	92.080000
509.3M	96.230000
509.4M	99.910000
511.1M	11.180000
511.2M	11.180000
511.3M	14.900000
511.4M	14.900000
511.5M	16.890000
511.6M	15.650000
512.1M	1.530000
512.2M	1.980000
512.3M	1.980000
512.4M	2.590000
512.5M	2.590000
512.6M	4.420000
512.7M	4.420000
512.8M	15.260000
512.9M	21.360000
514.1M	243.560000
514.2M	249.800000
514.3M	319.750000
514.4M	337.230000
514.5M	395.930000
515.1M	140.980000
515.2M	201.400000
515.3M	302.090000
515.4M	302.090000
515.5M	332.300000
515.6M	443.070000
515.7M	634.400000
515.8M	538.730000
517.1M	509.760000
517.2M	1,372.420000
517.3M	1,568.480000
517.4M	490.150000
517.5M	509.760000
517.6M	637.190000
518.1M	958.880000
518.2M	1,917.760000
518.3M	1,917.760000
518.4M	1,917.760000
519.1M	259.330000
519.2M	324.160000
519.3M	319.840000
519.4M	283.100000
519.5M	399.800000
519.6M	259.330000
521.1M	75.040000
521.2M	75.040000
521.3M	61.910000
521.4M	74.100000
521.5M	87.230000
521.6M	98.490000
521.7M	98.490000
523.1M	93.690000
525.1M	28.730000
526.1M	156.130000
527.1M	1,282.330000
527.2M	2,369.530000

528.1M	312.250000
528.2M	349.720000
528.3M	349.720000
528.4M	374.700000
529.1M	112.410000

501	501				
501.1		.100000 x	554.544106 =	55.454411	
501.3		.150000 x	554.544106 =	83.181616	
501.4		.150000 x	496.106257 =	74.415939	
501.2		.600000 x	697.362685 =	418.417611	
			H.Δ. =	631.469576	
501.1	501.1				
211		146.190706 x	1.056100 =	154.392005	
114		6.670000 x	23.886192 =	159.320901	
211		14.619071 x	1.056100 =	15.439201	
501.1M		.800000 x	281.740000 =	225.392000	
			H.Δ. =	554.544106	
501.2	501.2				
211		216.578823 x	1.056100 =	228.728895	
114		6.670000 x	23.886192 =	159.320901	
211		21.657882 x	1.056100 =	22.872889	
501.2M		.800000 x	358.050000 =	286.440000	
			H.Δ. =	697.362685	
501.3	501.3				
211		14.619071 x	1.056100 =	15.439201	
114		6.670000 x	23.886192 =	159.320901	
501.3M		.800000 x	281.740000 =	225.392000	
211		146.190706 x	1.056100 =	154.392005	
			H.Δ. =	554.544106	
501.4	501.4				
211		164.599905 x	1.056100 =	173.833960	
211		16.459991 x	1.056100 =	17.383396	
501.4M		.800000 x	181.960000 =	145.568000	
114		6.670000 x	23.886192 =	159.320901	
			H.Δ. =	496.106257	
502	502				
502.1		.200000 x	722.886947 =	144.577389	
502.3		.400000 x	1,182.535354 =	473.014142	
502.2		.400000 x	854.492837 =	341.797135	
			H.Δ. =	959.388666	

502.1	502.1			
211		24.365118 x	1.056100 =	25.732001
118		2.000000 x	10.001019 =	20.002038
211		243.651176 x	1.056100 =	257.320007
114		6.670000 x	23.886192 =	159.320901
502.1M		.800000 x	325.640000 =	260.512000
		-----		
			H.Δ. =	722.886947
502.2	502.2			
211		291.027794 x	1.056100 =	307.354453
211		29.102779 x	1.056100 =	30.735445
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.2M		.800000 x	421.350000 =	337.080000
		-----		
			H.Δ. =	854.492837
502.3	502.3			
211		414.207001 x	1.056100 =	437.444014
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.3M		.800000 x	652.530000 =	522.024000
211		41.420700 x	1.056100 =	43.744401
		-----		
			H.Δ. =	1,182.535354
503	503			
502.3		.150000 x	1,182.535354 =	177.380303
503.4		.400000 x	1,459.168065 =	583.667226
503.6		.100000 x	1,230.219623 =	123.021962
503.5		.350000 x	2,205.132744 =	771.796460
		-----		
			H.Δ. =	1,655.865952
503.4	503.4			
211		50.083853 x	1.056100 =	52.893557
211		500.838528 x	1.056100 =	528.935569
502.4M		.800000 x	872.520000 =	698.016000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	1,459.168065
503.5	503.5			
211		703.881180 x	1.056100 =	743.368914
118		2.000000 x	10.001019 =	20.002038
211		70.388118 x	1.056100 =	74.336891
114		6.670000 x	23.886192 =	159.320901
502.5M		.800000 x	1,510.130000 =	1,208.104000
		-----		
			H.Δ. =	2,205.132744

503.6	503.6			
211		44.669383 x	1.056100 =	47.175335
211		446.693825 x	1.056100 =	471.753349
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.6M		.800000 x	664.960000 =	531.968000
		-----		
			H.Δ. =	1,230.219623
504	504			
504.1		.350000 x	676.728999 =	236.855150
504.4		.100000 x	650.072855 =	65.007286
504.2		.450000 x	850.977535 =	382.939891
504.3		.100000 x	631.064999 =	63.106500
		-----		
			H.Δ. =	747.908826
504.1	504.1			
211		254.480118 x	1.056100 =	268.756453
114		6.670000 x	23.886192 =	159.320901
504.1M		.800000 x	277.220000 =	221.776000
211		25.448012 x	1.056100 =	26.875645
		-----		
			H.Δ. =	676.728999
504.2	504.2			
211		319.453766 x	1.056100 =	337.375122
211		31.945376 x	1.056100 =	33.737512
504.2M		.800000 x	400.680000 =	320.544000
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	850.977535
504.3	504.3			
211		25.448012 x	1.056100 =	26.875645
211		254.480118 x	1.056100 =	268.756453
114		6.670000 x	23.886192 =	159.320901
504.3M		.800000 x	220.140000 =	176.112000
		-----		
			H.Δ. =	631.064999
504.4	504.4			
211		237.153812 x	1.056100 =	250.458141
211		23.715381 x	1.056100 =	25.045814
114		6.670000 x	23.886192 =	159.320901
504.4M		.800000 x	269.060000 =	215.248000
		-----		
			H.Δ. =	650.072855

505	505				
505.1		.500000 x	1,093.563924 =	546.781962	
505.2		.500000 x	1,289.555924 =	644.777962	
-----					
			H.Δ. =	1,191.559924	
505.1	505.1				
211		35.735506 x	1.056100 =	37.740268	
118		4.000000 x	10.001019 =	40.004076	
114		6.670000 x	23.886192 =	159.320901	
505.1M		.800000 x	598.870000 =	479.096000	
211		357.355061 x	1.056100 =	377.402680	
-----					
			H.Δ. =	1,093.563924	
505.2	505.2				
211		35.735506 x	1.056100 =	37.740268	
211		357.355061 x	1.056100 =	377.402680	
505.2M		.800000 x	843.860000 =	675.088000	
118		4.000000 x	10.001019 =	40.004076	
114		6.670000 x	23.886192 =	159.320901	
-----					
			H.Δ. =	1,289.555924	
506	506				
506.1		.100000 x	402.053652 =	40.205365	
506.4		.350000 x	505.109784 =	176.788424	
506.2		.200000 x	439.407040 =	87.881408	
506.3		.350000 x	455.087239 =	159.280534	
-----					
			H.Δ. =	464.155731	
506.1	506.1				
211		10.675531 x	1.056100 =	11.274428	
118		2.000000 x	10.001019 =	20.002038	
506.1M		.800000 x	123.390000 =	98.712000	
114		6.670000 x	23.886192 =	159.320901	
211		106.755312 x	1.056100 =	112.744285	
-----					
			H.Δ. =	402.053652	
506.2	506.2				
211		13.373742 x	1.056100 =	14.124009	
506.2M		.800000 x	130.900000 =	104.720000	
114		6.670000 x	23.886192 =	159.320901	
118		2.000000 x	10.001019 =	20.002038	
211		133.737423 x	1.056100 =	141.240092	
-----					
			H.Δ. =	439.407040	

506.3	506.3			
211		117.313529 x	1.056100 =	123.894818
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.3M		.800000 x	174.350000 =	139.480000
211		11.731353 x	1.056100 =	12.389482
		-----		
			H.Δ. =	455.087239
506.4	506.4			
211		14.312251 x	1.056100 =	15.115168
211		143.122505 x	1.056100 =	151.151678
506.4M		.800000 x	199.400000 =	159.520000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	505.109784
507	507			
507.5		.100000 x	534.713819 =	53.471382
507.8		.100000 x	599.738347 =	59.973835
507.10		.250000 x	874.157195 =	218.539299
507.9		.350000 x	695.270910 =	243.344819
507.6		.100000 x	649.042614 =	64.904261
507.7		.100000 x	744.215044 =	74.421504
		-----		
			H.Δ. =	714.655100
507.10	507.10			
211		334.343559 x	1.056100 =	353.100233
118		2.000000 x	10.001019 =	20.002038
211		33.434356 x	1.056100 =	35.310023
114		6.670000 x	23.886192 =	159.320901
506.10M		.800000 x	383.030000 =	306.424000
		-----		
			H.Δ. =	874.157195
507.5	507.5			
211		187.701647 x	1.056100 =	198.231709
506.5M		.800000 x	171.670000 =	137.336000
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
211		18.770165 x	1.056100 =	19.823171
		-----		
			H.Δ. =	534.713819

507.6	507.6			
211		263.955441 x	1.056100 =	278.763341
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.6M		.800000 x	203.850000 =	163.080000
211		26.395544 x	1.056100 =	27.876334
-----				
			H.Δ. =	649.042614
507.7	507.7			
211		27.568679 x	1.056100 =	29.115282
211		275.686794 x	1.056100 =	291.152823
506.7M		.800000 x	305.780000 =	244.624000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
-----				
			H.Δ. =	744.215044
507.8	507.8			
211		191.221052 x	1.056100 =	201.948553
118		2.000000 x	10.001019 =	20.002038
211		19.122105 x	1.056100 =	20.194855
114		6.670000 x	23.886192 =	159.320901
506.8M		.800000 x	247.840000 =	198.272000
-----				
			H.Δ. =	599.738347
507.9	507.9			
211		23.931960 x	1.056100 =	25.274543
211		239.319599 x	1.056100 =	252.745429
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
506.9M		.800000 x	297.410000 =	237.928000
-----				
			H.Δ. =	695.270910
508	508			
508.1		.250000 x	363.309030 =	90.827258
508.4		.250000 x	442.582023 =	110.645506
508.2		.250000 x	407.122320 =	101.780580
508.3		.250000 x	407.122320 =	101.780580
-----				
			H.Δ. =	405.033923
508.1	508.1			
211		28.155247 x	1.056100 =	29.734756
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
508.1M		.800000 x	18.310000 =	14.648000
211		2.815525 x	1.056100 =	2.973476
-----				
			H.Δ. =	363.309030

508.2	508.2				
211		6.334931 x	1.056100 =	6.690321	
211		63.349306 x	1.056100 =	66.903202	
508.2M		.800000 x	21.970000 =	17.576000	
116		13.340000 x	20.419486 =	272.395943	
115		2.000000 x	21.778427 =	43.556854	
		-----			
			H.Δ. =	407.122320	
508.3	508.3				
211		6.334931 x	1.056100 =	6.690321	
116		13.340000 x	20.419486 =	272.395943	
211		63.349306 x	1.056100 =	66.903202	
115		2.000000 x	21.778427 =	43.556854	
508.3M		.800000 x	21.970000 =	17.576000	
		-----			
			H.Δ. =	407.122320	
508.4	508.4				
211		87.985147 x	1.056100 =	92.921114	
211		8.798515 x	1.056100 =	9.292112	
115		2.000000 x	21.778427 =	43.556854	
116		13.340000 x	20.419486 =	272.395943	
508.4M		.800000 x	30.520000 =	24.416000	
		-----			
			H.Δ. =	442.582023	
509	509				
509.1		.100000 x	515.800049 =	51.580005	
509.4		.500000 x	550.369251 =	275.184626	
509.2		.200000 x	468.624714 =	93.724943	
509.3		.200000 x	571.012918 =	114.202584	
		-----			
			H.Δ. =	534.692157	
509.1	509.1				
211		284.259705 x	1.056100 =	300.206674	
117		6.670000 x	16.777917 =	111.908706	
509.1M		.800000 x	92.080000 =	73.664000	
211		28.425971 x	1.056100 =	30.020668	
		-----			
			H.Δ. =	515.800049	
509.2	509.2				
211		243.651176 x	1.056100 =	257.320007	
211		24.365118 x	1.056100 =	25.732001	
509.2M		.800000 x	92.080000 =	73.664000	
117		6.670000 x	16.777917 =	111.908706	
		-----			
			H.Δ. =	468.624714	

509.3	509.3			
211		32.892909 x	1.056100 =	34.738201
211		328.929089 x	1.056100 =	347.382011
117		6.670000 x	16.777917 =	111.908706
509.3M		.800000 x	96.230000 =	76.984000
		-----		
			H.Δ. =	571.012918
509.4	509.4			
211		308.624825 x	1.056100 =	325.938678
211		30.862482 x	1.056100 =	32.593867
117		6.670000 x	16.777917 =	111.908706
509.4M		.800000 x	99.910000 =	79.928000
		-----		
			H.Δ. =	550.369251
511	511			
511.1		.150000 x	390.915556 =	58.637333
511.4		.225000 x	394.237509 =	88.703440
511.5		.125000 x	395.829509 =	49.478689
511.6		.125000 x	394.491556 =	49.311445
511.3		.225000 x	393.891556 =	88.625600
511.2		.150000 x	389.531746 =	58.429762
		-----		
			H.Δ. =	393.186268
511.1	511.1			
211		.496326 x	1.056100 =	.524170
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.1M		.800000 x	11.180000 =	8.944000
211		4.963265 x	1.056100 =	5.241704
		-----		
			H.Δ. =	390.915556
511.2	511.2			
211		.377208 x	1.056100 =	.398369
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.2M		.800000 x	11.180000 =	8.944000
211		3.772081 x	1.056100 =	3.983695
		-----		
			H.Δ. =	389.531746
511.3	511.3			
211		4.963265 x	1.056100 =	5.241704
211		.496326 x	1.056100 =	.524170
511.3M		.800000 x	14.900000 =	11.920000
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
		-----		
			H.Δ. =	393.891556

511.4	511.4			
211		5.261061 x	1.056100 =	5.556207
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.4M		.800000 x	14.900000 =	11.920000
211		.526106 x	1.056100 =	.555621
		-----		
			H.Δ. =	394.237509
511.5	511.5			
211		5.261061 x	1.056100 =	5.556207
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.5M		.800000 x	16.890000 =	13.512000
211		.526106 x	1.056100 =	.555621
		-----		
			H.Δ. =	395.829509
511.6	511.6			
211		4.963265 x	1.056100 =	5.241704
112		13.340000 x	17.312112 =	230.943574
511.6M		.800000 x	15.650000 =	12.520000
115		6.670000 x	21.778427 =	145.262108
211		.496326 x	1.056100 =	.524170
		-----		
			H.Δ. =	394.491556
512	512			
512.1		.200000 x	105.590769 =	21.118154
512.4		.200000 x	154.157227 =	30.831445
512.5		.200000 x	156.253909 =	31.250782
512.2		.200000 x	109.095791 =	21.819158
512.3		.200000 x	112.240813 =	22.448163
		-----		
			H.Δ. =	127.467702
512.1	512.1			
211		1.804824 x	1.056100 =	1.906075
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
512.1M		.800000 x	1.530000 =	1.224000
211		.180482 x	1.056100 =	.190607
		-----		
			H.Δ. =	105.590769

512.2	512.2			
211		4.512059 x	1.056100 =	4.765186
211		.451206 x	1.056100 =	.476519
512.2M		.800000 x	1.980000 =	1.584000
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
-----				
			H.Δ. =	109.095791
512.3	512.3			
211		.721929 x	1.056100 =	.762429
117		3.000000 x	16.777917 =	50.333751
211		7.219294 x	1.056100 =	7.624296
112		3.000000 x	17.312112 =	51.936336
512.3M		.800000 x	1.980000 =	1.584000
-----				
			H.Δ. =	112.240813
512.4	512.4			
211		1.353618 x	1.056100 =	1.429556
211		13.536176 x	1.056100 =	14.295555
112		4.000000 x	17.312112 =	69.248448
117		4.000000 x	16.777917 =	67.111668
512.4M		.800000 x	2.590000 =	2.072000
-----				
			H.Δ. =	154.157227
512.5	512.5			
211		15.341000 x	1.056100 =	16.201630
117		4.000000 x	16.777917 =	67.111668
112		4.000000 x	17.312112 =	69.248448
512.5M		.800000 x	2.590000 =	2.072000
211		1.534100 x	1.056100 =	1.620163
-----				
			H.Δ. =	156.253909
512A	512A			
512.1		.333333 x	105.590769 =	35.196888
512.2		.333333 x	109.095791 =	36.365227
512.3		.333333 x	112.240813 =	37.413567
-----				
			H.Δ. =	108.975682
512B	512B			
512.4		.500000 x	154.157227 =	77.078614
512.5		.500000 x	156.253909 =	78.126955
-----				
			H.Δ. =	155.205568

513	513				
513.6		.250000 x	205.436368 =	51.359092	
513.9		.250000 x	271.725354 =	67.931339	
513.8		.250000 x	259.506967 =	64.876742	
513.7		.250000 x	215.919775 =	53.979944	
		-----			
			H.Δ. =	238.147116	
513.6	513.6				
211		2.707235 x	1.056100 =	2.859111	
117		5.000000 x	16.777917 =	83.889585	
112		5.000000 x	17.312112 =	86.560560	
211		27.072353 x	1.056100 =	28.591112	
512.6M		.800000 x	4.420000 =	3.536000	
		-----			
			H.Δ. =	205.436368	
513.7	513.7				
211		3.609647 x	1.056100 =	3.812148	
512.7M		.800000 x	4.420000 =	3.536000	
117		5.000000 x	16.777917 =	83.889585	
112		5.000000 x	17.312112 =	86.560560	
211		36.096470 x	1.056100 =	38.121482	
		-----			
			H.Δ. =	215.919775	
513.8	513.8				
211		1.714582 x	1.056100 =	1.810770	
211		17.145823 x	1.056100 =	18.107704	
512.8M		.800000 x	15.260000 =	12.208000	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
		-----			
			H.Δ. =	259.506967	
513.9	513.9				
211		23.462706 x	1.056100 =	24.778964	
211		2.346271 x	1.056100 =	2.477897	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
512.9M		.800000 x	21.360000 =	17.088000	
		-----			
			H.Δ. =	271.725354	
513A	513A				
513.6		.500000 x	205.436368 =	102.718184	
513.7		.500000 x	215.919775 =	107.959888	
		-----			
			H.Δ. =	210.678072	

513B	513B				
513.9		1.000000 x	271.725354 =	271.725354	
			H.Δ. =	271.725354	
514	514				
514.1		.150000 x	581.631951 =	87.244793	
514.3		.150000 x	658.309063 =	98.746359	
514.4		.250000 x	719.468398 =	179.867100	
514.5		.300000 x	845.053955 =	253.516187	
514.2		.150000 x	596.059019 =	89.408853	
			H.Δ. =	708.783291	
514.1	514.1				
211		5.865676 x	1.056100 =	6.194740	
114		13.340000 x	23.886192 =	318.641801	
514.1M		.800000 x	243.560000 =	194.848000	
211		58.656765 x	1.056100 =	61.947410	
			H.Δ. =	581.631951	
514.2	514.2				
211		66.778471 x	1.056100 =	70.524743	
211		6.677847 x	1.056100 =	7.052474	
514.2M		.800000 x	249.800000 =	199.840000	
114		13.340000 x	23.886192 =	318.641801	
			H.Δ. =	596.059019	
514.3	514.3				
211		7.219294 x	1.056100 =	7.624296	
211		72.192941 x	1.056100 =	76.242965	
114		13.340000 x	23.886192 =	318.641801	
514.3M		.800000 x	319.750000 =	255.800000	
			H.Δ. =	658.309063	
514.4	514.4				
211		112.801471 x	1.056100 =	119.129634	
211		11.280147 x	1.056100 =	11.912963	
114		13.340000 x	23.886192 =	318.641801	
514.4M		.800000 x	337.230000 =	269.784000	
			H.Δ. =	719.468398	

514.5	514.5				
211		18.048235 x	1.056100 =	19.060741	
114		13.340000 x	23.886192 =	318.641801	
514.5M		.800000 x	395.930000 =	316.744000	
211		180.482353 x	1.056100 =	190.607413	
-----					
			H.Δ. =	845.053955	
515	515				
515.1		.200000 x	366.036233 =	73.207247	
515.2		.200000 x	446.241793 =	89.248359	
515.4		.200000 x	589.694240 =	117.938848	
515.5		.200000 x	651.602506 =	130.320501	
515.3		.200000 x	588.855568 =	117.771114	
-----					
			H.Δ. =	528.486068	
515.1	515.1				
211		8.085609 x	1.056100 =	8.539212	
515.1M		.800000 x	140.980000 =	112.784000	
211		80.856094 x	1.056100 =	85.392121	
114		6.670000 x	23.886192 =	159.320901	
-----					
			H.Δ. =	366.036233	
515.2	515.2				
211		10.828941 x	1.056100 =	11.436445	
211		108.289412 x	1.056100 =	114.364448	
114		6.670000 x	23.886192 =	159.320901	
515.2M		.800000 x	201.400000 =	161.120000	
-----					
			H.Δ. =	446.241793	
515.3	515.3				
211		16.171219 x	1.056100 =	17.078424	
515.3M		.800000 x	302.090000 =	241.672000	
114		6.670000 x	23.886192 =	159.320901	
211		161.712189 x	1.056100 =	170.784243	
-----					
			H.Δ. =	588.855568	
515.4	515.4				
211		16.243412 x	1.056100 =	17.154667	
114		6.670000 x	23.886192 =	159.320901	
515.4M		.800000 x	302.090000 =	241.672000	
211		162.434118 x	1.056100 =	171.546672	
-----					
			H.Δ. =	589.694240	

515.5	515.5			
211		194.920940 x	1.056100 =	205.856005
515.5M		.800000 x	332.300000 =	265.840000
114		6.670000 x	23.886192 =	159.320901
211		19.492094 x	1.056100 =	20.585600
		-----		
			H.Δ. =	651.602506
516	516			
515.5		.150000 x	651.602506 =	97.740376
516.6		.150000 x	756.991960 =	113.548794
516.8		.350000 x	898.936425 =	314.627749
516.7		.350000 x	981.343133 =	343.470097
		-----		
			H.Δ. =	869.387015
516.6	516.6			
211		209.359530 x	1.056100 =	221.104600
114		6.670000 x	23.886192 =	159.320901
515.6M		.800000 x	443.070000 =	354.456000
211		20.935953 x	1.056100 =	22.110460
		-----		
			H.Δ. =	756.991960
516.7	516.7			
211		27.072353 x	1.056100 =	28.591112
114		6.670000 x	23.886192 =	159.320901
515.7M		.800000 x	634.400000 =	507.520000
211		270.723530 x	1.056100 =	285.911120
		-----		
			H.Δ. =	981.343133
516.8	516.8			
211		265.670025 x	1.056100 =	280.574113
114		6.670000 x	23.886192 =	159.320901
211		26.567002 x	1.056100 =	28.057411
515.8M		.800000 x	538.730000 =	430.984000
		-----		
			H.Δ. =	898.936425
517	517			
517.1		.100000 x	1,224.898811 =	122.489881
517.2		.250000 x	2,156.145190 =	539.036298
517.3		.250000 x	2,459.760897 =	614.940224
517.4		.100000 x	1,130.585255 =	113.058526
517.6		.200000 x	1,379.259850 =	275.851970
517.5		.100000 x	1,198.690293 =	119.869029
		-----		
			H.Δ. =	1,785.245928

517.1	517.1				
211		15.792206 x	1.056100 =		16.678149
111		20.010000 x	15.741598 =		314.989376
114		13.340000 x	23.886192 =		318.641801
211		157.922058 x	1.056100 =		166.781485
517.1M		.800000 x	509.760000 =		407.808000
		-----			
			H.Δ. =		1,224.898811
517.2	517.2				
211		365.476765 x	1.056100 =		385.980012
114		13.340000 x	23.886192 =		318.641801
111		20.010000 x	15.741598 =		314.989376
211		36.547677 x	1.056100 =		38.598002
517.2M		.800000 x	1,372.420000 =		1,097.936000
		-----			
			H.Δ. =		2,156.145190
517.3	517.3				
211		49.181441 x	1.056100 =		51.940520
114		13.340000 x	23.886192 =		318.641801
111		20.010000 x	15.741598 =		314.989376
517.3M		.800000 x	1,568.480000 =		1,254.784000
211		491.814411 x	1.056100 =		519.405199
		-----			
			H.Δ. =		2,459.760897
517.4	517.4				
211		9.024118 x	1.056100 =		9.530371
211		90.241177 x	1.056100 =		95.303707
517.4M		.800000 x	490.150000 =		392.120000
114		13.340000 x	23.886192 =		318.641801
111		20.010000 x	15.741598 =		314.989376
		-----			
			H.Δ. =		1,130.585255
517.5	517.5				
211		135.361765 x	1.056100 =		142.955560
114		13.340000 x	23.886192 =		318.641801
211		13.536176 x	1.056100 =		14.295555
111		20.010000 x	15.741598 =		314.989376
517.5M		.800000 x	509.760000 =		407.808000
		-----			
			H.Δ. =		1,198.690293

517.6	517.6			
211		20.304265 x	1.056100 =	21.443334
211		203.042646 x	1.056100 =	214.433338
111		20.010000 x	15.741598 =	314.989376
114		13.340000 x	23.886192 =	318.641801
517.6M		.800000 x	637.190000 =	509.752000

-----  
 Η.Δ. = 1,379.259850

518	518			
518.1		.250000 x	1,892.381629 =	473.095407
518.4		.250000 x	2,718.192710 =	679.548178
518.2		.250000 x	2,659.485629 =	664.871407
518.3		.250000 x	2,688.839170 =	672.209793

-----  
 Η.Δ. = 2,489.724785

518.1	518.1			
211		265.309059 x	1.056100 =	280.192897
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
518.1M		.800000 x	958.880000 =	767.104000
211		26.530906 x	1.056100 =	28.019290

-----  
 Η.Δ. = 1,892.381629

518.2	518.2			
211		26.530906 x	1.056100 =	28.019290
211		265.309059 x	1.056100 =	280.192897
518.2M		.800000 x	1,917.760000 =	1,534.208000
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702

-----  
 Η.Δ. = 2,659.485629

518.3	518.3			
211		290.576588 x	1.056100 =	306.877935
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
211		29.057659 x	1.056100 =	30.687794
114		20.010000 x	23.886192 =	477.962702
518.3M		.800000 x	1,917.760000 =	1,534.208000

-----  
 Η.Δ. = 2,688.839170

518.4	518.4			
211		31.584412 x	1.056100 =	33.356298
211		315.844116 x	1.056100 =	333.562971
114		20.010000 x	23.886192 =	477.962702
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
518.4M		.800000 x	1,917.760000 =	1,534.208000
-----				
			H.Δ. =	2,718.192710
519	519			
519.1		.050000 x	722.391876 =	36.119594
519.6		.300000 x	682.447787 =	204.734336
519.5		.100000 x	976.081905 =	97.608191
519.2		.050000 x	813.356679 =	40.667834
519.4		.200000 x	739.623391 =	147.924678
519.3		.300000 x	775.829605 =	232.748882
-----				
			H.Δ. =	759.803514
519.1	519.1			
211		171.277754 x	1.056100 =	180.886436
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
519.1M		.800000 x	259.330000 =	207.464000
211		17.127775 x	1.056100 =	18.088643
-----				
			H.Δ. =	722.391876
519.2	519.2			
211		234.627058 x	1.056100 =	247.789636
211		23.462706 x	1.056100 =	24.778964
519.2M		.800000 x	324.160000 =	259.328000
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
-----				
			H.Δ. =	813.356679
519.3	519.3			
211		20.529868 x	1.056100 =	21.681594
116		6.670000 x	20.419486 =	136.197972
211		205.298676 x	1.056100 =	216.815932
115		6.670000 x	21.778427 =	145.262108
519.3M		.800000 x	319.840000 =	255.872000
-----				
			H.Δ. =	775.829605

519.4	519.4			
211		199.433001 x	1.056100 =	210.621192
211		19.943300 x	1.056100 =	21.062119
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.4M		.800000 x	283.100000 =	226.480000
		-----		
			H.Δ. =	739.623391
519.5	519.5			
211		32.261220 x	1.056100 =	34.071074
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
519.5M		.800000 x	399.800000 =	319.840000
211		322.612206 x	1.056100 =	340.710751
		-----		
			H.Δ. =	976.081905
519.6	519.6			
211		16.658521 x	1.056100 =	17.593064
211		166.585213 x	1.056100 =	175.930643
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.6M		.800000 x	259.330000 =	207.464000
		-----		
			H.Δ. =	682.447787
521	521			
521.1		.250000 x	316.156535 =	79.039134
521.4		.150000 x	363.208875 =	54.481331
521.5		.150000 x	373.712875 =	56.056931
521.2		.250000 x	322.446581 =	80.611645
521.3		.200000 x	308.168554 =	61.633711
		-----		
			H.Δ. =	331.822752
521.1	521.1			
211		7.471969 x	1.056100 =	7.891146
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.1M		.800000 x	75.040000 =	60.032000
211		74.719694 x	1.056100 =	78.911469
		-----		
			H.Δ. =	316.156535

521.2	521.2			
211		80.134165 x	1.056100 =	84.629692
114		6.670000 x	23.886192 =	159.320901
521.2M		.800000 x	75.040000 =	60.032000
118		1.000000 x	10.001019 =	10.001019
211		8.013417 x	1.056100 =	8.462970
		-----		
			H.Δ. =	322.446581
521.3	521.3			
211		76.885483 x	1.056100 =	81.198759
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.3M		.800000 x	61.910000 =	49.528000
211		7.688548 x	1.056100 =	8.119876
		-----		
			H.Δ. =	308.168554
521.4	521.4			
211		11.586967 x	1.056100 =	12.236996
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.4M		.800000 x	74.100000 =	59.280000
211		115.869671 x	1.056100 =	122.369960
		-----		
			H.Δ. =	363.208875
521.5	521.5			
211		115.869671 x	1.056100 =	122.369960
211		11.586967 x	1.056100 =	12.236996
521.5M		.800000 x	87.230000 =	69.784000
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	373.712875
522	522			
522.6		.500000 x	456.880349 =	228.440175
522.7		.500000 x	451.848313 =	225.924157
		-----		
			H.Δ. =	454.364331
522.6	522.6			
211		17.109727 x	1.056100 =	18.069583
521.6M		.800000 x	98.490000 =	78.792000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
211		171.097271 x	1.056100 =	180.695828
		-----		
			H.Δ. =	456.880349

522.7	522.7			
211		16.676569 x	1.056100 =	17.612125
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
521.7M		.800000 x	98.490000 =	78.792000
211		166.765694 x	1.056100 =	176.121249
		-----		
			H.Δ. =	451.848313
523	523			
523.1		1.000000 x	354.757612 =	354.757612
		-----		
			H.Δ. =	354.757612
523.1	523.1			
211		54.144706 x	1.056100 =	57.182224
523.1M		.800000 x	93.690000 =	74.952000
117		6.670000 x	16.777917 =	111.908706
111		6.670000 x	15.741598 =	104.996459
211		5.414471 x	1.056100 =	5.718223
		-----		
			H.Δ. =	354.757612
525	525			
525.1		1.000000 x	247.104294 =	247.104294
		-----		
			H.Δ. =	247.104294
525.1	525.1			
211		4.512059 x	1.056100 =	4.765186
118		6.670000 x	10.001019 =	66.706797
111		6.670000 x	15.741598 =	104.996459
525.1M		.800000 x	28.730000 =	22.984000
211		45.120588 x	1.056100 =	47.651853
		-----		
			H.Δ. =	247.104294
526	526			
526.1		1.000000 x	549.867771 =	549.867771
		-----		
			H.Δ. =	549.867771
526.1	526.1			
211		243.651176 x	1.056100 =	257.320007
118		3.000000 x	10.001019 =	30.003057
117		6.670000 x	16.777917 =	111.908706
526.1M		.800000 x	156.130000 =	124.904000
211		24.365118 x	1.056100 =	25.732001
		-----		
			H.Δ. =	549.867771

527	527			
527.1		.400000 x	2,109.667836 =	843.867134
527.2		.600000 x	3,105.228730 =	1,863.137238

H.Δ. = 2,707.004372

527.1	527.1			
211		433.157646 x	1.056100 =	457.457790
114		16.680000 x	23.886192 =	398.421683
118		6.670000 x	10.001019 =	66.706797
211		43.315765 x	1.056100 =	45.745779
112		6.670000 x	17.312112 =	115.471787
527.1M		.800000 x	1,282.330000 =	1,025.864000

H.Δ. = 2,109.667836

527.2	527.2			
211		54.144706 x	1.056100 =	57.182224
118		6.670000 x	10.001019 =	66.706797
114		16.680000 x	23.886192 =	398.421683
112		6.670000 x	17.312112 =	115.471787
211		541.447060 x	1.056100 =	571.822240
527.2M		.800000 x	2,369.530000 =	1,895.624000

H.Δ. = 3,105.228730

528	528			
528.1		.250000 x	799.025259 =	199.756315
528.4		.250000 x	913.982387 =	228.495597
528.2		.250000 x	858.354801 =	214.588700
528.3		.250000 x	847.871393 =	211.967848

H.Δ. = 854.808460

528.1	528.1			
211		79.412235 x	1.056100 =	83.867261
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
528.1M		.800000 x	312.250000 =	249.800000
211		7.941224 x	1.056100 =	8.386727

H.Δ. = 799.025259

528.2	528.2			
211		10.467976 x	1.056100 =	11.055229
211		104.679765 x	1.056100 =	110.552300
528.2M		.800000 x	349.720000 =	279.776000
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
		-----		
			H.Δ. =	858.354801
528.3	528.3			
211		9.565565 x	1.056100 =	10.102193
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
211		95.655647 x	1.056100 =	101.021929
112		13.340000 x	17.312112 =	230.943574
528.3M		.800000 x	349.720000 =	279.776000
		-----		
			H.Δ. =	847.871393
528.4	528.4			
211		135.361765 x	1.056100 =	142.955560
211		13.536176 x	1.056100 =	14.295555
112		13.340000 x	17.312112 =	230.943574
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
528.4M		.800000 x	374.700000 =	299.760000
		-----		
			H.Δ. =	913.982387
529	529			
529.1		1.000000 x	715.832289 =	715.832289
		-----		
			H.Δ. =	715.832289
529.1	529.1			
211		243.651176 x	1.056100 =	257.320007
117		6.670000 x	16.777917 =	111.908706
112		13.340000 x	17.312112 =	230.943574
529.1M		.800000 x	112.410000 =	89.928000
211		24.365118 x	1.056100 =	25.732001
		-----		
			H.Δ. =	715.832289

2730A	2730A			
234		48.000000 x	.869000 =	41.712000
509		.200000 x	534.692157 =	106.938431
513		.250000 x	238.147116 =	59.536779
511		.150000 x	393.186268 =	58.977940
517		1.000000 x	1,785.245928 =	1,785.245928
504		.400000 x	747.908826 =	299.163530
509		.400000 x	534.692157 =	213.876863
113		13.340000 x	20.419486 =	272.395943
251		.040000 x	290.000000 =	11.600000
112		6.670000 x	17.312112 =	115.471787
111		6.670000 x	15.741598 =	104.996459
235		24.000000 x	.633000 =	15.192000

-----  
 B.T = 3,085.107661

2730B	2730B			
234		1,000.000000 x	.869000 =	869.000000
506		2.500000 x	464.155731 =	1,160.389328
517		9.000000 x	1,785.245928 =	16,067.213352
515		7.000000 x	528.486068 =	3,699.402476
509		5.000000 x	534.692157 =	2,673.460785
509		2.209627 x	534.692157 =	1,181.470227
113		140.000000 x	20.419486 =	2,858.728040
112		360.000000 x	17.312112 =	6,232.360320
111		360.000000 x	15.741598 =	5,666.975280
252		2.000000 x	290.000000 =	580.000000
251		2.000000 x	290.000000 =	580.000000
235		500.000000 x	.633000 =	316.500000

-----  
 B.T = 41,885.499807

2730Γ	2730Γ			
222		350.000000 x	.116200 =	40.670000
625		.500000 x	16.068735 =	8.034368
630		.200000 x	.542375 =	.108475
623		.800000 x	14.558744 =	11.646995

-----  
 B.T = 60.459838

611	611			
111		1.400000 x	15.741598 =	22.038237

-----  
 B.T = 22.038237

612	612			
111		.250000 x	15.741598 =	3.935400
503		.000588 x	1,655.865952 =	.973649
504		.000833 x	747.908826 =	.623008

-----  
 B.T = 5.532057

613	613			
111		.200000 x	15.741598 =	3.148320
518		.000500 x	2,489.724785 =	1.244862
504		.001000 x	747.908826 =	.747909
503		.000667 x	1,655.865952 =	1.104463
-----				
			B.T =	6.245553
614	614			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,489.724785 =	6.224312
504		.001000 x	747.908826 =	.747909
509		.001950 x	534.692157 =	1.042650
503		.000909 x	1,655.865952 =	1.505182
-----				
			B.T =	10.905022
615	615			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,489.724785 =	6.224312
504		.001000 x	747.908826 =	.747909
509		.001950 x	534.692157 =	1.042650
503		.000909 x	1,655.865952 =	1.505182
-----				
			B.T =	10.905022
616	616			
112		.080000 x	17.312112 =	1.384969
503		.000909 x	1,655.865952 =	1.505182
518		.002500 x	2,489.724785 =	6.224312
504		.001000 x	747.908826 =	.747909
509		.001950 x	534.692157 =	1.042650
-----				
			B.T =	10.905022
617	617			
111		.100000 x	15.741598 =	1.574160
503		.001000 x	1,655.865952 =	1.655866
518		.000625 x	2,489.724785 =	1.556078
504		.001000 x	747.908826 =	.747909
-----				
			B.T =	5.534013
621	621			
213		1.000000 x	1.949500 =	1.949500
519		.002500 x	759.803514 =	1.899509
111		.650000 x	15.741598 =	10.232039
116		.060000 x	20.419486 =	1.225169
-----				
			B.T =	15.306217

622	622			
213		1.000000 x	1.949500 =	1.949500
518		.001515 x	2,489.724785 =	3.771933
504		.001111 x	747.908826 =	.830927
519		.002500 x	759.803514 =	1.899509
509		.001950 x	534.692157 =	1.042650
503		.000909 x	1,655.865952 =	1.505182
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211

-----  
 B.T = 14.772860

623	623			
213		1.000000 x	1.949500 =	1.949500
112		.100000 x	17.312112 =	1.731211
503		.000909 x	1,655.865952 =	1.505182
519		.002500 x	759.803514 =	1.899509
518		.001429 x	2,489.724785 =	3.557817
504		.001111 x	747.908826 =	.830927
509		.001950 x	534.692157 =	1.042650
116		.100000 x	20.419486 =	2.041949

-----  
 B.T = 14.558744

624	624			
213		1.000000 x	1.949500 =	1.949500
116		.100000 x	20.419486 =	2.041949
518		.001515 x	2,489.724785 =	3.771933
504		.001111 x	747.908826 =	.830927
519		.002500 x	759.803514 =	1.899509
509		.001950 x	534.692157 =	1.042650
503		.000909 x	1,655.865952 =	1.505182
112		.100000 x	17.312112 =	1.731211

-----  
 B.T = 14.772860

625	625			
213		1.000000 x	1.949500 =	1.949500
518		.002119 x	2,489.724785 =	5.275727
504		.000833 x	747.908826 =	.623008
519		.002500 x	759.803514 =	1.899509
509		.001950 x	534.692157 =	1.042650
503		.000909 x	1,655.865952 =	1.505182
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211

-----  
 B.T = 16.068735

626	626			
509		.001786 x	534.692157 =	.954960
504		.002000 x	747.908826 =	1.495818

-----  
 B.T = 2.450778

630	630			
512		.004255 x	127.467702 =	.542375
-----				
			B.T =	.542375
641	641			
231		.200000 x	.825000 =	.165000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000
251		.001500 x	290.000000 =	.435000
-----				
			B.T =	7.536243
642	642			
231		.300000 x	.825000 =	.247500
113		.250000 x	20.419486 =	5.104872
111		.250000 x	15.741598 =	3.935400
252		.005000 x	290.000000 =	1.450000
251		.003000 x	290.000000 =	.870000
-----				
			B.T =	11.607771
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
625		1.000000 x	16.068735 =	16.068735
511		.040000 x	393.186268 =	15.727451
509		.007516 x	534.692157 =	4.018746
509		.002166 x	534.692157 =	1.158143
630		.600000 x	.542375 =	.325425
224		120.000000 x	.070000 =	8.400000
-----				
			B.T =	92.951953
652	652			
221		650.000000 x	.099900 =	64.935000
111		1.500000 x	15.741598 =	23.612397
511		.040000 x	393.186268 =	15.727451
509		.002166 x	534.692157 =	1.158143
509		.007516 x	534.692157 =	4.018746
630		.320000 x	.542375 =	.173560
625		1.000000 x	16.068735 =	16.068735
112		.500000 x	17.312112 =	8.656056
-----				
			B.T =	134.350088

661	661			
353		.160000 x	3.720000 =	.595200
354		.220000 x	4.780000 =	1.051600
113		1.100000 x	20.419486 =	22.461435
355		.250000 x	.118300 =	.029575
-----				
			B.T =	24.137810
671	671			
215		.562500 x	.835000 =	.469688
525		.000067 x	247.104294 =	.016556
111		.002000 x	15.741598 =	.031483
321		.550000 x	.392000 =	.215600
-----				
			B.T =	.733327
671.1	671.1			
215		.562500 x	.835000 =	.469688
525		.000067 x	247.104294 =	.016556
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.517727
672	672			
215		.075000 x	.835000 =	.062625
321		.940000 x	.392000 =	.368480
525		.000067 x	247.104294 =	.016556
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.479144
672.1	672.1			
215		.075000 x	.835000 =	.062625
525		.000067 x	247.104294 =	.016556
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.110664
4311A	4311A			
321		80.000000 x	.392000 =	31.360000
626		.030000 x	2.450778 =	.073523
625		.500000 x	16.068735 =	8.034368
504		.001786 x	747.908826 =	1.335765
527		.001786 x	2,707.004372 =	4.834710
615		.370000 x	10.905022 =	4.034858
616		.200000 x	10.905022 =	2.181004
-----				
			B.T =	51.854228

4311A.1	4311A.1			
625		.500000 x	16.068735 =	8.034368
626		.030000 x	2.450778 =	.073523
615		.370000 x	10.905022 =	4.034858
616		.200000 x	10.905022 =	2.181004
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
-----				
			B.T =	20.494228
4311B	4311B			
321		80.000000 x	.392000 =	31.360000
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
626		.030000 x	2.450778 =	.073523
625		.500000 x	16.068735 =	8.034368
624		.200000 x	14.772860 =	2.954572
623		.370000 x	14.558744 =	5.386735
-----				
			B.T =	53.979673
4311B.1	4311B.1			
623		.370000 x	14.558744 =	5.386735
624		.200000 x	14.772860 =	2.954572
625		.500000 x	16.068735 =	8.034368
626		.030000 x	2.450778 =	.073523
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
-----				
			B.T =	22.619673
4312	4312			
509		.001622 x	534.692157 =	.867271
504		.001000 x	747.908826 =	.747909
-----				
			B.T =	1.615180
4411A	4411A			
321		80.000000 x	.392000 =	31.360000
625		.500000 x	16.068735 =	8.034368
616		.200000 x	10.905022 =	2.181004
615		.370000 x	10.905022 =	4.034858
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
626		.030000 x	2.450778 =	.073523
-----				
			B.T =	51.854228

4411A.1	4411A.1			
625		.500000 x	16.068735 =	8.034368
626		.030000 x	2.450778 =	.073523
616		.200000 x	10.905022 =	2.181004
615		.370000 x	10.905022 =	4.034858
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
-----				
			B.T =	20.494228
4411B	4411B			
321		80.000000 x	.392000 =	31.360000
623		.370000 x	14.558744 =	5.386735
624		.200000 x	14.772860 =	2.954572
625		.500000 x	16.068735 =	8.034368
626		.030000 x	2.450778 =	.073523
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
-----				
			B.T =	53.979673
4411B.1	4411B.1			
623		.370000 x	14.558744 =	5.386735
624		.200000 x	14.772860 =	2.954572
625		.500000 x	16.068735 =	8.034368
626		.030000 x	2.450778 =	.073523
504		.001786 x	747.908826 =	1.335765
527		.001786 x	2,707.004372 =	4.834710
-----				
			B.T =	22.619673
4412	4412			
509		.001622 x	534.692157 =	.867271
504		.001000 x	747.908826 =	.747909
-----				
			B.T =	1.615180
4511A	4511A			
321		90.000000 x	.392000 =	35.280000
625		.450000 x	16.068735 =	7.230931
626		.050000 x	2.450778 =	.122539
504		.001786 x	747.908826 =	1.335765
527		.001786 x	2,707.004372 =	4.834710
615		.370000 x	10.905022 =	4.034858
616		.300000 x	10.905022 =	3.271507
-----				
			B.T =	56.110309

4511A.1	4511A.1			
625		.450000 x	16.068735 =	7.230931
504		.001786 x	747.908826 =	1.335765
615		.370000 x	10.905022 =	4.034858
616		.300000 x	10.905022 =	3.271507
527		.001786 x	2,707.004372 =	4.834710
626		.050000 x	2.450778 =	.122539
-----				
			B.T =	20.830309
4511B	4511B			
321		90.000000 x	.392000 =	35.280000
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
626		.050000 x	2.450778 =	.122539
625		.450000 x	16.068735 =	7.230931
624		.300000 x	14.772860 =	4.431858
623		.370000 x	14.558744 =	5.386735
-----				
			B.T =	58.622538
4511B.1	4511B.1			
623		.370000 x	14.558744 =	5.386735
624		.300000 x	14.772860 =	4.431858
625		.450000 x	16.068735 =	7.230931
626		.050000 x	2.450778 =	.122539
527		.001786 x	2,707.004372 =	4.834710
504		.001786 x	747.908826 =	1.335765
-----				
			B.T =	23.342538
4512	4512			
509		.001622 x	534.692157 =	.867271
504		.001000 x	747.908826 =	.747909
-----				
			B.T =	1.615180
1110	1110			
503		.000455 x	1,655.865952 =	.753419
501		.000250 x	631.469576 =	.157867
-----				
			T.E =	.911286
1121	1121			
112		.005000 x	17.312112 =	.086561
501		.000083 x	631.469576 =	.052412
503		.000714 x	1,655.865952 =	1.182288
-----				
			T.E =	1.321261

1122	1122			
112		.005000 x	17.312112 =	.086561
509		.002000 x	534.692157 =	1.069384
507		.000385 x	714.655100 =	.275142
501		.000080 x	631.469576 =	.050518
505		.000316 x	1,191.559924 =	.376533
503		.000100 x	1,655.865952 =	.165587
		-----		
			T.E =	2.023724
1123.A	1123.A			
112		.005000 x	17.312112 =	.086561
503		.000500 x	1,655.865952 =	.827933
509		.001429 x	534.692157 =	.764075
507		.000769 x	714.655100 =	.549570
501		.000080 x	631.469576 =	.050518
		-----		
			T.E =	2.278656
1123.B	1123.B			
509		.000870 x	534.692157 =	.465182
		-----		
			T.E =	.465182
1131	1131			
213		1.000000 x	1.949500 =	1.949500
519		.000952 x	759.803514 =	.723333
112		.030000 x	17.312112 =	.519363
503		.000909 x	1,655.865952 =	1.505182
		-----		
			T.E =	4.697378
1132	1132			
213		1.000000 x	1.949500 =	1.949500
504		.001000 x	747.908826 =	.747909
503		.000909 x	1,655.865952 =	1.505182
112		.120000 x	17.312112 =	2.077453
519		.000952 x	759.803514 =	.723333
509		.002000 x	534.692157 =	1.069384
		-----		
			T.E =	8.072762
1133.A	1133.A			
213		1.000000 x	1.949500 =	1.949500
112		.120000 x	17.312112 =	2.077453
504		.001000 x	747.908826 =	.747909
519		.000952 x	759.803514 =	.723333
509		.001176 x	534.692157 =	.628798
503		.000909 x	1,655.865952 =	1.505182
		-----		
			T.E =	7.632175

1133.B	1133.B			
509		.000870 x	534.692157 =	.465182
		-----		
			T.E =	.465182
1140	1140			
112		.006000 x	17.312112 =	.103873
522		.000133 x	454.364331 =	.060430
501		.000050 x	631.469576 =	.031573
		-----		
			T.E =	.195877
1211	1211			
112		.200000 x	17.312112 =	3.462422
501		.001538 x	631.469576 =	.971200
507		.001538 x	714.655100 =	1.099140
		-----		
			T.E =	5.532762
1212	1212			
112		.200000 x	17.312112 =	3.462422
507		.001538 x	714.655100 =	1.099140
501		.001538 x	631.469576 =	.971200
509		.002298 x	534.692157 =	1.228723
		-----		
			T.E =	6.761485
1220	1220			
213		1.000000 x	1.949500 =	1.949500
116		.060000 x	20.419486 =	1.225169
519		.002222 x	759.803514 =	1.688283
111		.500000 x	15.741598 =	7.870799
112		.060000 x	17.312112 =	1.038727
		-----		
			T.E =	13.772478
1310	1310			
112		.070000 x	17.312112 =	1.211848
501		.000385 x	631.469576 =	.243116
		-----		
			T.E =	1.454964
1320	1320			
112		1.500000 x	17.312112 =	25.968168
		-----		
			T.E =	25.968168

1410	1410			
112		.005000 x	17.312112 =	.086561
501		.000083 x	631.469576 =	.052412
503		.000833 x	1,655.865952 =	1.379336
-----				
			T.E =	1.518309
1420	1420			
112		.006000 x	17.312112 =	.103873
509		.001826 x	534.692157 =	.976348
503		.000208 x	1,655.865952 =	.344420
501		.000050 x	631.469576 =	.031573
507		.000385 x	714.655100 =	.275142
505		.000316 x	1,191.559924 =	.376533
-----				
			T.E =	2.107889
1510	1510			
112		.007000 x	17.312112 =	.121185
509		.001429 x	534.692157 =	.764075
504		.000714 x	747.908826 =	.534007
503		.000385 x	1,655.865952 =	.637508
-----				
			T.E =	2.056775
1520	1520			
509		.000833 x	534.692157 =	.445399
-----				
			T.E =	.445399
1530	1530			
630		.150000 x	.542375 =	.081356
502		.000208 x	959.388666 =	.199553
501		.000250 x	631.469576 =	.157867
509		.000413 x	534.692157 =	.220828
522		.000556 x	454.364331 =	.252627
-----				
			T.E =	.912231
1610	1610			
111		.040000 x	15.741598 =	.629664
503		.000111 x	1,655.865952 =	.183801
507		.000118 x	714.655100 =	.084329
1122		.200000 x	2.023724 =	.404745
501		.000050 x	631.469576 =	.031573
-----				
			T.E =	1.334113

1620	1620			
112		.200000 x	17.312112 =	3.462422
1122		1.000000 x	2.023724 =	2.023724
501		.000714 x	631.469576 =	.450869
-----				
			T.E =	5.937016
2111	2111			
112		.010000 x	17.312112 =	.173121
503		.001053 x	1,655.865952 =	1.743627
507		.000667 x	714.655100 =	.476675
501		.000500 x	631.469576 =	.315735
509		.002124 x	534.692157 =	1.135686
-----				
			T.E =	3.844844
2112	2112			
213		1.000000 x	1.949500 =	1.949500
112		.250000 x	17.312112 =	4.328028
507		.000667 x	714.655100 =	.476675
519		.002041 x	759.803514 =	1.550759
509		.002124 x	534.692157 =	1.135686
503		.001613 x	1,655.865952 =	2.670912
116		.060000 x	20.419486 =	1.225169
-----				
			T.E =	13.336729
2151	2151			
213		.300000 x	1.949500 =	.584850
112		.100000 x	17.312112 =	1.731211
112		.200000 x	17.312112 =	3.462422
113		.030000 x	20.419486 =	.612585
112		.100000 x	17.312112 =	1.731211
507		.003333 x	714.655100 =	2.381945
519		.001200 x	759.803514 =	.911764
509		.002124 x	534.692157 =	1.135686
-----				
			T.E =	12.551675
2152	2152			
112		.100000 x	17.312112 =	1.731211
507		.006667 x	714.655100 =	4.764606
509		.003196 x	534.692157 =	1.708876
112		.200000 x	17.312112 =	3.462422
-----				
			T.E =	11.667115

2211	2211			
244		1.000000 x	2.590000 =	2.590000
515		.000004 x	528.486068 =	.002114
515		.000004 x	528.486068 =	.002114
509		.000051 x	534.692157 =	.027269
112		.002000 x	17.312112 =	.034624
112		.003000 x	17.312112 =	.051936
-----				
			T.E =	2.708058
2212	2212			
244		.125000 x	2.590000 =	.323750
112		.007000 x	17.312112 =	.121185
515		.000008 x	528.486068 =	.004228
509		.000051 x	534.692157 =	.027269
-----				
			T.E =	.476432
2213	2213			
236		3.000000 x	.613000 =	1.839000
517		.016667 x	1,785.245928 =	29.754694
515		.016667 x	528.486068 =	8.808277
113		.300000 x	20.419486 =	6.125846
111		.300000 x	15.741598 =	4.722479
-----				
			T.E =	51.250296
2214	2214			
111		.200000 x	15.741598 =	3.148320
515		.016667 x	528.486068 =	8.808277
113		.110000 x	20.419486 =	2.246143
111		.170000 x	15.741598 =	2.676072
113		.200000 x	20.419486 =	4.083897
-----				
			T.E =	20.962709
2251	2251			
111		.450000 x	15.741598 =	7.083719
112		.450000 x	17.312112 =	7.790450
509		.007516 x	534.692157 =	4.018746
621		1.050000 x	15.306217 =	16.071528
-----				
			T.E =	34.964444
2252	2252			
111		1.250000 x	15.741598 =	19.676998
621		1.050000 x	15.306217 =	16.071528
509		.007516 x	534.692157 =	4.018746
113		1.250000 x	20.419486 =	25.524358
-----				
			T.E =	65.291629

2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	15.306217 =	16.071528
652		.020000 x	134.350088 =	2.687002
509		.007891 x	534.692157 =	4.219256
651		.250000 x	92.951953 =	23.237988
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	124.339308
2254	2254			
111		.750000 x	15.741598 =	11.806199
652		.100000 x	134.350088 =	13.435009
113		1.450000 x	20.419486 =	29.608255
509		.002630 x	534.692157 =	1.406240
621		.350000 x	15.306217 =	5.357176
		-----		
			T.E =	61.612878
2311	2311			
243		1.020000 x	2.250000 =	2.295000
243		.080000 x	2.250000 =	.180000
		-----		
			T.E =	2.475000
2312	2312			
112		.080000 x	17.312112 =	1.384969
113		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	3.018528
2313	2313			
111		.400000 x	15.741598 =	6.296639
112		.400000 x	17.312112 =	6.924845
509		.003326 x	534.692157 =	1.778386
611		1.050000 x	22.038237 =	23.140149
		-----		
			T.E =	38.140019
2350	2350			
112		.100000 x	17.312112 =	1.731211
113		.250000 x	20.419486 =	5.104872
652		.022000 x	134.350088 =	2.955702
		-----		
			T.E =	9.791785
2411	2411			
327		.500000 x	.540000 =	.270000
113		.180000 x	20.419486 =	3.675507
		-----		
			T.E =	3.945507

2412	2412			
328		2.200000 x	1.840000 =	4.048000
113		.300000 x	20.419486 =	6.125846
2350		1.000000 x	9.791785 =	9.791785
111		.150000 x	15.741598 =	2.361240
329		2.000000 x	.730000 =	1.460000

-----  
 T.E = 23.786871

2511	2511			
221		200.000000 x	.099900 =	19.980000
113		.250000 x	20.419486 =	5.104872
623		.800000 x	14.558744 =	11.646995
625		.500000 x	16.068735 =	8.034368
630		.250000 x	.542375 =	.135594
112		.400000 x	17.312112 =	6.924845
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.016667 x	534.692157 =	8.911714
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569

-----  
 T.E = 69.614278

2512	2512			
221		250.000000 x	.099900 =	24.975000
113		.500000 x	20.419486 =	10.209743
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
625		.500000 x	16.068735 =	8.034368
641		2.000000 x	7.536243 =	15.072486
630		.250000 x	.542375 =	.135594
623		.800000 x	14.558744 =	11.646995
112		.500000 x	17.312112 =	8.656056

-----  
 T.E = 97.327906

2521	2521			
221		50.000000 x	.099900 =	4.995000
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
509		.006012 x	534.692157 =	3.214569
641		2.000000 x	7.536243 =	15.072486
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		.500000 x	20.419486 =	10.209743
112		.500000 x	17.312112 =	8.656056
221		250.000000 x	.099900 =	24.975000

T.E = 102.322906

2522	2522			
221		300.000000 x	.099900 =	29.970000
113		.800000 x	20.419486 =	16.335589
625		.500000 x	16.068735 =	8.034368
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
641		3.000000 x	7.536243 =	22.608729
630		.250000 x	.542375 =	.135594
623		.800000 x	14.558744 =	11.646995
112		.600000 x	17.312112 =	10.387267

T.E = 117.716206

2523	2523			
221		300.000000 x	.099900 =	29.970000
623		.800000 x	14.558744 =	11.646995
509		.001444 x	534.692157 =	.772095
509		.003758 x	534.692157 =	2.009373
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.018182 x	534.692157 =	9.721773
509		.006012 x	534.692157 =	3.214569
641		3.000000 x	7.536243 =	22.608729
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
113		1.050000 x	20.419486 =	21.440460
112		.750000 x	17.312112 =	12.984084

T.E = 125.417894

2524	2524			
221		300.000000 x	.099900 =	29.970000
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
641		1.300000 x	7.536243 =	9.797116
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		.800000 x	20.419486 =	16.335589
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 115.291860

2531	2531			
222		300.000000 x	.116200 =	34.860000
112		1.300000 x	17.312112 =	22.505746
113		.900000 x	20.419486 =	18.377537
630		.250000 x	.542375 =	.135594
509		.018182 x	534.692157 =	9.721773
509		.003758 x	534.692157 =	2.009373
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569
641		1.300000 x	7.536243 =	9.797116
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995

-----  
 T.E = 123.955020

2532	2532			
222		300.000000 x	.116200 =	34.860000
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
641		4.000000 x	7.536243 =	30.144972
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
112		1.600000 x	17.312112 =	27.699379
623		.800000 x	14.558744 =	11.646995
113		.900000 x	20.419486 =	18.377537
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860

-----  
 T.E = 149.496509

2533	2533			
222		300.000000 x	.116200 =	34.860000
112		1.800000 x	17.312112 =	31.161802
623		.800000 x	14.558744 =	11.646995
630		.250000 x	.542375 =	.135594
509		.001444 x	534.692157 =	.772095
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
641		8.000000 x	7.536243 =	60.289944
625		.500000 x	16.068735 =	8.034368
113		1.200000 x	20.419486 =	24.503383

-----  
 T.E = 189.229750

2541	2541			
222		300.000000 x	.116200 =	34.860000
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569
641		4.500000 x	7.536243 =	33.913094
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		1.200000 x	20.419486 =	24.503383
112		1.600000 x	17.312112 =	27.699379
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860

-----  
 T.E = 159.390477

2542	2542			
222		300.000000 x	.116200 =	34.860000
112		1.650000 x	17.312112 =	28.564985
623		.800000 x	14.558744 =	11.646995
630		.250000 x	.542375 =	.135594
509		.001444 x	534.692157 =	.772095
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
642		4.500000 x	11.607771 =	52.234970
625		.500000 x	16.068735 =	8.034368
113		1.250000 x	20.419486 =	25.524358

-----  
 T.E = 179.598933

2543	2543			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
509		.006012 x	534.692157 =	3.214569
641		5.000000 x	7.536243 =	37.681215
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
112		1.550000 x	17.312112 =	26.833774
113		1.250000 x	20.419486 =	25.524358
113		.500000 x	20.419486 =	10.209743

-----  
 T.E = 173.523710

2544	2544			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569
113		.700000 x	20.419486 =	14.293640
112		1.650000 x	17.312112 =	28.564985
625		.500000 x	16.068735 =	8.034368
642		5.000000 x	11.607771 =	58.038855
630		.250000 x	.542375 =	.135594
623		.800000 x	14.558744 =	11.646995
113		1.250000 x	20.419486 =	25.524358

-----  
 T.E = 199.696458

2545	2545			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
641		6.000000 x	7.536243 =	45.217458
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		1.900000 x	20.419486 =	38.797023
112		1.650000 x	17.312112 =	28.564985

-----  
 T.E = 185.854087

2546	2546			
222		300.000000 x	.116200 =	34.860000
112		1.850000 x	17.312112 =	32.027407
623		.800000 x	14.558744 =	11.646995
630		.250000 x	.542375 =	.135594
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
641		6.000000 x	7.536243 =	45.217458
625		.500000 x	16.068735 =	8.034368
113		1.900000 x	20.419486 =	38.797023

-----  
 T.E = 189.316509

2547	2547			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
641		5.000000 x	7.536243 =	37.681215
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
112		1.550000 x	17.312112 =	26.833774
623		.800000 x	14.558744 =	11.646995
113		1.900000 x	20.419486 =	38.797023

-----  
 T.E = 176.586633

2548	2548			
222		300.000000 x	.116200 =	34.860000
623		.800000 x	14.558744 =	11.646995
112		1.950000 x	17.312112 =	33.758618
630		.250000 x	.542375 =	.135594
509		.001444 x	534.692157 =	.772095
509		.006012 x	534.692157 =	3.214569
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.003758 x	534.692157 =	2.009373
509		.018182 x	534.692157 =	9.721773
641		5.000000 x	7.536243 =	37.681215
625		.500000 x	16.068735 =	8.034368
113		2.400000 x	20.419486 =	49.006766

-----  
 T.E = 193.721221

2551	2551			
222		360.000000 x	.116200 =	41.832000
514		.002857 x	708.783291 =	2.024994
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
641		4.500000 x	7.536243 =	33.913094
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		1.050000 x	20.419486 =	21.440460
112		1.550000 x	17.312112 =	26.833774

-----  
 T.E = 162.433948

2561	2561			
222		450.000000 x	.116200 =	52.290000
641		4.500000 x	7.536243 =	33.913094
514		.003704 x	708.783291 =	2.625333
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		2.800000 x	20.419486 =	57.174561
112		1.800000 x	17.312112 =	31.161802
111		1.250000 x	15.741598 =	19.676998

-----  
 T.E = 233.231414

2562	2562			
222		450.000000 x	.116200 =	52.290000
113		2.800000 x	20.419486 =	57.174561
514		.003704 x	708.783291 =	2.625333
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
509		.003758 x	534.692157 =	2.009373
642		4.500000 x	11.607771 =	52.234970
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
112		1.800000 x	17.312112 =	31.161802
111		1.950000 x	15.741598 =	30.696116

-----  
 T.E = 262.572408

2563	2563			
222		450.000000 x	.116200 =	52.290000
113		3.900000 x	20.419486 =	79.635995
641		5.000000 x	7.536243 =	37.681215
514		.003704 x	708.783291 =	2.625333
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		.900000 x	20.419486 =	18.377537
112		1.800000 x	17.312112 =	31.161802
111		1.950000 x	15.741598 =	30.696116

T.E = 288.857626

2564	2564			
222		450.000000 x	.116200 =	52.290000
111		1.950000 x	15.741598 =	30.696116
514		.003704 x	708.783291 =	2.625333
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
642		5.000000 x	11.607771 =	58.038855
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		.900000 x	20.419486 =	18.377537
113		3.900000 x	20.419486 =	79.635995
112		1.800000 x	17.312112 =	31.161802

T.E = 309.215266

2565	2565			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	708.783291 =	2.625333
504		.001143 x	747.908826 =	.854860
509		.006012 x	534.692157 =	3.214569
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
641		6.000000 x	7.536243 =	45.217458
112		2.350000 x	17.312112 =	40.683463
113		4.700000 x	20.419486 =	95.971584
625		.500000 x	16.068735 =	8.034368
630		.250000 x	.542375 =	.135594
623		.800000 x	14.558744 =	11.646995
111		2.350000 x	15.741598 =	36.992755

T.E = 310.170221

2566	2566			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	708.783291 =	2.625333
504		.001143 x	747.908826 =	.854860
509		.003758 x	534.692157 =	2.009373
509		.001444 x	534.692157 =	.772095
509		.018182 x	534.692157 =	9.721773
509		.006012 x	534.692157 =	3.214569
642		6.000000 x	11.607771 =	69.646626
630		.250000 x	.542375 =	.135594
625		.500000 x	16.068735 =	8.034368
623		.800000 x	14.558744 =	11.646995
113		4.700000 x	20.419486 =	95.971584
112		2.350000 x	17.312112 =	40.683463
111		2.350000 x	15.741598 =	36.992755
-----				
			T.E =	334.599389
2611	2611			
233		1.050000 x	.538600 =	.565530
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.280212
2612	2612			
238		1.050000 x	.538600 =	.565530
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.280212
2620	2620			
239		1.010000 x	7.950000 =	8.029500
113		.080000 x	20.419486 =	1.633559
113		.080000 x	20.419486 =	1.633559
239		.303000 x	7.950000 =	2.408850
-----				
			T.E =	13.705468
2651	2651			
235		1.050000 x	.633000 =	.664650
113		.100000 x	20.419486 =	2.041949
-----				
			T.E =	2.706599
2652	2652			
235		1.050000 x	.633000 =	.664650
661		.050000 x	24.137810 =	1.206891
113		.120000 x	20.419486 =	2.450338
-----				
			T.E =	4.321879

2653	2653			
241		1.050000 x	7.050000 =	7.402500
113		.800000 x	20.419486 =	16.335589
661		.120000 x	24.137810 =	2.896537
		-----		
			T.E =	26.634626
2671	2671			
237		1.000000 x	1.110000 =	1.110000
113		.015000 x	20.419486 =	.306292
		-----		
			T.E =	1.416292
2672	2672			
235		1.050000 x	.633000 =	.664650
661		.050000 x	24.137810 =	1.206891
113		.120000 x	20.419486 =	2.450338
		-----		
			T.E =	4.321879
2711	2711			
2551		1.000000 x	162.433948 =	162.433948
		-----		
			T.E =	162.433948
2712	2712			
2611		1.000000 x	1.280212 =	1.280212
		-----		
			T.E =	1.280212
2713	2713			
237		1.000000 x	1.110000 =	1.110000
113		.070000 x	20.419486 =	1.429364
		-----		
			T.E =	2.539364
2714	2714			
112		1.900000 x	17.312112 =	32.893013
516		.015385 x	869.387015 =	13.375519
517		.015385 x	1,785.245928 =	27.466009
		-----		
			T.E =	73.734541
2731	2731			
2730A		.149925 x	3,085.107661 =	462.534766
2730Γ		1.000000 x	60.459838 =	60.459838
2730B		.000667 x	41,885.499807 =	27.937628
		-----		
			T.E =	550.932232

2732	2732			
2730Α		.179910 x	3,085.107661 =	555.041719
2730Γ		1.000000 x	60.459838 =	60.459838
2730Β		.000667 x	41,885.499807 =	27.937628
-----				
			T.E =	643.439186
2733	2733			
233		1.050000 x	.538600 =	.565530
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.280212
2734	2734			
238		1.050000 x	.538600 =	.565530
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.280212
2811	2811			
112		.170000 x	17.312112 =	2.943059
509		.002217 x	534.692157 =	1.185413
501		.000500 x	631.469576 =	.315735
507		.001538 x	714.655100 =	1.099140
-----				
			T.E =	5.543346
2815	2815			
111		.250000 x	15.741598 =	3.935400
623		.400000 x	14.558744 =	5.823498
625		.700000 x	16.068735 =	11.248115
509		.003006 x	534.692157 =	1.607285
509		.005261 x	534.692157 =	2.813015
112		.350000 x	17.312112 =	6.059239
-----				
			T.E =	31.486551
2861	2861			
221		6.000000 x	.099900 =	.599400
113		.200000 x	20.419486 =	4.083897
281		1.000000 x	21.300000 =	21.300000
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	29.918697
2862	2862			
221		8.000000 x	.099900 =	.799200
111		.250000 x	15.741598 =	3.935400
113		.200000 x	20.419486 =	4.083897
282		1.000000 x	30.000000 =	30.000000
-----				
			T.E =	38.818497

2863	2863			
221		8.000000 x	.099900 =	.799200
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
283		1.000000 x	36.300000 =	36.300000
-----				
			T.E =	58.561956
2864	2864			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
284		1.000000 x	75.400000 =	75.400000
-----				
			T.E =	99.248236
2881	2881			
221		6.000000 x	.099900 =	.599400
261		1.000000 x	15.100000 =	15.100000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	23.718697
2882	2882			
221		8.000000 x	.099900 =	.799200
262		1.000000 x	26.300000 =	26.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	35.118497
2883	2883			
221		10.000000 x	.099900 =	.999000
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
263		1.000000 x	32.400000 =	32.400000
-----				
			T.E =	54.861756
2884	2884			
221		16.000000 x	.099900 =	1.598400
264		1.000000 x	64.100000 =	64.100000
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
-----				
			T.E =	87.948236

2885	2885			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		1.000000 x	15.741598 =	15.741598
113		.750000 x	20.419486 =	15.314615
-----				
			T.E =	148.154213
2888	2888			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.100000 x	20.419486 =	22.461435
111		1.400000 x	15.741598 =	22.038237
-----				
			T.E =	253.397072
2911	2911			
351		1.050000 x	745.000000 =	782.250000
113		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	884.347430
2912	2912			
352		1.050000 x	1,010.000000 =	1,060.500000
113		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	1,162.597430
2921	2921			
301		1.000000 x	4.060000 =	4.060000
113		.250000 x	20.419486 =	5.104872
652		.002000 x	134.350088 =	.268700
2522		.005000 x	117.716206 =	.588581
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	13.957552
2922	2922			
302		1.020000 x	6.700000 =	6.834000
113		.600000 x	20.419486 =	12.251692
111		.350000 x	15.741598 =	5.509559
652		.015000 x	134.350088 =	2.015251
-----				
			T.E =	26.610502
2951	2951			
512A		.150000 x	108.975682 =	16.346352
-----				
			T.E =	16.346352

2952	2952			
512B		.150000 x	155.205568 =	23.280835
-----				
			T.E =	23.280835
2953	2953			
513A		.150000 x	210.678072 =	31.601711
-----				
			T.E =	31.601711
2954	2954			
513B		.150000 x	271.725354 =	40.758803
-----				
			T.E =	40.758803
3111A	3111A			
112		.020000 x	17.312112 =	.346242
501		.000182 x	631.469576 =	.114927
522		.000263 x	454.364331 =	.119498
509		.000072 x	534.692157 =	.038498
614		.135000 x	10.905022 =	1.472178
509		.000193 x	534.692157 =	.103196
630		.020000 x	.542375 =	.010848
-----				
			T.E =	2.205386
3111B	3111B			
112		.020000 x	17.312112 =	.346242
509		.000193 x	534.692157 =	.103196
501		.000182 x	631.469576 =	.114927
509		.000072 x	534.692157 =	.038498
522		.000263 x	454.364331 =	.119498
630		.020000 x	.542375 =	.010848
622		.135000 x	14.772860 =	1.994336
-----				
			T.E =	2.727545
3112	3112			
509		.000094 x	534.692157 =	.050261
-----				
			T.E =	.050261
3121A	3121A			
112		.200000 x	17.312112 =	3.462422
522		.002632 x	454.364331 =	1.195887
509		.000722 x	534.692157 =	.386048
614		1.350000 x	10.905022 =	14.721780
501		.001818 x	631.469576 =	1.148012
509		.001929 x	534.692157 =	1.031421
630		.200000 x	.542375 =	.108475
-----				
			T.E =	22.054045

3121B	3121B			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	631.469576 =	1.148012
509		.000722 x	534.692157 =	.386048
509		.001929 x	534.692157 =	1.031421
522		.002632 x	454.364331 =	1.195887
630		.200000 x	.542375 =	.108475
622		1.350000 x	14.772860 =	19.943361
		-----		
			T.E =	27.275626
3122	3122			
509		.000940 x	534.692157 =	.502611
		-----		
			T.E =	.502611
3211A	3211A			
112		.025000 x	17.312112 =	.432803
509		.000072 x	534.692157 =	.038498
501		.000182 x	631.469576 =	.114927
614		.135000 x	10.905022 =	1.472178
509		.000193 x	534.692157 =	.103196
522		.000263 x	454.364331 =	.119498
630		.020000 x	.542375 =	.010848
		-----		
			T.E =	2.291947
3211B	3211B			
112		.025000 x	17.312112 =	.432803
501		.000182 x	631.469576 =	.114927
509		.000193 x	534.692157 =	.103196
509		.000072 x	534.692157 =	.038498
630		.020000 x	.542375 =	.010848
522		.000263 x	454.364331 =	.119498
622		.135000 x	14.772860 =	1.994336
		-----		
			T.E =	2.814105
3212	3212			
509		.000141 x	534.692157 =	.075392
		-----		
			T.E =	.075392

3221	3221			
622		.202500 x	14.772860 =	2.991504
501		.000250 x	631.469576 =	.157867
509		.000250 x	534.692157 =	.133673
509		.000469 x	534.692157 =	.250771
509		.000286 x	534.692157 =	.152922
509		.000250 x	534.692157 =	.133673
522		.000500 x	454.364331 =	.227182
630		.100000 x	.542375 =	.054238
		-----		
			T.E =	4.101830
3222	3222			
221		1.000000 x	.099900 =	.099900
		-----		
			T.E =	.099900
3223	3223			
509		.000141 x	534.692157 =	.075392
		-----		
			T.E =	.075392
3231	3231			
112		.025000 x	17.312112 =	.432803
522		.000286 x	454.364331 =	.129948
630		.015000 x	.542375 =	.008136
509		.000054 x	534.692157 =	.028873
501		.000213 x	631.469576 =	.134503
		-----		
			T.E =	.734263
3232A	3232A			
630		.200000 x	.542375 =	.108475
509		.001929 x	534.692157 =	1.031421
614		1.350000 x	10.905022 =	14.721780
		-----		
			T.E =	15.861676
3232B	3232B			
622		1.350000 x	14.772860 =	19.943361
630		.200000 x	.542375 =	.108475
509		.001929 x	534.692157 =	1.031421
		-----		
			T.E =	21.083257
3233	3233			
509		.000940 x	534.692157 =	.502611
		-----		
			T.E =	.502611

3241A	3241A			
112		.025000 x	17.312112 =	.432803
509		.000193 x	534.692157 =	.103196
501		.000213 x	631.469576 =	.134503
614		.135000 x	10.905022 =	1.472178
509		.000072 x	534.692157 =	.038498
630		.020000 x	.542375 =	.010848
522		.000286 x	454.364331 =	.129948
			T.E =	2.321973
3241B	3241B			
112		.025000 x	17.312112 =	.432803
501		.000213 x	631.469576 =	.134503
509		.000072 x	534.692157 =	.038498
522		.000286 x	454.364331 =	.129948
630		.020000 x	.542375 =	.010848
622		.135000 x	14.772860 =	1.994336
509		.000193 x	534.692157 =	.103196
			T.E =	2.844131
3242	3242			
509		.000094 x	534.692157 =	.050261
			T.E =	.050261
3311A	3311A			
112		.025000 x	17.312112 =	.432803
522		.000286 x	454.364331 =	.129948
509		.000072 x	534.692157 =	.038498
614		.135000 x	10.905022 =	1.472178
501		.000213 x	631.469576 =	.134503
509		.000193 x	534.692157 =	.103196
630		.020000 x	.542375 =	.010848
			T.E =	2.321973
3311B	3311B			
112		.025000 x	17.312112 =	.432803
501		.000213 x	631.469576 =	.134503
509		.000072 x	534.692157 =	.038498
509		.000193 x	534.692157 =	.103196
522		.000286 x	454.364331 =	.129948
630		.020000 x	.542375 =	.010848
622		.135000 x	14.772860 =	1.994336
			T.E =	2.844131

3312	3312			
509		.000094 x	534.692157 =	.050261
-----				
			T.E =	.050261
3321A	3321A			
112		.030000 x	17.312112 =	.519363
509		.000072 x	534.692157 =	.038498
501		.000213 x	631.469576 =	.134503
614		.135000 x	10.905022 =	1.472178
509		.000193 x	534.692157 =	.103196
522		.000286 x	454.364331 =	.129948
630		.020000 x	.542375 =	.010848
-----				
			T.E =	2.408533
3321B	3321B			
112		.030000 x	17.312112 =	.519363
501		.000213 x	631.469576 =	.134503
509		.000072 x	534.692157 =	.038498
509		.000193 x	534.692157 =	.103196
630		.020000 x	.542375 =	.010848
522		.000286 x	454.364331 =	.129948
622		.135000 x	14.772860 =	1.994336
-----				
			T.E =	2.930692
3322	3322			
509		.000094 x	534.692157 =	.050261
-----				
			T.E =	.050261
3401	3401			
111		1.300000 x	15.741598 =	20.464077
509		.000361 x	534.692157 =	.193024
521		.014286 x	331.822752 =	4.740420
630		.100000 x	.542375 =	.054238
112		.900000 x	17.312112 =	15.580901
-----				
			T.E =	41.032659
3402A	3402A			
509		.001929 x	534.692157 =	1.031421
614		1.350000 x	10.905022 =	14.721780
-----				
			T.E =	15.753201
3402B	3402B			
622		1.350000 x	14.772860 =	19.943361
509		.001929 x	534.692157 =	1.031421
-----				
			T.E =	20.974782

3403	3403			
509		.000940 x	534.692157 =	.502611
-----				
			T.E =	.502611
4110	4110			
112		.008000 x	17.312112 =	.138497
671		1.200000 x	.733327 =	.879992
523		.000143 x	354.757612 =	.050730
526		.000100 x	549.867771 =	.054987
-----				
			T.E =	1.124206
4110.1	4110.1			
112		.008000 x	17.312112 =	.138497
671.1		1.200000 x	.517727 =	.621272
523		.000143 x	354.757612 =	.050730
526		.000100 x	549.867771 =	.054987
-----				
			T.E =	.865486
4120	4120			
321		.500000 x	.392000 =	.196000
112		.006000 x	17.312112 =	.103873
523		.000143 x	354.757612 =	.050730
526		.000100 x	549.867771 =	.054987
525		.000067 x	247.104294 =	.016556
-----				
			T.E =	.422146
4120.1	4120.1			
112		.006000 x	17.312112 =	.103873
523		.000143 x	354.757612 =	.050730
525		.000067 x	247.104294 =	.016556
526		.000100 x	549.867771 =	.054987
-----				
			T.E =	.226146
4131A	4131A			
321		1.000000 x	.392000 =	.392000
616		.015000 x	10.905022 =	.163575
525		.000067 x	247.104294 =	.016556
526		.000143 x	549.867771 =	.078631
523		.000143 x	354.757612 =	.050730
504		.000143 x	747.908826 =	.106951
509		.000014 x	534.692157 =	.007486
509		.000028 x	534.692157 =	.014971
509		.000143 x	534.692157 =	.076461
522		.000143 x	454.364331 =	.064974
112		.008000 x	17.312112 =	.138497
-----				
			T.E =	1.110833

4131A.1	4131A.1			
112		.008000 x	17.312112 =	.138497
522		.000143 x	454.364331 =	.064974
509		.000028 x	534.692157 =	.014971
616		.015000 x	10.905022 =	.163575
525		.000067 x	247.104294 =	.016556
526		.000143 x	549.867771 =	.078631
523		.000143 x	354.757612 =	.050730
504		.000143 x	747.908826 =	.106951
509		.000014 x	534.692157 =	.007486
509		.000143 x	534.692157 =	.076461

T.E = .718833

4131B	4131B			
321		1.000000 x	.392000 =	.392000
522		.000143 x	454.364331 =	.064974
509		.000028 x	534.692157 =	.014971
523		.000143 x	354.757612 =	.050730
525		.000067 x	247.104294 =	.016556
526		.000143 x	549.867771 =	.078631
504		.000143 x	747.908826 =	.106951
509		.000143 x	534.692157 =	.076461
509		.000014 x	534.692157 =	.007486
112		.008000 x	17.312112 =	.138497
624		.015000 x	14.772860 =	.221593

T.E = 1.168850

4131B.1	4131B.1			
112		.008000 x	17.312112 =	.138497
624		.015000 x	14.772860 =	.221593
522		.000143 x	454.364331 =	.064974
525		.000067 x	247.104294 =	.016556
526		.000143 x	549.867771 =	.078631
523		.000143 x	354.757612 =	.050730
504		.000143 x	747.908826 =	.106951
509		.000143 x	534.692157 =	.076461
509		.000028 x	534.692157 =	.014971
509		.000014 x	534.692157 =	.007486

T.E = .776850

4132	4132			
509		.000009 x	534.692157 =	.004812

T.E = .004812

4141A	4141A			
112		.013000 x	17.312112 =	.225057
671		1.200000 x	.733327 =	.879992
509		.000038 x	534.692157 =	.020318
509		.000244 x	534.692157 =	.130465
616		.012000 x	10.905022 =	.130860
615		.015000 x	10.905022 =	.163575
526		.000244 x	549.867771 =	.134168
523		.000143 x	354.757612 =	.050730
504		.000244 x	747.908826 =	.182490
509		.000024 x	534.692157 =	.012833
672		1.500000 x	.479144 =	.718716
522		.000244 x	454.364331 =	.110865

T.E = 2.760070

4141A.1	4141A.1			
112		.013000 x	17.312112 =	.225057
509		.000024 x	534.692157 =	.012833
616		.012000 x	10.905022 =	.130860
615		.015000 x	10.905022 =	.163575
526		.000244 x	549.867771 =	.134168
523		.000143 x	354.757612 =	.050730
504		.000244 x	747.908826 =	.182490
509		.000244 x	534.692157 =	.130465
509		.000038 x	534.692157 =	.020318
671.1		1.200000 x	.517727 =	.621272
522		.000244 x	454.364331 =	.110865
672.1		1.500000 x	.110664 =	.165996

T.E = 1.948630

4141B	4141B			
112		.013000 x	17.312112 =	.225057
526		.000244 x	549.867771 =	.134168
523		.000143 x	354.757612 =	.050730
504		.000244 x	747.908826 =	.182490
509		.000244 x	534.692157 =	.130465
509		.000024 x	534.692157 =	.012833
509		.000038 x	534.692157 =	.020318
522		.000244 x	454.364331 =	.110865
672		1.500000 x	.479144 =	.718716
671		1.200000 x	.733327 =	.879992
624		.012000 x	14.772860 =	.177274
623		.015000 x	14.558744 =	.218381

T.E = 2.861290

4141B.1	4141B.1			
112		.013000 x	17.312112 =	.225057
672.1		1.500000 x	.110664 =	.165996
522		.000244 x	454.364331 =	.110865
526		.000244 x	549.867771 =	.134168
523		.000143 x	354.757612 =	.050730
504		.000244 x	747.908826 =	.182490
509		.000244 x	534.692157 =	.130465
509		.000024 x	534.692157 =	.012833
509		.000038 x	534.692157 =	.020318
671.1		1.200000 x	.517727 =	.621272
623		.015000 x	14.558744 =	.218381
624		.012000 x	14.772860 =	.177274
-----				
			T.E =	2.049850
4142	4142			
509		.000017 x	534.692157 =	.009090
-----				
			T.E =	.009090
4211A	4211A			
672		25.000000 x	.479144 =	11.978600
509		.001429 x	534.692157 =	.764075
615		.700000 x	10.905022 =	7.633515
501		.007024 x	631.469576 =	4.435442
616		.300000 x	10.905022 =	3.271507
526		.002857 x	549.867771 =	1.570972
522		.003846 x	454.364331 =	1.747485
-----				
			T.E =	31.401597
4211A.1	4211A.1			
672.1		25.000000 x	.110664 =	2.766600
509		.001429 x	534.692157 =	.764075
522		.003846 x	454.364331 =	1.747485
615		.700000 x	10.905022 =	7.633515
501		.007024 x	631.469576 =	4.435442
616		.300000 x	10.905022 =	3.271507
526		.002857 x	549.867771 =	1.570972
-----				
			T.E =	22.189597
4211B	4211B			
623		.700000 x	14.558744 =	10.191121
624		.300000 x	14.772860 =	4.431858
501		.007024 x	631.469576 =	4.435442
526		.002857 x	549.867771 =	1.570972
509		.001429 x	534.692157 =	.764075
522		.003846 x	454.364331 =	1.747485
672		25.000000 x	.479144 =	11.978600
-----				
			T.E =	35.119554

4211B.1	4211B.1			
623		.700000 x	14.558744 =	10.191121
522		.003846 x	454.364331 =	1.747485
509		.001429 x	534.692157 =	.764075
526		.002857 x	549.867771 =	1.570972
501		.007024 x	631.469576 =	4.435442
672.1		25.000000 x	.110664 =	2.766600
624		.300000 x	14.772860 =	4.431858
-----				
			T.E =	25.907554
4212	4212			
509		.000614 x	534.692157 =	.328301
-----				
			T.E =	.328301
4221A	4221A			
672		37.000000 x	.479144 =	17.728328
501		.008226 x	631.469576 =	5.194469
616		.400000 x	10.905022 =	4.362009
615		.600000 x	10.905022 =	6.543013
522		.004348 x	454.364331 =	1.975576
526		.004000 x	549.867771 =	2.199471
509		.001429 x	534.692157 =	.764075
-----				
			T.E =	38.766941
4221A.1	4221A.1			
672.1		37.000000 x	.110664 =	4.094568
501		.008226 x	631.469576 =	5.194469
616		.400000 x	10.905022 =	4.362009
615		.600000 x	10.905022 =	6.543013
526		.004000 x	549.867771 =	2.199471
509		.001429 x	534.692157 =	.764075
522		.004348 x	454.364331 =	1.975576
-----				
			T.E =	25.133181
4221B	4221B			
623		.600000 x	14.558744 =	8.735246
672		37.000000 x	.479144 =	17.728328
624		.400000 x	14.772860 =	5.909144
522		.004348 x	454.364331 =	1.975576
509		.001429 x	534.692157 =	.764075
501		.008226 x	631.469576 =	5.194469
526		.004000 x	549.867771 =	2.199471
-----				
			T.E =	42.506309

4221B.1	4221B.1			
623		.600000 x	14.558744 =	8.735246
672.1		37.000000 x	.110664 =	4.094568
624		.400000 x	14.772860 =	5.909144
501		.008226 x	631.469576 =	5.194469
526		.004000 x	549.867771 =	2.199471
509		.001429 x	534.692157 =	.764075
522		.004348 x	454.364331 =	1.975576
-----				
			T.E =	28.872549
4222	4222			
509		.000614 x	534.692157 =	.328301
-----				
			T.E =	.328301
4231A	4231A			
112		.005000 x	17.312112 =	.086561
112		.030000 x	17.312112 =	.519363
616		.006000 x	10.905022 =	.065430
615		.025000 x	10.905022 =	.272626
526		.000222 x	549.867771 =	.122071
523		.000143 x	354.757612 =	.050730
509		.000357 x	534.692157 =	.190885
509		.000036 x	534.692157 =	.019249
509		.000044 x	534.692157 =	.023526
522		.000357 x	454.364331 =	.162208
672		2.500000 x	.479144 =	1.197860
-----				
			T.E =	2.710509
4231A.1	4231A.1			
112		.005000 x	17.312112 =	.086561
522		.000357 x	454.364331 =	.162208
672.1		2.500000 x	.110664 =	.276660
112		.030000 x	17.312112 =	.519363
616		.006000 x	10.905022 =	.065430
615		.025000 x	10.905022 =	.272626
526		.000222 x	549.867771 =	.122071
523		.000143 x	354.757612 =	.050730
509		.000036 x	534.692157 =	.019249
509		.000044 x	534.692157 =	.023526
509		.000357 x	534.692157 =	.190885
-----				
			T.E =	1.789309

4231B	4231B			
112		.005000 x	17.312112 =	.086561
672		2.500000 x	.479144 =	1.197860
509		.000036 x	534.692157 =	.019249
523		.000143 x	354.757612 =	.050730
526		.000222 x	549.867771 =	.122071
509		.000357 x	534.692157 =	.190885
509		.000044 x	534.692157 =	.023526
112		.030000 x	17.312112 =	.519363
623		.025000 x	14.558744 =	.363969
522		.000357 x	454.364331 =	.162208
624		.006000 x	14.772860 =	.088637

T.E = 2.825059

4231B.1	4231B.1			
112		.005000 x	17.312112 =	.086561
112		.030000 x	17.312112 =	.519363
526		.000222 x	549.867771 =	.122071
523		.000143 x	354.757612 =	.050730
509		.000357 x	534.692157 =	.190885
509		.000036 x	534.692157 =	.019249
509		.000044 x	534.692157 =	.023526
522		.000357 x	454.364331 =	.162208
672.1		2.500000 x	.110664 =	.276660
624		.006000 x	14.772860 =	.088637
623		.025000 x	14.558744 =	.363969

T.E = 1.903859

4232	4232			
509		.000024 x	534.692157 =	.012833

T.E = .012833

4321A	4321A			
521		.000128 x	331.822752 =	.042473
522		.000128 x	454.364331 =	.058159
528		.000128 x	854.808460 =	.109415
4311A		.071000 x	51.854228 =	3.681650
4312		.071000 x	1.615180 =	.114678
523		.000143 x	354.757612 =	.050730
509		.000101 x	534.692157 =	.054004

T.E = 4.111110

4321A.1	4321A.1			
521		.000128 x	331.822752 =	.042473
523		.000143 x	354.757612 =	.050730
4312		.071000 x	1.615180 =	.114678
4311A.1		.071000 x	20.494228 =	1.455090
528		.000128 x	854.808460 =	.109415
522		.000128 x	454.364331 =	.058159
509		.000101 x	534.692157 =	.054004
-----				
			T.E =	1.884550
4321B	4321B			
521		.000128 x	331.822752 =	.042473
4312		.071000 x	1.615180 =	.114678
4311B		.071000 x	53.979673 =	3.832557
528		.000128 x	854.808460 =	.109415
523		.000143 x	354.757612 =	.050730
522		.000128 x	454.364331 =	.058159
509		.000101 x	534.692157 =	.054004
-----				
			T.E =	4.262016
4321B.1	4321B.1			
521		.000128 x	331.822752 =	.042473
4312		.071000 x	1.615180 =	.114678
4311B.1		.071000 x	22.619673 =	1.605997
528		.000128 x	854.808460 =	.109415
523		.000143 x	354.757612 =	.050730
509		.000101 x	534.692157 =	.054004
522		.000128 x	454.364331 =	.058159
-----				
			T.E =	2.035456
4322	4322			
509		.000049 x	534.692157 =	.026200
-----				
			T.E =	.026200
4421A	4421A			
521		.000128 x	331.822752 =	.042473
522		.000128 x	454.364331 =	.058159
4312		.071000 x	1.615180 =	.114678
4411A		.071000 x	51.854228 =	3.681650
528		.000128 x	854.808460 =	.109415
523		.000143 x	354.757612 =	.050730
509		.000101 x	534.692157 =	.054004
-----				
			T.E =	4.111110

4421A.1	4421A.1				
521		.000128 x	331.822752 =		.042473
522		.000128 x	454.364331 =		.058159
4412		.071000 x	1.615180 =		.114678
4411A.1		.071000 x	20.494228 =		1.455090
528		.000128 x	854.808460 =		.109415
523		.000143 x	354.757612 =		.050730
509		.000101 x	534.692157 =		.054004
-----					
			T.E =		1.884550
4421B	4421B				
521		.000128 x	331.822752 =		.042473
509		.000101 x	534.692157 =		.054004
523		.000143 x	354.757612 =		.050730
4411B		.071000 x	53.979673 =		3.832557
4412		.071000 x	1.615180 =		.114678
528		.000128 x	854.808460 =		.109415
522		.000128 x	454.364331 =		.058159
-----					
			T.E =		4.262016
4421B.1	4421B.1				
521		.000128 x	331.822752 =		.042473
522		.000128 x	454.364331 =		.058159
4412		.071000 x	1.615180 =		.114678
4411B.1		.071000 x	22.619673 =		1.605997
528		.000128 x	854.808460 =		.109415
523		.000143 x	354.757612 =		.050730
509		.000101 x	534.692157 =		.054004
-----					
			T.E =		2.035456
4422	4422				
509		.000049 x	534.692157 =		.026200
-----					
			T.E =		.026200
4521A	4521A				
521		.000128 x	331.822752 =		.042473
522		.000128 x	454.364331 =		.058159
528		.000128 x	854.808460 =		.109415
4511A		.071000 x	56.110309 =		3.983832
4512		.071000 x	1.615180 =		.114678
523		.000143 x	354.757612 =		.050730
509		.000101 x	534.692157 =		.054004
-----					
			T.E =		4.413291

4521A.1	4521A.1			
521		.000128 x	331.822752 =	.042473
523		.000143 x	354.757612 =	.050730
4512		.071000 x	1.615180 =	.114678
4511A.1		.071000 x	20.830309 =	1.478952
528		.000128 x	854.808460 =	.109415
522		.000128 x	454.364331 =	.058159
509		.000101 x	534.692157 =	.054004
-----				
			T.E =	1.908411
4521B	4521B			
521		.000128 x	331.822752 =	.042473
4512		.071000 x	1.615180 =	.114678
4511B		.071000 x	58.622538 =	4.162200
528		.000128 x	854.808460 =	.109415
523		.000143 x	354.757612 =	.050730
522		.000128 x	454.364331 =	.058159
509		.000101 x	534.692157 =	.054004
-----				
			T.E =	4.591660
4521B.1	4521B.1			
521		.000128 x	331.822752 =	.042473
4512		.071000 x	1.615180 =	.114678
4511B.1		.071000 x	23.342538 =	1.657320
528		.000128 x	854.808460 =	.109415
523		.000143 x	354.757612 =	.050730
509		.000101 x	534.692157 =	.054004
522		.000128 x	454.364331 =	.058159
-----				
			T.E =	2.086780
4522	4522			
509		.000049 x	534.692157 =	.026200
-----				
			T.E =	.026200
4611.1	4611.1			
326		45.000000 x	1.310000 =	58.950000
617		.013000 x	5.534013 =	.071942
4120.1		1.000000 x	.226146 =	.226146
529		.002857 x	715.832289 =	2.045133
525		.000286 x	247.104294 =	.070672
509		.000046 x	534.692157 =	.024596
522		.000667 x	454.364331 =	.303061
113		.100000 x	20.419486 =	2.041949
623		.033000 x	14.558744 =	.480439
-----				
			T.E =	64.213937

4611A	4611A			
321		3.000000 x	.392000 =	1.176000
509		.000046 x	534.692157 =	.024596
4120		1.000000 x	.422146 =	.422146
529		.002857 x	715.832289 =	2.045133
525		.000286 x	247.104294 =	.070672
522		.000667 x	454.364331 =	.303061
617		.013000 x	5.534013 =	.071942
623		.033000 x	14.558744 =	.480439
113		.100000 x	20.419486 =	2.041949
326		45.000000 x	1.310000 =	58.950000

-----  
 T.E = 65.585937

4612	4612			
509		.000040 x	534.692157 =	.021388

-----  
 T.E = .021388

4710A	4710A			
111		1.900000 x	15.741598 =	29.909036
613		1.000000 x	6.245553 =	6.245553
509		.000361 x	534.692157 =	.193024
509		.005305 x	534.692157 =	2.836542
630		.200000 x	.542375 =	.108475
112		1.200000 x	17.312112 =	20.774534
112		2.400000 x	17.312112 =	41.549069

-----  
 T.E = 101.616233

4710A.1	4710A.1			
111		1.900000 x	15.741598 =	29.909036
614		1.000000 x	10.905022 =	10.905022
509		.000361 x	534.692157 =	.193024
630		.200000 x	.542375 =	.108475
112		2.400000 x	17.312112 =	41.549069
509		.005305 x	534.692157 =	2.836542
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 106.275702

4710B	4710B			
111		1.900000 x	15.741598 =	29.909036
112		2.400000 x	17.312112 =	41.549069
509		.000361 x	534.692157 =	.193024
509		.005305 x	534.692157 =	2.836542
630		.200000 x	.542375 =	.108475
622		1.000000 x	14.772860 =	14.772860
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 110.143540

4720A	4720A			
111		1.900000 x	15.741598 =	29.909036
4512		1.000000 x	1.615180 =	1.615180
4522		140.000000 x	.026200 =	3.668000
4511B		1.000000 x	58.622538 =	58.622538
671		20.000000 x	.733327 =	14.666540
112		2.400000 x	17.312112 =	41.549069
112		2.000000 x	17.312112 =	34.624224
111		1.000000 x	15.741598 =	15.741598

-----  
 T.E = 200.396185

4720A.1	4720A.1			
111		1.900000 x	15.741598 =	29.909036
111		1.000000 x	15.741598 =	15.741598
4522		140.000000 x	.026200 =	3.668000
4512		1.000000 x	1.615180 =	1.615180
4511B.1		1.000000 x	23.342538 =	23.342538
671.1		20.000000 x	.517727 =	10.354540
112		2.000000 x	17.312112 =	34.624224
112		2.400000 x	17.312112 =	41.549069

-----  
 T.E = 160.804185

4800	4800			
325		1.000000 x	2.780000 =	2.780000
112		.010000 x	17.312112 =	.173121

-----  
 T.E = 2.953121