

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

2ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021		2.670000
029		.149900
051		15.400000
111	Κατχ Τιμή X 1.8117/ 6.46	15.951934
112	Κατχ Τιμή X 1.8117/ 6.46	17.729980
113	Κατχ Τιμή X 1.8117/ 6.46	23.479183
114	Κατχ Τιμή X 1.8117/ 6.67	22.739959
115	Κατχ Τιμή X 1.8117/ 6.67	18.893831
116	Κατχ Τιμή X 1.8117/ 6.46	22.893045
117	Κατχ Τιμή X 1.8117/ 6.67	18.893831
118	Κατχ Τιμή X 1.8117/ 6.67	17.283129
150		.074800
211		.779800
212		.829400
213		1.800000
214		3.800000
221		.097700
224		.070000
231		.650000
241		6.240000
242		5.000000
251		290.000000
252		210.000000
301		4.060000
302		6.700000
360		10.700000
361		27.500000
362		5.250000
363		.580000
364		3.520000
365		22.500000
366		20.630000
367		.112600
368		20.000000
369		12.150000
370		8.000000
371		7.200000
372		1.270000
373		2.040000
374		2.750000
375		1.500000
376		
377		3.190000
378		.540000
379		14.000000
380		.260000
401		254.090000
402		367.070000
403		99.790000
404		201.370000
405		199.590000
406		309.910000
407		52.260000
408		4.290000
409		119.340000
410		110.310000
411		25.900000
412		2.830000
417		127.340000

420
428
450
451
452
453
454
455

92.090000
422.740000
108.970000
151.020000
92.540000
85.880000
116.090000
409.860000

501	501			
211		50.000000 x	.779800 =	38.990000
214		3.000000 x	3.800000 =	11.400000
401		1.000000 x	254.090000 =	254.090000
118		3.000000 x	17.283129 =	51.849387
114		8.000000 x	22.739959 =	181.919672

			ΑΘΡΟΙΣΜΑ =	538.249059

			Η.Δ. =	592.073965
502	502			
211		80.000000 x	.779800 =	62.384000
114		8.000000 x	22.739959 =	181.919672
402		1.000000 x	367.070000 =	367.070000
214		7.000000 x	3.800000 =	26.600000
118		4.000000 x	17.283129 =	69.132516

			ΑΘΡΟΙΣΜΑ =	707.106188

			Η.Δ. =	777.816807
503	503			
211		110.000000 x	.779800 =	85.778000
428		1.000000 x	422.740000 =	422.740000
214		10.000000 x	3.800000 =	38.000000
118		4.000000 x	17.283129 =	69.132516
114		8.000000 x	22.739959 =	181.919672

			ΑΘΡΟΙΣΜΑ =	797.570188

			Η.Δ. =	877.327207
504	504			
211		40.000000 x	.779800 =	31.192000
214		2.000000 x	3.800000 =	7.600000
114		8.000000 x	22.739959 =	181.919672
403		1.000000 x	99.790000 =	99.790000

			ΑΘΡΟΙΣΜΑ =	320.501672

			Η.Δ. =	352.551839
505	505			
211		200.000000 x	.779800 =	155.960000
214		10.000000 x	3.800000 =	38.000000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032
404		1.000000 x	201.370000 =	201.370000

			ΑΘΡΟΙΣΜΑ =	715.514704

			Η.Δ. =	787.066174

506	506			
211		95.000000 x	.779800 =	74.081000
214		6.000000 x	3.800000 =	22.800000
405		1.000000 x	199.590000 =	199.590000
242		2.500000 x	5.000000 =	12.500000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672

			ΑΘΡΟΙΣΜΑ =	629.155704

			Η.Δ. =	692.071274
507	507			
211		165.000000 x	.779800 =	128.667000
214		10.000000 x	3.800000 =	38.000000
242		7.000000 x	5.000000 =	35.000000
406		1.000000 x	309.910000 =	309.910000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032

			ΑΘΡΟΙΣΜΑ =	831.761704

			Η.Δ. =	914.937874
508	508			
211		40.000000 x	.779800 =	31.192000
407		1.000000 x	52.260000 =	52.260000
115		4.000000 x	18.893831 =	75.575324
116		16.000000 x	22.893045 =	366.288720
408		2.000000 x	4.290000 =	8.580000
214		2.000000 x	3.800000 =	7.600000

			ΑΘΡΟΙΣΜΑ =	541.496044

			Η.Δ. =	595.645648
509	509			
211		80.000000 x	.779800 =	62.384000
117		8.000000 x	18.893831 =	151.150648
409		1.000000 x	119.340000 =	119.340000
214		5.000000 x	3.800000 =	19.000000

			ΑΘΡΟΙΣΜΑ =	351.874648

			Η.Δ. =	387.062113
510	510			
211		80.000000 x	.779800 =	62.384000
117		8.000000 x	18.893831 =	151.150648
214		5.000000 x	3.800000 =	19.000000
410		1.000000 x	110.310000 =	110.310000

			ΑΘΡΟΙΣΜΑ =	342.844648

			Η.Δ. =	377.129113

511	511			
212		17.000000 x	.829400 =	14.099800
411		1.000000 x	25.900000 =	25.900000
214		1.000000 x	3.800000 =	3.800000
115		4.000000 x	18.893831 =	75.575324
112		30.000000 x	17.729980 =	531.899400

			ΑΘΡΟΙΣΜΑ =	651.274524

			Η.Δ. =	716.401976
512	512			
211		10.000000 x	.779800 =	7.798000
115		2.000000 x	18.893831 =	37.787662
214		1.000000 x	3.800000 =	3.800000
112		2.000000 x	17.729980 =	35.459960
412		1.000000 x	2.830000 =	2.830000

			ΑΘΡΟΙΣΜΑ =	87.675622

			Η.Δ. =	96.443184
518	518			
211		180.000000 x	.779800 =	140.364000
212		5.000000 x	.829400 =	4.147000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
112		8.000000 x	17.729980 =	141.839840
417		1.000000 x	127.340000 =	127.340000
214		12.000000 x	3.800000 =	45.600000

			ΑΘΡΟΙΣΜΑ =	779.475544

			Η.Δ. =	857.423098
521	521			
211		40.000000 x	.779800 =	31.192000
118		4.000000 x	17.283129 =	69.132516
114		8.000000 x	22.739959 =	181.919672
214		3.000000 x	3.800000 =	11.400000
420		1.000000 x	92.090000 =	92.090000

			ΑΘΡΟΙΣΜΑ =	385.734188

			Η.Δ. =	424.307607
550	550			
211		80.000000 x	.779800 =	62.384000
214		5.000000 x	3.800000 =	19.000000
117		8.000000 x	18.893831 =	151.150648
450		1.000000 x	108.970000 =	108.970000

			ΑΘΡΟΙΣΜΑ =	341.504648

			Η.Δ. =	375.655113

560	560			
211		80.000000 x	.779800 =	62.384000
117		8.000000 x	18.893831 =	151.150648
455		1.000000 x	409.860000 =	409.860000
214		7.000000 x	3.800000 =	26.600000

			ΑΘΡΟΙΣΜΑ =	649.994648

			Η.Δ. =	714.994113
621	621			
213		.100000 x	1.800000 =	.180000
508		.005000 x	595.645648 =	2.978228
116		.200000 x	22.893045 =	4.578609
111		.800000 x	15.951934 =	12.761547

			B.T =	20.498384
623	623			
213		.100000 x	1.800000 =	.180000
508		.005000 x	595.645648 =	2.978228
504		.005000 x	352.551839 =	1.762759
116		.200000 x	22.893045 =	4.578609
112		.100000 x	17.729980 =	1.772998
518		.010000 x	857.423098 =	8.574231
509		.005000 x	387.062113 =	1.935311

			B.T =	21.782136
625	625			
213		.100000 x	1.800000 =	.180000
116		.200000 x	22.893045 =	4.578609
112		.100000 x	17.729980 =	1.772998
504		.005000 x	352.551839 =	1.762759
509		.005000 x	387.062113 =	1.935311
518		.014300 x	857.423098 =	12.261150
508		.005000 x	595.645648 =	2.978228

			B.T =	25.469055
630	630			
512		.020000 x	96.443184 =	1.928864

			B.T =	1.928864
630.1	630.1			
510		.006000 x	377.129113 =	2.262775

			B.T =	2.262775

641	641			
231		.200000 x	.650000 =	.130000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.951934 =	3.190387
113		.150000 x	23.479183 =	3.521877
252		.002500 x	210.000000 =	.525000

			B.T =	7.802264
651	651			
221		150.000000 x	.097700 =	14.655000
111		1.500000 x	15.951934 =	23.927901
112		.500000 x	17.729980 =	8.864990
509		.003600 x	387.062113 =	1.393424
509		.011100 x	387.062113 =	4.296389
511		.050000 x	716.401976 =	35.820099
630		.600000 x	1.928864 =	1.157318
625		1.000000 x	25.469055 =	25.469055
224		120.000000 x	.070000 =	8.400000

			B.T =	123.984176
652	652			
221		650.000000 x	.097700 =	63.505000
509		.011000 x	387.062113 =	4.257683
630		.320000 x	1.928864 =	.617236
625		1.000000 x	25.469055 =	25.469055
511		.050000 x	716.401976 =	35.820099
509		.001920 x	387.062113 =	.743159
112		.500000 x	17.729980 =	8.864990
111		1.500000 x	15.951934 =	23.927901

			B.T =	163.205124
1121	1121			
112		.007000 x	17.729980 =	.124110
501		.000100 x	592.073965 =	.059207
503		.002000 x	877.327207 =	1.754654

			T.E =	1.937972
1122	1122			
112		.007000 x	17.729980 =	.124110
503		.000330 x	877.327207 =	.289518
501		.000080 x	592.073965 =	.047366
505		.000600 x	787.066174 =	.472240
507		.001400 x	914.937874 =	1.280913
509		.004447 x	387.062113 =	1.721265

			T.E =	3.935412

1123A	1123A			
112		.007000 x	17.729980 =	.124110
501		.000100 x	592.073965 =	.059207
503		.002000 x	877.327207 =	1.754654
509		.005312 x	387.062113 =	2.056074
506		.001330 x	692.071274 =	.920455

			T.E =	4.914500
1123B	1123B			
509		.001487 x	387.062113 =	.575561

			T.E =	.575561
1140	1140			
112		.010000 x	17.729980 =	.177300
521		.000200 x	424.307607 =	.084862
501		.000100 x	592.073965 =	.059207

			T.E =	.321369
1610	1610			
111		.050000 x	15.951934 =	.797597
1122		.200000 x	3.935412 =	.787082
507		.000200 x	914.937874 =	.182988
501		.000100 x	592.073965 =	.059207
502		.000200 x	777.816807 =	.155563

			T.E =	1.982437
1620	1620			
112		.250000 x	17.729980 =	4.432495
1122		1.000000 x	3.935412 =	3.935412
501		.002000 x	592.073965 =	1.184148

			T.E =	9.552055
1710	1710			
360		1.000000 x	10.700000 =	10.700000
111		.250000 x	15.951934 =	3.987984
501		.000100 x	592.073965 =	.059207

			T.E =	14.747191
2111	2111			
112		.010000 x	17.729980 =	.177300
509		.005202 x	387.062113 =	2.013497
507		.001540 x	914.937874 =	1.409004
502		.002000 x	777.816807 =	1.555634
501		.000830 x	592.073965 =	.491421

			T.E =	5.646856

2112	2112			
213		.400000 x	1.800000 =	.720000
502		.002900 x	777.816807 =	2.255669
112		.250000 x	17.729980 =	4.432495
116		.250000 x	22.893045 =	5.723261
507		.002000 x	914.937874 =	1.829876
509		.004896 x	387.062113 =	1.895056
508		.004000 x	595.645648 =	2.382583
			T.E =	19.238939
2251	2251			
111		.600000 x	15.951934 =	9.571160
621		1.050000 x	20.498384 =	21.523303
112		.600000 x	17.729980 =	10.637988
509		.012432 x	387.062113 =	4.811956
			T.E =	46.544408
2252	2252			
111		1.400000 x	15.951934 =	22.332708
621		1.050000 x	20.498384 =	21.523303
113		1.400000 x	23.479183 =	32.870856
509		.012432 x	387.062113 =	4.811956
			T.E =	81.538823
2253	2253			
111		1.500000 x	15.951934 =	23.927901
621		1.050000 x	20.498384 =	21.523303
652		.020000 x	163.205124 =	3.264102
651		.250000 x	123.984176 =	30.996044
509		.012432 x	387.062113 =	4.811956
113		2.500000 x	23.479183 =	58.697958
112		.200000 x	17.729980 =	3.545996
			T.E =	146.767260
2254	2254			
111		.800000 x	15.951934 =	12.761547
652		.100000 x	163.205124 =	16.320512
621		.350000 x	20.498384 =	7.174434
509		.003788 x	387.062113 =	1.466191
113		1.500000 x	23.479183 =	35.218775
			T.E =	72.941460

2522	2522			
221		300.000000 x	.097700 =	29.310000
112		1.400000 x	17.729980 =	24.821972
623		.800000 x	21.782136 =	17.425709
630		.250000 x	1.928864 =	.482216
641		3.000000 x	7.802264 =	23.406792
625		.500000 x	25.469055 =	12.734528
511		.040000 x	716.401976 =	28.656079
509		.008880 x	387.062113 =	3.437112
509		.001500 x	387.062113 =	.580593
509		.005550 x	387.062113 =	2.148195
113		1.600000 x	23.479183 =	37.566693

			T.E =	180.569888
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	180.569888 =	.902849
652		.002000 x	163.205124 =	.326410
113		.400000 x	23.479183 =	9.391673
111		.400000 x	15.951934 =	6.380774

			T.E =	21.061706
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	163.205124 =	1.958461
111		.600000 x	15.951934 =	9.571160
113		.800000 x	23.479183 =	18.783346

			T.E =	37.146968
5110	5110			
111		.100000 x	15.951934 =	1.595193

			T.E =	1.595193
5120	5120			
111		.080000 x	15.951934 =	1.276155

			T.E =	1.276155
5130	5130			
111		.050000 x	15.951934 =	.797597

			T.E =	.797597
5140	5140			
111		.030000 x	15.951934 =	.478558
550		.003750 x	375.655113 =	1.408707

			T.E =	1.887265

5150	5150			
111		.030000 x	15.951934 =	.478558
550		.002500 x	375.655113 =	.939138

			T.E =	1.417696
5160	5160			
213		.400000 x	1.800000 =	.720000
111		.160000 x	15.951934 =	2.552309
508		.001500 x	595.645648 =	.893468

			T.E =	4.165778
5210	5210			
363		.100000 x	.580000 =	.058000
112		.050000 x	17.729980 =	.886499
111		.040000 x	15.951934 =	.638077

			T.E =	1.582576
5220	5220			
363		.100000 x	.580000 =	.058000
112		.030000 x	17.729980 =	.531899
111		.020000 x	15.951934 =	.319039

			T.E =	.908938
5230	5230			
364		1.000000 x	3.520000 =	3.520000
112		.080000 x	17.729980 =	1.418398

			T.E =	4.938398
5240	5240			
112		.080000 x	17.729980 =	1.418398

			T.E =	1.418398
5311	5311			
111		.002000 x	15.951934 =	.031904
630.1		.020000 x	2.262775 =	.045256
510		.000250 x	377.129113 =	.094282
630		.020000 x	1.928864 =	.038577

			T.E =	.210019

5312	5312			
111		.001300 x	15.951934 =	.020738
630.1		.020000 x	2.262775 =	.045256
510		.000163 x	377.129113 =	.061472
630		.020000 x	1.928864 =	.038577

			T.E =	.166042
5321	5321			
111		.004000 x	15.951934 =	.063808

			T.E =	.063808
5322	5322			
111		.003300 x	15.951934 =	.052641

			T.E =	.052641
5330	5330			
111		.022200 x	15.951934 =	.354133

			T.E =	.354133
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	15.951934 =	.052641

			T.E =	.110641
5351	5351			
113		.005000 x	23.479183 =	.117396

			T.E =	.117396
5352	5352			
111		.005000 x	15.951934 =	.079760
113		.014000 x	23.479183 =	.328709

			T.E =	.408468
5353	5353			
111		.010000 x	15.951934 =	.159519
113		.020000 x	23.479183 =	.469584

			T.E =	.629103

5354	5354			
111		.035000 x	15.951934 =	.558318
113		.025000 x	23.479183 =	.586980

			T.E =	1.145297
5361A	5361A			
365		.003000 x	22.500000 =	.067500
630		.000300 x	1.928864 =	.000579
510		.000188 x	377.129113 =	.070900
113		.001500 x	23.479183 =	.035219

			T.E =	.174198
5361B	5361B			
366		.003000 x	20.630000 =	.061890
510		.000188 x	377.129113 =	.070900
630		.000300 x	1.928864 =	.000579
113		.001500 x	23.479183 =	.035219

			T.E =	.168588
5362A	5362A			
365		.005000 x	22.500000 =	.112500
630		.000500 x	1.928864 =	.000964
510		.000313 x	377.129113 =	.118041
113		.002500 x	23.479183 =	.058698

			T.E =	.290204
5362B	5362B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	1.928864 =	.000964
510		.000313 x	377.129113 =	.118041
113		.002500 x	23.479183 =	.058698

			T.E =	.280854
5363A	5363A			
365		.003000 x	22.500000 =	.067500
113		.001000 x	23.479183 =	.023479
510		.000125 x	377.129113 =	.047141
630		.000300 x	1.928864 =	.000579

			T.E =	.138699

5363B	5363B			
366		.003000 x	20.630000 =	.061890
113		.001000 x	23.479183 =	.023479
630		.000300 x	1.928864 =	.000579
510		.000125 x	377.129113 =	.047141

			T.E =	.133089
5364A	5364A			
365		.005000 x	22.500000 =	.112500
113		.001800 x	23.479183 =	.042263
630		.000500 x	1.928864 =	.000964
510		.000225 x	377.129113 =	.084854

			T.E =	.240581
5364B	5364B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	1.928864 =	.000964
510		.000225 x	377.129113 =	.084854
113		.001800 x	23.479183 =	.042263

			T.E =	.231231
5371	5371			
111		17.300000 x	15.951934 =	275.968458
111		9.600000 x	15.951934 =	153.138566

			T.E =	429.107025
5372	5372			
379		2.000000 x	14.000000 =	28.000000
510		.100000 x	377.129113 =	37.712911
630		.100000 x	1.928864 =	.192886
113		.800000 x	23.479183 =	18.783346

			T.E =	84.689144
5380	5380			
111		5.000000 x	15.951934 =	79.759670
550		.412500 x	375.655113 =	154.957734

			T.E =	234.717404
5390	5390			
111		.120000 x	15.951934 =	1.914232
111		.030000 x	15.951934 =	.478558

			T.E =	2.392790

5510	5510			
361		15.000000 x	27.500000 =	412.500000
363		20.000000 x	.580000 =	11.600000
362		30.000000 x	5.250000 =	157.500000
550		.375000 x	375.655113 =	140.870667
113		20.000000 x	23.479183 =	469.583660
365		2.000000 x	22.500000 =	45.000000
111		20.000000 x	15.951934 =	319.038680

			T.E =	1,556.093007
5521	5521			
111		1.000000 x	15.951934 =	15.951934
630.1		10.000000 x	2.262775 =	22.627750
510		.125000 x	377.129113 =	47.141139
630		10.000000 x	1.928864 =	19.288640

			T.E =	105.009463
5522	5522			
111		1.500000 x	15.951934 =	23.927901

			T.E =	23.927901
5530	5530			
453		.187500 x	85.880000 =	16.102500
111		1.000000 x	15.951934 =	15.951934
111		1.000000 x	15.951934 =	15.951934

			T.E =	48.006368
5540	5540			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	15.951934 =	11.963951

			T.E =	20.663951
5551	5551			
111		2.000000 x	15.951934 =	31.903868
111		1.000000 x	15.951934 =	15.951934

			T.E =	47.855802
5552	5552			
379		1.000000 x	14.000000 =	14.000000
630		.100000 x	1.928864 =	.192886
510		.050000 x	377.129113 =	18.856456
113		.400000 x	23.479183 =	9.391673

			T.E =	42.441015

5560A	5560A			
365		1.000000 x	22.500000 =	22.500000
113		.800000 x	23.479183 =	18.783346
630		.100000 x	1.928864 =	.192886
510		.100000 x	377.129113 =	37.712911

			T.E =	79.189144
5560B	5560B			
366		1.000000 x	20.630000 =	20.630000
510		.100000 x	377.129113 =	37.712911
630		.100000 x	1.928864 =	.192886
113		.800000 x	23.479183 =	18.783346

			T.E =	77.319144
5570	5570			
111		.100000 x	15.951934 =	1.595193
111		.030000 x	15.951934 =	.478558

			T.E =	2.073751
5580	5580			
111		.020000 x	15.951934 =	.319039
111		.030000 x	15.951934 =	.478558

			T.E =	.797597
5610	5610			
363		15.000000 x	.580000 =	8.700000
111		30.000000 x	15.951934 =	478.558020
550		.125000 x	375.655113 =	46.956889
367		20,000.000000 x	.112600 =	2,252.000000

			T.E =	2,786.214909
5621	5621			
111		1.000000 x	15.951934 =	15.951934
630		10.000000 x	1.928864 =	19.288640
630.1		10.000000 x	2.262775 =	22.627750
510		.125000 x	377.129113 =	47.141139

			T.E =	105.009463
5622	5622			
111		1.500000 x	15.951934 =	23.927901

			T.E =	23.927901

5630	5630			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	15.951934 =	11.963951

			T.E =	20.663951
5640	5640			
111		10.000000 x	15.951934 =	159.519340
111		2.000000 x	15.951934 =	31.903868

			T.E =	191.423208
5650	5650			
111		.120000 x	15.951934 =	1.914232
111		.030000 x	15.951934 =	.478558

			T.E =	2.392790
5710	5710			
362		40.000000 x	5.250000 =	210.000000
111		5.000000 x	15.951934 =	79.759670
112		1.000000 x	17.729980 =	17.729980
560		.125000 x	714.994113 =	89.374264
510		.125000 x	377.129113 =	47.141139
509		.125000 x	387.062113 =	48.382764
114		1.000000 x	22.739959 =	22.739959
380		800.000000 x	.260000 =	208.000000
363		15.000000 x	.580000 =	8.700000
377		250.000000 x	3.190000 =	797.500000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,583.327776
5720	5720			
111		.500000 x	15.951934 =	7.975967
510		.062500 x	377.129113 =	23.570570
630		10.000000 x	1.928864 =	19.288640
630.1		10.000000 x	2.262775 =	22.627750

			T.E =	73.462927
5730	5730			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	15.951934 =	11.963951

			T.E =	20.663951