

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

1ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	Κατχ Τιμή X 1.8117/ 6.46	15.951934
112	Κατχ Τιμή X 1.8117/ 6.46	17.729980
113	Κατχ Τιμή X 1.8117/ 6.46	23.479183
114	Κατχ Τιμή X 1.8117/ 6.67	22.739959
115	Κατχ Τιμή X 1.8117/ 6.67	18.893831
116	Κατχ Τιμή X 1.8117/ 6.46	22.893045
117	Κατχ Τιμή X 1.8117/ 6.67	18.893831
118	Κατχ Τιμή X 1.8117/ 6.67	17.283129
150		.074800
211		.802900
212		.786500
213		1.875000
214		3.800000
221		.097700
221.1		.087500
222		.114100
222.1		.102800
223		.117200
223.1		.102900
224		.070000
231		.710000
232		1.900000
233		.536700
233.1		.536700
233.2		.555400
233.3		7.500000
234		.741500
234.1		.827500
234.2		.742000
234.3		.780000
235		.623000
236		.613000
237		1.060000
237.1		1.200000
241		6.240000
242		5.000000
243		2.050000
244		2.470000
251		290.000000
252		210.000000
252.1		
252.2		
261		14.500000
261.1		13.000000
261.2		19.900000
261.3		
261.4		
262		25.300000
262.1		
263		31.200000
263.1		
263.2		44.900000
263.3		
264		61.600000
264.1		
265		110.700000
265.1		
271		198.400000
271.1		

281	20.500000
281.1	16.900000
281.2	25.390000
282	28.900000
283	34.900000
283.1	53.400000
284	72.500000
301	4.320000
302	7.120000
324	.520000
326	1.180000
327	.480000
360.1	
360.2	2.120000
361.1	11.750000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	15.300000
361.3	19.280000
361.4	
361.5	36.800000
361.6	49.220000
361.7	76.000000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	8.000000
372.2	12.580000
372.3	16.500000
372.4	25.550000
372.5	32.410000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.500000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.270000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	88.960000
376.10	487.600000
376.11	528.600000
376.12	88.960000
376.13	98.960000
376.14	109.782000
376.15	140.650000
376.16	176.880000
376.17	224.520000
376.18	302.640000
376.19	336.580000
376.2	98.960000
376.20	400.990000
376.21	487.600000
376.22	528.600000
376.3	109.780000
376.4	140.650000
376.5	176.880000
376.6	224.520000
376.7	302.840000
376.8	336.580000
376.9	400.990000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	90,675.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	61,603.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	107,490.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	123,215.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	20,575.000000
387.1	
387.2	
387.3	17,260.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	5,345.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	4,516.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	6,566.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	12,320.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.560000
396.12	3.680000
396.13	1.770000
396.14	48.900000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	6.780000
397.2	6.320000
397.4	.165000
398.1	.225000
398.10	138.730000
398.11	136.770000
398.12	176.880000
398.13	8.330000
398.14	58.610000
398.15	75.690000
398.16	62.420000
398.17	88.000000
398.2	42.300000
398.3	49.800000
398.4	71.200000
398.5	5.590000

398.6	330.000000
398.7	1,360.000000
398.8	30.750000
398.9	128.000000
401	253.330000
402	365.970000
403	99.490000
404	200.770000
405	199.000000
406	308.980000
407	52.110000
408	4.280000
409	118.980000
410	109.980000
411	25.830000
412	2.820000
413	4.280000
414	5.900000
415	8.290000
416	12.780000
417	126.960000
419	4.280000
420	91.820000
421	30.740000
428	421.470000
429	73.220000
450	79.130000
451	4.600000
452	99.200000
453	
454	91.820000
455	29.520000
456	33.060000
457	431.960000
458	268.980000
459	406.290000
460	502.380000
461	225.580000
462	328.910000
463	41.330000
464	361.980000
465	96.840000
466	45.170000
467	328.910000
468	82.370000
469	82.370000
470	66.430000
471	57.570000
472	25.020000
473	16.090000
474	33.060000
475	1,859.540000
476	80.600000
477	6.560000
478	108.650000
479	174.790000
480	25.690000
481	766.790000

501	501				
401		1.000000 x	253.330000 =	253.330000	
211		50.000000 x	.802900 =	40.145000	
118		3.000000 x	17.283129 =	51.849387	
114		8.000000 x	22.739959 =	181.919672	
214		3.000000 x	3.800000 =	11.400000	

			ΑΘΡΟΙΣΜΑ =	538.644059	

			Η.Δ. =	592.508465	
502	502				
402		1.000000 x	365.970000 =	365.970000	
214		7.000000 x	3.800000 =	26.600000	
211		80.000000 x	.802900 =	64.232000	
118		4.000000 x	17.283129 =	69.132516	
114		8.000000 x	22.739959 =	181.919672	

			ΑΘΡΟΙΣΜΑ =	707.854188	

			Η.Δ. =	778.639607	
503	503				
428		1.000000 x	421.470000 =	421.470000	
214		10.000000 x	3.800000 =	38.000000	
114		8.000000 x	22.739959 =	181.919672	
211		110.000000 x	.802900 =	88.319000	
118		4.000000 x	17.283129 =	69.132516	

			ΑΘΡΟΙΣΜΑ =	798.841188	

			Η.Δ. =	878.725307	
504	504				
403		1.000000 x	99.490000 =	99.490000	
114		8.000000 x	22.739959 =	181.919672	
211		40.000000 x	.802900 =	32.116000	
214		2.000000 x	3.800000 =	7.600000	

			ΑΘΡΟΙΣΜΑ =	321.125672	

			Η.Δ. =	353.238239	
505	505				
404		1.000000 x	200.770000 =	200.770000	
211		200.000000 x	.802900 =	160.580000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
214		10.000000 x	3.800000 =	38.000000	

			ΑΘΡΟΙΣΜΑ =	719.534704	

			Η.Δ. =	791.488174	

506	506				
405		1.000000 x	199.000000 =	199.000000	
211		95.000000 x	.802900 =	76.275500	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
242		2.500000 x	5.000000 =	12.500000	
214		6.000000 x	3.800000 =	22.800000	

			ΑΘΡΟΙΣΜΑ =	630.760204	

			Η.Δ. =	693.836224	
507	507				
406		1.000000 x	308.980000 =	308.980000	
114		8.000000 x	22.739959 =	181.919672	
118		8.000000 x	17.283129 =	138.265032	
242		7.000000 x	5.000000 =	35.000000	
214		10.000000 x	3.800000 =	38.000000	
211		165.000000 x	.802900 =	132.478500	

			ΑΘΡΟΙΣΜΑ =	834.643204	

			Η.Δ. =	918.107524	
508	508				
407		1.000000 x	52.110000 =	52.110000	
116		16.000000 x	22.893045 =	366.288720	
115		4.000000 x	18.893831 =	75.575324	
214		2.000000 x	3.800000 =	7.600000	
408		2.000000 x	4.280000 =	8.560000	
211		40.000000 x	.802900 =	32.116000	

			ΑΘΡΟΙΣΜΑ =	542.250044	

			Η.Δ. =	596.475048	
509	509				
409		1.000000 x	118.980000 =	118.980000	
117		8.000000 x	18.893831 =	151.150648	
214		5.000000 x	3.800000 =	19.000000	
211		80.000000 x	.802900 =	64.232000	

			ΑΘΡΟΙΣΜΑ =	353.362648	

			Η.Δ. =	388.698913	
510	510				
410		1.000000 x	109.980000 =	109.980000	
117		8.000000 x	18.893831 =	151.150648	
211		80.000000 x	.802900 =	64.232000	
214		5.000000 x	3.800000 =	19.000000	

			ΑΘΡΟΙΣΜΑ =	344.362648	

			Η.Δ. =	378.798913	

511	511				
411		1.000000 x	25.830000 =	25.830000	
214		1.000000 x	3.800000 =	3.800000	
112		30.000000 x	17.729980 =	531.899400	
115		4.000000 x	18.893831 =	75.575324	
212		17.000000 x	.786500 =	13.370500	

			ΑΘΡΟΙΣΜΑ =	650.475224	

			Η.Δ. =	715.522746	
512	512				
412		1.000000 x	2.820000 =	2.820000	
214		1.000000 x	3.800000 =	3.800000	
115		2.000000 x	18.893831 =	37.787662	
112		2.000000 x	17.729980 =	35.459960	
211		10.000000 x	.802900 =	8.029000	

			ΑΘΡΟΙΣΜΑ =	87.896622	

			Η.Δ. =	96.686284	
513	513				
413		1.000000 x	4.280000 =	4.280000	
211		15.000000 x	.802900 =	12.043500	
115		3.000000 x	18.893831 =	56.681493	
112		3.000000 x	17.729980 =	53.189940	
214		1.500000 x	3.800000 =	5.700000	

			ΑΘΡΟΙΣΜΑ =	131.894933	

			Η.Δ. =	145.084426	
514	514				
414		1.000000 x	5.900000 =	5.900000	
115		4.000000 x	18.893831 =	75.575324	
112		4.000000 x	17.729980 =	70.919920	
214		2.000000 x	3.800000 =	7.600000	
211		21.000000 x	.802900 =	16.860900	

			ΑΘΡΟΙΣΜΑ =	176.856144	

			Η.Δ. =	194.541758	
515	515				
415		1.000000 x	8.290000 =	8.290000	
112		6.000000 x	17.729980 =	106.379880	
115		5.000000 x	18.893831 =	94.469155	
214		2.500000 x	3.800000 =	9.500000	
211		27.000000 x	.802900 =	21.678300	

			ΑΘΡΟΙΣΜΑ =	240.317335	

			Η.Δ. =	264.349069	

516	516				
416		1.000000 x	12.780000 =	12.780000	
115		6.000000 x	18.893831 =	113.362986	
112		8.000000 x	17.729980 =	141.839840	
214		3.500000 x	3.800000 =	13.300000	
211		33.000000 x	.802900 =	26.495700	

			ΑΘΡΟΙΣΜΑ =	307.778526	

			Η.Δ. =	338.556379	
517	517				
406		1.000000 x	308.980000 =	308.980000	
406		.400000 x	308.980000 =	123.592000	
116		8.000000 x	22.893045 =	183.144360	
115		8.000000 x	18.893831 =	151.150648	
114		8.000000 x	22.739959 =	181.919672	
113		2.000000 x	23.479183 =	46.958366	
112		16.000000 x	17.729980 =	283.679680	
111		16.000000 x	15.951934 =	255.230944	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	3.800000 =	30.400000	
211		240.000000 x	.802900 =	192.696000	
407		2.000000 x	52.110000 =	104.220000	

			ΑΘΡΟΙΣΜΑ =	1,905.471670	

			Η.Δ. =	2,096.018837	
518	518				
417		1.000000 x	126.960000 =	126.960000	
211		180.000000 x	.802900 =	144.522000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
112		8.000000 x	17.729980 =	141.839840	
214		12.000000 x	3.800000 =	45.600000	
212		5.000000 x	.786500 =	3.932500	

			ΑΘΡΟΙΣΜΑ =	783.039044	

			Η.Δ. =	861.342948	
520	520				
419		1.000000 x	4.280000 =	4.280000	
118		4.000000 x	17.283129 =	69.132516	
115		8.000000 x	18.893831 =	151.150648	
112		4.000000 x	17.729980 =	70.919920	
211		80.000000 x	.802900 =	64.232000	
214		5.000000 x	3.800000 =	19.000000	
212		2.000000 x	.786500 =	1.573000	

			ΑΘΡΟΙΣΜΑ =	380.288084	

			Η.Δ. =	418.316892	

521	521				
420		1.000000 x	91.820000 =	91.820000	
211		40.000000 x	.802900 =	32.116000	
118		4.000000 x	17.283129 =	69.132516	
114		8.000000 x	22.739959 =	181.919672	
214		3.000000 x	3.800000 =	11.400000	

			ΑΘΡΟΙΣΜΑ =	386.388188	

			Η.Δ. =	425.027007	
522	522				
421		1.000000 x	30.740000 =	30.740000	
118		2.000000 x	17.283129 =	34.566258	
114		8.000000 x	22.739959 =	181.919672	
214		2.000000 x	3.800000 =	7.600000	
211		20.000000 x	.802900 =	16.058000	

			ΑΘΡΟΙΣΜΑ =	270.883930	

			Η.Δ. =	297.972323	
529	529				
429		1.000000 x	73.220000 =	73.220000	
114		8.000000 x	22.739959 =	181.919672	
118		4.000000 x	17.283129 =	69.132516	
211		70.000000 x	.802900 =	56.203000	
214		4.000000 x	3.800000 =	15.200000	

			ΑΘΡΟΙΣΜΑ =	395.675188	

			Η.Δ. =	435.242707	
550	550				
450		1.000000 x	79.130000 =	79.130000	
115		4.000000 x	18.893831 =	75.575324	
116		32.000000 x	22.893045 =	732.577440	
211		90.000000 x	.802900 =	72.261000	
214		4.000000 x	3.800000 =	15.200000	
451		4.000000 x	4.600000 =	18.400000	

			ΑΘΡΟΙΣΜΑ =	993.143764	

			Η.Δ. =	1,092.458140	
551	551				
405		1.000000 x	199.000000 =	199.000000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
214		6.000000 x	3.800000 =	22.800000	
211		95.000000 x	.802900 =	76.275500	
452		1.000000 x	99.200000 =	99.200000	

			ΑΘΡΟΙΣΜΑ =	717.460204	

			Η.Δ. =	789.206224	

552	552				
453		1.000000 x	.000000 =	.000000	
115		8.000000 x	18.893831 =	151.150648	
214		1.000000 x	3.800000 =	3.800000	
211		18.000000 x	.802900 =	14.452200	

		ΑΘΡΟΙΣΜΑ =		169.402848	

		H.Δ. =			
553	553				
454		1.000000 x	91.820000 =	91.820000	
214		4.000000 x	3.800000 =	15.200000	
211		100.000000 x	.802900 =	80.290000	

		ΑΘΡΟΙΣΜΑ =		187.310000	

		H.Δ. =		206.041000	
554	554				
455		1.000000 x	29.520000 =	29.520000	

		ΑΘΡΟΙΣΜΑ =		29.520000	

		H.Δ. =		32.472000	
555	555				
456		1.000000 x	33.060000 =	33.060000	
212		17.000000 x	.786500 =	13.370500	
112		32.000000 x	17.729980 =	567.359360	
115		4.000000 x	18.893831 =	75.575324	
214		1.000000 x	3.800000 =	3.800000	

		ΑΘΡΟΙΣΜΑ =		693.165184	

		H.Δ. =		762.481702	
556	556				
457		1.000000 x	431.960000 =	431.960000	
114		8.000000 x	22.739959 =	181.919672	
118		8.000000 x	17.283129 =	138.265032	
214		18.000000 x	3.800000 =	68.400000	
211		200.000000 x	.802900 =	160.580000	

		ΑΘΡΟΙΣΜΑ =		981.124704	

		H.Δ. =		1,079.237174	
557	557				
458		1.000000 x	268.980000 =	268.980000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
214		11.000000 x	3.800000 =	41.800000	
211		130.000000 x	.802900 =	104.377000	

		ΑΘΡΟΙΣΜΑ =		735.341704	

		H.Δ. =		808.875874	

558	558				
459		1.000000 x	406.290000 =	406.290000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
242		9.500000 x	5.000000 =	47.500000	
214		12.000000 x	3.800000 =	45.600000	
211		200.000000 x	.802900 =	160.580000	

			ΑΘΡΟΙΣΜΑ =	980.154704	

			Η.Δ. =	1,078.170174	
559	559				
460		1.000000 x	502.380000 =	502.380000	
214		15.000000 x	3.800000 =	57.000000	
211		250.000000 x	.802900 =	200.725000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
242		12.000000 x	5.000000 =	60.000000	

			ΑΘΡΟΙΣΜΑ =	1,140.289704	

			Η.Δ. =	1,254.318674	
560	560				
461		1.000000 x	225.580000 =	225.580000	
211		160.000000 x	.802900 =	128.464000	
114		8.000000 x	22.739959 =	181.919672	
214		8.000000 x	3.800000 =	30.400000	

			ΑΘΡΟΙΣΜΑ =	566.363672	

			Η.Δ. =	623.000039	
561	561				
462		1.000000 x	328.910000 =	328.910000	
214		12.000000 x	3.800000 =	45.600000	
114		8.000000 x	22.739959 =	181.919672	
211		230.000000 x	.802900 =	184.667000	

			ΑΘΡΟΙΣΜΑ =	741.096672	

			Η.Δ. =	815.206339	
562	562				
463		1.000000 x	41.330000 =	41.330000	
214		2.400000 x	3.800000 =	9.120000	
211		50.000000 x	.802900 =	40.145000	

			ΑΘΡΟΙΣΜΑ =	90.595000	

			Η.Δ. =	99.654500	

563	563				
211.1		640.000000 x	.000000 =	.000000	
114		16.000000 x	22.739959 =	363.839344	
112		24.000000 x	17.729980 =	425.519520	
464		1.000000 x	361.980000 =	361.980000	
214		16.000000 x	3.800000 =	60.800000	
			AΘΡΟΙΣΜΑ =	1,212.138864	
			H.Δ. =		
564	564				
465		1.000000 x	96.840000 =	96.840000	
567		3.000000 x	344.394868 =	1,033.184604	
115		8.000000 x	18.893831 =	151.150648	
111		8.000000 x	15.951934 =	127.615472	
115		8.000000 x	18.893831 =	151.150648	
			AΘΡΟΙΣΜΑ =	1,559.941372	
			H.Δ. =	1,715.935509	
565	565				
450		3.000000 x	79.130000 =	237.390000	
115		8.000000 x	18.893831 =	151.150648	
115		12.000000 x	18.893831 =	226.725972	
465		1.000000 x	96.840000 =	96.840000	
			H.Δ. =	712.106620	
566	566				
211.1		680.000000 x	.000000 =	.000000	
112		1.000000 x	17.729980 =	17.729980	
466		1.000000 x	45.170000 =	45.170000	
115		2.000000 x	18.893831 =	37.787662	
			AΘΡΟΙΣΜΑ =	100.687642	
			H.Δ. =		
567	567				
450		1.000000 x	79.130000 =	79.130000	
211		90.000000 x	.802900 =	72.261000	
112		4.000000 x	17.729980 =	70.919920	
214		4.000000 x	3.800000 =	15.200000	
115		4.000000 x	18.893831 =	75.575324	
			AΘΡΟΙΣΜΑ =	313.086244	
			H.Δ. =	344.394868	

568.1	568.1				
467		1.000000 x	328.910000 =	328.910000	
214		16.000000 x	3.800000 =	60.800000	
113		32.000000 x	23.479183 =	751.333856	
114		8.000000 x	22.739959 =	181.919672	
510		.072000 x	378.798913 =	27.273522	
567		2.000000 x	344.394868 =	688.789736	
512		.240000 x	96.686284 =	23.204708	
118		32.000000 x	17.283129 =	553.060128	

				AΘΡΟΙΣΜΑ =	2,615.291622

				H.Δ. =	2,876.820784
568.2	568.2				
450		2.000000 x	79.130000 =	158.260000	
114		8.000000 x	22.739959 =	181.919672	
115		8.000000 x	18.893831 =	151.150648	
467		1.000000 x	328.910000 =	328.910000	

				H.Δ. =	820.240320
569.1	569.1				
468		1.000000 x	82.370000 =	82.370000	
567		2.000000 x	344.394868 =	688.789736	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
214		16.000000 x	3.800000 =	60.800000	

				AΘΡΟΙΣΜΑ =	1,152.144440

				H.Δ. =	1,267.358884
569.2	569.2				
450		2.000000 x	79.130000 =	158.260000	
114		8.000000 x	22.739959 =	181.919672	
115		8.000000 x	18.893831 =	151.150648	
468		1.000000 x	82.370000 =	82.370000	

				H.Δ. =	573.700320
570.1	570.1				
469		1.000000 x	82.370000 =	82.370000	
211		135.000000 x	.802900 =	108.391500	
114		8.000000 x	22.739959 =	181.919672	
118		4.000000 x	17.283129 =	69.132516	
214		16.000000 x	3.800000 =	60.800000	

				AΘΡΟΙΣΜΑ =	502.613688

				H.Δ. =	552.875057

570.2	570.2				
469		1.000000 x	82.370000 =		82.370000
118		4.000000 x	17.283129 =		69.132516
				H.Δ. =	151.502516
571.1	571.1				
470		1.000000 x	66.430000 =		66.430000
211		114.000000 x	.802900 =		91.530600
114		8.000000 x	22.739959 =		181.919672
214		4.000000 x	3.800000 =		15.200000
				AΘΡΟΙΣΜΑ =	355.080272
				H.Δ. =	390.588299
571.2	571.2				
470		1.000000 x	66.430000 =		66.430000
114		8.000000 x	22.739959 =		181.919672
				H.Δ. =	248.349672
572	572				
407		1.000000 x	52.110000 =		52.110000
471		1.000000 x	57.570000 =		57.570000
114		8.000000 x	22.739959 =		181.919672
111		24.000000 x	15.951934 =		382.846416
214		8.000000 x	3.800000 =		30.400000
211		54.000000 x	.802900 =		43.356600
				AΘΡΟΙΣΜΑ =	748.202688
				H.Δ. =	823.022957
573	573				
407		1.000000 x	52.110000 =		52.110000
472		.250000 x	25.020000 =		6.255000
473		1.000000 x	16.090000 =		16.090000
474		1.000000 x	33.060000 =		33.060000
474		.250000 x	33.060000 =		8.265000
473		.250000 x	16.090000 =		4.022500
407		.250000 x	52.110000 =		13.027500
472		1.000000 x	25.020000 =		25.020000
115		16.000000 x	18.893831 =		302.301296
111		24.000000 x	15.951934 =		382.846416
214		8.000000 x	3.800000 =		30.400000
211		54.000000 x	.802900 =		43.356600
				AΘΡΟΙΣΜΑ =	916.754312
				H.Δ. =	1,008.429743

574	574				
475		1.000000 x	1,859.540000 =		1,859.540000
211		590.000000 x	.802900 =		473.711000
214		30.000000 x	3.800000 =		114.000000
111		16.000000 x	15.951934 =		255.230944
114		8.000000 x	22.739959 =		181.919672
118		8.000000 x	17.283129 =		138.265032
242		7.000000 x	5.000000 =		35.000000

			ΑΘΡΟΙΣΜΑ =		3,057.666648

			Η.Δ. =		3,363.433313
574.1	574.1				
475		1.000000 x	1,859.540000 =		1,859.540000
114		8.000000 x	22.739959 =		181.919672
118		8.000000 x	17.283129 =		138.265032

			Η.Δ. =		2,179.724704
575	575				
476		1.000000 x	80.600000 =		80.600000
115		8.000000 x	18.893831 =		151.150648
211		470.000000 x	.802900 =		377.363000
214		23.000000 x	3.800000 =		87.400000

			ΑΘΡΟΙΣΜΑ =		696.513648

			Η.Δ. =		766.165013
575.1	575.1				
476		1.000000 x	80.600000 =		80.600000
115		8.000000 x	18.893831 =		151.150648

			Η.Δ. =		231.750648
576	576				
477		1.000000 x	6.560000 =		6.560000

			ΑΘΡΟΙΣΜΑ =		6.560000

			Η.Δ. =		7.216000
576.1	576.1				
477		1.000000 x	6.560000 =		6.560000

			Η.Δ. =		6.560000

577	577				
478		1.000000 x	108.650000 =	108.650000	
242		2.000000 x	5.000000 =	10.000000	
111		8.000000 x	15.951934 =	127.615472	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
214		4.000000 x	3.800000 =	15.200000	
211		70.000000 x	.802900 =	56.203000	

			ΑΘΡΟΙΣΜΑ =	637.853176	

			Η.Δ. =	701.638494	
577.1	577.1				
478		1.000000 x	108.650000 =	108.650000	
114		8.000000 x	22.739959 =	181.919672	
118		8.000000 x	17.283129 =	138.265032	

			Η.Δ. =	428.834704	
578	578				
479		1.000000 x	174.790000 =	174.790000	
211		50.000000 x	.802900 =	40.145000	
214		5.000000 x	3.800000 =	19.000000	
118		4.000000 x	17.283129 =	69.132516	
114		8.000000 x	22.739959 =	181.919672	
112		4.000000 x	17.729980 =	70.919920	
242		5.000000 x	5.000000 =	25.000000	

			ΑΘΡΟΙΣΜΑ =	580.907108	

			Η.Δ. =	638.997819	
579	579				
480		1.000000 x	25.690000 =	25.690000	
212		28.000000 x	.786500 =	22.022000	
117		8.000000 x	18.893831 =	151.150648	
214		1.000000 x	3.800000 =	3.800000	

			ΑΘΡΟΙΣΜΑ =	202.662648	

			Η.Δ. =	222.928913	
580	580				
481		1.000000 x	766.790000 =	766.790000	
211		168.000000 x	.802900 =	134.887200	
242		2.000000 x	5.000000 =	10.000000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
111		16.000000 x	15.951934 =	255.230944	
214		8.000000 x	3.800000 =	30.400000	

			ΑΘΡΟΙΣΜΑ =	1,517.492848	

			Η.Δ. =	1,669.242133	

581	581			
481		1.000000 x	766.790000 =	766.790000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032

H.Δ. = 1,086.974704

7020.2	7020.2			
111		8.000000 x	15.951934 =	127.615472
568.2		.550000 x	820.240320 =	451.132176
569.2		.670000 x	573.700320 =	384.379214
571.2		.150000 x	248.349672 =	37.252451
571.1		.350000 x	390.588299 =	136.705905
570.2		.350000 x	151.502516 =	53.025881
570.1		.150000 x	552.875057 =	82.931259
569.1		.330000 x	1,267.358884 =	418.228432
568.1		.450000 x	2,876.820784 =	1,294.569353
116		8.000000 x	22.893045 =	183.144360
567		1.000000 x	344.394868 =	344.394868

H.Δ. = 3,513.379370

7021.2	7021.2			
111		8.000000 x	15.951934 =	127.615472
568.1		.250000 x	2,876.820784 =	719.205196
569.1		.250000 x	1,267.358884 =	316.839721
570.1		.110000 x	552.875057 =	60.816256
571.2		.240000 x	248.349672 =	59.603921
571.1		.260000 x	390.588299 =	101.552958
570.2		.390000 x	151.502516 =	59.085981
569.2		.750000 x	573.700320 =	430.275240
568.2		.750000 x	820.240320 =	615.180240
567		1.000000 x	344.394868 =	344.394868
116		8.000000 x	22.893045 =	183.144360

H.Δ. = 3,017.714214

7022.2	7022.2			
111		8.000000 x	15.951934 =	127.615472
568.1		.150000 x	2,876.820784 =	431.523118
569.1		.180000 x	1,267.358884 =	228.124599
570.1		.080000 x	552.875057 =	44.230005
571.2		.310000 x	248.349672 =	76.988398
571.1		.190000 x	390.588299 =	74.211777
570.2		.420000 x	151.502516 =	63.631057
569.2		.820000 x	573.700320 =	470.434262
568.2		.850000 x	820.240320 =	697.204272
567		1.000000 x	344.394868 =	344.394868
116		8.000000 x	22.893045 =	183.144360

H.Δ. = 2,741.502188

613	613			
111		.140000 x	15.951934 =	2.233271
520		.003500 x	418.316892 =	1.464109
503		.000770 x	878.725307 =	.676618
504		.002800 x	353.238239 =	.989067

			B.T =	5.363065
614	614			
112		.070000 x	17.729980 =	1.241099
504		.002800 x	353.238239 =	.989067
518		.004375 x	861.342948 =	3.768375
509		.004375 x	388.698913 =	1.700558
503		.000700 x	878.725307 =	.615108

			B.T =	8.314207
621.1	621.1			
213		.100000 x	1.875000 =	.187500
116		.140000 x	22.893045 =	3.205026
504		.003500 x	353.238239 =	1.236334
508		.003500 x	596.475048 =	2.087663
111		.560000 x	15.951934 =	8.933083

			B.T =	15.649606
622	622			
213		.100000 x	1.875000 =	.187500
112		.070000 x	17.729980 =	1.241099
116		.140000 x	22.893045 =	3.205026
509		.003500 x	388.698913 =	1.360446
508		.003500 x	596.475048 =	2.087663
518		.004340 x	861.342948 =	3.738228
504		.003500 x	353.238239 =	1.236334

			B.T =	13.056296
6360.1 A1	6360.1 A1			
6304		9.800000 x	6.023671 =	59.031976
6330		.038000 x	185.662053 =	7.055158
6330		.190000 x	185.662053 =	35.275790
6314		.382500 x	2.179754 =	.833756
6314		7.650000 x	2.179754 =	16.675118

			B.T =	118.871798
6360.1 A2	6360.1 A2			
6304		.450000 x	6.023671 =	2.710652
6310		2.142000 x	1.561400 =	3.344519
6330		.013000 x	185.662053 =	2.413607

			B.T =	8.468777

6360.1 A3	6360.1 A3			
6304		.960000 x	6.023671 =	5.782724
6329.2		.037000 x	171.376110 =	6.340916
6310		1.974000 x	1.561400 =	3.082204

			B.T =	15.205844
6360.1 A4	6360.1 A4			
6304		2.490000 x	6.023671 =	14.998941
6329.2		.109000 x	171.376110 =	18.679996

			B.T =	33.678937
6360.1 A5	6360.1 A5			
112		1.700000 x	17.729980 =	30.140966
113		2.975000 x	23.479183 =	69.850569
113		.425000 x	23.479183 =	9.978653
6069.1		.056400 x	11.193189 =	.631296

			B.T =	110.601484
6360.2 A1	6360.2 A1			
6304		10.650000 x	6.023671 =	64.152096
6314		.392500 x	2.179754 =	.855553
6314		7.850000 x	2.179754 =	17.111069
6330		.041000 x	185.662053 =	7.612144
6330		.205000 x	185.662053 =	38.060721

			B.T =	127.791584
6360.2 A2	6360.2 A2			
6304		.750000 x	6.023671 =	4.517753
6330		.019000 x	185.662053 =	3.527579
6310		2.383500 x	1.561400 =	3.721597

			B.T =	11.766929
6360.2 A3	6360.2 A3			
6304		1.140000 x	6.023671 =	6.866985
6310		2.341500 x	1.561400 =	3.656018
6329.2		.054000 x	171.376110 =	9.254310

			B.T =	19.777313
6360.2 A4	6360.2 A4			
6304		2.800000 x	6.023671 =	16.866279
6329.2		.118000 x	171.376110 =	20.222381

			B.T =	37.088660

6360.2 A5	6360.2 A5			
112		2.550000 x	17.729980 =	45.211449
113		.382500 x	23.479183 =	8.980787
113		2.975000 x	23.479183 =	69.850569
6069.1		.059400 x	11.193189 =	.664875

			B.T =	124.707681
6360.3 A1	6360.3 A1			
6304		13.900000 x	6.023671 =	83.729027
6314		.557500 x	2.179754 =	1.215213
6314		11.150000 x	2.179754 =	24.304257
6330		.270000 x	185.662053 =	50.128754
6330		.054000 x	185.662053 =	10.025751

			B.T =	169.403002
6360.3 A2	6360.3 A2			
6304		.940000 x	6.023671 =	5.662251
6330		.031000 x	185.662053 =	5.755524
6310		3.360000 x	1.561400 =	5.246304

			B.T =	16.664078
6360.3 A3	6360.3 A3			
6304		1.830000 x	6.023671 =	11.023318
6310		10.678500 x	1.561400 =	16.673410
6329.2		.099000 x	171.376110 =	16.966235

			B.T =	44.662963
6360.3 A4	6360.3 A4			
6304		3.420000 x	6.023671 =	20.600955
6329.2		.139000 x	171.376110 =	23.821279

			B.T =	44.422234
6360.3 A5	6360.3 A5			
112		5.100000 x	17.729980 =	90.422898
113		.340000 x	23.479183 =	7.982922
113		2.975000 x	23.479183 =	69.850569
6069.1		.073800 x	11.193189 =	.826057

			B.T =	169.082447

6360.4 A1	6360.4 A1			
6304		16.250000 x	6.023671 =	97.884654
6314		.885000 x	2.179754 =	1.929082
6314		17.700000 x	2.179754 =	38.581646
6330		.075000 x	185.662053 =	13.924654
6330		.375000 x	185.662053 =	69.623270

			B.T =	221.943306
6360.4 A2	6360.4 A2			
6304		1.060000 x	6.023671 =	6.385091
6330		.048000 x	185.662053 =	8.911779
6310		4.641000 x	1.561400 =	7.246457

			B.T =	22.543327
6360.4 A3	6360.4 A3			
6304		2.270000 x	6.023671 =	13.673733
6310		20.454000 x	1.561400 =	31.936876
6329.2		.125000 x	171.376110 =	21.422014

			B.T =	67.032623
6360.4 A4	6360.4 A4			
6304		2.800000 x	6.023671 =	16.866279
6329.2		.118000 x	171.376110 =	20.222381

			B.T =	37.088660
6360.4 A5	6360.4 A5			
112		6.800000 x	17.729980 =	120.563864
113		.297500 x	23.479183 =	6.985057
113		4.250000 x	23.479183 =	99.786528
6069.1		.091800 x	11.193189 =	1.027535

			B.T =	228.362983
6360.5 A1	6360.5 A1			
6304		17.950000 x	6.023671 =	108.124894
6314		1.050000 x	2.179754 =	2.288742
6314		21.000000 x	2.179754 =	45.774834
6330		.088000 x	185.662053 =	16.338261
6330		.440000 x	185.662053 =	81.691303

			B.T =	254.218034
6360.5 A2	6360.5 A2			
6304		1.220000 x	6.023671 =	7.348879
6330		.061000 x	185.662053 =	11.325385
6310		6.048000 x	1.561400 =	9.443347

			B.T =	28.117611

6360.5 A3	6360.5 A3			
6304		2.480000 x	6.023671 =	14.938704
6310		22.291500 x	1.561400 =	34.805948
6329.2		.144000 x	171.376110 =	24.678160

			B.T =	74.422812
6360.5 A4	6360.5 A4			
6304		3.200000 x	6.023671 =	19.275747
6329.2		.112000 x	171.376110 =	19.194124

			B.T =	38.469872
6360.5 A5	6360.5 A5			
112		9.350000 x	17.729980 =	165.775313
113		5.950000 x	23.479183 =	139.701139
113		.255000 x	23.479183 =	5.987192
6069.1		.090600 x	11.193189 =	1.014103

			B.T =	312.477746
6360.6 A1	6360.6 A1			
6304		20.350000 x	6.023671 =	122.581705
6314		24.900000 x	2.179754 =	54.275875
6330		.116000 x	185.662053 =	21.536798
6330		.580000 x	185.662053 =	107.683991
6314		1.245000 x	2.179754 =	2.713794

			B.T =	308.792162
6360.6 A2	6360.6 A2			
6304		1.530000 x	6.023671 =	9.216217
6330		.092000 x	185.662053 =	17.080909
6310		10.206000 x	1.561400 =	15.935648

			B.T =	42.232774
6360.6 A3	6360.6 A3			
6304		2.670000 x	6.023671 =	16.083202
6329.2		.181000 x	171.376110 =	31.019076
6310		25.798500 x	1.561400 =	40.281778

			B.T =	87.384055
6360.6 A4	6360.6 A4			
6304		2.800000 x	6.023671 =	16.866279
6329.2		.118000 x	171.376110 =	20.222381

			B.T =	37.088660

6360.6 A5

6360.6 A5

112	12.750000 x	17.729980 =	226.057245
113	.212500 x	23.479183 =	4.989326
6069.1	.120000 x	11.193189 =	1.343183
113	7.650000 x	23.479183 =	179.615750

B.T = 412.005504

641

641

231	.200000 x	.710000 =	.142000
251	.001500 x	290.000000 =	.435000
113	.127500 x	23.479183 =	2.993596
111	.170000 x	15.951934 =	2.711829
252	.002500 x	210.000000 =	.525000

B.T = 6.807425

651

651

221	150.000000 x	.097700 =	14.655000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	388.698913 =	3.667374
509	.003060 x	388.698913 =	1.189419
T 630	.600000 x	1.643667 =	.986200
T 625	.850000 x	21.744241 =	18.482605
511	.042500 x	715.522746 =	30.409717
112	.425000 x	17.729980 =	7.535242
111	1.275000 x	15.951934 =	20.338716

B.T = 105.664272

652

652

221	650.000000 x	.097700 =	63.505000
T 630	.320000 x	1.643667 =	.525973
T 625	1.000000 x	21.744241 =	21.744241
511	.042500 x	715.522746 =	30.409717
509	.001632 x	388.698913 =	.634357
509	.009435 x	388.698913 =	3.667374
111	1.275000 x	15.951934 =	20.338716
112	.425000 x	17.729980 =	7.535242

B.T = 148.360619

652.1

652.1

221	450.000000 x	.097700 =	43.965000
111	1.275000 x	15.951934 =	20.338716
509	.010001 x	388.698913 =	3.887378
T 630	.320000 x	1.643667 =	.525973
T 625	1.060000 x	21.744241 =	23.048895
511	.042500 x	715.522746 =	30.409717
510	.001632 x	378.798913 =	.618200
112	.425000 x	17.729980 =	7.535242

B.T = 130.329121

652.2	652.2			
221		900.000000 x	.097700 =	87.930000
509		.007548 x	388.698913 =	2.933899
T 630		.320000 x	1.643667 =	.525973
T 625		.800000 x	21.744241 =	17.395393
511		.042500 x	715.522746 =	30.409717
510		.001632 x	378.798913 =	.618200
111		1.275000 x	15.951934 =	20.338716
112		.425000 x	17.729980 =	7.535242
			B.T =	167.687140
700	700			
397.4		4.000000 x	.165000 =	.660000
397.5		2.150000 x	.000000 =	.000000
113		.935000 x	23.479183 =	21.953036
324		7.650000 x	.520000 =	3.978000
221		13.000000 x	.097700 =	1.270100
			B.T =	
7001 A	7001 A			
502		.000365 x	778.639607 =	.284203
557		.001094 x	808.875874 =	.884910
			AΘΡΟΙΣΜΑ =	1.169114
	B.T =	.200000 x	1.169114 =	.233823
7001 B	7001 B			
558		.000700 x	1,078.170174 =	.754719
			B.T =	.754719
7001 E	7001 E			
503		.000875 x	878.725307 =	.768885
554		.000875 x	32.472000 =	.028413
			B.T =	.797298
7001 Γ	7001 Γ			
501		.000700 x	592.508465 =	.414756
502		.000700 x	778.639607 =	.545048
			B.T =	.959804

7001 Δ	7001 Δ			
502		.000292 x	778.639607 =	.227363
X 630.1		.060000 x	1.590955 =	.095457
X 630		.060000 x	1.353608 =	.081216
510		.000292 x	378.798913 =	.110609

			AΘΡΟΙΣΜΑ =	.514646
	B.T =	.600000 x	.514646 =	.308787

7003 Α	7003 Α			
502		.000365 x	778.639607 =	.284203
557		.001094 x	808.875874 =	.884910

			AΘΡΟΙΣΜΑ =	1.169114
	B.T =	.100000 x	1.169114 =	.116911

7003 Β	7003 Β			
559		.000464 x	1,254.318674 =	.582004

			B.T =	.582004
7003 Γ	7003 Γ			
502		.000700 x	778.639607 =	.545048

			B.T =	.545048
7003 Δ	7003 Δ			
502		.000875 x	778.639607 =	.681310
562		.000875 x	99.654500 =	.087198

			B.T =	.768507
7005 Α	7005 Α			
502		.000365 x	778.639607 =	.284203
557		.001094 x	808.875874 =	.884910

			AΘΡΟΙΣΜΑ =	1.169114
	B.T =	.100000 x	1.169114 =	.116911

7005 Β	7005 Β			
559		.000812 x	1,254.318674 =	1.018507

			B.T =	1.018507
7005 Ε	7005 Ε			
502		.000875 x	778.639607 =	.681310
562		.000875 x	99.654500 =	.087198

			B.T =	.768507

7005 Γ	7005 Γ			
559		.000232 x	1,254.318674 =	.291002

			B.T =	.291002
7005 Δ	7005 Δ			
502		.000700 x	778.639607 =	.545048

			B.T =	.545048
7010 Α	7010 Α			
558		.000315 x	1,078.170174 =	.339624

			B.T =	.339624
7010 Β	7010 Β			
558		.000473 x	1,078.170174 =	.509974

			B.T =	.509974
7010 Ε	7010 Ε			
503		.000875 x	878.725307 =	.768885
553		.000875 x	206.041000 =	.180286

			B.T =	.949171
7010 Γ	7010 Γ			
502		.000700 x	778.639607 =	.545048

			B.T =	.545048
7010 Δ	7010 Δ			
502		.000292 x	778.639607 =	.227363
510		.000292 x	378.798913 =	.110609
X 630.1		.060000 x	1.590955 =	.095457
X 630		.060000 x	1.353608 =	.081216

			AΘΡΟΙΣΜΑ =	.514646
	B.T =	.600000 x	.514646 =	.308787

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.830000 x	18.596033 =	15.434707
T 617		.500000 x	6.107390 =	3.053695
509		.007831 x	388.698913 =	3.043901
509		.004718 x	388.698913 =	1.833881
223		350.000000 x	.117200 =	41.020000

			B.T =	77.670070

7016.2	7016.2			
570.1		.586500 x	552.875057 =	324.261221
570.2		1.113500 x	151.502516 =	168.698052
571.1		.586500 x	390.588299 =	229.080037
571.2		1.113500 x	248.349672 =	276.537360

			AΘΡΟΙΣΜΑ =	998.576670
	B.T =	.025000 x	998.576670 =	24.964417

7016.3	7016.3			
564		.212500 x	1,715.935509 =	364.636296
565		.637500 x	712.106620 =	453.967970

			AΘΡΟΙΣΜΑ =	818.604266
	B.T =	.025000 x	818.604266 =	20.465107

7016.4	7016.4			
7016.1		1.000000 x	77.670070 =	77.670070
7016.3		1.000000 x	20.465107 =	20.465107
7016.2		1.000000 x	24.964417 =	24.964417

			B.T =	123.099594
7016.5	7016.5			
7016.4		.200000 x	123.099594 =	24.619919

			B.T =	24.619919
7016.6	7016.6			
7016.4		.250000 x	123.099594 =	30.774899
7016.5		.250000 x	24.619919 =	6.154980

			B.T =	36.929878
7016.7	7016.7			
111		5.100000 x	15.951934 =	81.354863

			B.T =	81.354863
7016.8	7016.8			
113		5.100000 x	23.479183 =	119.743833

			B.T =	119.743833

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
509		.007831 x	388.698913 =	3.043901
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.830000 x	18.596033 =	15.434707
T 617		.500000 x	6.107390 =	3.053695
509		.004718 x	388.698913 =	1.833881
223		350.000000 x	.117200 =	41.020000

			B.T =	77.670070
7017.2	7017.2			
564		.425000 x	1,715.935509 =	729.272591
565		.425000 x	712.106620 =	302.645314

			ΑΘΡΟΙΣΜΑ =	1,031.917905
	B.T =	.012500 x	1,031.917905 =	12.898974

7017.3	7017.3			
7017.1		1.000000 x	77.670070 =	77.670070
7017.2		1.000000 x	12.898974 =	12.898974

			B.T =	90.569044
7017.4	7017.4			
7017.3		.200000 x	90.569044 =	18.113809

			B.T =	18.113809
7017.5	7017.5			
7017.3		.300000 x	90.569044 =	27.170713
7017.4		.300000 x	18.113809 =	5.434143

			B.T =	32.604856
7017.6	7017.6			
111		5.100000 x	15.951934 =	81.354863

			B.T =	81.354863
7017.7	7017.7			
113		2.550000 x	23.479183 =	59.871917

			B.T =	59.871917

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
509		.007548 x	388.698913 =	2.933899
509		.004718 x	388.698913 =	1.833881
223		350.000000 x	.117200 =	41.020000

			B.T =	78.330613
7019 A2	7019 A2			
555		.012143 x	762.481702 =	9.258815

			B.T =	9.258815
7019 A3	7019 A3			
570.1		.850000 x	552.875057 =	469.943798
571.2		.850000 x	248.349672 =	211.097221
571.1		.850000 x	390.588299 =	332.000054
570.2		.850000 x	151.502516 =	128.777139

			ΑΘΡΟΙΣΜΑ =	1,141.818212
	B.T =	.014286 x	1,141.818212 =	16.312015

7019 A4	7019 A4			
112		2.295000 x	17.729980 =	40.690304
113		1.445000 x	23.479183 =	33.927419

			B.T =	74.617724
7019 A5	7019 A5			
113		.850000 x	23.479183 =	19.957306

			B.T =	19.957306
7019 A6	7019 A6			
7019 A1		1.000000 x	78.330613 =	78.330613
7019 A4		1.000000 x	74.617724 =	74.617724
7019 A5		1.000000 x	19.957306 =	19.957306
7019 A3		1.000000 x	16.312015 =	16.312015
7019 A2		1.000000 x	9.258815 =	9.258815

			B.T =	198.476473
7019 A7	7019 A7			
7019 A6		.100000 x	198.476473 =	19.847647

			B.T =	19.847647

710	710			
397.3		.006660 x	.000000 =	.000000
111		.510000 x	15.951934 =	8.135486
113		.170000 x	23.479183 =	3.991461
252		.001000 x	210.000000 =	.210000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	353.238239 =	1.775022
509		.003750 x	388.698913 =	1.457621

			B.T =	3.232643
T 611	T 611			
111		1.275000 x	15.951934 =	20.338716

			B.T =	20.338716
T 617	T 617			
111		.085000 x	15.951934 =	1.355914
504		.004250 x	353.238239 =	1.501263
520		.005270 x	418.316892 =	2.204530
503		.001190 x	878.725307 =	1.045683

			B.T =	6.107390
T 621	T 621			
213		.100000 x	1.875000 =	.187500
111		.680000 x	15.951934 =	10.847315
508		.004250 x	596.475048 =	2.535019
116		.170000 x	22.893045 =	3.891818

			B.T =	17.461652
T 623	T 623			
213		.100000 x	1.875000 =	.187500
508		.004250 x	596.475048 =	2.535019
518		.008500 x	861.342948 =	7.321415
509		.004250 x	388.698913 =	1.651970
116		.170000 x	22.893045 =	3.891818
504		.004250 x	353.238239 =	1.501263
112		.085000 x	17.729980 =	1.507048

			B.T =	18.596033

T 625	T 625			
213		.100000 x	1.875000 =	.187500
518		.012155 x	861.342948 =	10.469624
509		.004250 x	388.698913 =	1.651970
508		.004250 x	596.475048 =	2.535019
504		.004250 x	353.238239 =	1.501263
112		.085000 x	17.729980 =	1.507048
116		.170000 x	22.893045 =	3.891818

			B.T =	21.744241
T 630	T 630			
512		.017000 x	96.686284 =	1.643667

			B.T =	1.643667
T 630.1	T 630.1			
510		.005100 x	378.798913 =	1.931874

			B.T =	1.931874
X 611	X 611			
111		1.050000 x	15.951934 =	16.749531

			B.T =	16.749531
X 617	X 617			
111		.070000 x	15.951934 =	1.116635
520		.004340 x	418.316892 =	1.815495
503		.000980 x	878.725307 =	.861151
504		.003500 x	353.238239 =	1.236334

			B.T =	5.029615
X 621	X 621			
213		.100000 x	1.875000 =	.187500
508		.003500 x	596.475048 =	2.087663
111		.560000 x	15.951934 =	8.933083
116		.140000 x	22.893045 =	3.205026

			B.T =	14.413272
X 623	X 623			
213		.100000 x	1.875000 =	.187500
112		.070000 x	17.729980 =	1.241099
116		.140000 x	22.893045 =	3.205026
508		.003500 x	596.475048 =	2.087663
509		.003500 x	388.698913 =	1.360446
518		.007000 x	861.342948 =	6.029401
504		.003500 x	353.238239 =	1.236334

			B.T =	15.347468

X 625	X 625			
213		.100000 x	1.875000 =	.187500
112		.070000 x	17.729980 =	1.241099
508		.003500 x	596.475048 =	2.087663
518		.010010 x	861.342948 =	8.622043
509		.003500 x	388.698913 =	1.360446
504		.003500 x	353.238239 =	1.236334
116		.140000 x	22.893045 =	3.205026

			B.T =	17.940111
X 630	X 630			
512		.014000 x	96.686284 =	1.353608

			B.T =	1.353608
X 630.1	X 630.1			
510		.004200 x	378.798913 =	1.590955

			B.T =	1.590955
2522	2522			
221		300.000000 x	.097700 =	29.310000
112		1.190000 x	17.729980 =	21.098676
113		1.360000 x	23.479183 =	31.931689
509		.004718 x	388.698913 =	1.833881
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
509		.007548 x	388.698913 =	2.933899
509		.001275 x	388.698913 =	.495591
T 625		.500000 x	21.744241 =	10.872121
641		3.000000 x	6.807425 =	20.422275
T 630		.250000 x	1.643667 =	.410917

			T.E =	158.513649
6021	6021			
111		4.250000 x	15.951934 =	67.795720
509		.019380 x	388.698913 =	7.532985

			T.E =	75.328704
6022	6022			
111		2.550000 x	15.951934 =	40.677432
509		.008075 x	388.698913 =	3.138744

			T.E =	43.816175
6051	6051			
502		.000175 x	778.639607 =	.136262

			T.E =	.136262

6052	6052			
501		.000117 x	592.508465 =	.069323
502		.000088 x	778.639607 =	.068520
521		.000088 x	425.027007 =	.037402

			T.E =	.175246
6053	6053			
502		.000318 x	778.639607 =	.247607
507		.001000 x	918.107524 =	.918108

			T.E =	1.165715
6054	6054			
112		.004900 x	17.729980 =	.086877
509		.002975 x	388.698913 =	1.156379
507		.001077 x	918.107524 =	.988802

			T.E =	2.232058
6055	6055			
213		.400000 x	1.875000 =	.750000
503		.001167 x	878.725307 =	1.025472
508		.007000 x	596.475048 =	4.175325
504		.001400 x	353.238239 =	.494534
112		.490000 x	17.729980 =	8.687690
116		.280000 x	22.893045 =	6.410053

			T.E =	21.543074
6056	6056			
507		.001750 x	918.107524 =	1.606688

			T.E =	1.606688
6057	6057			
506		.087500 x	693.836224 =	60.710670

			T.E =	60.710670
6058	6058			
507		.087500 x	918.107524 =	80.334408

			T.E =	80.334408
6059	6059			
112		.070000 x	17.729980 =	1.241099

			T.E =	1.241099

6060	6060			
112		.350000 x	17.729980 =	6.205493

			T.E =	6.205493
6061	6061			
112		.007000 x	17.729980 =	.124110
507		.001077 x	918.107524 =	.988802
509		.002975 x	388.698913 =	1.156379
501		.000583 x	592.508465 =	.345432
502		.001400 x	778.639607 =	1.090095

			T.E =	3.704819
6062	6062			
213		.400000 x	1.875000 =	.750000
509		.002800 x	388.698913 =	1.088357
508		.002800 x	596.475048 =	1.670130
507		.001400 x	918.107524 =	1.285351
502		.002000 x	778.639607 =	1.557279
116		.175000 x	22.893045 =	4.006283
112		.175000 x	17.729980 =	3.102747

			T.E =	13.460146
6063	6063			
112		.700000 x	17.729980 =	12.410986
112		.070000 x	17.729980 =	1.241099
509		.003641 x	388.698913 =	1.415253
112		.070000 x	17.729980 =	1.241099
112		.140000 x	17.729980 =	2.482197

			T.E =	18.790633
6064	6064			
112		.140000 x	17.729980 =	2.482197
509		.003641 x	388.698913 =	1.415253
507		.014000 x	918.107524 =	12.853505
112		.070000 x	17.729980 =	1.241099

			T.E =	17.992054
6065	6065			
506		.002800 x	693.836224 =	1.942741
506		.002100 x	693.836224 =	1.457056

			T.E =	3.399797

6066	6066				
111		.070000 x	15.951934 =	1.116635	
502		.000700 x	778.639607 =	.545048	

				T.E =	1.661683
6067	6067				
111		.980000 x	15.951934 =	15.632895	
X 630		.100000 x	1.353608 =	.135361	
X 630.1		.100000 x	1.590955 =	.159096	

				T.E =	15.927352
6068	6068				
111		.560000 x	15.951934 =	8.933083	
622		1.351351 x	13.056296 =	17.643639	
X 630.1		.200000 x	1.590955 =	.318191	
X 630		.200000 x	1.353608 =	.270722	
112		.560000 x	17.729980 =	9.928789	
509		.016497 x	388.698913 =	6.412366	

				T.E =	43.506789
6068.1	6068.1				
111		.560000 x	15.951934 =	8.933083	
X 630.1		.200000 x	1.590955 =	.318191	
X 630		.200000 x	1.353608 =	.270722	
614		1.351351 x	8.314207 =	11.235412	
509		.016497 x	388.698913 =	6.412366	
112		.560000 x	17.729980 =	9.928789	

				T.E =	37.098562
6069	6069				
112		.070000 x	17.729980 =	1.241099	
509		.012017 x	388.698913 =	4.670995	
X 625		1.050000 x	17.940111 =	18.837117	

				T.E =	24.749210
6069.1	6069.1				
112		.070000 x	17.729980 =	1.241099	
509		.012017 x	388.698913 =	4.670995	
X 617		1.050000 x	5.029615 =	5.281096	

				T.E =	11.193189
6070	6070				
501		.000467 x	592.508465 =	.276701	

				T.E =	.276701

6071	6071			
504		.002333 x	353.238239 =	.824105
509		.002975 x	388.698913 =	1.156379

			T.E =	1.980484
6072	6072			
504		.003500 x	353.238239 =	1.236334
509		.002800 x	388.698913 =	1.088357

			T.E =	2.324691
6073	6073			
509		.000833 x	388.698913 =	.323786

			T.E =	.323786
6074	6074			
509		.000784 x	388.698913 =	.304740

			T.E =	.304740
6075	6075			
509		.001096 x	388.698913 =	.426014

			T.E =	.426014
6076	6076			
112		.004900 x	17.729980 =	.086877
503		.000700 x	878.725307 =	.615108
509		.003914 x	388.698913 =	1.521368
507		.000840 x	918.107524 =	.771210

			T.E =	2.994562
6077	6077			
503		.001400 x	878.725307 =	1.230215

			T.E =	1.230215
6078	6078			
112		.004900 x	17.729980 =	.086877
505		.001400 x	791.488174 =	1.108083
501		.000056 x	592.508465 =	.033180
503		.000350 x	878.725307 =	.307554

			T.E =	1.535695

6078.1	6078.1			
112		.004900 x	17.729980 =	.086877
501		.000056 x	592.508465 =	.033180
503		.000350 x	878.725307 =	.307554
556		.001400 x	1,079.237174 =	1.510932

			T.E =	1.938543
6079	6079			
112		.014000 x	17.729980 =	.248220
501		.000700 x	592.508465 =	.414756
529		.000980 x	435.242707 =	.426538
X 630		.150000 x	1.353608 =	.203041
509		.000630 x	388.698913 =	.244880
502		.000350 x	778.639607 =	.272524

			T.E =	1.809959
6080	6080			
112		.014000 x	17.729980 =	.248220
X 630.1		.100000 x	1.590955 =	.159096
X 630		.100000 x	1.353608 =	.135361
529		.000700 x	435.242707 =	.304670
502		.000292 x	778.639607 =	.227363
501		.000583 x	592.508465 =	.345432

			T.E =	1.420141
6081.1	6081.1			
111		.420000 x	15.951934 =	6.699812
112		.280000 x	17.729980 =	4.964394
112		.420000 x	17.729980 =	7.446592
506		.007000 x	693.836224 =	4.856854

			T.E =	23.967652
6081.2	6081.2			
111		.700000 x	15.951934 =	11.166354
112		.070000 x	17.729980 =	1.241099
6081.1		1.000000 x	23.967652 =	23.967652

			T.E =	36.375104
6081.3	6081.3			
111		1.400000 x	15.951934 =	22.332708
6081.1		1.000000 x	23.967652 =	23.967652
112		.140000 x	17.729980 =	2.482197

			T.E =	48.782557

6081.4	6081.4			
111		2.100000 x	15.951934 =	33.499061
6081.1		1.000000 x	23.967652 =	23.967652
112		.210000 x	17.729980 =	3.723296

			T.E =	61.190009
6082.1	6082.1			
213		.400000 x	1.875000 =	.750000
111		1.400000 x	15.951934 =	22.332708
116		.700000 x	22.893045 =	16.025132
508		.070000 x	596.475048 =	41.753253
116		1.400000 x	22.893045 =	32.050263

			T.E =	112.911355
6082.2	6082.2			
111		.700000 x	15.951934 =	11.166354
6082.1		1.000000 x	112.911355 =	112.911355
112		.140000 x	17.729980 =	2.482197

			T.E =	126.559906
6082.3	6082.3			
111		1.400000 x	15.951934 =	22.332708
6082.1		1.000000 x	112.911355 =	112.911355
112		.280000 x	17.729980 =	4.964394

			T.E =	140.208457
6082.4	6082.4			
111		2.100000 x	15.951934 =	33.499061
112		.420000 x	17.729980 =	7.446592
6082.1		1.000000 x	112.911355 =	112.911355

			T.E =	153.857008
6083.1	6083.1			
111		.280000 x	15.951934 =	4.466542
112		.280000 x	17.729980 =	4.964394
506		.005833 x	693.836224 =	4.047147
112		.140000 x	17.729980 =	2.482197

			T.E =	15.960280
6083.2	6083.2			
111		.560000 x	15.951934 =	8.933083
6083.1		1.000000 x	15.960280 =	15.960280
112		.070000 x	17.729980 =	1.241099

			T.E =	26.134462

6083.3	6083.3			
111		1.120000 x	15.951934 =	17.866166
112		.140000 x	17.729980 =	2.482197
6083.1		1.000000 x	15.960280 =	15.960280

			T.E =	36.308643
6083.4	6083.4			
111		1.680000 x	15.951934 =	26.799249
112		.210000 x	17.729980 =	3.723296
6083.1		1.000000 x	15.960280 =	15.960280

			T.E =	46.482825
6084.1	6084.1			
213		.400000 x	1.875000 =	.750000
111		1.470000 x	15.951934 =	23.449343
116		.700000 x	22.893045 =	16.025132
508		.035000 x	596.475048 =	20.876627
116		1.050000 x	22.893045 =	24.037697

			T.E =	85.138798
6084.2	6084.2			
111		.560000 x	15.951934 =	8.933083
112		.105000 x	17.729980 =	1.861648
6084.1		1.000000 x	85.138798 =	85.138798

			T.E =	95.933529
6084.3	6084.3			
111		1.120000 x	15.951934 =	17.866166
112		.210000 x	17.729980 =	3.723296
6084.1		1.000000 x	85.138798 =	85.138798

			T.E =	106.728260
6084.4	6084.4			
111		1.680000 x	15.951934 =	26.799249
112		.315000 x	17.729980 =	5.584944
6084.1		1.000000 x	85.138798 =	85.138798

			T.E =	117.522991
6085.1	6085.1			
111		.140000 x	15.951934 =	2.233271
506		.004666 x	693.836224 =	3.237440
502		.001400 x	778.639607 =	1.090095
112		.140000 x	17.729980 =	2.482197

			T.E =	9.043003

6085.2	6085.2			
111		.350000 x	15.951934 =	5.583177
112		.070000 x	17.729980 =	1.241099
6085.1		1.000000 x	9.043003 =	9.043003

			T.E =	15.867279
6085.3	6085.3			
111		.700000 x	15.951934 =	11.166354
112		.140000 x	17.729980 =	2.482197
6085.1		1.000000 x	9.043003 =	9.043003

			T.E =	22.691554
6085.4	6085.4			
111		1.050000 x	15.951934 =	16.749531
112		.210000 x	17.729980 =	3.723296
6085.1		1.000000 x	9.043003 =	9.043003

			T.E =	29.515830
6086.1	6086.1			
213		.400000 x	1.875000 =	.750000
508		.008750 x	596.475048 =	5.219157
111		1.120000 x	15.951934 =	17.866166
116		.490000 x	22.893045 =	11.217592
116		.280000 x	22.893045 =	6.410053

			T.E =	41.462967
6086.2	6086.2			
111		.350000 x	15.951934 =	5.583177
112		.105000 x	17.729980 =	1.861648
6086.1		1.000000 x	41.462967 =	41.462967

			T.E =	48.907792
6086.3	6086.3			
111		.700000 x	15.951934 =	11.166354
6086.1		1.000000 x	41.462967 =	41.462967
112		.210000 x	17.729980 =	3.723296

			T.E =	56.352617
6086.4	6086.4			
111		1.050000 x	15.951934 =	16.749531
6086.1		1.000000 x	41.462967 =	41.462967
112		.315000 x	17.729980 =	5.584944

			T.E =	63.797441

6087	6087				
252		.001000 x	210.000000 =		.210000
113		.210000 x	23.479183 =		4.930628
112		.350000 x	17.729980 =		6.205493
111		.210000 x	15.951934 =		3.349906

			T.E =		14.696028
6088	6088				
6081.1		1.000000 x	23.967652 =		23.967652
6081.1		.900000 x	23.967652 =		21.570887

			T.E =		45.538539
6089	6089				
6082.1		1.000000 x	112.911355 =		112.911355
6082.1		.900000 x	112.911355 =		101.620220

			T.E =		214.531575
6090	6090				
6083.1		1.000000 x	15.960280 =		15.960280
6083.1		1.300000 x	15.960280 =		20.748364

			T.E =		36.708644
6091	6091				
6084.1		1.000000 x	85.138798 =		85.138798
6084.1		1.300000 x	85.138798 =		110.680437

			T.E =		195.819235
6100	6100				
231		.200000 x	.710000 =		.142000
111		.175000 x	15.951934 =		2.791588
251		.002000 x	290.000000 =		.580000
113		.105000 x	23.479183 =		2.465314
252.1		.002000 x	.000000 =		.000000

			T.E =		
6101	6101				
231		15.000000 x	.710000 =		10.650000
252		.018000 x	210.000000 =		3.780000
113		3.500000 x	23.479183 =		82.177141
112		3.500000 x	17.729980 =		62.054930
252.1		.020000 x	.000000 =		.000000
251		.068000 x	290.000000 =		19.720000

			T.E =		

6102	6102			
244		1.000000 x	2.470000 =	2.470000
112		.002100 x	17.729980 =	.037233
112		.001400 x	17.729980 =	.024822
506		.000070 x	693.836224 =	.048569
509		.000051 x	388.698913 =	.019824
506		.000070 x	693.836224 =	.048569

			T.E =	2.649016
6103	6103			
244		.125000 x	2.470000 =	.308750
112		.002800 x	17.729980 =	.049644
112		.004200 x	17.729980 =	.074466
509		.000102 x	388.698913 =	.039647
506		.000140 x	693.836224 =	.097137
506		.000140 x	693.836224 =	.097137

			T.E =	.666781
6104	6104			
236		3.000000 x	.613000 =	1.839000
517		.017500 x	2,096.018837 =	36.680330
111		.280000 x	15.951934 =	4.466542
113		.280000 x	23.479183 =	6.574171

			T.E =	49.560042
6105	6105			
111		.210000 x	15.951934 =	3.349906
517		.014000 x	2,096.018837 =	29.344264
113		.140000 x	23.479183 =	3.287086

			T.E =	35.981255
6106	6106			
512		.087500 x	96.686284 =	8.460050

			T.E =	8.460050
6107	6107			
513		.087500 x	145.084426 =	12.694887

			T.E =	12.694887
6108	6108			
514		.087500 x	194.541758 =	17.022404

			T.E =	17.022404

6109	6109			
515		.087500 x	264.349069 =	23.130544

			T.E =	23.130544
6110	6110			
516		.087500 x	338.556379 =	29.623683

			T.E =	29.623683
6120	6120			
112		.004200 x	17.729980 =	.074466
502		.001750 x	778.639607 =	1.362619
501		.000070 x	592.508465 =	.041476

			T.E =	1.478561
6121	6121			
112		.004200 x	17.729980 =	.074466
509		.003113 x	388.698913 =	1.210020
502		.000315 x	778.639607 =	.245271
505		.000420 x	791.488174 =	.332425
507		.000875 x	918.107524 =	.803344
501		.000049 x	592.508465 =	.029033

			T.E =	2.694559
6151	6151			
243		1.020000 x	2.050000 =	2.091000
243		.080000 x	2.050000 =	.164000

			T.E =	2.255000
6152	6152			
112		.085000 x	17.729980 =	1.507048
113		.085000 x	23.479183 =	1.995731

			T.E =	3.502779
6153	6153			
111		.425000 x	15.951934 =	6.779572
T 611		1.050000 x	20.338716 =	21.355652
509		.003570 x	388.698913 =	1.387655
112		.425000 x	17.729980 =	7.535242

			T.E =	37.058120

6154	6154			
111		.425000 x	15.951934 =	6.779572
T 621		1.050000 x	17.461652 =	18.334735
112		.425000 x	17.729980 =	7.535242
509		.003570 x	388.698913 =	1.387655

T.E = 34.037203

6155	6155			
111		.680000 x	15.951934 =	10.847315
T 621		.350000 x	17.461652 =	6.111578
652		.100000 x	148.360619 =	14.836062
509		.003220 x	388.698913 =	1.251610
113		1.275000 x	23.479183 =	29.935958

T.E = 62.982524

6156	6156			
251		.000500 x	290.000000 =	.145000
652		.010000 x	148.360619 =	1.483606
113		.680000 x	23.479183 =	15.965844
112		.425000 x	17.729980 =	7.535242

T.E = 25.129692

6157	6157			
111		.420000 x	15.951934 =	6.699812
509		.002940 x	388.698913 =	1.142775
112		.420000 x	17.729980 =	7.446592
X 621		1.050000 x	14.413272 =	15.133936

T.E = 30.423114

6157.1	6157.1			
111		.420000 x	15.951934 =	6.699812
509		.002940 x	388.698913 =	1.142775
X 611		1.050000 x	16.749531 =	17.587008
112		.420000 x	17.729980 =	7.446592

T.E = 32.876186

6158	6158			
111		.560000 x	15.951934 =	8.933083
621.1		1.050000 x	15.649606 =	16.432086
509		.002940 x	388.698913 =	1.142775
504		.001400 x	353.238239 =	.494534

T.E = 27.002478

6201.1	6201.1			
261.1		1.000000 x	13.000000 =	13.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326

			T.E =	23.412984
6201.2	6201.2			
261		1.000000 x	14.500000 =	14.500000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326

			T.E =	24.912984
6201.3	6201.3			
261.2		1.000000 x	19.900000 =	19.900000
113		.212500 x	23.479183 =	4.989326
111		.340000 x	15.951934 =	5.423658

			T.E =	30.312984
6201.4	6201.4			
262		1.000000 x	25.300000 =	25.300000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326

			T.E =	35.712984
6201.5	6201.5			
263		1.000000 x	31.200000 =	31.200000
111		.850000 x	15.951934 =	13.559144
113		.637500 x	23.479183 =	14.967979

			T.E =	59.727123
6201.6	6201.6			
263.2		1.000000 x	44.900000 =	44.900000
111		.850000 x	15.951934 =	13.559144
113		.637500 x	23.479183 =	14.967979

			T.E =	73.427123
6201.7	6201.7			
264		1.000000 x	61.600000 =	61.600000
113		.637500 x	23.479183 =	14.967979
111		.850000 x	15.951934 =	13.559144

			T.E =	90.127123

6202.1	6202.1				
281.1		1.000000 x	16.900000 =	16.900000	
111		.340000 x	15.951934 =	5.423658	
113		.212500 x	23.479183 =	4.989326	
			T.E =	27.312984	
6202.2	6202.2				
281		1.000000 x	20.500000 =	20.500000	
111		.340000 x	15.951934 =	5.423658	
113		.212500 x	23.479183 =	4.989326	
			T.E =	30.912984	
6202.3	6202.3				
281.2		1.000000 x	25.390000 =	25.390000	
111		.340000 x	15.951934 =	5.423658	
113		.212500 x	23.479183 =	4.989326	
			T.E =	35.802984	
6202.4	6202.4				
282		1.000000 x	28.900000 =	28.900000	
113		.212500 x	23.479183 =	4.989326	
111		.340000 x	15.951934 =	5.423658	
			T.E =	39.312984	
6202.5	6202.5				
283		1.000000 x	34.900000 =	34.900000	
111		.850000 x	15.951934 =	13.559144	
113		.637500 x	23.479183 =	14.967979	
			T.E =	63.427123	
6202.6	6202.6				
283.1		1.000000 x	53.400000 =	53.400000	
111		.850000 x	15.951934 =	13.559144	
113		.637500 x	23.479183 =	14.967979	
			T.E =	81.927123	
6202.7	6202.7				
284		1.000000 x	72.500000 =	72.500000	
111		.850000 x	15.951934 =	13.559144	
113		.637500 x	23.479183 =	14.967979	
			T.E =	101.027123	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.255000 x	15.951934 =	4.067743

T.E =

6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326

T.E =

6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326

T.E =

6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326

T.E =

6204	6204			
111		.210000 x	15.951934 =	3.349906
X 625		.700000 x	17.940111 =	12.558078
X 623		.400000 x	15.347468 =	6.138987
509		.005439 x	388.698913 =	2.114133
509		.003108 x	388.698913 =	1.208076
112		.420000 x	17.729980 =	7.446592

T.E = 32.815772

6204.1	6204.1			
111		.210000 x	15.951934 =	3.349906
112		.420000 x	17.729980 =	7.446592
509		.008702 x	388.698913 =	3.382458
613		1.050000 x	5.363065 =	5.631218

T.E = 19.810174

6205	6205				
111		.210000 x	15.951934 =	3.349906	
112		.070000 x	17.729980 =	1.241099	
509		.002800 x	388.698913 =	1.088357	
613		1.000000 x	5.363065 =	5.363065	

			T.E =	11.042427	
6251	6251				
509		.002800 x	388.698913 =	1.088357	
613		1.000000 x	5.363065 =	5.363065	

			T.E =	6.451422	
6252	6252				
509		.000784 x	388.698913 =	.304740	

			T.E =	.304740	
6253	6253				
112		.210000 x	17.729980 =	3.723296	
X 630.1		.200000 x	1.590955 =	.318191	
501		.002917 x	592.508465 =	1.728347	
521		.007000 x	425.027007 =	2.975189	
X 630		.200000 x	1.353608 =	.270722	

			T.E =	9.015745	
6301	6301				
231		.200000 x	.710000 =	.142000	
252		.002500 x	210.000000 =	.525000	
113		.127500 x	23.479183 =	2.993596	
111		.170000 x	15.951934 =	2.711829	
251		.001500 x	290.000000 =	.435000	

			T.E =	6.807425	
6302	6302				
231		.300000 x	.710000 =	.213000	
251		.002000 x	290.000000 =	.580000	
111		.212500 x	15.951934 =	3.389786	
252		.004000 x	210.000000 =	.840000	
113		1.232500 x	23.479183 =	28.938093	

			T.E =	33.960879	
6303	6303				
6302		.666660 x	33.960879 =	22.640360	

			T.E =	22.640360	

6304	6304			
234.2		.018000 x	.742000 =	.013356
112		.212500 x	17.729980 =	3.767621
113		.010200 x	23.479183 =	.239488
113		.085000 x	23.479183 =	1.995731
235		.012000 x	.623000 =	.007476

			T.E =	6.023671
6310	6310			
233		1.050000 x	.536700 =	.563535
113		.042500 x	23.479183 =	.997865

			T.E =	1.561400
6311	6311			
233.1		1.050000 x	.536700 =	.563535
113		.042500 x	23.479183 =	.997865

			T.E =	1.561400
6312	6312			
233.3		1.010000 x	7.500000 =	7.575000
233.3		.303000 x	7.500000 =	2.272500
113		.085000 x	23.479183 =	1.995731
113		.085000 x	23.479183 =	1.995731

			T.E =	13.838961
6313	6313			
233.2		1.050000 x	.555400 =	.583170
113		.025500 x	23.479183 =	.598719

			T.E =	1.181889
6314	6314			
233.2		1.050000 x	.555400 =	.583170
113		.068000 x	23.479183 =	1.596584

			T.E =	2.179754
6320.1	6320.1			
396.1		1.000000 x	1.400000 =	1.400000
113		.000850 x	23.479183 =	.019957

			T.E =	1.419957

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	23.479183 =	.019957

			T.E =	.789957
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	23.479183 =	.019957

			T.E =	1.699957
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	23.479183 =	.019957

			T.E =	.999957
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	23.479183 =	.019957

			T.E =	1.199957
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	23.479183 =	.019957

			T.E =	1.599957
6321	6321			
221		140.000000 x	.097700 =	13.678000
111		.765000 x	15.951934 =	12.203230
113		.595000 x	23.479183 =	13.970114
509		.003302 x	388.698913 =	1.283484
509		.003019 x	388.698913 =	1.173482
T 630.1		.175000 x	1.931874 =	.338078
T 630		.175000 x	1.643667 =	.287642
T 625		.350000 x	21.744241 =	7.610484
T 623		.560000 x	18.596033 =	10.413778
T 621		.300000 x	17.461652 =	5.238496
511		.023800 x	715.522746 =	17.029441
509		.005284 x	388.698913 =	2.053885
112		.714000 x	17.729980 =	12.659206

			T.E =	97.939319

6322	6322			
221		140.000000 x	.097700 =	13.678000
509		.003019 x	388.698913 =	1.173482
T 623		.560000 x	18.596033 =	10.413778
T 630.1		.175000 x	1.931874 =	.338078
T 630		.175000 x	1.643667 =	.287642
T 625		.350000 x	21.744241 =	7.610484
511		.023800 x	715.522746 =	17.029441
T 611		.300000 x	20.338716 =	6.101615
509		.003302 x	388.698913 =	1.283484
509		.005284 x	388.698913 =	2.053885
113		.595000 x	23.479183 =	13.970114
111		.765000 x	15.951934 =	12.203230
112		.714000 x	17.729980 =	12.659206

T.E = 98.802439

6323	6323			
221		150.000000 x	.097700 =	14.655000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
509		.007548 x	388.698913 =	2.933899
113		.850000 x	23.479183 =	19.957306
112		1.020000 x	17.729980 =	18.084580

T.E = 108.435272

6323.1	6323.1			
221		150.000000 x	.097700 =	14.655000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
112		1.020000 x	17.729980 =	18.084580
509		.007548 x	388.698913 =	2.933899
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
113		.850000 x	23.479183 =	19.957306

T.E = 100.616846

6324	6324			
221		200.000000 x	.097700 =	19.540000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
112		1.020000 x	17.729980 =	18.084580
509		.004718 x	388.698913 =	1.833881
113		.850000 x	23.479183 =	19.957306
509		.007548 x	388.698913 =	2.933899

T.E = 113.320272

6324.1	6324.1			
221		200.000000 x	.097700 =	19.540000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
112		1.020000 x	17.729980 =	18.084580
509		.007548 x	388.698913 =	2.933899
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
113		.850000 x	23.479183 =	19.957306

T.E = 105.501846

6325	6325			
221		250.000000 x	.097700 =	24.425000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
509		.007548 x	388.698913 =	2.933899
113		.850000 x	23.479183 =	19.957306
112		1.020000 x	17.729980 =	18.084580

T.E = 118.205272

6325.1

6325.1

221	250.000000 x	.097700 =	24.425000
T 630.1	.250000 x	1.931874 =	.482969
T 630	.250000 x	1.643667 =	.410917
T 623	.800000 x	18.596033 =	14.876826
T 617	.500000 x	6.107390 =	3.053695
112	1.020000 x	17.729980 =	18.084580
509	.007548 x	388.698913 =	2.933899
511	.034000 x	715.522746 =	24.327773
509	.004718 x	388.698913 =	1.833881
113	.850000 x	23.479183 =	19.957306

T.E =

110.386846

6326

6326

221	300.000000 x	.097700 =	29.310000
T 630.1	.250000 x	1.931874 =	.482969
T 630	.250000 x	1.643667 =	.410917
T 625	.500000 x	21.744241 =	10.872121
T 623	.800000 x	18.596033 =	14.876826
511	.034000 x	715.522746 =	24.327773
509	.004718 x	388.698913 =	1.833881
509	.007548 x	388.698913 =	2.933899
113	1.360000 x	23.479183 =	31.931689
112	1.190000 x	17.729980 =	21.098676

T.E =

138.078751

6326.1

6326.1

221	300.000000 x	.097700 =	29.310000
T 630.1	.250000 x	1.931874 =	.482969
T 630	.250000 x	1.643667 =	.410917
T 623	.800000 x	18.596033 =	14.876826
T 617	.500000 x	6.107390 =	3.053695
112	1.190000 x	17.729980 =	21.098676
509	.007548 x	388.698913 =	2.933899
511	.034000 x	715.522746 =	24.327773
509	.004718 x	388.698913 =	1.833881
113	1.360000 x	23.479183 =	31.931689

T.E =

130.260326

6327	6327			
222		300.000000 x	.114100 =	34.230000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
509		.007548 x	388.698913 =	2.933899
113		1.275000 x	23.479183 =	29.935958
112		2.295000 x	17.729980 =	40.690304

T.E = 160.594649

6327.1	6327.1			
222		300.000000 x	.114100 =	34.230000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	388.698913 =	2.933899
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
113		1.275000 x	23.479183 =	29.935958

T.E = 152.776223

6328	6328			
221		350.000000 x	.097700 =	34.195000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	388.698913 =	2.933899
113		1.445000 x	23.479183 =	33.927419
509		.004718 x	388.698913 =	1.833881

T.E = 164.551110

6328.1	6328.1			
221		350.000000 x	.097700 =	34.195000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	388.698913 =	2.933899
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
113		1.445000 x	23.479183 =	33.927419

T.E = 156.732684

6329	6329			
222		350.000000 x	.114100 =	39.935000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
509		.007548 x	388.698913 =	2.933899
509		.004718 x	388.698913 =	1.833881
113		1.445000 x	23.479183 =	33.927419
112		2.295000 x	17.729980 =	40.690304

T.E = 170.291110

6329.1	6329.1			
222		350.000000 x	.114100 =	39.935000
112		2.295000 x	17.729980 =	40.690304
113		1.445000 x	23.479183 =	33.927419
509		.007548 x	388.698913 =	2.933899
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881

T.E = 162.472684

6329.2	6329.2			
223		350.000000 x	.117200 =	41.020000
112		2.295000 x	17.729980 =	40.690304
T 625		.500000 x	21.744241 =	10.872121
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
113		1.445000 x	23.479183 =	33.927419
511		.034000 x	715.522746 =	24.327773
509		.007548 x	388.698913 =	2.933899
509		.004718 x	388.698913 =	1.833881

T.E = 171.376110

6329.3	6329.3			
223		350.000000 x	.117200 =	41.020000
112		2.295000 x	17.729980 =	40.690304
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
511		.034000 x	715.522746 =	24.327773
509		.007548 x	388.698913 =	2.933899
509		.004718 x	388.698913 =	1.833881
113		1.445000 x	23.479183 =	33.927419

T.E = 163.557684

6330	6330			
223		420.000000 x	.117200 =	49.224000
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	388.698913 =	2.933899
509		.004718 x	388.698913 =	1.833881
113		1.445000 x	23.479183 =	33.927419
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.042500 x	715.522746 =	30.409717

T.E = 185.662053

6330.1	6330.1			
223		420.000000 x	.117200 =	49.224000
113		1.445000 x	23.479183 =	33.927419
509		.004718 x	388.698913 =	1.833881
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	388.698913 =	2.933899
511		.042500 x	715.522746 =	30.409717
T 617		.500000 x	6.107390 =	3.053695
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826

T.E = 177.843628

6331	6331			
222		450.000000 x	.114100 =	51.345000
113		5.525000 x	23.479183 =	129.722486
111		3.825000 x	15.951934 =	61.016148
T 623		.800000 x	18.596033 =	14.876826
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
509		.004718 x	388.698913 =	1.833881
511		.042500 x	715.522746 =	30.409717
509		.007548 x	388.698913 =	2.933899
112		3.400000 x	17.729980 =	60.281932

T.E = 364.185895

6331.1	6331.1			
222		450.000000 x	.114100 =	51.345000
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
511		.042500 x	715.522746 =	30.409717
509		.007548 x	388.698913 =	2.933899
509		.004718 x	388.698913 =	1.833881
113		5.525000 x	23.479183 =	129.722486
112		3.400000 x	17.729980 =	60.281932
111		3.825000 x	15.951934 =	61.016148

T.E = 356.367470

6351	6351			
221		120.000000 x	.097700 =	11.724000
509		.004246 x	388.698913 =	1.650416
509		.008020 x	388.698913 =	3.117365
6301		1.000000 x	6.807425 =	6.807425
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.450000 x	21.744241 =	9.784908
T 623		.850000 x	18.596033 =	15.806628
511		.034000 x	715.522746 =	24.327773
113		1.275000 x	23.479183 =	29.935958
112		1.275000 x	17.729980 =	22.605725

T.E = 126.654084

6351.1	6351.1			
221		120.000000 x	.097700 =	11.724000
509		.004246 x	388.698913 =	1.650416
6301		1.000000 x	6.807425 =	6.807425
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.850000 x	18.596033 =	15.806628
T 617		.450000 x	6.107390 =	2.748326
511		.034000 x	715.522746 =	24.327773
509		.008020 x	388.698913 =	3.117365
112		1.275000 x	17.729980 =	22.605725
113		1.275000 x	23.479183 =	29.935958

T.E = 119.617501

6352	6352			
221		300.000000 x	.097700 =	29.310000
112		2.125000 x	17.729980 =	37.676208
6301		1.000000 x	6.807425 =	6.807425
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 625		.500000 x	21.744241 =	10.872121
T 623		.800000 x	18.596033 =	14.876826
511		.034000 x	715.522746 =	24.327773
509		.004718 x	388.698913 =	1.833881
509		.007548 x	388.698913 =	2.933899
113		2.550000 x	23.479183 =	59.871917

T.E = 189.403936

6352.1	6352.1			
221		300.000000 x	.097700 =	29.310000
113		2.550000 x	23.479183 =	59.871917
112		2.125000 x	17.729980 =	37.676208
511		.034000 x	715.522746 =	24.327773
6301		1.000000 x	6.807425 =	6.807425
T 630.1		.250000 x	1.931874 =	.482969
T 630		.250000 x	1.643667 =	.410917
T 623		.800000 x	18.596033 =	14.876826
T 617		.500000 x	6.107390 =	3.053695
509		.007548 x	388.698913 =	2.933899
509		.004718 x	388.698913 =	1.833881
			T.E =	181.585510
6360.1	6360.1			
6360.1 A1		1.000000 x	118.871798 =	118.871798
6360.1 A2		1.000000 x	8.468777 =	8.468777
6360.1 A5		1.000000 x	110.601484 =	110.601484
6360.1 A4		1.000000 x	33.678937 =	33.678937
6360.1 A3		1.000000 x	15.205844 =	15.205844
			AΘΡΟΙΣΜΑ =	286.826840
	T.E =	.200000 x	286.826840 =	57.365368
6360.2	6360.2			
6360.2 A1		1.000000 x	127.791584 =	127.791584
6360.2 A2		1.000000 x	11.766929 =	11.766929
6360.2 A3		1.000000 x	19.777313 =	19.777313
6360.2 A4		1.000000 x	37.088660 =	37.088660
6360.2 A5		1.000000 x	124.707681 =	124.707681
			AΘΡΟΙΣΜΑ =	321.132167
	T.E =	.200000 x	321.132167 =	64.226433
6360.3	6360.3			
6360.3 A1		1.000000 x	169.403002 =	169.403002
6360.3 A2		1.000000 x	16.664078 =	16.664078
6360.3 A3		1.000000 x	44.662963 =	44.662963
6360.3 A5		1.000000 x	169.082447 =	169.082447
6360.3 A4		1.000000 x	44.422234 =	44.422234
			AΘΡΟΙΣΜΑ =	444.234724
	T.E =	.200000 x	444.234724 =	88.846945

6360.4	6360.4			
6360.4 A1		1.000000 x	221.943306 =	221.943306
6360.4 A2		1.000000 x	22.543327 =	22.543327
6360.4 A3		1.000000 x	67.032623 =	67.032623
6360.4 A5		1.000000 x	228.362983 =	228.362983
6360.4 A4		1.000000 x	37.088660 =	37.088660

			AΘΡΟΙΣΜΑ =	576.970899
	T.E =	.200000 x	576.970899 =	115.394180

6360.5	6360.5			
6360.5 A1		1.000000 x	254.218034 =	254.218034
6360.5 A2		1.000000 x	28.117611 =	28.117611
6360.5 A3		1.000000 x	74.422812 =	74.422812
6360.5 A5		1.000000 x	312.477746 =	312.477746
6360.5 A4		1.000000 x	38.469872 =	38.469872

			AΘΡΟΙΣΜΑ =	707.706075
	T.E =	.200000 x	707.706075 =	141.541215

6360.6	6360.6			
6360.6 A1		1.000000 x	308.792162 =	308.792162
6360.6 A2		1.000000 x	42.232774 =	42.232774
6360.6 A4		1.000000 x	37.088660 =	37.088660
6360.6 A3		1.000000 x	87.384055 =	87.384055
6360.6 A5		1.000000 x	412.005504 =	412.005504

			AΘΡΟΙΣΜΑ =	887.503155
	T.E =	.200000 x	887.503155 =	177.500631

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	23.479183 =	.399146
111		.085000 x	15.951934 =	1.355914

			T.E =	2.135061
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	23.479183 =	7.982922
111		.340000 x	15.951934 =	5.423658
396.14		.003000 x	48.900000 =	.146700

			T.E =	18.064280
6371	6371			
326		.500000 x	1.180000 =	.590000
113		.212500 x	23.479183 =	4.989326
111		.212500 x	15.951934 =	3.389786

			T.E =	8.969112

6372	6372				
396.11		1.050000 x	2.560000 =	2.688000	
396.13		.700000 x	1.770000 =	1.239000	
111		.340000 x	15.951934 =	5.423658	
113		.340000 x	23.479183 =	7.982922	

			T.E =	17.333580	
6373	6373				
396.12		1.050000 x	3.680000 =	3.864000	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	23.479183 =	9.978653	
111		.425000 x	15.951934 =	6.779572	

			T.E =	21.861225	
6401	6401				
327		.500000 x	.480000 =	.240000	
113		.212500 x	23.479183 =	4.989326	

			T.E =	5.229326	
6402	6402				
252		.000500 x	210.000000 =	.105000	
111		.595000 x	15.951934 =	9.491401	
113		.595000 x	23.479183 =	13.970114	
652		.011500 x	148.360619 =	1.706147	
652.2		.005500 x	167.687140 =	.922279	

			T.E =	26.194941	
6403	6403				
251		.000500 x	290.000000 =	.145000	
111		.850000 x	15.951934 =	13.559144	
113		.850000 x	23.479183 =	19.957306	
652.2		.005500 x	167.687140 =	.922279	
652		.016500 x	148.360619 =	2.447950	

			T.E =	37.031679	
6404	6404				
111		1.275000 x	15.951934 =	20.338716	
113		1.700000 x	23.479183 =	39.914611	
652		.020000 x	148.360619 =	2.967212	

			T.E =	63.220539	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	63.220539 =	63.220539	

			T.E =		

6405	6405			
111		.425000 x	15.951934 =	6.779572
113		.850000 x	23.479183 =	19.957306
652		.020000 x	148.360619 =	2.967212

			T.E =	29.704090
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	20,575.000000 =	20,575.000000
386.9		.150000 x	20,575.000000 =	3,086.250000

			T.E =	23,661.250000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	61,603.000000 =	61,603.000000
386.40		.150000 x	61,603.000000 =	9,240.450000

			T.E =	70,843.450000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	90,675.000000 =	90,675.000000
386.30		.150000 x	90,675.000000 =	13,601.250000

			T.E =	104,276.250000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17			
386.64		1.000000 x	123,215.000000 =	123,215.000000
386.64		.150000 x	123,215.000000 =	18,482.250000

			T.E =	141,697.250000
6453.18	6453.18			
386.65		1.000000 x	.000000 =	.000000
386.65		.150000 x	.000000 =	.000000

			T.E =	
6453.19	6453.19			
386.66		1.000000 x	.000000 =	.000000
386.66		.150000 x	.000000 =	.000000

			T.E =	
6453.2	6453.2			
386.49		1.000000 x	.000000 =	.000000
386.49		.150000 x	.000000 =	.000000

			T.E =	
6453.20	6453.20			
386.67		1.000000 x	.000000 =	.000000
386.67		.150000 x	.000000 =	.000000

			T.E =	
6453.3	6453.3			
386.50		1.000000 x	.000000 =	.000000
386.50		.150000 x	.000000 =	.000000

			T.E =	
6453.4	6453.4			
386.51		1.000000 x	.000000 =	.000000
386.51		.150000 x	.000000 =	.000000

			T.E =	
6453.5	6453.5			
386.52		1.000000 x	.000000 =	.000000
386.52		.150000 x	.000000 =	.000000

			T.E =	

6453.6	6453.6			
386.53		1.000000 x	107,490.000000 =	107,490.000000
386.53		.150000 x	107,490.000000 =	16,123.500000

			T.E =	123,613.500000
6453.7	6453.7			
386.54		1.000000 x	.000000 =	.000000
386.54		.150000 x	.000000 =	.000000

			T.E =	
6453.8	6453.8			
386.55		1.000000 x	.000000 =	.000000
386.55		.150000 x	.000000 =	.000000

			T.E =	
6453.9	6453.9			
386.56		1.000000 x	.000000 =	.000000
386.56		.150000 x	.000000 =	.000000

			T.E =	
6454.1	6454.1			
386.68		1.000000 x	.000000 =	.000000
386.68		.150000 x	.000000 =	.000000

			T.E =	
6454.10	6454.10			
386.77		1.000000 x	.000000 =	.000000
386.77		.150000 x	.000000 =	.000000

			T.E =	
6454.11	6454.11			
386.78		1.000000 x	.000000 =	.000000
386.78		.150000 x	.000000 =	.000000

			T.E =	
6454.12	6454.12			
386.79		1.000000 x	.000000 =	.000000
386.79		.150000 x	.000000 =	.000000

			T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000
<hr/>				
			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	17,260.000000 =	17,260.000000
387.3		.100000 x	17,260.000000 =	1,726.000000

			T.E =	18,986.000000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	.742000 =	154.336000
113		154.700001 x	23.479183 =	3,632.229634
235		338.000000 x	.623000 =	210.574000

			ΑΘΡΟΙΣΜΑ =	3,997.139634

			T.E =	5,995.709450
6456.2	6456.2			
234.2		336.000000 x	.742000 =	249.312000
113		249.900000 x	23.479183 =	5,867.447832
235		546.000000 x	.623000 =	340.158000

			ΑΘΡΟΙΣΜΑ =	6,456.917832

			T.E =	9,039.684964
6456.3	6456.3			
234.2		384.000000 x	.742000 =	284.928000
235		624.000000 x	.623000 =	388.752000
113		285.599998 x	23.479183 =	6,705.654618

			ΑΘΡΟΙΣΜΑ =	7,379.334618

			T.E =	10,331.068465
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	23.479183 =	399.146111

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	5,345.000000 =	5,345.000000
389.4		.200000 x	5,345.000000 =	1,069.000000

			T.E =	6,414.000000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	4,516.000000 =	4,516.000000
390.14		.150000 x	4,516.000000 =	677.400000

			T.E =	5,193.400000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	6,566.000000 =	6,566.000000
390.31		.150000 x	6,566.000000 =	984.900000

			T.E =	7,550.900000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	12,320.000000 =	12,320.000000
393.1		.150000 x	12,320.000000 =	1,848.000000

			T.E =	14,168.000000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.320000 =	6.320000

			T.E =	6.320000
6501	6501			
237		1.000000 x	1.060000 =	1.060000
113		.850000 x	23.479183 =	19.957306

			T.E =	21.017306
6502	6502			
112		.170000 x	17.729980 =	3.014097
517		.042500 x	2,096.018837 =	89.080801

			T.E =	92.094897
6505	6505			
233		1.050000 x	.536700 =	.563535
113		.042500 x	23.479183 =	.997865

			T.E =	1.561400

6506	6506				
233.1		1.050000 x	.536700 =	.563535	
113		.042500 x	23.479183 =	.997865	

			T.E =	1.561400	
6551.1	6551.1				
221		6.000000 x	.097700 =	.586200	
113		.255000 x	23.479183 =	5.987192	
111		.255000 x	15.951934 =	4.067743	
261		1.000000 x	14.500000 =	14.500000	

			T.E =	25.141135	
6551.2	6551.2				
221		8.000000 x	.097700 =	.781600	
262		1.000000 x	25.300000 =	25.300000	
111		.297500 x	15.951934 =	4.745700	
113		.297500 x	23.479183 =	6.985057	

			T.E =	37.812357	
6551.3	6551.3				
221		10.000000 x	.097700 =	.977000	
263		1.000000 x	31.200000 =	31.200000	
113		.340000 x	23.479183 =	7.982922	
111		.340000 x	15.951934 =	5.423658	

			T.E =	45.583580	
6551.4	6551.4				
221		13.000000 x	.097700 =	1.270100	
263.2		1.000000 x	44.900000 =	44.900000	
113		.510000 x	23.479183 =	11.974383	
111		.510000 x	15.951934 =	8.135486	

			T.E =	66.279970	
6551.5	6551.5				
221		16.000000 x	.097700 =	1.563200	
113		.595000 x	23.479183 =	13.970114	
111		.595000 x	15.951934 =	9.491401	
264		1.000000 x	61.600000 =	61.600000	

			T.E =	86.624715	

6551.6	6551.6			
221		20.000000 x	.097700 =	1.954000
265		1.000000 x	110.700000 =	110.700000
111		.850000 x	15.951934 =	13.559144
113		.850000 x	23.479183 =	19.957306

T.E = 146.170449

6551.7	6551.7			
221		26.000000 x	.097700 =	2.540200
271		1.000000 x	198.400000 =	198.400000
113		1.275000 x	23.479183 =	29.935958
111		1.275000 x	15.951934 =	20.338716

T.E = 251.214874

6552	6552			
221		26.000000 x	.097700 =	2.540200
6304		6.890000 x	6.023671 =	41.503093
6310		32.020000 x	1.561400 =	49.996028
6329.2		.418000 x	171.376110 =	71.635214
111		1.700000 x	15.951934 =	27.118288
113		1.275000 x	23.479183 =	29.935958

T.E = 222.728781

6553	6553			
113		.850000 x	23.479183 =	19.957306
6314		13.730000 x	2.179754 =	29.928022
6329.2		.478000 x	171.376110 =	81.917781
6304		9.290000 x	6.023671 =	55.959904

T.E = 187.763012

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	23.479183 =	4.689967
112		.276250 x	17.729980 =	4.897907
111		.067150 x	15.951934 =	1.071172

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.729980 =	54.344162
113		.901000 x	23.479183 =	21.154744
111		1.351500 x	15.951934 =	21.559039

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	23.479183 =	23.489749
112		3.858150 x	17.729980 =	68.404922
111		1.669400 x	15.951934 =	26.630159

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	23.479183 =	28.219630
112		5.523300 x	17.729980 =	97.927999
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.951934 =	52.189145
113		1.401650 x	23.479183 =	32.909597
112		6.712450 x	17.729980 =	119.011604
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.729980 =	155.014988
113		1.602250 x	23.479183 =	37.619521
111		4.272950 x	15.951934 =	68.161816
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	23.479183 =	5.867448
112		.379950 x	17.729980 =	6.736506
111		.104550 x	15.951934 =	1.667775
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.951934 =	2.399968
113		.300050 x	23.479183 =	7.044929
112		.488750 x	17.729980 =	8.665528

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	23.479183 =	9.399891
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.729980 =	13.563435
111		.266900 x	15.951934 =	4.257571

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.729980 =	18.024298
113		.500650 x	23.479183 =	11.754853
111		.417350 x	15.951934 =	6.657540

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	23.479183 =	14.089858
112		1.484950 x	17.729980 =	26.328134
111		.600950 x	15.951934 =	9.586315
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.951934 =	13.043896
113		.700400 x	23.479183 =	16.444820
112		1.926100 x	17.729980 =	34.149714

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	23.479183 =	18.799782
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.729980 =	43.176934
111		1.068450 x	15.951934 =	17.043844

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.729980 =	5.470585
113		.266900 x	23.479183 =	6.266594
111		.067150 x	15.951934 =	1.071172

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	23.479183 =	28.199673
112		4.232150 x	17.729980 =	75.035935
111		1.351500 x	15.951934 =	21.559039
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	23.479183 =	31.332970
112		5.156950 x	17.729980 =	91.432620
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.951934 =	26.630159

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700
113		1.602250 x	23.479183 =	37.619521
112		7.410300 x	17.729980 =	131.384471
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.729980 =	161.450084
113		1.869150 x	23.479183 =	43.886115
111		3.271650 x	15.951934 =	52.189145

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	23.479183 =	50.152709
112		11.979050 x	17.729980 =	212.388317
111		4.272950 x	15.951934 =	68.161816

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	23.479183 =	7.823264
112		.452200 x	17.729980 =	8.017497
111		.104550 x	15.951934 =	1.667775
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.951934 =	2.399968
113		.400350 x	23.479183 =	9.399891
112		.612850 x	17.729980 =	10.865818

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	23.479183 =	12.533188
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.729980 =	18.657258
111		.266900 x	15.951934 =	4.257571

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.729980 =	24.414182
113		.667250 x	23.479183 =	15.666485
111		.417350 x	15.951934 =	6.657540

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	23.479183 =	18.799782
112		1.989000 x	17.729980 =	35.264930
111		.600950 x	15.951934 =	9.586315
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.951934 =	13.043896
113		.934150 x	23.479183 =	21.933079
112		2.718300 x	17.729980 =	48.195405

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	23.479183 =	25.066376
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.729980 =	61.050598
111		1.068450 x	15.951934 =	17.043844

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.729980 =	7.068057
113		.333200 x	23.479183 =	7.823264
111		.067150 x	15.951934 =	1.071172

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	23.479183 =	35.244602
112		5.308250 x	17.729980 =	94.115166
111		1.351500 x	15.951934 =	21.559039
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	23.479183 =	39.156233
112		6.644450 x	17.729980 =	117.805966
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.951934 =	26.630159

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700
113		2.002600 x	23.479183 =	47.019412
112		9.562500 x	17.729980 =	169.542934
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.729980 =	205.486036
113		2.336650 x	23.479183 =	54.862633
111		3.271650 x	15.951934 =	52.189145

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	23.479183 =	62.685897
112		14.965950 x	17.729980 =	265.345994
111		4.272950 x	15.951934 =	68.161816

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	23.479183 =	9.779080
112		.523600 x	17.729980 =	9.283418
111		.104550 x	15.951934 =	1.667775
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	23.479183 =	11.754853
112		.748000 x	17.729980 =	13.262025
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.951934 =	2.399968

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.951934 =	4.257571
113		.667250 x	23.479183 =	15.666485
112		1.269050 x	17.729980 =	22.500231
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.729980 =	32.054917
113		.833850 x	23.479183 =	19.578117
111		.417350 x	15.951934 =	6.657540

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	23.479183 =	23.489749
112		2.597600 x	17.729980 =	46.055396
111		.600950 x	15.951934 =	9.586315

T.E =

6603.8 6603.8

366.8	1.020000 x	.000000 =	.000000
113	1.167900 x	23.479183 =	27.421338
112	3.439100 x	17.729980 =	60.975174
111	.817700 x	15.951934 =	13.043896
367.8	.224000 x	.000000 =	.000000

T.E =

6603.9 6603.9

366.9	1.020000 x	.000000 =	.000000
367.9	.224000 x	.000000 =	.000000
111	1.068450 x	15.951934 =	17.043844
113	1.334500 x	23.479183 =	31.332970
112	4.386850 x	17.729980 =	77.778763

T.E =

6604.1 6604.1

366.15	1.020000 x	.000000 =	.000000
113	.400350 x	23.479183 =	9.399891
367.15	.224000 x	.000000 =	.000000
112	.504900 x	17.729980 =	8.951867
111	.067150 x	15.951934 =	1.071172

T.E =

6604.10 6604.10

366.24	1.020000 x	.000000 =	.000000
367.24	.224000 x	.000000 =	.000000
112	6.546700 x	17.729980 =	116.072860
113	1.802000 x	23.479183 =	42.309488
111	1.351500 x	15.951934 =	21.559039

T.E =

6604.11 6604.11

366.25	1.020000 x	.000000 =	.000000
113	2.001750 x	23.479183 =	46.999455
112	8.181250 x	17.729980 =	145.053399
111	1.669400 x	15.951934 =	26.630159
367.25	.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700
113		2.403800 x	23.479183 =	56.439260
112		11.789500 x	17.729980 =	209.027599

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	23.479183 =	65.839151
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.729980 =	254.615810
111		3.271650 x	15.951934 =	52.189145

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.729980 =	331.867106
113		3.204500 x	23.479183 =	75.239042
111		4.272950 x	15.951934 =	68.161816

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	23.479183 =	11.734896
112		.647700 x	17.729980 =	11.483708
111		.104550 x	15.951934 =	1.667775
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.729980 =	16.547390
113		.600950 x	23.479183 =	14.109815
111		.150450 x	15.951934 =	2.399968

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	23.479183 =	18.799782
112		1.592900 x	17.729980 =	28.242085
111		.266900 x	15.951934 =	4.257571

T.E =

6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	23.479183 =	23.509706
112		2.094400 x	17.729980 =	37.133670
111		.417350 x	15.951934 =	6.657540

T.E =

6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	23.479183 =	28.199673
112		2.952900 x	17.729980 =	52.354858
111		.600950 x	15.951934 =	9.586315
367.21		.224000 x	.000000 =	.000000

T.E =

6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.729980 =	70.560001
113		1.401650 x	23.479183 =	32.909597
111		.817700 x	15.951934 =	13.043896
367.22		.224000 x	.000000 =	.000000

T.E =

6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.951934 =	17.043844
113		1.601400 x	23.479183 =	37.599564
112		5.210500 x	17.729980 =	92.382061
367.23		.224000 x	.000000 =	.000000

T.E =

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
113		.025500 x	23.479183 =	.598719
112		.042500 x	17.729980 =	.753524
111		.042500 x	15.951934 =	.677957

			T.E =	
6611.1	6611.1			
361.1		1.000000 x	11.750000 =	11.750000
113		.212500 x	23.479183 =	4.989326
112		.510000 x	17.729980 =	9.042290
111		.085000 x	15.951934 =	1.355914

			T.E =	27.137531
6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.951934 =	8.135486
112		2.125000 x	17.729980 =	37.676208
113		.765000 x	23.479183 =	17.961575

			T.E =	
6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.951934 =	10.169358
113		.935000 x	23.479183 =	21.953036
112		2.550000 x	17.729980 =	45.211449

			T.E =	
6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.951934 =	12.203230
113		1.105000 x	23.479183 =	25.944497
112		2.975000 x	17.729980 =	52.746691

			T.E =	
6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	23.479183 =	29.935958
112		3.400000 x	17.729980 =	60.281932
111		.892500 x	15.951934 =	14.237101

			T.E =	

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.951934 =	16.270973
112		3.825000 x	17.729980 =	67.817174
113		1.445000 x	23.479183 =	33.927419

			T.E =	
6611.2	6611.2			
361.2		1.000000 x	15.300000 =	15.300000
111		.085000 x	15.951934 =	1.355914
113		.212500 x	23.479183 =	4.989326
112		.552500 x	17.729980 =	9.795814

			T.E =	31.441055
6611.3	6611.3			
361.3		1.000000 x	19.280000 =	19.280000
111		.127500 x	15.951934 =	2.033872
113		.255000 x	23.479183 =	5.987192
112		.637500 x	17.729980 =	11.302862

			T.E =	38.603926
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	23.479183 =	6.985057
112		.680000 x	17.729980 =	12.056386
111		.170000 x	15.951934 =	2.711829

			T.E =	
6611.5	6611.5			
361.5		1.000000 x	36.800000 =	36.800000
111		.212500 x	15.951934 =	3.389786
112		.935000 x	17.729980 =	16.577531
113		.382500 x	23.479183 =	8.980787

			T.E =	65.748105
6611.6	6611.6			
361.6		1.000000 x	49.220000 =	49.220000
111		.255000 x	15.951934 =	4.067743
113		.425000 x	23.479183 =	9.978653
112		1.105000 x	17.729980 =	19.591628

			T.E =	82.858024

6611.7	6611.7			
361.7		1.000000 x	76.000000 =	76.000000
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
112		1.275000 x	17.729980 =	22.605725

T.E = 116.003765

6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	23.479183 =	14.967979
112		1.700000 x	17.729980 =	30.140966
111		.382500 x	15.951934 =	6.101615

T.E =

6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.951934 =	6.779572
112		1.870000 x	17.729980 =	33.155063
113		.680000 x	23.479183 =	15.965844

T.E =

6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.951934 =	1.288119
113		.176800 x	23.479183 =	4.151120
112		.055250 x	17.729980 =	.979581

T.E = 11.600420

6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.951934 =	2.088108
113		.224400 x	23.479183 =	5.268729
112		.089250 x	17.729980 =	1.582401

T.E = 17.150238

6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	23.479183 =	6.027106
112		.116450 x	17.729980 =	2.064656
111		.170850 x	15.951934 =	2.725388

T.E = 21.486350

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.951934 =	4.257571
112		.182750 x	17.729980 =	3.240154
113		.320450 x	23.479183 =	7.523904

			T.E =	31.606829
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.951934 =	5.396539
113		.360400 x	23.479183 =	8.461898
112		.228650 x	17.729980 =	4.053960

			T.E =	38.903997
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.951934 =	8.352433
113		.448800 x	23.479183 =	10.537457
112		.353600 x	17.729980 =	6.269321

			T.E =	58.146011
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	23.479183 =	11.854639
112		.445400 x	17.729980 =	7.896933
111		.662150 x	15.951934 =	10.562573

			T.E =	72.756346
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.951934 =	13.423552
112		.567800 x	17.729980 =	10.067083
113		.568650 x	23.479183 =	13.351437

			T.E =	90.789873
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.951934 =	17.043844
113		.640900 x	23.479183 =	15.047808
112		.717400 x	17.729980 =	12.719488

			T.E =	112.508540

6621.1	6621.1			
372.1		1.020000 x	8.000000 =	8.160000
111		.080750 x	15.951934 =	1.288119
113		.205700 x	23.479183 =	4.829668
112		.088400 x	17.729980 =	1.567330

			T.E =	15.845117
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	23.479183 =	6.146850
112		.141100 x	17.729980 =	2.501700
111		.130900 x	15.951934 =	2.088108

			T.E =	23.568258
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.951934 =	2.725388
112		.185300 x	17.729980 =	3.285365
113		.299200 x	23.479183 =	7.024972

			T.E =	29.865725
6621.4	6621.4			
372.4		1.020000 x	25.550000 =	26.061000
111		.266900 x	15.951934 =	4.257571
113		.374000 x	23.479183 =	8.781214
112		.289000 x	17.729980 =	5.123964

			T.E =	44.223750
6621.5	6621.5			
372.5		1.020000 x	32.410000 =	33.058200
111		.338300 x	15.951934 =	5.396539
113		.420750 x	23.479183 =	9.878866
112		.367200 x	17.729980 =	6.510449

			T.E =	54.844054
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	23.479183 =	12.293700
112		.564400 x	17.729980 =	10.006801
111		.523600 x	15.951934 =	8.352433

			T.E =	82.897334

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
111		.662150 x	15.951934 =	10.562573
112		.710600 x	17.729980 =	12.598924
113		.589050 x	23.479183 =	13.830413
			T.E =	103.342910
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
111		.841500 x	15.951934 =	13.423552
113		.663850 x	23.479183 =	15.586656
112		.901000 x	17.729980 =	15.974712
			T.E =	129.349120
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
111		1.068450 x	15.951934 =	17.043844
113		.748000 x	23.479183 =	17.562429
112		1.145800 x	17.729980 =	20.315011
			T.E =	161.715284
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
113		.235450 x	23.479183 =	5.528174
112		.131750 x	17.729980 =	2.335925
111		.080750 x	15.951934 =	1.288119
			T.E =	21.290217
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	15.951934 =	2.088108
112		.212500 x	17.729980 =	3.767621
113		.299200 x	23.479183 =	7.024972
			T.E =	32.036300
6622.3	6622.3			
373.3		1.020000 x	24.500000 =	24.990000
111		.170850 x	15.951934 =	2.725388
113		.341700 x	23.479183 =	8.022837
112		.277950 x	17.729980 =	4.928048
			T.E =	40.666273

6623	6623				
360.2		1.000000 x	2.120000 =	2.120000	
113		.085000 x	23.479183 =	1.995731	
111		.042500 x	15.951934 =	.677957	
113		.025500 x	23.479183 =	.598719	
112		.042500 x	17.729980 =	.753524	

			T.E =	6.145931	
6630.1	6630.1				
376.12		1.000000 x	88.960000 =	88.960000	
113		2.550000 x	23.479183 =	59.871917	
113		.610300 x	23.479183 =	14.329345	
113		1.067600 x	23.479183 =	25.066376	
112		2.439500 x	17.729980 =	43.252286	
111		.855100 x	15.951934 =	13.640499	

			T.E =	245.120423	
6630.10	6630.10				
376.21		1.000000 x	487.600000 =	487.600000	
111		7.690800 x	15.951934 =	122.683134	
113		3.349000 x	23.479183 =	78.631784	
113		3.203650 x	23.479183 =	75.219085	
113		2.550000 x	23.479183 =	59.871917	
112		13.396000 x	17.729980 =	237.510812	

			T.E =	1,061.516731	
6630.11	6630.11				
376.22		1.000000 x	528.600000 =	528.600000	
111		9.025300 x	15.951934 =	143.970990	
113		3.471400 x	23.479183 =	81.505636	
113		3.629500 x	23.479183 =	85.217695	
113		2.550000 x	23.479183 =	59.871917	
112		14.518000 x	17.729980 =	257.403850	

			T.E =	1,156.570087	
6630.2	6630.2				
376.13		1.000000 x	98.960000 =	98.960000	
113		2.550000 x	23.479183 =	59.871917	
113		1.201050 x	23.479183 =	28.199673	
113		.680000 x	23.479183 =	15.965844	
111		1.081200 x	15.951934 =	17.247231	
112		2.720000 x	17.729980 =	48.225546	

			T.E =	268.470210	

6630.3	6630.3				
376.14		1.000000 x	109.782000 =	109.782000	
113		1.334500 x	23.479183 =	31.332970	
113		2.550000 x	23.479183 =	59.871917	
113		.760750 x	23.479183 =	17.861788	
112		3.043000 x	17.729980 =	53.952329	
111		1.334500 x	15.951934 =	21.287856	

			T.E =	294.088860	
6630.4	6630.4				
376.15		1.000000 x	140.650000 =	140.650000	
111		1.922700 x	15.951934 =	30.670784	
113		.892500 x	23.479183 =	20.955171	
113		1.602250 x	23.479183 =	37.619521	
113		2.550000 x	23.479183 =	59.871917	
112		3.570000 x	17.729980 =	63.296029	

			T.E =	353.063421	
6630.5	6630.5				
376.16		1.000000 x	176.880000 =	176.880000	
111		2.617150 x	15.951934 =	41.748604	
113		1.164500 x	23.479183 =	27.341509	
113		2.550000 x	23.479183 =	59.871917	
113		1.869150 x	23.479183 =	43.886115	
112		4.658000 x	17.729980 =	82.586247	

			T.E =	432.314391	
6630.6	6630.6				
376.17		1.000000 x	224.520000 =	224.520000	
113		2.550000 x	23.479183 =	59.871917	
113		2.136050 x	23.479183 =	50.152709	
113		1.470500 x	23.479183 =	34.526139	
111		3.418700 x	15.951934 =	54.534877	
112		5.882000 x	17.729980 =	104.287742	

			T.E =	527.893383	
6630.7	6630.7				
376.18		1.000000 x	302.640000 =	302.640000	
113		2.402950 x	23.479183 =	56.419303	
113		2.550000 x	23.479183 =	59.871917	
113		2.031500 x	23.479183 =	47.697960	
112		8.126000 x	17.729980 =	144.073817	
111		4.326500 x	15.951934 =	69.016042	

			T.E =	679.719040	

6630.8	6630.8			
376.19		1.000000 x	336.580000 =	336.580000
111		5.340550 x	15.951934 =	85.192101
113		2.261000 x	23.479183 =	53.086433
113		2.669850 x	23.479183 =	62.685897
113		2.550000 x	23.479183 =	59.871917
112		9.044000 x	17.729980 =	160.349939
			T.E =	757.766286
6630.9	6630.9			
376.20		1.000000 x	400.990000 =	400.990000
111		6.461700 x	15.951934 =	103.076612
113		2.737000 x	23.479183 =	64.262524
113		2.550000 x	23.479183 =	59.871917
113		2.936750 x	23.479183 =	68.952491
112		10.948000 x	17.729980 =	194.107821
			T.E =	891.261364
6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
113		2.550000 x	23.479183 =	59.871917
113		1.667700 x	23.479183 =	39.156233
111		1.334500 x	15.951934 =	21.287856
112		3.043000 x	17.729980 =	53.952329
			T.E =	
6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.550000 x	23.479183 =	59.871917
113		2.002600 x	23.479183 =	47.019412
112		3.570000 x	17.729980 =	63.296029
111		1.922700 x	15.951934 =	30.670784
			T.E =	
6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
111		2.617150 x	15.951934 =	41.748604
112		4.658000 x	17.729980 =	82.586247
113		2.550000 x	23.479183 =	59.871917
113		2.336650 x	23.479183 =	54.862633
			T.E =	

6640.4 6640.4

377.4	1.000000 x	.000000 =	.000000
111	3.418700 x	15.951934 =	54.534877
112	5.882000 x	17.729980 =	104.287742
113	2.669850 x	23.479183 =	62.685897
113	2.550000 x	23.479183 =	59.871917

T.E =

6640.5 6640.5

377.5	1.000000 x	.000000 =	.000000
111	4.326500 x	15.951934 =	69.016042
113	3.003900 x	23.479183 =	70.529118
113	2.550000 x	23.479183 =	59.871917
112	8.126000 x	17.729980 =	144.073817

T.E =

6640.6 6640.6

377.6	1.000000 x	.000000 =	.000000
113	2.550000 x	23.479183 =	59.871917
113	3.337100 x	23.479183 =	78.352382
112	9.044000 x	17.729980 =	160.349939
111	5.340550 x	15.951934 =	85.192101

T.E =

6640.7 6640.7

377.7	1.000000 x	.000000 =	.000000
111	6.461700 x	15.951934 =	103.076612
112	10.948000 x	17.729980 =	194.107821
113	3.671150 x	23.479183 =	86.195603
113	2.550000 x	23.479183 =	59.871917

T.E =

6640.8 6640.8

377.8	1.000000 x	.000000 =	.000000
111	7.690800 x	15.951934 =	122.683134
112	13.396000 x	17.729980 =	237.510812
113	2.550000 x	23.479183 =	59.871917
113	4.004350 x	23.479183 =	94.018866

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.951934 =	143.970990
113		4.339250 x	23.479183 =	101.882045
113		2.550000 x	23.479183 =	59.871917
112		14.518000 x	17.729980 =	257.403850

			T.E =	
6641	6641			
233.3		1.000000 x	7.500000 =	7.500000

			T.E =	7.500000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		.100000 x	.000000 =	.000000
382.6		1.000000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7	6662.7			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.8		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6662.8	6662.8			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.6		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.1	6663.1			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.4		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.2	6663.2			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6701.1	6701.1			
368.1		1.020000 x	.000000 =	.000000
369.1		.224000 x	.000000 =	.000000
113		.068000 x	23.479183 =	1.596584
111		.382500 x	15.951934 =	6.101615

		T.E =		

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	23.479183 =	7.982922
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.951934 =	10.847315

T.E =

6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
369.2		.224000 x	.000000 =	.000000

T.E =

6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.951934 =	6.915163
113		.102000 x	23.479183 =	2.394877

T.E =

6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	23.479183 =	2.794023
111		.459000 x	15.951934 =	7.321938

T.E =

6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	23.479183 =	3.392742
111		.484500 x	15.951934 =	7.728712

T.E =

6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078
369.6		.224000 x	.000000 =	.000000

T.E =

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.951934 =	8.813444
113		.195500 x	23.479183 =	4.590180

T.E =

6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	23.479183 =	5.588046
111		.595000 x	15.951934 =	9.491401

T.E =

6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	23.479183 =	6.785484
111		.637500 x	15.951934 =	10.169358

T.E =

6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	23.479183 =	1.596584
111		.382500 x	15.951934 =	6.101615
369.11		.224000 x	.000000 =	.000000

T.E =

6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.951934 =	10.847315
113		.340000 x	23.479183 =	7.982922

T.E =

6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389

T.E =

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	23.479183 =	2.394877
111		.433500 x	15.951934 =	6.915163

T.E =

6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	23.479183 =	2.794023
111		.459000 x	15.951934 =	7.321938
369.14		.224000 x	.000000 =	.000000

T.E =

6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	15.951934 =	7.728712
113		.144500 x	23.479183 =	3.392742

T.E =

6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078

T.E =

6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	23.479183 =	4.590180
111		.552500 x	15.951934 =	8.813444

T.E =

6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	23.479183 =	5.588046
111		.595000 x	15.951934 =	9.491401
369.18		.224000 x	.000000 =	.000000

T.E =

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	23.479183 =	6.785484
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.951934 =	10.169358

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.951934 =	6.101615
113		.068000 x	23.479183 =	1.596584
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	23.479183 =	7.982922
111		.680000 x	15.951934 =	10.847315

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	23.479183 =	2.394877
111		.433500 x	15.951934 =	6.915163
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.951934 =	7.321938
113		.119000 x	23.479183 =	2.794023

T.E =

6703.5 6703.5

368.25	1.020000 x	.000000 =	.000000
369.25	.224000 x	.000000 =	.000000
113	.144500 x	23.479183 =	3.392742
111	.484500 x	15.951934 =	7.728712

T.E =

6703.6 6703.6

368.26	1.020000 x	.000000 =	.000000
369.26	.224000 x	.000000 =	.000000
113	.170000 x	23.479183 =	3.991461
111	.518500 x	15.951934 =	8.271078

T.E =

6703.7 6703.7

368.27	1.020000 x	.000000 =	.000000
113	.195500 x	23.479183 =	4.590180
111	.552500 x	15.951934 =	8.813444
369.27	.224000 x	.000000 =	.000000

T.E =

6703.8 6703.8

368.28	1.020000 x	.000000 =	.000000
369.28	.224000 x	.000000 =	.000000
111	.595000 x	15.951934 =	9.491401
113	.238000 x	23.479183 =	5.588046

T.E =

6703.9 6703.9

368.29	1.020000 x	.000000 =	.000000
369.29	.224000 x	.000000 =	.000000
113	.289000 x	23.479183 =	6.785484
111	.637500 x	15.951934 =	10.169358

T.E =

6704.1 6704.1

370.1	1.000000 x	.000000 =	.000000
370.8	1.000000 x	.000000 =	.000000
113	.068000 x	23.479183 =	1.596584
111	.382500 x	15.951934 =	6.101615

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	15.951934 =	6.915163
113		.102000 x	23.479183 =	2.394877

T.E =

6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	23.479183 =	2.794023
111		.459000 x	15.951934 =	7.321938

T.E =

6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	23.479183 =	3.392742
111		.484500 x	15.951934 =	7.728712

T.E =

6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	15.951934 =	8.813444
113		.195500 x	23.479183 =	4.590180

T.E =

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	23.479183 =	1.596584
111		.382500 x	15.951934 =	6.101615

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	23.479183 =	2.394877
111		.433500 x	15.951934 =	6.915163
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	15.951934 =	7.321938
113		.119000 x	23.479183 =	2.794023

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	23.479183 =	3.392742
111		.484500 x	15.951934 =	7.728712

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078

T.E =

6705.7 6705.7

370.15	1.000000 x	.000000 =	.000000
113	.195500 x	23.479183 =	4.590180
111	.552500 x	15.951934 =	8.813444
370.16	1.000000 x	.000000 =	.000000

T.E =

6706.1 6706.1

370.17	1.000000 x	.000000 =	.000000
370.24	1.000000 x	.000000 =	.000000
111	.382500 x	15.951934 =	6.101615
113	.068000 x	23.479183 =	1.596584

T.E =

6706.2 6706.2

370.18	1.000000 x	.000000 =	.000000
370.24	1.000000 x	.000000 =	.000000
113	.085000 x	23.479183 =	1.995731
111	.408000 x	15.951934 =	6.508389

T.E =

6706.3 6706.3

370.19	1.000000 x	.000000 =	.000000
370.24	1.000000 x	.000000 =	.000000
113	.102000 x	23.479183 =	2.394877
111	.433500 x	15.951934 =	6.915163

T.E =

6706.4 6706.4

370.20	1.000000 x	.000000 =	.000000
113	.119000 x	23.479183 =	2.794023
111	.459000 x	15.951934 =	7.321938
370.24	1.000000 x	.000000 =	.000000

T.E =

6706.5 6706.5

370.21	1.000000 x	.000000 =	.000000
370.24	1.000000 x	.000000 =	.000000
111	.484500 x	15.951934 =	7.728712
113	.144500 x	23.479183 =	3.392742

T.E =

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	23.479183 =	4.590180
111		.552500 x	15.951934 =	8.813444

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
6326		.327500 x	138.078751 =	45.220791
113		.026350 x	23.479183 =	.618676
111		.085000 x	15.951934 =	1.355914

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
111		.119000 x	15.951934 =	1.898280
113		.040800 x	23.479183 =	.957951
6326		.352500 x	138.078751 =	48.672760

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
111		.161500 x	15.951934 =	2.576237
6326		.372500 x	138.078751 =	51.434335
113		.051000 x	23.479183 =	1.197438

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.951934 =	2.711829
6326		.382500 x	138.078751 =	52.815122
113		.063750 x	23.479183 =	1.496798

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	138.078751 =	54.023311
113		.068000 x	23.479183 =	1.596584
111		.187000 x	15.951934 =	2.983012

T.E =

6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.951934 =	3.254195
113		.076500 x	23.479183 =	1.796157
6327		.393750 x	160.594649 =	63.234143

T.E =

6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	15.951934 =	4.610109
6327		.431250 x	160.594649 =	69.256442
113		.093500 x	23.479183 =	2.195304

T.E =

6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
6327		.500000 x	160.594649 =	80.297325
113		.119000 x	23.479183 =	2.794023

T.E =

6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	24.749210 =	9.157208
113		.017000 x	23.479183 =	.399146
111		.161500 x	15.951934 =	2.576237

T.E =

20.812791

6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	15.951934 =	2.983012
6069		.390000 x	24.749210 =	9.652192
113		.021250 x	23.479183 =	.498933

T.E =

26.730736

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	15.951934 =	3.254195
6069		.400000 x	24.749210 =	9.899684
113		.026350 x	23.479183 =	.618676

			T.E =	34.978355
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.951934 =	3.932152
6069		.420000 x	24.749210 =	10.394668
113		.040800 x	23.479183 =	.957951

			T.E =	49.607771
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	24.749210 =	10.642160
113		.051000 x	23.479183 =	1.197438
111		.289000 x	15.951934 =	4.610109

			T.E =	60.105708
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	24.749210 =	10.889652
113		.063750 x	23.479183 =	1.496798
111		.297500 x	15.951934 =	4.745700

			T.E =	72.446751
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	24.749210 =	12.869589
113		.076500 x	23.479183 =	1.796157
111		.357000 x	15.951934 =	5.694840

			T.E =	110.028787
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306

			T.E =	42.339306

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306

			T.E =	45.846306
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306

			T.E =	51.274806
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306

			T.E =	58.771806
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
113		.850000 x	23.479183 =	19.957306
375.13		1.000000 x	10.160000 =	10.160000

			T.E =	66.405306
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
113		.021250 x	23.479183 =	.498933
111		.187000 x	15.951934 =	2.983012
375.14		1.000000 x	17.510000 =	17.510000

			T.E =	31.151944
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	108.435272 =	9.759174
112		1.190000 x	17.729980 =	21.098676
113		.255000 x	23.479183 =	5.987192

			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	118.205272 =	26.123365
700		.350000 x	.000000 =	.000000
113		.510000 x	23.479183 =	11.974383
112		1.360000 x	17.729980 =	24.112773

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.729980 =	25.619821
113		.595000 x	23.479183 =	13.970114
6325		.234000 x	118.205272 =	27.660034
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	118.205272 =	28.487471
112		1.487500 x	17.729980 =	26.373345
700		.400000 x	.000000 =	.000000
113		.637500 x	23.479183 =	14.967979

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	108.435272 =	11.927880
112		1.275000 x	17.729980 =	22.605725
700		.250000 x	.000000 =	.000000
113		.340000 x	23.479183 =	7.982922

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	108.435272 =	14.205021
700		.300000 x	.000000 =	.000000
113		.425000 x	23.479183 =	9.978653
112		1.275000 x	17.729980 =	22.605725

T.E =

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.729980 =	24.112773
113		.510000 x	23.479183 =	11.974383
6323		.154000 x	108.435272 =	16.699032
700		.350000 x	.000000 =	.000000

T.E =

6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	108.435272 =	18.000255
112		1.445000 x	17.729980 =	25.619821
700		.380000 x	.000000 =	.000000
113		.595000 x	23.479183 =	13.970114

T.E =

6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.729980 =	26.373345
700		.400000 x	.000000 =	.000000
6323		.173000 x	108.435272 =	18.759302
113		.637500 x	23.479183 =	14.967979

T.E =

6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	118.205272 =	16.312328
700		.200000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192
112		1.190000 x	17.729980 =	21.098676

T.E =

6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.729980 =	22.605725
113		.340000 x	23.479183 =	7.982922
6325		.165000 x	118.205272 =	19.503870
700		.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	118.205272 =	22.813617
112		1.275000 x	17.729980 =	22.605725
700		.300000 x	.000000 =	.000000
113		.425000 x	23.479183 =	9.978653

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	108.435272 =	6.506116
112		1.190000 x	17.729980 =	21.098676
700		.200000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	118.205272 =	15.366685
700		.350000 x	.000000 =	.000000
113		.510000 x	23.479183 =	11.974383
112		1.360000 x	17.729980 =	24.112773

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.729980 =	25.619821
113		.595000 x	23.479183 =	13.970114
6325		.140000 x	118.205272 =	16.548738
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	118.205272 =	17.730791
112		1.487500 x	17.729980 =	26.373345
700		.400000 x	.000000 =	.000000
113		.637500 x	23.479183 =	14.967979

T.E =

6721.2 6721.2

394.9	1.050000 x	.000000 =	.000000
6323	.070000 x	108.435272 =	7.590469
112	1.275000 x	17.729980 =	22.605725
700	.250000 x	.000000 =	.000000
113	.340000 x	23.479183 =	7.982922

T.E =

6721.3 6721.3

394.10	1.050000 x	.000000 =	.000000
6323	.080000 x	108.435272 =	8.674822
700	.300000 x	.000000 =	.000000
113	.425000 x	23.479183 =	9.978653
112	1.275000 x	17.729980 =	22.605725

T.E =

6721.4 6721.4

394.11	1.050000 x	.000000 =	.000000
112	1.360000 x	17.729980 =	24.112773
113	.510000 x	23.479183 =	11.974383
6323	.090000 x	108.435272 =	9.759174
700	.350000 x	.000000 =	.000000

T.E =

6721.5 6721.5

394.12	1.050000 x	.000000 =	.000000
6323	.100000 x	108.435272 =	10.843527
112	1.445000 x	17.729980 =	25.619821
700	.380000 x	.000000 =	.000000
113	.595000 x	23.479183 =	13.970114

T.E =

6721.6 6721.6

394.13	1.050000 x	.000000 =	.000000
112	1.487500 x	17.729980 =	26.373345
700	.400000 x	.000000 =	.000000
6323	.110000 x	108.435272 =	11.927880
113	.637500 x	23.479183 =	14.967979

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	118.205272 =	11.820527
700		.200000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192
112		1.190000 x	17.729980 =	21.098676

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.729980 =	22.605725
113		.340000 x	23.479183 =	7.982922
6325		.110000 x	118.205272 =	13.002580
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	118.205272 =	14.184633
112		1.275000 x	17.729980 =	22.605725
700		.300000 x	.000000 =	.000000
113		.425000 x	23.479183 =	9.978653

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.729980 =	7.535242
700		.120000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192

T.E =

6730.1	6730.1			
261		1.050000 x	14.500000 =	15.225000
6323		.090000 x	108.435272 =	9.759174
652		.002500 x	148.360619 =	.370902
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
111		.170000 x	15.951934 =	2.711829

T.E = 40.082290

6730.10	6730.10			
263		1.050000 x	31.200000 =	32.760000
111		.297500 x	15.951934 =	4.745700
112		.425000 x	17.729980 =	7.535242
6325		.249000 x	118.205272 =	29.433113
652		.004500 x	148.360619 =	.667623
113		.340000 x	23.479183 =	7.982922
			T.E =	83.124600
6730.11	6730.11			
263.2		1.050000 x	44.900000 =	47.145000
6325		.310000 x	118.205272 =	36.643634
652		.005000 x	148.360619 =	.741803
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
112		.552500 x	17.729980 =	9.795814
			T.E =	111.724292
6730.12	6730.12			
264		1.050000 x	61.600000 =	64.680000
111		.425000 x	15.951934 =	6.779572
113		.595000 x	23.479183 =	13.970114
6325		.370000 x	118.205272 =	43.735951
652		.006500 x	148.360619 =	.964344
112		.680000 x	17.729980 =	12.056386
			T.E =	142.186367
6730.2	6730.2			
261.2		1.050000 x	19.900000 =	20.895000
6323		.110000 x	108.435272 =	11.927880
652		.003000 x	148.360619 =	.445082
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
111		.170000 x	15.951934 =	2.711829
			T.E =	47.995175
6730.3	6730.3			
262		1.050000 x	25.300000 =	26.565000
111		.212500 x	15.951934 =	3.389786
112		.382500 x	17.729980 =	6.781717
6323		.131000 x	108.435272 =	14.205021
652		.003500 x	148.360619 =	.519262
113		.297500 x	23.479183 =	6.985057
			T.E =	58.445843

6730.4	6730.4			
263		1.050000 x	31.200000 =	32.760000
6323		.170000 x	108.435272 =	18.433996
652		.004500 x	148.360619 =	.667623
111		.297500 x	15.951934 =	4.745700
113		.340000 x	23.479183 =	7.982922
112		.425000 x	17.729980 =	7.535242
			T.E =	72.125483
6730.5	6730.5			
263.2		1.050000 x	44.900000 =	47.145000
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
6323		.226000 x	108.435272 =	24.506371
652		.005000 x	148.360619 =	.741803
112		.552500 x	17.729980 =	9.795814
			T.E =	99.587029
6730.6	6730.6			
264		1.050000 x	61.600000 =	64.680000
6323		.274000 x	108.435272 =	29.711265
652		.006500 x	148.360619 =	.964344
113		.595000 x	23.479183 =	13.970114
112		.680000 x	17.729980 =	12.056386
111		.425000 x	15.951934 =	6.779572
			T.E =	128.161681
6730.7	6730.7			
261		1.050000 x	14.500000 =	15.225000
111		.170000 x	15.951934 =	2.711829
112		.340000 x	17.729980 =	6.028193
6325		.138000 x	118.205272 =	16.312328
652		.002500 x	148.360619 =	.370902
113		.255000 x	23.479183 =	5.987192
			T.E =	46.635443
6730.8	6730.8			
261.2		1.050000 x	19.900000 =	20.895000
6325		.165000 x	118.205272 =	19.503870
652		.003000 x	148.360619 =	.445082
111		.170000 x	15.951934 =	2.711829
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
			T.E =	55.571165

6730.9	6730.9			
262		1.050000 x	25.300000 =	26.565000
111		.212500 x	15.951934 =	3.389786
113		.297500 x	23.479183 =	6.985057
6325		.193000 x	118.205272 =	22.813617
652		.003500 x	148.360619 =	.519262
112		.382500 x	17.729980 =	6.781717

T.E = 67.054440

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	108.435272 =	9.759174
652		.002500 x	148.360619 =	.370902
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
111		.170000 x	15.951934 =	2.711829

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.951934 =	4.745700
112		.425000 x	17.729980 =	7.535242
6325		.249000 x	118.205272 =	29.433113
652		.004500 x	148.360619 =	.667623
113		.340000 x	23.479183 =	7.982922

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	118.205272 =	36.643634
652		.005000 x	148.360619 =	.741803
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
112		.552500 x	17.729980 =	9.795814

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.951934 =	6.779572
113		.595000 x	23.479183 =	13.970114
6325		.370000 x	118.205272 =	43.735951
652		.006500 x	148.360619 =	.964344
112		.680000 x	17.729980 =	12.056386

T.E =

6731.2 6731.2

261.4	1.050000 x	.000000 =	.000000
6323	.110000 x	108.435272 =	11.927880
652	.003000 x	148.360619 =	.445082
113	.255000 x	23.479183 =	5.987192
112	.340000 x	17.729980 =	6.028193
111	.170000 x	15.951934 =	2.711829

T.E =

6731.3 6731.3

262.1	1.050000 x	.000000 =	.000000
111	.212500 x	15.951934 =	3.389786
112	.382500 x	17.729980 =	6.781717
6323	.131000 x	108.435272 =	14.205021
652	.003500 x	148.360619 =	.519262
113	.297500 x	23.479183 =	6.985057

T.E =

6731.4 6731.4

263.1	1.050000 x	.000000 =	.000000
6323	.170000 x	108.435272 =	18.433996
652	.004500 x	148.360619 =	.667623
111	.297500 x	15.951934 =	4.745700
113	.340000 x	23.479183 =	7.982922
112	.425000 x	17.729980 =	7.535242

T.E =

6731.5 6731.5

263.3	1.050000 x	.000000 =	.000000
111	.340000 x	15.951934 =	5.423658
113	.510000 x	23.479183 =	11.974383
6323	.226000 x	108.435272 =	24.506371
652	.005000 x	148.360619 =	.741803
112	.552500 x	17.729980 =	9.795814

T.E =

6731.6 6731.6

264.1	1.050000 x	.000000 =	.000000
6323	.274000 x	108.435272 =	29.711265
652	.006500 x	148.360619 =	.964344
113	.595000 x	23.479183 =	13.970114
112	.680000 x	17.729980 =	12.056386
111	.425000 x	15.951934 =	6.779572

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.951934 =	2.711829
112		.340000 x	17.729980 =	6.028193
6325		.138000 x	118.205272 =	16.312328
652		.002500 x	148.360619 =	.370902
113		.255000 x	23.479183 =	5.987192

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	118.205272 =	19.503870
652		.003000 x	148.360619 =	.445082
111		.170000 x	15.951934 =	2.711829
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.951934 =	3.389786
113		.297500 x	23.479183 =	6.985057
6325		.193000 x	118.205272 =	22.813617
652		.003500 x	148.360619 =	.519262
112		.382500 x	17.729980 =	6.781717

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	23.479183 =	19.957306

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	138.078751 =	129.794026
6303		1.880000 x	22.640360 =	42.563877

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	138.078751 =	100.797488

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	138.078751 =	129.794026

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	138.078751 =	100.797488

			T.E =	
6742.1	6742.1			
6303		3.040000 x	22.640360 =	68.826694
6328		.400000 x	164.551110 =	65.820444

			T.E =	134.647138
6742.10	6742.10			
6303		7.520000 x	22.640360 =	170.255507
6328		2.110000 x	164.551110 =	347.202842

			T.E =	517.458349
6742.11	6742.11			
6303		8.030000 x	22.640360 =	181.802091
6328		2.430000 x	164.551110 =	399.859197

			T.E =	581.661288
6742.2	6742.2			
6303		3.500000 x	22.640360 =	79.241260
6328		.500000 x	164.551110 =	82.275555

			T.E =	161.516815
6742.3	6742.3			
6303		4.020000 x	22.640360 =	91.014247
6328		.630000 x	164.551110 =	103.667199

			T.E =	194.681447
6742.4	6742.4			
6303		4.530000 x	22.640360 =	102.560831
6328		.800000 x	164.551110 =	131.640888

			T.E =	234.201719

6742.5	6742.5			
6303		5.000000 x	22.640360 =	113.201800
6328		.950000 x	164.551110 =	156.323555

			T.E =	269.525355
6742.6	6742.6			
6303		5.530000 x	22.640360 =	125.201191
6328		1.170000 x	164.551110 =	192.524799

			T.E =	317.725990
6742.7	6742.7			
6303		6.040000 x	22.640360 =	136.747774
6328		1.410000 x	164.551110 =	232.017065

			T.E =	368.764840
6742.8	6742.8			
6303		6.520000 x	22.640360 =	147.615147
6328		1.610000 x	164.551110 =	264.927287

			T.E =	412.542434
6742.9	6742.9			
6303		7.040000 x	22.640360 =	159.388134
6328		1.880000 x	164.551110 =	309.356087

			T.E =	468.744221
6743.1	6743.1			
6303		3.040000 x	22.640360 =	68.826694
6328		.440000 x	164.551110 =	72.402488

			T.E =	141.229183
6743.10	6743.10			
6303		7.520000 x	22.640360 =	170.255507
6328		2.240000 x	164.551110 =	368.594486

			T.E =	538.849994
6743.11	6743.11			
6303		8.030000 x	22.640360 =	181.802091
6328		2.570000 x	164.551110 =	422.896353

			T.E =	604.698444

6743.12	6743.12			
6303		3.040000 x	22.640360 =	68.826694
6328		.750000 x	164.551110 =	123.413333

			T.E =	192.240027
6743.13	6743.13			
6303		3.500000 x	22.640360 =	79.241260
6328		.910000 x	164.551110 =	149.741510

			T.E =	228.982770
6743.14	6743.14			
6303		4.020000 x	22.640360 =	91.014247
6328		1.090000 x	164.551110 =	179.360710

			T.E =	270.374957
6743.15	6743.15			
6303		4.530000 x	22.640360 =	102.560831
6328		1.300000 x	164.551110 =	213.916443

			T.E =	316.477274
6743.16	6743.16			
6303		5.000000 x	22.640360 =	113.201800
6328		1.550000 x	164.551110 =	255.054221

			T.E =	368.256021
6743.17	6743.17			
6303		5.530000 x	22.640360 =	125.201191
6328		1.850000 x	164.551110 =	304.419554

			T.E =	429.620744
6743.2	6743.2			
6303		3.500000 x	22.640360 =	79.241260
6328		.550000 x	164.551110 =	90.503111

			T.E =	169.744371
6743.3	6743.3			
6303		4.020000 x	22.640360 =	91.014247
6328		.690000 x	164.551110 =	113.540266

			T.E =	204.554513

6743.4	6743.4			
6303		4.530000 x	22.640360 =	102.560831
6328		.860000 x	164.551110 =	141.513955

			T.E =	244.074785
6743.5	6743.5			
6303		5.000000 x	22.640360 =	113.201800
6328		1.020000 x	164.551110 =	167.842132

			T.E =	281.043932
6743.6	6743.6			
6303		5.530000 x	22.640360 =	125.201191
6328		1.260000 x	164.551110 =	207.334399

			T.E =	332.535589
6743.7	6743.7			
6303		6.040000 x	22.640360 =	136.747774
6328		1.500000 x	164.551110 =	246.826665

			T.E =	383.574439
6743.8	6743.8			
6303		6.520000 x	22.640360 =	147.615147
6328		1.720000 x	164.551110 =	283.027909

			T.E =	430.643056
6743.9	6743.9			
6303		7.040000 x	22.640360 =	159.388134
6328		2.000000 x	164.551110 =	329.102220

			T.E =	488.490354
6744	6744			
111		2.125000 x	15.951934 =	33.897860
113		2.125000 x	23.479183 =	49.893264
113		2.125000 x	23.479183 =	49.893264
112		2.125000 x	17.729980 =	37.676208
111		4.250000 x	15.951934 =	67.795720

			T.E =	239.156315

6751	6751			
234.2		.400000 x	.742000 =	.296800
113		.170000 x	23.479183 =	3.991461
113		.051000 x	23.479183 =	1.197438
235		.650000 x	.623000 =	.404950

			T.E =	5.890649
6752	6752			
237		1.050000 x	1.060000 =	1.113000
111		.025500 x	15.951934 =	.406774
113		.017000 x	23.479183 =	.399146

			T.E =	1.918920
6753	6753			
237		1.050000 x	1.060000 =	1.113000
113		.085000 x	23.479183 =	1.995731
112		.085000 x	17.729980 =	1.507048

			T.E =	4.615779
6754	6754			
237.1		1.000000 x	1.200000 =	1.200000
111		.051000 x	15.951934 =	.813549
112		.017000 x	17.729980 =	.301410
113		.212500 x	23.479183 =	4.989326

			T.E =	7.304285
6801	6801			
232		.700000 x	1.900000 =	1.330000
251		.008000 x	290.000000 =	2.320000
113		2.550000 x	23.479183 =	59.871917
112		1.700000 x	17.729980 =	30.140966
111		.850000 x	15.951934 =	13.559144

			T.E =	107.222027
6802	6802			
231		15.000000 x	.710000 =	10.650000
113		2.550000 x	23.479183 =	59.871917
111		4.250000 x	15.951934 =	67.795720
252.1		.050000 x	.000000 =	.000000
251		.050000 x	290.000000 =	14.500000

			T.E =	

6803	6803			
302		1.020000 x	7.120000 =	7.262400
652		.012000 x	148.360619 =	1.780327
111		.510000 x	15.951934 =	8.135486
113		.680000 x	23.479183 =	15.965844

			T.E =	33.144058
6804	6804			
111		.510000 x	15.951934 =	8.135486
652		.120000 x	148.360619 =	17.803274
113		.680000 x	23.479183 =	15.965844

			T.E =	41.904605
6805	6805			
301		1.000000 x	4.320000 =	4.320000
111		.340000 x	15.951934 =	5.423658
2522		.005000 x	158.513649 =	.792568
652		.002000 x	148.360619 =	.296721
113		.340000 x	23.479183 =	7.982922

			T.E =	18.815869
6806	6806			
111		.340000 x	15.951934 =	5.423658
113		.340000 x	23.479183 =	7.982922
6326		.005000 x	138.078751 =	.690394
652		.002000 x	148.360619 =	.296721

			T.E =	14.393695
6807	6807			
111		1.700000 x	15.951934 =	27.118288

			T.E =	27.118288
6808	6808			
111		.425000 x	15.951934 =	6.779572

			T.E =	6.779572
6810	6810			
241		2.600000 x	6.240000 =	16.224000
241		1.300000 x	6.240000 =	8.112000
113		1.062500 x	23.479183 =	24.946632
113		.850000 x	23.479183 =	19.957306
111		1.062500 x	15.951934 =	16.948930

			T.E =	86.188867

6811	6811			
236		6.430000 x	.613000 =	3.941590
241		3.150000 x	6.240000 =	19.656000
113		3.400000 x	23.479183 =	79.829222
113		.850000 x	23.479183 =	19.957306

			T.E =	123.384118
6812	6812			
397.1		2.100000 x	6.780000 =	14.238000
111		.425000 x	15.951934 =	6.779572
113		4.250000 x	23.479183 =	99.786528
6324		.250000 x	113.320272 =	28.330068
243		11.900000 x	2.050000 =	24.395000

			AΘΡΟΙΣΜΑ =	173.529168
	T.E =	.262500 x	173.529168 =	45.551407

7001	7001			
7001 Α		1.000000 x	.233823 =	.233823
7001 Β		1.000000 x	.754719 =	.754719
7001 Δ		1.000000 x	.308787 =	.308787
7001 Ε		1.000000 x	.797298 =	.797298
7001 Γ		1.000000 x	.959804 =	.959804

			AΘΡΟΙΣΜΑ =	3.054431

			T.E =	3.512596
7002	7002			
560		.005104 x	623.000039 =	3.179792

			T.E =	3.179792
7003	7003			
7003 Α		1.000000 x	.116911 =	.116911
7003 Δ		1.000000 x	.768507 =	.768507
7003 Γ		1.000000 x	.545048 =	.545048
7003 Β		1.000000 x	.582004 =	.582004

			AΘΡΟΙΣΜΑ =	2.012470

			T.E =	2.213717
7004	7004			
561		.003250 x	815.206339 =	2.649421

			T.E =	2.649421

7005	7005			
7005 Α		1.000000 x	.116911 =	.116911
7005 Β		1.000000 x	1.018507 =	1.018507
7005 Γ		1.000000 x	.291002 =	.291002
7005 Δ		1.000000 x	.545048 =	.545048
7005 Ε		1.000000 x	.768507 =	.768507

			ΑΘΡΟΙΣΜΑ =	2.739975

			T.E =	3.013973
7006	7006			
561		.001723 x	815.206339 =	1.404601
561		.000812 x	815.206339 =	.661948
561		.000862 x	815.206339 =	.702708

			T.E =	2.769256
7007	7007			
213		.100000 x	1.875000 =	.187500
502		.000583 x	778.639607 =	.453947
116		.280000 x	22.893045 =	6.410053
550		.003500 x	1,092.458140 =	3.823603
518		.001750 x	861.342948 =	1.507350

			T.E =	12.382453
7008	7008			
111		.021000 x	15.951934 =	.334991
112		.210000 x	17.729980 =	3.723296
7007		1.100000 x	12.382453 =	13.620698
507		.000875 x	918.107524 =	.803344
558		.000972 x	1,078.170174 =	1.047981
503		.001750 x	878.725307 =	1.537769

			T.E =	21.068079
7009	7009			
560		.006417 x	623.000039 =	3.997791

			T.E =	3.997791
7010	7010			
7010 Α		1.000000 x	.339624 =	.339624
7010 Γ		1.000000 x	.545048 =	.545048
7010 Β		1.000000 x	.509974 =	.509974
7010 Δ		1.000000 x	.308787 =	.308787
7010 Ε		1.000000 x	.949171 =	.949171

			ΑΘΡΟΙΣΜΑ =	2.652604

			T.E =	3.050495

7011	7011			
502		.001367 x	778.639607 =	1.064400
558		.000729 x	1,078.170174 =	.785986
563		.001367 x	.000000 =	.000000
558		.000729 x	1,078.170174 =	.785986
554		.000438 x	32.472000 =	.014223
502		.000700 x	778.639607 =	.545048
503		.000438 x	878.725307 =	.384882

			AΘΡΟΙΣΜΑ =	3.580525

			T.E =	
7012	7012			
7008		1.000000 x	21.068079 =	21.068079

			AΘΡΟΙΣΜΑ =	21.068079

			T.E =	23.174887
7013	7013			
7003		1.000000 x	2.213717 =	2.213717

			AΘΡΟΙΣΜΑ =	2.213717

			T.E =	2.435089
7014	7014			
7005		1.000000 x	3.013973 =	3.013973

			AΘΡΟΙΣΜΑ =	3.013973

			T.E =	3.315370
7015	7015			
111		.056000 x	15.951934 =	.893308
X 630.1		.300000 x	1.590955 =	.477287
7001		.900000 x	3.512596 =	3.161336
X 630		.300000 x	1.353608 =	.406082

			T.E =	4.938014
7016.9	7016.9			
7016.4		1.000000 x	123.099594 =	123.099594
7016.8		1.000000 x	119.743833 =	119.743833
7016.5		1.000000 x	24.619919 =	24.619919
7016.6		1.000000 x	36.929878 =	36.929878
7016.7		1.000000 x	81.354863 =	81.354863

			T.E =	385.748087

7017.8	7017.8				
7017.3		1.000000 x	90.569044 =		90.569044
7017.4		1.000000 x	18.113809 =		18.113809
7017.5		1.000000 x	32.604856 =		32.604856
7017.6		1.000000 x	81.354863 =		81.354863
7017.7		1.000000 x	59.871917 =		59.871917

			T.E =		282.514489
7018	7018				
233.2		1.150000 x	.555400 =		.638710
113		.051000 x	23.479183 =		1.197438

			AΘΡΟΙΣΜΑ =		1.836148

			T.E =		2.019763
7019	7019				
7019 A6		1.000000 x	198.476473 =		198.476473
7019 A7		1.000000 x	19.847647 =		19.847647

			T.E =		218.324120
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	218.324120 =		218.324120

			T.E =		212.424120
7020	7020				
213		.150000 x	1.875000 =		.281250
116		.980000 x	22.893045 =		22.435184
7020.2		.010938 x	3,513.379370 =		38.429344

			T.E =		61.145778
7020.1	7020.1				
570.2		.350000 x	151.502516 =		53.025881
571.1		.280000 x	390.588299 =		109.364724
571.2		.070000 x	248.349672 =		17.384477

			AΘΡΟΙΣΜΑ =		179.775081
	T.E =	.015625 x	179.775081 =		2.808986

7021	7021				
213		.150000 x	1.875000 =		.281250
7021.2		.014583 x	3,017.714214 =		44.007326
116		1.120000 x	22.893045 =		25.640210

			T.E =		69.928787

7021.1	7021.1			
570.2		.350000 x	151.502516 =	53.025881
571.1		.280000 x	390.588299 =	109.364724
571.2		.070000 x	248.349672 =	17.384477

			AΘΡΟΙΣΜΑ =	179.775081
	T.E =	.020833 x	179.775081 =	3.745254

7022	7022			
213		.150000 x	1.875000 =	.281250
7022.2		.020000 x	2,741.502188 =	54.830044
116		1.400000 x	22.893045 =	32.050263

			T.E =	87.161557
7022.1	7022.1			
570.2		.350000 x	151.502516 =	53.025881
571.1		.280000 x	390.588299 =	109.364724
571.2		.070000 x	248.349672 =	17.384477

			AΘΡΟΙΣΜΑ =	179.775081
	T.E =	.028571 x	179.775081 =	5.136354

7023	7023			
398.2		1.050000 x	42.300000 =	44.415000
111		.425000 x	15.951934 =	6.779572
550		.012143 x	1,092.458140 =	13.265719
116		.850000 x	22.893045 =	19.459088

			T.E =	83.919379
7024	7024			
398.3		1.050000 x	49.800000 =	52.290000
111		.425000 x	15.951934 =	6.779572
550		.020238 x	1,092.458140 =	22.109168
116		.850000 x	22.893045 =	19.459088

			T.E =	100.637828
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	148.360619 =	.148361
550		.020238 x	1,092.458140 =	22.109168
116		.850000 x	22.893045 =	19.459088
112		.425000 x	17.729980 =	7.535242
111		.425000 x	15.951934 =	6.779572
233		6.180000 x	.536700 =	3.316806
398.4		1.000000 x	71.200000 =	71.200000

			T.E =	130.558856

7026	7026				
398.5		125.400000 x	5.590000 =	700.986000	
236		16.808000 x	.613000 =	10.303304	
113		.909160 x	23.479183 =	21.346334	
113		3.400000 x	23.479183 =	79.829222	
6310		12.350000 x	1.561400 =	19.283290	
			AΘΡΟΙΣΜΑ =	831.748150	
	T.E =	.007259 x	831.748150 =	6.037660	
7027	7027				
236		1.100000 x	.613000 =	.674300	
113		.059500 x	23.479183 =	1.397011	
			T.E =	2.071311	
7028	7028				
111		.144500 x	15.951934 =	2.305054	
6751		.120000 x	5.890649 =	.706878	
6751		.600000 x	5.890649 =	3.534389	
111		.425000 x	15.951934 =	6.779572	
112		.144500 x	17.729980 =	2.561982	
			AΘΡΟΙΣΜΑ =	15.887876	
			T.E =	18.271057	
7029	7029				
568.1		.021250 x	2,876.820784 =	61.132442	
569.2		.021250 x	573.700320 =	12.191132	
570.2		.021250 x	151.502516 =	3.219428	
571.2		.021250 x	248.349672 =	5.277431	
			T.E =	81.820432	
7030	7030				
398.6		.015385 x	330.000000 =	5.077050	
572		.026563 x	823.022957 =	21.861959	
			AΘΡΟΙΣΜΑ =	26.939009	
			T.E =	37.714612	
7031	7031				
573		.106250 x	1,008.429743 =	107.145660	
			AΘΡΟΙΣΜΑ =	107.145660	
			T.E =	123.217509	
7032	7032				
573		.212500 x	1,008.429743 =	214.291320	
			AΘΡΟΙΣΜΑ =	214.291320	
			T.E =	278.578717	

7101.1	7101.1			
398.1		15.000000 x	.225000 =	3.375000
574		.132813 x	3,363.433313 =	446.707669
T 630		.105000 x	1.643667 =	.172585
T 630.1		.105000 x	1.931874 =	.202847
567		.132813 x	344.394868 =	45.740116

			AΘΡΟΙΣΜΑ =	496.198216

			T.E =	511.084162
7101.2	7101.2			
398.1		15.000000 x	.225000 =	3.375000
574		.148750 x	3,363.433313 =	500.310705
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585
567		.148750 x	344.394868 =	51.228737

			AΘΡΟΙΣΜΑ =	555.289874

			T.E =	571.948570
7101.3	7101.3			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585
574		.159375 x	3,363.433313 =	536.047184
567		.159375 x	344.394868 =	54.887932

			AΘΡΟΙΣΜΑ =	594.685548

			T.E =	612.526115
7101.4	7101.4			
398.1		15.000000 x	.225000 =	3.375000
567		.170000 x	344.394868 =	58.547128
574		.170000 x	3,363.433313 =	571.783663
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585

			AΘΡΟΙΣΜΑ =	634.081223

			T.E =	653.103659
7101.5	7101.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.931874 =	.202847
567		.191250 x	344.394868 =	65.865519
T 630		.105000 x	1.643667 =	.172585
574		.191250 x	3,363.433313 =	643.256621

			AΘΡΟΙΣΜΑ =	712.872571

			T.E =	734.258749

7102.1	7102.1			
398.1		15.000000 x	.225000 =	3.375000
567		.302813 x	344.394868 =	104.287243
T 630		.105000 x	1.643667 =	.172585
T 630.1		.105000 x	1.931874 =	.202847
574		.302813 x	3,363.433313 =	1,018.491332

			AΘΡΟΙΣΜΑ =	1,126.529007

			T.E =	1,160.324877
7102.2	7102.2			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585
574		.329375 x	3,363.433313 =	1,107.830847
567		.329375 x	344.394868 =	113.435060

			AΘΡΟΙΣΜΑ =	1,225.016339

			T.E =	1,261.766829
7102.3	7102.3			
398.1		15.000000 x	.225000 =	3.375000
567		.361250 x	344.394868 =	124.412646
T 630		.105000 x	1.643667 =	.172585
T 630.1		.105000 x	1.931874 =	.202847
574		.361250 x	3,363.433313 =	1,215.040284

			AΘΡΟΙΣΜΑ =	1,343.203362

			T.E =	1,383.499463
7102.4	7102.4			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585
574		.403750 x	3,363.433313 =	1,357.986200
567		.403750 x	344.394868 =	139.049428

			AΘΡΟΙΣΜΑ =	1,500.786060

			T.E =	1,545.809642
7102.5	7102.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585
567		.446250 x	344.394868 =	153.686210
574		.446250 x	3,363.433313 =	1,500.932116

			AΘΡΟΙΣΜΑ =	1,658.368758

			T.E =	1,708.119820

7103	7103			
113		3.400000 x	23.479183 =	79.829222
113		.283333 x	23.479183 =	6.652427
115		.070833 x	18.893831 =	1.338307
575		.106250 x	766.165013 =	81.405033

			T.E =	169.224989
7104	7104			
113		1.700000 x	23.479183 =	39.914611
576		.106250 x	7.216000 =	.766700
567		.106250 x	344.394868 =	36.591955

			T.E =	77.273266
7105	7105			
111		.850000 x	15.951934 =	13.559144
113		.850000 x	23.479183 =	19.957306
576		.106250 x	7.216000 =	.766700
567		.106250 x	344.394868 =	36.591955

			T.E =	70.875104
7106.1	7106.1			
577		.265625 x	701.638494 =	186.372725

			AΘΡΟΙΣΜΑ =	186.372725

			T.E =	195.691361
7106.2	7106.2			
577		.297500 x	701.638494 =	208.737452

			AΘΡΟΙΣΜΑ =	208.737452

			T.E =	219.174325
7106.3	7106.3			
577		.350625 x	701.638494 =	246.011997

			AΘΡΟΙΣΜΑ =	246.011997

			T.E =	258.312597
7106.4	7106.4			
577		.425000 x	701.638494 =	298.196360

			AΘΡΟΙΣΜΑ =	298.196360

			T.E =	313.106178

7106.5	7106.5			
577		.531250 x	701.638494 =	372.745450

			ΑΘΡΟΙΣΜΑ =	372.745450

			T.E =	391.382722
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	195.691361 =	195.691361

			T.E =	236.491361
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	219.174325 =	219.174325

			T.E =	259.974325
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	258.312597 =	258.312597

			T.E =	299.112597
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	313.106178 =	313.106178

			T.E =	353.906178
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	391.382722 =	391.382722

			T.E =	432.182722
7108	7108			
398.11		1.000000 x	136.770000 =	136.770000
574		.053125 x	3,363.433313 =	178.682395

			T.E =	315.452395
7109	7109			
398.12		1.000000 x	176.880000 =	176.880000
574		.053125 x	3,363.433313 =	178.682395

			T.E =	355.562395

7110	7110				
398.10		1.170000 x	138.730000 =		162.314100
574		.053125 x	3,363.433313 =		178.682395
				T.E =	340.996495
7111	7111				
398.9		1.170000 x	128.000000 =		149.760000
574		.053125 x	3,363.433313 =		178.682395
				T.E =	328.442395
7112	7112				
398.13		1.300000 x	8.330000 =		10.829000
577		.010625 x	701.638494 =		7.454909
				T.E =	18.283909
7113	7113				
241		1.200000 x	6.240000 =		7.488000
574		.001063 x	3,363.433313 =		3.575330
				T.E =	11.063330
7114	7114				
398.8		.120000 x	30.750000 =		3.690000
577		.053125 x	701.638494 =		37.274545
				T.E =	40.964545
7115	7115				
574		.026563 x	3,363.433313 =		89.342879
				T.E =	89.342879
7116	7116				
577		.170000 x	701.638494 =		119.278544
				T.E =	119.278544
7117	7117				
574		.001063 x	3,363.433313 =		3.575330
				T.E =	3.575330

7118.1	7118.1			
111		27.200000 x	15.951934 =	433.892605
578		.850000 x	638.997819 =	543.148146
574.1		.425000 x	2,179.724704 =	926.382999

			T.E =	1,903.423750
7118.2	7118.2			
111		40.800000 x	15.951934 =	650.838907
574.1		.850000 x	2,179.724704 =	1,852.765998
578		.850000 x	638.997819 =	543.148146

			T.E =	3,046.753052
7119.1	7119.1			
111		13.600000 x	15.951934 =	216.946302
577.1		.255000 x	428.834704 =	109.352850

			T.E =	326.299152
7119.2	7119.2			
111		13.600000 x	15.951934 =	216.946302
577.1		.595000 x	428.834704 =	255.156649

			T.E =	472.102951
7120.1	7120.1			
111		10.200000 x	15.951934 =	162.709727
575.1		.425000 x	231.750648 =	98.494025
578		.425000 x	638.997819 =	271.574073

			T.E =	532.777825
7120.2	7120.2			
111		17.000000 x	15.951934 =	271.182878
578		1.275000 x	638.997819 =	814.722219
575.1		1.275000 x	231.750648 =	295.482076

			T.E =	1,381.387173
7121.1	7121.1			
111		6.800000 x	15.951934 =	108.473151
576.1		.425000 x	6.560000 =	2.788000
578		.425000 x	638.997819 =	271.574073

			T.E =	382.835224

7121.2	7121.2			
111		6.800000 x	15.951934 =	108.473151
576.1		.425000 x	6.560000 =	2.788000
578		.425000 x	638.997819 =	271.574073

			T.E =	382.835224
7122	7122			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.643667 =	.172585
T 630.1		.105000 x	1.931874 =	.202847
567		.122188 x	344.394868 =	42.080920
580		.122188 x	1,669.242133 =	203.961358

			AΘΡΟΙΣΜΑ =	249.792710

			T.E =	257.286491
7123	7123			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585
580		.286875 x	1,669.242133 =	478.863837
567		.286875 x	344.394868 =	98.798278

			AΘΡΟΙΣΜΑ =	581.412546

			T.E =	598.854923
7124	7124			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585
567		.063750 x	344.394868 =	21.955173
580		.063750 x	1,669.242133 =	106.414186

			T.E =	132.119791
7125	7125			
398.1		15.000000 x	.225000 =	3.375000
580		.127500 x	1,669.242133 =	212.828372
567		.127500 x	344.394868 =	43.910346
T 630.1		.105000 x	1.931874 =	.202847
T 630		.105000 x	1.643667 =	.172585

			T.E =	260.489149
7126	7126			
398.16		1.000000 x	62.420000 =	62.420000
580		.053125 x	1,669.242133 =	88.678488

			T.E =	151.098488

7127	7127				
398.15		1.170000 x	75.690000 =		88.557300
580		.015938 x	1,669.242133 =		26.604381
				T.E =	115.161681
7128	7128				
398.14		1.170000 x	58.610000 =		68.573700
580		.015938 x	1,669.242133 =		26.604381
				T.E =	95.178081
7129	7129				
6751		1.000000 x	5.890649 =		5.890649
				T.E =	5.890649