

ΑΤΛΣ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

2ο Τρίμηνο του 2011

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	1.218700
212	1.421100
213	4.160000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.545500
252	2.100000
253	4.300000
254	5.000000
255	1.001500
256	4.100000
261	
262	.980000
263	.600000
311	437.840000
312	134.530000
313	206.720000
314	4.530000
315	55.210000
316	4.530000
317	126.080000
318	27.370000
319	22.070000
320	156.740000
321	213.360000
322	296.440000
323	337.580000
324	185.200000
325	317.230000
326	103.360000
327	4.530000
351	451.770000
352	383.570000
353	451.770000
354	592.710000
355	296.440000
356	48.650000
357	233.080000
358	46.930000
359	97.290000
360	102.460000

361	78.370000
362	271.240000
363	102.610000
380	568.910000
381	568.910000
382	568.910000
383	654.300000
384	1,083.720000
385	196.900000
386	519.550000
387	74.960000
388	74.960000
389	74.960000

401	401				
211		110.000000 x	1.218700 =	134.057000	
117		4.000000 x	10.001019 =	40.004076	
213		10.000000 x	4.160000 =	41.600000	
311		1.000000 x	437.840000 =	437.840000	
116		8.000000 x	23.886192 =	191.089536	
			ΑΘΡΟΙΣΜΑ =	844.590612	
			Η.Δ. =	929.049673	
402	402				
211		180.000000 x	1.218700 =	219.366000	
213		12.000000 x	4.160000 =	49.920000	
117		8.000000 x	10.001019 =	80.008152	
116		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
312		1.000000 x	134.530000 =	134.530000	
212		5.000000 x	1.421100 =	7.105500	
			ΑΘΡΟΙΣΜΑ =	820.516084	
			Η.Δ. =	902.567692	
403	403				
211		80.000000 x	1.218700 =	97.496000	
254		2.500000 x	5.000000 =	12.500000	
213		6.000000 x	4.160000 =	24.960000	
116		8.000000 x	23.886192 =	191.089536	
117		8.000000 x	10.001019 =	80.008152	
313		1.000000 x	206.720000 =	206.720000	
			ΑΘΡΟΙΣΜΑ =	612.773688	
			Η.Δ. =	674.051057	
404	404				
211		80.000000 x	1.218700 =	97.496000	
212		2.000000 x	1.421100 =	2.842200	
118		8.000000 x	21.778427 =	174.227416	
119		4.000000 x	10.001019 =	40.004076	
314		1.000000 x	4.530000 =	4.530000	
112		4.000000 x	17.312112 =	69.248448	
213		5.000000 x	4.160000 =	20.800000	
			ΑΘΡΟΙΣΜΑ =	409.148140	
			Η.Δ. =	450.062954	

405	405				
211		40.000000 x	1.218700 =	48.748000	
213		2.000000 x	4.160000 =	8.320000	
118		4.000000 x	21.778427 =	87.113708	
115		16.000000 x	20.419486 =	326.711776	
316		2.000000 x	4.530000 =	9.060000	
315		1.000000 x	55.210000 =	55.210000	
		-----			
		ΑΘΡΟΙΣΜΑ =		535.163484	
		-----			
		Η.Δ. =		588.679832	
406	406				
211		80.000000 x	1.218700 =	97.496000	
213		5.000000 x	4.160000 =	20.800000	
317		1.000000 x	126.080000 =	126.080000	
120		8.000000 x	16.777917 =	134.223336	
		-----			
		ΑΘΡΟΙΣΜΑ =		378.599336	
		-----			
		Η.Δ. =		416.459270	
407	407				
212		17.000000 x	1.421100 =	24.158700	
112		30.000000 x	17.312112 =	519.363360	
118		4.000000 x	21.778427 =	87.113708	
213		1.000000 x	4.160000 =	4.160000	
318		1.000000 x	27.370000 =	27.370000	
		-----			
		ΑΘΡΟΙΣΜΑ =		662.165768	
		-----			
		Η.Δ. =		728.382345	
408	408				
211		30.000000 x	1.218700 =	36.561000	
320		1.000000 x	156.740000 =	156.740000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
213		3.000000 x	4.160000 =	12.480000	
		-----			
		ΑΘΡΟΙΣΜΑ =		506.123060	
		-----			
		Η.Δ. =		556.735366	
409	409				
211		50.000000 x	1.218700 =	60.935000	
213		5.000000 x	4.160000 =	20.800000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
324		1.000000 x	185.200000 =	185.200000	
		-----			
		ΑΘΡΟΙΣΜΑ =		567.277060	
		-----			
		Η.Δ. =		624.004766	

410	410				
211		100.000000 x	1.218700 =	121.870000	
213		10.000000 x	4.160000 =	41.600000	
321		1.000000 x	213.360000 =	213.360000	
116		8.000000 x	23.886192 =	191.089536	
117		4.000000 x	10.001019 =	40.004076	
112		4.000000 x	17.312112 =	69.248448	
			-----		
			ΑΘΡΟΙΣΜΑ =	677.172060	
			-----		
			Η.Δ. =	744.889266	
411	411				
211		200.000000 x	1.218700 =	243.740000	
325		1.000000 x	317.230000 =	317.230000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
213		20.000000 x	4.160000 =	83.200000	
			-----		
			ΑΘΡΟΙΣΜΑ =	944.512060	
			-----		
			Η.Δ. =	1,038.963266	
412	412				
211		40.000000 x	1.218700 =	48.748000	
116		8.000000 x	23.886192 =	191.089536	
326		1.000000 x	103.360000 =	103.360000	
213		2.000000 x	4.160000 =	8.320000	
			-----		
			ΑΘΡΟΙΣΜΑ =	351.517536	
			-----		
			Η.Δ. =	386.669290	
413	413				
211		15.000000 x	1.218700 =	18.280500	
213		1.500000 x	4.160000 =	6.240000	
118		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
327		1.000000 x	4.530000 =	4.530000	
			-----		
			ΑΘΡΟΙΣΜΑ =	146.322117	
			-----		
			Η.Δ. =	160.954329	
501	501				
211		170.000000 x	1.218700 =	207.179000	
213		3.000000 x	4.160000 =	12.480000	
351		1.000000 x	451.770000 =	451.770000	
380		1.000000 x	568.910000 =	568.910000	
			-----		
			ΑΘΡΟΙΣΜΑ =	1,240.339000	
			-----		
			Η.Δ. =	1,364.372900	

502	502				
211		170.000000 x	1.218700 =	207.179000	
213		3.000000 x	4.160000 =	12.480000	
381		1.000000 x	568.910000 =	568.910000	
352		1.000000 x	383.570000 =	383.570000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,172.139000	
		-----			
			Η.Δ. =	1,289.352900	
503	503				
211		170.000000 x	1.218700 =	207.179000	
382		1.000000 x	568.910000 =	568.910000	
353		1.000000 x	451.770000 =	451.770000	
213		3.000000 x	4.160000 =	12.480000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,240.339000	
		-----			
			Η.Δ. =	1,364.372900	
504	504				
211		190.000000 x	1.218700 =	231.553000	
213		6.000000 x	4.160000 =	24.960000	
354		1.000000 x	592.710000 =	592.710000	
383		1.000000 x	654.300000 =	654.300000	
		-----			
			ΑΘΡΟΙΣΜΑ =	1,503.523000	
		-----			
			Η.Δ. =	1,653.875300	
505	505				
211		1,250.000000 x	1.218700 =	1,523.375000	
213		7.500000 x	4.160000 =	31.200000	
384		1.000000 x	1,083.720000 =	1,083.720000	
355		1.000000 x	296.440000 =	296.440000	
		-----			
			ΑΘΡΟΙΣΜΑ =	2,934.735000	
		-----			
			Η.Δ. =	3,228.208500	
506	506				
211		200.000000 x	1.218700 =	243.740000	
213		2.000000 x	4.160000 =	8.320000	
385		1.000000 x	196.900000 =	196.900000	
356		1.000000 x	48.650000 =	48.650000	
		-----			
			ΑΘΡΟΙΣΜΑ =	497.610000	
		-----			
			Η.Δ. =	547.371000	
507	507				
211		2,100.000000 x	1.218700 =	2,559.270000	
386		1.000000 x	519.550000 =	519.550000	
357		1.000000 x	233.080000 =	233.080000	
213		35.000000 x	4.160000 =	145.600000	
		-----			
			ΑΘΡΟΙΣΜΑ =	3,457.500000	
		-----			
			Η.Δ. =	3,734.100000	

508	508				
358		1.000000 x	46.930000 =		46.930000
387		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	121.890000
				Η.Δ. =	127.984500
509	509				
359		1.000000 x	97.290000 =		97.290000
388		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	172.250000
				Η.Δ. =	180.862500
510	510				
360		1.000000 x	102.460000 =		102.460000
389		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	177.420000
				Η.Δ. =	186.291000
511	511				
509		.800000 x	180.862500 =		144.690000
				Η.Δ. =	144.690000
512	512				
501		.600000 x	1,364.372900 =		818.623740
				Η.Δ. =	818.623740
513	513				
363		1.000000 x	102.610000 =		102.610000
123		8.000000 x	64.260999 =		514.087992
122		8.000000 x	13.510339 =		108.082712
121		8.000000 x	16.585068 =		132.680544
				Η.Δ. =	857.461248
1111A	1111A				
214		.200000 x	1.949500 =		.389900
511		.020000 x	144.690000 =		2.893800
405		.020000 x	588.679832 =		11.773597
513		.020000 x	857.461248 =		17.149225
				Β.Τ =	32.206522

1111B	1111B			
501		1.000000 x	1,364.372900 =	1,364.372900
506		1.000000 x	547.371000 =	547.371000
509		2.000000 x	180.862500 =	361.725000
			-----	
			ΑΘΡΟΙΣΜΑ =	2,273.468900
	B.T =	.002500 x	2,273.468900 =	5.683672
			-----	
1112A	1112A			
506		1.000000 x	547.371000 =	547.371000
512		1.000000 x	818.623740 =	818.623740
			-----	
			ΑΘΡΟΙΣΜΑ =	1,365.994740
	B.T =	.025000 x	1,365.994740 =	34.149869
			-----	
1112B	1112B			
1111B		1.000000 x	5.683672 =	5.683672
			-----	
			B.T =	5.683672
1113A	1113A			
214		.200000 x	1.949500 =	.389900
112		.250000 x	17.312112 =	4.328028
511		.035000 x	144.690000 =	5.064150
513		.035000 x	857.461248 =	30.011144
405		.025000 x	588.679832 =	14.716996
			-----	
			B.T =	54.510217
1113B	1113B			
1111B		1.000000 x	5.683672 =	5.683672
			-----	
			B.T =	5.683672
1114A	1114A			
112		.250000 x	17.312112 =	4.328028
506		.033000 x	547.371000 =	18.063243
512		.033000 x	818.623740 =	27.014583
			-----	
			B.T =	49.405854
1114B	1114B			
1111B		1.000000 x	5.683672 =	5.683672
			-----	
			B.T =	5.683672

1121A	1121A			
214		.150000 x	1.949500 =	.292425
115		.500000 x	20.419486 =	10.209743
405		.020000 x	588.679832 =	11.773597
		-----		
			B.T =	22.275765
1121B	1121B			
1111B		1.000000 x	5.683672 =	5.683672
		-----		
			B.T =	5.683672
1122A	1122A			
506		1.000000 x	547.371000 =	547.371000
512		1.000000 x	818.623740 =	818.623740
		-----		
			ΑΘΡΟΙΣΜΑ =	1,365.994740
	B.T =	.012500 x	1,365.994740 =	17.074934
		-----		
1122B	1122B			
1111B		1.000000 x	5.683672 =	5.683672
		-----		
			B.T =	5.683672
1123A	1123A			
214		.150000 x	1.949500 =	.292425
112		.150000 x	17.312112 =	2.596817
405		.025000 x	588.679832 =	14.716996
115		1.000000 x	20.419486 =	20.419486
		-----		
			B.T =	38.025724
1123B	1123B			
1111B		1.000000 x	5.683672 =	5.683672
		-----		
			B.T =	5.683672
1124A	1124A			
112		.150000 x	17.312112 =	2.596817
506		.020000 x	547.371000 =	10.947420
512		.020000 x	818.623740 =	16.372475
		-----		
			B.T =	29.916712
1124B	1124B			
1111B		1.000000 x	5.683672 =	5.683672
		-----		
			B.T =	5.683672

3110A 1	3110A 1			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.081799 =	.770450
701 2		.800000 x	4.930878 =	3.944702
701 2		.500000 x	4.930878 =	2.465439
630		.250000 x	3.219087 =	.804772
607		.500000 x	10.388843 =	5.194422
606		.800000 x	9.477148 =	7.581718
407		.040000 x	728.382345 =	29.135294
714		1.400000 x	7.218484 =	10.105878
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	22.070000 =	.441400

-----  
B.T = 130.696992

3110A 2	3110A 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.081799 =	.770450
701 4		.500000 x	4.622698 =	2.311349
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
319		.020000 x	22.070000 =	.441400
112		1.200000 x	17.312112 =	20.774534
407		.040000 x	728.382345 =	29.135294
611		.500000 x	25.875818 =	12.937909
606		.800000 x	9.477148 =	7.581718
714		1.400000 x	7.218484 =	10.105878
113		1.200000 x	20.419486 =	24.503383

-----  
B.T = 138.286389

3110A 3	3110A 3			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.081799 =	.770450
701 4		.800000 x	4.622698 =	3.698158
701 2		.500000 x	4.930878 =	2.465439
630		.250000 x	3.219087 =	.804772
610		.800000 x	21.994777 =	17.595822
607		.500000 x	10.388843 =	5.194422
407		.040000 x	728.382345 =	29.135294
714		1.400000 x	7.218484 =	10.105878
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534

-----  
B.T = 140.464551

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
714		1.400000 x	7.218484 =	10.105878
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	3.081799 =	.770450
701 4		.800000 x	4.622698 =	3.698158
701 4		.500000 x	4.622698 =	2.311349
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
610		.800000 x	21.994777 =	17.595822
407		.040000 x	728.382345 =	29.135294
112		1.200000 x	17.312112 =	20.774534
			B.T =	148.053949
3110B	3110B			
713 1		1.000000 x	5.836758 =	5.836758
704		1.000000 x	11.673515 =	11.673515
			B.T =	17.510273
3120A 1	3120A 1			
3110A 1		1.000000 x	130.696992 =	130.696992
			B.T =	130.696992
3120A 2	3120A 2			
3110A 2		1.000000 x	138.286389 =	138.286389
			B.T =	138.286389
3120A 3	3120A 3			
3110A 3		1.000000 x	140.464551 =	140.464551
			B.T =	140.464551
3120A 4	3120A 4			
3110A 4		1.000000 x	148.053949 =	148.053949
			B.T =	148.053949
3120B	3120B			
713 2		1.000000 x	6.321886 =	6.321886
705		1.000000 x	12.643771 =	12.643771
			B.T =	18.965657

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.930878 =	1.577881
601		.320000 x	23.612397 =	7.555967
3110A 1		.800000 x	130.696992 =	104.557594
-----				
			B.T =	119.988081
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	138.286389 =	110.629111
701 2		.320000 x	4.930878 =	1.577881
601		.320000 x	23.612397 =	7.555967
-----				
			B.T =	126.059598
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	140.464551 =	112.371641
701 2		.320000 x	4.930878 =	1.577881
601		.320000 x	23.612397 =	7.555967
-----				
			B.T =	127.802128
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.930878 =	1.577881
601		.320000 x	23.612397 =	7.555967
3110A 4		.800000 x	148.053949 =	118.443159
-----				
			B.T =	133.873646
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
3110A 1		.800000 x	130.696992 =	104.557594
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
-----				
			B.T =	118.773082
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
3110A 2		.800000 x	138.286389 =	110.629111
-----				
			B.T =	124.844599

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
3110A 3		.800000 x	140.464551 =	112.371641
		-----		
			B.T =	126.587129
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
3110A 4		.800000 x	148.053949 =	118.443159
		-----		
			B.T =	132.658647
3210B	3210B			
713 1		1.000000 x	5.836758 =	5.836758
704		1.000000 x	11.673515 =	11.673515
		-----		
			B.T =	17.510273
3220A 1	3220A 1			
3210A 1		1.000000 x	119.988081 =	119.988081
		-----		
			B.T =	119.988081
3220A 2	3220A 2			
3210A 2		1.000000 x	126.059598 =	126.059598
		-----		
			B.T =	126.059598
3220A 3	3220A 3			
3210A 3		1.000000 x	127.802128 =	127.802128
		-----		
			B.T =	127.802128
3220A 4	3220A 4			
3210A 4		1.000000 x	133.873646 =	133.873646
		-----		
			B.T =	133.873646
3220A 5	3220A 5			
3210A 5		1.000000 x	118.773082 =	118.773082
		-----		
			B.T =	118.773082

3220A 6	3220A 6			
3210A 6		1.000000 x	124.844599 =	124.844599
		-----		
			B.T =	124.844599
3220A 7	3220A 7			
3210A 7		1.000000 x	126.587129 =	126.587129
		-----		
			B.T =	126.587129
3220A 8	3220A 8			
3210A 8		1.000000 x	132.658647 =	132.658647
		-----		
			B.T =	132.658647
3220B	3220B			
713 2		1.000000 x	6.321886 =	6.321886
705		1.000000 x	12.643771 =	12.643771
		-----		
			B.T =	18.965657
3300A 1	3300A 1			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.081799 =	.770450
701 2		.500000 x	4.930878 =	2.465439
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
607		.500000 x	10.388843 =	5.194422
606		.800000 x	9.477148 =	7.581718
407		.040000 x	728.382345 =	29.135294
714		2.600000 x	7.218484 =	18.768058
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800
		-----		
			B.T =	182.858942
3300A 2	3300A 2			
221		300.000000 x	.099900 =	29.970000
111		2.700000 x	15.741598 =	42.502315
714		2.600000 x	7.218484 =	18.768058
701 5		.250000 x	3.081799 =	.770450
701 4		.500000 x	4.622698 =	2.311349
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
606		.800000 x	9.477148 =	7.581718
407		.040000 x	728.382345 =	29.135294
113		2.000000 x	20.419486 =	40.838972
319		.040000 x	22.070000 =	.882800
		-----		
			B.T =	190.448339

3300A 3

3300A 3

221		300.000000 x	.099900 =	29.970000
630		.250000 x	3.219087 =	.804772
701	5	.250000 x	3.081799 =	.770450
701	4	.800000 x	4.622698 =	3.698158
701	2	.500000 x	4.930878 =	2.465439
607		.500000 x	10.388843 =	5.194422
610		.800000 x	21.994777 =	17.595822
407		.040000 x	728.382345 =	29.135294
113		2.000000 x	20.419486 =	40.838972
714		2.600000 x	7.218484 =	18.768058
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800

B.T =

192.626501

3300A 4

3300A 4

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.081799 =	.770450
701	4	.800000 x	4.622698 =	3.698158
701	4	.500000 x	4.622698 =	2.311349
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
610		.800000 x	21.994777 =	17.595822
407		.040000 x	728.382345 =	29.135294
714		2.600000 x	7.218484 =	18.768058
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800

B.T =

200.215898

3300B 1

3300B 1

713	1	1.000000 x	5.836758 =	5.836758
704		1.000000 x	11.673515 =	11.673515

B.T =

17.510273

3300B 2

3300B 2

713	2	1.000000 x	6.321886 =	6.321886
705		1.000000 x	12.643771 =	12.643771

B.T =

18.965657

3400A 1	3400A 1			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	1.001500 =	5.007500
111		2.700000 x	15.741598 =	42.502315
112		1.000000 x	17.312112 =	17.312112
113		2.000000 x	20.419486 =	40.838972
701 5		.250000 x	3.081799 =	.770450
701 2		.800000 x	4.930878 =	3.944702
701 2		.500000 x	4.930878 =	2.465439
630		.250000 x	3.219087 =	.804772
607		.500000 x	10.388843 =	5.194422
606		.800000 x	9.477148 =	7.581718
407		.040000 x	728.382345 =	29.135294
113		.500000 x	20.419486 =	10.209743
319		.030000 x	22.070000 =	.662100

-----  
B.T = 196.399538

3400A 2	3400A 2			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	1.001500 =	5.007500
611		.500000 x	25.875818 =	12.937909
701 5		.250000 x	3.081799 =	.770450
701 4		.500000 x	4.622698 =	2.311349
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
606		.800000 x	9.477148 =	7.581718
407		.040000 x	728.382345 =	29.135294
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100

-----  
B.T = 203.988936

3400A 3	3400A 3			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.081799 =	.770450
701 4		.800000 x	4.622698 =	3.698158
701 2		.500000 x	4.930878 =	2.465439
630		.250000 x	3.219087 =	.804772
610		.800000 x	21.994777 =	17.595822
607		.500000 x	10.388843 =	5.194422
407		.040000 x	728.382345 =	29.135294
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
255		5.000000 x	1.001500 =	5.007500

-----  
B.T = 206.167097

3400A 4	3400A 4			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	1.001500 =	5.007500
112		1.000000 x	17.312112 =	17.312112
701 5		.250000 x	3.081799 =	.770450
701 4		.800000 x	4.622698 =	3.698158
701 4		.500000 x	4.622698 =	2.311349
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
610		.800000 x	21.994777 =	17.595822
407		.040000 x	728.382345 =	29.135294
113		.500000 x	20.419486 =	10.209743
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
			B.T =	213.756495
3400B 1	3400B 1			
704		1.000000 x	11.673515 =	11.673515
			B.T =	11.673515
3400B 2	3400B 2			
705		1.000000 x	12.643771 =	12.643771
			B.T =	12.643771
4110A 1	4110A 1			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.081799 =	.308180
701 2		.800000 x	4.930878 =	3.944702
701 2		.500000 x	4.930878 =	2.465439
630		.100000 x	3.219087 =	.321909
607		.500000 x	10.388843 =	5.194422
606		.800000 x	9.477148 =	7.581718
407		.070000 x	728.382345 =	50.986764
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392
			B.T =	199.363755

4110A 2	4110A 2			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
407		.070000 x	728.382345 =	50.986764
611		.500000 x	25.875818 =	12.937909
701 4		.500000 x	4.622698 =	2.311349
701 5		.100000 x	3.081799 =	.308180
701 2		.800000 x	4.930878 =	3.944702
630		.100000 x	3.219087 =	.321909
606		.800000 x	9.477148 =	7.581718
113		1.500000 x	20.419486 =	30.629229

-----  
B.T = 206.953153

4110A 3	4110A 3			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.081799 =	.308180
701 4		.800000 x	4.622698 =	3.698158
701 2		.500000 x	4.930878 =	2.465439
630		.100000 x	3.219087 =	.321909
610		.800000 x	21.994777 =	17.595822
607		.500000 x	10.388843 =	5.194422
111		4.000000 x	15.741598 =	62.966392
407		.070000 x	728.382345 =	50.986764
113		1.500000 x	20.419486 =	30.629229

-----  
B.T = 209.131314

4110A 4	4110A 4			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	728.382345 =	50.986764
611		.500000 x	25.875818 =	12.937909
701 5		.100000 x	3.081799 =	.308180
701 4		.800000 x	4.622698 =	3.698158
701 4		.500000 x	4.622698 =	2.311349
630		.100000 x	3.219087 =	.321909
610		.800000 x	21.994777 =	17.595822
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

-----  
B.T = 216.720712

4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
513		1.000000 x	857.461248 =	857.461248
508		1.000000 x	127.984500 =	127.984500
506		1.000000 x	547.371000 =	547.371000

-----  
B.T = 1,671.313644

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
701 2		1.200000 x	4.930878 =	5.917054
607		1.200000 x	10.388843 =	12.466612
263		42.000000 x	.600000 =	25.200000
112		5.000000 x	17.312112 =	86.560560
		-----		
			B.T =	165.109225
4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
701 4		1.200000 x	4.622698 =	5.547238
611		1.200000 x	25.875818 =	31.050982
263		42.000000 x	.600000 =	25.200000
112		5.000000 x	17.312112 =	86.560560
		-----		
			B.T =	183.323779
4120B	4120B			
4110B		.040000 x	1,671.313644 =	66.852546
		-----		
			B.T =	66.852546
4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.600000 =	25.200000
407		.050000 x	728.382345 =	36.419117
606		.800000 x	9.477148 =	7.581718
607		.500000 x	10.388843 =	5.194422
701 2		.500000 x	4.930878 =	2.465439
701 2		.800000 x	4.930878 =	3.944702
111		2.000000 x	15.741598 =	31.483196
		-----		
			B.T =	147.253595
4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	728.382345 =	36.419117
701 4		.500000 x	4.622698 =	2.311349
701 2		.800000 x	4.930878 =	3.944702
611		.500000 x	25.875818 =	12.937909
606		.800000 x	9.477148 =	7.581718
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.600000 =	25.200000
		-----		
			B.T =	154.842992

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
701 4		.800000 x	4.622698 =	3.698158
701 2		.500000 x	4.930878 =	2.465439
610		.800000 x	21.994777 =	17.595822
607		.500000 x	10.388843 =	5.194422
407		.050000 x	728.382345 =	36.419117
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.600000 =	25.200000

-----  
B.T = 157.021154

4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.622698 =	2.311349
701 4		.800000 x	4.622698 =	3.698158
611		.500000 x	25.875818 =	12.937909
610		.800000 x	21.994777 =	17.595822
407		.050000 x	728.382345 =	36.419117
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.600000 =	25.200000

-----  
B.T = 164.610551

4130B	4130B			
4120B		1.000000 x	66.852546 =	66.852546

-----  
B.T = 66.852546

4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.081799 =	.462270
601		1.050000 x	23.612397 =	24.793017
630		.150000 x	3.219087 =	.482863
701 2		1.050000 x	4.930878 =	5.177422
701 2		.300000 x	4.930878 =	1.479263
607		.300000 x	10.388843 =	3.116653
222		10.000000 x	.070000 =	.700000

-----  
B.T = 42.704988

4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.081799 =	.462270
701 4		.300000 x	4.622698 =	1.386809
701 2		1.050000 x	4.930878 =	5.177422
630		.150000 x	3.219087 =	.482863
611		.300000 x	25.875818 =	7.762745
601		1.050000 x	23.612397 =	24.793017
222		10.000000 x	.070000 =	.700000

-----  
B.T = 47.258626

4210A 3	4210A 3			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.388843 =	3.116653
630		.150000 x	3.219087 =	.482863
701 5		.150000 x	3.081799 =	.462270
701 2		.300000 x	4.930878 =	1.479263
701 2		1.050000 x	4.930878 =	5.177422
609		1.050000 x	19.815525 =	20.806301

-----  
B.T = 38.718272

4210A 4	4210A 4			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.930878 =	5.177422
701 5		.150000 x	3.081799 =	.462270
701 4		.300000 x	4.622698 =	1.386809
609		1.050000 x	19.815525 =	20.806301
630		.150000 x	3.219087 =	.482863
611		.300000 x	25.875818 =	7.762745

-----  
B.T = 43.271911

4210B	4210B			
111		4.000000 x	15.741598 =	62.966392
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
112		1.500000 x	17.312112 =	25.968168

-----  
B.T = 143.445697

4220A 1	4220A 1			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
407		.040000 x	728.382345 =	29.135294
606		.800000 x	9.477148 =	7.581718
607		.500000 x	10.388843 =	5.194422
630		.250000 x	3.219087 =	.804772
701 5		.250000 x	3.081799 =	.770450
701 2		.800000 x	4.930878 =	3.944702
701 2		.500000 x	4.930878 =	2.465439

-----  
B.T = 109.186200

4220A 2	4220A 2			
221		200.000000 x	.099900 =	19.980000
113		1.000000 x	20.419486 =	20.419486
606		.800000 x	9.477148 =	7.581718
701 5		.250000 x	3.081799 =	.770450
701 4		.500000 x	4.622698 =	2.311349
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
407		.040000 x	728.382345 =	29.135294
111		1.200000 x	15.741598 =	18.889918

-----  
B.T = 116.775598

4220A 3	4220A 3			
221		200.000000 x	.099900 =	19.980000
701 4		.800000 x	4.622698 =	3.698158
701 2		.500000 x	4.930878 =	2.465439
630		.250000 x	3.219087 =	.804772
610		.800000 x	21.994777 =	17.595822
607		.500000 x	10.388843 =	5.194422
407		.040000 x	728.382345 =	29.135294
113		1.000000 x	20.419486 =	20.419486
111		1.200000 x	15.741598 =	18.889918
701 5		.250000 x	3.081799 =	.770450

-----  
B.T = 118.953759

4220A 4	4220A 4			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	728.382345 =	29.135294
611		.500000 x	25.875818 =	12.937909
701 5		.250000 x	3.081799 =	.770450
701 4		.500000 x	4.622698 =	2.311349
701 4		.800000 x	4.622698 =	3.698158
630		.250000 x	3.219087 =	.804772
610		.800000 x	21.994777 =	17.595822
113		1.000000 x	20.419486 =	20.419486

-----  
B.T = 126.543157

4300A 1	4300A 1			
221		350.000000 x	.099900 =	34.965000
607		.500000 x	10.388843 =	5.194422
701 2		.500000 x	4.930878 =	2.465439
701 5		.250000 x	3.081799 =	.770450
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
606		.800000 x	9.477148 =	7.581718
111		2.000000 x	15.741598 =	31.483196
714		1.150000 x	7.218484 =	8.301257
407		.040000 x	728.382345 =	29.135294
113		1.200000 x	20.419486 =	24.503383
			AΘΡΟΙΣΜΑ =	149.149632
	B.T =	.200000 x	149.149632 =	29.829926
4300A 2	4300A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.081799 =	.770450
701 4		.500000 x	4.622698 =	2.311349
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
606		.800000 x	9.477148 =	7.581718
407		.040000 x	728.382345 =	29.135294
714		1.150000 x	7.218484 =	8.301257
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
			AΘΡΟΙΣΜΑ =	156.739030
	B.T =	.200000 x	156.739030 =	31.347806
4300A 3	4300A 3			
221		350.000000 x	.099900 =	34.965000
607		.500000 x	10.388843 =	5.194422
701 5		.250000 x	3.081799 =	.770450
701 4		.800000 x	4.622698 =	3.698158
701 2		.500000 x	4.930878 =	2.465439
630		.250000 x	3.219087 =	.804772
610		.800000 x	21.994777 =	17.595822
407		.040000 x	728.382345 =	29.135294
714		1.150000 x	7.218484 =	8.301257
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
			AΘΡΟΙΣΜΑ =	158.917192
	B.T =	.200000 x	158.917192 =	31.783438

4300A 4	4300A 4			
221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.741598 =	31.483196
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	3.081799 =	.770450
701 4		.800000 x	4.622698 =	3.698158
701 4		.500000 x	4.622698 =	2.311349
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
610		.800000 x	21.994777 =	17.595822
407		.040000 x	728.382345 =	29.135294
714		1.150000 x	7.218484 =	8.301257
			-----	
			ΑΘΡΟΙΣΜΑ =	166.506589
	B.T =	.200000 x	166.506589 =	33.301318
			-----	
4300B	4300B			
221		2.000000 x	.099900 =	.199800
262		4.000000 x	.980000 =	3.920000
112		.400000 x	17.312112 =	6.924845
			-----	
			B.T =	11.044645
601	601			
111		1.500000 x	15.741598 =	23.612397
			-----	
			B.T =	23.612397
602	602			
403		.002500 x	674.051057 =	1.685128
			-----	
			B.T =	1.685128
603	603			
111		.300000 x	15.741598 =	4.722479
401		.001000 x	929.049673 =	.929050
412		.003300 x	386.669290 =	1.276009
			-----	
			B.T =	6.927538
604	604			
111		.200000 x	15.741598 =	3.148320
401		.001100 x	929.049673 =	1.021955
412		.004000 x	386.669290 =	1.546677
404		.005000 x	450.062954 =	2.250315
			-----	
			B.T =	7.967266

605	605			
112		.100000 x	17.312112 =	1.731211
402		.006200 x	902.567692 =	5.595920
412		.004000 x	386.669290 =	1.546677
406		.006200 x	416.459270 =	2.582047
401		.001000 x	929.049673 =	.929050

-----  
B.T = 12.384905

606	606			
111		.100000 x	15.741598 =	1.574160
412		.005000 x	386.669290 =	1.933346
406		.006700 x	416.459270 =	2.790277
404		.005000 x	450.062954 =	2.250315
401		.001000 x	929.049673 =	.929050

-----  
B.T = 9.477148

607	607			
111		.100000 x	15.741598 =	1.574160
412		.005000 x	386.669290 =	1.933346
406		.006700 x	416.459270 =	2.790277
404		.006200 x	450.062954 =	2.790390
401		.001400 x	929.049673 =	1.300670

-----  
B.T = 10.388843

608	608			
111		.100000 x	15.741598 =	1.574160
404		.012500 x	450.062954 =	5.625787
401		.002000 x	929.049673 =	1.858099
412		.005000 x	386.669290 =	1.933346
406		.006700 x	416.459270 =	2.790277

-----  
B.T = 13.781670

609	609			
214		.100000 x	1.949500 =	.194950
111		.800000 x	15.741598 =	12.593278
115		.200000 x	20.419486 =	4.083897
405		.005000 x	588.679832 =	2.943399

-----  
B.T = 19.815525

610	610				
214		.100000 x	1.949500 =	.194950	
112		.100000 x	17.312112 =	1.731211	
412		.005000 x	386.669290 =	1.933346	
406		.005000 x	416.459270 =	2.082296	
405		.005000 x	588.679832 =	2.943399	
402		.010000 x	902.567692 =	9.025677	
115		.200000 x	20.419486 =	4.083897	
			B.T =	21.994777	
611	611				
214		.100000 x	1.949500 =	.194950	
112		.100000 x	17.312112 =	1.731211	
115		.200000 x	20.419486 =	4.083897	
406		.005000 x	416.459270 =	2.082296	
412		.005000 x	386.669290 =	1.933346	
405		.005000 x	588.679832 =	2.943399	
402		.014300 x	902.567692 =	12.906718	
			B.T =	25.875818	
612	612				
214		.150000 x	1.949500 =	.292425	
408		.010000 x	556.735366 =	5.567354	
115		.200000 x	20.419486 =	4.083897	
405		.005000 x	588.679832 =	2.943399	
111		.300000 x	15.741598 =	4.722479	
			AΘΡΟΙΣΜΑ =	17.609554	
	B.T =	1.068000 x	17.609554 =	18.807004	
613	613				
214		.150000 x	1.949500 =	.292425	
409		.010000 x	624.004766 =	6.240048	
405		.005000 x	588.679832 =	2.943399	
115		.200000 x	20.419486 =	4.083897	
111		.500000 x	15.741598 =	7.870799	
			AΘΡΟΙΣΜΑ =	21.430568	
	B.T =	1.282000 x	21.430568 =	27.473988	
614	614				
214		.150000 x	1.949500 =	.292425	
111		.500000 x	15.741598 =	7.870799	
115		.200000 x	20.419486 =	4.083897	
410		.010000 x	744.889266 =	7.448893	
405		.005000 x	588.679832 =	2.943399	
			AΘΡΟΙΣΜΑ =	22.639413	
	B.T =	1.602000 x	22.639413 =	36.268340	

615	615				
214		.150000 x	1.949500 =	.292425	
410		.010000 x	744.889266 =	7.448893	
111		.700000 x	15.741598 =	11.019119	
405		.005000 x	588.679832 =	2.943399	
115		.200000 x	20.419486 =	4.083897	
			-----		
			ΑΘΡΟΙΣΜΑ =	25.787733	
	B.T =	1.832000 x	25.787733 =	47.243126	
			-----		
616	616				
214		.150000 x	1.949500 =	.292425	
111		.800000 x	15.741598 =	12.593278	
405		.005000 x	588.679832 =	2.943399	
411		.010000 x	1,038.963266 =	10.389633	
115		.200000 x	20.419486 =	4.083897	
			-----		
			ΑΘΡΟΙΣΜΑ =	30.302632	
	B.T =	2.137000 x	30.302632 =	64.756725	
			-----		
617	617				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	857.461248 =	857.461248	
506		1.000000 x	547.371000 =	547.371000	
503		1.000000 x	1,364.372900 =	1,364.372900	
			-----		
			ΑΘΡΟΙΣΜΑ =	2,838.453596	
	B.T =	.006250 x	2,838.453596 =	17.740335	
			-----		
618	618				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	857.461248 =	857.461248	
506		1.000000 x	547.371000 =	547.371000	
503		1.000000 x	1,364.372900 =	1,364.372900	
			-----		
			ΑΘΡΟΙΣΜΑ =	2,838.453596	
	B.T =	.007700 x	2,838.453596 =	21.856093	
			-----		
619	619				
112		4.000000 x	17.312112 =	69.248448	
503		1.000000 x	1,364.372900 =	1,364.372900	
506		1.000000 x	547.371000 =	547.371000	
513		1.000000 x	857.461248 =	857.461248	
			-----		
			ΑΘΡΟΙΣΜΑ =	2,838.453596	
	B.T =	.010000 x	2,838.453596 =	28.384536	
			-----		

620	620			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	547.371000 =	547.371000
503		1.000000 x	1,364.372900 =	1,364.372900
			-----	
			ΑΘΡΟΙΣΜΑ =	2,838.453596
	B.T =	.012500 x	2,838.453596 =	35.480670
			-----	
621	621			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	547.371000 =	547.371000
503		1.000000 x	1,364.372900 =	1,364.372900
513		1.000000 x	857.461248 =	857.461248
			-----	
			ΑΘΡΟΙΣΜΑ =	2,838.453596
	B.T =	.016600 x	2,838.453596 =	47.118330
			-----	
630	630			
413		.020000 x	160.954329 =	3.219087
			-----	
			B.T =	3.219087
701 1	701 1			
406		.012580 x	416.459270 =	5.239058
			-----	
			B.T =	5.239058
701 2	701 2			
406		.011840 x	416.459270 =	4.930878
			-----	
			B.T =	4.930878
701 3	701 3			
406		.011544 x	416.459270 =	4.807606
			-----	
			B.T =	4.807606
701 4	701 4			
406		.011100 x	416.459270 =	4.622698
			-----	
			B.T =	4.622698
701 5	701 5			
406		.007400 x	416.459270 =	3.081799
			-----	
			B.T =	3.081799

702	702			
112		8.000000 x	17.312112 =	138.496896
506		1.000000 x	547.371000 =	547.371000
513		.300000 x	857.461248 =	257.238374
509		2.000000 x	180.862500 =	361.725000
			-----	
			ΑΘΡΟΙΣΜΑ =	1,304.831270
	B.T =	.002500 x	1,304.831270 =	3.262078
			-----	
703	703			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,364.372900 =	1,364.372900
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	547.371000 =	547.371000
513		.300000 x	857.461248 =	257.238374
			-----	
			ΑΘΡΟΙΣΜΑ =	2,610.812722
	B.T =	.002500 x	2,610.812722 =	6.527032
			-----	
704	704			
112		4.000000 x	17.312112 =	69.248448
502		1.000000 x	1,289.352900 =	1,289.352900
513		.500000 x	857.461248 =	428.730624
506		1.000000 x	547.371000 =	547.371000
			-----	
			ΑΘΡΟΙΣΜΑ =	2,334.702972
	B.T =	.005000 x	2,334.702972 =	11.673515
			-----	
705	705			
112		4.000000 x	17.312112 =	69.248448
513		.600000 x	857.461248 =	514.476749
506		1.000000 x	547.371000 =	547.371000
504		1.000000 x	1,653.875300 =	1,653.875300
			-----	
			ΑΘΡΟΙΣΜΑ =	2,784.971497
	B.T =	.004540 x	2,784.971497 =	12.643771
			-----	
706	706			
501		1.000000 x	1,364.372900 =	1,364.372900
509		2.000000 x	180.862500 =	361.725000
506		1.000000 x	547.371000 =	547.371000
			-----	
			ΑΘΡΟΙΣΜΑ =	2,273.468900
	B.T =	.002500 x	2,273.468900 =	5.683672
			-----	
707	707			
505		1.000000 x	3,228.208500 =	3,228.208500
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	547.371000 =	547.371000
			-----	
			ΑΘΡΟΙΣΜΑ =	4,148.161500
	B.T =	.001000 x	4,148.161500 =	4.148162
			-----	

ΑΤΛΕ		2ο Τρίμηνο του 2011		Σελ.	31
				Ημ/νία	22/12/2011
708	708				
708A		1.000000 x	17.477485 =		17.477485
708B		1.000000 x	5.683672 =		5.683672
-----					
			B.T =		23.161157
708A	708A				
214		.050000 x	1.949500 =		.097475
513		.010000 x	857.461248 =		8.574612
511		.010000 x	144.690000 =		1.446900
405		.012500 x	588.679832 =		7.358498
-----					
			B.T =		17.477485
708B	708B				
706		1.000000 x	5.683672 =		5.683672
-----					
			B.T =		5.683672
709	709				
709A		1.000000 x	17.074934 =		17.074934
709B		1.000000 x	5.683672 =		5.683672
-----					
			B.T =		22.758606
709A	709A				
506		1.000000 x	547.371000 =		547.371000
512		1.000000 x	818.623740 =		818.623740
-----					
			AΘΡΟΙΣΜΑ =		1,365.994740
	B.T =	.012500 x	1,365.994740 =		17.074934
-----					
709B	709B				
706		1.000000 x	5.683672 =		5.683672
-----					
			B.T =		5.683672
710	710				
710A		1.000000 x	50.182189 =		50.182189
710B		1.000000 x	5.683672 =		5.683672
-----					
			B.T =		55.865861
710A	710A				
214		.200000 x	1.949500 =		.389900
405		.025000 x	588.679832 =		14.716996
513		.035000 x	857.461248 =		30.011144
511		.035000 x	144.690000 =		5.064150
-----					
			B.T =		50.182189

710B	710B			
706		1.000000 x	5.683672 =	5.683672
		-----		
			B.T =	5.683672
711	711			
711A		1.000000 x	45.487625 =	45.487625
711B		1.000000 x	5.683672 =	5.683672
		-----		
			B.T =	51.171297
711A	711A			
506		1.000000 x	547.371000 =	547.371000
512		1.000000 x	818.623740 =	818.623740
		-----		
			AΘΡΟΙΣΜΑ =	1,365.994740
	B.T =	.033300 x	1,365.994740 =	45.487625
		-----		
711B	711B			
706		1.000000 x	5.683672 =	5.683672
		-----		
			B.T =	5.683672
712	712			
513		1.000000 x	857.461248 =	857.461248
		-----		
			AΘΡΟΙΣΜΑ =	857.461248
	B.T =	.004000 x	857.461248 =	3.429845
		-----		
713 1	713 1			
704		.500000 x	11.673515 =	5.836758
		-----		
			B.T =	5.836758
713 2	713 2			
705		.500000 x	12.643771 =	6.321886
		-----		
			B.T =	6.321886
714	714			
714A		1.000000 x	3.445324 =	3.445324
714B		1.000000 x	3.773160 =	3.773160
		-----		
			B.T =	7.218484

714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	2.100000 =	2.100000
113		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	103.463196
	B.T =	.033300 x	103.463196 =	3.445324
714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211
			B.T =	3.773160
1111	1111			
1111A		1.000000 x	32.206522 =	32.206522
1111B		1.000000 x	5.683672 =	5.683672
			T.E =	37.890194
1112	1112			
1112A		1.000000 x	34.149869 =	34.149869
1112B		1.000000 x	5.683672 =	5.683672
			T.E =	39.833541
1113	1113			
1113A		1.000000 x	54.510217 =	54.510217
1113B		1.000000 x	5.683672 =	5.683672
			T.E =	60.193889
1114	1114			
1114A		1.000000 x	49.405854 =	49.405854
1114B		1.000000 x	5.683672 =	5.683672
			T.E =	55.089526
1121	1121			
1121A		1.000000 x	22.275765 =	22.275765
1121B		1.000000 x	5.683672 =	5.683672
			T.E =	27.959437
1122	1122			
1122A		1.000000 x	17.074934 =	17.074934
1122B		1.000000 x	5.683672 =	5.683672
			T.E =	22.758606

1123	1123				
1123A		1.000000 x	38.025724 =		38.025724
1123B		1.000000 x	5.683672 =		5.683672
		-----			
			T.E =		43.709396
1124	1124				
1124A		1.000000 x	29.916712 =		29.916712
1124B		1.000000 x	5.683672 =		5.683672
		-----			
			T.E =		35.600384
1210	1210				
707		1.000000 x	4.148162 =		4.148162
		-----			
			T.E =		4.148162
1220	1220				
708		1.000000 x	23.161157 =		23.161157
		-----			
			T.E =		23.161157
1230	1230				
709		1.000000 x	22.758606 =		22.758606
		-----			
			T.E =		22.758606
1311	1311				
712		.250000 x	3.429845 =		.857461
		-----			
			T.E =		.857461
1312	1312				
712		.250000 x	3.429845 =		.857461
701 1		1.000000 x	5.239058 =		5.239058
602		1.000000 x	1.685128 =		1.685128
		-----			
			T.E =		7.781647
1313	1313				
712		.250000 x	3.429845 =		.857461
603		1.000000 x	6.927538 =		6.927538
701 2		1.000000 x	4.930878 =		4.930878
		-----			
			T.E =		12.715877

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
712		.250000 x	3.429845 =	.857461	
		-----			
			T.E =	37.431621	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
701	1	1.000000 x	5.239058 =	5.239058	
602		1.000000 x	1.685128 =	1.685128	
		-----			
			T.E =	10.386608	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
603		1.000000 x	6.927538 =	6.927538	
701	2	1.000000 x	4.930878 =	4.930878	
		-----			
			T.E =	15.320838	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
112		.100000 x	17.312112 =	1.731211	
		-----			
			T.E =	38.305371	
2110	2110				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.262078 =	3.262078	
608		1.000000 x	13.781670 =	13.781670	
701	4	1.000000 x	4.622698 =	4.622698	
		-----			
			T.E =	23.381369	
2120	2120				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.262078 =	3.262078	
701	2	1.000000 x	4.930878 =	4.930878	
603		1.000000 x	6.927538 =	6.927538	
		-----			
			T.E =	16.835417	
2130	2130				
712		.500000 x	3.429845 =	1.714923	
604		1.000000 x	7.967266 =	7.967266	
701	2	1.000000 x	4.930878 =	4.930878	
702		1.000000 x	3.262078 =	3.262078	
		-----			
			T.E =	17.875145	

2140	2140				
712		.500000 x	3.429845 =	1.714923	
605		1.000000 x	12.384905 =	12.384905	
702		1.000000 x	3.262078 =	3.262078	
701	2	1.000000 x	4.930878 =	4.930878	
				-----	
			T.E =	22.292784	
2210	2210				
712		.500000 x	3.429845 =	1.714923	
609		1.050000 x	19.815525 =	20.806301	
702		1.000000 x	3.262078 =	3.262078	
701	2	1.000000 x	4.930878 =	4.930878	
				-----	
			T.E =	30.714180	
2220	2220				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.262078 =	3.262078	
701	2	1.000000 x	4.930878 =	4.930878	
609		1.150000 x	19.815525 =	22.787854	
				-----	
			T.E =	32.695732	
2230	2230				
111		.200000 x	15.741598 =	3.148320	
609		1.200000 x	19.815525 =	23.778630	
701	2	1.000000 x	4.930878 =	4.930878	
				-----	
			T.E =	31.857828	
2240	2240				
111		.300000 x	15.741598 =	4.722479	
609		1.200000 x	19.815525 =	23.778630	
701	2	1.000000 x	4.930878 =	4.930878	
				-----	
			T.E =	33.431987	
2310	2310				
612		1.000000 x	18.807004 =	18.807004	
701	3	1.000000 x	4.807606 =	4.807606	
703		1.000000 x	6.527032 =	6.527032	
				-----	
			T.E =	30.141642	
2320	2320				
613		1.000000 x	27.473988 =	27.473988	
703		1.000000 x	6.527032 =	6.527032	
701	3	1.000000 x	4.807606 =	4.807606	
				-----	
			T.E =	38.808626	

2330	2330				
614		1.000000 x	36.268340 =		36.268340
703		1.000000 x	6.527032 =		6.527032
701	3	1.000000 x	4.807606 =		4.807606
		-----			
			T.E =		47.602978
2340	2340				
615		1.000000 x	47.243126 =		47.243126
703		1.000000 x	6.527032 =		6.527032
701	3	1.000000 x	4.807606 =		4.807606
		-----			
			T.E =		58.577764
2350	2350				
616		1.000000 x	64.756725 =		64.756725
703		1.000000 x	6.527032 =		6.527032
701	3	1.000000 x	4.807606 =		4.807606
		-----			
			T.E =		76.091363
2410	2410				
617		1.000000 x	17.740335 =		17.740335
703		1.000000 x	6.527032 =		6.527032
		-----			
			T.E =		24.267367
2420	2420				
618		1.000000 x	21.856093 =		21.856093
703		1.000000 x	6.527032 =		6.527032
		-----			
			T.E =		28.383125
2430	2430				
619		1.000000 x	28.384536 =		28.384536
703		1.000000 x	6.527032 =		6.527032
		-----			
			T.E =		34.911568
2440	2440				
620		1.000000 x	35.480670 =		35.480670
703		1.000000 x	6.527032 =		6.527032
		-----			
			T.E =		42.007702
2450	2450				
621		1.000000 x	47.118330 =		47.118330
703		1.000000 x	6.527032 =		6.527032
		-----			
			T.E =		53.645362

3110	1	3110	1			
	3110A 1			1.000000 x	130.696992 =	130.696992
	3110B			1.000000 x	17.510273 =	17.510273
-----						
						T.E =
						148.207265
3110	2	3110	2			
	3110A 2			1.000000 x	138.286389 =	138.286389
	3110B			1.000000 x	17.510273 =	17.510273
-----						
						T.E =
						155.796662
3110	3	3110	3			
	3110A 3			1.000000 x	140.464551 =	140.464551
	3110B			1.000000 x	17.510273 =	17.510273
-----						
						T.E =
						157.974824
3110	4	3110	4			
	3110A 4			1.000000 x	148.053949 =	148.053949
	3110B			1.000000 x	17.510273 =	17.510273
-----						
						T.E =
						165.564222
3120	1	3120	1			
	3120A 1			1.000000 x	130.696992 =	130.696992
	3120B			1.000000 x	18.965657 =	18.965657
-----						
						T.E =
						149.662649
3120	2	3120	2			
	3120A 2			1.000000 x	138.286389 =	138.286389
	3120B			1.000000 x	18.965657 =	18.965657
-----						
						T.E =
						157.252046
3120	3	3120	3			
	3120A 3			1.000000 x	140.464551 =	140.464551
	3120B			1.000000 x	18.965657 =	18.965657
-----						
						T.E =
						159.430208
3120	4	3120	4			
	3120A 4			1.000000 x	148.053949 =	148.053949
	3120B			1.000000 x	18.965657 =	18.965657
-----						
						T.E =
						167.019606

3210 1	3210 1				
3210A 1		1.000000 x	119.988081 =	119.988081	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	137.498354	
3210 2	3210 2				
3210A 2		1.000000 x	126.059598 =	126.059598	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	143.569871	
3210 3	3210 3				
3210A 3		1.000000 x	127.802128 =	127.802128	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	145.312401	
3210 4	3210 4				
3210A 4		1.000000 x	133.873646 =	133.873646	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	151.383919	
3210 5	3210 5				
3210A 5		1.000000 x	118.773082 =	118.773082	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	136.283355	
3210 6	3210 6				
3210A 6		1.000000 x	124.844599 =	124.844599	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	142.354872	
3210 7	3210 7				
3210A 7		1.000000 x	126.587129 =	126.587129	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	144.097402	
3210 8	3210 8				
3210A 8		1.000000 x	132.658647 =	132.658647	
3210B		1.000000 x	17.510273 =	17.510273	
		-----			
			T.E =	150.168920	

3220 1	3220 1				
3220A 1		1.000000 x	119.988081 =	119.988081	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	138.953738	
3220 2	3220 2				
3220A 2		1.000000 x	126.059598 =	126.059598	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	145.025255	
3220 3	3220 3				
3220A 3		1.000000 x	127.802128 =	127.802128	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	146.767785	
3220 4	3220 4				
3220A 4		1.000000 x	133.873646 =	133.873646	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	152.839303	
3220 5	3220 5				
3220A 5		1.000000 x	118.773082 =	118.773082	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	137.738739	
3220 6	3220 6				
3220A 6		1.000000 x	124.844599 =	124.844599	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	143.810256	
3220 7	3220 7				
3220A 7		1.000000 x	126.587129 =	126.587129	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	145.552786	
3220 8	3220 8				
3220A 8		1.000000 x	132.658647 =	132.658647	
3220B		1.000000 x	18.965657 =	18.965657	
		-----			
			T.E =	151.624304	

ΑΤΛΕ		2ο Τρίμηνο του 2011		Σελ.	41
				Ημ/νία	22/12/2011
3300	1	3300	1		
	3300A 1		1.000000 x	182.858942 =	182.858942
	3300B 1		1.000000 x	17.510273 =	17.510273
				-----	
				T.E =	200.369215
3300	2	3300	2		
	3300A 1		1.000000 x	182.858942 =	182.858942
	3300B 2		1.000000 x	18.965657 =	18.965657
				-----	
				T.E =	201.824599
3300	3	3300	3		
	3300A 2		1.000000 x	190.448339 =	190.448339
	3300B 1		1.000000 x	17.510273 =	17.510273
				-----	
				T.E =	207.958612
3300	4	3300	4		
	3300A 2		1.000000 x	190.448339 =	190.448339
	3300B 2		1.000000 x	18.965657 =	18.965657
				-----	
				T.E =	209.413996
3300	5	3300	5		
	3300A 3		1.000000 x	192.626501 =	192.626501
	3300B 1		1.000000 x	17.510273 =	17.510273
				-----	
				T.E =	210.136774
3300	6	3300	6		
	3300A 3		1.000000 x	192.626501 =	192.626501
	3300B 2		1.000000 x	18.965657 =	18.965657
				-----	
				T.E =	211.592158
3300	7	3300	7		
	3300A 4		1.000000 x	200.215898 =	200.215898
	3300B 1		1.000000 x	17.510273 =	17.510273
				-----	
				T.E =	217.726171
3300	8	3300	8		
	3300A 4		1.000000 x	200.215898 =	200.215898
	3300B 2		1.000000 x	18.965657 =	18.965657
				-----	
				T.E =	219.181555

3400 1	3400 1				
3400A 1		1.000000 x	196.399538 =	196.399538	
3400B 1		1.000000 x	11.673515 =	11.673515	
		-----			
			T.E =	208.073053	
3400 2	3400 2				
3400A 1		1.000000 x	196.399538 =	196.399538	
3400B 2		1.000000 x	12.643771 =	12.643771	
		-----			
			T.E =	209.043309	
3400 3	3400 3				
3400A 2		1.000000 x	203.988936 =	203.988936	
3400B 1		1.000000 x	11.673515 =	11.673515	
		-----			
			T.E =	215.662451	
3400 4	3400 4				
3400A 2		1.000000 x	203.988936 =	203.988936	
3400B 2		1.000000 x	12.643771 =	12.643771	
		-----			
			T.E =	216.632707	
3400 5	3400 5				
3400A 3		1.000000 x	206.167097 =	206.167097	
3400B 1		1.000000 x	11.673515 =	11.673515	
		-----			
			T.E =	217.840612	
3400 6	3400 6				
3400A 3		1.000000 x	206.167097 =	206.167097	
3400B 2		1.000000 x	12.643771 =	12.643771	
		-----			
			T.E =	218.810868	
3400 7	3400 7				
3400A 4		1.000000 x	213.756495 =	213.756495	
3400B 1		1.000000 x	11.673515 =	11.673515	
		-----			
			T.E =	225.430010	
3400 8	3400 8				
3400A 4		1.000000 x	213.756495 =	213.756495	
3400B 2		1.000000 x	12.643771 =	12.643771	
		-----			
			T.E =	226.400266	

4110	1	4110	1			
	4110A 1			1.000000 x	199.363755 =	199.363755
	4110B			.025000 x	1,671.313644 =	41.782841
				-----		
					T.E =	241.146596
4110	2	4110	2			
	4110A 2			1.000000 x	206.953153 =	206.953153
	4110B			.025000 x	1,671.313644 =	41.782841
				-----		
					T.E =	248.735994
4110	3	4110	3			
	4110A 3			1.000000 x	209.131314 =	209.131314
	4110B			.025000 x	1,671.313644 =	41.782841
				-----		
					T.E =	250.914155
4110	4	4110	4			
	4110A 4			1.000000 x	216.720712 =	216.720712
	4110B			.025000 x	1,671.313644 =	41.782841
				-----		
					T.E =	258.503553
4120	1	4120	1			
	4120A 1			1.000000 x	165.109225 =	165.109225
	4120B			1.000000 x	66.852546 =	66.852546
				-----		
					T.E =	231.961771
4120	2	4120	2			
	4120A 2			1.000000 x	183.323779 =	183.323779
	4120B			1.000000 x	66.852546 =	66.852546
				-----		
					T.E =	250.176325
4130	1	4130	1			
	4130A 1			1.000000 x	147.253595 =	147.253595
	4130B			1.000000 x	66.852546 =	66.852546
				-----		
					T.E =	214.106141
4130	2	4130	2			
	4130A 2			1.000000 x	154.842992 =	154.842992
	4130B			1.000000 x	66.852546 =	66.852546
				-----		
					T.E =	221.695538

4130	3	4130	3			
4130A	3			1.000000 x	157.021154 =	157.021154
4130B				1.000000 x	66.852546 =	66.852546
-----						
T.E =						223.873700
4130	4	4130	4			
4130A	4			1.000000 x	164.610551 =	164.610551
4130B				1.000000 x	66.852546 =	66.852546
-----						
T.E =						231.463097
4210	1	4210	1			
4210A	1			1.000000 x	42.704988 =	42.704988
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						186.150685
4210	2	4210	2			
4210A	2			1.000000 x	47.258626 =	47.258626
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						190.704323
4210	3	4210	3			
4210A	3			1.000000 x	38.718272 =	38.718272
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						182.163969
4210	4	4210	4			
4210A	4			1.000000 x	43.271911 =	43.271911
4210B				1.000000 x	143.445697 =	143.445697
-----						
T.E =						186.717608
4220B	1	4220B	1			
319				.020000 x	22.070000 =	.441400
701	2			.320000 x	4.930878 =	1.577881
601				.320000 x	23.612397 =	7.555967
4220A	1			.800000 x	109.186200 =	87.348960
111				.400000 x	15.741598 =	6.296639
714				1.150000 x	7.218484 =	8.301257
-----						
T.E =						111.522104

4220B 2	4220B 2			
319		.020000 x	22.070000 =	.441400
4220A 2		.800000 x	116.775598 =	93.420478
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.930878 =	1.577881
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.218484 =	8.301257

T.E = 117.593622

4220B 3	4220B 3			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.930878 =	1.577881
601		.320000 x	23.612397 =	7.555967
4220A 3		.800000 x	118.953759 =	95.163007
714		1.150000 x	7.218484 =	8.301257
111		.400000 x	15.741598 =	6.296639

T.E = 119.336151

4220B 4	4220B 4			
319		.020000 x	22.070000 =	.441400
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	126.543157 =	101.234526
701 2		.320000 x	4.930878 =	1.577881
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.218484 =	8.301257

T.E = 125.407669

4220B 5	4220B 5			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
4220A 1		.800000 x	109.186200 =	87.348960
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.218484 =	8.301257

T.E = 110.307105

4220B 6	4220B 6			
319		.020000 x	22.070000 =	.441400
4220A 2		.800000 x	116.775598 =	93.420478
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
714		1.150000 x	7.218484 =	8.301257

T.E = 116.378623

4220B 7	4220B 7			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
4220A 3		.800000 x	118.953759 =	95.163007
714		1.150000 x	7.218484 =	8.301257
111		.400000 x	15.741598 =	6.296639

T.E = 118.121152

4220B 8	4220B 8			
319		.020000 x	22.070000 =	.441400
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.218484 =	8.301257
701 2		.320000 x	4.930878 =	1.577881
609		.320000 x	19.815525 =	6.340968
4220A 4		.800000 x	126.543157 =	101.234526

T.E = 124.192670

4230 1	4230 1			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.081799 =	.770450
701 2		.500000 x	4.930878 =	2.465439
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.419486 =	24.503383
407		.040000 x	728.382345 =	29.135294
607		.500000 x	10.388843 =	5.194422
606		.800000 x	9.477148 =	7.581718
714		1.150000 x	7.218484 =	8.301257
111		2.000000 x	15.741598 =	31.483196

T.E = 139.601032

4230 2	4230 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.081799 =	.770450
701 4		.500000 x	4.622698 =	2.311349
701 2		.800000 x	4.930878 =	3.944702
630		.250000 x	3.219087 =	.804772
611		.500000 x	25.875818 =	12.937909
606		.800000 x	9.477148 =	7.581718
407		.040000 x	728.382345 =	29.135294
714		1.150000 x	7.218484 =	8.301257
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	22.070000 =	.441400

T.E = 147.190430

4230	3	4230	3		
221				250.000000 x	.099900 = 24.975000
701	5			.250000 x	3.081799 = .770450
701	4			.800000 x	4.622698 = 3.698158
701	2			.500000 x	4.930878 = 2.465439
630				.250000 x	3.219087 = .804772
610				.800000 x	21.994777 = 17.595822
319				.020000 x	22.070000 = .441400
111				2.000000 x	15.741598 = 31.483196
407				.040000 x	728.382345 = 29.135294
607				.500000 x	10.388843 = 5.194422
714				1.150000 x	7.218484 = 8.301257
113				1.200000 x	20.419486 = 24.503383

T.E = 149.368592

4230	4	4230	4		
221				250.000000 x	.099900 = 24.975000
701	5			.250000 x	3.081799 = .770450
701	4			.500000 x	4.622698 = 2.311349
701	4			.800000 x	4.622698 = 3.698158
630				.250000 x	3.219087 = .804772
611				.500000 x	25.875818 = 12.937909
610				.800000 x	21.994777 = 17.595822
407				.040000 x	728.382345 = 29.135294
714				1.150000 x	7.218484 = 8.301257
319				.020000 x	22.070000 = .441400
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196

T.E = 156.957989

4240	1	4240	1		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	3.081799 = .770450
701	2			.500000 x	4.930878 = 2.465439
701	2			.800000 x	4.930878 = 3.944702
630				.250000 x	3.219087 = .804772
607				.500000 x	10.388843 = 5.194422
606				.800000 x	9.477148 = 7.581718
319				.020000 x	22.070000 = .441400
113				1.200000 x	20.419486 = 24.503383
407				.040000 x	728.382345 = 29.135294
714				1.150000 x	7.218484 = 8.301257
111				2.000000 x	15.741598 = 31.483196

T.E = 144.596032

4240	2	4240	2			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	3.081799 =	.770450
701	4			.500000 x	4.622698 =	2.311349
701	2			.800000 x	4.930878 =	3.944702
630				.250000 x	3.219087 =	.804772
611				.500000 x	25.875818 =	12.937909
606				.800000 x	9.477148 =	7.581718
407				.040000 x	728.382345 =	29.135294
714				1.150000 x	7.218484 =	8.301257
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196
319				.020000 x	22.070000 =	.441400

-----  
T.E = 152.185430

4240	3	4240	3			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	3.081799 =	.770450
701	4			.800000 x	4.622698 =	3.698158
701	2			.500000 x	4.930878 =	2.465439
630				.250000 x	3.219087 =	.804772
610				.800000 x	21.994777 =	17.595822
319				.020000 x	22.070000 =	.441400
111				2.000000 x	15.741598 =	31.483196
407				.040000 x	728.382345 =	29.135294
607				.500000 x	10.388843 =	5.194422
714				1.150000 x	7.218484 =	8.301257
113				1.200000 x	20.419486 =	24.503383

-----  
T.E = 154.363592

4240	4	4240	4			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	3.081799 =	.770450
701	4			.500000 x	4.622698 =	2.311349
701	4			.800000 x	4.622698 =	3.698158
630				.250000 x	3.219087 =	.804772
611				.500000 x	25.875818 =	12.937909
610				.800000 x	21.994777 =	17.595822
407				.040000 x	728.382345 =	29.135294
714				1.150000 x	7.218484 =	8.301257
319				.020000 x	22.070000 =	.441400
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196

-----  
T.E = 161.952989

4300	1	4300	1			
4300A	1			1.000000 x	29.829926 =	29.829926
4300B				1.000000 x	11.044645 =	11.044645

-----  
T.E = 40.874571

ΑΤΛΕ		2ο Τρίμηνο του 2011		Σελ.	49
				Ημ/νία	22/12/2011
4300	2	4300	2		
	4300A 2		1.000000 x	31.347806 =	31.347806
	4300B		1.000000 x	11.044645 =	11.044645
			-----		
				T.E =	42.392451
4300	3	4300	3		
	4300A 3		1.000000 x	31.783438 =	31.783438
	4300B		1.000000 x	11.044645 =	11.044645
			-----		
				T.E =	42.828083
4300	4	4300	4		
	4300A 4		1.000000 x	33.301318 =	33.301318
	4300B		1.000000 x	11.044645 =	11.044645
			-----		
				T.E =	44.345963
4400		4400			
	251		1.050000 x	.545500 =	.572775
	113		.050000 x	20.419486 =	1.020974
			-----		
				T.E =	1.593749
4500		4500			
	251		1.050000 x	.545500 =	.572775
	113		.100000 x	20.419486 =	2.041949
	114		.100000 x	17.312112 =	1.731211
			-----		
				T.E =	4.345935
4600		4600			
	256		1.000000 x	4.100000 =	4.100000
	113		.100000 x	20.419486 =	2.041949
			-----		
				T.E =	6.141949
4700		4700			
	253		1.000000 x	4.300000 =	4.300000
	113		.100000 x	20.419486 =	2.041949
			-----		
				T.E =	6.341949